

Component Serial Number

VIN

225093

473909C0613366

W1T96342420499867

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

96342422-XAU30

30/06/2021

**Vehicle Notes :**

21/04/2021 12:00:00AM RO#: M104626 DATE: 21/04/2021 CUST: QS COMMODITIES ODOM: 1777 TOTAL: \$9437.62 ADVISOR: Peter Boys  
BRANCH: 447MB SALE TYPE: |||||

## OP\_CODES

88MB0000|88MBZZZZZA|67MBZZZZZA|91MBZZZZB|40MBCOVERS|88MBZZZZB|43MBZZZZZA

## OP\_DESC

exterior trim|||CHROME HUB &amp; NUT COV||

## COMPLAINT

SUPPLY AND FIT JOST JSK37 GREASY TURNTABLE^HIGHT 270mm, ON 20mm PLATE|SUPPLY AND FIT BLACK PLASTIC DRIVE GUARDS^ON CHROME POLES WITH PLASTIC GUARD MOUNTS^LOOP KITS, DTB MUDFLAPS TO REAR WITH MARKER PLATES^TAIL LAMPS ON NEW STYLE BRACKETS|SUPPLY AND FIT WI

## CAUSE

|||||

## CORRECTION

|||||

27/04/2021 12:00:00AM RO#: M104740 DATE: 27/04/2021 CUST: QS COMMODITIES ODOM: 1775 TOTAL: \$2238.64 ADVISOR: Peter Boys  
BRANCH: 447MB SALE TYPE: |||

## OP\_CODES

00MB10ZZPD|40MBZZZZZA

## OP\_DESC

CARRY OUT PRE-DELIVE|carry out wheel align

## COMPLAINT

|FRONT AND REAR ALIGNMENT - NO AXLE BEND

## CAUSE

|

## CORRECTION

PREDELIVERY INSPECTION|

1/06/2021 12:00:00AM RO#: M105800 DATE: 01/06/2021 CUST: QS COMMODITIES ODOM: 1780 TOTAL: \$2523.80 ADVISOR: Peter Boys  
BRANCH: 447MB SALE TYPE: |||

## OP\_CODES

54MBZZZZZA|54MB10ZZ000099.BAK

## OP\_DESC

ELECTRICAL REPAIRS 4|ELECTRICAL REPAIRS

## COMPLAINT

SUPPLY AND FIT PTO SWITCH AND WIRING^WIRE IN RAISE AND LOWER SWITCH|WIRE IN BULBAR LIGHTS

## CAUSE

|

## CORRECTION

|

15/06/2021 12:00:00AM RO#: M106230 DATE: 15/06/2021 CUST: QS COMMODITIES ODOM: 1785 TOTAL: \$2537.09 ADVISOR: Peter Boys  
BRANCH: 447MB SALE TYPE: I

## OP\_CODES

43MBZZZZZA

## OP\_DESC

## COMPLAINT

SUPPLY AND FIT TRAILER BRAKE RELEASE KIT

## CAUSE

## CORRECTION

Component Serial Number

VIN

225093

473909C0613366

W1T96342420499867

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

96342422-XAU30

30/06/2021

29/06/2021 12:00:00AM RO#: M106619 DATE: 29/06/2021 CUST: QS COMMODITIES ODOM: 1800 TOTAL: \$240.00 ADVISOR: Peter Boys  
BRANCH: 447MB SALE TYPE: I

OP\_CODES  
88MB0000

OP\_DESC  
exterior trim

COMPLAINT  
SWAP OVER TURNTABLE WITH GREASLESS E TYPE

CAUSE

CORRECTION

14/07/2021 12:00:00AM RO#: M107060 DATE: 14/07/2021 CUST: QS COMMODITIES ODOM: 7592 TOTAL: \$661.70 ADVISOR: Zoe Millington  
BRANCH: 447MB SALE TYPE: C

OP\_CODES  
60MBZZZZZA

OP\_DESC

COMPLAINT  
air leaking from rear of vehicle^number 1 reservoir was empty yesterday-sounds like under^tunrtable

CAUSE  
Trailer brake valve bypassing to exhaust line

CORRECTION  
Inspected and found air leaking out of trailer brake valve exhaust^line^Removed intake line and inserted lubricant to try  
and unstick^valve - Failed^removed trailer brake valve and replaced leaking/ damaged fittings^installed new trailer brake  
valve and r

10/09/2021 12:00:00AM RO#: M108523 DATE: 10/09/2021 CUST: QS COMMODITIES ODOM: 41957 TOTAL: \$912.14 ADVISOR: Joe Kenny  
BRANCH: 447MB SALE TYPE: M|W|C

OP\_CODES  
00MB|91MBZZZZZA|54MB10ZZ000099.BAK

OP\_DESC  
TELLIGENT SERV 1|CHECK SEAT|ELECTRICAL REPAIRS

COMPLAINT  
CARRY OUT 40K SCHEULED SERVICE|SEAT KEEPS GOING DOWN AND NOT COMING BACK UP|FIT WIRING  
HARNESS FOR SPOT LIGHTS^

CAUSE  
DC 21118SV^00530602 1.0 Perform Annual Inspection^00503501 0.2 General Telligent maintenance lubrication  
Perform|DC 9117552^54101101 0.3 PERFORM QUICK TEST^91344101 0.4 R/R VALVE|

CORRECTION  
14504 10/09/2021^Brought vehicle into workshop. ^Printed downloads. ^Checked A3 & A4 diff oil levels. ^Checked  
gearbox oil level^Checked suspension & driveline.^Greased chassis & driveline. ^Greased turntable jaw.^Checked  
batteries. ^Checked lights & guar

Component Serial Number

VIN

225093

473909C0613366

W1T96342420499867

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

96342422-XAU30

30/06/2021

12/11/2021 12:00:00AM RO#: M109946 DATE: 12/11/2021 CUST: QS COMMODITIES ODOM: 83206 TOTAL: \$1415.22 ADVISOR: Zoe Millington BRANCH: 447MB SALE TYPE: M|W|W

OP\_CODES  
00MBMRSERV|54MBZZZZZA|83MB0000

OP\_DESC  
M & R SERVICE|ELECTRICAL REPAIRS 4|CHECK A/C NOT COLD

COMPLAINT  
CARRY OUT M & R SERVICE|set speed to 100km|CHECK A/C NOT COLD

CAUSE  
DC 21120SV^00500002 0.8 Engine filter change Perform^00504101 0.5 Fuel filter^00525801 0.2 Fuel filter element water separator^00532001 0.7 Telligent periodic maintenance safety related^00506001 2.2 Perform Top Tune^00503501 0.2 General Telligent maintena

CORRECTION  
Engine filter change Perform^Fuel filter^Fuel filter element water separator^ Telligent periodic maintenance safety related^Perform Top Tune^General Telligent maintenance lubrication Perform||

---

23/12/2021 12:00:00AM RO#: M111020 DATE: 23/12/2021 CUST: QS COMMODITIES ODOM: 108900 TOTAL: \$1751.07 ADVISOR: Tyler Day BRANCH: 447MB SALE TYPE: I||M|C|C

OP\_CODES  
54MB0099|01MB|54MH0099|60MBZZZZZA|54MBZZZZZA

OP\_DESC  
ELECTRICAL REPAIRS 1|ENGINE MECH 1|ELECTRICAL REPAIRS 1||ELECTRICAL REPAIRS 4

COMPLAINT  
SUPPLY & FIT SPOT LIGHTS|SUPPLY & FIT DIFF & GEARBOX BREATHERS|CHECK ALL LIGHTS|RH lower mirror cover missing ( impact damage)|Replace cracked fog light as requested by customer ( Impact^damage)

CAUSE  
||DC - 21208SV^54101001 0.5 Electrical system Check, findings:.....^54794301 0.2 Repair..... cable set||

CORRECTION  
||RH high beam open circuit at headlight plug due to loose pin^tension in pin 3 and 1, RHF fog lightimpacted causing lens to^crack^Correction:~-Check lights, found RH high beam inop and RHF fog lightlens^cracked^~Remove headlight cover and test power at s

---

27/01/2022 12:00:00AM RO#: M111764 DATE: 27/01/2022 CUST: QS COMMODITIES ODOM: 123739 TOTAL: \$1303.06 ADVISOR: Kristie Scott BRANCH: 447MB SALE TYPE: M|W

OP\_CODES  
00MB10ZZSTDSE|60MB10ZZ000099

OP\_DESC  
STANDARD SERVICE|CAB/BODY

COMPLAINT  
CARRY OUT 120K SERVICE|DRIVER SEAT HEIGHT ERRATIC

CAUSE  
DC - 21118SV^00530602 1.0 Telligent time-based maintenance - annual Perform^00600001 0.3 Oil level in engine Correct^00602001 0.2 Correct oil level in manual transmission (at further^oil level checks/oil changes)^00605601 0.2 Lubricant level in both rear

CORRECTION  
Correction: Carry out inspection service ^top up engine oil 7 litres ^ Top up transmission oil 2 litres ^Top up A3 and A4 diffs 7 litres^Grease as required ^Replace service sticker carry out finals ^ Top up washer bottle 8 litres|Cause: drivers seat going u

Component Serial Number

VIN

225093

473909C0613366

W1T96342420499867

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

96342422-XAU30

30/06/2021

## Repair Order History

AmtPriceExtended

SlsId : RA920031007:02 Total : \$0.00

Date Invoice : 01/23/2025

OdomIn: 552,861

OdomOut: 552,861

## Rejected Operations

OpsId : 2 Job : ASR REPLACE TACOGRAPH UNIT  
 Cause :  
 Correction :

1.00	CONTROL UNIT TACHOGRAPH	2,457.49	2,457.49
0.00	EX MELB	0.00	0.00
1.00	FREIGHT833	25.00	25.00
1.00	COMPUTER DOWNLOAD	120.00	120.00

SlsId : RA920031007:01 Total : \$400.00

Date Invoice : 01/23/2025

OdomIn: 552,861

OdomOut: 552,861

## Sold Operations

OpsId : 1 Job : 99 CHECK ENGINE LIGHT RELATED TO SPEED SIGNAL.  
 Cause :  
 Correction : CAUSE: Tachograph module not working ( Internal circuit issue)

0.00	CONTROL UNIT TACHOGRAPH	2,228.92	0.00
0.00	PUT BACK INTO STOCK	0.00	0.00
1.00	COMPUTER DOWNLOAD	60.00	60.00

SlsId : RA920031006:01 Total : -\$440.00

Date Invoice : 01/23/2025

OdomIn: 552,861

OdomOut: 552,861

## Sold Operations

OpsId : 1 Job : 99 CHECK ENGINE LIGHT RELATED TO SPEED SIGNAL.  
 Cause :  
 Correction : CAUSE: Tachograph module not working ( Internal circuit issue)

0.00	CONTROL UNIT TACHOGRAPH	2,362.49	0.00
0.00	PUT BACK INTO STOCK	0.00	0.00
-1.00	COMPUTER DOWNLOAD	60.00	-60.00

## Rejected Operations

OpsId : 2 Job : ASR REPLACE TACOGRAPH UNIT  
 Cause :  
 Correction :

-1.00	CONTROL UNIT TACHOGRAPH	2,362.49	-2,362.49
0.00	EX MELB	0.00	0.00
-1.00	FREIGHT833	25.00	-25.00
-1.00	COMPUTER DOWNLOAD	120.00	-120.00

SlsId : RA920027077:01 Total : \$440.00

Date Invoice : 11/19/2024

OdomIn: 552,861

OdomOut: 552,861

Component Serial Number

VIN

225093

473909C0613366

W1T96342420499867

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

96342422-XAU30

30/06/2021

**Sold Operations**

OpsId : 1 Job : 99 CHECK ENGINE LIGHT RELATED TO SPEED SIGNAL.

Cause :

Correction : CAUSE: Tachograph module not working ( Internal circuit issue)

0.00	CONTROL UNIT TACHOGRAPH	2,362.49	0.00
0.00	PUT BACK INTO STOCK	0.00	0.00
1.00	COMPUTER DOWNLOAD	60.00	60.00

**Rejected Operations**

OpsId : 2 Job : ASR REPLACE TACOGRAPH UNIT

Cause :

Correction :

1.00	CONTROL UNIT TACHOGRAPH	2,362.49	2,362.49
0.00	EX MELB	0.00	0.00
1.00	FREIGHT833	25.00	25.00
1.00	COMPUTER DOWNLOAD	120.00	120.00

SIsId : RA920024048:01 Total : \$532.00

Date Invoice : 06/13/2024

OdomIn: 552,861

OdomOut: 552,861

**Sold Operations**

OpsId : 1 Job : 99 LH FRONT HUB SEAL LEAKING

Cause : DONE - HP

Correction : CAUSE:

OpsId : 2 Job : 99 ENGINE FAULT CAME ON DASH AND TRUCK DERATED. FAULT CLEAF

Cause : DONE - HP

Correction : CAUSE:

SIsId : RA920009280:01 Total : \$3,560.99

Date Invoice : 03/31/2023

OdomIn: 316,460

OdomOut: 316,460

**Sold Operations**

OpsId : 1 Job : 47 CHECK AND REPORT ON RHS FUEL TANK MOVEMENT - RUBBED THI

Cause : FUEL TANK MOVEMENT - RUBBED THROUGH

Correction : CARRIED OUT DRIVING TRUCK INTO THE WORKSHOP

1.00	TANK FUEL 400L	3,284.99	3,284.99
------	----------------	----------	----------

SIsId : RA920003900:04 Total : \$0.00

Date Invoice : 08/22/2022

OdomIn: 225,828

OdomOut: 225,828

**Sold Operations**

OpsId : 3 Job : 00 Problem with steering, severe shaking in the steering, had wheel alignmer

Cause : Done JB

Correction : needs more investigation

SIsId : RA920003900:03 Total : \$1,557.45

Date Invoice : 08/09/2022

OdomIn: 225,828

OdomOut: 225,828

Component Serial Number

VIN

225093

473909C0613366

W1T96342420499867

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

96342422-XAU30

30/06/2021

**Sold Operations**

OpsId : 2 Job : 00 Ice pack not working  
 Cause : Done JB, requires sublet to Brisk air  
 Correction : working just not blowing cold air re gas may fix this problem

OpsId : 6 Job : 00 Brendan has ordered replacement panel that is missing on passenger side  
 Cause : Done JB  
 Correction :

1.00 **FENDER** 279.99 279.99

1.00 **FENDER** 173.99 173.99

OpsId : 8 Job : 88 Fuel tank strap bent  
 Cause : Done JB  
 Correction :

1.00 **STRAP 62MM W X 1396MM L** 134.99 134.99

1.00 **PAD** 98.99 98.99

OpsId : 9 Job : 54 RH foglight assembly impacted  
 Cause : Done JB  
 Correction :

1.00 **FOG LAMP RH** 242.49 242.49

SIId : RA920003900:02 Total : \$4,951.82

Date Invoice : 08/05/2022

OdomIn: 225,828

OdomOut: 225,828

**Sold Operations**

OpsId : 4 Job : 00 Air leak in the chassis rail  
 Cause : Done JB.  
 Correction : CAUSE - Found Air leak in front r/h brake chamber due to rubber perished also EAPU exhurting a

1.00 **BRAKE CYLINDER ATEGO E5** 205.45 205.45

1.00 **MUFFLER** 138.68 138.68

1.00 **CONNECTING PIECE** 24.53 24.53

1.00 **AIR PROCESSING UNIT** 2,925.13 2,925.13

OpsId : 5 Job : 00 Overheating uphill  
 Cause : Done JB  
 Correction : CAUSE - Thermostat seized;

1.00 **THERMOSTAT** 196.15 196.15

1.00 **CLAMP** 16.41 16.41

36.00 **COOLANT - ALLIANCE PRIMECOOL GP P-40 (205L) - QABP AFM4604205** 4.86 174.96

1.00 **Adjust Parts Cost [[Warranty Only]]** 0.01 0.01

SIId : RA920003900:01 Total : \$145.04

Date Invoice : 08/05/2022

OdomIn: 225,828

OdomOut: 225,828

**Sold Operations**

OpsId : 1 Job : 00 Due for a service -please look at passenger side fuel tank and straps.  
 Cause : Done JB  
 Correction : 37360 Alex 20/07/2022

Component Serial Number

VIN

225093

473909C0613366

W1T96342420499867

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

96342422-XAU30

30/06/2021

SlId : RA920001744:01 Total : \$262.36

Date Invoice : 06/08/2022

OdomIn: 183,512

OdomOut: 183,512

## Sold Operations

OpsId : 1 Job : 13 repair air leak under walk plate,  
 Cause : DONE  
 Correction : Drove truck round found eapu consistently exhausting,

1.00 WORKSHOP SUNDRIES

0.01

0.01

SlId : RA920001433:03 Total : \$0.00

Date Invoice : 06/13/2022

OdomIn: 176,084

OdomOut: 176,084

## Rejected Operations

OpsId : 2 Job : 00 quote  
 Cause :  
 Correction :

1.00 LAMP UNIT - EX MELB - RH HEADLIGHT

2,287.49

2,287.49

SlId : RA920001433:02 Total : \$1,803.98

Date Invoice : 05/30/2022

OdomIn: 176,084

OdomOut: 176,084

## Sold Operations

OpsId : 1 Job : 00 service  
 Cause : Service due by kms  
 Correction : Drove truck onto pit

1.00	FILTER PACKAGE	63.39	63.39
1.00	SCREW PLUG	33.94	33.94
1.00	TS FUEL FILTER	176.26	176.26
1.00	DUST FILTER	84.81	84.81
2.00	AIR FILTER	54.97	109.94
1.00	AIR FILTER INSERT	315.54	315.54
0.00	DELIVER TO PIT#2 PLEASE!@!@	0.00	0.00
1.00	TS WIPER BLADE	58.81	58.81
1.00	BULB H/BEAM H1 24V/70W	11.24	11.24
40.00	Engine-ALLIANCE PRIME ENGINE GLOBAL 10W40-205 Litre Pack	7.14	285.60
0.40	COMPLEX GREASE	33.47	13.39
1.00	HAZ WASTE & ENVIRO DISPOSAL	16.00	16.00
1.00	WORKSHOP SUNDRIES	30.26	30.26

SlId : RA920001433:01 Total : \$2,455.57

Date Invoice : 05/30/2022

OdomIn: 176,084

OdomOut: 176,084

Component Serial Number

VIN

225093

473909C0613366

W1T96342420499867

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

96342422-XAU30

30/06/2021

**Sold Operations**

OpsId : 3 Job : 54 Rectify Headlight not working high beam

Cause : Done JB,

Correction : R/H Headlight not working;

1.00	LAMP UNIT	1,966.05	1,966.05
------	-----------	----------	----------

1.00	WORKSHOP SUNDRIES	0.01	0.01
------	-------------------	------	------

OpsId : 4 Job : 43 front brake hose leaking

Cause : VOSS FITTING IN LH FRONT BRAKE BOOSTER CIRCLIP LOST TENSION

Correction : CHECKED FOR AIR LEAKS FOUND LH FRONT VOSS FITTING LEAKING OUT OF BOOSTER

2.00	UNION SCREW	5.92	11.84
------	-------------	------	-------

1.00	BRAKE HOSE	186.15	186.15
------	------------	--------	--------

1.00	WORKSHOP SUNDRIES	0.02	0.02
------	-------------------	------	------