104727

Component Serial Number

473909C0594827

VIN W1T96342420483763

YEAR	MAKE	MODEL	IN SERVICE
2021	MB	ACTROS	29/04/2021

Vehicle Notes:

1/02/2021 12:00:00AM

OP CODES

67MBZZZZ|69MBZZZZ03|54MBZZZZ02|65MBZZZZ|69MBZZZZ|69MBZZZZ13|69MBZZZZ02|65MBZZZZ01|70MBZZZZ1 1|70MBZZZZ1 2|69MBZZZZ32|69MBZZZZ32|69MBZZZZ48|70MBZZZZ10|69MBZZZZ12|69MBZZZZ09|62MBZZZZ27|53MBZZZZ|65MBZZ ZZ13|99MBZZZZ01|99MBZZZZ02

OP_DESC

COMPLAINT

GME TX4500 UHF WITH ANTENNA^SUPPLY AND FIT ON HIGHWAY|WINDOW TINT^SUPPLY AND FIT TWEED TINTING.|FIREEXTINGUISHERS TO BE FITTED.^SUPPLY AND FIT DTGC|WHEEL NUT INDICATORS.^SUPPLY AND FIT DTGC|JOST JSK37 GREASELESS 1270MM HIGH WITH CARRABEAN CLIP. 50MM^FOC^S

CAUSE

CORRECTION

28/06/2021 12:00:00AM

RO#: R54516 DATE: 28/06/2021 CUST: D & G QLD TRANSPORT PTY LTD ODOM: 45226 TOTAL: \$306.36 ADVISOR:

BRANCH: 417RB SALE TYPE: MII

OP CODES

51MBZZZZ|69MBZZZZ

OP_DESC

COMPLAINT

CARRY OUT 40K INSPECTION SERVICE|FIT SUZI COIL DUMMY PLATE AND D/G SIGN

CAUSE

DAMAGE CODE 21118SV^00530602

1.0 Telligent time-based maintenance - annual Perform^CONS \$6.10|

CORRECTION

CARRIED OUT INSPECTION SERVICE.

20/07/2021 12:00:00AM

RO#: R54694 DATE: 20/07/2021 CUST: D & G QLD TRANSPORT PTY LTD ODOM: 45226 TOTAL: \$1646.39 ADVISOR:

BRANCH: 417RB SALE TYPE: I

OP_CODES

67MBZZZZ

OP_DESC

COMPLAINT

SUPPLY AND FIT REDARC TRAILER REDUCER.

CAUSE

CORRECTION

CARRIED OUT FIT UP AS REQUIRED

21/07/2021 12:00:00AM

RO#: R54709 DATE: 21/07/2021 CUST: D & G QLD TRANSPORT PTY LTD ODOM: 45226 TOTAL: \$0.00 ADVISOR:

BRANCH: 417RB SALE TYPE: I

OP_CODES

62MBZZZZ

OP_DESC

COMPLAINT

INSPECT BRAKES WONT RELEASE ON TRAILER

CAUSE

CORRECTION

CORRECTED AIR LINES.

10/727

Component Serial Number

473909C0594827

VIN

W1T96342420483763

YEAR	MAKE	MODEL	IN SERVICE
2021	MB	ACTROS	29/04/2021

30/07/2021 12:00:00AM

RO#: M107458 DATE: 30/07/2021 CUST: D & G QLD TRANSPORT PTY LTD ODOM: 68042 TOTAL: \$412.96 ADVISOR: Joe Kenny BRANCH: 447MB SALE TYPE: W

OP_CODES 00FLBREAKDOWN

OP DESC

ATTEND BREAKDOWN

COMPLAINT

VEHICLE WON'T BUILD UP AIR

CAUSE

DC 4327204^43000099 0.3 R/R Compressed air drier granulate cartridge^54101101 0.3^00962701 1.0

CORRECTION

VEHICLE WON'T BUILD UP AIR^HOLE IN AIR DRYER, SPLIT MATERIAL FAILURE^REMOVED AND REPLACED AIR DRYER^DROVE FROM WORKSHOP TO BREAKDOWN LOCATION 51 ARC PLACE^LARAPINTATESTED OPERATION AND FOUND HAS A HOLE IN IT CAUSING AIR^TO TRAVEL THROUGH INSTEAD OF BUILDI

18/08/2021 12:00:00AM

RO#: R54928 DATE: 18/08/2021 CUST: D & G QLD TRANSPORT PTY LTD ODOM: 81368 TOTAL: \$1931.82 ADVISOR: BRANCH: 417RB SALE TYPE: M

OP_CODES 51MBZZZZ

OP_DESC

COMPLAINT

CARRY OUT TELLIGENT SERVICE

CAUSE

DAMAGE CODE 21120SV^00530602 1.5 Telligent time-based maintenance - annual Perform^00503501 0.2 GeneralTelligent maintenance lubrication Perform^(with additional Telligent maintenance)^00532001 0.7 Telligent periodic maintenance safety-related^operations

CORRECTION

REPLACED: 'ENGINE OIL AND FILTER'FUEL FILTERS'ADBLUE FILTER'AIR FILTER'POLLEN FILTER'FITTED DIPSTICKSCREW IN FITTING AND CAP AS WAS MISSING.

23/08/2021 12:00:00AM

RO#: M108045 DATE: 23/08/2021 CUST: D & G QLD TRANSPORT PTY LTD ODOM: 81703 TOTAL: \$874.88 ADVISOR: Zoe Millington BRANCH: 447MB SALE TYPE: I

OP_CODES 00FLAHBDOWN

OP_DESC A/H BREAKDOWN

COMPLAINT

VEHICLE WILL NOT START - KNOCKING NOISE FROM ENGINE

CAUSE

CORRECTION

ATTENDED BREAKDOWN^-NO. 5 EXHAUST ROCKER NUT HEAD HAS COME FREE FROM ROCKER ARM-^INSPECTED AND TESTED OPERATION OF VEHICLE FROM KNOCKING NOISE FROM'ENGINE CONCERN^CONFIRMED KNOCKING NOISE TO BE PRESENT^TILTED CAB ^REMOVED ROCKER COVER^FOUND SCREW FOR EXHA

194727

473909C0594827

VIN W1T96342420483763

YEAR	MAKE	MODEL	IN SERVICE
2021	MB	ACTROS	29/04/2021

27/09/2021 12:00:00AM

RO#: F162155 DATE: 27/09/2021 CUST: D & G QLD TRANSPORT ODOM: 110933 TOTAL: \$0.00 ADVISOR: Daniel Sladek BRANCH: 801MF SALE TYPE: C

OP_CODES 95MBZZIHBD

OP DESC

WORK HOURS BREAKDOWN

COMPLAINT

CARRY OUT DURING HOURS BREAKDOWN 27-09-2021 9:05Am VIP GOLD^COAST^Orange engine light, engine faultydisplaying on dash - code^CPC & 580602 & driving and braking characteristics^changed^1 Horsburgh; Near Ampol Servo^MUHAMMAD - 0401 263 064

CAUSE

vehicle speed signal missing between techograph & ICUC

CORRECTION

4/10/2021 12:00:00AM

RO#: F162575 DATE: 04/10/2021 CUST: D & G QLD TRANSPORT ODOM: 118099 TOTAL: \$72.55 ADVISOR: Saras Balaji BRANCH: 801MF SALE TYPE: M

OP_CODES 18MB

OP_DESC Engine Lubrication

COMPLAINT TOP UP ENGINE OIL 7L

CAUSE

TOP UP REQUIRED

CORRECTION

TOPPED UP ENGINE OIL 5L AS REQUIRED^ALL OK

13/10/2021 12:00:00AM

RO#: R55355 DATE: 13/10/2021 CUST: D & G QLD TRANSPORT PTY LTD ODOM: 126604 TOTAL: \$1214.27

ADVISOR: BRANCH: 417RB SALE TYPE: M|C|C

OP_CODES

51MBZZZZ|67MBZZZZ05|64MBZZZZ03

OP_DESC

COMPLAINT

CARRY OUT INSPECTION SERVICE (120K)|RH FOG LIGHT BROKEN|CHECK NOISE FROM STEERING - CHECK OVER SUSPENSION COMPONENTS

CAUSE

DC - 21118SV^00530602 1.0 Perform Annual Inspection^00503501 0.2 General Telligent maintenance lubrication Perform|

CORRECTION

CARRIED OUT INSPECTION SERVICE AS REQUIRED.|REPLACED FOG LIGH, SPOT LIGHT AND WASHER BOTTLE CAP.|CHECKED OVER SUSPENSION AND STEERING COMPONENTS - ALL OK.

VIN

W1T96342420483763

 YEAR
 MAKE
 MODEL
 IN SERVICE

 2021
 MB
 ACTROS
 29/04/2021

15/11/2021 12:00:00AM

RO#: R55628 DATE: 15/11/2021 CUST: D & G QLD TRANSPORT PTY LTD ODOM: 157235 TOTAL: \$1727.57 ADVISOR: BRANCH: 417RB SALE TYPE: MIMIIIII

OP CODES

51MBZZZZ|56MBZZZZ02|70MBZZZZ26|58MBZZZZ05|67MBZZZZ

OP DESC

Ш

COMPLAINT

CARRY OUT TELLIGENT SERVICE (160K).; JUSING 7-8 LITRES OF ENGINE OIL EVERY 10K AND WATER/SEP^FILTER KEEPS FILLING QUICKLY. JRH SEAT NOISY ON THE WAY DOWN JNOT SHIFTING AUTOMATICALL INTO 5TH AND 8TH GEARS- NEED TO SHIFT MANUALLY. JCRUISE CONTROL NOT WORKING -

CAUSE

DC - 21119SV^00530602 1.5 Perform Annual Inspection^00532001 0.7 Perform Telligent periodic maintenance safety related^00500002 0.8 Engine filter change Perform^00504101 0.5 Fuel filter^00525801 0.2 Fuel filter element water separator^00503501 0.2 General

CORRECTION

CARRIED OUT SERVICE AS PER 160K SCHEDULE. JACTIVATED OIL CONSUMPTION TEST. "VEHICLE TO RETURN IN 2000KMS FOR FURTHER TESTING. JRESECURED SEAT AS REQUIRED. JFOUND TRUCK WAS IN LIMP MODE DUE TO BLOCKED FUEL FILTERS. JIN LIMP MODE DUE TO BLOCKED FUEL FILTERS.

10/12/2021 12:00:00AM

RO#: R55856 DATE: 10/12/2021 CUST: D & G QLD TRANSPORT PTY LTD ODOM: 179534 TOTAL: \$270.72 ADVISOR: BRANCH: 417RB SALE TYPE: M|M|M|M|M|M

OP CODES

56MBZZZZ10|69MBZZZZ03|69MBZZZZ|69MBZZZZ22|67MBZZZZ|70MBZZZZ26

OP DESC

Ш

COMPLAINT

USING 10L OF ENGINE OIL EVERY 10K.|WASHER JETS NOT WORKING|LH PANEL CATCHING ON DOOR WHEN OPENING DOOR|RH DOOR FRONT GRAB HANDLE LOOSE|C-TYPE USB PORT NOT WORKING|DRIVERS SEAT LOOSE - HAS BACKWARDS/FORWARDS TILT MOVEMENT^WHILE DRIVING FROM SEAT BACK.

CAUSE

DC - 21207SV^01101001 0.5 Oil loss from engine Determine^00600001 0.3 Oil level in engine Correct|DC-21212SV^82735001 0.8 Hose for washer system replace|REPORT ONLY|DC - 21212SV^72727001 0.3 Outsidedoor handle of 1st door on right as hinged^door Replace|

CORRECTION

CARRIED OUT ENGINE OIL CONSUMPTION TEST DUE TO USING OIL. TOPPED UP OIL LEVEL AND ADVISDE CUSTOMER TO RETUN IN 200KMS FOUND T PIECE FOR HOSES HAD COME OFF UNDER FRONT CAB PANEL. REMOVED ALL COMPONENTS TO ACCESS AND RECONNECTED T-PIECE. REASSEMBLED AND RECH

23/12/2021 12:00:00AM

RO#: R55943 DATE: 23/12/2021 CUST: D & G QLD TRANSPORT PTY LTD ODOM: 190381 TOTAL: \$33.33 ADVISOR: BRANCH: 417RB SALE TYPE: I

OP_CODES 69MBZZZZ03

OP_DESC

COMPLAINT

WASHER JETS N/W AGAIN

CAUSE

CORRECTION

FOUND WASHER LINES BLOCKED DUE TO SOAPY WATER. CLEANED LINES AND RECHECKED - ALL OK.

4727

VIN

W1T96342420483763

 YEAR
 MAKE
 MODEL
 IN SERVICE

 2021
 MB
 ACTROS
 29/04/2021

19/01/2022 12:00:00AM

RO#: R56083 DATE: 19/01/2022 CUST: D & G QLD TRANSPORT PTY LTD ODOM: 216168 TOTAL: \$550.22 ADVISOR: BRANCH: 417RB SALE TYPE: M

OP_CODES 51MBZZZZ

OP_DESC

COMPLAINT

CARRY OUT INSPECTION SERVICE

CAUSE

DC 21118SV^00530602 1.0 Perform Annual Inspection^00503501 0.2 General Telligent maintenance lubrication Perform^(with additional Telligent maintenance^00509301 0.2 Air filter cartridge replace

CORRECTION

CARRIED OUT INSPECTION SERVICE. REPLACED WIPERS. REPLACED AIR FILTER.

23/02/2022 12:00:00AM

RO#: R56399 DATE: 23/02/2022 CUST: D & G QLD TRANSPORT PTY LTD ODOM: 244526 TOTAL: \$2116.43 ADVISOR: BRANCH: 417RB SALE TYPE: M|M|W

OP CODES

51MBZZZZ|67MBZZZZ06|69MBZZZZ03

OP_DESC

COMPLAINT

CARRY OUT TELLIGENT SERVICE (240K)|RHF INDICATOR NOT WORKING|WASHER JETS NOT WORKING

CAUSE

DC - 21119SV^00530602 1.5 Telligent time-based maintenance - annual Perform^00532001 0.7 Telligent periodic maintenance safety-related^operations Perform^00503501 0.2 General Telligent maintenance lubrication Perform^(with additional Telligent maintenance

CORRECTION

CARRIED OUT 240K SERVICE.|FOUND BLOWN GLOBE - REPLACED GLOBE.|TESTED POWER AT PUMP - ALL OK.^BLEW WATER LINES OUT CLEAN - STILL INOP.^FOUND OPEN CIRCUIT IN PUMP.^REMOVED AND REPLACED WASHER PUMP.^RECHECKED OPERATION - ALL OK.

194727

473909C0594827

VIN W1T96342420483763

 YEAR
 MAKE
 MODEL
 IN SERVICE

 2021
 MB
 ACTROS
 29/04/2021

Repair Order History <u>AmtPrice</u> <u>Extended</u>

SIsId: RA950003770:01 Total: \$770.00 Date Invoice: 09/06/2022 OdomIn: 390,915 OdomOut: 390,915

Sold Operations

Opsid: 1 Job: BDA BREAKDOWN AFTERHOURS

Cause:

Correction: Attend to truck @ 3 Federation way in Moorabbin.

60.00 KMS TRAVELLED 1.50 90.00 1.00 A/HOURS CALL OUT 185.00 185.00

SIsId: RA931012039:01 Total: \$2,228.14 Date Invoice: 01/03/2024 OdomIn: 734,295 OdomOut: 734,295

Sold Operations

Opsid: 1 Job: 00 CHECK AND INSPECT DPF REGEN WARNING ON DASH

Cause:

Correction: REPLACED METERING UNIT

 1.00
 METERING UNIT
 1,739.26
 1,739.26

 1.00
 CORE - METERING UNIT
 300.46
 300.46

 1.00
 CORE MUST BE CLEANED AND RETURNED IN ORGINAL PACKAGING
 0.00
 0.00

 -1.00
 CORE - METERING UNIT
 300.46
 -300.46

SIsId: RA931009665:01 Total: \$2,298.41 Date Invoice: 08/21/2023 OdomIn: 639,112 OdomOut: 639,112

Sold Operations

Opsid: 1 Job: BDA BREAKDOWN AFTERHOURS

Cause:

Correction: BREAKDOWN STARTER MOTOR REPLACEMENT

 1.00 STARTER
 1,187.47

 1.00 CORE DEPOSIT
 230.82

 1.00 PARTS CALLOUT FEE
 150.00

 -1.00 CORE DEPOSIT
 230.82

 -230.82
 -230.82

Opsld: 2 Job: 00 TECH STANDDOWN

Cause:

Correction: TECH STANDOWN

Date Invoice: 05/25/2023 Odomln: 580,673 OdomOut: SIsId: RA921004447:02 Total: \$819.78 580,673 **Sold Operations** OpsId: Job: EA INSPECT ENGINE OIL LEAKING Cause: Correction: Complaint: INSPECT ENGINE OIL LEAKING. **2.00 GASKET** 17.13 34.26 72.60 10.00 ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 7.26 2.00 HIGH-PRESSURE LINE (1-2-3) 170.26 340.52 2.00 INJECTOR LINE KIT 4 5 6 111.35 222.70

194727

473909C0594827

VIN W1T96342420483763

0.01

-0.01

 YEAR
 MAKE
 MODEL
 IN SERVICE

 2021
 MB
 ACTROS
 29/04/2021

SIsId: RA921004447:01 Total: \$0.00 Date Invoice: 05/04/2023 OdomIn: 580,673 OdomOut: 580,673

Sold Operations

Opsid: 2 Job: EA DPF LIGHT ON DASH

Cause :

Correction: Complaint: DPF LIGHT ON DASH.

OpsId: 3 Job: 79 RECALL - SM3272 Update software release in motor control module (MCN

Cause:

Correction: Complaint: RECALL - SM3272 Update software release in motor control module (MCM).

SIsId: RA921004041:02 Total: \$512.99 Date Invoice: 03/28/2023 OdomIn: 542,070 OdomOut: 542,070

Sold Operations

OpsId: 2 Job: EA CABIN LIGHT INOP

Cause:

Correction: FURTHER DIAGNOSIS REQUIRED

Opsid: 3 Job: 54 FRONT FOG LIGHT DAMAGED DUE TO HIT & IS INOP

Cause:

Correction: CARRIED OUT R&R OF LH FOG LAMP ASSY

1.00 **FOG LAMP LH** 309.99 309.99

SIsId: RA921004041:01 Total: \$2,890.39 Date Invoice: 03/25/2023 OdomIn: 542,070 OdomOut: 542,070

Sold Operations

Opsid: 1 Job: EA RH HEADLIGHT INOP

Cause : Internal short in RH head light causing Sam to open circuit

Correction : CARRIED OUT INVESTIGATION

1.00 **LAMP UNIT** 2,082.99 2,082.99

-1.00 Adjust Parts Cost [[Warranty Only]] 0.01 -0.01

Opsid: 4 Job: 54 REAR TAIL LIGHT HAS WATER INGRESS

Cause :

Correction: CARRIED OUT INVESTIGATION

1.00 TAIL LAMP RH(B/NECK 4TH Q 567.90

-1.00 Adjust Parts Cost [[Warranty Only]]

SIsId: RA921003767:01 Total: \$0.00 Date Invoice: 05/30/2023 OdomIn: 580,673 OdomOut: 580,673

Sold Operations

Opsid: 2 Job: 72 DRIVERS DOOR DOESNT OPEN FAR ENOUGH

Cause:

Correction: carried out checks off door not opening correctly.

OpsId: 7 Job: 18 Replace missing engine oil dipstick tube plug

Cause : Correction :

SIsId: RA921003682:01 Total: \$3,401.36 Date Invoice: 02/24/2023 OdomIn: 522,372 OdomOut: 522,372

94727

VIN

 YEAR
 MAKE
 MODEL
 IN SERVICE

 2021
 MB
 ACTROS
 29/04/2021

	Sold Operation	ıs	
Opsld : Cause :	4 Job: 00 CARRY OUT TELLIC	GENT SERVICE	
Correction	carried out telligent service		
1.00	FILTER PACKAGE	95.99	95.99
1.00	SCREW PLUG	46.09	46.09
1.00	TS FUEL FILTER	267.49	267.49
1.00	FILTER CARTRIDGE	224.99	224.99
2.00	AIR FILTER	86.99	173.98
1.00	DUST FILTER	128.99	128.99
1.00	FILTER INSERT	292.49	292.49
1.00	FILTER ELEMENT	198.99	198.99
1.00	FILTER ELEMENT	17.69	17.69
1.00	ROCKER COVER SEAL DD13/15	137.99	137.99
1.00	TS WIPER BLADE	88.99	88.99
43.00	ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10	W40 18.16	780.88
1.00	GREASE- COMPLEX A0019894051 09	33.65	33.65
35.00	COOLANT - ALLIANCE PRIMECOOL GP P-40 (20	5L) - QABP AFM4604205 11.29	395.15

SIsId: RA92100	3651:01 Total: \$1,387.50	Date Invoice : 02/28/2023	Odomln:	527,973	OdomOut:	527,973
		Sold Operations				
OpsId : Cause : Correction	10 Job: 15	INSPECT A/C NOT COLD AFTER	1 HR OF DR	IVING, HAS E	BEEN PREVI	
1.00				1,005	5.02 1,0	05.02
2.00	FULL FACE GASKET			15	5.38	30.76
0.93	R134A AC GAS			24	1.83	23.09
-1.00	Adjust Parts Cost [[Warran	ty Only]]		C).71	-0.71

SIsId: RA921003622:03 Total: \$0.00 Date Invoice: 02/24/2023 OdomIn: 522,368 OdomOut: 522,372

Sold Operations

Opsld: 1 Job: 83 A/C INOP

Cause:

Correction: CARRIED OUT INSPECTION AND FOUND A/C TO BE OPERATING OK

Opsid: 3 Job: 54 VEHICLE DOES 97KM/H

Cause:

Correction: mark carried out test drive

SIsId: RA921003622:02 Total: \$463.10 Date Invoice: 02/24/2023 OdomIn: 522,368 OdomOut: 522,372

VIN

W1T96342420483763

MAKE YEAR MODEL IN SERVICE 2021 MB **ACTROS** 29/04/2021

Sold Operations

OpsId: Job: 40 Replace missing wheel nut indicators

Cause:

194727

Correction: carried out fitment of wheel nut indictor due to some missing

8.00 WHEEL SAFE 32MM YELL 1.63 13.04

OpsId: 8 Job: 60 Replace missing fire extinguisher and hold down clamp

Cause:

Correction: carried out removal of fire extinguisher bracket due to being broken

1.00 9KG FIRE EXT BAG 5.58 5.58 1.00 9KG EXTINGUISHER BRA 97.99 97.99 1.00 FIRE EXTINGUISER 9KG 142.99 142.99

SIsId: RA921003622:01 Total: \$1,371.36 Date Invoice: 02/17/2023 Odomln: 522,368 OdomOut: 522,372

Sold Operations

Job: 20 COOLANT LEAK AT RESERVOIR OpsId:

Cause:

Correction: carried out replacement of coolant header tank due to tank leaking from seem

1.00 EXPANSION RESERVOIR 1,071.96 1,071.96

445,319 OdomOut: 445,322 SIsId: RA921002704:02 Total: \$3,819.43 Date Invoice: 12/08/2022 Odomln:

Sold Operations

INSPECT AIRBAGS NOT OPERATING STUCK IN POSITION. OpsId: 1 Job: 32

Cause: Correction:

> 2.00 AIR SSP. BELLOWS, RA 987.49 1.974.98

1.00 AIR SSP. BELLOWS, RA 987.49 987.49

OpsId: 2 Job: 18 Carry out Telli service

Cause:

Correction:

CARRIED OUT HELPING DYLAN WITH TELLI SERVICE 2.00 SCREW PLUG 58.99 117.98 1.00 FILTER PACKAGE 91.99 91.99 269.99 269.99 1.00 TS FUEL FILTER (MAHLE) 43.99 43.99 1.00 SCREW PLUG 1.00 FILTER CARTRIDGE 214.99 214.99 2.00 AIR FILTER 82.99 165.98 1.00 **DUST FILTER** 123.99 123.99 199.99 1.00 FILTER ELEMENT 199.99 -1.00 CORE DEPOSIT 2.349.99 -2.349.99 279.36 32.00 ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 8.73 1.00 GREASE - ALLIANCE AFX2 GREASE (180KGL) - QABP AFM4215180 15.19 15.19

Date Invoice: 11/23/2022 Odomln: 445,319 OdomOut: 445,322 SIsId: RA921002704:01 Total: \$467.77

194727

473909C0594827

VIN W1T96342420483763

3.92

 YEAR
 MAKE
 MODEL
 IN SERVICE

 2021
 MB
 ACTROS
 29/04/2021

Sold Operations

Opsid: 3 Job: 42 PARKING BRAKE FAULT ON DASH CANNOT REALEASE PARKING BRA

Cause:

Correction: PARKING BRAKE FAULT ON DASH CANNOT REALEASE PARKING BRAKE;

1.00 **CONTROL LEVER** 254.27 254.27

1.00 MISC SHOP SUPPLIES 3.92

SISId: RA921002622:01 Total:-\$317.37 Date Invoice: 12/21/2022 OdomIn: 421,609 OdomOut: 421,609

Sold Operations

OpsId: 13 Job: 00 core credit for the compressor A4711307215 - \$317.37

Cause : Correction :

-1.00 **CORE DEPOSIT** 317.37 -317.37

SIsId: RA921002516:01 Total: \$329.78 Date Invoice: 12/21/2022 OdomIn: 0 OdomOut: 445,322

Sold Operations

Opsid: 3 Job: 60 RHS CORNER CABIN PANEL LOOSE

Cause : Correction :

6.00 **COMBI-FILLISTER HEAD SCR.** 0.77 4.62

 6.00
 SPREADER NUT
 1.00
 6.00

 1.00
 COVER
 106.40
 106.40

WASHER CAP MISSING

OpsId : Cause :

Correction: Carried out inspection - Found washer fluid cap missing.

Job: 67

5

1.00 **SCREW CAP** 6.76 6.76

SISId: RA921002211:02 Total: \$1,227.55 Date Invoice: 11/11/2022 OdomIn: 421,603 OdomOut: 421,609

194727

473909C0594827

VIN

YEAR	MAKE	MODEL	IN SERVICE
2021	MB	ACTROS	29/04/2021

Sold Operations

Opsid: 4 Job: 72 RHS MIRROR MISSING FRONT COVER

Cause:

Correction: Carried out inspection - Found drivers side mirror (RHS) front trim cover missing.

1.00 **COVER BOTTOM RIGHT** 43.39 43.39

Opsid: 8 Job: 00 TELLIGENT SERVICE

Cause:

Correction: * Completed Telligent inspection service as required,

 1.00
 BATTERY
 8.89
 8.89

 6.00
 ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (205L) - QABP AFM4982;
 7.26
 43.56

 22.00
 GEAR OIL - ALLIANCE PRIME AXLE PLUS 235.8 75W90 (205L) - QABP AFM461
 22.16
 487.52

 1.00
 GREASE - ALLIANCE AFX2 GREASE (180KGL) - QABP AFM4215180
 15.19
 15.19

OpsId: 12 Job: 54 Repair inoperative bar lights

Cause:

Correction: Carried out replacement of the bar lights

SIsId: RA921002211:01 Total: \$13,303.17 Date Invoice: 10/14/2022 OdomIn: 421,603 OdomOut: 421,609

VIN

MAKE YEAR MODEL IN SERVICE 2021 MB **ACTROS** 29/04/2021

		Sold Operations		
OpsId : Cause :	7 Job : 49 INS	PECT EXHAUST LEAK AT ENGINE.		
Correction	* Found exhaust leak, the E	GR cooler has a crack in it replacement will be	e required,	
2.00	PIPE CLAMP		85.71	171.42
2.00	CONNECTING PIPE		47.37	94.74
1.00	RECIRCULATION COOLER		3,327.80	3,327.80
1.00	RECIRCULATION LINE		527.82	527.82
40.00	COOLANT - ALLIANCE PRIMECO	OOL GP P-40 (205L) - QABP AFM4604205	5.75	230.00
1.00	MISC SHOP SUPPLIES		0.02	0.02
Opsld : Cause :		PECT BATTERY BOX HAS BROKEN.CRACK		ED ON
Correction		get access to mounting bracket for the battery		
	BATTERY SUPPORT		1,522.87	1,522.87
1.00	FOOTPLATE		686.11	686.11
1.00	FASTENING CLAMP		27.14	27.14
1.00	BRKT BTTRY LFT SPPRT LF		494.46	494.46
1.00	BRKT- BTTRY RL SUPPORT		453.88	453.88
1.00	BRKT BTTRY RGT SPPRT FR		494.46	494.46
1.00	BRKT BTTRY RGT SPPRT RR		467.23	467.23
-1.00	Adjust Parts Cost [[Warranty On	[y]]	0.01	-0.01
OpsId : Cause :	10 Job : 18 Rep	pair engine oil leaking from air compressor		
Correction	oil leaking from air compres	sor;		
1.00	DUAL COMPRESSOR		3,399.85	3,399.85
-1.00	Adjust Parts Cost [[Warranty On	ly]]	31.74	-31.74

Sisid: RA921001	710:02 Total : \$403.92	Date Invoice : 08/31/2022	Odomln:	395,634	OdomOut:	395,634
		Sold Operations				
OpsId : Cause :	2 Job: 01 SEAL LEAKING AT FU	INJECTOR SEALS LEAKING #3	& #4			
Correction :	Carried out inspection	- Found engine oil leak from injecto	r seals. (Cyline	ders 3&4)		
2.00	GASKET			14	4.16	28.32
1.00	HIGH-PRESSURE LINE			9.	7.98	97.98
1.00	HIGH-PRESSURE LINE			9	7.98	97.98

395,634 395,634 SIsId: RA921001710:01 Total: \$635.42 Date Invoice: 08/31/2022 Odomln: OdomOut:

VIN

13.55

13.55

MODEL IN SERVICE

				12/41	IVI) U.L	WODEL	III OLITVIOL	
				2021	MB	ACTROS	29/04/2021	
			Sold Oper	rations				
OpsId : Cause : Correction	6	Job: 00 SERVICE DUE Carried out Tellig	C/O TELLIGEN					
1.00	AIR	FILTER INSERT					321.86	321.86
2.00	coo	LANT - ALLIANCI	E PRIMECOOL GP P-4	0 (205L) - C	QABP AFM460	04205	5.37	10.74
1.90	WOF	RKSHOP SUNDRIE	S				7.25	13.78

SIsId: RA92100	1252:01 Total:\$1,773.09	Date Invoice : 07/19/2022	Odomln:	354,563	OdomOut:	354,563
		Sold Operations				
OpsId : Cause : Correction :	1 Job : 00 SERVICE DUE * Completed 320k Tel	CARRY OUT TELLIGENT SERVICE ligent service check list,				
1.00	FILTER PACKAGE			64.6	35	64.65
1.00	FILTER CARTRIDGE			150.7	77	150.77
1.00	AIR FILTER ELEMENT			130.5	54 <i>'</i>	130.54
2.00	AIR FILTER			57.8	33	115.66
1.00	SCREW PLUG			34.6	31	34.61
1.00	DUST FILTER			86.5	55	86.55
1.00	TS FUEL FILTER			179.8	30	179.80
42.00	ENGINE - ALLIANCE PRIM	E ENGINE GLOBAL 10W40		8.0)3 (337.26
4.50	CONSUMABLES			7.2	25	32.63
42.00	HAZ WASTE & ENVIRO DIS	SPOSAL		0.4	10	16.80
0.40	COMPLEX GREASE - A001	1989405109		33.4	17	13.39

Sisid: RA92100	0633:01 Total : \$398.68	Date Invoice : 05/25/2022	Odomln:	308,426	OdomOut:	308,426
		Sold Operations				
Opsld : Cause :	1 Job: 00	CARRY OUT 300K SERVICE				
Correction	: CARRIED OUT INSF	PECTION SERVICE AS REQUIRED.				
1.00	WORKSHOP SUNDRIES			1	17.64	17.64
1.00	Grease -ALLIANCE AFX2	GREASE-450g CARTRIDGE		1	14.65	14.65
0.40	Complex grease			3	33.47	13.39

SIsId: RA920036319 Total: \$289.00 Date Invoice : IN SHOP Odomln: 0 OdomOut: 0

Sold Operations

R & R BATTERIES OpsId: 1 Job: 99

1.00 Adjust Parts Cost [[Warranty Only]]

Cause: Correction:

SIsId: RA920034379:03 Total: \$1,992.94 Date Invoice: 05/27/2025 Odomln: 844,937 OdomOut: 844,937

194727

473909C0594827

VIN W1T96342420483763

 YEAR
 MAKE
 MODEL
 IN SERVICE

 2021
 MB
 ACTROS
 29/04/2021

Sold Operations

Opsid: 2 Job: 00 BATTERIES NEED REPLACING

Cause: Done CP

Correction: C - BATTERIES NEED REPLACING

2.00 **ELECTRICAL SYSTEM BATTERY** 911.47 1,822.94

SIsId: RA920034379:02 Total: \$340.00 Date Invoice: 05/27/2025 OdomIn: 844,937 OdomOut: 844,937

Sold Operations

Opsid: 1 Job: 00 ROADWORTHY INSPECTION WITH LIST/COST OF WORKS REQUIRED

Cause:

Correction: C - ROADWORTHY INSPECTION WITH LIST/COST OF WORKS REQUIRED

SISId: RA920034379:01 Total: \$463.72 Date Invoice: 05/23/2025 OdomIn: 844,937 OdomOut: 844,937

Sold Operations

OpsId: 3 Job: 79 SM3311 Replace coolant thermostat 30976

Cause: Done CP

Correction: Brought the vehicle from the front gate

1.00 **THERMOSTAT** 222.18 222.18

1.00 ELASTOMERIC MOLDED SEAL 12.41 12.41

SISId: RA920020047:05 Total: \$1,421.54 Date Invoice: 03/25/2024 OdomIn: 736,920 OdomOut: 736,920

Sold Operations

Opsid: 7 Job: 54 APPLY FOR ESKULAB - BATTERY BRACKETS CRACKED AGAIN - REP

Cause: ESK-322314 SUBMITTED AND DECLINED Correction: C.BATTERY BRACKETS CRACKED

1.00 **BRKT BTTRY RGT SPPRT FR** 570.77

1.00 **BRKT BTTRY LFT SPPRT LF** 570.77

SISId: RA920020047:04 Total: -\$1,063.72 Date Invoice: 02/10/2024 OdomIn: 736,920 OdomOut: 736,920

Sold Operations

Opsld: 10 Job: 88 CORE REFUNDS

Cause : Correction :

-1.00 **CORE - DUAL-PLATE DRY CLUTCH** 869.52 -869.52

-1.00 **CORE - RELEASE BEARING** 194.20 -194.20

SISId: RA920020047:03 Total: \$1,969.05 Date Invoice: 02/10/2024 OdomIn: 736,920 OdomOut: 736,920

194727

OpsId:

473909C0594827

VIN W1T96342420483763

162.66

162.66

YEAR	MAKE	MODEL	IN SERVICE
2021	MB	ACTROS	29/04/2021

		Sold Operations
2	Job: 79	RECALL - FLASH MCM

Cause: done
Correction: C:Recall

Opsld: 8 Job: 18 SUMP LEAK

Cause: done

1.00 GASKET

Correction: C. CHECK ENGINE FOR OIL LEAKS

1.00	SCREW PLUG	38.25	38.25
0.00	Bay 6	0.00	0.00
1.00	MB GASKET SEALANT	65.78	65.78
1.00	ROCKER COVER SEAL DD13/15	97.45	97.45
0.00	Gearbox Bay	0.00	0.00
1.00	OIL FILLER PIPE	69.69	69.69
1.00	IN FREIGHT 2006	25.00	25.00

Opsid: 9 Job: 18 NO. 2 AND NO . 3 INJECTOR TUBES/SEALS LEAKING

Cause: done

Correction: c. Check engine for oil leaks

 2.00
 HIGH-PRESSURE LINE (1-2-3)
 180.59
 361.18

 2.00
 METAL SEAL
 30.59
 61.18

 -1.00
 Adjust Parts Price [[Warranty Only]]
 17.64
 -17.64

SIsId: RA920020047:02 Total: \$0.00 Date Invoice: 02/09/2024 OdomIn: 736,920 OdomOut: 736,920

SIsId: RA920020047:01 Total: \$11,431.26 Date Invoice: 02/09/2024 OdomIn: 736,920 OdomOut: 736,920

eempenene eena manie

VIN V1T96342420483763

194727

473909C0594827

 YEAR
 MAKE
 MODEL
 IN SERVICE

 2021
 MB
 ACTROS
 29/04/2021

		2021	MB	ACTROS	29/04/2021	
		Sold Operations				
Opsld : Cause :	1 Job : 54 done	AFTERTREATMENT WAR			/EN AFTER CI	LE
Correction		soiled and main adblue filter	safety valve abou	ut to pop		
1.00	KIT ADBLUE FILTER				32.72	32.72
1.00	ADBLUE FILTER ELEMEN	Т			176.13	176.13
0.00	ex gold coast?				0.00	0.00
OpsId : Cause : Correction :	6 Job : 25 done C: EST - CLUTCH	EST - CLUTCH				
1.00	DUAL-PLATE DRY CLUTC	Н		4,	,926.43	4,926.43
1.00	CORE - DUAL-PLATE DRY	CLUTCH			869.52	869.52
1.00	CORE MUST BE CLEANED	AND RETURNED IN ORGIN	IAL PACKAGING	i	0.00	0.00
1.00	RELEASE BEARING			2,	,154.18	2,154.18
1.00	SEAL RING				8.72	8.72
1.00	RADIAL SHAFT SEALING	RING			109.49	109.49
1.00	ANNULAR BALL BEARING	3			104.26	104.26
1.00	UNION SCREW				7.10	7.10
1.00	BLEEDER VALVE				122.71	122.71
0.00	ALL PARTS IN STOCK				0.00	0.00
0.00	outside back counter offic	e			0.00	0.00
Opsid:	10 Job : 01 done	oil filler tube leaking				

Correction: C. oil filler tube leaking

d: RA920000	758:01 Total : \$845.00	Date Invoice : 05/23/2022	Odomln:	267,353	OdomOut:	267,353
		Sold Operations				
Opsld:	1 Job: BDA	ATTEND BREAKDOWN AFTERH	OURS			
Cause :	AIR LINE SPLIT ON A	44 BRAKE CIRCUIT				
Correction:	DROVE FROM YAMA	ANTO TO FOREST LAKE - LOCATE	D VEHICLE			
30.00	KMS TRAVELLED			2	2.00	60.00
1.00	A/HOURS CALL OUT			185	5.00 1	85.00