

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Vehicle Notes :**

9/09/2021 12:00:00AM RO#: M108529 DATE: 09/09/2021 CUST: PB18 PTY LMTD ODOM: 1120 TOTAL: \$9852.84 ADVISOR: Peter Boys  
 BRANCH: 447MB SALE TYPE: |||||

OP\_CODES  
 88MB0000|88MBZZZZZA|88MBZZZZZB|43MBZZZZZA|40MBCOVERS|72MBZZZZZA|54MBZZZZZA|82MBZZZZZ  
 ZA|82MBZZZZZB

OP\_DESC  
 exterior trim|||CHROME HUB & NUT COV||ELECTRICAL REPAIRS 4||

COMPLAINT  
 SUPPLY AND FIT JOST JSK37 GREASLESS TURNTABLE|SUPPLY AND FIT ALLOY WALK PLATE|SUPPLY AND FIT  
 BLACK PLASTIC MUDGUARDS^ON CHROME POLES AITH PLASTIC GUARD MOUNTS^LOOP KITS, DTB  
 MUDFLAPS TO REAR WITH MARKER PLATES^TAIL LAMP BRACKETS|AIR AND ELECTRICS TO POGO

CAUSE  
 |||||

CORRECTION  
 |||||

9/09/2021 12:00:00AM RO#: M108530 DATE: 09/09/2021 CUST: PB18 PTY LMTD ODOM: 1116 TOTAL: \$2238.64 ADVISOR: Peter Boys  
 BRANCH: 447MB SALE TYPE: |||

OP\_CODES  
 00MB10ZZPD|40MBZZZZZA

OP\_DESC  
 CARRY OUT PRE-DELIVE|carry out wheel align

COMPLAINT  
 |FRONT AND REAR ALIGNMENT - NO AXLE BEND

CAUSE  
 |

CORRECTION  
 |

30/09/2021 12:00:00AM RO#: M109006 DATE: 30/09/2021 CUST: PB18 PTY LMTD ODOM: 1125 TOTAL: \$611.22 ADVISOR: Peter Boys  
 BRANCH: 447MB SALE TYPE: I

OP\_CODES  
 91MBZZZZZB

OP\_DESC

COMPLAINT  
 SUPPLY AND FIT SEAT COVERS^SUPPLY RUBBER FLOOR MATS

CAUSE

CORRECTION

5/10/2021 12:00:00AM RO#: M109042 DATE: 05/10/2021 CUST: PB18 PTY LMTD ODOM: 1130 TOTAL: \$552.96 ADVISOR: Peter Boys  
 BRANCH: 447MB SALE TYPE: I

OP\_CODES  
 67MB10ZZ000099

OP\_DESC  
 WINDOWS

COMPLAINT  
 SUPPLY AND FIT WINDSCREEN STONE GUARD

CAUSE

CORRECTION

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

14/10/2021 12:00:00AM RO#: M109262 DATE: 14/10/2021 CUST: PB18 PTY LMTD ODOM: 1200 TOTAL: \$2344.38 ADVISOR: Peter Boys  
BRANCH: 447MB SALE TYPE: I||||

## OP\_CODES

54MBZZZZZA|91MBZZZZZB|88MBZZZZZA

## OP\_DESC

ELECTRICAL REPAIRS 4||

## COMPLAINT

SUPPLY AND FIT ROUND DRIVING LIGHTS TO BULBAR|SUPPLY AND FIT SEAT COVERS IF NOT FITTED|SUPPLY  
AND FIT 1KG FIRE EXTINGUISHER TO R/H SEAT BASE

## CAUSE

requested||requested

## CORRECTION

||

18/11/2021 12:00:00AM RO#: M110080 DATE: 18/11/2021 CUST: PB18 PTY LMTD ODOM: 45100 TOTAL: \$219.11 ADVISOR: Kristie Scott  
BRANCH: 447MB SALE TYPE: M

## OP\_CODES

00MB10ZZSTDSE

## OP\_DESC

STANDARD SERVICE

## COMPLAINT

CARRY OUT SERVICE.;

## CAUSE

DC - 21118SV^00530602 1.0 Perform Annual Inspection^00503501 0.2 General Telligent maintenance lubrication Perform

## CORRECTION

-Carried out inspection service as per service sheet:^-Greased vehicle, topped up washer fluid and engine oil,  
replaced^service sticker, carried out and printed initial and final quick^tests and printed the vehicle data sheet^-Replaced  
RHF fog light bulb.

2/02/2022 12:00:00AM RO#: M111900 DATE: 02/02/2022 CUST: PB18 PTY LMTD ODOM: 89187 TOTAL: \$1515.90 ADVISOR: Kristie Scott  
BRANCH: 447MB SALE TYPE: M

## OP\_CODES

00MB10ZZSTDSE

## OP\_DESC

STANDARD SERVICE

## COMPLAINT

CARRY OUT SERVICE

## CAUSE

DC 21120SV^00500002 0.7 Engine filter change Perform^00504101 0.5 Fuel filter^00525801 0.2 Fuel filter element water  
separator^00506001 2.2 General Telligent maintenance: Adjust valve clearance^on engine with 5 setting screws per  
cylinder^005300532001 0.7

## CORRECTION

C: CARRY OUT SERVICE^C: Service due^C: Ordered parts^drove truck onto pit^checked lights^jacked  
cabover^inspected truck^filled out extra work sheet^dropped oil^opened tappet cover^carried out top tune^applied new  
tappet cover gasket ^reinstalled tappet co

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

28/02/2022 12:00:00AM RO#: M18238 DATE: 28/02/2022 CUST: PB 18 PTY LTD ODOM: 111152 TOTAL: \$1761.02 ADVISOR: BRANCH:  
223DM SALE TYPE: W

OP\_CODES  
00FLBDOWN

OP\_DESC  
ATTEND BREAKDOWN

COMPLAINT  
ATTEND BREAKDOWN AND INVESTIGATE CUSTOMER COMPLAINT OF^GENERATOR WARNING LIGHT ON DASH  
AND BATTERY WARNING LIGHT ON^DASH^28.02.22 Outbound time 00.00am - 00.45am^28.02.22 Repair time  
00.45am - 02.00am^28.02.22 Inbound travel 02.00am - 02.30am

CAUSE  
Alternator short to ground^DAMAGE CODE 1510173^15503001 1.2 Alternator Remove/install^15507601 0.1 Alternator  
Exchange (with alternator removed)^00962701 1.3 Brkdown assist.: Mechanic travel to/from^00963601 0.6 Breakdown  
assistance: 25% supplement

CORRECTION  
Connected xentry and completed quick test and found alternator^short to ground. Checked wiring to actuator - all ok.  
Found^alternator no charging batteries. Removed belts, intake pipes and^disconnected batteries. Removed and replaced  
alternator. Refit^bel

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

## Repair Order History

AmtPriceExtended

SlsId : RA971001304:01 Total : \$36.00

Date Invoice : 06/30/2023

OdomIn: 454,701

OdomOut: 454,701

## Sold Operations

OpsId : 1 Job : 00 CHECK AND REPORT ON ENGINE LIGHT ON DASH  
 Cause :  
 Correction : connected xentry found fault for sensor miss reading carried out tests

SlsId : RA971001301:01 Total : \$1,972.41

Date Invoice : 06/29/2023

OdomIn: 454,636

OdomOut: 454,636

## Sold Operations

OpsId : 1 Job : 00 CHECK AND REPORT ON BATTERY FAULT ON DASH  
 Cause : -Internal electrical failure of Alternator causing alternator to not charge batteries  
 Correction : -Check vehicle and confirm battery low voltage warning light on dash, connected

|       |              |          |          |
|-------|--------------|----------|----------|
| 1.00  | ALTERNATOR   | 1,689.09 | 1,689.09 |
| 1.00  | CORE DEPOSIT | 286.60   | 286.60   |
| -1.00 | CORE DEPOSIT | 286.60   | -286.60  |

SlsId : RA920036393 Total : \$170.00

Date Invoice : IN SHOP

OdomIn: 0

OdomOut: 0

## Sold Operations

OpsId : 1 Job : 99 R & R BATTERIES  
 Cause :  
 Correction :

SlsId : RA920032911:01 Total : \$855.00

Date Invoice : 05/21/2025

OdomIn: 827,057

OdomOut: 827,057

## Sold Operations

OpsId : 1 Job : ASR Compression test  
 Cause :  
 Correction : Complaints - Compression test

OpsId : 2 Job : ASR Check Trans Faults  
 Cause :  
 Correction : C - Check Trans Faults

OpsId : 3 Job : ASR Carry out check over  
 Cause :  
 Correction : C - Carry out check over

SlsId : RA920030898:01 Total : \$1,704.53

Date Invoice : 03/03/2025

OdomIn: 790,973

OdomOut: 790,973

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 1 Job : 13 AC COMPRESSOR NOT ENGAGING

Cause :

Correction :

|       |                                                        |          |          |
|-------|--------------------------------------------------------|----------|----------|
| 1.00  | REFRIGERANT COMPRESSOR                                 | 1,704.23 | 1,704.23 |
| 1.00  | CORE - REFRIGERANT COMPRESSOR                          | 310.98   | 310.98   |
| 0.00  | CORE MUST BE CLEANED AND RETURNED IN ORGINAL PACKAGING | 0.00     | 0.00     |
| -1.00 | CORE - REFRIGERANT COMPRESSOR                          | 310.98   | -310.98  |
| 1.00  | Adjust Parts Price [[Warranty Only]]                   | 0.30     | 0.30     |

SlId : RA920030896:01 Total : \$1,704.53 Date Invoice : 02/13/2025 OdomIn: 787,361 OdomOut: 790,973

**Sold Operations**

OpsId : 1 Job : 13 PARTS WARRANTY

Cause :

Correction : COMPRESSOR SEIZED;

|       |                                                        |          |          |
|-------|--------------------------------------------------------|----------|----------|
| 1.00  | REFRIGERANT COMPRESSOR                                 | 1,704.53 | 1,704.53 |
| 1.00  | CORE - REFRIGERANT COMPRESSOR                          | 310.98   | 310.98   |
| 0.00  | CORE MUST BE CLEANED AND RETURNED IN ORGINAL PACKAGING | 0.00     | 0.00     |
| -1.00 | CORE - REFRIGERANT COMPRESSOR                          | 310.98   | -310.98  |

SlId : RA920027681:01 Total : \$199.54 Date Invoice : 10/29/2024 OdomIn: 744,390 OdomOut: 744,390

**Sold Operations**

OpsId : 2 Job : 99 WIPER BLADES SMEARING

Cause : Done CP

Correction : Remove and replaced wiper blades.

|      |                                                           |        |        |
|------|-----------------------------------------------------------|--------|--------|
| 1.00 | PARTS KIT WIPER BLADE                                     | 72.93  | 72.93  |
| 1.00 | PNEUMATIC SPRING                                          | 101.61 | 101.61 |
| 0.00 | CLAYTONS RACK                                             | 0.00   | 0.00   |
| 0.00 | CONTRACT EXPIRED - WORKS NOT APPROVED BY CUSTOMER. REWORK | 0.00   | 0.00   |

SlId : RA920027016:02 Total : \$7,323.67 Date Invoice : 10/18/2024 OdomIn: 735,059 OdomOut: 735,059

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 1 Job : 79 Thermostat Recall

Cause : Done CP

Correction : C - thermostat recall

|      |                                             |        |        |
|------|---------------------------------------------|--------|--------|
| 1.00 | <b>THERMOSTAT</b>                           | 213.63 | 213.63 |
| 1.00 | <b>SEAL</b>                                 | 16.31  | 16.31  |
| 0.00 | <b>Clayton's Desk</b>                       | 0.00   | 0.00   |
| 1.00 | <b>Adjust Parts Price [[Warranty Only]]</b> | 0.01   | 0.01   |

OpsId : 3 Job : 20 LEAKING COOLANT FROM HEAD

Cause :

Correction : C: PASSED SNIFF TEST

|       |                                |       |        |
|-------|--------------------------------|-------|--------|
| 0.00  | <b>sTAGING rOOM</b>            | 0.00  | 0.00   |
| 2.00  | <b>TITAN PSF</b>               | 11.00 | 22.00  |
| -1.00 | <b>PART NOT IN HEAD REPAIR</b> | 22.00 | -22.00 |

OpsId : 5 Job : 01 LEAKING COOLANT FROM ENGINE

Cause :

Correction : C: HEAD GASKET BLOWN OUT/LOST TENSION AROUND COOLANT PORTS ALLOWING COO

|       |                                             |        |        |
|-------|---------------------------------------------|--------|--------|
| 1.00  | <b>SEAL CYLINDER HEAD COVER</b>             | 106.97 | 106.97 |
| 3.00  | <b>HIGH PRESSURE LINE</b>                   | 192.23 | 576.69 |
| 3.00  | <b>HIGH PRESSURE LINE</b>                   | 212.35 | 637.05 |
| 6.00  | <b>METAL SEAL</b>                           | 32.01  | 192.06 |
| 1.00  | <b>CIRCUMFERENTIAL SEAL</b>                 | 74.16  | 74.16  |
| 4.00  | <b>HEX HEAD SCREW W FLANGE</b>              | 20.27  | 81.08  |
| 1.00  | <b>METAL SEAL</b>                           | 96.81  | 96.81  |
| 1.00  | <b>CYLINDER HEAD GASKET</b>                 | 663.70 | 663.70 |
| 10.00 | <b>SEALING RING</b>                         | 4.23   | 42.30  |
| 1.00  | <b>O RING</b>                               | 9.51   | 9.51   |
| 2.00  | <b>HIGH PRESSURE LINE</b>                   | 316.26 | 632.52 |
| 6.00  | <b>SEAL</b>                                 | 16.48  | 98.88  |
| 1.00  | <b>CIRCUMFERENTIAL SEAL</b>                 | 74.16  | 74.16  |
| 1.00  | <b>SEAL</b>                                 | 78.59  | 78.59  |
| 1.00  | <b>SEAL</b>                                 | 78.59  | 78.59  |
| 1.00  | <b>SEALING RING</b>                         | 4.07   | 4.07   |
| 1.00  | <b>Adjust Parts Price [[Warranty Only]]</b> | 16.58  | 16.58  |

SIsId : RA920027016:01 Total : \$8,452.54

Date Invoice : 09/30/2024

OdomIn: 735,059

OdomOut: 735,059

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 4 Job : 49

NOT DOING REGEN AND SHOWING UP WITH EGR FAULT

Cause :

Correction : C: EGR ACTUATOR MOTOR BINDING INTERNALLY DUE TO EXCESSIVE SHAFT MOVEMENT

|      |                     |          |          |
|------|---------------------|----------|----------|
| 1.00 | RECIRCULATION VALVE | 1,039.59 | 1,039.59 |
| 1.00 | ACTUATOR MOTOR      | 1,792.24 | 1,792.24 |
| 2.00 | HEXAGON NUT         | 12.65    | 25.30    |
| 4.00 | STUD BOLT           | 15.19    | 60.76    |
| 1.00 | METAL SEAL          | 45.67    | 45.67    |

OpsId : 6 Job : 49

EGR COOLER CRACKED AT REAR WELD - FOUND DURING ACTUATC

Cause :

Correction : C: WELD CRACKED DUE TO EXCESSIVE HEAT EXPOSURE AND MATERIAL FATIGUE

|      |                                      |          |          |
|------|--------------------------------------|----------|----------|
| 1.00 | EXH GAS RECIRC COOLER                | 3,830.15 | 3,830.15 |
| 2.00 | CONNECTING PIPE                      | 53.53    | 107.06   |
| 1.00 | CONNECTING PIPE                      | 53.53    | 53.53    |
| 1.00 | MOLDED HOSE                          | 153.12   | 153.12   |
| 1.00 | EXHAUST GAS HOSE                     | 74.61    | 74.61    |
| 0.00 | staging room                         | 0.00     | 0.00     |
| 1.00 | Adjust Parts Price [[Warranty Only]] | 0.01     | 0.01     |

SIId : RA920022500:01 Total : \$1,620.71

Date Invoice : 04/30/2024

OdomIn: 652,285

OdomOut: 652,285

**Sold Operations**

OpsId : 1 Job : 54

Check out headlight wiring -

Cause :

Correction : Cause:

|      |            |          |          |
|------|------------|----------|----------|
| 1.00 | LAMP UNIT  | 1,280.71 | 1,280.71 |
| 0.00 | STAGE ROOM | 0.00     | 0.00     |

SIId : RA920017472:03 Total : \$0.00

Date Invoice : 01/12/2024

OdomIn: 562,686

OdomOut: 562,686

**Sold Operations**

OpsId : 1 Job : 54

BATTERY BOX MOUNTS CRACKED - PARTS ORDERED

Cause : Done JR

Correction : C - no batteries box mounts cracked

|      |                        |        |      |
|------|------------------------|--------|------|
| 0.00 | BRKT BTTRY LFT SPRT LF | 543.23 | 0.00 |
| 0.00 | BRKT BTTRY RGT SPRT FR | 543.23 | 0.00 |
| 0.00 | Staging Room           | 0.00   | 0.00 |

OpsId : 2 Job : 60

WASHER JETS NOP - ORDERED WASHER MOTOR IN CASE ITS REQI

Cause : Done JR

Correction : C - wiper washer hoses twisted and R/h plastic halfway out

|      |      |        |      |
|------|------|--------|------|
| 0.00 | PUMP | 323.51 | 0.00 |
|------|------|--------|------|

SIId : RA920017472:02 Total : \$165.00

Date Invoice : 12/28/2023

OdomIn: 562,686

OdomOut: 562,686

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 3 Job : 99 Miscellaneous  
 Cause :  
 Correction :

SlsId : RA920017472:01 Total : \$2,908.01 Date Invoice : 12/08/2023 OdomIn: 562,686 OdomOut: 562,686

**Sold Operations**

OpsId : 3 Job : 00 CARRY OUT SERVICE AS PER DATA SHEET & HISTORY  
 Cause :  
 Correction : C - carry out service as per data sheet & history

|       |                                                                |        |        |
|-------|----------------------------------------------------------------|--------|--------|
| 1.00  | <b>FILTER PACKAGE</b>                                          | 99.99  | 99.99  |
| 1.00  | <b>ROCKER COVER SEAL DD13/15</b>                               | 137.99 | 137.99 |
| 1.00  | <b>TS FUEL FILTER</b>                                          | 274.99 | 274.99 |
| 1.00  | <b>SEPERATOR FILTER CARTRIDGE</b>                              | 237.49 | 237.49 |
| 1.00  | <b>SCREW PLUG</b>                                              | 46.39  | 46.39  |
| 2.00  | <b>AIR FILTER</b>                                              | 87.99  | 175.98 |
| 1.00  | <b>DUST FILTER</b>                                             | 128.99 | 128.99 |
| 0.00  | <b>pit 1</b>                                                   | 0.00   | 0.00   |
| 42.00 | <b>ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40</b>             | 14.20  | 596.40 |
| 1.00  | <b>HAZ WASTE &amp; ENVIRO DISPOSAL</b>                         | 27.50  | 27.50  |
| 1.00  | <b>GREASE - ALLIANCE AFX2 GREASE (180KG) - QABP AFM4215180</b> | 17.89  | 17.89  |
| 0.40  | <b>GREASE - COMPLEX (400G) - A001989405109</b>                 | 60.99  | 24.40  |

SlsId : RA920016673:01 Total : \$1,346.94 Date Invoice : 10/20/2023 OdomIn: 521,735 OdomOut: 521,735

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 1 Job : 00

CARRY OUT SERVICE AS PER DATA SHEET &amp; HISTORY

Cause :

Correction : cause -

|      |                                                                      |        |        |
|------|----------------------------------------------------------------------|--------|--------|
| 1.00 | TS WIPER BLADE                                                       | 89.99  | 89.99  |
| 1.00 | BULB P21/5W 24V                                                      | 4.96   | 4.96   |
| 1.00 | BULB H/BEAM H1 24V/70W                                               | 17.99  | 17.99  |
| 0.00 | Pit 2                                                                | 0.00   | 0.00   |
| 1.00 | AIR FILTER INSERT                                                    | 417.27 | 417.27 |
| 1.00 | BULB H/BEAM H1 24V/70W                                               | 17.99  | 17.99  |
| 0.00 | PIT 2                                                                | 0.00   | 0.00   |
| 5.50 | ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (PUMP-IN) - QABP AFM4    | 7.82   | 43.01  |
| 1.00 | GREASE - ALLIANCE AFX2 GREASE (180KG) - QABP AFM4215180              | 13.97  | 13.97  |
| 1.10 | GEAR OIL - ALLIANCE PRIME AXLE PLUS 235.8 75W90 (205L) - QABP AFM461 | 18.30  | 20.13  |
| 1.00 | Credit Card Surcharge   RA920016673                                  | 9.63   | 9.63   |

OpsId : 3 Job : 15

CARRY OUT DPF BURN - PREVENTATIVE MAINTENANCE

Cause :

Correction : cause -

SIsId : RA920014984:03 Total : \$585.07

Date Invoice : 08/25/2023

OdomIn: 485,100

OdomOut: 485,100

**Sold Operations**

OpsId : 4 Job : 18

DIAGNOSE &amp; REPAIR - DRIVE BELTS CRACKED BADLY

Cause :

Correction : C- DRIVE BELTS CRACKED BADLY

|      |                                     |        |        |
|------|-------------------------------------|--------|--------|
| 1.00 | V-RIBBED BELT 2642MM                | 183.99 | 183.99 |
| 1.00 | V-RIBBED BELT 1493 MM               | 96.99  | 96.99  |
| 0.00 | PIT 1                               | 0.00   | 0.00   |
| 1.00 | Credit Card Surcharge   RA920014984 | 4.09   | 4.09   |

OpsId : 5 Job : 14

DIAGNOSE &amp; REPAIR - EGR CROSS OVER HOSE SPLIT

Cause : Related to Job 1.

Correction :

**Rejected Operations**

OpsId : 2 Job : 99

EWS

Cause :

Correction :

SIsId : RA920014984:02 Total : \$314.74

Date Invoice : 08/21/2023

OdomIn: 485,100

OdomOut: 485,100

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 1 Job : EA DIAGNOSE &amp; REPORT - WHISTLING NOISE WHEN IN MOTION

Cause : Done JB

Correction : C: check and report on whistling noise when in motion and crack in belt

|      |                           |       |       |
|------|---------------------------|-------|-------|
| 1.00 | EXHAUST GAS HOSE          | 69.00 | 69.00 |
| 2.00 | CLAMP MBN 10272-A- 45- 65 | 7.37  | 14.74 |

SIsId : RA920014984:01 Total : \$2,768.00

Date Invoice : 08/17/2023

OdomIn: 485,100

OdomOut: 485,100

**Sold Operations**

OpsId : 3 Job : 00 CARRY OUT SERVICE AS PER DATA SHEET &amp; HISTORY

Cause : Done JB

Correction : C- CARRY OUT SERVICE AS PER DATA SHEET &amp; HISTORY

|       |                                                                    |          |           |
|-------|--------------------------------------------------------------------|----------|-----------|
| 1.00  | FILTER PACKAGE                                                     | 69.95    | 69.95     |
| 1.00  | TS FUEL FILTER                                                     | 193.07   | 193.07    |
| 1.00  | FILTER CARTRIDGE                                                   | 165.54   | 165.54    |
| 1.00  | SCREW PLUG                                                         | 36.50    | 36.50     |
| 1.00  | DUST FILTER                                                        | 90.62    | 90.62     |
| 2.00  | SEALING RING                                                       | 3.50     | 7.00      |
| 1.00  | TS WIPER BLADE                                                     | 62.73    | 62.73     |
| 1.00  | TS DPF                                                             | 832.69   | 832.69    |
| 1.00  | CORE DEPOSIT                                                       | 1,942.95 | 1,942.95  |
| 0.00  | PIT 1                                                              | 0.00     | 0.00      |
| 0.00  | GEAR OIL - ALLIANCE PRIME TRANS PLUS MB 75W90 (PUMP-IN) - QABP AFM | 0.00     | 0.00      |
| 0.00  | ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (PUMP-IN) - QABP AFM4  | 0.00     | 0.00      |
| 1.00  | WORKSHOP SUNDRIES                                                  | 32.65    | 32.65     |
| 1.00  | HAZ WASTE & ENVIRO DISPOSAL                                        | 21.20    | 21.20     |
| 41.00 | ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (1000L) - QABP AFM498: | 7.82     | 320.62    |
| 12.00 | GEAR OIL - ALLIANCE PRIME TRANS PLUS MB 75W90 (205L) - QABP AFM430 | 22.15    | 265.80    |
| -1.00 | CORE DEPOSIT                                                       | 1,942.95 | -1,942.95 |
| 0.40  | GREASE - COMPLEX (400G) - A001989405109                            | 54.29    | 21.72     |
| -4.72 | Adjust Parts Cost [[Warranty Only]]                                | 1.00     | -4.72     |

SIsId : RA920012963:02 Total : \$4,221.92

Date Invoice : 06/22/2023

OdomIn: 445,332

OdomOut: 445,332

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 4 Job : EA REPORT AND DIAGNOSE - MAY HAVE CLUTCH ISSUE - TRUCK JERKI  
 Cause : clutch actuator internal seal split and failed clutch actuator test  
 Correction : C:

|       |                                     |          |          |
|-------|-------------------------------------|----------|----------|
| 1.00  | RING,GENERAL,METAL                  | 2.65     | 2.65     |
| 1.00  | BLEEDER VALVE                       | 112.75   | 112.75   |
| 1.00  | UNION SCREW                         | 6.53     | 6.53     |
| 1.00  | SEAL RING                           | 7.95     | 7.95     |
| 1.00  | RELEASE BEARING CLUTCH              | 2,010.09 | 2,010.09 |
| 0.00  | @@CORE@@ - A0032502115              | 0.00     | 0.00     |
| 2.00  | ENGINE SUPPORT                      | 478.00   | 956.00   |
| 0.00  | HCV BAY 11                          | 0.00     | 0.00     |
| -1.00 | CORE DEPOSIT                        | 232.06   | -232.06  |
| -1.00 | Adjust Parts Cost [[Warranty Only]] | 27.99    | -27.99   |

SIsId : RA920012963:01 Total : \$467.45

Date Invoice : 06/22/2023

OdomIn: 445,332

OdomOut: 445,332

**Sold Operations**

OpsId : 1 Job : 00 CARRY OUT SERVICE AS PER HISTORY AND DATA SHEET  
 Cause : inspection service due  
 Correction : correction -

|       |                                                                      |       |       |
|-------|----------------------------------------------------------------------|-------|-------|
| 1.00  | TS WIPER BLADE                                                       | 62.36 | 62.36 |
| 0.00  | DELIVER TO PIT#1                                                     | 0.00  | 0.00  |
| 0.50  | COOLANT - ALLIANCE PRIMECOOL GP P-40 (5L) - QABP AFM4604005          | 7.21  | 3.61  |
| 0.50  | GEAR OIL - ALLIANCE PRIME TRANS PLUS MB 75W90 (PUMP-IN) - QABP AFM   | 22.16 | 11.08 |
| 0.70  | GEAR OIL - ALLIANCE PRIME AXLE PLUS 235.8 75W90 (PUMP IN) - QABP AFM | 24.99 | 17.49 |
| 1.00  | MISC SHOP SUPPLIES                                                   | 15.00 | 15.00 |
| -1.00 | Adjust Parts Cost [[Warranty Only]]                                  | 4.66  | -4.66 |

SIsId : RA920011063:03 Total : \$0.00

Date Invoice : 05/10/2023

OdomIn: 407,835

OdomOut: 407,835

**Rejected Operations**

OpsId : 4 Job : 99 ESTIMATE FOR REPAIRS  
 Cause :  
 Correction :

|      |                          |           |           |
|------|--------------------------|-----------|-----------|
| 1.00 | ENGINE 630HP             | 49,777.49 | 49,777.49 |
| 1.00 | CORE DEPOSIT             | 12,304.99 | 12,304.99 |
| 0.00 | in stock - WARRANTY ONLY | 0.00      | 0.00      |
| 1.00 | COOLANT RADIATOR         | 2,159.99  | 2,159.99  |
| 1.00 | CHARGE AIR COOLER, AIR   | 2,917.49  | 2,917.49  |
| 2.00 | FULL FACE GASKET         | 21.89     | 43.78     |
| 2.00 | FULL FACE GASKET         | 28.59     | 57.18     |
| 2.00 | FULL FACE GASKET         | 20.79     | 41.58     |

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

SlsId : RA920011063:02    Total : \$15,921.17

Date Invoice : 05/06/2023

OdomIn: 407,835

OdomOut: 407,835

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 1 Job : 60 RECTIFY BATTERY BOX BRACKETS BROKEN

Cause : Battery box brackets snapped due to stress fractures

Correction : COMPLAINT;

|       |                                     |        |        |
|-------|-------------------------------------|--------|--------|
| 0.00  | STAGING ROOM                        | 0.00   | 0.00   |
| 1.00  | BRKT BTTRY RGT SPPRT FR             | 522.76 | 522.76 |
| 1.00  | BRKT BTTRY LFT SPPRT LF             | 522.76 | 522.76 |
| 1.00  | RETAINING STRAP                     | 31.06  | 31.06  |
| 1.00  | BRACKET                             | 251.31 | 251.31 |
| 1.00  | BULB                                | 2.07   | 2.07   |
| -1.00 | Adjust Parts Cost [[Warranty Only]] | 2.07   | -2.07  |

OpsId : 3 Job : 20 CHECK &amp; REPORT ON COOLANT LEVEL LOW WARNING ON THE DAS

Cause : Exhaust gases in cooling system, due to block and head being warped

Correction : TIPS CASE# 515326504

|      |                           |          |          |
|------|---------------------------|----------|----------|
| 1.00 | PROTECTIVE COVER          | 4.73     | 4.73     |
| 1.00 | PROTECTIVE COVERS         | 6.17     | 6.17     |
| 1.00 | PROTECTIVE COVER          | 11.71    | 11.71    |
| 1.00 | SET, PROTECTIVE COVERS    | 33.16    | 33.16    |
| 1.00 | CYLINDER HEAD OM473       | 6,250.21 | 6,250.21 |
| 1.00 | CORE DEPOSIT              | 1,046.27 | 1,046.27 |
| 0.00 | stock                     | 0.00     | 0.00     |
| 6.00 | TWELVE-POINT HEAD BOLT    | 3.57     | 21.42    |
| 6.00 | O-RING                    | 5.98     | 35.88    |
| 6.00 | O-RING                    | 7.25     | 43.50    |
| 6.00 | O-RING                    | 14.42    | 86.52    |
| 6.00 | SEALING RING              | 9.85     | 59.10    |
| 6.00 | GASKET                    | 17.13    | 102.78   |
| 3.00 | HIGH-PRESSURE LINE        | 106.72   | 320.16   |
| 3.00 | HIGH-PRESSURE LINE        | 189.05   | 567.15   |
| 1.00 | ROCKER COVER SEAL DD13/15 | 96.54    | 96.54    |
| 1.00 | GASKET, CIRCUMFERENTIAL   | 68.26    | 68.26    |
| 2.00 | HIGH-PRESSURE LINE        | 189.05   | 378.10   |
| 6.00 | GASKET                    | 15.20    | 91.20    |
| 1.00 | GASKET                    | 43.94    | 43.94    |
| 1.00 | SEAL                      | 264.06   | 264.06   |
| 1.00 | SEAL                      | 156.90   | 156.90   |
| 1.00 | GSK EXH COOLER CYL 1-3    | 72.22    | 72.22    |
| 1.00 | GSK EXH COOLER CYL 4-6    | 72.22    | 72.22    |
| 2.00 | SEAL RING, VLRUB          | 3.82     | 7.64     |
| 0.00 | all in stock              | 0.00     | 0.00     |
| 1.00 | CYLINDER HEAD GASKET      | 604.85   | 604.85   |
| 1.00 | METAL SEAL                | 89.27    | 89.27    |

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations (Cont.)**

|       |                                            |          |           |
|-------|--------------------------------------------|----------|-----------|
| 4.00  | <b>BOLT W FLANGE</b>                       | 18.27    | 73.08     |
| 1.00  | <b>IN FREIGHT 080</b>                      | 25.00    | 25.00     |
| -1.00 | <b>CORE DEPOSIT</b>                        | 1,046.27 | -1,046.27 |
| -1.00 | <b>Adjust Parts Cost [[Warranty Only]]</b> | 24.99    | -24.99    |

**Rejected Operations**

OpsId : 5 Job : 00 Quote cyl head replacement  
 Cause :  
 Correction :

SIsId : RA920011063:01 Total : \$131.13

Date Invoice : 04/28/2023

OdomIn: 407,835

OdomOut: 407,835

**Sold Operations**

OpsId : 6 Job : 00 PLEASE REPLACE DRIVE BELT  
 Cause : Belt fraying and starting to split  
 Correction : Dropped bull bar, and tilted cab, removed fan hub connector and P clamp, removed fan hub mount

|      |                             |        |        |
|------|-----------------------------|--------|--------|
| 1.00 | <b>V-RIBBED BELT 2642MM</b> | 131.13 | 131.13 |
|------|-----------------------------|--------|--------|

SIsId : RA920010272:03 Total : \$0.00

Date Invoice : 04/03/2023

OdomIn: 396,454

OdomOut: 396,454

**Rejected Operations**

OpsId : 3 Job : 99 EW found during service  
 Cause :  
 Correction :

|      |                            |          |          |
|------|----------------------------|----------|----------|
| 1.00 | <b>CU, DISTANCE SENSOR</b> | 6,827.49 | 6,827.49 |
| 0.00 | <b>EX MELB</b>             | 0.00     | 0.00     |
| 1.00 | <b>BRACKET</b>             | 447.49   | 447.49   |
| 1.00 | <b>MOLDING RIGHT</b>       | 94.99    | 94.99    |
| 1.00 | <b>FOG LAMP RH</b>         | 309.99   | 309.99   |

SIsId : RA920010272:02 Total : \$6,724.92

Date Invoice : 03/27/2023

OdomIn: 396,454

OdomOut: 396,454

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 2 Job : 25 PLEASE DIAGNOSE AND REPORT ON CLUTCH -

Cause :

Correction : Front clutch disc was siezed to the intermediate plate causing clutch drag

|       |                        |          |          |
|-------|------------------------|----------|----------|
| 1.00  | DUAL-PLATE DRY CLUTCH  | 5,000.97 | 5,000.97 |
| 1.00  | CORE DEPOSIT           | 882.67   | 882.67   |
| 0.00  | RELEASE BEARING CLUTCH | 2,010.09 | 0.00     |
| 0.00  | @@CORE@@ - A0032502115 | 0.00     | 0.00     |
| 1.00  | SEAL RING              | 7.95     | 7.95     |
| 0.00  | ANNULAR BALL BEARING   | 94.06    | 0.00     |
| 0.00  | HCV BAY 8              | 0.00     | 0.00     |
| -1.00 | CORE DEPOSIT           | 882.67   | -882.67  |

OpsId : 4 Job : 79 RECALL SOFTWARE UPDATE MCM

Cause : done pb

Correction : Complaint: Carry out MCM update

SlId : RA920010272:01 Total : \$1,755.10

Date Invoice : 03/24/2023

OdomIn: 396,454

OdomOut: 396,454

**Sold Operations**

OpsId : 1 Job : 00 SERVICE AS PER HISTORY

Cause : done pb

Correction : Correction:

|       |                                                                      |        |        |
|-------|----------------------------------------------------------------------|--------|--------|
| 1.00  | FILTER PACKAGE                                                       | 67.24  | 67.24  |
| 1.00  | TS FUEL FILTER                                                       | 186.99 | 186.99 |
| 1.00  | FILTER CARTRIDGE                                                     | 156.81 | 156.81 |
| 2.00  | AIR FILTER                                                           | 61.04  | 122.08 |
| 1.00  | DUST FILTER                                                          | 90.35  | 90.35  |
| 1.00  | TS WIPER BLADE                                                       | 62.36  | 62.36  |
| 1.00  | SCREW PLUG                                                           | 36.30  | 36.30  |
| 1.00  | ADD. TURN SIGNAL LAMP                                                | 112.06 | 112.06 |
| 0.00  | Staging Room                                                         | 0.00   | 0.00   |
| 40.00 | ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (PUMP-IN) - QABP AFM4    | 3.50   | 140.00 |
| 3.50  | GEAR OIL - ALLIANCE PRIME AXLE PLUS 235.8 75W90 (PUMP IN) - QABP AFI | 3.50   | 12.25  |

SlId : RA920008652:03 Total : \$218.68

Date Invoice : 03/17/2023

OdomIn: 373,007

OdomOut: 373,007

**Sold Operations**

OpsId : 7 Job : 01 DIAGNOSE BELTS SPLIT, TENSIONER OR PULLEY FAILURE?

Cause : Done JB

Correction : jacked over cab

|      |                      |        |        |
|------|----------------------|--------|--------|
| 1.00 | V-RIBBED BELT        | 91.99  | 91.99  |
| 1.00 | V-RIBBED BELT 2642MM | 126.69 | 126.69 |

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Rejected Operations**

OpsId : 3 Job : 99

EW FOUND DURING SERVICE

Cause :

Correction :

|      |                         |          |          |
|------|-------------------------|----------|----------|
| 1.00 | CU, DISTANCE SENSOR     | 4,699.85 | 4,699.85 |
| 1.00 | BRACKET                 | 324.82   | 324.82   |
| 1.00 | FOG LAMP RH             | 225.46   | 225.46   |
| 1.00 | TRANSMISSION COOLER     | 2,712.23 | 2,712.23 |
| 1.00 | COVER OUTSIDE RIGHT     | 73.13    | 73.13    |
| 1.00 | COVER BOTTOM RIGHT      | 33.02    | 33.02    |
| 1.00 | SEAT BELT               | 998.44   | 998.44   |
| 1.00 | SEAT BELT LOCK          | 161.01   | 161.01   |
| 1.00 | SPRING SHEET METAL LOCK | 1.69     | 1.69     |
| 0.00 | SMALL CLIP - BOTTOM     | 0.00     | 0.00     |
| 1.00 | MIRROR GLASS            | 212.46   | 212.46   |
| 1.00 | GAS PRESSURE STRUT      | 39.61    | 39.61    |

SIsId : RA920008652:02 Total : \$12,072.20

Date Invoice : 02/15/2023

OdomIn: 373,007

OdomOut: 373,007

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 2 Job : 32 CUSTOMER HAS NOTICED FRONT SHOCKS LEAKING  
 Cause : Done JB  
 Correction : Checked all both shocks absorbers and found front RH shock absorbers seal bypassing oil cause c

|        |                                            |        |        |
|--------|--------------------------------------------|--------|--------|
| 1.00   | <b>SHOCK ABSORBER</b>                      | 307.29 | 307.29 |
| -15.21 | <b>Adjust Parts Cost [[Warranty Only]]</b> | 1.00   | -15.21 |

OpsId : 5 Job : 54 CHECK & REPORT ON VEHICLE HARD TO START  
 Cause : Done JB  
 Correction :

|       |                                    |          |          |
|-------|------------------------------------|----------|----------|
| 1.00  | <b>STARTER MOTOR</b>               | 1,863.10 | 1,863.10 |
| 0.00  | <b>@@CORE ITEM@@ - A0071516201</b> | 0.00     | 0.00     |
| -1.00 | <b>CORE DEPOSIT</b>                | 369.13   | -369.13  |

OpsId : 6 Job : 27 TRANSMISSION CRUNCHING INTERMITTANTLY  
 Cause : Done JB  
 Correction :

|       |                                  |          |          |
|-------|----------------------------------|----------|----------|
| 1.00  | <b>DUAL-PLATE DRY CLUTCH</b>     | 4,700.97 | 4,700.97 |
| 1.00  | <b>CORE DEPOSIT</b>              | 882.67   | 882.67   |
| 1.00  | <b>ANNULAR BALL BEARING</b>      | 94.06    | 94.06    |
| 12.00 | <b>TWELVE-POINT HEAD BOLT</b>    | 11.74    | 140.88   |
| 1.00  | <b>RADIAL SHAFT SEALING RING</b> | 73.30    | 73.30    |
| 1.00  | <b>RELEASE BEARING CLUTCH</b>    | 1,876.14 | 1,876.14 |
| 0.00  | <b>@@CORE@@ - A0032502115</b>    | 0.00     | 0.00     |
| 1.00  | <b>SEAL RING</b>                 | 7.95     | 7.95     |
| 1.00  | <b>SEAL RING</b>                 | 26.88    | 26.88    |
| 1.00  | <b>SEAL RING</b>                 | 6.15     | 6.15     |
| 1.00  | <b>SEAL RING</b>                 | 1.12     | 1.12     |
| 1.00  | <b>SEAL RING</b>                 | 5.26     | 5.26     |
| 1.00  | <b>SEAL RING TRANS COVER</b>     | 9.97     | 9.97     |
| 1.00  | <b>BLEEDER VALVE</b>             | 112.75   | 112.75   |
| 0.00  | <b>HCV BAY 12</b>                | 0.00     | 0.00     |
| -1.00 | <b>CORE DEPOSIT</b>              | 882.67   | -882.67  |
| -1.00 | <b>CORE DEPOSIT</b>              | 232.06   | -232.06  |

OpsId : 8 Job : 33 A1 AXLE TIE ROD HAS EXCESSIVE MOVEMENT  
 Cause : Done JB  
 Correction :

|      |                           |        |        |
|------|---------------------------|--------|--------|
| 1.00 | <b>TIE ROD</b>            | 856.18 | 856.18 |
| 1.00 | <b>NUT</b>                | 14.20  | 14.20  |
| 2.00 | <b>NUT</b>                | 14.20  | 28.40  |
| 0.00 | <b>GAS PRESSURE STRUT</b> | 38.26  | 0.00   |
| 1.00 | <b>IN FREIGHT 7651</b>    | 25.00  | 25.00  |

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 1 Job : 00

CARRY OUT SERVICE AS PER DATA SHEET &amp; HISTORY

Cause : Done JB

Correction : moved onto pit

|       |                                                                    |       |       |
|-------|--------------------------------------------------------------------|-------|-------|
| 1.00  | TS WIPER BLADE                                                     | 62.36 | 62.36 |
| 0.00  | PREPICK                                                            | 0.00  | 0.00  |
| 6.00  | ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (1000L) - QABP AFM498: | 6.95  | 41.70 |
| 0.40  | GREASE- COMPLEX A0019894051 09                                     | 37.69 | 15.08 |
| 3.00  | COOLANT - ALLIANCE PRIMECOOL GP P-40 (205L) - QABP AFM4604205      | 5.16  | 15.48 |
| 1.00  | WORKSHOP SUNDRIES                                                  | 21.76 | 21.76 |
| -3.69 | Adjust Parts Cost [[Warranty Only]]                                | 1.00  | -3.69 |

SIsId : RA920008040:01 Total : \$1,352.08

Date Invoice : 12/15/2022

OdomIn: 350,649

OdomOut: 350,649

**Sold Operations**

OpsId : 1 Job : 83

AIR CON NOT WORKING AT ALL

Cause : A/C high pressure seal lost tension and lost oil/gas at A/C compressor discharge port

Correction : Short test

|      |                                     |        |        |
|------|-------------------------------------|--------|--------|
| 1.00 | REFRIGERANT DRIER                   | 304.46 | 304.46 |
| 2.00 | FULL FACE GASKET                    | 18.28  | 36.56  |
| 2.00 | FULL FACE GASKET                    | 13.65  | 27.30  |
| 0.00 | DELIVER TO EXP #2 - ADAM            | 0.00   | 0.00   |
| 1.00 | R134A AC GAS                        | 19.97  | 19.97  |
| 1.00 | Adjust Parts Cost [[Warranty Only]] | 0.02   | 0.02   |

OpsId : 2 Job : 00

PARK BRAKE WILL NOT APPLY

Cause : Park brake will not apply

Correction : Park out in yard and park brake will not apply

|      |                         |        |        |
|------|-------------------------|--------|--------|
| 1.00 | CONTROL LEVER           | 254.27 | 254.27 |
| 0.00 | DELIVER TO EXP#2 - ADAM | 0.00   | 0.00   |

SIsId : RA920007021:02 Total : \$758.45

Date Invoice : 11/24/2022

OdomIn: 319,615

OdomOut: 319,615

**Sold Operations**

OpsId : 3 Job : 00

CHECK CYLINDER BRACKETS LOOSE NEAR BATTERY

Cause : Battery box bracket snapped drivers side

Correction : Took batteries off and battery box off

|       |                                     |        |        |
|-------|-------------------------------------|--------|--------|
| 1.00  | BRKT BTTRY RGT SPRT FR              | 494.46 | 494.46 |
| 0.00  | DELIVER TO PIT#1 - BRAD!~@!@        | 0.00   | 0.00   |
| -1.00 | Adjust Parts Cost [[Warranty Only]] | 0.01   | -0.01  |

SIsId : RA920007021:01 Total : \$1,898.48

Date Invoice : 11/24/2022

OdomIn: 319,615

OdomOut: 319,615

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 1 Job : 00 CARRY OUT SERVICE AS PER DATA SHEET & HISTORY - BEST BASIC  
 Cause : Engine service Due  
 Correction : Initial test & data

|       |                                                                |        |        |
|-------|----------------------------------------------------------------|--------|--------|
| 1.00  | <b>FILTER CARTRIDGE</b>                                        | 150.77 | 150.77 |
| 1.00  | <b>FILTER PACKAGE</b>                                          | 64.65  | 64.65  |
| 1.00  | <b>TS FUEL FILTER</b>                                          | 179.80 | 179.80 |
| 1.00  | <b>SCREW PLUG</b>                                              | 34.61  | 34.61  |
| 1.00  | <b>ROCKER COVER SEAL DD13/15</b>                               | 92.11  | 92.11  |
| 2.00  | <b>AIR FILTER</b>                                              | 57.83  | 115.66 |
| 1.00  | <b>DUST FILTER</b>                                             | 86.55  | 86.55  |
| 0.00  | <b>Staging room</b>                                            | 0.00   | 0.00   |
| 5.40  | <b>MISC SHOP SUPPLIES</b>                                      | 7.30   | 39.42  |
| 40.00 | <b>HAZ WASTE &amp; ENVIRO DISPOSAL</b>                         | 0.40   | 16.00  |
| 40.00 | <b>ENGINE - ALLIANCE AFM E9/E7/E6 (205L) - QABP AFM4213205</b> | 8.03   | 321.20 |
| 1.00  | <b>Adjust Parts Cost [[Warranty Only]]</b>                     | 14.55  | 14.55  |

SlId : RA920006649:01 Total : \$0.00

Date Invoice : 11/21/2022

OdomIn: 304,278

OdomOut: 304,278

**Sold Operations**

OpsId : 1 Job : BD LOCATION: 651 JOHNSON RD, FOREST LAKE  
 Cause : FURTHER TEST + TIPS CASE REQUIRED  
 Correction : TRAVEL FROM DARRA TO VEHICLE. SHORT TEST. ROAD TEST + SPLITTER CRUNCHING IN

SlId : RA920006423:01 Total : \$373.86

Date Invoice : 10/19/2022

OdomIn: 303,889

OdomOut: 303,889

**Sold Operations**

OpsId : 1 Job : 26 GEAR CHANGES NOISY WITH LOAD  
 Cause : NO FAULT FOUND AT TIME OF TESTING - CUSTOMER TO MONITOR  
 Correction : Carried out quick test found no faults in TCM, CPC

|      |                                   |      |      |
|------|-----------------------------------|------|------|
| 1.00 | <b>AU Surcharge   RA920006423</b> | 2.61 | 2.61 |
|------|-----------------------------------|------|------|

SlId : RA920005803:01 Total : \$560.74

Date Invoice : 09/30/2022

OdomIn: 285,789

OdomOut: 285,789

**Sold Operations**

OpsId : 1 Job : 00 CARRY OUT SERVICE AS PER DATA SHEET & HISTORY  
 Cause : Done JB  
 Correction :

|       |                                            |       |       |
|-------|--------------------------------------------|-------|-------|
| 1.00  | <b>TS WIPER BLADE</b>                      | 59.97 | 59.97 |
| 0.00  | <b>STAGING ROOM PRE PICK</b>               | 0.00  | 0.00  |
| 1.00  | <b>WORKSHOP SUNDRIES</b>                   | 23.20 | 23.20 |
| 0.40  | <b>COMPLEX GREASE</b>                      | 37.69 | 15.08 |
| -1.61 | <b>Adjust Parts Cost [[Warranty Only]]</b> | 1.00  | -1.61 |

SlId : RA920004797:03 Total : \$199.39

Date Invoice : 08/29/2022

OdomIn: 250,801

OdomOut: 250,801

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 5 Job : 88 Turntable pads lifting

Cause : Done JB

Correction : Bolts lost tension, one missing

1.00 AU Surcharge | RA920004797

1.39

1.39

**Rejected Operations**

OpsId : 4 Job : 00 EWS

Cause :

Correction :

1.00 MIRROR GLASS 279.99 279.99

1.00 COVER OUTSIDE RIGHT 96.99 96.99

1.00 COVER BOTTOM RIGHT 43.39 43.39

1.00 LAMP UNIT 2,854.99 2,854.99

1.00 COVER - HEADLAMP LEFT 607.49 607.49

1.00 GREASELESS INSERT KIT C/W 492.49 492.49

0.00 PADS EX JOST, OTHER PARTS IN STOCK 0.00 0.00

SIsId : RA920004797:02 Total : \$1,431.88

Date Invoice : 08/27/2022

OdomIn: 250,801

OdomOut: 250,801

**Sold Operations**

OpsId : 3 Job : 18 BELT NOISE PRESENT ON START UP OR AFTER 10MIN OF DRIVING

Cause : Done JB - NOT REPAIRED NOT CLAIMABLE

Correction : CAUSE - NO NOISE PRESENT BUT ON INSPECTION FOUND BELTS FEATHERED

1.00 V-RIBBED BELT 64.08 64.08

1.00 V-RIBBED BELT 2642MM 121.82 121.82

1.00 BELT TENSIONER 687.26 687.26

2.00 GUIDE PULLEY 106.10 212.20

1.00 Adjust Parts Cost [[Warranty Only]] 0.02 0.02

SIsId : RA920004797:01 Total : \$3,264.77

Date Invoice : 08/27/2022

OdomIn: 250,801

OdomOut: 250,801

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 1 Job : 00 CARRY OUT SERVICE AS PER DATA SHEET & HISTORY - BEST BASIC  
 Cause : Done JB  
 Correction : CAUSE - 240,000KM SERVICE DUE

|       |                                                                           |        |        |
|-------|---------------------------------------------------------------------------|--------|--------|
| 1.00  | <b>FILTER PACKAGE</b>                                                     | 64.65  | 64.65  |
| 1.00  | <b>TS FUEL FILTER</b>                                                     | 179.80 | 179.80 |
| 1.00  | <b>SCREW PLUG</b>                                                         | 34.61  | 34.61  |
| 2.00  | <b>AIR FILTER</b>                                                         | 57.83  | 115.66 |
| 1.00  | <b>FILTER CARTRIDGE</b>                                                   | 150.77 | 150.77 |
| 1.00  | <b>AIR FILTER INSERT</b>                                                  | 321.86 | 321.86 |
| 2.00  | <b>SEALING RING</b>                                                       | 3.27   | 6.54   |
| 1.00  | <b>DUST FILTER</b>                                                        | 86.55  | 86.55  |
| 1.00  | <b>TS WIPER BLADE</b>                                                     | 59.97  | 59.97  |
| 42.00 | <b>ENGINE - ALLIANCE AFM E9/E7/E6 (205L) - QABP AFM4213205</b>            | 8.03   | 337.26 |
| 26.00 | <b>GEAR OIL - ALLIANCE PRIME TRANS PLUS MB 75W90 (205L) - QABP AFM430</b> | 22.15  | 575.90 |
| 68.00 | <b>HAZ WASTE &amp; ENVIRO DISPOSAL</b>                                    | 0.40   | 27.20  |
| 4.70  | <b>MISC SHOP SUPPLIES</b>                                                 | 7.30   | 34.31  |
| 1.00  | <b>Adjust Parts Cost [[Warranty Only]]</b>                                | 0.05   | 0.05   |

OpsId : 2 Job : 54 RHR LIGHT INOP  
 Cause : Done JB  
 Correction : CAUSE - DAMAGED WATER INGRESS

|      |                                  |        |        |
|------|----------------------------------|--------|--------|
| 1.00 | <b>TAIL LAMP RH(B/NECK 4TH Q</b> | 544.49 | 544.49 |
|------|----------------------------------|--------|--------|

SIsId : RA920004009:01 Total : \$0.00

Date Invoice : 09/14/2022

OdomIn: 10

OdomOut: 10

**Rejected Operations**

OpsId : 2 Job : 99 QUOTE PARTS  
 Cause :  
 Correction :

|      |                                       |        |        |
|------|---------------------------------------|--------|--------|
| 1.00 | <b>TAIL LAMP RH(B/NECK 4TH Q</b>      | 554.99 | 554.99 |
| 0.00 | <b>NIL STOCK - ETA APPROX 1 MONTH</b> | 0.00   | 0.00   |

SIsId : RA920003363:01 Total : \$557.47

Date Invoice : 07/27/2022

OdomIn: 213,182

OdomOut: 213,182

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 1 Job : 00 CARRY OUT SERVICE AS PER DATA SHEET & HISTORY  
 Cause : Done GB  
 Correction : carried out inspection service as requested...

|      |                                                                   |       |       |
|------|-------------------------------------------------------------------|-------|-------|
| 1.00 | BULB P21/5W 24V                                                   | 3.32  | 3.32  |
| 1.00 | TS WIPER BLADE                                                    | 59.97 | 59.97 |
| 0.00 | DELIVER TO BAY #5                                                 | 0.00  | 0.00  |
| 3.00 | COOLANT - ALLIANCE PRIMECOOL GP P-40 (1000L) - QABP AFM46041000   | 5.07  | 15.21 |
| 5.00 | ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (PUMP-IN) - QABP AFM4 | 7.82  | 39.10 |
| 0.40 | GREASE- COMPLEX A0019894051 09                                    | 33.65 | 13.46 |
| 1.00 | WORKSHOP SUNDRIES                                                 | 20.33 | 20.33 |

SlId : RA920002267:01 Total : \$171.63

Date Invoice : 06/25/2022

OdomIn: 179,814

OdomOut: 179,814

**Sold Operations**

OpsId : 1 Job : 43 AIRLEAKING FROM UNDERNEATH VEHICLE  
 Cause : air dryer filter split  
 Correction : Carried out short test. Remove filter and inspect, no rub marks or impact damage. Replace and cle

|      |                               |        |        |
|------|-------------------------------|--------|--------|
| 1.00 | AIR FILTER ELEMENT            | 127.90 | 127.90 |
| 0.00 | Deliver to Adam Express1 ASAP | 0.00   | 0.00   |

SlId : RA920001641:02 Total : \$1,267.24

Date Invoice : 05/31/2022

OdomIn: 167,430

OdomOut: 167,430

**Sold Operations**

OpsId : 1 Job : 00 SERVICE AS PER SCHEDULE  
 Cause : Done KG  
 Correction : carried out service as per service sheet.

|       |                                                          |        |        |
|-------|----------------------------------------------------------|--------|--------|
| 1.00  | FILTER PACKAGE                                           | 63.39  | 63.39  |
| 1.00  | TS FUEL FILTER                                           | 176.26 | 176.26 |
| 1.00  | SCREW PLUG                                               | 33.94  | 33.94  |
| 1.00  | DUST FILTER                                              | 84.81  | 84.81  |
| 2.00  | AIR FILTER                                               | 54.97  | 109.94 |
| 1.00  | FILTER CARTRIDGE                                         | 147.83 | 147.83 |
| 38.00 | Engine-ALLIANCE PRIME ENGINE GLOBAL 10W40-205 Litre Pack | 7.76   | 294.88 |
| 0.40  | MISC SHOP SUPPLIES                                       | 33.47  | 13.39  |
| 1.00  | HAZ WASTE & ENVIRO DISPOSAL                              | 15.20  | 15.20  |

SlId : RA920001641:01 Total : \$4,107.15

Date Invoice : 05/31/2022

OdomIn: 167,430

OdomOut: 167,430

Component Serial Number

VIN

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

**Sold Operations**

OpsId : 3 Job : 79 RECALL #30569 REPLACE UPPER STEERING SHAFT

Cause : Done JB

Correction : C: upper steering shaft recall

|      |                  |          |          |
|------|------------------|----------|----------|
| 1.00 | STEERING SHAFT   | 1,558.83 | 1,558.83 |
| 1.00 | NUT              | 2.11     | 2.11     |
| 1.00 | HEXAGON FIT BOLT | 12.98    | 12.98    |

OpsId : 4 Job : 18 CAM BOX GASKET LEAKING

Cause : Done JB

Correction : C: cambox seal material failure

|      |                        |        |        |
|------|------------------------|--------|--------|
| 1.00 | CIRCUMFERENTIAL GASKET | 77.10  | 77.10  |
| 0.00 | STAGE ROOM PLS         | 0.00   | 0.00   |
| 3.00 | HIGH-PRESSURE LINE     | 93.13  | 279.39 |
| 3.00 | HIGH-PRESSURE LINE     | 93.13  | 279.39 |
| 6.00 | GASKET                 | 13.45  | 80.70  |
| 2.00 | HIGH-PRESSURE LINE     | 164.98 | 329.96 |
| 0.00 | Deliver to HCV Bay 11  | 0.00   | 0.00   |
| 1.00 | WORKSHOP SUNDRIES      | 0.04   | 0.04   |

SlId : RA920001400:01 Total : \$294.73

Date Invoice : 05/26/2022

OdomIn: 154,433

OdomOut: 154,433

**Sold Operations**

OpsId : 1 Job : 18 Check &amp; Report on engine oil leak or engine fuel leak?

Cause : Done Rocker cover gasket perished

Correction : -Tilt cab

|      |                           |       |       |
|------|---------------------------|-------|-------|
| 1.00 | ROCKER COVER SEAL DD13/15 | 90.30 | 90.30 |
| 1.00 | MISC SHOP SUPPLIES        | 0.38  | 0.38  |

SlId : RA920000610:02 Total : \$0.00

Date Invoice : 04/12/2022

OdomIn: 130,423

OdomOut: 130,423

328288

473909C0652380

W1T96342420534038

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS 9634240

08/10/2021

## Rejected Operations

OpsId : 2 Job : 00 QUOTE

Cause :

Correction :

|      |                                                               |          |          |
|------|---------------------------------------------------------------|----------|----------|
| 1.00 | CU, DISTANCE SENSOR - BACK ORDER GERMANY - FRONT RADAR***     | 6,219.99 | 6,219.99 |
| 1.00 | FRAME SEGMENT - STOCK - RADAR BUG MESH                        | 163.99   | 163.99   |
| 1.00 | FRAME SEGMENT RIGHT - STOCK - RADAR BUG MESH                  | 163.99   | 163.99   |
| 1.00 | SCREW CAP - STOCK - WASHER BOTTLE CAP                         | 11.69    | 11.69    |
| 1.00 | FRONT SPOILER - STOCK - LHS HEADLIGHT PANEL ***UNDERCOATED*** | 532.49   | 532.49   |
| 1.00 | ROCKER COVER SEAL DD13/15 - STOCK                             | 125.99   | 125.99   |
| 1.00 | TOOL BOX - EX MELB - DOG BOX                                  | 592.49   | 592.49   |
| 1.00 | STANCHION - STOCK - DOG BOX BAR                               | 47.29    | 47.29    |
| 1.00 | CLOSING FLAP - 1 EX MELB - DOG BOX PANEL **UNDERCOATED**      | 3,094.99 | 3,094.99 |
| 1.00 | FILLING PIPE - EX MELB - HEADER TANK HOSE                     | 392.49   | 392.49   |

SIsId : RA920000610:01 Total : \$334.64

Date Invoice : 03/29/2022

OdomIn: 130,423

OdomOut: 130,423

## Sold Operations

OpsId : 1 Job : 10 CARR OUT INSPECTION SERVICE - BEST BASIC 500/2026

Cause : Done

Correction : C: carry out inspection service

|      |                                                   |       |       |
|------|---------------------------------------------------|-------|-------|
| 1.00 | TS WIPER BLADE                                    | 58.81 | 58.81 |
| 0.00 | DELIVER TO: PIT 2 SEBASTIAN                       | 0.00  | 0.00  |
| 0.40 | COMPLEX GREASE (MB)                               | 33.23 | 13.29 |
| 1.70 | WORKSHOP SUNDRIES                                 | 6.30  | 10.71 |
| 5.00 | Engine-ALLIANCE PRIME ENGINE GLOBAL 10W40-PUMP IN | 6.45  | 32.25 |
| 1.00 | Coolant-ALLIANCE PRIMECOOL GP P-40-205L DRUM      | 5.16  | 5.16  |
| 1.00 | MISC SHOP SUPPLIES                                | 0.22  | 0.22  |

SIsId : RA920000278:01 Total : \$744.94

Date Invoice : 03/24/2022

OdomIn: 119,550

OdomOut: 119,550

## Sold Operations

OpsId : 1 Job : 91 RHF SEAT HEIGHT GOES UP &amp; DOWN WHILE DRIVING - VALVE IN ST

Cause : DONE

Correction : Cause: INCONSISTANT RIDE HEIGHT D/S SEAT HEIGHT VALVE BYPASSING INTERNALLY

|      |             |        |        |
|------|-------------|--------|--------|
| 1.00 | VALVE BLOCK | 642.92 | 642.92 |
|------|-------------|--------|--------|

OpsId : 2 Job : 33 STRANGE NOISE FROM STEER RH AXLE WHEN TURNING INT

Cause : NFF - REPORT ONLY

Correction : C: strange noise from steer R/H axle when turning intermittent