

Component Serial Number

VIN

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Vehicle Notes :

20/05/2021 12:00:00AM RO#: R54236 DATE: 20/05/2021 CUST: FARGO CARGO PTY LTD ODOM: 0 TOTAL: \$36868.99 ADVISOR: BRANCH: 417RZ SALE TYPE: |||||

OP_CODES

53MBZZZ|65MBZZZ13|67MBZZZ|69MBZZZ04|54MBZZZ02|69MBZZZ|69MBZZZ13|69MBZZZ03|65MBZZZ|70MBZZZ11|70MBZZZ26|69MBZZZ32|62MBZZZ|70MBZZZ10|69MBZZZ12|62MBZZZ08|67MBZZZ09|60MBZZZ|65MBZZZ01|65MBZZZ02|67MBZZZ03|67MBZZZ01|52MBZZZ02|99MBZZZ

OP_DESC

|||||

COMPLAINT

CARRY OUT PDI^DTGC SERVICE|CARRY OUT W/A^D&L LASER|GME TX4500 WITH ANTENNAE^ON HIGHWAY|TINT^TWEED TINTING|FIRE EXT BETWEEN GUARDS^DTGC SERVICE|JSK37 GREASELESS AT 1270MM HIGH^CARRABEAN CLIP TO BE FITTED.^TURN TABLE WORK LIGHT TO BE FITTED^SET AT 50MM FOC^D

CAUSE

|||||

CORRECTION

|||||

19/07/2021 12:00:00AM RO#: R54689 DATE: 19/07/2021 CUST: FARGO CARGO PTY LTD ODOM: 10 TOTAL: \$2304.83 ADVISOR: BRANCH: 417RB SALE TYPE: |||

OP_CODES

69MBZZZ|67MBZZZ

OP_DESC

|

COMPLAINT

fit bullbar.|SUPPLY AND FIT REDARC TRAILER CONNECTION.

CAUSE

|

CORRECTION

CARRIED OUT|CARRIED OUT

24/11/2021 12:00:00AM RO#: R55709 DATE: 24/11/2021 CUST: FARGO CARGO PTY LTD ODOM: 48712 TOTAL: \$204.63 ADVISOR: BRANCH: 417RB SALE TYPE: M|||

OP_CODES

51MBZZZ|70MBZZZ26|67MBZZZ22|69MBZZZ

OP_DESC

|||

COMPLAINT

CARRY OUT INSPECTION SERVICE (40K)|CHECK DRIVERS SEAT OPERATION|CALIBRATE SPEEDO TO 100 KM/H - GPS SHOWING 96 KM/H.|CHECK RH FOG LAMP

CAUSE

DC - 21118SV^00530602 1.0 Telligent time-based maintenance - annual Perform^00600001 0.3 Oil level in engine Correct|||

CORRECTION

VEHICLE DUE FOR SERVICE^^Carried out inspection service as per sheet.^Greased the Jack shaft. Toppedup engine oil.^3L engine oil used|FOUND SEATBASE NOT CLIPPED IN PROPERLY.^CLIPPED IN SEATBASE AND RECHECKED - ALL OK.|FOUND SPEED SET TO 100 KM/H.|FOUND RH

Component Serial Number

VIN

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

17/01/2022 12:00:00AM RO#: R56061 DATE: 17/01/2022 CUST: FARGO CARGO PTY LTD ODOM: 91651 TOTAL: \$2037.63 ADVISOR:
BRANCH: 417RB SALE TYPE: M

OP_CODES
51MBZZZZ

OP_DESC

COMPLAINT
CARRY OUT TELLIGENT SERVICE (80K).

CAUSE
DC 21120SV^00500002 0.8 Engine filter change Perform^00504101 0.5 Fuel filter^00525801 0.2 Fuel filter element water separator^00509101 0.2 Air drier filter replace^00506001 2.2 Valve adjustment^00532001 0.7 Telligent periodic maintenance safety related^0

CORRECTION
CARRIED OUT TELIGENT SERVICE.^Engine filter change Perform^Fuel filter^Fuel filter element water separator^Air drier filter replace^Perform Valve adjustment^Telligent periodic maintenance safety related^2x Mesh filters in fuel tank^Perform Annual Inspecti

8/02/2022 12:00:00AM RO#: R56260 DATE: 08/02/2022 CUST: FARGO CARGO PTY LTD ODOM: 91651 TOTAL: \$54.00 ADVISOR: BRANCH:
417RB SALE TYPE: I

OP_CODES
69MBZZZZ

OP_DESC

COMPLAINT
REPLACE TURNTABLE PADS

CAUSE

CORRECTION
REPLACED PADS AS REQUIRED.

Component Serial Number

VIN

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Repair Order History

AmtPriceExtended

SlId : RA970009813:02 Total : \$898.97 Date Invoice : 11/13/2023 OdomIn: 531,935 OdomOut: 531,940

Sold Operations

OpsId : 2 Job : 88 Detachable Parts
Cause :
Correction :

1.00	COOLANT LINE	160.99	160.99
2.00	ALLIANCE PRIMECOOL GP P-4	143.99	287.98

SlId : RA970009813:01 Total : \$3,385.34 Date Invoice : 11/10/2023 OdomIn: 531,935 OdomOut: 531,940

Sold Operations

OpsId : 1 Job : EA VEHICLE RUNNING ROUGH
Cause :
Correction : Complaint - Unable to complete burn - aftertreatment fault on dash

1.00	SOLENOID VALVE	355.58	355.58
0.00	see notes for instrutions	0.00	0.00
1.00	ACTUATOR MOTOR	1,625.76	1,625.76

SlId : RA960021761:01 Total : \$0.00 Date Invoice : 12/05/2023 OdomIn: 531,940 OdomOut: 531,940

Sold Operations

OpsId : 1 Job : EA TOP UP ENGINE OIL
Cause :
Correction :

SlId : RA921003989:01 Total : \$0.00 Date Invoice : 04/15/2023 OdomIn: 0 OdomOut: 400,902

Sold Operations

OpsId : 4 Job : 54 CENTRE DISPLAY DROPS OUT INTERMITTANTLY
Cause :
Correction : Complaint: CENTRE DISPLAY DROPS OUT INTERMITTENTLY.

SlId : RA921003940:04 Total : \$522.49 Date Invoice : 05/04/2023 OdomIn: 400,902 OdomOut: 400,902

Sold Operations

OpsId : 3 Job : 00 REPLACE TURNTABLE PLATES - UNDER 3MM
Cause :
Correction : COMPLAINT:

1.00	GREASELESS INSERT KIT CW	522.49	522.49
------	--------------------------	--------	--------

SlId : RA921003940:03 Total : \$2,352.44 Date Invoice : 03/21/2023 OdomIn: 400,902 OdomOut: 400,902

Component Serial Number

VIN

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Sold Operations

OpsId : 2 Job : 79 SM3272 Update software release in motor control module (MCM)

Cause :

Correction : Complaint: SM3272 - Update software release in motor control module (MCM).

OpsId : 5 Job : 15 LOOSE PART IN LH HEADLIGHT

Cause :

Correction : Complaint:

1.00 LAMP UNIT 2,082.99 2,082.99

-1.00 Adjust Parts Cost [[Warranty Only]] 0.01 -0.01

SIsId : RA921003940:01 Total : \$3,200.58 Date Invoice : 03/21/2023 OdomIn: 400,902 OdomOut: 400,902

Sold Operations

OpsId : 1 Job : 00 CARRY OUT TELLIGENT SERVICE

Cause :

Correction : Carried out intelligent service Actros.

1.00 FILTER PACKAGE 67.24 67.24

1.00 SCREW PLUG 36.30 36.30

1.00 TS FUEL FILTER 186.99 186.99

1.00 FILTER CARTRIDGE 156.81 156.81

2.00 AIR FILTER 61.04 122.08

1.00 FILTER ELEMENT 139.81 139.81

1.00 AIR FILTER INSERT 334.72 334.72

1.00 DUST FILTER 90.35 90.35

1.00 TS WIPER BLADE 62.36 62.36

42.00 ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 8.03 337.26

1.00 GREASE - COMPLEX - A001989405109 54.14 54.14

14.00 GEAR OIL - ALLIANCE PRIME TRANS PLUS MB 75W90 (PUMP-IN) - QABP AFM 22.16 310.24

30.00 GEAR OIL - ALLIANCE PRIME AXLE PLUS FE 75W90 (PUMP IN) - QABP AFM4 20.11 603.30

-1.00 Adjust Parts Cost [[Warranty Only]] 34.55 -34.55

1.00 MISC SHOP SUPPLIES 23.03 23.03

SIsId : RA921003535:02 Total : \$2,117.33 Date Invoice : 02/28/2023 OdomIn: 379,720 OdomOut: 379,720

Sold Operations

OpsId : 2 Job : 54 BATTERY BOX SUPPORTS BROKEN

Cause :

Correction : Complaint: Broken battery tray brackets.

1.00 BRKT BTTRY LFT SPPRT LF 522.76 522.76

1.00 BRKT BTTRY RGT SPPRT FR 522.76 522.76

SIsId : RA921003535:01 Total : \$1,982.66 Date Invoice : 02/13/2023 OdomIn: 379,720 OdomOut: 379,720

Component Serial Number

VIN

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Sold Operations

OpsId : 1 Job : 00 CARRY OUT TELLIGENT SERVICE

Cause :

Correction : Carried out as per service telligent work sheet

1.00	AIR FILTER INSERT	334.72	334.72
1.00	ANDERSON PLUG	25.79	25.79
1.00	9KG FIRE EXT BAG	3.72	3.72
1.00	FILTER CARTRIDGE	156.81	156.81
2.00	AIR FILTER	61.04	122.08
1.00	FILTER PACKAGE	67.24	67.24
1.00	SCREW PLUG	36.30	36.30
1.00	DUST FILTER	90.35	90.35
1.00	FILTER ELEMENT	139.81	139.81
6.00	ENGINE - ALLIANCE AFM CK-4 15W40	7.85	47.10
1.00	GREASE- COMPLEX A0019894051 09	33.65	33.65
1.00	TS FUEL FILTER	186.99	186.99
-1.00	Adjust Parts Cost [[Warranty Only]]	1.40	-1.40

SlId : RA921003138:01 Total : \$2,854.99 Date Invoice : 12/30/2022 OdomIn: 0 OdomOut: 324,584

Sold Operations

OpsId : 2 Job : 60 RH HEADLIGHT ASSY CRACKED

Cause :

Correction :

1.00	LAMP UNIT	2,854.99	2,854.99
------	-----------	----------	----------

SlId : RA921002885:03 Total : \$399.07 Date Invoice : 12/08/2022 OdomIn: 324,582 OdomOut: 324,584

Sold Operations

OpsId : 3 Job : 47 Replace missing fuel tank strap rubber

Cause :

Correction :

1.00	9KG FIRE EXT BAG	5.58	5.58
1.00	PROFILE BASE	115.99	115.99

SlId : RA921002885:02 Total : \$1,733.49 Date Invoice : 12/06/2022 OdomIn: 324,582 OdomOut: 324,584

Sold Operations

OpsId : 2 Job : 15 INPECT HARD STARTING. \$198.48 TAKING OFF CORES ADDING

Cause :

Correction : Complaint:

1.00	STARTER MOTOR	1,493.97	1,493.97
1.00	Adjust Parts Cost [[Warranty Only]]	7.52	7.52

SlId : RA921002885:01 Total : \$2,151.46 Date Invoice : 11/30/2022 OdomIn: 324,582 OdomOut: 324,584

Component Serial Number

VIN

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Sold Operations

OpsId : 1 Job : 00 TELLIGENT SERVICE

Cause :

Correction : Carried out Telligent service.

1.00	FILTER CARTRIDGE	150.77	150.77
1.00	FILTER PACKAGE	64.65	64.65
1.00	TS FUEL FILTER (MAHLE)	189.91	189.91
1.00	SCREW PLUG	34.61	34.61
1.00	DUST FILTER	86.55	86.55
1.00	FILTER INSERT	206.50	206.50
1.00	FILTER ELEMENT	140.67	140.67
2.00	AIR FILTER	57.83	115.66
1.00	PROFILE BASE	81.25	81.25
1.00	PREM LL 12V 21W BA15S BUL	6.38	6.38
40.00	ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (205L) - QABP AFM4982	8.73	349.20
1.00	COOLANT - ALLIANCE PRIMECOOL GP P-40 (205L) - QABP AFM4604205	5.75	5.75
1.00	GREASE - ALLIANCE AFX2 GREASE (180KGL) - QABP AFM4215180	14.00	14.00
1.00	HAZ WASTE & ENVIRO DISPOSAL	16.00	16.00
1.00	MISC SHOP SUPPLIES	34.00	34.00
-1.00	Adjust Parts Cost [[Warranty Only]]	25.94	-25.94

SIsId : RA921002406:03 Total : \$4.18

Date Invoice : 11/08/2022

OdomIn: 288,708

OdomOut: 288,708

Sold Operations

OpsId : 4 Job : 60 FIRE EXTINGUISHER BAG MISSING

Cause :

Correction :

1.00	9KG FIRE EXT BAG	4.18	4.18
------	------------------	------	------

SIsId : RA921002406:02 Total : \$370.28

Date Invoice : 10/20/2022

OdomIn: 288,708

OdomOut: 288,708

Sold Operations

OpsId : 1 Job : 00 CARRY OUT TELLIGENT SERVICE.

Cause :

Correction : * Completed Telligent inspection service check list as required,

1.00	24V 21W BA15S BULB 10	5.02	5.02
0.40	GREASE - ALLIANCE AFX2 GREASE (180KGL) - QABP AFM4215180	7.57	3.03
7.00	ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (PUMP-IN) - QABP AFM4	8.03	56.21
1.00	WORKSHOP SUNDRIES	14.50	14.50
1.00	Adjust Parts Cost [[Warranty Only]]	1.52	1.52

SIsId : RA921002406:01 Total : \$366.93

Date Invoice : 10/19/2022

OdomIn: 288,708

OdomOut: 288,708

Component Serial Number

VIN

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Sold Operations

OpsId : 3 Job : 32 LHF SHOCK ABSORBER LEAKING

Cause :

Correction : LHF SHOCK ABSORBER LEAKING;

1.00 SHOCK ABSORBER

292.08

292.08

SIsId : RA921001575:01 Total : \$1,894.96

Date Invoice : 08/08/2022

OdomIn: 234,639

OdomOut: 234,639

Sold Operations

OpsId : 1 Job : 00 TELLIGANT SERVICE

Cause : SERVICE DUE

Correction : Carried out Telligent service as per Mercedes-Benz service sheet.

1.00 FILTER CARTRIDGE

150.77

150.77

1.00 TS FUEL FILTER (MAHLE)

189.91

189.91

1.00 FILTER PACKAGE

64.65

64.65

1.00 SCREW PLUG

34.61

34.61

2.00 AIR FILTER

57.83

115.66

1.00 DUST FILTER

86.55

86.55

1.00 AIR FILTER ELEMENT

130.54

130.54

1.00 TS WIPER BLADE

59.97

59.97

45.00 ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (PUMP-IN) - QABP AFM4

8.03

361.35

45.00 HAZ WASTE & ENVIRO DISPOSAL

0.40

18.00

4.70 CONSUMBLES

6.78

31.87

1.00 Adjust Parts Cost [[Warranty Only]]

13.52

13.52

SIsId : RA921000539:02 Total : \$0.00

Date Invoice : 05/27/2022

OdomIn: 167,220

OdomOut: 167,220

Rejected Operations

OpsId : 3 Job : 00 ADDITIONAL PARTS REQUIRED

Cause :

Correction : IMPACT DAMAGE RHS HEADLIGHT, REPLACE

1.00 LAMP UNIT

2,797.49

2,797.49

SIsId : RA921000539:01 Total : \$1,547.35

Date Invoice : 05/24/2022

OdomIn: 167,220

OdomOut: 167,220

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Sold Operations

OpsId : 1 Job : 00 CARRY OUT 160K ENGINE SERVICE

Cause :

Correction : CARRY OUT 160,000 SERVICE, INCLUDING ENGINE, AS PER SCHEDULE.

1.00	AIR FILTER INSERT	315.54	315.54
1.00	FILTER PACKAGE	63.39	63.39
1.00	TS FUEL FILTER	176.26	176.26
1.00	FILTER CARTRIDGE	147.83	147.83
40.00	Engine-ALLIANCE PRIME ENGINE GLOBAL 10W40-PUMP IN	6.45	258.00
1.00	HAZ WASTE & ENVIRO DISPOSAL	16.00	16.00
1.00	MISC SHOP SUPPLIES	23.95	23.95

OpsId : 2 Job : 54 TRACKING NOT WORKING

Cause :

Correction : CARRIED OUT INSPECTING FOUND NO FAULTS FOR TRACKING OR RADAR.

OpsId : 4 Job : 15 WARNING LIGHT ON DASH

Cause :

Correction : trailer light out on dash

1.00	24V 21/5W BAY15D BULB 10	6.08	6.08
1.00	24V 21W LOAD RESISTOR BL	17.20	17.20
1.00	MISC SHOP SUPPLIES	6.50	6.50

SIsId : RA920036317

Total : \$374.00

Date Invoice : IN SHOP

OdomIn: 0

OdomOut: 0

Sold Operations

OpsId : 1 Job : 99 R & R BATTERIES

Cause :

Correction :

SIsId : RA920034585:01

Total : \$516.09

Date Invoice : 05/27/2025

OdomIn: 707,631

OdomOut: 707,631

Sold Operations

OpsId : 1 Job : 00 ROADWORTHY INSPECTION WITH LIST/COST OF WORK REQUIRED

Cause :

Correction :

1.00	BATTERY	6.09	6.09
------	---------	------	------

OpsId : 2 Job : 00 BATTERIES NEED REPLACING

Cause :

Correction : C: BATTERIES NEED REPLACING

OpsId : 39 Job : ASR WINDSCREEN CRACKED REPLACE

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
------	--	------	------

SIsId : RA920034374:01

Total : \$0.00

Date Invoice : 06/26/2025

OdomIn: 707,631

OdomOut: 707,631

Component Serial Number

VIN

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Rejected Operations

OpsId : 36 Job : ASR ---

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

SIsId : RA920029141:01 Total : \$80.00

Date Invoice : 11/21/2024

OdomIn: 707,631

OdomOut: 707,631

Sold Operations

OpsId : 1 Job : 00 REWORK - BATTERY ISOLATOR NOT WORKING

Cause : Aftermarket accessories connected to negative post on batteries bypassing isolator switch

Correction : Check for cause of isolator not working.

SIsId : RA920028490:02 Total : \$416.25

Date Invoice : 12/03/2024

OdomIn: 707,630

OdomOut: 707,630

Sold Operations

OpsId : 2 Job : 20 SM3311 Replace coolant thermostat

Cause : DONE

Correction : Drained coolant.

1.00 ONE EAR CLAMP 21.50 21.50

1.00 THERMOSTAT 213.63 213.63

1.00 SEAL 16.31 16.31

-1.00 Adjust Parts Price [[Warranty Only]] 16.69 -16.69

SIsId : RA920028490:01 Total : \$567.66

Date Invoice : 11/11/2024

OdomIn: 707,630

OdomOut: 707,630

Sold Operations

OpsId : 1 Job : 54 FIT SUPPLIED BATTERIES

Cause :

Correction : fitted up batteries out in carpark

OpsId : 3 Job : 90 SUPPLY AND FIT BATTERY ISOLATOR

Cause :

Correction : Make up cabling and fit iso switch

1.00 LOCKOUT LEVER KIT RE 29.06 29.06

1.00 BATTERY MASTER SW 124.10 124.10

1.00 SWITCH MOUNT BRACKET 50.00 50.00

0.00 PD STAGE ROOM PLEASE 0.00 0.00

SIsId : RA920026412:05 Total : \$3,358.46

Date Invoice : 10/28/2024

OdomIn: 707,607

OdomOut: 707,607

Component Serial Number

VIN

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Sold Operations

OpsId : 6 Job : 99 R&R Drivers side lower step & paint

Cause : Done CP

Correction : Complaint: R&R Drivers side lower step & paint

1.00 ENTRANCE 623.32 623.32

4.00 EXPANSION RIVET 6.07 24.28

0.00 STAGE ROOM PLEASE 0.00 0.00

1.00 PAINTING \$611.11 611.11 611.11

OpsId : 7 Job : 99 Driver side door hinge trim piece missing ,sublet to paint and fit new

Cause : Done CP

Correction : Complaint: Driver side door hinge trim piece missing ,sublet to paint and fit new

1.00 MOLDING 351.05 351.05

1.00 PAINT \$330 731.25 731.25

OpsId : 8 Job : 54 Fuel tank marker light INOP wires pulled out -Re-connect

Cause : Done CP

Correction : C - full tank marker lights inop

SIsId : RA920026412:04 Total : \$646.25

Date Invoice : 10/26/2024

OdomIn: 707,607

OdomOut: 707,607

Sold Operations

OpsId : 5 Job : 18 Sump leaking Oil - FOUND ON INSPECTION

Cause : Done CP

Correction : Complaint: sump leaking

1.00 SEAL 167.74 167.74

1.00 Adjust Parts Price [[Warranty Only]] 0.01 0.01

SIsId : RA920026412:03 Total : \$443.98

Date Invoice : 10/24/2024

OdomIn: 707,607

OdomOut: 707,607

Sold Operations

OpsId : 9 Job : 13 Air Compressor leaking from mounting seal & rear plate - FOUND ON INS

Cause : Done CP

Correction : cause-

1.00 SEAL 4.63 4.63

1.00 O RING 16.13 16.13

1.00 SEAL 10.71 10.71

0.00 Clayton's Desk 0.00 0.00

1.00 Adjust Parts Price [[Warranty Only]] 0.01 0.01

SIsId : RA920026412:02 Total : \$3,859.69

Date Invoice : 09/30/2024

OdomIn: 707,607

OdomOut: 707,607

Component Serial Number

VIN

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Sold Operations

OpsId : 10 Job : 09 - Turbocharger bypassing - FOUND ON INSPECTION

Cause : DONE BM

Correction : Cause: - Turbocharger bypassing air due to waste gate internal seal failure

1.00	EXHAUST GAS TURBOCHARGER	2,769.93	2,769.93
1.00	CORE - EXHAUST GAS TURBOCHARGE	477.78	477.78
0.00	CORE MUST BE CLEANED AND RETURNED IN ORGINAL PACKAGING	0.00	0.00
1.00	METAL SEAL	96.81	96.81
4.00	HEX HEAD SCREW W FLANGE	20.27	81.08
4.00	SEALING RING	4.23	16.92
4.00	SEALING RING	4.07	16.28
1.00	GASKET	11.54	11.54
1.00	O RING	7.97	7.97
0.00	BAY 10 NEAR BBQ AREA	0.00	0.00
-1.00	CORE - EXHAUST GAS TURBOCHARGE	477.78	-477.78
1.00	Adjust Parts Price [[Warranty Only]]	1.16	1.16

SIsId : RA920026412:01 Total : \$2,350.12

Date Invoice : 09/30/2024

OdomIn: 707,607

OdomOut: 707,607

Sold Operations

OpsId : 1 Job : 00 Service Due

Cause : Done CP

Correction : C- SERVICE DUE

1.00	AIR FILTER ELEMENT	390.27	390.27
1.00	PARTS KIT WIPER BLADE	72.93	72.93
1.00	DUST FILTER	107.31	107.31
0.00	Bay 9	0.00	0.00
1.00	GREASE - ALLIANCE AFX2 GREASE	17.49	17.49
1.00	GREASE - COMPLEX	59.80	59.80
10.00	ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (5L) - QABP AFM498200	13.50	135.00
30.00	COOLANT - ALLIANCE PRIMECOOL GP P-40 (5L) - QABP AFM4604005	8.49	254.70

OpsId : 2 Job : 85 Air leak while driving - diagnose & advise

Cause : Diag only

Correction : C: Turbo waste gate diaphragm not sealing causing air leak at idle

OpsId : 4 Job : 60 Rear Cab Mount bushes worn R&R

Cause :

Correction : Worn Rear cab mount bushes removed and replaced

2.00	ELASTOMER BEARING	23.81	47.62
0.00	CLAYTONS RACK	0.00	0.00

SIsId : RA920018706:02 Total : \$8,807.91

Date Invoice : 12/27/2023

OdomIn: 558,925

OdomOut: 558,925

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Sold Operations

OpsId : 1 Job : EA WHEN STOPPING GEARS GOES INTO NEUTRAL
 Cause : Release bearing loss of vacuum through internal seals causing constant drag on pressure plate, cc
 Correction : C: Release bearing loss of vacuum through internal seals causing constant drag on pressure plate,

OpsId : 6 Job : 27 EST - REMOVE TRANS AND INSPECT
 Cause : Release bearing loss of vacuum through internal seals causing constant drag on pressure plate, cc
 Correction : *CONTINUATION FROM JOB OP LINE 1**

1.00	DUAL-PLATE DRY CLUTCH	4,822.85	4,822.85
1.00	CORE - DUAL-PLATE DRY CLUTCH	827.56	827.56
0.00	CORE MUST BE CLEANED AND RETURNED IN ORGINAL PACKAGING	0.00	0.00
0.00	IN STOCK	0.00	0.00
1.00	RELEASE BEARING CLUTCH	1,996.39	1,996.39
0.00	@@CORE@@ - A0032502115	0.00	0.00
0.00	IN STOCK	0.00	0.00
1.00	SEAL RING	8.33	8.33
0.00	IN STOCK	0.00	0.00
1.00	ANNULAR BALL BEARING	99.21	99.21
0.00	EX MELB	0.00	0.00
1.00	BLEEDER VALVE	117.04	117.04
0.00	IN STOCK	0.00	0.00
1.00	UNION SCREW	7.10	7.10
0.00	IN STOCK	0.00	0.00
1.00	RADIAL SHAFT SEALING RING	108.98	108.98
0.00	IN STOCK	0.00	0.00
-1.00	CORE - DUAL-PLATE DRY CLUTCH	827.56	-827.56
-1.00	CORE - RELEASE BEARING	240.90	-240.90
1.00	CORE - RELEASE BEARING	240.90	240.90
1.00	Adjust Parts Price [[Warranty Only]]	0.01	0.01

SIsId : RA920018706:01 Total : \$470.32

Date Invoice : 12/21/2023

OdomIn: 558,925

OdomOut: 558,925

Sold Operations

OpsId : 2 Job : 54 STARTER MOTOR ISSUES
 Cause :
 Correction : C:High resistance in wire A4 MCM X2 21/21 to Terminal 50 relay at Starter motor pin 50, black/yellc

2.00	CABLE CONNECTOR	13.66	27.32
1.00	IN FREIGHT	25.00	25.00

OpsId : 3 Job : 54 WARNING LIGHT ON
 Cause :
 Correction : C: Radar fault

Component Serial Number

VIN

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Rejected Operations

OpsId : 5 Job : 54 EST - RADAR DAMAGED REPLACE

Cause :

Correction :

1.00	COVER	77.36	77.36
1.00	BRACKET	351.86	351.86
1.00	FRAME SEGMENT	139.76	139.76
0.00	EX MELB	0.00	0.00
1.00	FRAME SEGMENT RIGHT	139.76	139.76
1.00	BUMPER FRONT CENTRAL	1,070.74	1,070.74
0.00	EX MELB	0.00	0.00
1.00	TRANSMISSION COOLER	1,041.73	1,041.73
2.00	TITAN PSF	12.06	24.12

SIsId : RA920004551:01 Total : \$2,482.48

Date Invoice : 08/24/2022

OdomIn: 239,219

OdomOut: 239,219

Sold Operations

OpsId : 1 Job : BDA ATTENDED BREAKDOWN AFTERHOURS

Cause :

Correction : CAUSE - Alternator housing belt lost tension causing alternator to short internally;

15.00	KMS TRAVELLED	0.75	11.25
1.00	A/HOURS CALL OUT	150.00	150.00
1.00	ALTERNATOR	2,131.51	2,131.51
0.00	GIVE TO MATT	0.00	0.00
-1.00	ALTERNATOR	286.60	-286.60
1.00	Adjust Parts Cost [[Warranty Only]]	30.82	30.82

SIsId : ES920001175

Total : \$40,238.31

Date Invoice : IN SHOP

OdomIn: 0

OdomOut: 0

Estimate Operations

OpsId : 40 Job : ASR WINDSCREEN CRACKED REPLACE

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
1.00	WINDSHIELD - EX MELB	901.54	901.54
1.00	FREIGHT INBOUND	100.00	100.00

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Rejected Operations

OpsId : 3 Job : ASR COOLANT LEVEL LOW - DIAGNOSE

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
------	--	------	------

OpsId : 4 Job : ASR INTERIOR ROOF LIGHTS BLOWN - REPLACE BULB

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
------	--	------	------

1.00	BULB - STOCK	5.75	5.75
------	--------------	------	------

OpsId : 5 Job : ASR ENGINE - TRANS - DIFF - TIME BASE SERVICE DUE

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
------	--	------	------

1.00	PARTS KIT FILTER PACKAGE - STOCK	75.41	75.41
------	----------------------------------	-------	-------

1.00	PARTS KIT FUEL FILTER - STOCK	208.13	208.13
------	-------------------------------	--------	--------

1.00	FILTER CARTRIDGE - STOCK	178.46	178.46
------	--------------------------	--------	--------

1.00	DUST FILTER - STOCK	97.69	97.69
------	---------------------	-------	-------

1.00	AIR FILTER ELEMENT - STOCK	355.29	355.29
------	----------------------------	--------	--------

2.00	SEALING RING - STOCK	3.56	7.12
------	----------------------	------	------

1.00	SEALING RING - STOCK	4.09	4.09
------	----------------------	------	------

3.00	AIR RELEASE FILTER - STOCK	65.99	197.97
------	----------------------------	-------	--------

1.00	PARTS KIT FILT CARTRI - STOCK	163.55	163.55
------	-------------------------------	--------	--------

1.00	AIR FILTER ELEMENT - STOCK	144.21	144.21
------	----------------------------	--------	--------

1.00	OIL FILTER - STOCK	21.86	21.86
------	--------------------	-------	-------

6.00	TITAN PSF - STOCK	12.15	72.90
------	-------------------	-------	-------

OpsId : 6 Job : ASR INJECTOR TUBES + SEALS 3,4,5,6

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
------	--	------	------

1.00	HIGH-PRESSURE LINE - STOCK	181.15	181.15
------	----------------------------	--------	--------

3.00	HIGH-PRESSURE LINE - EX DEALERS	200.11	600.33
------	---------------------------------	--------	--------

4.00	METAL SEAL - STOCK	30.16	120.64
------	--------------------	-------	--------

2.00	HIGH-PRESSURE LINE - EX MELB	298.02	596.04
------	------------------------------	--------	--------

OpsId : 7 Job : ASR FRONT CAM BOX WELSH PLUGS TO BE REPLACED

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
------	--	------	------

1.00	CLOSING CAP - STOCK	17.08	17.08
------	---------------------	-------	-------

6.00	CLOSING CAP - EX MELB	2.35	14.10
------	-----------------------	------	-------

6.00	CLOSING CAP - EX MELB	7.86	47.16
------	-----------------------	------	-------

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Rejected Operations (Cont.)

OpsId : 8 Job : ASR ALL BELTS + IDLERS WORN

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
1.00	POLY-V-BELT - STOCK	48.87	48.87
1.00	POLY-V-BELT - STOCK	134.11	134.11
2.00	GUIDE PULLEY - STOCK	112.62	225.24
1.00	BELT TENSIONER - EX MELB	768.43	768.43

OpsId : 9 Job : ASR STEER TYRES UNEVEN WEAR - SUBLET

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
------	--	------	------

OpsId : 10 Job : ASR CHECK ALL BRAKES + QUOTE REPAIRS

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
------	--	------	------

OpsId : 11 Job : ASR AIRBAG CLIP MISSING X 3

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
3.00	SPRING LOCK NUT - STOCK	3.34	10.02
3.00	SPRING LOCK NUT - STOCK	1.69	5.07
0.00	SMALL CLIP - BOTTOM	0.00	0.00

OpsId : 12 Job : ASR 1 X AIRBAG PEDASTOL CRACKED - REPLACE

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
1.00	CENTERING CONE - STOCK	40.52	40.52
1.00	SPRING LOCK NUT - STOCK	1.69	1.69
0.00	SMALL CLIP - BOTTOM	0.00	0.00
1.00	SPRING LOCK NUT - STOCK	3.34	3.34

OpsId : 13 Job : ASR OIL SPINNER LEAKING - REPLACE OIL SPINNER + GASKET

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
1.00	OIL SEPARATOR - STOCK	1,084.32	1,084.32
1.00	SCREW-IN FITTING - STOCK	35.33	35.33
1.00	ELASTOMER METAL SEAL - STOCK	12.89	12.89

OpsId : 14 Job : ASR P/S GRILL NOT LOCKING

Cause :

Correction :

236932

473909C0619381

W1T96342420506521

YEAR	MAKE	MODEL	IN SERVICE
2021	MB	ACTROS	06/10/2021

Rejected Operations (Cont.)

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
1.00	CLOSURE - STOCK	35.95	35.95
1.00	CLOSURE - STOCK	38.16	38.16
1.00	HOLDER - STOCK	38.09	38.09
1.00	HOLDER - STOCK	38.09	38.09

OpsId : 15 Job : ASR P/S MIRROR COVER LOWER MISSING
Cause :
Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
1.00	COVER - STOCK	42.71	42.71

OpsId : 16 Job : ASR LH + RH REAR BATTERY BRACKETS CRACKED
Cause :
Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
1.00	HOLDER - EX MELB	523.07	523.07
1.00	HOLDER - STOCK	545.20	545.20
1.00	HOLDER - STOCK	545.20	545.20
1.00	HOLDER - STOCK	515.12	515.12

OpsId : 17 Job : ASR EBS SOCKET HAS CORROSION
Cause :
Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
1.00	7P 12V ABS EBS SOCKET SCREW CO - STOCK	34.56	34.56

OpsId : 18 Job : ASR FUEL TANK LIGHT SKIRTS IMPACTED - REPLACE FUEL TANK
Cause :
Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
1.00	TANK FUEL 700L LH - EX SUPPLIER	2,346.40	2,346.40
1.00	FREIGHT INBOUND	200.00	200.00

OpsId : 19 Job : ASR CAB RAM BUSHES WORN - REPLACE
Cause :
Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
1.00	HYDRAULIC CYLINDER - EX MELB	2,442.47	2,442.47

OpsId : 20 Job : ASR FRONT CAB SUPPORT BUSHES SPLIT
Cause :
Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
4.00	SPACER DISK - **EX DEALERS	16.25	65.00
1.00	CONSOLE - EX MELB	1,048.16	1,048.16
1.00	CONSOLE - EX MELB	1,078.85	1,078.85

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Rejected Operations (Cont.)

OpsId : 21 Job : ASR ROCKER COVER GASKET LEAKING

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

1.00 SEAL CYLINDER HEAD COVER - STOCK 100.80 100.80

OpsId : 22 Job : ASR WIPER BLADES STREAKING

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

1.00 PARTS KIT WIPER BLADE - STOCK 66.39 66.39

OpsId : 23 Job : ASR FRONT A/C HOSE RUBBING

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

1.00 SUCTION LINE - STOCK 570.20 570.20

OpsId : 24 Job : ASR RADAR IMPACTED/BRACKET BENT

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

1.00 CU DISTANCE SENSOR - STOCK 3,182.76 3,182.76

1.00 SOCKET-OUTLET - EX MELB 28.96 28.96

6.00 CONTACT SOCKET - STOCK 5.04 30.24

6.00 SEAL - EX MELB 5.21 31.26

2.00 BLANKING PLUG - EX MELB 2.40 4.80

1.00 HOLDER - STOCK 320.66 320.66

OpsId : 25 Job : ASR GRILL MESH CRACKED/MISSING

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

1.00 FRAME SEGMENT - STOCK 127.36 127.36

1.00 FRAME SEGMENT - EX MELB 127.36 127.36

OpsId : 26 Job : ASR D/S DOOR SEAL RUBBER SPLIT

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

1.00 DOOR SEAL - STOCK 289.88 289.88

OpsId : 27 Job : ASR KEY BATTERY MISSING

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

1.00 BATTERY - STOCK 6.09 6.09

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Rejected Operations (Cont.)

OpsId : 28 Job : ASR REAR REFLECTOR PLATES FADED

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

1.00 REAR MARKER CAT PA - STOCK 55.55 55.55

OpsId : 29 Job : ASR RHS TAIL LIGHT CRACKED/BUZZER INOP

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

1.00 TAIL LAMP - STOCK 589.95 589.95

OpsId : 30 Job : ASR A3+A4 GUARD POLES LOOSE - RESECURE / TIGHTEN

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

OpsId : 31 Job : ASR SNAIL BRACKET MISSING GRUB SCREEN

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

4.00 HANGER BRKT BLACK 12.73 50.92

OpsId : 32 Job : ASR LH AND RH LOOP KIT WORN

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

2.00 LOOP KIT 595 X 330MM EA - STOCK 26.09 52.18

OpsId : 33 Job : ASR FIRE EXTINGUISHER MISSING FROM TRUCK

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

1.00 4.5KG FIRE EXTINGUISHER - STOCK 77.72 77.72

1.00 9KG FIRE EXT BAG - STOCK 5.98 5.98

OpsId : 34 Job : ASR TURNTABLE TEFLOW PADS WARPED

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

1.00 GREASELESS INSERT KIT CW - STOCK 464.07 464.07

OpsId : 35 Job : ASR A3 + A4 VSTAY BUSHES SPLIT

Cause :

Correction :

0.00 Choose appropriate Labour Guide for type of work to be performed 0.00 0.00

2.00 WISHBONE CONTROL ARM - EX MELB 1,905.85 3,811.70

2.00 LOCKING PLATE 85 4MM DIA - STOCK 33.51 67.02

Component Serial Number

VIN

236932

473909C0619381

W1T96342420506521

YEAR

MAKE

MODEL

IN SERVICE

2021

MB

ACTROS

06/10/2021

Rejected Operations (Cont.)

OpsId : 37 Job : ASR FUEL TANK STRAP INCORRECET

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
1.00	BASE - STOCK	89.64	89.64
1.00	STRAP 62MM W X 1396MM L - STOCK	115.60	115.60

OpsId : 38 Job : ASR D/S LOWER MIRROR COVER MISSING

Cause :

Correction :

0.00	Choose appropriate Labour Guide for type of work to be performed	0.00	0.00
1.00	COVER - STOCK	39.89	39.89