



Sales and Service Detail



RAB00646

Arrangement No:	444-5741	Build Date:	20Feb2019
Mfg Model:	D10T	Factory Ship Date:	25Feb2019
Mktg Model Year:	2019	Dealer/Invoiced Ship Date:	25Feb2019
Year of Manufacture:	2019 (Applies to EU, China, Brazil, India, EEU)	Sales Date:	27Sep2019
Month of Manufacture:	02 (Applies to EU, China, Brazil, India, EEU)	Delivery Date:	30Sep2019
Prod Family:	LT Large Track Type Tractors	Selling Dlr:	K030
Sims Prod Family:	04 Track Type Tractors	Owner Cls:	1
Source Facility:	16 East Peoria Plt (TTT)		
Principle Work:	510 Coal - Surface		



Sales and Service Detail



Group Number	Part Causing Failure	Repairing Dealer	Service Meter Measurement	Repair Date	Work Order Number	Comment
7527	1R-1808	K031	18035 Hours	04Apr2024	2100375368	1800HR Ervice
7527	1R-1808	K031	16124 Hours	19Sep2023	2100345703	16000 Hrs Service
7526	1R-0755	K031	15022 Hours	13Jun2023	2100340687	15 000HRS Service
238-0489	230-3728	K031	14690 Hours	11May2023	2100337317	Attend To Fuel Dilution
7527	139-1537	K031	14061 Hours	07Mar2023	2100328749	14000HRS Service
7760	555-5510	K030	13910 Hours	24Feb2023	OTAP	From 614-8657 To 627-9042
7526	000-7000	K031	13172 Hours	06Dec2022	2100319024	13000HR Service
7606	459-0786	FOTA	11871 Hours	16Sep2022	OTAP	Rem Flash Pn 619-7213 To Pn 625-4518 See Rel Notes
372-4283	2J-0564	K031	9815 Hours	21Aug2022	2100298200	Attend To Left Side Blade Lift Cylinder
7751	PI33318	K030	11317 Hours	16Aug2022	2100266015	
7755	PS47264	K031	11182 Hours	08Aug2022	2100298844	
7755	PS47264	K031	11182 Hours	08Aug2022	2100298844	Ps47264
7526	000-7000	K031	7000 Hours	04Aug2022	2100303352	1000HR Service
7527	000-7000	K031	7000 Hours	31May2022	2100296601	General Service
4101	9G-2991	K031	8935 Hours	18Mar2022	21286892	Attend To Final Drive Slipping
7000	000-7527	K031	8067 Hours	10Jan2022	2100279478	8000 Hour Service
7606	459-0786	FOTA	4702 Hours	08Jun2021	OTAP	Rem Flash Pn 552-6072 To Pn 613-7739 See Rel Notes
7606	380-5288	FOTA	9999999 Hours (Estimated)	22May2021	OTAP	Rem Flash Pn 552-3605 To Pn Unknown See Rel Notes
7755	PS54294	K031	2500 Hours	20May2021	2100227539	Piston Nuts Were Loose On Both Cylinder.
7606	380-5288	FOTA	9999999 Hours (Estimated)	13May2021	OTAP	Rem Flash Pn 552-3605 To Pn Unknown See Rel Notes



Sales and Service Detail



Group Number	Part Causing Failure	Repairing Dealer	Service Meter Measurement	Repair Date	Work Order Number	Comment
7606	380-5288	FOTA	9999999 Hours (Estimated)	07May2021	OTAP	Rem Flash Pn 552-3605 To Pn Unknown See Rel Notes
7606	440-2105	FOTA	4599 Hours	14Apr2021	OTAP	Rem Flash Pn 596-4600 To Pn 604-5666 See Rel Notes
7526	000-7000	K031	4051 Hours	11Nov2020	2100234176	Service
377-6104	349-6089	K031	3403 Hours	19Aug2020	2100221848	
7312	349-6089	K031	3403 Hours	19Aug2020	2100221848	Harness
7606	440-2105	FOTA	2530 Hours	18May2020	OTAP	Rem Flash Pn 560-0261 To Pn 596-4600 See Rel Notes
7527	000-7000	K031	1973 Hours	26Mar2020	2100210695	Service
7751	PI33106	K040	421 Hours	11Nov2019	2100195317	Inspecting And Possibly Cleaning The Hydraulic System
7525	000-7000	K031	485 Hours	09Nov2019	2100197816	Service
7943	No Part Number	K040	10 Hours	30Sep2019		36NKA03630300
7755	PS46162	K040	11 Hours	02Sep2019	2100185269	
7751	PI33041	K040	9 Hours	15Jul2019	2100177968	
7751	PI33041	K040	9 Hours	15Jul2019	2100177968	