



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71459	Station Name: Funk Mechanical
Technician #: 91482	Technician Name: Kyle Bryson
Signing Officer #: 88859	Signing Officer Name: Patty Lindsay

Customer Details:	
Name: Wayne Megli	Address: Box 607, Carrot River, Saskatchewan, S0E0L0

Vehicle Details:	
VIN: 2L9A13380XH003243	Hubometer Reading:
Year: 1999	Vehicle Make/Model: LORNES TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	ID light out, repaired; Front left marker pushed in, repaired;
		x		Reflex Reflectors (6)	Reflectors missing, replaced;
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
		x		Rear Impact Guard (8)	Rear bumper rotting on bottom side, repaired;
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	Middle right brake pot leaking bad, repaired; Red coily hose between trailers leaking, repaired;
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
		x		Tires/Wheels (9)	Front left tire tread low, replaced;
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 1 mm
 Brake(1): No Brake
 N/A
 Wheel2-On : Tire Tread Depth: 15 mm
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .654 in • Cam Rotation: 45.0 degrees • Brake Stroke: 1 1/2 in
 Wheel3-On : Tire Tread Depth: 9 mm
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .471 in • Cam Rotation: 83.0 degrees • Brake Stroke: 1 1/2 in
 Wheel4 : Tire Tread Depth: 9 mm
 Brake(1): No Brake
 N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 7 mm
 Brake(1): No Brake
 N/A
 Wheel2-On : Tire Tread Depth: 9 mm
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .741 in • Cam Rotation: 32.0 degrees • Brake Stroke: 1 1/2 in
 Wheel3-On : Tire Tread Depth: 7 mm
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .556 in • Cam Rotation: 75.0 degrees • Brake Stroke: 1 1/2 in
 Wheel4 : Tire Tread Depth: 9 mm
 Brake(1): No Brake
 N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 3 mm
 Brake(1): No Brake
 N/A
 Wheel2-On : Tire Tread Depth: 8 mm
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .531 in • Cam Rotation: 80.0 degrees • Brake Stroke: 1 1/2 in
 Wheel3-On : Tire Tread Depth: 10 mm
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .688 in • Cam Rotation: 39.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 10 mm
Brake(1): No Brake
N/A

PASS - vehicle passes inspection	Decal # A217542	Inspection Completed Date: 28Oct2025
----------------------------------	-----------------	--------------------------------------