



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71459

Station Name: Funk Mechanical

Technician #: 91482

Technician Name: Kyle Bryson

Signing Officer #: 88859

Signing Officer Name: Patty Lindsay

NOT CERTIFIED

Customer Details:

Name: Wayne Megli

Address: Box 607, Carrot River, Saskatchewan, S0E0L0

Vehicle Details:

VIN: 2L9A13280XH003244

Hubometer Reading:

Year: 1999

Vehicle Make/Model: LORNES TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
	x			Vehicle Identification (5)	Wrong Vin,
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
	x			Lamps (6)	Left side signal box rotten, replaced; ID light out, repaired; Right signal marker out, repaired;
	x			Reflex Reflectors (6)	Reflectors missing, replaced;
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
	x			Wheel Bearings (9)	Rear right hub cap melty, replaced;
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 11 mm
 Brake(1): No Brake
 N/A
 Wheel2-On : Tire Tread Depth: 11 mm
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .537 in • Cam Rotation: 80 degrees • Brake Stroke: 1 1/2 in
 Wheel3-On : Tire Tread Depth: 14 mm
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .542 in • Cam Rotation: 68 degrees • Brake Stroke: 1 1/2 in
 Wheel4 : Tire Tread Depth: 14 mm
 Brake(1): No Brake
 N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 10 mm
 Brake(1): No Brake
 N/A
 Wheel2-On : Tire Tread Depth: 12 mm
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .745 in • Cam Rotation: 25 degrees • Brake Stroke: 1 1/2 in
 Wheel3-On : Tire Tread Depth: 14 mm
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .65 in • Cam Rotation: 47 degrees • Brake Stroke: 1 1/2 in
 Wheel4 : Tire Tread Depth: 13 mm
 Brake(1): No Brake
 N/A

Fail: Vehicle failed inspection. Vehicle is eligible to return to this inspection facility until 27Nov2025 for re-inspection of the failed components.

A vehicle that has failed inspection is unsafe for operation on public roads. This vehicle should not be operated until the repairs or adjustments have been made to restore it to a safe operating condition and a qualified technician has re-inspected the vehicle.