



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

CH-3
SEP

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

MG07

Hr Meter:

Date:

May 15/25

Subcontractor:

Shrum

Description:

Hours

- assist Ian with installation of new upper / lower / and side circle skid replacement
- set table for proper turning
- attach water sword hose in cab (rear window)
- wash grader
- install all panels / stamp parts
- install front cover / fire extinguisher

NO.


QNTS.

Parts/Materials

6 hrs

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Alan Fitzsimon
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

M4-07

Date:

May 14 2025

Hr Meter:

Subcontractor:

CJ Begler

Description:

Hours

- Put new little
drain plug driver side
diff
- Topped off diff
fluid

NO.


QNTS.

Parts/Materials

Diff Fluid

WORK DESCRIPTION

Shop supplies



**A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

Ph: (780) 623-2242
Cell: (780) 623-0340

Shop

Unit No:

Hr Meter:

Date:**Subcontractor:****Description:**

Hours

- Took broken bracket
off, got it welded
by John

- Put bracket back on

- Took skins out		3hrs
for black, bent		
back, put back in,		
tightened back up		


- Helped Shawn
all around

- ~~Put~~ Attached cylinder to rollers -

NO.

QNTS.

Parts/Materials



**A. Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

Allan Przysięzny

Ph: (780) 623-2242

Cell: (780) 623-0340

Site:

Shop

Unit No: NG01

Hr Meter:

Date: May 12/23

Subcontractor: OACM

Description:

Hours


- secure rub points on hyd hoses with hose guard
- install steering wheel panels
- install cab filters / cover
- bend side light so door opens
- press out pin for front wheel tilt cylinder
- install new bushings / pin
- install new hose wrap on GWB hoses
- install front tire (torque 350 lbs)
- remove upper / side / lower table shims.

NO.

QNTS.

Parts/Materials

10/2hrs



2005 LTD.

**A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: Mg-07

Date: May 9 2025

Hr Meter:

Subcontractor: CS Biegler

Description:	Hours
Put - Switched	-
2 hydraulic hoses	
out	
- Put smaller new	
AC line	
- Fixed leak in AC	7.5 hrs
- changed AC	
- Messed around with	
hydraulic hose in steering	
column	
- 2 new hydraulic hoses	
on wheels	
- Put coolant and hydraulic	-

[illegible]

WORK DESCRIPTION

Shop supplies

OK



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Fitzsimony
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: _____

Unit No: *Mg-07*

Hr Meter: _____

Date: *May 8 2025*

Subcontractor: *CJ. Biegler*

Description:	Hours
- switched quick connect	
hydraulic hose out	
for new one	
- Put B&K side	
radiator in	2hrs
- Hooked all hoses up	
- put new fitting	
- Bracket r/h side	
handle back on	
- Another new hose	
- Put new o-rings	

NO.	QNTS.	Parts/Materials
	2	Hydraulic hose

WORK DESCRIPTION

Shop supplies



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Fitzsimon
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No:

Mg-07

Hr Meter:

Date:

May 7 2025

Subcontractor:


CS Biegler

Description:	Hours
- Took handle brackets	-
in engine bay off	
R/h side back	
- unhooked hoses from	
bracket and took	5 hrs
fittings off	
- Drained hydraulic fluid	
- Rechecked broken	
bolt	-

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Fitzsimmons
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

#M607

Hr Meter:

Date:

May 7/25

Subcontractor:

Lon

Description:

Hours

NO.

QNTS.

Parts/Materials

① Troubleshoot belt squeal
↳ Found alternator support bolt
broken causing alternator to shift inward.
That caused belt to be loose and
tensioner not doing anything.

② Drill out broken alternator mounting
bolt. Install new bolt and
put on belt.

2 hrs

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: shop

Unit No: MG-07

Date: May 6/25

Hr Meter:

Subcontractor: Dylan Bogdan

Description:	Hours
drained Rear diff hubs	7
drained Hyd oil tank	
Filled Transmission/	
Hyd tank	
changed Hyd hose	
for Front wheel tilt	
cylinder	
Removed Hyd hose for	
tilt cylinder	
Removed front tires	
changed front hub oil	

NO.	QNTS.	Parts/Materials
	1 1/4 pails	TRANSMISSION oil
	1 1/2 pails	hyd oil
	1	Hyd hose
	14L	differential oil
		TRAVEL:

WORK DESCRIPTION

oil / parts from John Deere,

OK



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Fitzsimmons
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

Mg-07

Hr Meter:

14,826.4 hrs

Date:

May 6, 2025

Subcontractor:

CJ Biegler

Description:	Hours
- Took passenger side hydraulic radiator out	
- Hoses disconnected and capped	
- Took coolant radiator hose off and put new hose	9 hrs
- Took hydraulic hose out and put new	
- Drained coolant	

NO.	QNTS.	Parts/Materials
	1	chunk of Rad hose
	2	Hose clamps
	1	Hydraulic hose

WORK DESCRIPTION

All Shop Supplies besides Hydraulic hose from Sapphire



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M6107

Date: May 6th / 25

Hr Meter:

Subcontractor: Shawn

Description:	Hours
- finished hooking up grease lines and greased wobble wheels	
- helped remove front wheels to access worn out pins	
- removed worn harness and grease lines	
- jacked up front end	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: shop

Unit No: MG-07

Date: May 5/25

Hr Meter:

Subcontractor: Dylan Backassa


Description:	Hours
drained diff/Transmission	-4 hrs
oil	
changed hyd hose in	
steering column	
changed lower intake	
tube That Goes too Bad	

NO.	QNTS.	Parts/Materials
	1	hyd hose
	1	intake tube

WORK DESCRIPTION

use Parts from John Deere,

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Mg-07

Hr Meter: 14,826.4hrs

Date: May 5 2025

Subcontractor: CS Bieder


Description:	Hours
- changed both fuel filters	4hrs
- changed Tranny, hydraulic, Gwd, diff filters	
- changed fuel tank breathe	
- changed fuel strainer and tranny	

NO.	QNTS.	Parts/Materials
	1	Hydraulic filter
	1	Diff filter
	1	Tranny filter
	1	Gwd filter
	1	Fuel strainer
	1	Tranny strainer
	1	Fuel tank breathe

WORK DESCRIPTION

<u>Shop Supplies</u>

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lao La Biche, Alberta T0A 2C0

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M6107

Hr Meter: 14826.4hrs

Date: May 5/25


Subcontractor: Shawn

Description:	Hours
- lift install and Press in	
new brass bushing	
- install pins from wobble wheels	
- lift up wheels to repack bearings	
- repack - 12 wheels grease them.	
new roller pins	
- change out 1 hose for	
steering cylinder	

NO.	QNTS.	Parts/Materials
		3 bushing made by Highmark.

10 1/2 hrs

WORK DESCRIPTION



2005 LTD.

A. Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: MGO7

Date: May 2/23

Hr Meter:

Subcontractor: Shawn

Description:	Hours
- Replace 2 hoses on a/w/o system on front end	
- change out long hose from front end to articulation	
Access hole.	
- repair panels and plates behind cab seat - new bolts and secure panels	
- clean up in cab behind seat	
repair left joystick tension bolts	
for arm rest.	
- try to change hyd hose on oil cooler (wrench hose)	

[illegible]

WORK DESCRIPTION

- painted new spill tray base on nose of gradier
- fewd more like rubbed threw
- and consistent bottom line worn out



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M607

Date: May 1/25

Hr Meter:


Subcontractor: Shawn

Description:	Hours
install protective wrap on	
hoses that have rub points	
- inspect wiring on harness	
under cab beside front windshield	
- paint front end of grader	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M607

Date: April 30/25

Hr Meter:

Subcontractor: Shawn

Description:

Hours

NO.

QNTS.

Parts/Materials

- inspect all hoses for rub points
- mark and tag out all rub points and hoses that need changing
- clean pin pickets for new washings on wobble packer
- blow out cab, and remove cab panels
- switch hyd lines on valve bank for side shift controls on packers
- try to find hyd hose from nose of cab to articulation area
- remove nose panels
- bolt up front fenders

9 1/2 hrs

WORK DESCRIPTION

- remove rear fenders for joint auto rebuild fender brackets





A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: MG07

Hr Meter:

Date: April 29/25

Subcontractor: Shawn

Description:	Hours
- help CJ hook onto wabble	
peelers onto grader	
- take wabble wheel main pins out	
press bushings out	
- bring worn bushing and pin to	
highmark mechanical to get 3 new ones	
made	
- check front end for worn parts	

NO.	QNTS.	Parts/Materials
5hrs		

WORK DESCRIPTION





A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

Mg-07

Date:

April 29 2025

Hr Meter:

Subcontractor:

CJ Biegler

Description:

Hours

- Washed engine bay

- Hoisted up rollers

and Hydraulic hoses

- Washed oil of

rollers

8hrs

- Me even took

rollers separately off

- Took blow motor

out of cab

- Blew out dust

- changed air filter

NO.

QNTS.

Parts/Materials

2

Air filter

WORK DESCRIPTION

OK



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: _____

Unit No: MG-07

Hr Meter: _____

Date: April 28 2025

Subcontractor: CS Biegler

Description:	Hours
- Pressure washed	-
- Pulled all panels off and stub pins	7hrs
- Pulled wing attachment off	
- wrapped hoses up	
- Pulled wing attachment in the back off	
- Put back plate back on	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

OK



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: meg energy

Unit No: M6-07

Date: April 22/25

Hr Meter: 14,797 hrs


Subcontractor: Dylan Bourassa

Description:	Hours
changed engine oil/ filter	1 hr

NO.	QNTS.	Parts/Materials
	27L	5W40 oil
	1	oil filter
		TRAVEL: 

WORK DESCRIPTION

oil from 4FA,
filter from C-CAN,



**A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

Site:

Meg

Unit No: # MGO7


Hr Meter:

Date: April 9/25

Subcontractor: Lane

[illegible][illegible]

WORK DESCRIPTION



2005 LTD.

**A. Division of 848875 Alberta Ltd.
Box 247, Lao La Biche, Alberta T0A 2C0**

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Meg

Unit No:

MG-07

Date:

April 7/25

Hr Meter:**Subcontractor:**

∴ Total

Description:	Hours
① Troubleshoot why all upper cab work lights not working. ↳ check fuses - good. Disconnect lights and test for power / ground - good Will order new lights.	
② Troubleshoot why belt squeals ↳ Squealing only occurs when A/C is kicked in. Tensioner is weak. Ordered parts.	
	(1 1/2 hrs)

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg energy

Unit No: MG-07

Date: March 23/25

Hr Meter: 11,499

Subcontractor: Dylan Bortassa


Description:	Hours
Installed Hyd hose	2 hrs
From Nose in Neck	
Hyd Junction too	
Blt side wheel	
Cleaned off	
zip tied hyd hoses /	
Put Bqb protectors	
ON	
Put Panels Back	
ON	

NO.	QNTS.	Parts/Materials
	1	Hyd hose

WORK DESCRIPTION

Hyd hose Made At Sapphire,

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg energy

Unit No: MG-07

Date: March 22/25

Hr Meter:

Subcontractor: Dylan Barragosa


Description:	Hours
changed Hyd hose	- 2hrs
for front RH wheel	
Removed Rubbed	
out Hyd hose going	
too RH front wheel	

NO.	QNTS.	Parts/Materials
	1	Hyd hose (from sapphire)

WORK DESCRIPTION

Hyd hose from sapphire,

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Mag energy

Unit No: MG-07

Date: March 6/25

Hr Meter: 14,324 hrs

Subcontractor: Dylan Bourassa

Description:	Hours
took Apart steering	1.5 hrs
column to examin hyd	
hose leak	
Got hyd hose ordered	1 hrs
Put steering column	
Back together	
Tryd drilling out	1 hrs
Bolts that snapped	
off for hose Bracket	
under turn table	

NO.	QNTS.	Parts/Materials
		TRAVEL:

WORK DESCRIPTION

oil/ Filter out of Me-O₃



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Site services (Meg energy)

Unit No: MG-07

Date: February 11/25

Hr Meter: 13,951 hrs

Subcontractor: Dylan Barrassa

Description:	Hours
Removed cutting edges ON Blade	5 hrs
Disconnected wing to take off	
took hyd hoses off for wing cylinder	
took off wing	
checked lights	
changed Right side work light bulb	
changed Reverse lights	

NO.	QNTS.	Parts/Materials
	1	LED light bulb
	2	LED light bulb
		TRAVEL:

WORK DESCRIPTION

LED light bulb from MC-03,



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Mea Pad MC

Unit No: #MGO7

Date: Feb 10/25

Hr Meter:

Subcontractor: Tom L

Description:	Hours
① Replace alternator	(2 hrs)
② Boost batteries	
③ Start machine, test battery/alternator operation — all good	

NO.	QNTS.	Parts/Materials
	x/	alternator (Brandt)

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: site services

Unit No: MG-07

Hr Meter: 13,861 hrs

[illegible]

Date: February 6/25

Subcontractor: Dylqn Bourassa

[illegible]

WORK DESCRIPTION

Hyd hose. Ian Got made,



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: site services (Meg energy)

Unit No: MG-07

Date: February 3/25


Hr Meter:

Subcontractor: Dylā N Bōrāssq

[illegible][illegible]

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Unit M607 grader

Date: Jan 14/25

Hr Meter:


Subcontractor: Shaun

Description:	Hours
- retorque sandvicks boards	
- replace worn sandvicks	
- remove upper saddle yoke arm	
- cut out worn bushings	
- install new bushing and seals	
- re-install saddle yoke arm	
- torque bolts	

NO.	QNTS.	Parts/Materials
		Darton - sandvicks 1 bucket

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: 1607

Date: DEC 9/24

Hr Meter:

Subcontractor: Shawn


Description:	Hours
- Finish installing the wing hoses, brackets	
- wrap hoses with hose guard	
- install front work sign	
- tighten hoses for hyd lines	
- install wear strips on hyd lines	
- install front blade, shims and hardware	
- hook up hyd lines for blade set blade shims.	

NO.	QNTS.	Parts/Materials

6 1/2 hrs

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

MG-07

Date:

December 5-2024

Hr Meter:

Subcontractor:


CJ Biegler

Description:	Hours
- Took old hoses	-
off for side	
blade	
- Me, Shawn and	
Al put blade on	9hrs
- Put all new hoses	
- Messing around to	
find out which	
hose goes where	+

NO.	QNTS.	Parts/Materials
	9	Hoses

WORK DESCRIPTION


Sapphire Supplies



REPAIR REPORT

[illegible]

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: _____

Shop

Unit No:

MG-07

Date:

~~November~~ *December 2 2004*

Hr Meter:

Subcontractor:


CJ Biegler

Description:	Hours
<i>- Took hydraulic lines off</i>	<i>1hr</i>
<i>- Pin for sliding cylinder / too big</i>	
<i>- Blade off</i>	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: #M607

Hr Meter:

Date: Nov 21/24


Subcontractor: Jan

Description:	Hours
① Replace tranny cooler hoses and bulkhead fittings.	
② Replace x2 hyd. hoses for fan motor. ↳ Bulkhead coupler for case drain hose is sweating. Ordered new fitting	
③ Assist with repair and replace of rear light harness.	
	6 1/2 hrs

NO.	QNTS.	Parts/Materials
	x1	lower harness (Brandt)
	x1	upper harness "
	x2	bulkheads STC "
	x2	cooler hoses "
	x2	fan hoses "
	x4	light grommets "

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Mre

Unit No:

MG07

Date:

Nov 2/24

Hr Meter:

Subcontractor:


IonL

Description:	Hours
① Replace T-stat return hose that goes to reservoir.	
	1 1/2 hrs

NO.	QNTS.	Parts/Materials
	x 8	5/16 hose (5mtr)

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg

Unit No: #M607

Date: Oct. 7/24

Hr Meter:

Subcontractor: Jon L

Description:

Hours

NO.

QNTS.

Parts/Materials

① Replace oring on RH front wheel hose

x1 P/2 oring

② Replace upper table shims

x4 brass wear strips


③ Drill out broken bolt for circle swivel guard

x2 LED lights

④ Replace burnt out headlights with LED lights

3hrs

WORK DESCRIPTION



2005 LTD.

**A Division of 848875 Alberta Ltd.
Box 247, Lao La Biche, Alberta T0A 2C0**

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Mrq

Unit No:

M607

Date:

Sept. 3/24

Hr Meter:

13013 hrs.

Subcontractor:


Lucy

Description:	Hours
① Replace leaking AWD hose on front R/H wheel.	
② Assist with AWD hose replacement on front L/H wheel	
	1 1/2 hrs

[illegible]


WORK DESCRIPTION

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lao La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0346



2005 LTD.

**A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

Allan Przysiezný
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Meeg

Unit No:

Date:

Hr Meter:

Subcontractor:

[illegible][illegible]

WORK DESCRIPTION

[illegible]



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: shop

Unit No: MG-07

Hr Meter: 21,415 hrs

Date: July 24/24


Subcontractor: Dylan Boarassa

Description:	Hours
removed panels	7
greased attachment	
drained hyd oil	
changed o-ring	
for hyd pump	
put hyd oil in	- 6 hrs
pressure washed	
put panels on	
started to take	
panels out of cab	
to see why	
washer fluid	
is leaking	

NO.	QNTS.	Parts/Materials
	1	Grease tubes
	1	o-ring
	2	Bolts/washers
		TRAVEL:

WORK DESCRIPTION

Grease from shop supplies,
parts from John Deere.



**A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

Site: MEG

Description:	Hours
Tightened up loose blade by adjusting table shims	1h

[illegible]



**A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: MEG SITE

Unit No: MG07Hr Meter: _____

Date: July 11/24

Subcontractor: Shawn

Description:	Hours
A/c compressor broken	
and belt	
remove panels	
drain A/c system	
remove fan belt	
remove A/c Compressor	
install new compressor / belt	
re-assemble	
re-charge A/c system	
R134 - (5.25/bs)	

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: shop

Unit No: 19-07

Date: June 21/24


Hr Meter: 12,465.5 hrs

Subcontractor: Dylan Boykassa

Description:	Hours
Greased/ Filled	-5 hrs
4P Tires with	
Air/ Tightened	
down sign for	
Packer on Back	
hooked up hyd	
lines for heat	
Attachment	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: MG-07

Hr Meter: 12461.6 hrs

Date: June 4 2024

Subcontractor: CJ Biegler

[illegible][illegible]

WORK DESCRIPTION

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

Site:

Mr

Unit No: th M607

Date: May 15/24

Subcontractor: Land

Hours

NO.

QNTS.

Parts/Materials

① Troubleshoot why blade pitch function not working

- ↳ Check joystick control and signal - good
- ↳ Check for signal @ solenoids - zero
- ↳ Follow wiring and inspect.
- ↳ Followed troubleshooting tree for incentive codes relating to problem


Possible. AUC controller faulty or needs programming

(3 1/2 hrs)

3 1/2 hrs

TRAVEL:

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: STEP

Unit No: MG07


Hr Meter: 12,272.2 hrs

Date: April 17/24

Subcontractor: Shawn

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340


Unit No: MG07

Date: April 16/24

Hr Meter: 12272.4 hrs

Subcontractor: Shawn

[illegible]



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

REPAIR REPORT

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

Site:

Unit No:Hr Meter:

Description:

Description:	Hours
--------------	-------

Date:Subcontractor:NO.

QNTS.

Parts/Materials

DAYTON

42254

Sapphire


oms	

		TRAVEL.
--	--	---------

WORK DESCRIPTION

- Adyast

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M9-07

Date: April 15/24

Hr Meter: 12272.4 hrs

Subcontractor: Dylan Boudryssa

Description:	Hours 2.5
changed hydroil filters	4 hrs
changed fuel filters	
Flashed TRANSMISSION	
two times	
Pqt door panelson	


NO.	QNTS.	Parts/Materials
	2	hydroil filter
	2	Fuel filters
5 pals	2	TDH Tractor fluid
	2	TRANSMISSION filters

WORK DESCRIPTION

Filters from shop supplies/ Dayton Parts/ Sapphire.

TDH Tractor Fluid from Dayton Parts.

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Mg-07

Date: April 12/24

Hr Meter: couldn't get hours


Subcontractor: Dylan Baurassa

Description:	Hours
Pgt engine in	4hrs
Pgt engine maint's	
ON/ Bolted Trng	
to engine with	
Ian	
hooked 4P wires/	
hoses/ pipes	
Pgt plates on/	
brackets	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: #MG07

Date: April 12/2024

Hr Meter:

Subcontractor: Ione

Description:	Hours
① Clean tranny bellhousing	
② Install engine into machine and bolt up transmission	
③ Connect hoses, wiring, plumbing	
④ Fill with engine oil and coolant	
	6 1/2 hrs

NO.	QNTS.	Parts/Materials
	x30L	5W40 eng. oil
	x1	B7335 MP6 oil filter
	x1	tube silicone
	x1	tube blue loctite

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Mg-07

Date: April 11/24

Hr Meter: couldn't get work

Subcontractor: Dylan Backus


Description:	Hours
Cleaned old oil	
Pan Gasket off/	
helped Ian change	
crank case seal	
Put gert / housing	4 hrs
Back on	
Put oil Pan on	
Preped engine	
Bay to Be Washed	

NO.	QNTS.	Parts/Materials
	1	housing gasket
	1	oil Pan ^{7100PM} Gasket
6.2 hrs		

WORK DESCRIPTION

Ian ordered parts.

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

#M607

Date:

April 11/24

Hr Meter:

Subcontractor:

Iron

Description:

Hours

NO.

QNTS.

Parts/Materials

① Install oil pan and rear bell housing

x1 oil pan gasket

x1 bell housing gasket

② Install rear crank seal


x1 rear crank seal

x1 crankseal housing gasket

2 hrs

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

M607

Date:

April 8/24

Hr Meter:

Subcontractor:

Low

Description:

Hours

NO.

QNTS.

Parts/Materials

① Remove hood, panels

② Drain coolant and remove plumbing


③ Disconnect wiring, fuel lines and
A/C compressor

④ Unbolt transmission and remove
engine.

6 1/2 hrs

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M9-a7

Date: April 10/24

Hr Meter: couldn't get hrs


Subcontractor: Dylan Borkowski

Description:	Hours
took engine housing/ oil pan off/ Gear	- 2 hrs
cleaned off	
housing / oil pan	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiechny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

#MG07

Date:

March 26/24

Hr Meter:

Subcontractor:

Ionel

Description:

Hours

① Remove snow wing

2 hrs

NO.

QNTS.

Parts/Materials

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meq

Unit No: #M607

Date: Feb 23/24

Hr Meter:

Subcontractor: Joe

Description:

Hours

① R-R turbo to muffler sleeve
collar and v-clamp

② Install two new belts and washers
for rear fan shroud door.

(2 1/2 hrs)

NO.

QNTS.

Parts/Materials

x1 sleeve (Bendt)

x1 clamp "

x2 bolts "

x2 wide washers "

TRAVEL:

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Ph: (780) 623-2242
Cell: (780) 623-0346

REPAIR REPORT

Site: Meg

Unit No: # MG07Hr Meter: _____[illegible]

Date: Feb 18/24

Subcontractor: Ianl

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Sh. Mea

Unit No:

o: #MG-07

Date:

Feb 8/24

Hr Meter:

Subcontractor:

Tenl

Description:	Hours
① Install transmission cooler, both hoses and bulkheads.	
② Top up transmission oil. Run machine, check for leaks.	2 hrs

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Mea

Unit No: #MG07

Hr Meter:

Date: Feb 1/2024

Subcontractor:

Icon L

Description:

Hours

NO.

QNTS.

Parts/Materials

- ① Troubleshoot rough running engine
 - ↳ Injector 4,5,6 codes
 - ↳ Accelerator pedal code
 - ↳ Turbo Hi temp code
- Chase electrical problem. Found ECM connector lock wash worn and connector had come out of its socket. Re-connect and secure with zip ties.
- All codes cleared and engine runs as it should.
- ② Install one circle shoe that had fallen off.

(2 hrs)

x 4 1" x 5 1/2 bolts (Sapphire)

x 4 1" washers (Dayton)

TRAVEL:

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

o: # MG07

agades

Date:

: Jan 24/24

Hr Meter:

Subcontractor:

Tal

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: # MG07 grader

Date: Jan 23/24

Hr Meter:

Subcontractor: ZonL

Description:	Hours
① Begin removing inside panels to access heater coolant valve	
	(1/hr)

NO.	QNTS.	Parts/Materials
		TRAVEL :

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: M9-07

Hr Meter: 11621.6_{hrs}

Date: JUN 22/24

Subcontractor: Dylan Boarasso

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No. # MG07 J. Dreere

Date: Jan 22/24


Hr Meter:

Subcontractor: Ian L

Description:	Hours
① Replace AWD hose (pump to bulkhead)	
② Blow out drain hole for center cavity to drain out water/oil	
③ Run and operate machine in yard to get to temperature	
④ Check for leaks and re-check fluid levels ↳ confirm leak coming out of heater box	
	6 hrs

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: # M607 J. Duerr

Date: Jan 18/24

Hr Meter:

Subcontractor: Lent

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M607

Hr Meter: 11621.6hrs

Date: January 19 2024

Subcontractor: Shaun.

Description:	Hours
- change oring on front tilt steering hose.	
- loosen blade shims install used lower brass shims, retighten bolts and table.	
- remove broken bolts from small orbit motor on blade install new one	
- rebuild motor gear and install under swing table.	
- install new belt	
- install guards shields	
- recharge A/C pump. (leak)	

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Mg-07

Date: JAN 18/24

Hr Meter: 11621.6 hrs


Subcontractor: Dylan Boudreau

Description:	Hours
FINISHED PUTTING	
stuff back together/	
ON engine	
Put engine casing ON	
zip tied up wires	
changed TRANNG oil	3.5 hrs
changed TRANNG oil filter	
changed engine oil	
changed engine oil filter	
Put coolant in	
topped off hyd oil	
preped to Be started	

NO.	QNTS.	Parts/Materials
		zip ties
	22L	22L TRANNG oil
	1	TRANMISSION oil filter
	1.5 gals	5W40 engine oil
	1	engine oil filter
	12L	12L of coolant
	3L	hyd oil
		TRAVEL:

WORK DESCRIPTION

Part's/ suppl's from Part's room



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny

Ph: (780) 623-2242

Cell: (780) 623-0340

Site: SHOP

Unit No: MGO7

Hr Meter: ?

Date: Jan 17/24

Subcontractor: Shawn

Description:	Hours
- begin to install engine	
bolt up to tranny.	
- remove engine to retread Alignment	
bolts	
- re install engine / sealant.	
- install mounts, brackets	
- install hyd hoses and filter	8 hrs
- correct wiring hardware	
- correct coolant lines	

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

#M607

grader

Date:

Jan 17/2024

Hr Meter:

Subcontractor:

Loni

Description:

Hours

① Install engine into machine. Bolt
up transmission and mounts.

② Install engine components on LH side

6 hrs

NO.

QNTS.

Parts/Materials

TRAVEL:

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: 19-07Hr Meter: 11621.6 hrs

Date: JUN 12/24

Subcontractor: Dylan Bortasso

[illegible][illegible]

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

REPAIR REPORT

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

Site: Shqp

Unit No: 19-07

Hr Meter: 116 $\pm$ 1.6 hrs


Date: Jan 5/24

Subcontractor: Ngilan Bayrassq

Description:	Hours
took motor mounts off/	3.5 hrs
rest of hoses	
caped off hoses/lines	
took Tmng to engine	3.5 hrs
Belts out	
Pulled out Motor	
Blowed out debris	
Pressure Washed	
engine/engine bay/	
under cage of Grader	

[illegible]

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

REPAIR REPORT

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

Site: Shop

Unit No: 19-07

Hr Meter: 11621.6 hrs

Date: JAN 4/24

Subcontractor: DylaN Boerqssa

Description:	Hours
took off Panels /	7.5 hrs
Frames around engine	
unhooked hoses / wires /	
Pipes / mounts	
connected to motor	
Drained coolant	
took off motor	
Mounts	
started to take	
Bolts off Trans	
connected to motor	7.5 hrs
Fixed leak (hose)	

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: # MG07


Date: Jan 4/2023

Hr Meter:

Subcontractor: Ion L

[illegible][illegible]

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: #MG07 J. Deere

Hr Meter:

Description:	Hours
① Test engine blow by pressure.	
② Check all service coils.	
③ Inspect machine for leaks.	
	3 hrs

Date: Jan 2/2023

Subcontractor: Lonl

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: SHOP

Unit No: M607 JD GRADER

Date: Jan 2 / 24

Hr Meter: 11621.6 hrs

Subcontractor: Shawn

Description:	Hours
- remove upper sideshift table wearshims	
- remove setter bolts and replace with new one's	
set table slack and re-install shim guards	4 hrs
- remove fuel lines and inspect for leaks	

NO.	QNTS.	Parts/Materials
3	bolts	Inv 41521
4	nuts	\$ 59.69
		TRAVEL:

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340


Unit No: Mg-07

Date: Jan 2/24

Hr Meter: 11621.6 hrs

Subcontractor: Dylan Baykassa

[illegible]



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Me.

Unit No:

#MG07 J. Deere

Date:

Nov 23/2023

Hr Meter:

Subcontractor:

Lon L.

Description:

Hours

NO.

QNTS.

Parts/Materials

① Install new triangle slow moving sign @ rear of machine.

 $x/$


Sign

(Brandt)

 $\frac{1}{2}hr$

TRAVEL:

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0


Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

Unit No: *MG-07*

Date: NOV 15/23

Description:	Hours
change oil seals on blade	4
change oil seals on locking pin	4
wash it off	2
put covers back on	1
help Ashut erul shams	1

[illegible]



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

Unit No: MG07 J. Deere

Date: 11/06/2023

Hr Meter: 11095

Subcontractor:

[illegible]



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: shop

Unit No: MG
CM-07


Hr Meter:

Date: Nov 14 / 23

Subcontractor: Will Rashman

[illegible][illegible]

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

REPAIR REPORT

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

Site:

Shop

Unit No: #1607 J. Deere

Hr Meter:

Date: Nov 14/2023

Subcontractor: Land

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: shop

Unit No: ~~GM~~-07

Hr Meter: 000000

Date: Nov 13 / 23

Subcontractor: Will Rosborough

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Mg-07

Date: November 13/23

Hr Meter: 11,092.9 hrs

Subcontractor: pglan Boarassg

Description:	Hours
Fixed steering wheel	}
tilt/shock	
change oil/fuel filters	
oil filter	
checked all fluids	
hooked up side Plaw	7 hrs
Brace/ Blade frame	
and Blade	
hANNed hydraulic lines/	
hooked up for side	
mount Blade	
Put hose wear	
Protecters on hyd line's	

NO.	QNTS.	Parts/Materials
	1	6 gallons of 5W40/ fuel filter
	1	oil filter
		zip ties/ pieces of hose
		TRAVEL:

WORK DESCRIPTION

Supply's from parts room in Shop.

Change Hydraulic Lines TILT Lines
4 of them on Grader Pass U-Bolt
So No Further Problems



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meag

Unit No: # MG01 J. Deere 872GP

Date: Oct. 23/23

Hr Meter:

Subcontractor: Lon

Description:	Hours
<u>Replace alternator</u>	
	<u>(1 hr)</u>

NO.	QNTS.	Parts/Materials
	<u>x1</u>	<u>alternator</u>
		<u>TRAVEL :</u>

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Mig

Unit No: # M607 872GP grad-der

Hr Meter: _____


Date: Oct. 22/2023

Subcontractor: Ion L

[illegible]

NO.	QNTS.	Parts/Materials
x1	bolt hook	(Brandt)
x1	nut	(Brandt)
x1	washer	(Brandt)
x2	1/2 clamps	
		TRAVEL :

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieczn
Ph: (780) 623-224
Cell: (780) 623-034

REPAIR REPORT

Site:

Meo

Unit No:

#MG07 J. Deer 8726

Date:

Dec. 3/2023

Hr Meter:


Subcontractor:

Tom

[illegible][illegible]

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg

Unit No: #MG07 J. Deere 872GP

Date: Sept. 6/2023

Hr Meter:


Subcontractor: IonL

Description:	Hours
① Replace R/H armrest micro switch for hydraulic lock out	
② Replace cab air filters	1 hr

NO.	QNTS.	Parts/Materials
	x1	Switch (Brendt)

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meq

Unit No: #MG07 J. Deere 872gp

Date: Sept. 2/23

Hr Meter:

Subcontractor: Ian L

Description:	Hours
① Replace gas-shock for steering column	
	1 1/2 hrs

NO.	QNTS.	Parts/Materials
	x/	Shock (Brenett)
	x/	Spring (Brenett)
	x/	detent (Brenett)

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: MG07

Hr Meter: 9760.8hrs

Date: April 26/23


Subcontractor: Shawn

Description:	Hours
Build 2 support brackets for roof panels to stop rear side from sagging down	
re assemble roof panels hook up lights,	5hrs

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

MG07

Hr Meter:

9760.8hrs

Date:

April 25/23

Subcontractor:

Shawn.

Description:

Hours

- change all filters
- install output shaft seals
- install drive line U joints
- repair foil cover on door panel.
- start engine check for leaks
- install 2 door panels
- remove fresh air fan to clean
- remove roof panel to see why its sagging down
- broken bolts need to be repaired

NO.

QNTS.

Parts/Materials

See invoice Sapphire


- 011-035709

- 011-035712

9 hrs

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M607

Date: April 24/23

Hr Meter: will get hrs when it get running

Subcontractor: Shaun.

Description:	Hours
- Complete engine install	
- mount bolts / hardware	
- coolant line	
- fuel lines	
- install output shaft seals	
- install harnesses, electrical plugs	
- roof panels / side panels	
and alternator	

NO.	QNTS.	Parts/Materials

6 1/2 hrs

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: SHOP

Unit No: MG07

Date: MARCH 28/23

Hr Meter:


Subcontractor: Shawn.

Description:	Hours
- change 2 zerts on passenger side front end	
- grease grader	
- paint front counter weight and blade attachment	
- torque front counter weight bolts to 280lbs.	
- inspect shims on table / gear circle	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

MV

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: MG07

Date: March 23/23

Hr Meter: —


Subcontractor: Shawn

Description:	Hours
- remove head / exhaust on engine	
- coolant pump removed	
- pull off oil pan	
- clean up parts / gaskets etc	
- remove tranny plate on engine	
- remove seal from engine to tranny plate	9 1/2 hrs
- clean up spring pack / housing	
- clean off block with razor blade	
- hoist engine in air inspect for cracks	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Poudre, Alberta T0A 2C0

REPAIR REPORT

Site: SHOP

MU
Allan Przysiezny

Ph: (780) 623-2242

Cell: (780) 623-0340

Unit No: M1607

Date: March 27/23

Hr Meter:

Subcontractor: Shawn.

Description:

Hours

- Remove steering column
change out tilt cylinder, spring
and uni ball
- repair 12v cig lighter tighten
all panels in cab
- install new hose guard on front and
hoses
- Reinstall rear panels / bolts.
- install new mud flaps and
repair front fenders
- install new front counter weight.
- repair front steering boot / clip
- remove exhaust manifold from head (pack up for shipping).

NO.


QNTS.

Parts/Materials

9 1/2 hrs

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

mv
Allan Przysiezhy
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: MG07

Date: March 24/23

Hr Meter:


Subcontractor: Shawn.

Description:	Hours
- clean up engine parts, head valve cover etc	
- paint and install rear flay on bumper	
- disconnect wing hoses, cap them and remove wing attachment and support brackets	7 1/2 hrs
- rip apart right front wheel drive harness found short and respliced together	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

REPAIR REPORT

Site: SHOP

M. W.

Allan Przysiezny

Ph: (780) 623-2242

Cell: (780) 623-0340

Unit No: MG07- JD GRADER

Date: March 21/23

will have hrs once engine back in
Hr Meter:


Subcontractor: Shawn

Description:	Hours
- Bring grader in shop	
- Remove outer panels, Exhaust, Engine roof panel, Air filter housing.	
- drain coolant, Engine oil, transmission oil	
- remove all parts, wiring to pull engine out	10 hrs
- remove all transmission bolts	
- Set up jack under transmission.	
- clean up floor around grader.	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

- noticed oil leak from rear diff output shaft seal
- some hoses rubbed thru.



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

REPAIR REPORT

h.v.

Allan Przysięzny

Ph: (780) 623-2242

Cell: (780) 623-0340

Site: Shop

Unit No: MG07

Hr Meter: no hrs yet

Date: March 22/23


Subcontractor: Shawn

Description:	Hours
- remove hyd hoses, and engine mounts	
- Set up overhead crane to remove engine.	
- remove engine set up on stands	
- plug off all lines for washing	
- wash inside engine compartment	
clean up floor	
- remove leaky hoses replace with new ones.	
- remove drive shaft and seals.	
clean up mess.	

[illegible]

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: SHOP

Unit No: M607

Date: DEC 5/22

Hr Meter:


Subcontractor: Shawn P.

Description:	Hours
- Remove driver front tire	
take to ok-tire for repair	
- install step bolts	
- tightend wind bolts	
- secure aux hyd hoses	
- reinstall front tire	
torque 300lbs.	2hrs

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT


Site: L.L.B. Shop

Unit No: <u>MB MG-07</u>		Date: <u>Nov 24 2021</u>		
Hr Meter: <u>8765 hrs</u>		Subcontractor: <u>Gerald Helaychuk</u>		
Description:	Hours	NO.	QNTS.	Parts/Materials
<u>From Blant Tractor</u>			<u>4</u>	<u>SHIMS Shims</u>
<u>FROM Sepphire</u>			<u>1</u>	<u>Hydraulic oil Filter</u>

WORK DESCRIPTION

<u>Change All Four Bottom Shims on moleboard, Blow out Reds</u>
<u>Change one Hydraulic oil Filter, Change 4 Coolant hose</u>
<u>Clamps, grease grader complete</u>
<u>Not complete</u> <u>4.0 hours</u>

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: L.L.B Shop

Unit No: MB-07

Date: Nov 23 2022

Hr Meter: 8765 Hrs

Subcontractor: Gerald Helagochuk

Description:	Hours
<u>Oil's from stock</u>	

NO.	QNTS.	Parts/Materials
	<u>25</u>	<u>Litres Hydraulic oil</u>

WORK DESCRIPTION

~~Put Betty~~ put stump puller's Back on end all other Removable panels, Run a Tap Through all the Holes needed to be used for Brees for the wing, Top Hydraulic oil, Remove Top small Hose and Fittings Re Seal

Not complete

3.0 Hours



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: LLB Shop

Unit No: <u>MG-07</u>	Date: <u>Nov 21 2022</u>
Hr Meter: <u>8765 hrs</u>	Subcontractor: <u>Gerald Melapchuk</u>

Description:	Hours

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

<u>Remove All side panels, unbolt pull out Rads and Remove</u> <u>Stump pons</u>
<u>not complete</u>
<u>1-hour</u>



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: LLB Shop

Unit No: MG-07

Date: NOV 17 2022

Hr Meter: 8765 Hrs

Subcontractor: Genel Melnychuk

Description:	Hours
From Brant tractor →	
From Sapphire →	

NO.	QNTS.	Parts/Materials
	2	Cab filters
	4	Work lights

WORK DESCRIPTION

Replace Left & Right Lights by steps, Replace Left & Right
Lights @ above turn table, Replace cab air filters, Help put
wing on and Hydraulic cylinder

not complete 4.5 hours



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: LLB Shop

Unit No: MG-07

Date: NOV 15 2022

Hr Meter: 8765 Hrs

Subcontractor: Gerald Helnychuk

Description:	Hours
<u>part from Brant</u>	

NO.	QNTS.	Parts/Materials
<u>2</u>	<u>2</u>	<u>engine Air Filter</u>
<u>2</u>	<u>2</u>	<u>Fuel Filters</u>
<u>3</u>	<u>3</u>	<u>Hydraulic Filters</u>

WORK DESCRIPTION

Change engine air Filter, fuel filters, and Hydraulic filters	
not complete	2-0 hours



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: _____

Unit No: MG07 Grader.

Hr Meter: 8159hrs


Date: July 25/22

Subcontractor: Shawn.P.

Description:	Hours
- remove old micro switches and harness for passenger joystick	
- install new harness and switches	
- drain tranny fluid into pails	
- remove Ujoints and drive link	
- remove tranny seals	7hrs
- install new seals	
- re-install Ujoints / drag link	
- refill tranny oil	
- remove upper table shims bolts	
lube up and re install	

NO.	QNTS.	Parts/Materials
		Previous order from Brent, rework
		clear invoices that were previously

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny

Ph: (780) 623-2242

Cell: (780) 623-0340

Site: L-L B STOP

Site: L-L B STOP


[illegible]

WORK DESCRIPTION

Put new engine Rad in and other Rads Fan shroud and all other
stuff to keep Rad in place, put all doors back on, Fill with
Coolant, put stamp pans back on

not complete. 4. hours

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: MG07

Hr Meter: 8159hrs

Date: July 22/22

Subcontractor: Shawn P.

Description:	Hours
* install radiator, air cooler	
attach hoses, clamps	
guards and brackets	
→ cleaned up by trony	
* rad tank check while	6hrs
grader was running	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

output shaft seal seeping on trony.
- all rads are clean and good to go.

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: SHOP

Unit No: M607

Date: JULY 21/22

Hr Meter:

Subcontractor: Shawn

Description:	Hours
- Wash and degrease grader	
- blow out all dirt from engine and under carriage	
	6 hrs

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: SHOP.

Unit No: MG07

Hr Meter:

Date: July 20/22

Subcontractor: Shawn.

Description:	Hours
- help and assist Gerald with removal of coolant radiator (Heat exchanger)	
- remove all panels	
stump pen's	
- began blowing out dirt / dust around engine bay	
	3 hrs.

NO.	QNTS.	Parts/Materials
		Brant Env
		OG. 4655617
		\$ 4279.31
		no core on rad.

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: L.L.B. Shop

Unit No: MG-07

Date: July 20 2022

Hr Meter:

Subcontractor: Gerald Melnyk

Description:	Hours

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

Dro's coolant and take all Rib mounts and supports out	
not complete	4.5 hours



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: ~~March~~ L. L. B. Shop

Unit No: 8726P MG07.

Hr Meter:

Date: March 15 2022

Subcontractor: Gerald Melnychuk

[illegible][illegible]

WORK DESCRIPTION

Remove front cover take old fan Belt off, Reattach
Edler pulley put new one on wrong one, change back
to old one put new belt on

2 hour

7.5.4.08



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M607 872G

Date: MARCH 10 2022

Hr Meter:

Subcontractor: Shawn P.

Description:

Hours

- remove 3 main boom lines and replace with new ones
- remove side guards and curtains
- remove stump pen's and blow and clean out dirt in under carriage
- blow out valve bank on top of blade
- help prep engine for removal.
- clean up shop, set up blade shims.

NO.

QNTS.

Parts/Materials

10 1/2 hrs

TRAVEL:

WORK DESCRIPTION