

REPAIR REPORT

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

Site:

Subcontractor: Law L

Description:	Hours
① Replace rubbed out cylinder hyd. hose.	1/4 hr
② Remove quick attach cylinder access cover. Locate oil leak. ↳ Fittings ORB jam nut loose. Ice and snow accumulation loosened the fitting. Readjust fitting position and tighten.	
③ Top up hyd. oil level	1 1/2 hrs

[illegible]

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Mag energy

Unit No: WL-06

Date: March 5/25

Hr Meter: 7,565 hrs

Subcontractor: Dylan Boarass

Description:

Hours

'cat Bolts off

For Blade too

Remove Blade cutting
edges

— 265 —

installed new cutting
edges

NO.

QNTS.

Parts/Materials

2

Middle cutting edges

2

end cutting edges

TRAVEL:

WORK DESCRIPTION

cutting edges from shop,

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: site services (Meg energy)

Unit No: WL-06

Date: February 28/25

Hr Meter: 7,502 hrs

Subcontractor: Dylan Bourassa

Description:	Hours
changed oil/ oil	}
filter	
Cleaned oil off	
sid of engine/	-1.5 hrs
diff	

NO.	QNTS.	Parts/Materials
	28L	5W40 oil
	1	engine oil filter
		TRAVEL:

ORK DESCRIPTION

oil / Filter out of MC-03,

big Hyd base from Deere, small Hyd base from sapphire,



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Site services (Meg energy)

Unit No: WL-06

Date: February 20/25

Hr Meter: 7,423 hrs

Subcontractor: Dylan Bagrassg

Description:	Hours
Removed hgd hose for	} <u>2 hrs</u>
Bucket weighing/capped	
off lines	
Boosted/Heated engine	
to start	} <u>6 hrs</u>
changed 2 small hgd	
hoses by drive shaft ^(Front)	
changed RH lift	
cylinder Hydraulic	} <u>6 hrs</u>
hoses	
Filled hgd oil	
Banned to test for	
any leaks,	

NO.	QNTS.	Parts/Materials
	2	hgd hoses
	2	Hgd hoses
	1/2 pale	Hgd oil
		TRAVEL:

WORK DESCRIPTION

Hgd hoses from John Deere,
Hgd oil from C-can,



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Site services Meg energy

Unit No: WL-06

Hr Meter:

Date: February 19/25

Subcontractor: Dylan Boatass


Description:	Hours
Heated 4P engine	7
Boosted Batterys	
Got started	
changed main lift	
- cylinder hyd hose	
changed O-Rings for	
hoses/ the fittings	
That were taken off	9 hrs
to change main lift	
cylinder hyd hose	

NO.	QNTS.	Parts/Materials
	1	hyd hose
		TRAVEL:

WORK DESCRIPTION

hyd hose dropped off by willg, O-Rings from MC-Q3 supply,

Get Hyd hoses from TAN.



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Site services (meg energy)

Unit No: WL-06

Hr Meter: 7,128 hrs

[illegible]

Date: February 4/25

Subcontractor: Dylan Bocirassa

[illegible]

WORK DESCRIPTION

I an Picked 4P Battery's,



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysleznny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meq

Unit No: #WL06

Hr Meter:

Date: Feb 4/25

Subcontractor: Ford

Description:

Hours

① Replace batteries

(1 hr)

NO.

QNTS.

Parts/Materials

x2

batteries

(Brandt)

WORK DESCRIPTION

WORK DESCRIPTION

A black and white line drawing of a semi-truck pulling a flatbed trailer. On the trailer is a bulldozer. The truck is on the left, facing left, and the bulldozer is on the right, facing right. The bulldozer has a large blade at the front. The drawing is simple, with bold lines and no shading.

**A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

Meg

Date: Feb 3/25

Subcontractor: Lane

Parts/Materials

$1\frac{1}{2}h5$

WORK DESCRIPTION

A black and white line drawing of a truck and a bulldozer. The truck is on the left, and the bulldozer is on the right, pushing a large pile of material.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

Shop

[illegible]



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: # WLO6

Hr Meter:

Date: Jan 22/25

Subcontractor: Icon

Description:	Hours
① Troubleshoot grind/clunk noise from front diff	
↳ input shaft bearings gone.	
② Remove front driveshaft, hyd. lines and grease lines and front tires	
③ Unbolt diff housing from frame	
④ Remove axles from diff carrier	
	6 hrs

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION
