

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meq energy

Unit No: MG-06

Date: May 13/25

Hr Meter:

Subcontractor: Dylan Bourassa

Description:

Hours

inspected for leaks/

Bubbed out hoses

changed hgd fitting

- 1.5 hrs

on Axel filter housing

installed Ryb protectors

NO.

QNTS.

Parts/Materials

1

fitting P# 6241012

TRAVEL:

WORK DESCRIPTION

Fitting from C-can,



A Division of 848875 Alberta Ltd.
Box 247, Lao La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meq energy

Unit No: MG-06Hr Meter:

Date: May 12/25

Subcontractor: Dglyn Bortessa

[illegible][illegible]

WORK DESCRIPTION

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg energy

Unit No: MG-06

Date: May 7/25

Hr Meter: 23,552.8 hrs

Subcontractor: Dylan Boerassa

[illegible][illegible]

WORK DESCRIPTION

a-Ring out of MC-03,





A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Mezenetog

Unit No: MG-06

Date: May 2/25

Hr-Meter:

Subcontractor: Dylan Bockass

Description:

Hours

Bolted Sid-shift

cylander mount Back

up

30 minutes

NO.

QNTS.

Parts/Materials

TRAVEL:

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg energy

Unit No: MG-06

Date: May 11 / 25

Hr Meter: 23,496 hrs

Subcontractor: Dylon Bourgeois

Description:	Hours
Removed LH lower	- 1 hr
panels on Rear end	
examined why intake	
Pipes Are getting	
Hot (Found Ripped tube)	
Removed intake tube	
installed new intake	
tube	
Filled wobbly wheel	- 1 hr
with Air	

NO.	QNTS.	Parts/Materials
	1	intake tube
	1	pt# AT359297 CLAMP
		TRAVEL:

WORK DESCRIPTION

- intake tube from shop,
- CLAMP from C-can,



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: VLG06Hr Meter:


Date: April 11/25

Subcontractor: Shen

Description:	Hours
- grease front end components	
- install both front fenders	
- install front tires	
torque to 350 lbs 5 1/2 hrs	
top up hyd	
take grader off stands	
- b	
install stump puller	

NO.	QNTS.	Parts/Materials
		(OK)
		TRAVEL :

WORK DESCRIPTION



**A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

Allan Przysięzny

Ph: (780) 623-2242

Cell: (780) 623-0340

Site: Shop.

Site: Shop.

Unit No: M606-

Date: April 10 / 25.

Hr Meter:


Subcontractor: Sham

Description:	Hours
- Complete install upper and lower ball joint bearings on front left and front right	
- install new pivot bushings and new pins	
- assemble bearings and cups together into housing.	
- bolt up and slide housing back onto greaser	
both side :	

[illegible]

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: #M656

Hr Meter:

Date: April 10/25

Subcontractor: Lorl

Description:	Hours
① Replace tie rod ends $\frac{1}{4}$ R/H	
② Assist Shawn to install both front spindle/hub assemblies	
③ Connect hyd. hoses to circle gear box	
④ Top up hyd. oil level	
	<u>5 1/2 hrs</u>

NO.	QNTS.	Parts/Materials
	x1	$\frac{1}{4}$ tie rod
	x1	R/H tie rod
	x30L	hyd. oil

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

#MG 06

Hr Meter:

Date:

April 9/25

Subcontractor:

Iron L

Description:

Hours

① Install fittings into circle turn control
valve and connect hyd. hoses

② Replace pressure relief valve on control
valve assembly

1 1/2 hrs

NO.

QNTS.

Parts/Materials

x2


Fittings metric (Brendt)

x1

press. relief

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysleżny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: _____

Unit No: 14-06

Hr Meter: _____

Date: March 27 2025

Subcontractor: CJ Biegler

Description:	Hours
- Drained tranny fluid	7
- Drained Diff fluid	
- Topped up both	
- Changed breather	
filter for diff	5 hrs
- Put side to side	
lock cylinder back	
in with Tor	
Shawn and Allen	
- Hooked up hoses	1

NO.	QNTS.	Parts/Materials
	2.5	Pale's Trans/Diff oil
	1	Breather Strain filter

WORK DESCRIPTION

<u>Shop Supplies</u>



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Mg-06

Date: March 25 2025

Hr Meter:


Subcontractor: CS Biegle

Description:	Hours
- Put one new	5 hrs
hose right side hub	
- wrapped all hoses	
and mounted	
- Took left side	5 hrs
apart to inspect	
hoses	
- changed one hose	
left side	5 hrs
- Put all back together	

NO.	QNTS.	Parts/Materials
	1	Hose

WORK DESCRIPTION

Sapphire Hose



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: MG06Hr Meter: _____

Description:	Hours
① Replace both axle filter hoses	
② Replace diff cooler hose #8	
③ Assist CJ with cylinder install (side shift and articulation)	
④ Replace both flange o-rings on AWD pump over.	
	6 hrs

Date: March 25/25

Subcontractor: Low

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Mg-06

Date: March 24 2025

Hr Meter:


Subcontractor: CS Biegle

Description:	Hours
- Put one articulator	-
cylinder back together	1
- Put articulator cylinder	
back on grade, hoses	
hooked up	
- Put side to side	
cylinder for table back	9 hrs
on	
- Front right, took all	
the hoses off for	
hydraulics by the hub	
and put all new	
hoses	-

NO.	QNTS.	Parts/Materials
	4	hoses
	1	hose

WORK DESCRIPTION

<u>Sapphire Hoses besides one from Shop</u>



2005 LTD.

**A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

REPAIR REPORT

Site:

Allan Przysięzny

Ph: (780) 623-2242

Cell: (780) 623-0340

Unit No: 49-06

Hr Meter:

Date: March 21 2025

Subcontractor: CJ Biegler

[illegible][illegible]

WORK DESCRIPTION

Shop supplies

Hyd Hoses Made At saphire,



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: MG-06

Hr Meter:

Date: March 20/25


Subcontractor: Dylan Bayrassa

Description:	Hours
changed Diff/Hyd tank	3 hrs
Breather tube filters	
Put clamps on Breather tubes	
Removed hose from	
turn table Gear Box	
too Hyd Junction under	
left side of cab	

NO.	QNTS.	Parts/Materials
	2	filters ^{pt#} A+101565
	4	small hose clamps

WORK DESCRIPTION

Filters from John Deere, clamps out of MC-03,



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

shop

Unit No: FF MG06

Hr Meter:[illegible]

Date: Mar 20/25

Subcontractor: Lonk

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Mg-06

Date: March 18 2025

Hr Meter:

Subcontractor: CJ Biegler

Description:	Hours
- Took Steer	-
Cylinders off	
- Took them apart	
- Replaced all seal	
- Put back together	8hrs
- Put the cylinder	
back on	
- Connected hoses	

NO.	QNTS.	Parts/Materials
	2	Seal Kits
		TRAVEL:

WORK DESCRIPTION

Shop Supplies



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: MG-06

Date: March 18/25

Hr Meter:

Subcontractor: Dylan Boarassa

Description:	Hours
changed Hyd hoses	7 hrs
for side shift	
cylinder on table	
too junction under	
cab RH side	
Helped CJ with	
cylinders	
changed opinion	
seal on turn table	
Gear Box	
Put Rub protectors	
on Hyd hoses	

NO.	QNTS.	Parts/Materials
	2	Hyd hoses
	1	opinion seal
		TRAVEL:

WORK DESCRIPTION

Hyd hoses made at sapphire, opinion seal. from
John Deere,



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: MG-06

Date: March 17/25

Hr Meter:

Subcontractor: Dylan Boag 9559

Description:	Hours
changed hyd hose from pump to accumulator Put clamp on accumulator	
changed Transmission cooler Hyd lines/ Fittings	9.5 hrs
changed Hyd lines from turn table to Hyd Junction under cab LH side	
Put Rub protectors on Hyd hoses	
Helped CJ with cylinders	

NO.	QNTS.	Parts/Materials
	1	Hyd hose PT# KH-A+387384
	1	CLAMP PT# A+186653
	2	Hyd hoses PT# A+335697
	2	Fittings PT# 62H1061
	2	Hyd hoses (made at sapphire)
		TRAVEL:

WORK DESCRIPTION

Parts from John Deere, 2 hoses from sapphire,



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: Mg-06

Hr Meter:


Date: March 17 2025

Subcontractor: CS Bieder

Description:	Hours
- Took side to	
side cylinder apart	
- Took both left	
cylinders off	
- Rebuild them	
- Put back together	9 hrs
- Put back on	
with lon and dylans	
help	
- Started taking	
steering cylinder boxes	
off	

[illegible]

WORK DESCRIPTION



2005 LTD.

**A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:4

#M606

Date:

March 17/25

Hr Meter:**Subcontractor:**

Tand

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: Mg-06

Hr Meter:

Date: March 14 2025

Subcontractor: CS Biegle

Description:	Hours
- Took both articulation cylinders apart	-
- changed all seats inside of it	
- pulled the circle sideshift off	2 hrs
- changed all seats inside of that	
- Saddle-lock cylinder	
me I can pull off	-

[illegible]

WORK DESCRIPTION

Shop	Supplier



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: shop

Unit No: MG-06

Date: March 14/25

Hr Meter:

Subcontractor: Dylan Boyrassq

Description:	Hours
Removed Fan cover	7
Removed Fan	
Unhooked Hyd lines too	
Fan Motor	
Changed Fan Motor	3.5 hrs
shaft seal	
installed New Fan Blade	
Put Fan Guard on/	
Back Fan Panels	
tightened lose bolts	
on Fan shroud	
Hooked Hyd hoses up	
for Fan Motor	

NO.	QNTS.	Parts/Materials
	1	seal kit
	1	FAN Blade
	3	O-Rings
		TRAVEL:

WORK DESCRIPTION

- seal kit/ Fan Blade from John Deere,
- O-Rings ogt of MC-03,



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny

Ph: (780) 623-2242

Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: MG-06

Date: March 13/25

Hr Meter:

Subcontractor: Dylan Boettger

Description:

Hours

NO.

QNTS.

Parts/Materials

↑ Pgt clamp on intake

1. Pipe/Clamp Heater Box

changed fitting for

1-Axis Filter housing

Welded Nuts ON

- 3 hrs

* Brackets for fqn

cover Bolt's

Tightened work

1. light Bolts

NO.

QNTS.

Parts/Materials

1

Pipe clay

pt# J 294653

)

hose clamp

1


Fitting Pt# A1306111

TRAVEL:

WORK DESCRIPTION

- Pipe clamp / Fitting from Deere.

- base clamp from shop supplies,



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: # MG06Hr Meter:

Date: March 7/25

Subcontractor: *Long*

Description:	Hours
① Remove cover and access panels to prep for washing and repairs	

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: #MG06


Hr Meter:

Date: March 6/25

Subcontractor: Toni

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny

Ph: (780) 623-2242

Cell: (780) 623-0340

REPAIR REPORT

Site: Meg energy

Unit No: MG-06

Date: March 3/25


Hr Meter:

Subcontractor: Dylan Bozrassa

Description:	Hours
examined for leaks	
Removed Panels on Neck	
Found 2 cylinder leaks/ turntable Gear Box seal leak/ 2 Bubbed out hyd hoses/ Axel / oil Filter leaking/ hyd hose leak under cqb LH side/ Fitting leak in front window on Neck	1.5 hrs

[illegible]**WORK DESCRIPTION**

Put Panels Back on,
Rubbed out hoses marked.



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Meg

Unit No:

HMG06

Date:

Feb 25/25

Hr Meter:

Subcontractor:

Land

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Site Services (Meg energy)

Unit No: MG-06

Date: February 13/25

Hr Meter: 23,401 hrs

Subcontractor: Dylan Boyko

Description:	Hours
changed axle filter	30 minutes

NO.	QNTS.	Parts/Materials
	1	Axle filter
		TRAVEL:

WORK DESCRIPTION

filter from C-CAN.



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg

Unit No: #M606.

Hr Meter:


Date: Feb 10/25

Subcontractor: Toni

Description:	Hours
① Diagnose engine won't start ↳ low battery voltage (cold weather) ↳ extension cord used to plug unit in was no good. Cord was burnt and 4 different spots on cord were broken wires.	
② Replace extension cord, turn on pro heat and boost batteries.	
③ Start engine.	<u>Thr</u>

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

REPAIR REPORT

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

Site: Site services (meg energy)

Unit No: MG-26

Hr Meter:[illegible]


Date: February 8/25

Subcontractor: Dylan Boorass

[illegible]

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Sit Services

Unit No: MG-06

Date: January 31/25

Hr Meter:

Subcontractor: Dylan Baurassa

Description:

Hours

checked fluids
looked for Trans
leaks

-15 mins

1 hyd hose leak
axel filter leak

NO.


QNTS.

Parts/Materials

TRAVEL:

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg

Unit No: #M606

Date: Jan 27/25

Hr Meter: 23183 hrs

Subcontractor: Tom

Description:	Hours
① Engine oil change	
② Inspect unit	
↳ axle filter sweating	
↳ circle free spins	
↳ hyd hose from pump to accumulator	
③ Tighten loose fitting on R/H ripper cyl.	
	2 hrs

NO.	QNTS.	Parts/Materials
	x1	B7335mer oil filter
	x30L	S140 eng. oil

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg

Unit No: #17606

Date: Dec 9/2024


Hr Meter:

Subcontractor: Isnt

Description:	Hours
① Replace all hoses & rear piping to ripper cylinders.	
	(1 hr)

NO.	QNTS.	Parts/Materials
	x4	hyd. hoses (Brandt)

WORK DESCRIPTION



2005 LTD.

**A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

REPAIR REPORT

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

Site: Mesa

Unit No: # MG06Hr Meter: _____


Description:	Hours
① Replace 4 H ripper cylinder hyd. hose. New rings installed also	

Date: Nov 22/24

Subcontractor: Teal

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

Meg

#MG06

Oct. 17/24

Toni Heurich

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Mag energy fuel yard

Unit No: Mg-06

Date: October 10/24

Hr Meter: 22,047 hrs


Subcontractor: Dylan Bourassa

Description:	Hours
changed Rad	3 hrs
Hyd hose's	
changed hyd hose fitting connector	

NO.	QNTS.	Parts/Materials
	2	hyd hose's (push connect
	2	hyd push connect Fitting
		TRAVEL: 5 hrs

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Mea

Unit No: #M606

Date: Oct. 8/24

Hr Meter: 22036 hrs.

Subcontractor: None

Description:

Hours

① Replace all 3 wiper blades on
front windows

2 hrs

② Bleed off hyd. pressure from wobbly
packer side shift cylinder and
greaser to connect quick couplers

③ Replace seat tilt gears and
spring

④ Inspect gear shifter mechanism
as operator says it's loose and
shifts itself when hitting bumps.
↳ Shifter worn. Will need new

NO.

QNTS.

Parts/Materials

x 3 wipers (Brandt)
x 1 Seat tilt kit "

WORK DESCRIPTION



**A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Meg (A-Road)

Unit No: # **MG06**

Date: Oct. 7/24

Hr Meter: 22030 hrs.

Subcontractor: Len

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lao La Biche, Alberta T0A 2C0

Allan Przysiechny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meag

Unit No: #M606

Hr Meter:

Date: Sept 3/24

Subcontractor: Tort

Description:

Hours

① Transport unit

② Troubleshoot why machine has
steering angle sensor code.
↳ Found damaged wire @ R/H
wheel for sensor. Clean and
repair wire.

Thr


NO.

QNTS.

Parts/Materials

TRAVEL:

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

REPAIR REPORT

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

Site:

Meg

Unit No:

#M606

Date:

3: Aug 15/24

Hr Meter:

Subcontractor:

For L

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meq

Unit No: #MG06

Date: Aug 8/24

Hr Meter:

Subcontractor: Lonk

Description:

Hours

① Troubleshoot why A/C not working.
↳ A/C clutch burnt up. Ordered parts.

② Install wobble wheel to wobbly attachment.

1 1/2 hrs

NO.

QNTS.

Parts/Materials

TRAVEL:

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: MG-06

Date: July 30/24

Hr Meter: 21,415 hrs

Subcontractor: Dylan Boarassa

Description:	Hours
installed Back	5 hrs
work light	
helped IAN put	
Blade on/line up	
tighten Blade deck	
screws/JAM Nuts.	
removed Blade cylinder	
hoses/ Got New ones	
and installed	
tied up cylinder hoses/	
installed wear rubber	

NO.	QNTS.	Parts/Materials
	2	work lights
	4	hgd hoses
		TRAVEL:

WORK DESCRIPTION

work lights/ hoses made at Ethos,



**A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No: #MGO6Hr Meter:[illegible]

Date: July 30/24

Subcontractor: Ian L

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: # MG06

Hr Meter:

Description:	Hours
① Install circle frame to draft frame and adjust to specs.	
	(4 hrs)

Date: July 29/04

Subcontractor: IonL

NO.	QNTS.	Parts/Materials
		5
		TRAVEL:

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

REPAIR REPORT

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0346

Site: Shop

Unit No: MB-06

Hr Meter: 21,415 hrs

[illegible]

Date: July 29/24

Subcontractor: Dylan Bourassa

[illegible]

WORK DESCRIPTION

Ben Jon ordered parts.



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: shop

Unit No: MG-06

Date: July 26/24

Hr Meter: 21,415 hrs

Subcontractor: Dylan Bourassa

Description:	Hours
Figured out wiring	
Problem for reverse	
lights	
tested wires for	
low Beams and	
found out module	
for low Beams	- 6.5 hrs
Needs replaced	
removed rear work lights	
Made Bracket for	
front fender/welded	
Brackets on for	
front fenders	

NO.	QNTS.	Parts/Materials
		TRAVEL:

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M9-06

Date: July 25/24

Hr Meter: 21,415 hrs

Subcontractor: Dylan Boarassa

Description:	Hours
removed Panels/ switches/ wiring harness to fix washer fluid leak/ put back together and tested	- 8.5 hrs
put washer fluid in changed front lights changed side work lights/ wired tried to figure out why reverse lights weren't working	

NO.	QNTS.	Parts/Materials
	1,5	Washer fluid jug
	4	Night rider work pod lig
	2	work lights (used)
		TRAVEL:

WORK DESCRIPTION

Night rider lights from Ethos, other parts/
supplies from shop supplies



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-034C

REPAIR REPORT

Site:

Shop

Unit No: # M606

Hr Meter:

Date: July 25/24

Subcontractor: Ionl

Description:	Hours
① Diagnose why reverse lamps not working.	
↳ Found rear module harness not good.	
Ordered new harness.	
② Test harness for low beam headlights to confirm FLC is no good	
	3 1/2 hrs

NO.	QNTS.	Parts/Materials
		TRAVEL:

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Mg-06

Hr Meter: 24415.3 hrs

Description:	Hours
- Drained gear oil	-
by pinion shaft	
- Pressed new	
bearing onto the	
new circle pinion shaft	
- Installed the shaft	2 hrs
- Torqued the bolts	
of the shaft	
- Put new circle pinion	
shaft seal	
- Filled up gear oil	
for the shaft	-

Date: July 24 2024

Subcontractor: CJ Biegler

NO.	QNTS.	Parts/Materials
	1	Shaft
	1	Seal
		oil
	1	Bearing
		TRAVEL:

WORK DESCRIPTION

<u>All parts from shop</u>



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: shop

Unit No: Packer Attachment M9-06

Hr Meter: 21,415 hrs

Date: July 23/24


Subcontractor: Dylan Bourassa

Description:	Hours
checked/tightened	
and set wheel	
hub Bearings	
took out Broken	
grease nipples from	5 hrs
wheel hub	
changed Market	
Flag Posts on	
side of Attach-	
ment	

NO.	QNTS.	Parts/Materials
	2	Plastic Market Posts
	2	Market flags
		TRAVEL:

WORK DESCRIPTION

Parts from shop supplys.



**A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0**

Allian Przysięzny

Ph: (780) 623-2242

Cell: (780) 623-0340

Site: 9 MEG SITE

Unit No: M606Hr Meter: —

Description:	Hours
--------------	-------

Hours

Installed 3 new bolts on lower front passenger side fender	1/1r
--	------

112

removed 3 broken bolts

Date: July 11/24

Subcontractor: Shawn

NO.	QNTS.	Parts/Materials
-----	-------	-----------------



TRAVEL.



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg

Unit No. # M606

Hr Meter:

Date: June 20/24

Subcontractor: Lent

Description:	Hours
① Engine oil change	
② Adjust cirde gear	
③ Replace R/H door assembly because of the broken glass.	
	(2 hrs)

NO.	QNTS.	Parts/Materials
	x1	B7335-meg filter
	x26L	15w40 eng oil
		TRAVEL :

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg

Unit No: #M606

Date: May 24/24

Hr Meter:


Subcontractor: Iron

Description:	Hours
① Install 1/6" bolts on wobbly frame	
② Tighten wheel bearings on front first bogie	
	1 1/2 hrs

NO.	QNTS.	Parts/Materials
	x 4	1/6" bolt rod (SMK)
	x 8	nuts "
	x 8	washers "
		TRAVEL :

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: May

Unit No: #MG06

Date: May 16/24

Hr Meter:


Subcontractor: Lon

Description:	Hours
① Replace leaking steel line & cooling fan - Replaced o-rings -	
② Clamp and secure lines. Reinstall fan guard -	
	1 1/2 hrs

NO.	QNTS.	Parts/Materials
	x/	steel line (Brandt)
	x/	steel line (Brandt)
	x/	clamp (Brandt)
		TRAVEL:

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg

Unit No: #11506

Date: April 6/24

Hr Meter:


Subcontractor: None

Description:	Hours
① Install wobbly picker attachment and connect hydraulic lines.	
② Replace R/H burnt out brake light will order new fitting.	
③ Replace broken grease ricks on wobbly	1 hr
④ R/H wobbly pivot not taking grease. Remove pin, clean and buff rust and grease. Drill out grease port. Re-install pin and grease.	3 hrs

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meag

Unit No: #MG06

Date: March 28/04

Hr Meter:


Subcontractor: Jonk

Description:	Hours
① Tighten loose R/H fender	
	1 1/2 hr

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezn
Ph: (780) 623-224
Cell: (780) 623-034

REPAIR REPORT

Site:

Shop

Unit No:

MG06

Hr Meter:

20239 hrs.

Date:

March 25/24

Subcontractor:

Ion L

Description:

Hours

NO.

QNTS.

Parts/Materials

① Diagnose poor, slow and chattering hydraulics

x 1

Hyd. pump

(Brandt)

↳ Test pressures, load pressure good,

x 1

mantle ring

"

Standby pressure @ 850 psi on dash and

x 1

hyd. filter

"

be 1900 psi.

x 80L

hyd. oil

② Drain hydraulic oil and remove hyd. filter. Cut open filter and find particles.

③ Disconnect hoses and wiring from pump. Remove pump.

④ Swap fittings over to new pump.

⑤ Install new pump. Connect hoses and wiring.

⑥ Fill hyd. tank and install filter.

8 hrs

WORK DESCRIPTION

⑦ Run and test machine. Hydraulics work good ✓



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meag

Unit No: # MG06

Date: March 15/24


Hr Meter:

Subcontractor: IonL

Description:	Hours
① Engine oil change	
② Repair broken bolt on 1/4 lower blade wear strip.	
	1 1/2 hrs

NO.	QNTS.	Parts/Materials
	x 1	oil filter
	x 30L	S40 eng. oil
	x 1	M12 x 60mm bolt

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Ph: (780) 623-2242
Cell: (780) 623-0346

REPAIR REPORT

Site: MeqUnit No: #M6-06Date: Feb 18/24

Hr Meter:

Subcontractor: IonL

Description:

Hours

① Finish installing alternator and
belt.

1/2 hr

NO.

QNTS.

Parts/Materials

x1

alternator

(Brand)

x1

belt

(Brand)

TRAVEL:

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meg

Unit No: #M606 J. Deere

Date: Dec 5/2023

Hr Meter:

Subcontractor: Iarl

Description:	Hours
① Change engine oil and filter	
	1 1/2 hrs

NO.	QNTS.	Parts/Materials
	x 32	5W40 engine oil
	x 1	oil filter
		TRAVEL:

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieznj
Ph: (780) 623-2242
Cell: (780) 623-0346

REPAIR REPORT

Site: _____

Meag

Unit No:

#M606

J. Deere

Date:

Jan 19/24

Hr Meter:

Subcontractor:

Iron

Description:

Hours

NO.

QNTS.

Parts/Materials

① Locate trans/hyd. oil leak.

↳ Found hose @ tranny cooler popped out of bulkhead quick connect fitting.

Ordered parts.

② Remove tranny cooler, hoses and bulkhead fittings.

3 hrs

TRAVEL:

WORK DESCRIPTION

REPAIR REPORT

Ph: (780) 623-2242

Cell: (780) 623-0340

Meq

Unit No: [#] MG26 J. Deere grader

Date: Dec 2/2023

Subcontractor: Tom C

Hours

NO.

QNTS.

Parts/Materials

x4	litres content
----	----------------

x/	rad hose	(Branch)
----	----------	----------

x2	clamps	(Brondt)
----	--------	----------

② Locate hydrostatic leak.

2) Section hose clamp loose - tighten.

↳ Adjustment screws on rear AWD


pump looking - Tighten jam nut. Will
 or der new seal.

3 hrs

TRAVEL:

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

M29

Unit No: #M607 J. Duere

Date: Dec 2/2023

Hr Meter:

Subcontractor: Tene

Description:

Hours

① Diagnose hard start in the mornings.
Operator states is as if bloc heater
isn't working. Tested and found
bloc heater element is good.
Will order new.

1hr

NO.


QNTS.

Parts/Materials

TRAVEL:

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meeg

Unit No:

MG06 J. Deere

Date:

Nov 28/2022

Hr Meter:

Subcontractor:

Ian L

Description:

Hours

NO.

QNTS.

Parts/Materials

① Replace surge tank to lower rad
have coolant line.

x1 coolant lines (Brandt)

x2 hyd. lines (Brandt)

x1 fitting (Brandt)

x1 fitting (Brandt)

x2 H3 24V bulbs

② Replace for hyd. hose and snap
fitting

③ Replace axle hose and fitting snap

④ Install missing sandwich bolts

⑤ Replace high beam bulbs.

4 1/2 hrs

TRAVEL:

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Meg

Unit No: # MG06 J. Deery

Date: Nov 23/2023

Hr Meter:

Subcontractor: Earl

Description:	Hours
① Locate coolant leaks. Found coolant hose clamp leaking from hose from cool surge tank to lower rad hoses. Will order new clamps.	1hr
② Locate hydraulic leaks ↳ Fan motor lines leaking @ valve ↳ Axle hose leaking @ filter housing ↳ Rippers hose sweating. Will order parts needed for repairs.	Thr

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: SHOP

Unit No: M6106

Date: Sept 20/23

Hr Meter: 18197.9hrs


Subcontractor: Shawn.

Description:	Hours
- Installing and routing new hydraulic lines, clamps and fitting for pull behind packer	
- install new fitting for lower grease lines	
- check air pressure's in tire 100 PSI for each packer wheel	
- grease attachment	
- weld frame plates for better securement	
- install sign on rear of packer and new flagging	

8hrs

NO.	QNTS.	Parts/Materials
		Sepphine Inv 001-05 5517
		greggs - Inv - 327532
		Sepphine Inv - 001-05 5416 (72.91)
		TRAVEL:

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiężn
Ph: (780) 623-224;
Cell: (780) 623-034;

REPAIR REPORT

Site:

Shop

Unit No: #M606 J. Dure 872,6

Hr Meter:

Description:	Hours
--------------	-------

① Locate hpd. oil leak @ rear of hpd pumps
Fan pressure relief leaking around
mounting. Ordered o-ring kit

② Assist with hpt. plumbing for wobble attachment	

③ Install rear view camera kit

6 hrs

Date: Sept. 19/2023

Subcontractor: Jon L

NO.	QNTS.	Parts/Materials
-----	-------	-----------------

	x/	Cam kit	(Martin Deedha)

		TRAVEL :

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: MG06

Date: Sept 19/23


Hr Meter: 18187.9hr

Subcontractor: Shawn

Description:	Hours
- Install both new door panels	
- Set up packer wheels behind grader	
- Try to configure hyd hoses and lines	

NO.	QNTS.	Parts/Materials
<u>Supprie</u>		<u>001-055376</u>
		<u>793.73</u>
	<u>5hrs</u>	<u>Hoses and fitting for pull behind for grader</u>

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0


Allan Przysiezn
Ph: (780) 623-2242
Cell: (780) 623-0340

Site: Christy Creek Welding shop

Date: Sept. 18/2023

Subcontractor: Zach

[illegible]



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: S 404.

Unit No: MG06

Hr Meter: 18196.2hrs

Description:	Hours
Went for parts	
added oil back onto tandem	
dove grader back to shop	
- adjusted sideshift table shims	
- in charge A/C	
- repaired o-ring on compressor pump	
- re-charge A/C	
-	


Date: Sept 15/23

Subcontractor: Shamp.

[illegible]

WORK DESCRIPTION

- need to adjust Articulation sensors
- need new lower steering council bushings



REPAIR REPORT

Allan Przysięzny

Ph: (780) 623-2242

Cell: (780) 623-0340

Stop

Unit No: M606

Date: Aug 29/23

Hr Meter: 18187.9 hrs

Subcontractor: Shawn

[illegible][illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: MG06

Hr Meter: 18181.9 hrs

Date: Aug 28 / 23

Subcontractor: Shawn

Description:	Hours
reseal - blade tilt cylinder	
and install cylinder/pins/keepers	
2 coats of paint on blade-	
Install hyd lines to blade tilt	
cylinder	
install hyd lines for blade shift	
cylinder	
install hose holder and secure	
lines for rub points	
remove / polish rear door panels	

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiecki
Ph: (780) 623-224
Cell: (780) 623-034

REPAIR REPORT

Site: Shop

Unit No: #M606 J. Deere 812G

Hr Meter: _____


Date: Aug 29/2023

Subcontractor: Jan

Description:	Hours
① Install circle assembly to frame	
② Begin installing engine side paneling and front neck covers	
	4 hrs

NO.	QNTS.	Parts/Materials
	x6	upper wear strips (Brandt)
	x6	lower wear strips (Brandt)
		TRAVEL:

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Ph: (780) 623-2244
Cell: (780) 623-0340

REPAIR REPORT

Site: S40P

Unit No: MG06

Hr Meter: 18187.9hrs


Description:	Hours
change seals in steering cylinder	
- Paint table frame	
- install new bushings on both rear panel doors	
- secure loose wiring hoses in engine compartment.	
- prep hose holders for under table	
clean out bushing holes for table pins	

Date: Aug 25/23

Subcontractor: Shawn

[illegible]

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Alan Przybylo
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: SHOPUnit No: M606Date: Aug 24/23Hr Meter: 18187.9hrsSubcontractor: Shawn

Description:

Hours

- replace packings in passenger side front steering cylinder
- re-install cylinder (steering)
- remove blade tilt cylinder and start removing packing
- prep grader for blade install
- install side shift table board cylinder
- install blade onto circle board arms
- paint main frame on table

NO.

QNTS.

Parts/Materials

8hrs

TRAVEL:

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Alan Przysiecki
Ph: (780) 623-2244
Cell: (780) 623-0344

REPAIR REPORT

Site: S409

Unit No: M606

Date: Aug 23/23

Hr Meter: 18197.9hrs

Subcontractor: Shawn

Description:

Hours

NO.

QNTS.


Parts/Materials

- install shims, turn table
brackets and bolts to
re-install turn table
to grader

6hrs

TRAVEL:

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiężny

Ph: (780) 623-2242

Cell: (780) 623-0346


Site: SIAEP

Date: Aug 18 / 23

Subcontractor: Shawm

5hrs

TRAVEL:



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Ph: (780) 623-2241
Cell: (780) 623-0341

REPAIR REPORT

Site: SAOP

Unit No: MG06

Hr Meter: 18187.9 hrs

[illegible]

Date: Aug 17/23

Subcontractor: Shawn

[illegible]

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiechny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M9-06

Date: August 17, 2023

Hr Meter: 18191.1 hrs


Subcontractor: Dylan Boutguss

Description:	Hours
changed hydraulic filter	} 1 hr
put hydraulic oil in	
started putting door panels ^{ON}	

NO.	QNTS.	Parts/Materials
		hydraulic filter
		50L hydraulic oil
		TRAVEL:

WORK DESCRIPTION

filter/oil from shop supplies



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny

Ph: (780) 623-2242

Cell: (780) 623-0340

Site: SHOP

Date: Aug 14 / 23

Subcontractor: Shawn.

[illegible]



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: MG06

Hr Meter: 18187.9hrs


Date: Aug 10 / 23

Subcontractor: Shawn P.

Description:	Hours
remove both front end	
main pins and bushings	
remove lines / hyd hoses	
install new bushings / pins	
on front end.	
reinstall lift cylinder rod	
and hoses	
install new bushings on	
lift cylinder support arm's.	

[illegible]

WORK DESCRIPTION



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieczny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: SHOP

Unit No: M606

Hr Meter: 18187.9 hrs


Date Aug 9 2023

Subcontractor: Shawn

Description:	Hours
- re-install steering cylinder and hoses.	
- help remove broken Hyd Hoses with Ian	
- remove broken bolt from rotating manifold / re-tap threads and install new bolts	
- remove lift cylinder rods (2) and install new packing	
- remove both saddle yokes and remove worn out bushings	
- clean up around grader	
- hose wrap hoses by turn table	

WORK DESCRIPTION

[illegible]



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Mg-06

Hr Meter: 18187.9 hrs

Date: July 25

Subcontractor: DGLYN BOUTSON

[illegible][illegible]

WORK DESCRIPTION

Putt ordered



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: MG-06 (8726)

Date: July 10, 2023

Hr Meter: 18187.9

Subcontractor: Dylan Boukassa

Description:	Hours
Put on New left front fender	15 min's

NO.	QNTS.	Parts/Materials
	1	front fender/bolts/backets
		TRAVEL :

WORK DESCRIPTION

~~FENDER - scratched~~



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M6-06 (8726)

Hr Meter: 18187.9hrs

Description:	Hours
took out A/C motor	2.5hrs
cleaned A/C motor	
Put A/C motor Back in	
took teeth mounts off ripper	
cut teeth off mounts	
Put New teeth on mounts	
Put mounts Back on ripper	


Date: July 6, 2023

Subcontractor: Dylan Bagnasco

NO.	QNTS.	Parts/Materials
	8	Grader ripper teeth
		TRAVEL:

WORK DESCRIPTION

Ian Got Parts



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

Ordering from SbaF Supply



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: SHOP

Unit No: MG06

Date: June 29/23

Hr Meter: 18,187.9 hrs


Subcontractor: Shawn

Description:	Hours
- Install bolts and hardware for passenger rear fenders	
Copper Coat all bolts	

NO.	QNTS.	Parts/Materials
		1 hr.

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M/G06

Date: May 30/23

Hr Meter: 18,107.1hrs

Subcontractor: Shaun

Description:	Hours
- add oil to tenders	
and top up diffs to	
proper level.	3hrs

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M606

Date: May 29 123

Hr Meter: 18,187.1 hrs.


Subcontractor: Shawn

Description:	Hours
- drain oil, front diff and	
drawn oil from driver side	
tandem.	
- fill oil in both tandem housings	
- re seal inspection plates	

NO.	QNTS.	Parts/Materials
Saphire	INV	001-040749
oil and		\$ 1275.75
filters	-	

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: SHOP

Unit No: M606

Hr Meter: 18,187.1 hrs

Date: May 26 / 23

Subcontractor: Shawn

Description:	Hours
--------------	-------


- | | |
|---|--|
| - start process to re-install tandem housing new seals | |
| - bolt flange onto tandems | |
| - torque bolts 190lbs | |
| - install internal chain sprocket and hook up both drive chains | |
| - install / seal up all access plates | |
| | |
| | |
| | |
| | |
| | |

NO.	QNTS.	Parts/Materials
-----	-------	-----------------

9 1/2 hrs		

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M406

Date: May 25/23

Hr Meter: 18,187.2hrs

Subcontractor: Shawn


Description:	Hours
- remove both front steering cylinders, install new packing and seals	
new tie rod ends and hub	
up hyd lines	
- try to remove pin / bushing on steering tilt cylinder	
- buff up tandem Access hole plate for new gaskets	

NO.	QNTS.	Parts/Materials

10hrs

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M606

Hr Meter: 18,187.2 hrs

Date: May 24 / 23


Subcontractor: Shawn P.

Description:	Hours
- Remove circle table gear (pressed out)	
- Remove tandem axle unit remove bearings, seals hub assembly	
- buff off old rust on face plates	
- clean up old parts and prep for new seals / bearings.	

NO.	QNTS.	Parts/Materials
9 1/2 hrs		

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: M606

Date: May 23/23

Hr Meter: 18,187.2 hrs

Subcontractor: Shawn.

Description:

Hours

- remove grader mowboard
- remove table circle for grader mowboard.
- jack up passenger side of grader
- Remove both rear fenders
- Remove both tires
- Remove both broken front fenders.

NO.

QNTS.

Parts/Materials

5 hrs

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: L.L.B Shop

Unit No: MG-06

Date: Oct 27 2022

Hr Meter: 16543 hrs

Subcontractor: Gerald Helaydek


Description:	Hours
From Blarf tractor →	

NO.	QNTS.	Parts/Materials
	1	mirror

WORK DESCRIPTION

Change out driver's side mirror, Remove stump pads
Clean out all dirt, Clean up all dirt under grader
Not complete
3 hours

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: L.L.B Shop

Unit No: HG-06

Date: Oct 26 2022

Hr Meter: 16 543 Hrs

Subcontractor: Gerald Melnychuk


Description:	Hours
<u>From Self-purchase</u>	
<u>Outs From Stock</u>	

NO.	QNTS.	Parts/Materials
	<u>2</u>	<u>Hydraulic Filters</u>
	<u>5</u>	<u>Hydraulic Filter</u>
	<u>10</u>	<u>Viscos 5-40 oil</u>

WORK DESCRIPTION

Change out Hydraulic Filters, Top Hydraulic oil,	
Re-press Repress Threads on plate for Right front plate to hold Fender	
Assembly Fender Brackets	
not complete	3.5 hours

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: L.L.B Shop

Unit No: H 6-06

Date: ~~Canada Holiday~~ Oct 25 2022

Hr Meter: 16543 Hrs

Subcontractor: Bond Melnyckuk

Description:	Hours
<u>From Brent</u>	

NO.	QNTS.	Parts/Materials
	<u>1</u>	<u>Turbo with gaskets</u>
		<u>and clamp</u>

WORK DESCRIPTION

Install new turbo & gaskets and Exhaust clamp, Run machine
all good no leaks

not complete

3 hours



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: L-L-B Shop

Unit No: MG-06

Date: Oct 24 2022

Hr Meter: 16543 Hrs


Subcontractor: Geralt Melnych

Description:	Hours

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

Remove Air Hose to Turbo and Remove Turbo, change fittings to new Turbo	
Not complete	3 hours



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: LLB Shop

Unit No: 116-06

Hr Meter: 16543 Hrs

Date: Oct 21 2021

Subcontractor: Gerald Hefnyckle

Description:	Hours
FROM Breat Erector	

[illegible]

WORK DESCRIPTION

press in all bushings with Hydraulic Jack, clean up pin holes where there's no Bushing Coat all pins and bushing with Copper Coat

not complete 46 rods

press out pin's on both hydraulic cylinders with a bottle
jack Remove all bushings & seals clean up cylinders
ends for new bushings, seals, and pin's

not complete 4.5 hours



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: L.L.B Shop

Unit No: M6-06

Date: Oct 19 2022

Hr Meter: 16543 Hrs

Subcontractor: Gerald Melnychuk


Description:	Hours
From Brent tractor	

NO.	QNTS.	Parts/Materials
2		Hydraulic cylinder kits
5		sets of yoke Bushings
		and seals

WORK DESCRIPTION

Finish Re Dringins cylinder put Back on grader Assemble left
cylinder Bushings and seals put yoke on and Hydraulic cylinder
Right side Take apart and Re bushing and seal And Assemble fully
Both Right & left yoke Bushings and seals are new
not complete B.S Hoors

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: L-L-B Shop

Unit No: MG-06

Date: Oct 18 2021

Hr Meter: 16543 hrs

Subcontractor: Gerald Melnyk


Description:	Hours
<u>From Front Erector</u>	

NO.	QNTS.	Parts/Materials
	<u>2</u>	<u>Hydraulic steel kits</u>

WORK DESCRIPTION

<u>Finish Re oringing cylinder for moving Blade sideways and</u>		
<u>Install, put driver's door back on, Take hydraulic cylinder off</u>		
<u>for turning the Table Take apart, Remove one bushing for</u>		
<u>left cylinder lift and Tilt Bushing was damaged FROM</u>		
<u>Installation</u>	<u>not complete</u>	<u>8.5 Hours</u>

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: L.H.B Shop

Unit No: <u>M6-06</u>		Date: <u>Oct 07 / 2022</u>		
Hr Meter: <u>16543 Hrs</u>		Subcontractor: <u>Gerald Metnychuk</u>		
Description:	Hours	NO.	QNTS.	Parts/Materials
<u>parts from Brant Tractor</u>			<u>2</u>	<u>Hydraulic cylinder Seal kit</u>

WORK DESCRIPTION

<u>Remove moleboard and keep load onto a trailer to take to earl's</u>
<u>Take cylinder apart for make the moleboard back and forth side way?</u>
<u>make & drill 8 lockets for left front fender, Remove cylinder</u>
<u>on left side of turn table Remove all bushings and seals</u>
<u>Seals keep Remove Left cab door to take to glass shop</u>
<u>Not complete</u>
<u>8.5 hours</u>



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: LLB Shop

Unit No: ME-061

Date: Oct 14 2022

Hr Meter: 16543 Hrs

Subcontractor: Gerald Kelnychuk


Description:	Hours
<u>ours From Stock</u>	

NO.	QNTS.	Parts/Materials
	<u>2</u>	<u>Fuel Filters</u>

WORK DESCRIPTION

Change Fuel Filters, Remove all but 2 Bolts to drop the Blade off	
Take Left Rear Door off for Repair, drilled out Bracket to hold	
Right front Fender	
not complete	4 hours

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: MEET GATE

Unit No: M606

Date: July 9 / 22

Hr Meter:

Subcontractor: Shawn

Description:	Hours
- remove side guards	
change w/ A/C pump	
- new belt.	
- change batteries 2 of them	
- change A/C	
- re install side guards	

NO.	QNTS.	Parts/Materials
1	@	A/C pump
1	@	belt.
2		batteries-

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: High Energy

Unit No: 116-06

Hr Meter:


Date: JAN 20 / 2022

Subcontractor: Gerald Melnychuk

[illegible][illegible]

WORK DESCRIPTION

Change out Batteries Bring old ones Back to shop
1.5 hrs



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

REPAIR REPORT

Allan Przysieźny
Ph: (780) 623-2242
Cell: (780) 623-0340

Site:

Shop

Unit No:

#MGO6 Gyoder

Date:

Jan 16/22

Hr Meter:

Subcontractor:

IonL

Description:

Hours

① Replace front R/A wheel sensor

② No power complaint

↳ Sand air cooler boat blown

4 HRS

NO.

QNTS.

Parts/Materials

x1	wheel sensor (Bradt)
----	----------------------

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: SHOP

Unit No: M606

Hr Meter: 14 231

Date: Jan 13/22


Subcontractor: kan L.

Description:	Hours
Replace Front left	
① HAND WHEEL SPEED SENSOR	
② Remove lower Bracket.	
for front left fender, extract	
broken bolts, re-install	
lower fender Bracket.	
	(15)

NO.	QNTS.	Parts/Materials
	x1	wheel sensor (BRANDT.)

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: SHOP

Unit No: M606 Grator

Hr Meter: 14 231 Hrs.

Date: Jan 12/22

Subcontractor: lan L.

Description:	Hours
① DIAGNOSE fuel leak @ injection pump. remove output fitting, clean & inspect. re-install fitting to spec, run engine for leaks, <u>Good!</u>	
② trouble shoot WHY ProHeat NOT WORKING. inspect fuses, <u>Good!</u> inspect fuel supply, <u>Good!</u> disconnect controller & reconnect. test ProHeat, worked fine for 1/2 hr. timer	

NO.	QNTS.	Parts/Materials
	x1	oval amber lamp
	x1	3 wire pigtail

WORK DESCRIPTION

③ replace rear left HAND signal lamp

6.



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Mea

Unit No: # MG-06 grader

Date: Jan 6/22


Hr Meter:

Subcontractor: Ion L

Description:	Hours
① Replace cab heater motor	
	2 HRS

NO.	QNTS.	Parts/Materials
	x1	heater motor (Brandt)

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiężny
Ph: (780) 623-2244
Cell: (780) 623-0344

Site: Leclabiche

[illegible]

Remove & Replaced Electrical to passenger's side front
Replace missing Bottom Fender Bracket Bolts
Replace missing driver's side front fender



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0346

REPAIR REPORT

Site: MEG

Unit No: M606

Date: Jan 10th 2022

Hr Meter:

Subcontractor: Shawn

Description:	Hours
drive to meg from km 112.	
- due test wait to get in	
- get gate pass	
- talk to Don about grader	
- remove Belt housing cover	
side panel	
- change out fuel line	
- remove old alternator	6 1/2 hrs
- wait for new one	
- install new alternator	
- panels and Belt guard cover	
test.	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION

- found coolant leak - tightened clamps
- still small fuel leak on fuel line assembly (O rings)