E24-4



Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A113479

Station #: 70400

Station Name: 101076904 Saskatchewan Ltd.

Technician #: 83537

Technician Name: Wayde Pollock

Signing Officer #: 89229

Signing Officer Name: Carla Harris

Customer Details:

Name: Yorkton Concrete Products Ltd (2012)

Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

Inspection Completed Date: 20Feb2025

Inspection Expiry Date: 28Feb2026

Vehicle Details:

VIN: 4WW5533A3C6618846

Hubometer Reading:

Year: 2012

Vehicle Make/Model: WILSON TRAILER/TRAILER

Plate: 914 MPE

Jurisdiction: Saskatchewan

Unit: STEP DECK

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70400 Sta

Station Name: 101076904 Saskatchewan Ltd.

Technician #: 83537

Technician Name: Wayde Pollock

Signing Officer #: 89229

Signing Officer Name: Carla Harris

Customer Details:

Name: Yorkton Concrete Products Ltd (2012)

Address: Box 129, Yorkton, Saskatchewan, S3N 2V6

Vehicle Details:

VIN: 4WW5533A3C6618846

Hubometer Reading:

Year: 2012

Vehicle Make/Model: WILSON TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
х				Fire Extinguisher (5)	
, x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		х		Lamps (6)	PLATE LIGHT OUT
		x		Reflex Reflectors (6)	LHS REAR SIDE FACING REFLECTOR GONE
X		_		Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
×				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
×				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
×				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
х				Hyd Brake System/Components (3.1)	
		×		Air Brake System/Components (3.2)	ABS LIGHT NOT WORKING
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
		x		Tires/Wheels (9)	2ND LHS WHEEL SEAL LEAKING, 1ST LHS/RHS & 2ND LHS OIL LEVELS LOW
X			_	Self-Steering Axle (2&4)	
х				Frame/Crossmembers/Mounts (8)	
		×		Suspension/Axles (2)	3RD RHS SHOCK LEAKING
х				Exhaust/Emission System (1)	
х				Stiding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axie 1-Pass

Wheel1-On: Tire Tread Depth: 9 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 5/8 in • Brake Drum/Rotor: 1.64 in

Wheel2: Tire Tread Depth: 9 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 16 in

Brake(1): No Brake

N/A

Wheel4-On: Tire Tread Depth: 17 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 1/2 in • Brake Drum/Rotor: 1.64 in

Axle 2-Pass

Wheel1-On: Tire Tread Depth: 10 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 9/16 in • Brake Drum/Rotor: 1.66 in

Wheel2 : Tire Tread Depth: 12 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 15 in

Brake(1): No Brake

N/A

Wheel4-On: Tire Tread Depth: 17 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 9/16 in • Brake Drum/Rotor: 1.65 in

Axle 3-Pass

Wheel1-On: Tire Tread Depth: 14 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 3/4 in • Brake Drum/Rotor: 1.81 in

Wheel2 : Tire Tread Depth: 15 in

Brake(1): No Brake

N/A

Wheel3: Tire Tread Depth: 3 in

Brake(1): No Brake

N/A

•

Wheel4-On: Tire Tread Depth: 6 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 5/8 in • Brake Drum/Rotor: 1.65 in

PASS - vehicle passes inspection

Decal # A113479

Inspection Completed Date: 20Feb2025