

R24-1



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # P261922

Station #: 70854

Station Name: Roberge Transport Inc

Technician #: 85764

Technician Name: Kody Syhlonyk

Signing Officer #: 85305

Signing Officer Name: Debbie Noble

Customer Details:

Name: Roberge Transport Inc

Address: Box 700, moose jaw, Saskatchewan, s6h4p4

Inspection Completed Date: 01Apr2025

Inspection Expiry Date: 30Apr2026

Vehicle Details:

VIN: 1MT2N533XBH022290

Hubometer Reading: 1 km

Year: 2011

Vehicle Make/Model: MERRITT TRAILER/MERRITT

Plate: 744NFI

Jurisdiction: Saskatchewan

Unit: MTH12

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70854

Station Name: Roberge Transport Inc

Technician #: 85764

Technician Name: Kody Syhlonyk

Signing Officer #: 85305

Signing Officer Name: Debbie Noble

Customer Details:

Name: Roberge Transport Inc

Address: Box 700, moose jaw, Saskatchewan, s6h4p4

Vehicle Details:

VIN: 1MT2N533XBH022290

Hubometer Reading: 1 km

Year: 2011

Vehicle Make/Model: MERRITT TRAILER MERRITT TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	Fixed marker light wiring
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	RF, LC brakes low
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 16/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 14/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 55 degrees • Brake Stroke: 1 in

Wheel3-Off : Tire Tread Depth: 15/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Brake Drum/Rotor: 16.5 in • Brake Stroke: 1 in

Wheel4 : Tire Tread Depth: 15/32 in

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 14/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 15/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 75 degrees • Brake Stroke: 1 1/8 in

Wheel3-Off : Tire Tread Depth: 12/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Brake Drum/Rotor: 16.5 in • Brake Stroke: 1 in

Wheel4 : Tire Tread Depth: 12/32 in

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 14/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 14/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 60 degrees • Brake Stroke: 1 in

Wheel3-Off : Tire Tread Depth: 15/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Brake Drum/Rotor: 16.5 in • Brake Stroke: 3/4 in

Wheel4 : Tire Tread Depth: 15/32 in
Brake(1): No Brake
N/A

PASS - vehicle passes inspection

Decal # P261922

Inspection Completed Date: 01Apr2025

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km.
Failure to do so may result in damage or serious injury.



Vehicle Standards and Inspection

Semi-Trailer Record of FAILED Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70854

Station Name: Roberge Transport Inc

Technician #: 85764

Technician Name: Kody Syhlonyk

Signing Officer #: 85305

Signing Officer Name: Debbie Noble

NOT CERTIFIED

Customer Details:

Name: Roberge Transport Inc

Address: Box 700, moose jaw, Saskatchewan, s6h4p4

Vehicle Details:

VIN: 1MT2N533XBH022290

Hubometer Reading: 1 km

Year: 2011

Vehicle Make/Model: MERRITT TRAILER MERRITT TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
	x			Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
	x			Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Fail

Axle 2-Fail

Axle 3-Fail

Fail: Vehicle failed inspection. Vehicle is eligible to return to this inspection facility until 01May2025 for re-inspection of the failed components.

A vehicle that has failed inspection is unsafe for operation on public roads. This vehicle should not be operated until the repairs or adjustments have been made to restore it to a safe operating condition and a qualified technician has re-inspected the vehicle.