



Vehicle Standards and Inspection

X33-1

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A227428

Station #: 71753	Station Name: 101211165 Saskatchewan Ltd
Technician #: 88991	Technician Name: Aaron From
Signing Officer #: 89518	Signing Officer Name: Austin Liggins

Customer Details:	
Name: J WILK LANDSCAPING	Address: 634 FAIRFORD ST W, MOOSE JAW, Saskatchewan, S6H7W9

Inspection Completed Date: 03Mar2026	Inspection Expiry Date: 30Sep2026
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 1XKDD40X4EJ967114	Odometer Reading: 1279009 km
Year: 2014	Vehicle Make/Model: KENWORTH/HEAVY VEHICLE
Plate: 963MDQ	Jurisdiction: Saskatchewan
Unit: 117	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

X33-1

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71753	Station Name: 101211165 Saskatchewan Ltd
Technician #: 88991	Technician Name: Aaron From
Signing Officer #: 89518	Signing Officer Name: Austin Liggins

Customer Details:	
Name: J WILK LANDSCAPING	Address: 634 FAIRFORD ST W, MOOSE JAW, Saskatchewan,

Vehicle Details:	
VIN: 1XKDD40X4EJ967114	Odometer Reading: 1279009 km
Year: 2014	Vehicle Make/Model: KENWORTH HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
		x		Clutch/Clutch Pedal (1)	INTERIOR PANEL HANGING DOWN CATCHING ON FOOT/CLUTCH PEDAL.

		x		Fire Extinguisher/Hazard Kit (5)	FIRE EXTINGUISHER EMPTY.
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
		x		Body/Bumpers (8)	LH HOOD POCKET IN HOOD LOOSE.
		x		Trailer Hitch (10)	FIFTH WHEEL DRY.
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
		x		Fuel System (1)	FUEL LEAKING FROM FITTING ON BACK OF CYLINDER HEAD.
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
------	----------	-----------	----------	---------	----------

x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	REAR DRIVE CAM ROTATIONS OVER 120 DEGREES. RH FRONT DRIVE SCAM+CLEVIS BUSHING WORN OUT AND WHEEL SEAL LEAKING. AIR LEAK UNDER CAB.
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
		x		Tires/Wheels (9)	RH REAR INNER DRIVE TIRE OFF BEAD. LH REAR OUTER TIRE HAS LARGE CUT IN SIDEWALL. LF FRONT DRIVE INNER TIRE FLAT.
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
		x		Exhaust/Emission System (1)	LH STACK BUSHING DAMAGED. RH STACK BUSHING ASSEMBLY AND CLAMPING PORTION DAMAGED. FLEXPIPE DOWNPIPE MOUNT LOOSE.

Brake/Tire Measurements

Axle 1-Pass

Wheel1-Off : Tire Tread Depth: 8/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Brake Drum/Rotor: .010 in • Brake Stroke: 1 in

Wheel2-Off : Tire Tread Depth: 12/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 7/8 in • Brake Drum/Rotor: 0 in • Brake Stroke: 1 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 20/32 in

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 20/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Brake Drum/Rotor: .01 in • Brake Stroke: 1 in

Wheel3-Off : Tire Tread Depth: 20/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Brake Drum/Rotor: .01 in • Brake Stroke: 1 in

Wheel4 : Tire Tread Depth: 20/32 in

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 20/32 in

Brake(1): No Brake

N/A

- Wheel2-Off : Tire Tread Depth: 20/32 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 7/8 in • Brake Drum/Rotor: 0 in • Brake Stroke: 1 in
- Wheel3-Off : Tire Tread Depth: 20/32 in
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 7/8 in • Brake Drum/Rotor: 0 in • Brake Stroke: 1 in
- Wheel4 : Tire Tread Depth: 20/32 in
Brake(1): No Brake
N/A

PASS - vehicle passes inspection

Decal # A227428

Inspection Completed Date: 03Mar2026

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km.
Failure to do so may result in damage or serious injury.