

## **Plant & Vehicle Maintenance & Repairs**

Asset Number: CO224 Serial Number: CAT0305E5DJX00615

Make: CaterpillarModel: 305E ExcavatorYear of Manufacture: 2015

| Make: Caterpinal |        | Model: 303E EXCAVATOR Fear of Manufacture   | 2015                  |
|------------------|--------|---|-----------------------|
| Date             | Hr/Kms | Work Conducted  | Responsible<br>Person |
| 09/14/2015       | 162    | Repair door. Straighten door hinge. Test and adjust.  | TG/GC                 |
| 10/27/2015       |        | 250 hrs service. Change tilt bucket edge. (Rotate)  | TG/GC                 |
| 02/12/2016       | 458    | Rotate cutting edge.  | TG/GC                 |
| 02/19/2016       | 477    | Refit track check and adjust tracks.  | TG/GC                 |
| 02/24/2016       | 490    | Change out LH front window latch.   | TG/GC                 |
| 03/08/2016       | 526    | Adjust fan belt.  | TG/GC                 |
| 05/26/2016       | 599    | Rotate cutting edge. HD check A/C.  | TG/GC                 |
| 06/28/2016       | 723    | Top up coolant and check for leaks.   | TG/GC                 |
| 06/29/2016       | 725    | Hastings. Warranty. Ongoing air con fault.  |                       |
| 07/01/2016       |        | Refer to Hastings Deering Invoice AS300038107   |                       |
| 07/27/2016       |        | Refer to Hastings Deering Invoice AP300552627   |                       |
| 07/29/2016       | 779    | Replace bucket teeth.   | TG/GC                 |
| 07/30/2016       | 763    | 250 hrs service.  | TG/GC                 |
| 08/25/2016       | 830    | Repair hydraulic oil leak (replace O ring).   | GC                    |
| 09/17/2016       | 876    | Fit front window rubber   | TG                    |
| 10/14/2016       | 915    | Remove flashing light bracket, remanufacture new ariel bracket and fit.                                     | TG/GC                 |
| 10/18/2016       |        | Refer to Hastings Deering Invoice 2010113196  |                       |
| 01/13/2017       | 1024   | Spin cutting edge on bucket.  | GC                    |
| 01/23/2017       |        | Refer to Hastings Deering Invoice 5000505339  |                       |
| 01/24/2017       |        | 1000 hrs service. Repair A/C belt adjuster, replace A/C belt and alternator belt. Refer to Hastings Deering |                       |
| 01/24/2017       | 1032   | Invoice   | TG/GC                 |
| 07/03/2017       |        | Done - Door lock open latch   |                       |
| 07/14/2017       |        | Change out quick coupler ends and tilt bucket hose ends   | GC                    |
| 07/17/2017       | 1231   | Replace hydraulic coupler, repair beacon mounts   | TG /GC                |
| 07/21/2017       |        | Done - cutting edge on bucket needs to be changed   | TG                    |
| 08/01/2017       | 1262   | Adjust fan and a/c belts. Replace tilt bucket hydraulic hose coupling                                       | GC TG                 |
| 08/02/2017       | 1264   | Remove and replace faulty quick couplers  | TG                    |
| 08/02/2017       | 1264   | Done - V belt needs tensioning, tightened fuel filter, checked windscreen rattle                            | GC                    |
| 08/03/2017       | 1266   | Change bucket teeth to cutting edge   | TG                    |
| 08/19/2017       | 1305   | Repair hole in fuel hose  | MM                    |
| 08/28/2017       |        | Replace teeth with tiger teeth  | SS                    |
| 09/04/2017       |        | Done - tilt hose connection broken  | TG                    |
| 09/23/2017       | 1404   | Replace bucket edge   | GC SS                 |
|                  |        |   |                       |

| EASTARM<br>civil |
|------------------|
|------------------|

## Plant & Vehicle Maintenance & Repairs

| civil            |          |  |                 |
|------------------|----------|--|-----------------|
| Asset Number:    | : CO224  | Serial Number: CAT0305E5DJX00615   |                 |
| Make: Caterpilla | ar       | Model: 305E Excavator Year of Manufacture:   | 2015            |
| 10/27/2017       | 1562     | 500hr service  | GC              |
| 10/30/2017       |          | Done - door locking latch fallen off   | GC              |
| 11/03/2017       | 1587     | Replace cutting edge   | TG              |
| 11/28/2017       | 1681     | Cleaned out a/c evaporator   | ВО              |
| 01/24/2018       | 1774     | Inspected LH Track for split, will last longer. Rotated cutting edge on bucket   | BO TG           |
| 02/19/2018       | 1842     | BY passed coolant heater hose  | BO SS           |
| 02/22/2018       |          | Inspect leaking tilt bucket hose   | GC              |
| 02/26/2018       | 1867     | Tighten radiator hose, inspected track beeper  | BO MM           |
| 02/28/2018       |          | Inspect track - OK for use, tighten up rod hose  | ВО              |
| 03/06/2018       | 1908     | Fit new tracking beeper, inspect start fault, tightened battery terminals and cleaned                                    | ВО              |
| 03/13/2018       | 1929     | Remove and replace starter motor   | ВО              |
| 03/14/2018       | 1933     | Remove and replace battery   | GC              |
| 03/27/2018       | 1973     | Replaced engine belt and a/c belt, replaced top radiator hose, complete engine service                                   | ВО              |
| 02/20/2010       |          | Complete 2000hr service, drained hydraulic fluid, replaced pump supply oring and hose clamps, replace filters            |                 |
| 03/28/2018       | 1973     | and refilled hydraulic oil, replace coolant and top radiator hoses, Replaced both tracks                                 | ВО              |
| 04/09/2018       | 2007     | Fixed rotating light, replaced work light globe  | BO MM           |
| 04/16/2018       | 2023     | Removed and replaced cutting edge  | BI GC           |
| 07/10/2018       |          | Beacon replaced  | GC SS           |
| 07/06/2018       |          | Tilt buckets rams resealed   | GC SS           |
| 08/28/2018       | 2173     | Rotate cutting edge  | TG              |
| 11/15/2018       | 2259     | 250 hour service, wash down, clean out track frames, adjust tracks, repair oil leak at ball valve, clean up              | SS TG           |
| 11/13/2010       |          | joysticks  | 33 10           |
| 01/22/2010       | 2300     | Check A/C fault, replace suction hose to evaporator, regas and check for leaks, all OK. Clean and inspect evaporator.    | Ellis Auto / TG |
| 01/22/2019       | 2300     | Change cutting edge  | EIIIS AULO / TG |
| 01/22/2010       | 2627     | Check engine warning light on, DPF system fault, do manual DPF burnoff, shut down, isolate, restart fault still present, | TG              |
| 01/22/2019       | 2627     | take to CJD to remove fault code. CJD removed 1 x code for ECU inactive too long. Test. OK.                              |                 |
| 03/13/2020       | 387      | Replace rear mud flaps and support brackets, repair LH front mud flap  | TG SS           |
| 03/25/2020       | 400/4763 | Check brake air system fault, faulty ABS valve, replaced valve, test. OK.  | TG SS           |
|                  | 2512     | 500 hr service - change engine oil and filters, fuel filters, sample hydraulic oil, engine oil, cooland sample and final |                 |
| 04/02/2020       |          | drives   | TG SS           |
| 05/22/2020       | 2572     | Remove and replace cutting edge on tilt bucket   | TG SS           |
|                  |          | Remove evaporator and fan from cab and wash down, remove radiator oil cooler intercooler etc to access A/C               |                 |
| 07/17/2020       | 2652     | compressor, pressurise with nitrogen and test system. Found leaking hose at evaporator inlet. Replace A/C and            | TG              |
|                  |          | alternator belts. Re-assemble and test.  |                 |
|                  |          | dictinator belief the abbenium test.   |                 |

| EASTARM<br>civil |         | Plant & Vehicle Maintenance & Repairs   |              |
|------------------|---------|---|--------------|
| Asset Number     | : CO224 | Serial Number: CAT0305E5DJX00615  |              |
| Make: Caterpil   | lar     | Model: 305E Excavator Year of Manufacture:  | 2015         |
| 07/22/2020       | 2652    | A/C - Replace hose and replace insulation to block air leaks, changed Gas with 1kg R134A  | SS           |
| 07/22/2020       | 2652    | Re-seal front windows with new seals, make up wedges to stop front window rattling  | TG           |
| 07/27/2020       | 2652    | Test cooling system with pressure tester, no leaks detected   | SS           |
| 12/08/2020       | 2759    | 500 hr service completed. Engine oil filter, fuel filter, A/C and air filters   | TG SS        |
| 01/19/2021       | 2854    | Replaced tiger teeth on 500mm bucket  | SS           |
| 02/17/2021       |         | Replaced front windscreen   | SS           |
| 03/05/2021       | 2976    | Stripped and replaced shaft seal on planetary drive. (leaking auger shaft)  | SS           |
| 03/05/2021       | 2980    | Cut an drecrimp hoses at Hosepower  | SS/Hosepower |
| 02/25/2021       | 2952    | Replaced battery  | BL/WG        |
| 03/10/2021       | 3001    | Removed radiator and condenser units to repair broken bolt in alternator. Requires 10mm shorter belt  | SS           |
| 03/11/2021       | 3007    | 500 hr service complete, sampled hyd oil, final drives and engine oils, replaced listed oils and filters, tensioned tracks.   | SS           |
| 03/19/2021       | 3015    | Remove front windscreen, reglue new glass to screen   | SS           |
| 03/23/2021       | 3030    | Fit new 10mm belt   | SS           |
| 05/01/2021       | 3111    | A/C compressor discharge hose leaking; REPAIRED. Re-glued top window  | SS           |
| 07/24/2021       | 3316    | 250 hr service. Replaced oil & filter, sample engine oil, blew out all filters, air and A/C, greased machine, replaced oil in final drives  | SS           |
| 09/08/2021       | 3435    | In progress parts ordered. Removed damaged quick hitch cylinder and double acting hitch an dreplaced with new unit.   | SS           |
| 09/20/2021       | 3437    | Repaired damaged hose ends  | TG           |
| 09/29/2021       | 3480    | Hydraulic top up  | SS           |
| 10/20/2021       | 3512    | Service alarm reset   | HR           |
| 11/01/2021       | 3515    | 500 hr service. Changed engine oil, filter, fuel filters, air filters   | TG           |
| 11/09/2021       | 3566    | In progress - Track inspected, parts ordered. 9/11 - new tracks arrived. Old tracks still serviceable; will only replace when unserviceable   | TG           |
| 11/25/2021       | 3602    | Order new hose, travel to site to fit hose  | TG           |
| 12/08/2021       | 3638    | Replaced cutting edge on 1200 tilt bucket part # 4T-6232  | TG           |
| 01/08/2022       | 2852    | Refit Main lift cylinder protection plate, straightened   | SS           |
| 01/17/2022       | 3683    | Replace fan & AC belts  | TG           |
| 04/09/2022       | 3893    | Replaced damage quick hitch computer hydraulic live, hosepower  | SS           |
| 04/05/2022       | 3890    | Replaced tiger teeth x 3 on bucket  | SS           |
| 05/21/2022       | 3976    | 4000hr service, sampled final drives, engine oil replaced, engine oil and filler final drives drained & filled. Fillers replaced, air filters & a/c cab filters all blown out, machine greased. | SS           |
| 06/02/2022       | 3976    | Note that A/C was repaired on mtce job 2922 on 25/2/22. Now closed.   | SS           |

| Asset Number:   |       |  |            |
|-----------------|-------|--|------------|
|                 | CO224 | Serial Number: CAT0305E5DJX00615   |            |
| Make: Caterpill | ar    | Model: 305E Excavator Year of Manufacture:   | 2015       |
| 08/29/2022      | 4231  | JN#3160 - Rotate cutting edges due to wear.  | TG         |
| 10/07/2022      | 4298  | JN#3124 - Fault, Tracks unservicable, replaced tracks. Cleaned a/c filters, tested ok.                           | SS TG      |
| 10/13/2022      |       | JN#3224 - Removed radiator grills & wash dirt & rocks from Radiators.  | SS         |
| 25/10/2022      | 4317  | JN#3203 - Re-seal stick cylinder, straighten cylinder guard & re-mount, replace 2 way hand piecce                | TG/SS      |
| 24/10/2022      | 4317  | JN#3235 - Completed 250 hr Service   | TG/SS      |
| 24/10/2022      | 4317  | JN#2963 - Inspect speed selector, working OK, ram guard repaired, replaced mirror                                | TG/SS      |
| 21/10/2022      | 4317  | JN#3114 - Re sealed stick cylinder   | TG/SS      |
| 11/15/2022      |       | Strip & quote bucketref Inv 18383 Norline  | Norline    |
| 12/05/2022      | 4318  | Top up hyd oil, blug in beacon light, check reverse beeper circuit, preplace reverse beeper                      | TG, SS     |
| 12/23/2022      | 4318  | Remove bracket and disassemble - Wilkinsons re-bush cylinders and bucket, reassemble refer Inv 16313             | Wilkinsons |
| 01/24/2023      | 4334  | A/C stopped getting cold and engine overheated. Checked belts and found loose. Tightened. OK                     | SS         |
| 06/02/2023      | 4520  | 500 hr service, changed engine oil and filter, fuel filter, air filters, sample all oils and coolant             | SS, TG     |
| 06/06/2023      | 4520  | Replaced fan belt and tensioner bracket  | SS, TG     |
| 07/07/2023      | 4555  | Dissasemble bucket cylinder and prep for re-seal, ordered piston seal kit  | SS, TG     |
| 07/19/2023      |       | Drop bucket cylinder rod to Wilkinsons Eng to make piston  | ,          |
| 07/20/2023      | 4555  | Collect new piston from Wilkinsin Engineering, reassemble cylinder and refit. Drain final drives oil             | Workshop   |
| 07/21/2023      | 4555  | Flush out final drives and refit with 85-140 gear oil  | Workshop   |
| 08/03/2023      |       | Started bucket rebuild (wear strips etc)   | Ту         |
| 08/08/2023      | 4577  | Remove and replace battery refer att Hastings Inv 2015920819   | Hastings   |
| 08/17/2023      | 4584  | Fit new coolant header tank  | Workshop   |
|                 |       | Replaced idler pulley and a/c belt, removed front window and weld up wear in frame. Replaced window seal         |            |
| 09/04/2023      | 4544  | and reassemble   | SS         |
| 09/13/2023      | 4638  | Fit new tiger teeth to bucket (part of JN 3429?)   | Workshop   |
| 09/14/2023      | 4638  | Refit boom lift cylinder guard back to cylindar properly. Spaced out with washers                                | Jordan     |
| 09/21/2023      | 4648  | Change teeth on 300mm bucket   | Workshop   |
| 10/12/2023      | 4696  | Replaced tiger teeth on bucket   | Workshop   |
| 10/25/2023      | 4715  | Quick hitch alarm fixed by Serg  | SS         |
| 10/30/2023      | 4733  | Inspect alarm when using tilt bucket. Found lifting arlarm switched on.  | Workshop   |
|                 |       | 250 hour service, changed engine oil and filter, oil leak hydraulic tank suction fitting. Replaced O ring, refit |            |
| 12/08/2023      | 4755  | hydraulic tank.  | Workshop   |
| , 00, 2020      |       | Re-seal 4 x solenoids on control valve, replace control valve and hook up hoses, refill tank and bleed hydraulic |            |
| 12/12/2023      | 4755  | pump, run up and test. OK.   | Workshop   |
| ,,              |       | Found broken door latch, ordered parts 5/4/24 Replaced door latch assembly, job completed, @ 4821hrs             |            |
| 04/10/2024      | 4821  | 10/4/24  | Workshop   |

| EASTARM<br>civil    |      | Plant & Vehicle Maintenance & Repairs   |          |  |  |
|---------------------|------|---|----------|--|--|
| Asset Number: CO224 |      | Serial Number: CAT0305E5DJX00615  |          |  |  |
| Make: Caterpillar   |      | Model: 305E Excavator Year of Manufacture:  | 2015     |  |  |
| 05/15/2024          | 4850 | Clean out condenser & fit thermo fan onto condenser, wire up using cab fan power supply for relay switching to thermo fan, monitor system for improvement. check with operator a/c working ok now, job complete 15/5/24 @ 4850hrs | Workshop |  |  |
| 06/07/2024          | 4880 | Lubricated latch with dry lube, tested operation, all ok  |          |  |  |
| 06/11/2024          | 4885 | Removed & replaced right side track carrier roller  |          |  |  |
| 06/20/2024          | 4910 | Inspected, still serviceable, will order edge for use when required.  | Workshop |  |  |
| 07/18/2024          |      | Secure beacon on roof.  | Serg     |  |  |
| 01/31/2025          | 4982 | 1000 hour service, changed engine oil and filter, fuel filter, final drive oils, SOS sampled all compartments   | Workshop |  |  |
|                     |      |   |          |  |  |
|                     |      |   |          |  |  |
|                     |      |   |          |  |  |
|                     |      |   |          |  |  |