

Plant & Vehicle Maintenance & Repairs

Asset Number: CO205	Registration Number: CB79N0	Serial Number: CATCB22BC46600307	«
Make: Caterpillar	Model: CB22B Twin Drum Roller	Date of Manufacture: 2014	
Date	Hr / Kms	Work Conducted	Responsible Person
23/9/2015	53	Fit new belts to canopy.	TG
23/9/2015	53	Remove broken strutt stud.	GC
2/10/2015		Replace broken ball end ROPS strutt.	GC
6/1/2016		Refer to Hastings Deering Invoice AP300531985	Hastings
14/6/2016		Refer to CJD Equipment Invoice 1381542	CJD
18/6/2016	248	Inspect seat operation.	GC
27/6/2016	249	250 hrs service. Oil. 1 oil filter 220-1523.	TG/GC
12/7/2016	253	Replace manual holder. Drill and tap new holes and fit.	TG/GC
12/7/2016		Refer to Hastings Deering Invoice AP300550859	
27/7/2016	255	Remove hydraulic hose, take to Hose Power for new one to be made.	TG/GC
28/7/2016	255	Fit front drum vibrator hose. Reassemble and test.	TG/GC
6/9/2016	274	Jump Start (Isolator left on)	TG
8/9/2016	277	Replace Battery, Daily Servicing, Refuel Service Truck	TG
9/11/2016		Change and test battery. Replace battery (warranty).	GC
27/6/2017	342	#30 Fuel system blockage, check fuel lines, blow out, restart all OK	TG
16/8/2017	357	Change out air filters	SS MM
23/10/2017	387	Repair reverse switch on gear selection	SS
29/11/2018	467	Replaced roof, replaced roll bar struts, refitted flashing light, repaired some bolts and threads, replaced e-stop	TH
15/6/2020	495	500 hr service. Changed engine oil and filters, fuel filters and transmission filter, sample oil fluids	TG SS
8/9/2021	585	Fit new strut on L/H side of ROPS (old ore snapped off)	SS
4/8/2022	673	JN#3169 - Fault, Seatbelt freyed, replaced seatbelt.	SS
5/8/2022	673	JN#3173 - Fault, rear drum drive motor leaking, removed drive motor & re-sealed, re-assembled.	TG
17/11/2022	673	CAT recall on roof bracket. Removed roof and drop off to Norline to repair. Refit.	Norline, SC
24/2/2023		Engine panel shroud - loose bolts missing (on engine cover LHS). Serg advised Fi on	SS

[illegible]