

Exodas Pty Ltd

02/08/2021
Page: 1

14:47:11

User: CHERYLC
Comp: EXO

Work Order History

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee	Product Code	W/H Code	Supplier Code	Invoice	Details	Purchase Order	Units Value	Rate Extension
PM57	XQ26AV	00000027	5/19/2016	CUMAE5	01	LABOUR	Labour				0.00	0.00	0.00		
PM57	XQ26AV	00000027	5/19/2016	CUMBE5	01	LABOUR	Labour				0.00	0.00	0.00		
PM57	XQ26AV	00000027	5/19/2016	CUMCE5	01	LABOUR	MECH	Labour			0.00	0.00	0.00		
PM57	XQ26AV	00000027	5/19/2016	EXOINS	01	LABOUR	MECH	Labour			0.00	0.00	0.00		
PM57	XQ26AV	00000027	5/19/2016	ROTDRI	15	LABOUR	MECH	Labour			0.00	0.00	0.00		
PM57	XQ26AV	00000027	5/19/2016	STEROT	15	LABOUR	MECH	Labour			0.00	0.00	0.00		
PM57	XQ26AV	00000027	5/19/2016	TUNE	00	LABOUR	MECH	Labour			0.00	0.00	0.00		
PM57	XQ26AV	00000345	6/2/2016	CUMAE5	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00000346	6/10/2016	CUMAE5	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00000347	6/24/2016	CUMAE5	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00000348	7/4/2016	CUMAE5	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00000348	7/4/2016	CUMBE5	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00000349	7/18/2016	CUMAE5	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00000350	8/8/2016	CUMAE5	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00000350	8/8/2016	CUMBE5	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00000351	8/11/2016	ECO	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00000352	8/22/2016	CUMCE5	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00000352	8/22/2016	EXOINS	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00000754	9/14/2016	CUMAE5	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00000942	9/30/2016	CUMAE5	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00001018	10/13/2016	CUMAE5	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00001018	10/13/2016	CUMBE5	01	LABOUR	MECH	Labour			0.00	85.00	0.00		
PM57	XQ26AV	00001168	10/31/2016	CUMAE5	01	LABOUR	MECH	Labour			1.50	55.00	82.50		
PM57	XQ26AV	00001168	10/31/2016	CUMAE5	16	CON	YAT	Consumables				6.00	0.00	0.00	
PM57	XQ26AV	00001155	10/31/2016	GEN	39	LABOUR	MECH	Labour			1.50	55.00	82.50		
PM57	XQ26AV	00001357	11/8/2016	WEICAL	00	LABOUR	Labour				0.00	0.00	0.00		
PM57	XQ26AV	00001486	11/8/2016	WEICAL	00	LABOUR	Labour				0.00	0.00	0.00		
PM57	XQ26AV	00001486	11/8/2016	WEICAL	Airgauge 16.5, weighbridge 16.16										
PM57	XQ26AV	00001426	11/12/2016	CUMAE5	01	LABOUR	Labour				0.00	0.00	0.00		
PM57	XQ26AV	00001426	11/12/2016	CUMBE5	01	LABOUR	Labour				0.00	0.00	0.00		
PM57	XQ26AV	00001426	11/12/2016	CUMBE5	01	LABOUR	MECH1	Labour			1.50	55.00	82.50		
PM57	XQ26AV	00001426	11/12/2016	CUMBE5	01	LABOUR	TRADEA	Labour			1.50	55.00	82.50		
PM57	XQ26AV	00001426	11/12/2016	CUMBE5	03	ENGOIL	YAT	CJ-4 15w/40				47.00	3.50	164.50	
PM57	XQ26AV	00001426	11/12/2016	CUMBE5	06	LF14000NN	YAT	Oil Filter (was LF9080)				1.00	48.00	48.00	
PM57	XQ26AV	00001426	11/12/2016	CUMBE5	06	FF5776	YAT	FF5776 Fuel Filter				1.00	42.00	42.00	
PM57	XQ26AV	00001426	11/12/2016	CUMBE5	06	AS2474	YAT	Ad Blue filter Kenworth				1.00	14.99	14.99	
PM57	XQ26AV	00001426	11/12/2016	CUMBE5	16	CON	YAT	Consumables				3.00	10.00	30.00	
PM57	XQ26AV	00001426	11/12/2016	CUMBE5	SERVICE COMPLETED. FIRE EXTINGUISHER EXCHANGED. LHR SHOCKY TO BE MONITORED.										
PM57	XQ26AV	00001634	11/14/2016	TYRES	00	LABOUR	APPREN	0.00	85.00	0.00					
PM57	XQ26AV	00001475	11/17/2016	WEICAL	00	LABOUR	Labour				0.00	0.00	0.00		
PM57	XQ26AV	00001475	11/17/2016	WEICAL	Air gauge 14.5, Weighbridge 13.92.										
PM57	XQ26AV	00001552	11/18/2016	CUMAE5	01	LABOUR	MECH1	Labour			1.00	55.00	55.00		
PM57	XQ26AV	00001552	11/18/2016	CUMAE5	16	CON	YAT	Consumables				2.00	10.00	20.00	

PM57	XQ26AV	00001552	11/18/2016	CUMAE5	TIGHTEN FRONT U BOLTS PRE PERTH FIRE EXT EXPRY 5/17										
PM57	XQ26AV	00001599	11/29/2016	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00001599	11/29/2016	CUMAE5	00	LABOUR	MECH	Labour		2.50	55.00	137.50			
PM57	XQ26AV	00001599	11/29/2016	CUMAE5	00	LABOUR	TRADEA	Labour		2.50	55.00	137.50			
PM57	XQ26AV	00001599	11/29/2016	CUMAE5	16	CON	YAT	Consumables			3.00	10.00	30.00		
PM57	XQ26AV	00001599	11/29/2016	CUMAE5	10	M85902	YAT	Shocky Drv. (Meritor) K'worth			2.00	70.00	140.00		
PM57	XQ26AV	00001599	11/29/2016	CUMAE5	99	5264404	YAT	1.00	59.50	59.50					
PM57	XQ26AV	00001599	11/29/2016	CUMAE5	'A' service completed. Flushed the ad blue system, replaced the inline filter and kit. Pressure checked the CAC system. Oil leak present LHS of the engine.										
PM57	XQ26AV	00001698	11/30/2016	GEN	39	BROCHA	BROHUR01	EX00000229	Brown & Hurley Charges & Levys,QV11OZ 57			EX000000	0.00	12.91	0.00
PM57	XQ26AV	00001698	11/30/2016	GEN	39	BROLABOUR	BROHUR01	EX00000229	Brown & Hurley Labour,QV11OZ 57			EX000000	0.00	130.00	0.00
PM57	XQ26AV	00001698	11/30/2016	GEN	39	CON	BROHUR01	EX00000229	Consumables ,QV11OZ 57			EX000000	0.00	7.38	0.00
PM57	XQ26AV	00001698	11/30/2016	GEN	39	CON	BROHUR01	1018708	Consumables ,QV11OZ 57			EX000000	1.00	7.38	7.38
PM57	XQ26AV	00001698	11/30/2016	GEN	39	BROLABOUR	BROHUR01	1018708	Brown & Hurley Labour,QV11OZ 57			EX000000	4.00	130.00	520.00
PM57	XQ26AV	00001698	11/30/2016	GEN	39	BROCHA	BROHUR01	1018708	Brown & Hurley Charges & Levys,QV11OZ 57			EX000000	1.00	12.91	12.91
PM57	XQ26AV	00001698	11/30/2016	GEN	B&H YATALA REPAIRED AD BLUE DOSING UNIT										
PM57	XQ26AV	00001764	12/12/2016	GEN	39	R22-1365R	BROHUR01	EX00000282	Head lamp cover RHS, Kenworth,QV11OZ 57			EX000000	0.00	113.23	0.00
PM57	XQ26AV	00001765	12/12/2016	GEN	39	9.1358.01	BROHUR01	EX00000283	Lamp-Insert H3,QV11OZ 57			EX000000	0.00	71.80	0.00
PM57	XQ26AV	00001764	12/12/2016	GEN	39	LABOUR	MECH	Labour		1.50	55.00	82.50			
PM57	XQ26AV	00001765	12/12/2016	GEN	39	9.1358.01	BROHUR01	1025204	Lamp-Insert H3,QV11OZ 57			EX000000	1.00	71.80	71.80
PM57	XQ26AV	00001764	12/12/2016	GEN	16	CON	YAT	Consumables			2.00	10.00	20.00		
PM57	XQ26AV	00001764	12/12/2016	GEN	14	9.1358.01	YAT	Lamp-Insert H3			1.00	69.78	69.78		
PM57	XQ26AV	00001764	12/12/2016	GEN	Straightened the bullbar, R/R head light insert and headlight cover, replaced globe.										
PM57	XQ26AV	00001764	12/12/2016	GEN	39	R22-1365R	BROHUR01	1025189	Head lamp cover RHS, Kenworth,QV11OZ 57			EX000000	1.00	113.23	113.23
PM57	XQ26AV	00001868	12/15/2016	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00001868	12/15/2016	CUMBE5	01	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00001868	12/15/2016	CUMBE5	01	LABOUR	MECH	Labour		1.50	55.00	82.50			
PM57	XQ26AV	00001868	12/15/2016	CUMBE5	01	LABOUR	TRADEA	Labour		1.50	55.00	82.50			
PM57	XQ26AV	00001868	12/15/2016	CUMBE5	16	AS2474	YAT	Ad Blue filter Kenworth			0.00	10.00	0.00		
PM57	XQ26AV	00001868	12/15/2016	CUMBE5	06	LF14000NN	YAT	Oil Filter (was LF9080)			1.00	48.00	48.00		
PM57	XQ26AV	00001868	12/15/2016	CUMBE5	06	FF5776	YAT	FF5776 Fuel Filter			1.00	42.00	42.00		
PM57	XQ26AV	00001868	12/15/2016	CUMBE5	06	K37-1004	YAT	Water/Fuel Filter Sperator			1.00	21.78	21.78		
PM57	XQ26AV	00001868	12/15/2016	CUMBE5	03	3380365	YAT	Engine oil, 15w/40 CJ, Vecton, Castrol			48.00	3.54	169.92		
PM57	XQ26AV	00001868	12/15/2016	CUMBE5	16	CON	YAT	Consumables			3.00	15.00	45.00		
PM57	XQ26AV	00001868	12/15/2016	CUMBE5	'B' SERVICE COMPLETED. DG KIT COMPLETE.										
PM57	XQ26AV	00001970	12/23/2016	GEN	14	D27-1001-100	VISMEC01	EX00000432	Alternator, K200,QV11OZ PM57			EX000000	0.00	560.82	0.00
PM57	XQ26AV	00001970	12/23/2016	GEN	39	LABEXT	VISMEC01	EX00000432	Labour External,QV11OZ PM57			EX000000	0.00	129.00	0.00
PM57	XQ26AV	00001970	12/23/2016	GEN	14	D27-1001-100	VISMEC01	KLCS184435	Alternator, K200,QV11OZ PM57			EX000000	1.00	560.84	560.84

PM57	XQ26AV	00001970	12/23/2016	GEN	39	LABEXT	VISMEC01	KLCS184435	Labour External,QV11OZ PM57	EX000000	1.20	129.00	154.80
PM57	XQ26AV	00001970	12/23/2016	TYRES	15	TYR295/80YOK	TYRMOR01	EX00000153	Yokohama 295/80R22.5,PM57	EX000000	0.00	481.82	0.00
PM57	XQ26AV	00001970	12/23/2016	TYRES	15	TYR295/80YOK	TYRMOR01	10202	Yokohama 295/80R22.5,PM57	EX000000	2.00	481.82	963.64
PM57	XQ26AV	00001994	12/30/2016	cumae5	01	LABOUR	Labour		0.00 0.00 0.00				
PM57	XQ26AV	00001994	12/30/2016	cumae5	01	LABOUR	MECH1	Labour	1.00 55.00 55.00				
PM57	XQ26AV	00001994	12/30/2016	cumae5	03	3380365	YAT	Engine oil, 15w/40 CJ, Vecton, Castrol	5.00 3.54 17.70				
PM57	XQ26AV	00001994	12/30/2016	cumae5	16	con	YAT	Consumables	3.00 15.00 45.00				
PM57	XQ26AV	00001994	12/30/2016	cumae5		'A' SERVICE COMPLETED. TOPPED UP ENGINE OIL.							
PM57	XQ26AV	00002099	1/11/2017	GEN	39	LABEXT	QUAWIND01	EX00000527	Labour External,QV11OZ 57	EX000000	0.00	222.73	0.00
PM57	XQ26AV	00002099	1/11/2017	GEN		CALL OUT TO PAINT REPAIR RHR BEHIND CAB							
PM57	XQ26AV	00002099	1/11/2017	GEN	39	LABEXT	QUAWIND01	1986	Labour External,QV11OZ 57	EX000000	1.00	222.73	222.73
PM57	XQ26AV	00002227	1/24/2017	TYRES	15	TYR11R22.5	TYRMOR01	EX00000631	Yokohama 11R22.5,QV11OZ PM57	EX000000	0.00	490.91	0.00
PM57	XQ26AV	00002227	1/24/2017	TYRES	15	TYR11R22.5	TYRMOR01	11208	Yokohama 11R22.5,QV11OZ PM57	EX000000	4.00	490.91	1,963.64
PM57	XQ26AV	00002209	1/31/2017	CUMAE5	00	LABOUR	APPREN	0.00 85.00 0.00					
PM57	XQ26AV	00002209	1/31/2017	CUMBE5	00	LABOUR	MECH1	Labour - Internal	3.00 39.00 117.00				
PM57	XQ26AV	00002209	1/31/2017	CUMBE5	16	CON	YAT	Consumables	3.00 15.45 46.35				
PM57	XQ26AV	00002209	1/31/2017	CUMBE5	16	AS2474	YAT	Ad Blue filter Kenworth	1.00 10.00 10.00				
PM57	XQ26AV	00002209	1/31/2017	CUMBE5	16	LF14000NN	YAT	Oil Filter (was LF9080)	1.00 48.00 48.00				
PM57	XQ26AV	00002209	1/31/2017	CUMBE5	16	FF5776	YAT	FF5776 Fuel Filter	1.00 42.00 42.00				
PM57	XQ26AV	00002209	1/31/2017	CUMBE5	08	3334800	YAT	Diff/Gear Oil 80W90 Castrol	35.00 6.76 236.60				
PM57	XQ26AV	00002209	1/31/2017	CUMBE5	16	A3380W1687	YAT	Filter Diff	1.00 18.22 18.22				
PM57	XQ26AV	00002209	1/31/2017	CUMBE5	03	3380365	YAT	Engine oil, 15w/40 CJ, Vecton, Castrol	48.00 3.54 169.92				
PM57	XQ26AV	00002209	1/31/2017	CUMBE5		'B' SERVICE COMPLETED. DIFF OIL AND FILTER CHANGED.							
PM57	XQ26AV	00002932	2/16/2017	WEICAL		AIRGAUGE 13.00							
						WB 12.5							
PM57	XQ26AV	00002954	2/20/2017	CUMAE5	00	LABOUR	MECH	Labour - Internal	0.50 85.00 42.50				
PM57	XQ26AV	00003139	3/8/2017	CUMAE5	00	LABOUR	APPREN	Labour - Internal	0.00 85.00 0.00				
PM57	XQ26AV	00003139	3/8/2017	CUMBE5	00	LABOUR	MECH	Labour - Internal	1.50 85.00 127.50				
PM57	XQ26AV	00003139	3/8/2017	CUMBE5	16	CON	YAT	Consumables	3.00 15.00 45.00				
PM57	XQ26AV	00003139	3/8/2017	CUMBE5	06	LF14000NN	YAT	Oil Filter (was LF9080)	1.00 48.00 48.00				
PM57	XQ26AV	00003139	3/8/2017	CUMBE5	06	AS2474	YAT	Ad Blue filter Kenworth	1.00 10.84 10.84				
PM57	XQ26AV	00003139	3/8/2017	CUMBE5	06	FF5776	YAT	FF5776 Fuel Filter	1.00 42.00 42.00				
PM57	XQ26AV	00003139	3/8/2017	CUMBE5	03	3380365	YAT	Engine oil, 15w/40 CJ, Vecton, Castrol	48.00 3.54 169.92				
PM57	XQ26AV	00003139	3/8/2017	CUMBE5		FRONT DIFF HEAD LEAKING. FRONT DIFF OUTPUT SHAFT SEAL LEAKING. S/F WIPER BLADES.							
PM57	XQ26AV	00003139	3/8/2017	CUMBE5	13	WIPBLA	YAT	Wiper Blades Refill	2.00 27.27 54.54				
PM57	XQ26AV	00003220	3/14/2017	GEN	00	LABOUR	APPREN	Labour - Internal	0.50 85.00 42.50				
PM57	XQ26AV	00003220	3/14/2017	GEN	13	10.477.29	YAT	Louvre Assembly	2.00 28.00 56.00				
PM57	XQ26AV	00003220	3/14/2017	GEN		s/f 2x dash vents							
PM57	XQ26AV	00003249	3/17/2017	CUMAE5	00	LABOUR	MECH1	Labour - Luke	1.00 85.00 85.00				
PM57	XQ26AV	00003249	3/17/2017	CUMAE5	16	CON	YAT	Consumables	3.00 15.00 45.00				
PM57	XQ26AV	00003249	3/17/2017	CUMAE5		PRE PERTH INSPECTION COMPLETED.							
PM57	XQ26AV	00003334	3/27/2017	CUMAE5	00	LABOUR	APPREN	Labour - Internal	0.75 85.00 63.75				
PM57	XQ26AV	00003334	3/27/2017	CUMAE5	00	LABOUR	MECH	Labour - Internal	0.75 85.00 63.75				
PM57	XQ26AV	00003334	3/27/2017	CUMAE5	16	CON	YAT	Consumables	4.00 15.00 60.00				

PM57	XQ26AV	00003334	3/27/2017	CUMAE5	REPLACED DASH GLOBES. REPLACED SCREWS IN THE SUNVISOR									
PM57	XQ26AV	00003652	3/29/2017	TYRES	15	TYR295/80YOK	TYRMOR01	EX00001222	Yokohama 295/80R22.5,	EX00001	0.00	481.82	0.00	
PM57	XQ26AV	00003652	3/29/2017	TYRES	15	TYRDIS	TYRMOR01	EX00001222	Tyre Disposal,	EX00001	0.00	13.64	0.00	
PM57	XQ26AV	00003652	3/29/2017	TYRES	15	TYR295/80YOK	TYRMOR01	12218	Yokohama 295/80R22.5,	EX00001	2.00	481.82	963.64	
PM57	XQ26AV	00003652	3/29/2017	TYRES	15	TYRDIS	TYRMOR01	12218	Tyre Disposal,	EX00001	2.00	13.64	27.27	
PM57	XQ26AV	00003553	4/12/2017	CUMAE5	00	LABOUR MECH		0.00 85.00 0.00						
PM57	XQ26AV	00003553	4/12/2017	CUMBE5	00	LABOUR MECH1	Labour - Internal		2.50 85.00 212.50					
PM57	XQ26AV	00003553	4/12/2017	CUMBE5	03	3380365	YAT Engine oil, 15w/40 CJ, Vecton, Castrol		47.00 3.54 166.38					
PM57	XQ26AV	00003553	4/12/2017	CUMBE5	06	LF14000NN	YAT Oil Filter (was LF9080)		1.00 40.00 40.00					
PM57	XQ26AV	00003553	4/12/2017	CUMBE5	06	FF5776	YAT FF5776 Fuel Filter		1.00 53.46 53.46					
PM57	XQ26AV	00003553	4/12/2017	CUMBE5	06	AS2474	YAT Ad Blue filter Kenworth		1.00 10.84 10.84					
PM57	XQ26AV	00003553	4/12/2017	CUMBE5	16	CON	YAT Consumables		4.00 15.00 60.00					
PM57	XQ26AV	00003588	4/17/2017	GEN	00	LABOUR MECH	Labour - Internal		2.00 85.00 170.00					
PM57	XQ26AV	00003588	4/17/2017	GEN	16	CON	YAT Consumables		2.00 15.00 30.00					
PM57	XQ26AV	00003588	4/17/2017	GEN	14	SS70ZZM	YAT Battery 12v		4.00 133.18 532.72					
PM57	XQ26AV	00003699	4/19/2017	GEN	15	1301-0014	BROHUR01	EX00001298	Valve - Height Control,	EX00001	0.00	151.81	0.00	
PM57	XQ26AV	00003699	4/19/2017	GEN	15	1301-0014	BROHUR01	1103284	Valve - Height Control,	EX00001	2.00	151.81	303.62	
PM57	XQ26AV	00003751	4/21/2017	GEN	39	LABEXT	CARFRE01	EX00001366	Labour External A/H CALLOUT TO JUMP START	EX00001	0.00	200.00	0.00	
PM57	XQ26AV	00003751	4/21/2017	GEN	39	LABEXT	CARFRE01	21042017	PRIME MOVER,	EX00001	1.00	200.00	200.00	
									Labour External A/H CALLOUT TO JUMP START					
PM57	XQ26AV	00003856	4/28/2017	TRA	00	LABOUR MECH1	Labour - Internal		1.00 85.00 85.00					
PM57	XQ26AV	00003856	4/28/2017	TRA	00	LABOUR APPREN	Labour - Internal		1.50 85.00 127.50					
PM57	XQ26AV	00003856	4/28/2017	TRA	16	CON	YAT Consumables		4.00 10.00 40.00					
PM57	XQ26AV	00003856	4/28/2017	TRA	16	1301-0014	YAT Valve - Height Control LI		1.00 151.81 151.81					
PM57	XQ26AV	00003855	5/2/2017	GEN	39	LABOUR MECH	Labour		0.00 0.00 0.00					
PM57	XQ26AV	00003920	5/4/2017	ECO	01	LABOUR MECH	Labour		0.75 85.00 63.75					
PM57	XQ26AV	00003920	5/4/2017	ECO	00	LABOUR APPREN	Labour - Internal		0.75 85.00 63.75					
PM57	XQ26AV	00003920	5/4/2017	ECO	16	CON	YAT Consumables		3.00 10.00 30.00					
PM57	XQ26AV	00003920	5/4/2017	ECO	01	FS1251	YAT Fuel/Water seperator filter		1.00 19.14 19.14					
PM57	XQ26AV	00003920	5/4/2017	ECO	01	ED0021751550	YAT Oil Filter Eco/Sleeper		1.00 48.18 48.18					
PM57	XQ26AV	00003920	5/4/2017	ECO	16	ENGOIL	YAT CJ-4 15w/40		1.10 10.05 11.06					
PM57	XQ26AV	00004023	5/9/2017	GEN	39	275707	CUMMIN01	EX00001513	Valve Governor,	EX00001	0.00	54.50	0.00	
PM57	XQ26AV	00004023	5/9/2017	GEN	39	LABEXT	CUMMIN01	EX00001513	Labour External,	EX00001	0.00	688.00	0.00	
PM57	XQ26AV	00004023	5/9/2017	GEN	39	TRAVEL FEE	CUMMIN01	EX00001513	Travel Fee to Breakdowns,	EX00001	0.00	31.60	0.00	
PM57	XQ26AV	00004023	5/9/2017	GEN	TRAVELLED TO DIRECT FREIGHT YARD COPPERS STREET FOR COMPLAINT OF ENGINE WOULD NOT BUILD UP AIR CARRIED OUT TRUCK SHOOTING FINDING THE AIR GOVERNOR STARTED UP CHECKED OPERATION ALL OK TRAVELLED BACK TO CUMMINS									
PM57	XQ26AV	00004023	5/9/2017	GEN	39	TRAVEL FEE	CUMMIN01	7380336	Travel Fee to Breakdowns,	EX00001	1.00	31.59	31.59	
PM57	XQ26AV	00004023	5/9/2017	GEN	39	LABEXT	CUMMIN01	7380336	Labour External,	EX00001	1.00	688.00	688.00	
PM57	XQ26AV	00004023	5/9/2017	GEN	39	275707	CUMMIN01	7380336	Valve Governor,	EX00001	1.00	54.50	54.50	
PM57	XQ26AV	00004152	5/18/2017	CUMAE5	01	LABOUR Labour			0.00 0.00 0.00					
PM57	XQ26AV	00004152	5/18/2017	CUMBE5	01	LABOUR Labour			0.00 0.00 0.00					
PM57	XQ26AV	00004152	5/18/2017	CUMBE5	00	LABOUR MECH1	Labour - Internal		1.50 85.00 127.50					

PM57	XQ26AV	00004152	5/18/2017	CUMBE5	00	LABOUR APPREN	Labour - Internal		1.50	85.00	127.50						
PM57	XQ26AV	00004152	5/18/2017	CUMBE5	00	LABOUR MECH	Labour - Internal		1.50	85.00	127.50						
PM57	XQ26AV	00004152	5/18/2017	CUMBE5	06	LF14000NN	YAT	Oil Filter (was LF9080)			1.00	40.00	40.00				
PM57	XQ26AV	00004152	5/18/2017	CUMBE5	06	FF5776	YAT	FF5776 Fuel Filter			1.00	53.46	53.46				
PM57	XQ26AV	00004152	5/18/2017	CUMBE5	06	AS2474	YAT	Ad Blue filter Kenworth			1.00	10.82	10.82				
PM57	XQ26AV	00004152	5/18/2017	CUMBE5	03	3380365	YAT	Engine oil, 15w/40 CJ, Vecton, Castrol		47.00	3.54	166.38					
PM57	XQ26AV	00004152	5/18/2017	CUMBE5	11	D84-1000-3122380	YAT	Belt-Fan Drive		1.00	0.00	0.00					
PM57	XQ26AV	00004152	5/18/2017	CUMBE5	11	6PK1590	YAT	Fan Belt		1.00	40.77	40.77					
PM57	XQ26AV	00004152	5/18/2017	CUMBE5	11	3691283	YAT	TENSIONER BELT		1.00	0.00	0.00					
PM57	XQ26AV	00004152	5/18/2017	CUMBE5	11	3690067	YAT	TENSIONER BELT		1.00	0.00	0.00					
PM57	XQ26AV	00004152	5/18/2017	CUMBE5	16	CON	YAT	Consumables		3.00	10.00	30.00					
PM57	XQ26AV	00004152	5/18/2017	CUMBE5		REPLACED BELTS AND TENSIONER PULLEYS											
PM57	XQ26AV	00004106	5/18/2017	GEN	11	D84-1000-3122380	BROHUR01	EX00001546	Belt-Fan Drive				EX00001	0.00	172.73	0.00	
PM57	XQ26AV	00004152	5/18/2017	GEN	11	D84-1000-3122380	BROHUR01	EX00001592	Belt-Fan Drive				EX00001	0.00	0.00	0.00	
PM57	XQ26AV	00004154	5/18/2017	GEN	00	LABOUR MECH	Labour - Internal			0.00	85.00	0.00					
PM57	XQ26AV	00004106	5/18/2017	GEN	11	6PK1590	BROHUR01	EX00001546	Fan Belt,				EX00001	0.00	40.77	0.00	
PM57	XQ26AV	00004152	5/18/2017	GEN	11	6PK1590	BROHUR01	EX00001592	Fan Belt,				EX00001	0.00	0.00	0.00	
PM57	XQ26AV	00004106	5/18/2017	GEN	11	3691283	BROHUR01	EX00001546	TENSIONER BELT,				EX00001	0.00	605.93	0.00	
PM57	XQ26AV	00004152	5/18/2017	GEN	11	3691283	BROHUR01	EX00001592	TENSIONER BELT,				EX00001	0.00	0.00	0.00	
PM57	XQ26AV	00004106	5/18/2017	GEN	11	3690067	BROHUR01	EX00001546	TENSIONER BELT,				EX00001	0.00	416.87	0.00	
PM57	XQ26AV	00004152	5/18/2017	GEN	11	3690067	BROHUR01	EX00001592	TENSIONER BELT,				EX00001	0.00	0.00	0.00	
PM57	XQ26AV	00004106	5/18/2017	GEN	11	3690067	BROHUR01	1122279	TENSIONER BELT,				EX00001	1.00	416.87	416.87	
PM57	XQ26AV	00004106	5/18/2017	GEN	11	3691283	BROHUR01	1122279	TENSIONER BELT,				EX00001	1.00	605.93	605.93	
PM57	XQ26AV	00004106	5/18/2017	GEN	11	6PK1590	BROHUR01	1122279	Fan Belt,				EX00001	1.00	40.77	40.77	
PM57	XQ26AV	00004106	5/18/2017	GEN	1												

PM57	XQ26AV	00004382	6/5/2017	GEN	39	LABOUR	MECH	Labour		0.00	85.00	0.00			
PM57	XQ26AV	00004441	6/7/2017	GEN	39	LABOUR		Labour	0.00	0.00	0.00				
PM57	XQ26AV	00004441	6/7/2017	GEN	00	LABOUR	MECH1	Labour - Internal		0.50	85.00	42.50			
PM57	XQ26AV	00004441	6/7/2017	GEN	16	5264404		YAT	Connector Kit for Ad Blue inline filter		1.00	69.30	69.30		
PM57	XQ26AV	00004441	6/7/2017	GEN	06	AS2474		YAT	Ad Blue filter Kenworth		1.00	10.82	10.82		
PM57	XQ26AV	00004441	6/7/2017	GEN	16	CON		YAT	Consumables		2.00	10.00	20.00		
PM57	XQ26AV	00004441	6/7/2017	GEN		FLUSH ADBLU SYSTEM									
PM57	XQ26AV	00004441	6/7/2017	GEN	00	LABOUR	APPREN	Labour - Internal		0.50	85.00	42.50			
PM57	XQ26AV	00004474	6/12/2017	CUMAE5	01	LABOUR		Labour	0.00	0.00	0.00				
PM57	XQ26AV	00004474	6/12/2017	CUMAE5	00	LABOUR	MECH	Labour - Internal		0.50	85.00	42.50			
PM57	XQ26AV	00004474	6/12/2017	CUMAE5	00	LABOUR	APPREN	Labour - Internal		0.50	85.00	42.50			
PM57	XQ26AV	00004474	6/12/2017	CUMAE5	00	LABOUR	MECH1	Labour - Internal		0.50	85.00	42.50			
PM57	XQ26AV	00004474	6/12/2017	CUMAE5	40	3380365		YAT	Engine oil, 15w/40 CJ, Vecton, Castrol		5.00	3.54	17.70		
PM57	XQ26AV	00004474	6/12/2017	CUMAE5	16	CON		YAT	Consumables		3.00	10.00	30.00		
PM57	XQ26AV	00004733	6/27/2017	GEN		FIRE EXP 12/17									
PM57	XQ26AV	00004733	6/27/2017	GEN		ADJUSTED CLUTCH									
PM57	XQ26AV	00004733	6/27/2017	GEN	07	208935.515		BROHUR01	EX00001954	Clutch Kit (advance),		EX00001	0.00	1,354.55	0.00
PM57	XQ26AV	00004733	6/27/2017	GEN	07	752EAT17		BROHUR01	EX00001954	CLUTCH ASSEMBLY - PACCAR GENUINE		EX00001	0.00	54.55	0.00
PM57	XQ26AV	00004733	6/27/2017	GEN	07	K-2468		BROHUR01	EX00001954	DISCOUNT,		EX00001	0.00	273.23	0.00
PM57	XQ26AV	00004733	6/27/2017	GEN	07	208935.515		BROHUR01	1149559	Kit-Clutch Install 10sp,		EX00001	1.00	1,354.55	1,354.55
PM57	XQ26AV	00004733	6/27/2017	GEN	07	752EAT17		BROHUR01	1149559	Clutch Kit (advance),		EX00001	-1.00	54.55	-54.55
PM57	XQ26AV	00004733	6/27/2017	GEN	07	K-2468		BROHUR01	1149559	CLUTCH ASSEMBLY - PACCAR GENUINE		EX00001			
PM57	XQ26AV	00004757	6/28/2017	GEN	07	K-2468		BROHUR01	1149559	DISCOUNT,		EX00001	1.00	273.23	273.23
PM57	XQ26AV	00004757	6/28/2017	GEN	07	K-2468		BROHUR01	1149559	Kit-Clutch Install 10sp,		EX00001	1.00	273.23	273.23
PM57	XQ26AV	00004757	6/28/2017	GEN	39	LABOUR		Labour	0.00	0.00	0.00				
PM57	XQ26AV	00004757	6/28/2017	GEN	00	LABOUR	MECH1	Labour - Internal		10.00	85.00	850.00			
PM57	XQ26AV	00004757	6/28/2017	GEN	00	LABOUR	MECH1	Labour - Internal		8.00	85.00	680.00			
PM57	XQ26AV	00004757	6/28/2017	GEN	00	LABOUR	APPREN	Labour - Internal		3.00	85.00	255.00			
PM57	XQ26AV	00004757	6/28/2017	GEN	07	K-2468		YAT	Kit-Clutch Install 10sp		1.00	0.00	0.00		
PM57	XQ26AV	00004757	6/28/2017	GEN	07	208935.515		YAT	Clutch Kit (advance)		1.00	0.00	0.00		
PM57	XQ26AV	00004757	6/28/2017	GEN	16	CON		YAT	Consumables		10.00	10.00	100.00		
PM57	XQ26AV	00004757	6/28/2017	GEN		REMOVED GEARBOX AND FOUND CLUTCH TO BE BROKEN									
PM57	XQ26AV	00010837	7/4/2017	GEN		REPLACED GEARBOX INPUT SHAFTS AND GASKETS									
PM57	XQ26AV	00010837	7/4/2017	GEN		REPALCED CLUTCH ASSEMBLY									
PM57	XQ26AV	00010837	7/4/2017	GEN		REPLACED CLUTCH BRAKE ASSEMBLY									
PM57	XQ26AV	00010837	7/4/2017	GEN		REPLACED FLY WHEEL									
PM57	XQ26AV	00010837	7/4/2017	GEN	39	CALL OUT FEE		EXPMAI01	EX00005718	Call Out After Hours/Off Site,PM57		EX00005	0.00	600.00	0.00
PM57	XQ26AV	00010837	7/4/2017	GEN	39	TRAVEL FEE		EXPMAI01	EX00005718	Travel Fee to Breakdowns,PM57		EX00005	0.00	80.00	0.00
PM57	XQ26AV	00010837	7/4/2017	GEN	39	CON		EXPMAI01	EX00005718	Consumables		EX00005	0.00	20.00	0.00
PM57	XQ26AV	00010837	7/4/2017	GEN		EXPRESS MAINTENANCE TRAVELLED TO BREAK DOWN.									
PM57	XQ26AV	00010837	7/4/2017	GEN		REPLACED FAULTY BATTERY.									
PM57	XQ26AV	00010837	7/4/2017	GEN	39	CON		EXPMAI01	INV-0267	Consumables		EX00005	1.00	20.00	20.00
PM57	XQ26AV	00010837	7/4/2017	GEN	39	TRAVEL FEE		EXPMAI01	INV-0267	,PM57		EX00005	1.00	80.00	80.00
PM57	XQ26AV	00010837	7/4/2017	GEN	39	CALL OUT FEE		EXPMAI01	INV-0267	Travel Fee to Breakdowns,PM57		EX00005	1.00	80.00	80.00
PM57	XQ26AV	00010837	7/4/2017	GEN	39	CALL OUT FEE		EXPMAI01	INV-0267	Call Out After Hours/Off Site,PM57		EX00005	1.00	600.00	600.00

PM57	XQ26AV	00005087	7/14/2017	CUMAE5	01	LABOUR	MECH	Labour		0.00	85.00	0.00							
PM57	XQ26AV	00005087	7/14/2017	CUMBE5	01	LABOUR	MECH	Labour		0.00	85.00	0.00							
PM57	XQ26AV	00005087	7/14/2017	CUMBE5	00	LABOUR	MECH	Labour - Internal		1.50	85.00	127.50							
PM57	XQ26AV	00005087	7/14/2017	CUMBE5	00	LABOUR	MECH1	Labour - Internal		1.50	85.00	127.50							
PM57	XQ26AV	00005087	7/14/2017	CUMBE5	06	K37-1004		YAT	Water/Fuel Filter Seperator		1.00	26.11	26.11						
PM57	XQ26AV	00005087	7/14/2017	CUMBE5	06	LF1400NN		YAT	Oil Filter (was LF9080)		1.00	40.00	40.00						
PM57	XQ26AV	00005087	7/14/2017	CUMBE5	06	FF5776		YAT	FF5776 Fuel Filter		1.00	42.46	42.46						
PM57	XQ26AV	00005087	7/14/2017	CUMBE5	06	AS2474		YAT	Ad Blue filter Kenworth		1.00	10.82	10.82						
PM57	XQ26AV	00005087	7/14/2017	CUMBE5	16	CON		YAT	Consumables		3.00	10.00	30.00						
PM57	XQ26AV	00005087	7/14/2017	CUMBE5		FIRE EXP 12/17													
						EYEWASH EXP 12/18													
						TENSIONED LOOSE BELLY BAR													
						REPLACED 1 X 1UNI GREASE NIPPLE													
PM57	XQ26AV	00005186	7/24/2017	GEN	39	LABOUR		Labour		0.00	0.00	0.00							
PM57	XQ26AV	00005186	7/24/2017	GEN	00	LABOUR	MECH1	Labour - Internal		0.50	85.00	42.50							
PM57	XQ26AV	00005186	7/24/2017	GEN	16	CON		YAT	Consumables		1.00	15.00	15.00						
PM57	XQ26AV	00005186	7/24/2017	GEN		DIAGNOSED SPEED SENSOR FAULT. WATER IN THE PLUG. CLEANED AWAY CORROSION, ADDED													
						DIEELECTRIC GREASE, ASSEMBLED AND TESTED, ALL OK.													
PM57	XQ26AV	00005273	7/28/2017	CUMAE5	01	LABOUR		Labour		0.00	0.00	0.00							
PM57	XQ26AV	00005273	7/28/2017	CUMAE5		'A' SERVICE COMPLETED. LOAD LIGHT RHS R/R. SPEEDO REPAIRED BY MICK AND ALEX 24TH JULY '17.													
PM57	XQ26AV	00005273	7/28/2017	CUMAE5	00	LABOUR	MECH1	Labour - Internal		1.00	85.00	85.00							
PM57	XQ26AV	00005273	7/28/2017	CUMAE5	00	LABOUR	APPREN	Labour - Internal		1.00	85.00	85.00							
PM57	XQ26AV	00005273	7/28/2017	CUMAE5	13	WIPBLA		YAT	Wiper Blades Refill		2.00	27.27	54.54						
PM57	XQ26AV	00005299	7/31/2017	TYRES	15	33000084		BRIAUS01	EX00002268	FIT TBR TYRE,PM57					EX00002	0.00	0.00	0.00	
PM57	XQ26AV	00005299	7/31/2017	TYRES	15	77000180		BRIAUS01	EX00002268	CASE STOCK 11-22.5,PM57					EX00002	0.00	20.00	0.00	
PM57	XQ26AV	00005299	7/31/2017	TYRES	15	33000085		BRIAUS01	EX00002268	ROTATE TBR TYRE,PM57					EX00002	0.00	0.00	0.00	
PM57	XQ26AV	00005299	7/31/2017	TYRES	15	TYRRUN		YAT	Tyre Runouts 11R22.5		2.00	0.00	0.00						
PM57	XQ26AV	00005299	7/31/2017	TYRES		FIT UP 2X RUN OUTS													
PM57	XQ26AV	00005299	7/31/2017	TYRES	15	33000085		BRIA											

PM57	XQ26AV	00005583	8/21/2017	DEFECT	Reported Defect :- Defect Code : 00000379 Defect Reference : 5807 Date : 12/08/2017 Description of Defect : 'A' SERVICE DUE AT 627.714KMS 'A' SERVICE COMPLETED.								
PM57	XQ26AV	00005583	8/21/2017	DEFECT	'A' SERVICE COMPLETED.								
PM57	XQ26AV	00005640	8/24/2017	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00		
PM57	XQ26AV	00005640	8/24/2017	CUMAE5	00	LABOUR	MECH	Labour - Internal		0.00	85.00	0.00	
PM57	XQ26AV	00005640	8/24/2017	CUMAE5	00	LABOUR	MECH	Labour - Internal		0.00	85.00	0.00	
PM57	XQ26AV	00005640	8/24/2017	CUMBE5	01	LABOUR	Labour		0.00	0.00	0.00		
PM57	XQ26AV	00005640	8/24/2017	CUMBE5	00	LABOUR	MECH	Labour - Internal		2.00	85.00	170.00	
PM57	XQ26AV	00005640	8/24/2017	CUMBE5	06	MK13555	YAT	FILTER KIT, OIL & FUEL FILTER, (E5)			1.00	63.63	63.63
PM57	XQ26AV	00005640	8/24/2017	CUMBE5	06	AS2474	YAT	Ad Blue filter Kenworth			0.00	10.82	0.00
PM57	XQ26AV	00005640	8/24/2017	CUMBE5	40	3380369	YAT	ENGINE OIL, VECTON 15W/40 CJ-4/E9 BULK			48.00	3.54	169.92
PM57	XQ26AV	00005640	8/24/2017	CUMBE5	16	CON	YAT	Consumables			2.00	15.00	30.00
PM57	XQ26AV	00005640	8/24/2017	CUMBE5	'B' SERVICE COMPLETED.								
PM57	XQ26AV	00005641	8/24/2017	CUMCE5	01	LABOUR	Labour		0.00	0.00	0.00		
PM57	XQ26AV	00005641	8/24/2017	CUMCE5	00	LABOUR	MECH	Labour - Internal		1.50	85.00	127.50	
PM57	XQ26AV	00005641	8/24/2017	CUMCE5	06	ALLCOOL-WF	YAT	Cooling System Filter			1.00	29.82	29.82
PM57	XQ26AV	00005641	8/24/2017	CUMCE5	06	A3380W1687	YAT	Filter Diff			1.00	18.16	18.16
PM57	XQ26AV	00005641	8/24/2017	CUMCE5	40	3334800	YAT	Diff/Gear Oil 80W90 Castrol			36.00	6.76	243.36
PM57	XQ26AV	00005641	8/24/2017	CUMCE5	06	17237	YAT	Filter Element Gearbox Eaton			1.00	26.00	26.00
PM57	XQ26AV	00005641	8/24/2017	CUMCE5	40	3372765	YAT	Syntrans Gear Oil 75w/90			12.00	13.41	160.92
PM57	XQ26AV	00005641	8/24/2017	CUMCE5	06	HHW0116	YAT	Ad Blue Filter (K200)			1.00	26.91	26.91
PM57	XQ26AV	00005641	8/24/2017	CUMCE5	06	LF637	YAT	Power Steer Filter LF637			1.00	24.86	24.86
PM57	XQ26AV	00005641	8/24/2017	CUMCE5	16	CON	YAT	Consumables			2.00	15.00	30.00
PM57	XQ26AV	00005641	8/24/2017	CUMCE5	ADJUSTED THE TURNTABLE ADJUSTED THE CLUTCH.								
PM57	XQ26AV	00005640	8/24/2017	DEFECT	01	LABOUR	MECH	Labour		0.00	0.00	0.00	
PM57	XQ26AV	00005641	8/24/2017	DEFECT	01	LABOUR	MECH	Labour		0.00	0.00	0.00	
PM57	XQ26AV	00005642	8/24/2017	DEFECT	01	LABOUR	MECH	Labour		0.00	0.00	0.00	
PM57	XQ26AV	00005640	8/24/2017	DEFECT	Reported Defect :- Defect Code : 00000355 Defect Reference : 5807 Date : 12/08/2017 Description of Defect : 'A' SERVICE OVERDUE. DUE AT 629.147MS Reported Defect :- Defect Code : 00000355 Defect Reference : 5807 Date : 12/08/2017 Description of Defect : 'A' SERVICE OVERDUE, DUE AT 629.147MS								
PM57	XQ26AV	00005641	8/24/2017	DEFECT									

PM57	XQ26AV	00005642	8/24/2017	DEFECT	Reported Defect :- Defect Code : 00000355 Defect Reference : 5807 Date : 12/08/2017 Description of Defect : 'A' SERVICE OVERDUE, DUE AT 629,147MS						
PM57	XQ26AV	00005640	8/24/2017	DEFECT	Reported Defect :- Defect Code : 00000379 Defect Reference : 5807 Date : 12/08/2017 Description of Defect : 'A' SERVICE DUE AT 627,714KMS						
PM57	XQ26AV	00005641	8/24/2017	DEFECT	Reported Defect :- Defect Code : 00000379 Defect Reference : 5807 Date : 12/08/2017 Description of Defect : 'A' SERVICE DUE AT 627,714KMS						
PM57	XQ26AV	00005642	8/24/2017	DEFECT	Reported Defect :- Defect Code : 00000379 Defect Reference : 5807 Date : 12/08/2017 Description of Defect : 'A' SERVICE DUE AT 627,714KMS						
PM57	XQ26AV	00005640	8/24/2017	DEFECT	'A' SERVICE DUE AT 627,714KMS 'A' SERVICE DEFECT 00000379 COMPLETED. 'A' SERVICE DEFECT 00000355 COMPLETED.						
PM57	XQ26AV	00005642	8/24/2017	EXOINS	01 LABOUR MECH Labour		1.00	85.00	85.00		
PM57	XQ26AV	00005642	8/24/2017	EXOINS	ANNUAL SERVICE INSPECTION, PASSED.						
PM57	XQ26AV	00005834	8/29/2017	WEICAL	00 LABOUR Labour	0.00	0.00	0.00			
PM57	XQ26AV	00005834	8/29/2017	WEICAL	00 LABOUR MECH Labour - Internal		0.00	85.00	0.00		
PM57	XQ26AV	00005834	8/29/2017	WEICAL	AIR GAUGE 16.50 ADJUSTED 16.25 WEIGHBRIDGE 15.88						
PM57	XQ26AV	00005834	8/29/2017	WEICAL	00 LABOUR MECH 0.00 85.00 0.00						
PM57	XQ26AV	00005837	9/6/2017	GEN	39 LABOUR MECH Labour		0.00	85.00	0.00		
PM57	XQ26AV	00005837	9/6/2017	GEN	00 LABOUR MECH Labour - Internal		1.00	85.00	85.00		
PM57	XQ26AV	00005837	9/6/2017	GEN	16 CON YAT Consumables			5.00	15.00	75.00	
PM57	XQ26AV	00005837	9/6/2017	GEN	REPAIRED 3 AIR LEAKS.						
PM57	XQ26AV	00005837	9/6/2017	GEN	00 LABOUR MECH Labour - Internal		0.00	85.00	0.00		
PM57	XQ26AV	00005837	9/6/2017	GEN	00 LABOUR MECH Labour - Internal		0.00	85.00	0.00		
PM57	XQ26AV	00005837	9/6/2017	GEN	00 LABOUR MECH 0.00 85.00 0.00						
PM57	XQ26AV	00006038	9/19/2017	CUMAE5	01 LABOUR Labour	0.00	0.00	0.00			
PM57	XQ26AV	00006038	9/19/2017	CUMAE5	00 LABOUR APPREN Labour - Internal		0.75	85.00	63.75		
PM57	XQ26AV	00006038	9/19/2017	CUMAE5	00 LABOUR MECH1 Labour - Internal		0.75	85.00	63.75		
PM57	XQ26AV	00006038	9/19/2017	CUMAE5	40 3380369 YAT ENGINE OIL, VECTON 15W/40 CJ-4/E9 BULK			5.00	3.54	17.70	
PM57	XQ26AV	00006038	9/19/2017	CUMAE5	16 CON YAT Consumables			4.00	15.00	60.00	
PM57	XQ26AV	00006038	9/19/2017	CUMAE5	SERVICE COMPLETED.						

PM57	XQ26AV	00006038	9/19/2017	DEFECT	01	LABOUR	MECH	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00006038	9/19/2017	DEFECT	Reported Defect :- Defect Code : 00000355 Defect Reference : 5807 Date : 12/08/2017 Description of Defect : 'A' SERVICE OVERDUE. DUE AT 629.147MS										
PM57	XQ26AV	00006038	9/19/2017	DEFECT	Reported Defect :- Defect Code : 00000379 Defect Reference : 5807 Date : 12/08/2017 Description of Defect : 'A' SERVICE DUE AT 627.714KMS										
PM57	XQ26AV	00006038	9/19/2017	DEFECT	'A' SERVICE COMPLETED.										
PM57	XQ26AV	00006111	9/22/2017	TYRES	15	33000241	BRIAUS01	EX00002778	SCRAP TYRES TBR,PM58			EX000002	0.00	14.00	0.00
PM57	XQ26AV	00006111	9/22/2017	TYRES	15	77000180	BRIAUS01	EX00002778	CASE STOCK 11-22.5,PM57			EX000002	0.00	20.00	0.00
PM57	XQ26AV	00006111	9/22/2017	TYRES	15	33000084	YAT	FIT TBR TYRE		4.00	0.00	0.00			
PM57	XQ26AV	00006111	9/22/2017	TYRES	15	33000356	YAT	NWR R CASE - WORN TOO FAR		0.00	0.00	0.00			
PM57	XQ26AV	00006111	9/22/2017	TYRES	15	11002831	YAT	TYRE 11R22.5 146/143L		2.00	495.00	990.00			
PM57	XQ26AV	00006111	9/22/2017	TYRES	FIT UP 2X M766 FROM STOCK										
PM57	XQ26AV	00006111	9/22/2017	TYRES	15	33000241	BRIAUS01	4420374348	SCRAP TYRES TBR,PM58			EX000002	2.00	14.00	28.00
PM57	XQ26AV	00006111	9/22/2017	TYRES	15	77000180	BRIAUS01	4420374348	CASE STOCK 11-22.5,PM57			EX000002	-2.00	20.00	-40.00
PM57	XQ26AV	00006158	9/26/2017	CUMAE5	01	LABOUR	MECH1	Labour		1.50	85.00	127.50			
PM57	XQ26AV	00006158	9/26/2017	CUMAE5	00	LABOUR	APPREN	Labour - Internal		0.25	85.00	21.25			
PM57	XQ26AV	00006158	9/26/2017	CUMAE5	40	3380369	YAT	ENGINE OIL, VECTON 15W/40 CJ-4/E9 BULK		5.00	3.54	17.70			
PM57	XQ26AV	00006158	9/26/2017	CUMAE5	FLUSHED AD BLUE SYSTEM, LIGHTSTILL STAYS ON.										
PM57	XQ26AV	00006158	9/26/2017	CUMAE5	16	CON	YAT	Consumables			3.00	15.00	45.00		
PM57	XQ26AV	00006158	9/26/2017	DEFECT	01	LABOUR	MECH	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00006158	9/26/2017	DEFECT	Reported Defect :- Defect Code : 00000355 Defect Reference : 5807 Date : 12/08/2017 Description of Defect : 'A' SERVICE OVERDUE. DUE AT 629.147MS										
PM57	XQ26AV	00006158	9/26/2017	DEFECT	Reported Defect :- Defect Code : 00000379 Defect Reference : 5807 Date : 12/08/2017 Description of Defect : 'A' SERVICE DUE AT 627.714KMS										
PM57	XQ26AV	00006158	9/26/2017	DEFECT	SERVICE COMPLETED.										
PM57	XQ26AV	00006212	9/27/2017	GEN	39	LABEXT	CUMMIN01	EX00002844	Labour External,PM57			EX000002	0.00	147.00	0.00
PM57	XQ26AV	00006212	9/27/2017	GEN	39	CON	CUMMIN01	EX00002844	Consumables			EX000002	0.00	39.00	0.00
PM57	XQ26AV	00006212	9/27/2017	GEN	39	5273337	CUMMIN01	EX00002844	,PM57 DOSER PUMP, K200,PM57			EX000002	0.00	2,798.06	0.00

PM57	XQ26AV	00006212	9/27/2017	GEN	00	LABOUR MECH	0.00	85.00	0.00								
PM57	XQ26AV	00006212	9/27/2017	GEN		CUMMINS DIAGNOSED A FAILED DOSER UNIT, BLOCKED, TRIED TO FLUSH OUT, WAS UNSUCCESSFUL. SUPPLIED AND FITTED A NEW DOSER PUMP UNIT.											
PM57	XQ26AV	00006212	9/27/2017	GEN	39	LABEXT	CUMMIN01	1301426		Labour External,PM57				EX00002	3.00	147.00	441.00
PM57	XQ26AV	00006212	9/27/2017	GEN	39	CON	CUMMIN01	1301426		Consumables				EX00002	1.00	39.00	39.00
PM57	XQ26AV	00006212	9/27/2017	GEN	39	5273337	CUMMIN01	1301426		DOSER PUMP, K200,PM57				EX00002	1.00	2,798.06	2,798.06
PM57	XQ26AV	00006321	10/5/2017	CUMAE5	01	LABOUR Labour				0.00	0.00	0.00					
PM57	XQ26AV	00006321	10/5/2017	CUMAE5	00	LABOUR APPREN	Labour - Internal			0.75	85.00	63.75					
PM57	XQ26AV	00006321	10/5/2017	CUMAE5	00	LABOUR MECH1	Labour - Internal			0.75	85.00	63.75					
PM57	XQ26AV	00006321	10/5/2017	CUMAE5	16	con	YAT	Consumables				3.00	15.00	45.00			
PM57	XQ26AV	00006321	10/5/2017	DEFECT	01	LABOUR MECH	Labour				0.00	0.00	0.00				
PM57	XQ26AV	00006321	10/5/2017	DEFECT		Reported Defect :- Defect Code : 00000379 Defect Reference : 5807 Date : 12/08/2017 Description of Defect : 'A' SERVICE DUE AT 627.714KMS											
PM57	XQ26AV	00006321	10/5/2017	DEFECT		Reported Defect :- Defect Code : 00000355 Defect Reference : 5807 Date : 12/08/2017 Description of Defect : 'A' SERVICE OVERDUE, DUE AT 629.147MS											
PM57	XQ26AV	00006366	10/8/2017	GEN	39	LABOUR APPREN	Labour			1.50	85.00	127.50					
PM57	XQ26AV	00006366	10/8/2017	GEN	13	SK3221/52Z	YAT	Jaw Repair Kit JSK37/42				1.00	147.27	147.27			
PM57	XQ26AV	00006366	10/8/2017	GEN	16	CON	YAT	Consumables				6.00	15.00	90.00			
PM57	XQ26AV	00006366	10/8/2017	GEN	13	SK2105/19	YAT	Wear ring (3 hole turntable)				1.00	83.00	83.00			
PM57	XQ26AV	00006366	10/8/2017	GEN		R/R TURNABLE JAW KIT AND WEAR RING.											
PM57	XQ26AV	00006463	10/16/2017	GEN	39	LABOUR Labour				0.00	0.00	0.00					
PM57	XQ26AV	00006463	10/16/2017	GEN	00	LABOUR MECH1	0.50	85.00	42.50								
PM57	XQ26AV	00006463	10/16/2017	GEN	13	R56-1025R	YAT	Door Handle RHS, K200				1.00	128.10	128.10			
PM57	XQ26AV	00006463	10/16/2017	GEN	16	CON	YAT	Consumables				1.00	15.00	15.00			
PM57	XQ26AV	00006463	10/16/2017	GEN		REPLACED RHF DOOR HANDLE											
PM57	XQ26AV	00006498	10/18/2017	CUMAE5	01	LABOUR Labour				0.00	0.00	0.00					
PM57	XQ26AV	00006498	10/18/2017	CUMBE5	01	LABOUR Labour				0.00	0.00	0.00					
PM57	XQ26AV	00006498	10/18/2017	CUMBE5	00	LABOUR APPREN	Labour - Internal			1.50	85.00	127.50					
PM57	XQ26AV	00006498	10/18/2017	CUMBE5	00	LABOUR MECH1	Labour - Internal			1.50	85.00	127.50					
PM57	XQ26AV	00006498	10/18/2017	CUMBE5	06	MK13555PRO	YAT	Kit Filter Cummins ISX/E5				1.00	63.63	63.63			
PM57	XQ26AV	00006498	10/18/2017	CUMBE5	06	AS2474	YAT	Ad Blue filter Kenworth				1.00	10.82	10.82			
PM57	XQ26AV	00006498	10/18/2017	CUMBE5	06	FS36401	YAT	Fuel Filter				1.00	16.83	16.83			
PM57	XQ26AV	00006498	10/18/2017	CUMBE5	40	3380369	YAT	ENGINE OIL, VECTON 15W/40 CJ-4/E9 BULK				48.00	3.54	169.92			
PM57	XQ26AV	00006498	10/18/2017	CUMBE5	16	CON	YAT	Consumables				0.00	15.00	0.00			
PM57	XQ26AV	00006498	10/18/2017	CUMBE5		SERVICE COMPLETED.											

PM57	XQ26AV	00006528	10/23/2017	TYRES	15	33000051	BRIAUS01	EX00003044	BALANCE TBR,PM57	EX00003	0.00	25.00	0.00
PM57	XQ26AV	00006533	10/23/2017	TYRES	15	11001553	BRIAUS01	EX00003049	TYRE 295/80R22.5 152/148M BS R150,PM57	EX00003	0.00	494.00	0.00
PM57	XQ26AV	00006528	10/23/2017	TYRES	15	33000241	BRIAUS01	EX00003044	SCRAP TYRES TBR,PM57	EX00003	0.00	14.00	0.00
PM57	XQ26AV	00006533	10/23/2017	TYRES	15	33000241	BRIAUS01	EX00003049	SCRAP TYRES TBR,PM57	EX00003	0.00	14.00	0.00
PM57	XQ26AV	00006528	10/23/2017	TYRES	15	33000084	YAT	FIT TBR TYRE	2.00	0.00	0.00		
PM57	XQ26AV	00006533	10/23/2017	TYRES	15	33000125	BRIAUS01	EX00003049	ETA MIN FEE,PM57	EX00003	0.00	355.00	0.00
PM57	XQ26AV	00006528	10/23/2017	TYRES	15	33000356	YAT	NWR R CASE - WORN TOO FAR	2.00	0.00	0.00		
PM57	XQ26AV	00006533	10/23/2017	TYRES	15	33000084	YAT	FIT TBR TYRE	2.00	0.00	0.00		
PM57	XQ26AV	00006528	10/23/2017	TYRES	15	TYRRUN	YAT	Tyre Runouts (295/80R22.5)	2.00	0.00	0.00		
PM57	XQ26AV	00006533	10/23/2017	TYRES	15	33000351	YAT	NWR N CASE - STAKED	2.00	0.00	0.00		
PM57	XQ26AV	00006528	10/23/2017	TYRES	15	33000051	BRIAUS01	4420376166	BALANCE TBR,PM57	EX00003	2.00	25.00	50.00
PM57	XQ26AV	00006533	10/23/2017	TYRES					BRIDGESTONE EASTERN CREEK REPLACED 2X STEERS THAT HAD BEEN CUT.				
PM57	XQ26AV	00006528	10/23/2017	TYRES	15	33000241	BRIAUS01	4420376166	SCRAP TYRES TBR,PM57	EX00003	2.00	14.00	28.00
PM57	XQ26AV	00006533	10/23/2017	TYRES	15	11001553	BRIAUS01	2720054118	TYRE 295/80R22.5 152/148M BS R150,PM57	EX00003	2.00	494.00	988.00
PM57	XQ26AV	00006533	10/23/2017	TYRES	15	33000241	BRIAUS01	2720054118	SCRAP TYRES TBR,PM57	EX00003	2.00	14.00	28.00
PM57	XQ26AV	00006533	10/23/2017	TYRES	15	33000125	BRIAUS01	2720054118	ETA MIN FEE,PM57	EX00003	1.00	355.00	355.00
PM57	XQ26AV	00006628	10/27/2017	TYRES	15	33000051	BRIAUS01	EX00003093	BALANCE TBR,PM57	EX00003	0.00	25.00	0.00
PM57	XQ26AV	00006628	10/27/2017	TYRES	15	33000084	YAT	FIT TBR TYRE	2.00	0.00	0.00		
PM57	XQ26AV	00006628	10/27/2017	TYRES	15	33000241	YAT	SCRAP TYRES TBR	2.00	0.00	0.00		
PM57	XQ26AV	00006628	10/27/2017	TYRES	15	33000356	YAT	NWR R CASE - WORN TOO FAR	2.00	0.00	0.00		
PM57	XQ26AV	00006628	10/27/2017	TYRES	15	TYRRUN	YAT	Tyre Runouts 275/70R22.5	2.00	0.00	0.00		
PM57	XQ26AV	00006628	10/27/2017	TYRES	15	33000051	BRIAUS01	4420376609	BALANCE TBR,PM57	EX00003	2.00	25.00	50.00
PM57	XQ26AV	00006694	11/1/2017	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00		
PM57	XQ26AV	00006694	11/1/2017	CUMAE5	00	LABOUR	APPREN	Labour - Internal	0.75	85.00	63.75		
PM57	XQ26AV	00006694	11/1/2017	CUMAE5	00	LABOUR	MECH1	Labour - Internal	0.75	85.00	63.75		
PM57	XQ26AV	00006694	11/1/2017	CUMAE5	16	CON	YAT	Consumables	4.00	15.00	60.00		
PM57	XQ26AV	00006694	11/1/2017	CUMAE5					SERVICE COMPLETED.				
PM57	XQ26AV	00007352	12/16/2017	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00		
PM57	XQ26AV	00007352	12/16/2017	CUMBE5	01	LABOUR	Labour		0.00	0.00	0.00		
PM57	XQ26AV	00007352	12/16/2017	CUMBE5	00	LABOUR	APPREN	Labour - Internal	1.00	85.00	85.00		
PM57	XQ26AV	00007352	12/16/2017	CUMBE5	00	LABOUR	MECH	Labour - Internal	1.00	85.00	85.00		
PM57	XQ26AV	00007352	12/16/2017	CUMBE5	06	MK13555	YAT	FILTER KIT, OIL & FUEL FILTER, (E5)	1.00	63.63	63.63		
PM57	XQ26AV	00007352	12/16/2017	CUMBE5	06	AS2474	YAT	Ad Blue filter Kenworth	1.00	10.82	10.82		
PM57	XQ26AV	00007352	12/16/2017	CUMBE5	06	AF1969M	YAT	Air Filter	1.00	80.43	80.43		
PM57	XQ26AV	00007352	12/16/2017	CUMBE5	40	3380369	YAT	ENGINE OIL, VECTON 15W/40 CJ-4/E9 BULK	54.00	3.54	191.16		
PM57	XQ26AV	00007352	12/16/2017	CUMBE5	16	CON	YAT	Consumables	8.00	15.00	120.00		
PM57	XQ26AV	00007352	12/16/2017	CUMBE5					SERVICE COMPLETED.				
PM57	XQ26AV	00007352	12/16/2017	CUMBE5					REPLACED CLUTCH PEDAL PAD.				
PM57	XQ26AV	00007633	1/6/2018	CUMAE5	13	32237P	YAT	Pedal Pad (clutch/brake)	1.00	42.44	42.44		
PM57	XQ26AV	00007633	1/6/2018	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00		
PM57	XQ26AV	00007633	1/6/2018	CUMAE5	00	LABOUR	MECH1	Labour - Internal NICK	1.00	85.00	85.00		

PM57	XQ26AV	00007633	1/6/2018	CUMAE5	00	LABOUR	MECH1	Labour - Internal	LUKE	1.00	85.00	85.00			
PM57	XQ26AV	00007633	1/6/2018	CUMAE5	40	3380369		YAT	ENGINE OIL, VECTON 15W/40 CJ-4/E9 BULK		4.00	3.54	14.16		
PM57	XQ26AV	00007633	1/6/2018	CUMAE5	16	CON		YAT	Consumables		2.00	15.00	30.00		
PM57	XQ26AV	00007633	1/6/2018	CUMAE5		SERVICE COMPLETED.									
PM57	XQ26AV	00007885	1/17/2018	GEN	39	5327754RX		CUMMIN01	EX00003892	TURBO E5, GASKETS AND FITTINGS,PM57				EX000003	0.00 2,930.00 0.00
PM57	XQ26AV	00007885	1/17/2018	GEN		CUMMINS FITTED TURBO CHARGER.									
PM57	XQ26AV	00007885	1/17/2018	GEN	39	5327754RX		CUMMIN01	7653536	TURBO E5, GASKETS AND FITTINGS,PM57				EX000003	1.00 2,930.00 2,930.00
PM57	XQ26AV	00007894	1/19/2018	TYRES	15	77000180		BRIAUS01	EX00003900	CASE STOCK 11-22.5,PM57				EX000003	0.00 20.00 0.00
PM57	XQ26AV	00007894	1/19/2018	TYRES	15	33000084		YAT	FIT TBR TYRE		4.00	0.00	0.00		
PM57	XQ26AV	00007894	1/19/2018	TYRES	15	11002831		YAT	TYRE 11R22.5 146/143L M766		4.00	495.00	1,980.00		
PM57	XQ26AV	00007894	1/19/2018	TYRES	15	33000085		YAT	ROTATE TBR TYRE		4.00	0.00	0.00		
PM57	XQ26AV	00007894	1/19/2018	TYRES	15	77000180		BRIAUS01	4420382485	CASE STOCK 11-22.5,PM57				EX000003	-4.00 20.00 -80.00
PM57	XQ26AV	00007898	1/20/2018	CUMAE5	01	LABOUR	Labour			0.00 0.00 0.00					
PM57	XQ26AV	00007898	1/20/2018	CUMAE5	00	LABOUR	APPREN	Labour - Internal		1.50 85.00 127.50					
PM57	XQ26AV	00007898	1/20/2018	CUMAE5	00	LABOUR	MECH1	Labour - Internal		1.50 85.00 127.50					
PM57	XQ26AV	00007898	1/20/2018	CUMAE5	16	CON		YAT	Consumables		5.00 15.00 75.00				
PM57	XQ26AV	00007898	1/20/2018	CUMAE5		SERVICE COMPLETED.									
						ADJUSTED THE CLUTCH.									
						REPLACED RHS SPOT LIGHT GLOBE.									
						REPLACED BLOWN FUSES.									
PM57	XQ26AV	00008115	2/6/2018	CUMAE5	01	LABOUR	Labour			0.00 0.00 0.00					
PM57	XQ26AV	00008115	2/6/2018	CUMAE5	00	LABOUR	APPREN	Labour - Internal		1.00 85.00 85.00					
PM57	XQ26AV	00008115	2/6/2018	CUMAE5	00	LABOUR	MECH1	Labour - Internal		1.00 85.00 85.00					
PM57	XQ26AV	00008115	2/6/2018	CUMAE5	16	CON		YAT	Consumables		4.00 15.00 60.00				
PM57	XQ26AV	00008115	2/6/2018	CUMAE5		SERVICE COMPLETED.									
PM57	XQ26AV	00008386	2/16/2018	WEICAL	00	LABOUR	Labour			0.00 0.00 0.00					
PM57	XQ26AV	00008386	2/16/2018	WEICAL		AIR GAUGE	16.80								
						ADJUSTED	16.80								
						WEIGHBRIDGE	16.30								
PM57	XQ26AV	00008440	2/21/2018	CUMAE5	01	LABOUR	Labour			0.00 0.00 0.00					
PM57	XQ26AV	00008440	2/21/2018	CUMBE5	01	LABOUR	Labour			0.00 0.00 0.00					
PM57	XQ26AV	00008440	2/21/2018	CUMBE5	00	LABOUR	APPREN	Labour - Internal		0.75 85.00 63.75					
PM57	XQ26AV	00008440	2/21/2018	CUMBE5	00	LABOUR	MECH1	Labour - Internal		0.75 85.00 63.75					
PM57	XQ26AV	00008440	2/21/2018	CUMBE5	40	3380369		YAT	ENGINE OIL, VECTON 15W/40 CJ-4/E9 BULK		47.00 3.54 166.38				
PM57	XQ26AV	00008440	2/21/2018	CUMBE5	06	as2474		YAT	Ad Blue filter Kenworth		1.00 10.82 10.82				
PM57	XQ26AV	00008440	2/21/2018	CUMBE5	06	MK13555PRO		YAT	Kit Filter Cummins ISX/E5		1.00 63.63 63.63				
PM57	XQ26AV	00008440	2/21/2018	CUMBE5	16	CON		YAT	Consumables		3.00 15.00 45.00				
PM57	XQ26AV	00008440	2/21/2018	CUMBE5		SERVICE COMPLETED.									
PM57	XQ26AV	00008820	3/17/2018	CUMAE5	01	LABOUR	Labour			0.00 0.00 0.00					
PM57	XQ26AV	00008820	3/17/2018	CUMAE5	00	LABOUR	APPREN	Labour - Internal		1.50 85.00 127.50					

PM57	XQ26AV	00008820	3/17/2018	CUMAE5	40	3380369	YAT	ENGINE OIL, VECTON 15W/40 CJ-4/E9 BULK	5.00	3.54	17.70			
PM57	XQ26AV	00008820	3/17/2018	CUMAE5	16	COO	YAT	Coolant Allcool K/worth	2.00	5.40	10.80			
PM57	XQ26AV	00008820	3/17/2018	CUMAE5	14	235A12	YAT	LED AUTOLAMPS 235 SERIES	1.00	38.05	38.05			
PM57	XQ26AV	00008820	3/17/2018	CUMAE5	16	CON	YAT	Consumables	6.00	15.00	90.00			
PM57	XQ26AV	00008820	3/17/2018	CUMAE5	SERVICE COMPLETED. TOPPED UP ENGINE OIL. REPLACED REGO LABEL. REPLACED EYE WASH. REPLACED BULL BAR INDICATOR. NEEDS MASS MANAGEMENT LABEL. MINOR OIL LEAK FROM COMPRESSOR. MONITOR.									
PM57	XQ26AV	00008848	3/19/2018	GEN	39	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00008848	3/19/2018	GEN	00	LABOUR	APPREN	Labour - Internal		0.75	85.00	63.75		
PM57	XQ26AV	00008848	3/19/2018	GEN	00	LABOUR	MECH	Labour - Internal		0.75	85.00	63.75		
PM57	XQ26AV	00008848	3/19/2018	GEN	06	25189011	YAT	Air Filter-Cabin		1.00	32.17	32.17		
PM57	XQ26AV	00008848	3/19/2018	GEN	16	CON	YAT	Consumables		3.00	15.00	45.00		
PM57	XQ26AV	00008848	3/19/2018	GEN	REPLACED THE CABIN AIR FILTER.									
PM57	XQ26AV	00008988	3/28/2018	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00008988	3/28/2018	CUMAE5	00	LABOUR	APPREN	Labour - Internal		1.00	85.00	85.00		
PM57	XQ26AV	00008988	3/28/2018	CUMAE5	00	LABOUR	TRADEA	Labour - Internal		1.00	85.00	85.00		
PM57	XQ26AV	00008988	3/28/2018	CUMAE5	16	CON	YAT	Consumables		6.00	15.00	90.00		
PM57	XQ26AV	00008988	3/28/2018	CUMAE5	13	K295-75-815	YAT	Valve-Drain, Cable Release		1.00	30.00	30.00		
PM57	XQ26AV	00008988	3/28/2018	CUMAE5	SERVICE COMPLETED. REPLACED AIR TANK DRAIN CABLE.									
PM57	XQ26AV	00009149	3/29/2018	GEN	12	WHEALI	DLLAS01	EX00004710	Wheel Alignment,PM57		EX000004	0.00	450.00	0.00
PM57	XQ26AV	00009149	3/29/2018	GEN	15	TYRROT	DLLAS01	EX00004710	Tyre Rotated,PM57		EX000004	0.00	50.00	0.00
PM57	XQ26AV	00009149	3/29/2018	GEN	WHEEL ALIGNMENT CARRIED OUT BY D&L ALIGNMENT VICTORIA									
PM57	XQ26AV	00009149	3/29/2018	GEN	12	WHEALI	DLLAS01	Q58000	Wheel Alignment,PM57		EX000004	1.00	450.00	450.00
PM57	XQ26AV	00009149	3/29/2018	GEN	15	TYRROT	DLLAS01	Q58000	Tyre Rotated,PM57		EX000004	1.00	50.00	50.00
PM57	XQ26AV	00009201	4/11/2018	GEN	39	3690864RX	BROHUR01	EX00004747	AIR COMPRESSOR SX, RECONDITIONED,PM57		EX000004	0.00	2,260.38	0.00
PM57	XQ26AV	00009201	4/11/2018	GEN	39	3680441D	BROHUR01	EX00004747	CORE DEPOSIT, A/C COMPRESSOR,PM57		EX000004	0.00	700.00	0.00
PM57	XQ26AV	00009201	4/11/2018	GEN	39	3685614	BROHUR01	EX00004747	GASKET,PM57		EX000004	0.00	48.35	0.00
PM57	XQ26AV	00009201	4/11/2018	GEN	39	4988280	BROHUR01	EX00004747	GASKET, HYDRAULIC PUMP,PM57		EX000004	0.00	10.94	0.00
PM57	XQ26AV	00009201	4/11/2018	GEN	39	ALLC00L-20M	BROHUR01	EX00004747	NO LONGER USE - Coolant KW 20litres,PM57		EX000004	0.00	16.91	0.00
PM57	XQ26AV	00009201	4/11/2018	GEN	39	TRAVEL FEE	BROHUR01	EX00004747	Travel Fee to Breakdowns,PM57		EX000004	0.00	227.70	0.00
PM57	XQ26AV	00009201	4/11/2018	GEN	39	BROLABOUR	BROHUR01	EX00004747	Brown & Hurley Labour,PM57		EX000004	0.00	118.75	0.00
PM57	XQ26AV	00009201	4/11/2018	GEN	39	BROCHA	BROHUR01	EX00004747	Brown & Hurley Charges & Levys,PM57		EX000004	0.00	5.00	0.00
PM57	XQ26AV	00009201	4/11/2018	GEN	BROWN & HURLEY COFFS HARBOUR TRAVELLED TO CLYBUCCA AND CARRIED OUT ROADSIDE REPAIRS.									
PM57	XQ26AV	00009201	4/11/2018	GEN	39	BROCHA	BROHUR01	1342618	Brown & Hurley Charges & Levys,PM57		EX000004	2.00	5.00	10.00
PM57	XQ26AV	00009201	4/11/2018	GEN	39	BROLABOUR	BROHUR01	1342618	Brown & Hurley Labour,PM57		EX000004	8.00	118.75	950.00
PM57	XQ26AV	00009201	4/11/2018	GEN	39	TRAVEL FEE	BROHUR01	1342618	Travel Fee to Breakdowns,PM57		EX000004	1.00	227.70	227.70

PM57	XQ26AV	00009201	4/11/2018	GEN	39	ALLC00L-20M	BROHUR01	1342618	NO LONGER USE - Coolant KW 20litres,PM57	EX00004	1.00	16.91	16.91
PM57	XQ26AV	00009201	4/11/2018	GEN	39	4988280	BROHUR01	1342618	GASKET, HYDRAULIC PUMP,PM57	EX00004	1.00	10.94	10.94
PM57	XQ26AV	00009201	4/11/2018	GEN	39	3685614	BROHUR01	1342618	GASKET,PM57	EX00004	1.00	48.35	48.35
PM57	XQ26AV	00009201	4/11/2018	GEN	39	3680441D	BROHUR01	1342618	CORE DEPOSIT, A/C COMPRESSOR,PM57	EX00004	1.00	700.00	700.00
PM57	XQ26AV	00009201	4/11/2018	GEN	39	3690864RX	BROHUR01	1342618	AIR COMPRESSOR SX, RECONDITIONED,PM57	EX00004	1.00	2,260.38	2,260.38
PM57	XQ26AV	00009255	4/16/2018	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00		
PM57	XQ26AV	00009255	4/16/2018	CUMAE5	00	LABOUR	MECH1	Labour - Internal		1.00	85.00	85.00	
PM57	XQ26AV	00009255	4/16/2018	CUMAE5	40	3380367	YAT	VECTON 15W-40 CJ ENGINE OIL			3.00	4.92	14.76
PM57	XQ26AV	00009255	4/16/2018	CUMAE5	16	CON	YAT	Consumables			3.00	15.00	45.00
PM57	XQ26AV	00009255	4/16/2018	CUMAE5		SERVICE COMPLETED.							
						FITTED MASS MANAGEMENT LABEL.							
PM57	XQ26AV	00009255	4/16/2018	DEFECT	01	LABOUR	MECH	Labour			0.00	0.00	0.00
PM57	XQ26AV	00009255	4/16/2018	DEFECT		Reported Defect :-							
						Defect Code : 00001159							
						Defect Reference : 7941							
						Date : 11/04/2018							
						Description of Defect :							
						DRIVERS SEAT SQUEAKS AND WONT GLIDE							
						LUBED TRACKS AND MECHANISM.							
PM57	XQ26AV	00009255	4/16/2018	DEFECT		Reported Defect :-							
						Defect Code : 00001161							
						Defect Reference : 7939							
						Date : 11/04/2018							
						Description of Defect :							
						AIR LEAK FROM SHIFTER GREY BUTTON.							
						NO AIR LEAK FOUND.							
PM57	XQ26AV	00009255	4/16/2018	DEFECT		Reported Defect :-							
						Defect Code : 00001158							
						Defect Reference : 7940							
						Date : 11/04/2018							
						Description of Defect :							
						HEADLIGHTS NEED TO BE ADJUSTED.							
						ADJUSTED.							
PM57	XQ26AV	00009578	5/4/2018	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00		
PM57	XQ26AV	00009578	5/4/2018	CUMBE5	01	LABOUR	Labour		0.00	0.00	0.00		
PM57	XQ26AV	00009578	5/4/2018	CUMBE5	00	LABOUR	MECH1	Labour - Internal			2.00	85.00	170.00
PM57	XQ26AV	00009578	5/4/2018	CUMBE5	40	3380369	YAT	ENGINE OIL, VECTON 15W/40 CJ-4/E9 BULK			7.00	3.54	24.78
PM57	XQ26AV	00009578	5/4/2018	CUMBE5	06	mk13555pro	YAT	Kit Filter Cummins ISX/E5			1.00	63.63	63.63
PM57	XQ26AV	00009578	5/4/2018	CUMBE5	06	AS2474	YAT	Ad Blue filter Kenworth			1.00	11.61	11.61
PM57	XQ26AV	00009578	5/4/2018	CUMBE5	06	T224P	YAT	Turbo 2000 Air dryer			1.00	158.18	158.18
PM57	XQ26AV	00009578	5/4/2018	CUMBE5	16	CON	YAT	Consumables			5.00	15.00	75.00
PM57	XQ26AV	00009578	5/4/2018	CUMBE5		SERVICE COMPLETED.							
						REPLACED AIR DRYER FILTER.							
						RHS WINDSCREEN CRACKED.							
PM57	XQ26AV	00009806	5/21/2018	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00		

[illegible]

PM57	XQ26AV	00010325	6/13/2018	DEFECT	Reported Defect :- Defect Code : 00001083 Defect Reference : W/O 8820 Date : 17/03/2018 Description of Defect : MINOR OIL LEAK FROM COMPRESSOR, MONITOR. OK. STILL MONITOR.										
PM57	XQ26AV	00010325	6/13/2018	DEFECT	Reported Defect :- Defect Code : 00001160 Defect Reference : 7942 Date : 11/04/2018 Description of Defect : HORTON FAN TOO NOISY ALL OK. MONITOR.										
PM57	XQ26AV	00010325	6/13/2018	TUNE	00	LABOUR	MECH	Labour			0.00	0.00	0.00		
PM57	XQ26AV	00010555	6/26/2018	TYRES											
PM57	XQ26AV	00010555	6/26/2018	TYRES	15	LABOUR	Labour			0.00	0.00	0.00			
PM57	XQ26AV	00010555	6/26/2018	TYRES	15	33000188		YAT	B FLEET PRESSURE CHECK			10.00	0.00	0.00	0.00
PM57	XQ26AV	00010603	6/29/2018	CUMAE5	01	LABOUR	Labour			0.00	0.00	0.00			
PM57	XQ26AV	00010603	6/29/2018	CUMAE5	00	LABOUR	MECH1	Labour - Internal			1.50	85.00	127.50		
PM57	XQ26AV	00010603	6/29/2018	CUMAE5	00	LABOUR	MECH1	Labour - Internal			1.50	85.00	127.50		
PM57	XQ26AV	00010603	6/29/2018	CUMAE5	14	SS70ZZM		YAT	Battery 12v			4.00	145.16	580.64	
PM57	XQ26AV	00010603	6/29/2018	CUMAE5	40	3413005		YAT	OIL 15W-40, CK 4/E9			4.00	3.54	14.16	
PM57	XQ26AV	00010603	6/29/2018	CUMAE5	16	CON		YAT	Consumables			3.00	15.00	45.00	
PM57	XQ26AV	00010603	6/29/2018	CUMAE5	SERVICE COMPLETED. 4 NEW BATTERIES FITTED. DEFECTS INSPECTED.										
PM57	XQ26AV	00010603	6/29/2018	DEFECT	01	LABOUR	MECH	Labour			0.00	0.00	0.00		
PM57	XQ26AV	00010603	6/29/2018	DEFECT	Reported Defect :- Defect Code : 00001399 Defect Reference : 7948 Date : 14/06/2018 Description of Defect : CLUTCH NEEDS TO BE ADJUSTED, NO CLUTCH BRAKE AT ALL. ADJUSTED										
PM57	XQ26AV	00010603	6/29/2018	DEFECT	Reported Defect :- Defect Code : 00001394 Defect Reference : 7944 Date : 13/06/2018 Description of Defect : STEERING IS WANDERING. COULD NOT FAULT IT.										
PM57	XQ26AV	00010603	6/29/2018	DEFECT	Reported Defect :- Defect Code : 00001393 Defect Reference : 7944 Date : 13/06/2018 Description of Defect : DRIVERS SEAT IS STUFFED. COULD NOT FAULT IT.										

[illegible]

PM57	XQ26AV	00010737	7/6/2018	GEN	00	LABOUR MECH1	Labour - Internal	4.00	85.00	340.00						
PM57	XQ26AV	00010749	7/6/2018	GEN	39	LABEXT	CORAUT01 00014677	Labour External,M57				EX00005	1.50	105.00	157.50	
PM57	XQ26AV	00010737	7/6/2018	GEN	16	CON	YAT Consumables		4.00	15.00	60.00					
PM57	XQ26AV	00010737	7/6/2018	GEN			DIAGNOSED STARTING FAILURE. STARTER LOCKED OUT FROM ECU. MADE A JUMP CABLE ACROSS STARTER RELAY AS A TEMP REPAIR. FITTED A NEW BACK UP STARTER WIRE.									
PM57	XQ26AV	00010808	7/14/2018	CUMAE5	01	LABOUR	Labour	0.00	0.00	0.00						
PM57	XQ26AV	00010808	7/14/2018	CUMBE5	01	LABOUR	Labour	0.00	0.00	0.00						
PM57	XQ26AV	00010808	7/14/2018	CUMBE5	00	LABOUR MECH	Labour - Internal	2.50	85.00	212.50						
PM57	XQ26AV	00010808	7/14/2018	CUMBE5	00	LABOUR MECH1	Labour - Internal	2.50	85.00	212.50						
PM57	XQ26AV	00010808	7/14/2018	CUMBE5	06	MK13555PRO	YAT Kit Filter Cummins ISX/E5		1.00	63.63	63.63					
PM57	XQ26AV	00010808	7/14/2018	CUMBE5	40	3413005	YAT OIL 15W-40, CK 4/E9		47.00	3.54	166.38					
PM57	XQ26AV	00010808	7/14/2018	CUMBE5	06	AS2474	YAT Ad Blue filter Kenworth		1.00	10.82	10.82					
PM57	XQ26AV	00010808	7/14/2018	CUMBE5	16	CON	YAT Consumables		6.00	15.00	90.00					
PM57	XQ26AV	00010808	7/14/2018	CUMBE5			SERVICE COMPLETED. NEEDS FUEL FILTER FS36401. TENSIONED BELLY BAR. REPLACED SEVERAL DASH LIGHTS.									
PM57	XQ26AV	00011130	7/27/2018	DEFECT	01	LABOUR MECH	Labour	0.00	0.00	0.00						
PM57	XQ26AV	00011130	7/27/2018	DEFECT			Reported Defect :- Defect Code : 00001212 Defect Reference : W/O 9578 Date : 04/05/2018 Description of Defect : RHS WINDSCREEN CRACKED. WINDSCREEN REPLACED									
PM57	XQ26AV	00011130	7/27/2018	DEFECT			Reported Defect :- Defect Code : 00001400 Defect Reference : 7949 Date : 14/06/2018 Description of Defect : RHF SCREEN CRACKED. WINDSCREEN REPLACED									
PM57	XQ26AV	00011130	7/27/2018	DEFECT	00	LABOUR MECH1	Labour - Internal	0.50	85.00	42.50						
PM57	XQ26AV	00011130	7/27/2018	DEFECT	16	CON	YAT Consumables		3.00	15.00	45.00					
PM57	XQ26AV	00011130	7/27/2018	DEFECT			ABS PLUG REPLACED ICE PACK FUEL LEAK REPAIRED DEFECT ID - SD 28580101, CRACKED WINDSCREEN REPAIRED COPY MAILED TO TMR COMPLINANCE									
PM57	XQ26AV	00011110	7/27/2018	ECO	01	LABOUR	Labour	0.00	0.00	0.00						
PM57	XQ26AV	00011110	7/27/2018	ECO	00	LABOUR MECH1	Labour - Internal	1.00	85.00	85.00						
PM57	XQ26AV	00011110	7/27/2018	ECO	06	ED002175254-S	YAT Air Filter Sleeper Air		1.00	53.50	53.50					
PM57	XQ26AV	00011110	7/27/2018	ECO	06	ED0021751550	YAT Oil Filter Eco/Sleeper		1.00	46.50	46.50					
PM57	XQ26AV	00011110	7/27/2018	ECO	06	FS1251	YAT Fuel/Water seperator filter		1.00	17.27	17.27					
PM57	XQ26AV	00011110	7/27/2018	ECO	40	3380345	YAT ENGINE OIL RX 50 MONO. SLEEPER AIR		1.10	4.26	4.69					
PM57	XQ26AV	00011110	7/27/2018	ECO	16	CON	YAT Consumables		6.00	15.00	90.00					

PM57	XQ26AV	00011110	7/27/2018	ECO	SERVICE COMPLETED									
PM57	XQ26AV	00011180	7/27/2018	GEN	REPLACED SPILT FUEL LINE AND WASHED MOTOR									
PM57	XQ26AV	00011124	7/27/2018	GEN	13	WINSR	QUAWIND01	EX00005959	Windscreen Replacement,PM57	EX00005	0.00	268.18	0.00	
PM57	XQ26AV	00011180	7/27/2018	GEN	39	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00011180	7/27/2018	GEN	SUPPLY AND FIT WINDSCREEN									
PM57	XQ26AV	00011124	7/27/2018	GEN	00	LABOUR	MECH1	Labour - Internal	0.50	85.00	42.50			
PM57	XQ26AV	00011180	7/27/2018	GEN	13	WINSR	QUAWIND01	3030	Windscreen Replacement,PM57	EX00005	1.00	268.18	268.18	
PM57	XQ26AV	00011124	7/27/2018	GEN	14	82196	YAT	EBS Plug, 7 pin 12/24v	1.00	37.73	37.73			
PM57	XQ26AV	00011124	7/27/2018	GEN	16	CON	YAT	Consumables	2.00	15.00	30.00			
PM57	XQ26AV	00011124	7/27/2018	GEN	REPLACED BROKEN ABS PLUG									
PM57	XQ26AV	00011215	8/3/2018	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00011215	8/3/2018	CUMAE5	00	LABOUR	MECH1	Labour - Internal	0.50	85.00	42.50			
PM57	XQ26AV	00011215	8/3/2018	CUMAE5	00	LABOUR	MECH1	Labour - Internal	0.50	85.00	42.50			
PM57	XQ26AV	00011215	8/3/2018	CUMAE5	13	57215	YAT	Anderson Plug	1.00	15.82	15.82			
PM57	XQ26AV	00011215	8/3/2018	CUMAE5	06	COO	YAT	Coolant Allcool K/worth	5.00	3.39	16.95			
PM57	XQ26AV	00011215	8/3/2018	CUMAE5	13	K299-682	YAT	Sunvisor Retaining Clip	1.00	7.02	7.02			
PM57	XQ26AV	00011215	8/3/2018	CUMAE5	16	CON	YAT	Consumables	4.00	15.00	60.00			
PM57	XQ26AV	00011215	8/3/2018	CUMAE5	COOLANT TOPPED UP									
					SUNVISOR HOLDER FITTED									
					ANDERSON LEAD FITTED									
PM57	XQ26AV	00011223	8/4/2018	GEN	39	2894943RX	BROHUR01	EX00005993	NOX SENSOR, KENWORTH,PM57	EX00005	0.00	714.88	0.00	
PM57	XQ26AV	00011223	8/4/2018	GEN	39	2872298D	BROHUR01	EX00005993	CORE CHARGE FOR NOX SENSOR.,PM57	EX00005	0.00	300.00	0.00	
PM57	XQ26AV	00011239	8/4/2018	GEN	39	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00011223	8/4/2018	GEN	PARTS ONLY									
PM57	XQ26AV	00011239	8/4/2018	GEN	00	LABOUR	mech1	Labour - Internal	0.50	85.00	42.50			
PM57	XQ26AV	00011223	8/4/2018	GEN	39	2872298D	BROHUR01	1426647	CORE CHARGE FOR NOX SENSOR.,PM57	EX00005	1.00	300.00	300.00	
PM57	XQ26AV	00011239	8/4/2018	GEN	03	2894943rx	YAT	NOX SENSOR, KENWORTH	1.00	716.25	716.25			
PM57	XQ26AV	00011223	8/4/2018	GEN	39	2894943RX	BROHUR01	1426647	NOX SENSOR, KENWORTH,PM57	EX00005	1.00	714.88	714.88	
PM57	XQ26AV	00011239	8/4/2018	GEN	16	CON	YAT	Consumables	2.00	15.00	30.00			
PM57	XQ26AV	00011239	8/4/2018	GEN	REPLACED NOX SENSOR AS 2ND HAND SENSOR DIDN'T FIX THE ISSUE									
PM57	XQ26AV	00011274	8/7/2018	GEN	39	LABEXT	BROHUR01	EX00006031	Labour External,PM57	EX00006	0.00	469.45	0.00	
PM57	XQ26AV	00011385	8/7/2018	GEN	39	BROLABOUR	BROHUR01	EX00006095	Brown & Hurley Labour,PM57	EX00006	0.00	0.00	0.00	
PM57	XQ26AV	00011274	8/7/2018	GEN	39	5307918	BROHUR01	EX00006031	DOSER INJECTOR, AD BLUE,PM57	EX00006	0.00	50.01	0.00	
PM57	XQ26AV	00011385	8/7/2018	GEN	39	BHPAR	BROHUR01	EX00006095	PARTS,PM57	EX00006	0.00	0.00	0.00	
PM57	XQ26AV	00011274	8/7/2018	GEN	39	MISCON	BROHUR01	EX00006031	MISCELLANEOUS CONSUMABLES,PM57	EX00006	0.00	5.00	0.00	
PM57	XQ26AV	00011385	8/7/2018	GEN	39	MISCON	BROHUR01	EX00006095	MISCELLANEOUS CONSUMABLES,PM57	EX00006	0.00	0.00	0.00	
PM57	XQ26AV	00011274	8/7/2018	GEN	39	ENVLEV	BROHUR01	EX00006031	ENVIRONMENTAL LEVY,PM57	EX00006	0.00	5.00	0.00	
PM57	XQ26AV	00011385	8/7/2018	GEN	39	ENVLEV	BROHUR01	EX00006095	ENVIRONMENTAL LEVY,PM57	EX00006	0.00	0.00	0.00	

PM57	XQ26AV	00011274	8/7/2018	GEN	DIAGNOSED AND FOUND CODE 2772 AND 585 BROWN & HURLEY FOLLOWED DIAGNOSTIC FOR CODE 2772. FOUND ADBLUE INJECTOR IS BLOCKED AND CRACKED AT THE BASE. REMOVED AND REPLACED INJECTOR WITH NEW ONE. CONTINUED TROUBLE SHOOTING PROCEDURE AS REQUIRED. CARRIED OUT CAL FILE UPDATE AS REQUIRED. CLEARED CODES, CODE 585 IS STILL ACTIVE FOR THE ENGINE STARTER MOTOR RELAY CIRCUIT, THIS FAULT NEEDS FURTHER DIAGNOSING AS TRUCK HAD TO GO. ALREADY ENTERED #6031								
PM57	XQ26AV	00011385	8/7/2018	GEN	39	ENVLEV	BROHUR01	1428643	ENVIRONMENTAL LEVY,PM57	EX00006	1.00	5.00	5.00
PM57	XQ26AV	00011274	8/7/2018	GEN	39	MISCON	BROHUR01	1428643	MISCELLANEOUS CONSUMABLES,PM57	EX00006	2.00	5.00	10.00
PM57	XQ26AV	00011274	8/7/2018	GEN	39	5307918	BROHUR01	1428643	DOSER INJECTOR, AD BLUE,PM57	EX00006	1.00	50.01	50.01
PM57	XQ26AV	00011274	8/7/2018	GEN	39	LABEXT	BROHUR01	1428643	Labour External,PM57	EX00006	1.00	469.45	469.45
PM57	XQ26AV	00011311	8/9/2018	DEFECT	01	LABOUR	Labour		0.00 0.00 0.00				
PM57	XQ26AV	00011311	8/9/2018	DEFECT	Reported Defect :- Defect Code : 00001612 Defect Reference : W/O11274 Date : 06/08/2018 Description of Defect : CODE 585 IS STILL ACTIVE FOR THE ENGINE STARTER MOTOR RELAY CIRCUIT, THIS FAULT NEEDS FURTHER DIAGNOSING COMPLETED BY MICK								
PM57	XQ26AV	00011595	8/28/2018	CUMAE5	01	LABOUR	Labour		0.00 0.00 0.00				
PM57	XQ26AV	00011595	8/28/2018	CUMAE5	00	LABOUR	mech1	Labour - Internal			1.00	85.00	85.00
PM57	XQ26AV	00011595	8/28/2018	CUMAE5	00	LABOUR	MECH1	Labour - Internal			1.00	85.00	85.00
PM57	XQ26AV	00011595	8/28/2018	CUMAE5	13	235A12	YAT	LED AUTOLAMPS 235 SERIES			1.00	38.04	38.04
PM57	XQ26AV	00011595	8/28/2018	CUMAE5	16	CON	YAT	Consumables			6.00	15.00	90.00
PM57	XQ26AV	00011595	8/28/2018	CUMAE5	SERVICE COMPLETED LHS CAB SHOCK LEAK BEING MONITORED REPLACED INDICATOR IN BULLBAR								
PM57	XQ26AV	00011784	9/10/2018	GEN	39	2872298D	BROHUR01	EX00006327	CORE CHARGE FOR NOX SENSOR.,PM57	EX00006	0.00	300.00	0.00
PM57	XQ26AV	00011784	9/10/2018	GEN	PARTS ONLY								
PM57	XQ26AV	00011784	9/10/2018	GEN	39	2872298D	BROHUR01	1452438	CORE CHARGE FOR NOX SENSOR.,PM57	EX00006	-1.00	300.00	-300.00
PM57	XQ26AV	00011908	9/13/2018	GEN	39	LABEXT	AUTELE01	EX00006423	Labour External,PM57	EX00006	0.00	200.00	0.00
PM57	XQ26AV	00011908	9/13/2018	GEN	39	CON	AUTELE01	EX00006423	H1 GLOBE,PM57	EX00006	0.00	7.27	0.00
PM57	XQ26AV	00011908	9/13/2018	GEN	39	LABEXT	AUTELE01	EX00006423	DIAGNOSTIC TOOL FEE,PM57	EX00006	0.00	150.00	0.00
PM57	XQ26AV	00011908	9/13/2018	GEN	39	CON	AUTELE01	EX00006423	WORKSHOP CONSUMABLES,PM57	EX00006	0.00	10.00	0.00
PM57	XQ26AV	00011908	9/13/2018	GEN	LOCATE FAULT WITH AD BLUE PICK UP TANK BLOCKED BLOW OUT HOSE & PRIMED								
PM57	XQ26AV	00011908	9/13/2018	GEN	39	CON	AUTELE01	00003758	WORKSHOP CONSUMABLES,PM57	EX00006	1.00	10.00	10.00
PM57	XQ26AV	00011908	9/13/2018	GEN	39	LABEXT	AUTELE01	00003758	DIAGNOSTIC TOOL FEE,PM57	EX00006	1.00	150.00	150.00
PM57	XQ26AV	00011908	9/13/2018	GEN	39	CON	AUTELE01	00003758	H1 GLOBE,PM57	EX00006	1.00	7.27	7.27
PM57	XQ26AV	00011908	9/13/2018	GEN	39	LABEXT	AUTELE01	00003758	Labour External,PM57	EX00006	1.00	200.00	200.00
PM57	XQ26AV	00011877	9/15/2018	CUMAE5	01	LABOUR	Labour		0.00 0.00 0.00				
PM57	XQ26AV	00011877	9/15/2018	CUMBE5	01	LABOUR	Labour		0.00 0.00 0.00				
PM57	XQ26AV	00011877	9/15/2018	CUMBE5	00	LABOUR	MECH	Labour - Internal			1.00	85.00	85.00

PM57	XQ26AV	00011877	9/15/2018	CUMBE5	00	LABOUR MECH1	Labour - Internal	1.00	85.00	85.00			
PM57	XQ26AV	00011877	9/15/2018	CUMBE5	00	LABOUR MECH1	Labour - Internal	1.00	85.00	85.00			
PM57	XQ26AV	00011877	9/15/2018	CUMBE5	06	MK13584	YAT MAINTENANCE KIT		1.00	86.55	86.55		
PM57	XQ26AV	00011877	9/15/2018	CUMBE5	40	3413005	YAT OIL 15W-40, CK 4/E9		48.00	3.54	169.92		
PM57	XQ26AV	00011877	9/15/2018	CUMBE5	06	FS36401	YAT Fuel Filter		1.00	17.01	17.01		
PM57	XQ26AV	00011877	9/15/2018	CUMBE5	06	AF1969M	YAT Air Filter		1.00	80.00	80.00		
PM57	XQ26AV	00011877	9/15/2018	CUMBE5	16	CON	YAT Consumables		3.00	15.00	45.00		
PM57	XQ26AV	00011877	9/15/2018	CUMBE5	SERVICE COMPLETED REPLACED WIPER BLADES REPLACED AIR FILTER NEEDS AIR DRYER KIT, CHECK VALVE NOT CLOSING								
PM57	XQ26AV	00011877	9/15/2018	DEFECT	01	LABOUR MECH	Labour	0.00	0.00	0.00			
PM57	XQ26AV	00011877	9/15/2018	DEFECT	Reported Defect :- Defect Code : 00001727 Defect Reference : W/O11596 Date : 28/08/2018 Description of Defect : NEEDS NEW HUB METER FITTED COMPLETED Reported Defect :- Defect Code : 00001513 Defect Reference : W/O 10808 Date : 14/07/2018 Description of Defect : NEEDS FUEL FILTER FS36401. REPLACED								
PM57	XQ26AV	00011877	9/15/2018	DEFECT	01	LABOUR mech	Labour	3.00	85.00	255.00			
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	00	LABOUR MECH1	Labour - Internal	3.00	85.00	255.00			
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	40	3334800	YAT Diff/Gear Oil 80W90 Castrol		33.00	6.75	222.75		
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	40	3372765	YAT Syntrans Gear Oil 75w/90		12.00	13.41	160.92		
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	06	A-3380W1687	YAT DIFF FILTER		1.00	18.22	18.22		
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	06	ALLCOOL-WF	YAT Cooling System Filter		1.00	30.63	30.63		
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	06	17237	YAT Filter Element Gearbox Eaton		1.00	26.00	26.00		
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	06	T224P	YAT Turbo 2000 Air dryer		1.00	162.73	162.73		
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	06	LF637	YAT Power Steer Filter LF637		1.00	24.86	24.86		
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	06	HHW0116	YAT Ad Blue Filter (K200)		1.00	26.91	26.91		
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	16	CON	YAT Consumables		4.00	15.00	60.00		
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	SERVICE COMPLETED REKITTED AIR DRYER UNBLOCKED LHS WINDSCREEN WASHER								
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	01	T2000SK-P	BROHUR01 EX00006448 Kit Air Dryer,PM57			EX00006	0.00	271.82	0.00
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	01	CON	BROHUR01 EX00006448 DISCOUNT,PM57			EX00006	0.00	45.45	0.00
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	PARTS FROM B&H								
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	01	CON	BROHUR01 1459242 DISCOUNT,PM57			EX00006	-1.00	45.45	-45.45
PM57	XQ26AV	00011954	9/20/2018	CUMCE5	01	T2000SK-P	BROHUR01 1459242 Kit Air Dryer,PM57			EX00006	1.00	271.83	271.83
PM57	XQ26AV	00011954	9/20/2018	DEFECT	01	LABOUR MECH	Labour	0.00	0.00	0.00			

PM57	XQ26AV	00011954	9/20/2018	DEFECT	Reported Defect :- Defect Code : 00001817 Defect Reference : WO11877 Date : 15/09/2018 Description of Defect : NEEDS AIR DRYER KIT, CHECK VALVE NOT CLOSING REKITTED									
PM57	XQ26AV	00011953	9/20/2018	EXOINS	01	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00011953	9/20/2018	EXOINS	00	LABOUR	MECH	Labour - Internal		2.00	85.00	170.00		
PM57	XQ26AV	00011953	9/20/2018	EXOINS	PASSED 1ST INSPECTION									
PM57	XQ26AV	00011982	9/20/2018	GEN	39	PART	GIBBS01	EX00006459	BRAKE SHOES & HARDWARE KIT 4707,PM57		EX000006	0.00	70.63	0.00
PM57	XQ26AV	00011982	9/20/2018	GEN	PARTS ONLY									
PM57	XQ26AV	00011982	9/20/2018	GEN	39	PART	GIBBS01	1271304	BRAKE SHOES & HARDWARE KIT 4707,PM57		EX000006	2.00	70.63	141.26
PM57	XQ26AV	00012007	9/24/2018	TYRES	15	33000051	BRI AUS01	EX00006476	BALANCE TBR,PM57		EX000006	0.00	25.00	0.00
PM57	XQ26AV	00012007	9/24/2018	TYRES	TYRE ROTATION - STEER									
PM57	XQ26AV	00012007	9/24/2018	TYRES	15	33000051	BRI AUS01	96128364	BALANCE TBR,PM57		EX000006	2.00	25.00	50.00
PM57	XQ26AV	00012064	9/26/2018	GEN	39	LABEXT	BROHUR01	EX00006503	Labour External,PM57		EX000006	0.00	175.71	0.00
PM57	XQ26AV	00012064	9/26/2018	GEN	39	CON	BROHUR01	EX00006503	Consumables		EX000006	0.00	10.00	0.00
									,PM57					
PM57	XQ26AV	00012064	9/26/2018	GEN	39	ENVLEV	BROHUR01	EX00006503	ENVIRONMENTAL LEVY,PM57		EX000006	0.00	15.00	0.00
PM57	XQ26AV	00012064	9/26/2018	GEN	RECITIFY ADBLUE INJECTOR NOT SEATING CORRECTLY IN EXHAUST CLEANED INJECTOR & FITTED CORRECTLY. FITTED SEAT COVERS TO DRIVERS SEAT									
PM57	XQ26AV	00012064	9/26/2018	GEN	39	ENVLEV	BROHUR01	1463643	ENVIRONMENTAL LEVY,PM57		EX000006	1.00	15.00	15.00
PM57	XQ26AV	00012064	9/26/2018	GEN	39	CON	BROHUR01	1463643	Consumables		EX000006	1.00	10.00	10.00
									,PM57					
PM57	XQ26AV	00012064	9/26/2018	GEN	39	LABEXT	BROHUR01	1463643	Labour External,PM57		EX000006	1.00	175.71	175.71
PM57	XQ26AV	00012061	9/27/2018	DEFECT	01	LABOUR	MECH	Labour	0.00	0.00	0.00			
PM57	XQ26AV	00012061	9/27/2018	DEFECT	Reported Defect :- Defect Code : 00001382 Defect Reference : W/O 10325 Date : 13/06/2018 Description of Defect : RHS CAB LOCK LEAKING BADLY. REPLACED RHS CAB LOCK									
PM57	XQ26AV	00012105	9/27/2018	GEN	39	LABEXT	CORAU T01	EX00006546	Labour External,PM57		EX000006	0.00	105.00	0.00
PM57	XQ26AV	00012061	9/27/2018	GEN	39	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00012105	9/27/2018	GEN	39	R134A	CORAU T01	EX00006546	R134A, A/C GAS,PM57		EX000006	0.00	150.00	0.00
PM57	XQ26AV	00012061	9/27/2018	GEN	00	LABOUR	MECH1	Labour - Internal		1.00	85.00	85.00		
PM57	XQ26AV	00012105	9/27/2018	GEN	REGASED SLEEPER AIR									
PM57	XQ26AV	00012061	9/27/2018	GEN	00	LABOUR	APPREN	Labour - Internal		1.00	85.00	85.00		
PM57	XQ26AV	00012105	9/27/2018	GEN	39	R134A	CORAU T01	00015028	R134A, A/C GAS,PM57		EX000006	1.00	150.00	150.00
PM57	XQ26AV	00012061	9/27/2018	GEN	16	CON	YAT	Consumables	4.00	15.00	60.00			
PM57	XQ26AV	00012105	9/27/2018	GEN	39	LABEXT	CORAU T01	00015028	Labour External,PM57		EX000006	1.00	105.00	105.00

PM57	XQ26AV	00012061	9/27/2018	GEN	REPLACED RHS CAB LOCK CHECKED SLEEPER AIR FOUND PROBLEM TO BE LOW GAS, SLEEPER AIR FILLED WITH GAS BY CORRECT AUTO									
PM57	XQ26AV	00012183	10/6/2018	GEN	39 LABOUR Labour	0.00	0.00	0.00						
PM57	XQ26AV	00012183	10/6/2018	GEN	00 LABOUR MECH1 Labour - Internal		1.00	85.00	85.00					
PM57	XQ26AV	00012183	10/6/2018	GEN	00 LABOUR MECH Labour - Internal		0.50	85.00	42.50					
PM57	XQ26AV	00012183	10/6/2018	GEN	16 CON YAT Consumables			3.00	15.00	45.00				
PM57	XQ26AV	00012183	10/6/2018	GEN	REMOVE & REPAIR CLUTCH CONDRAN AS REQUIRED, COULDN'T ADJUST FREE TRAVEL ON CLUTCH									
PM57	XQ26AV	00012225	10/11/2018	CUMAE5	01 LABOUR Labour	0.00	0.00	0.00						
PM57	XQ26AV	00012225	10/11/2018	CUMAE5	00 LABOUR MECH Labour - Internal		1.00	85.00	85.00					
PM57	XQ26AV	00012225	10/11/2018	CUMAE5	00 LABOUR MECH1 Labour - Internal		1.00	85.00	85.00					
PM57	XQ26AV	00012225	10/11/2018	CUMAE5	00 LABOUR APPREN Labour - Internal		1.00	85.00	85.00					
PM57	XQ26AV	00012225	10/11/2018	CUMAE5	16 CON YAT Consumables			6.00	15.00	90.00				
PM57	XQ26AV	00012225	10/11/2018	CUMAE5	SERVICE COMPLETED REPAIRED DRIVING LIGHT ELEC CIRCUIT WASHED OUT RADIATOR & INTERCOOLER (EXTERNAL) REMOVED 1 SET OF DRIVING LIGHTS									
PM57	XQ26AV	00012613	11/3/2018	CUMAE5	01 LABOUR Labour	0.00	0.00	0.00						
PM57	XQ26AV	00012613	11/3/2018	CUMAE5	00 LABOUR MECH1 Labour - Internal		0.75	85.00	63.75					
PM57	XQ26AV	00012613	11/3/2018	CUMAE5	00 LABOUR TRADEA Labour - Internal		0.75	85.00	63.75					
PM57	XQ26AV	00012613	11/3/2018	CUMAE5	40 3413005 YAT OIL 15W-40, CK 4/E9			5.00	3.54	17.70				
PM57	XQ26AV	00012613	11/3/2018	CUMAE5	16 CON YAT Consumables			5.00	15.00	75.00				
PM57	XQ26AV	00012613	11/3/2018	CUMAE5	SERVICE COMPLETED TOPPED UP OIL (5LT) TIGHTENED BELLY BAR									
PM57	XQ26AV	00012815	11/13/2018	CUMAE5	01 LABOUR Labour	0.00	0.00	0.00						
PM57	XQ26AV	00012815	11/13/2018	CUMBE5	01 LABOUR Labour	0.00	0.00	0.00						
PM57	XQ26AV	00012815	11/13/2018	CUMBE5	00 LABOUR MECH1 Labour - Internal		1.50	85.00	127.50					
PM57	XQ26AV	00012815	11/13/2018	CUMBE5	00 LABOUR APPREN Labour - Internal		1.50	85.00	127.50					
PM57	XQ26AV	00012815	11/13/2018	CUMBE5	06 MK13555 YAT FILTER KIT, OIL & FUEL FILTER, (E5)			1.00	82.89	82.89				
PM57	XQ26AV	00012815	11/13/2018	CUMBE5	06 AS2474 YAT Ad Blue filter Kenworth			1.00	10.82	10.82				
PM57	XQ26AV	00012815	11/13/2018	CUMBE5	40 3413005 YAT OIL 15W-40, CK 4/E9			48.00	3.54	169.92				
PM57	XQ26AV	00012815	11/13/2018	CUMBE5	13 K161-4819-1 YAT FUEL TANK STRAP RUBBER			2.00	28.04	56.08				
PM57	XQ26AV	00012815	11/13/2018	CUMBE5	16 CON YAT Consumables			5.00	15.00	75.00				
PM57	XQ26AV	00012815	11/13/2018	CUMBE5	SERVICE COMPLETED TENSIONED LOOSE BELLY BAR REPLACED 2 X TANK STRAP RUBBERS TENSIONED LOOSE CHECKER PLATE CLAMPS REPALCED WIPER BLADES									
PM57	XQ26AV	00013055	11/23/2018	TYRES	15 33000241 BRIAUS01 EX00007093 SCRAP TYRES TBR,PM57			EX00007	0.00	14.00	0.00			
PM57	XQ26AV	00013055	11/23/2018	TYRES	PUNCTURE REPAIR									
PM57	XQ26AV	00013055	11/23/2018	TYRES	15 33000241 BRIAUS01 96331943 SCRAP TYRES TBR,PM57			EX00007	1.00	14.00	14.00			
PM57	XQ26AV	00013058	11/24/2018	GEN	39 499080B BROHUR01 EX00007095 Tilt Lock - Gas Strut Gen 2.5,PM57			EX00007	0.00	561.65	0.00			
PM57	XQ26AV	00013058	11/24/2018	GEN	39 499080B BROHUR01 EX00007096 Tilt Lock - Gas Strut Gen 2.5,PM57			EX00007	0.00	561.65	0.00			
PM57	XQ26AV	00013058	11/24/2018	GEN	WRONG PART									
PM57	XQ26AV	00013058	11/24/2018	GEN	39 499080B BROHUR01 1505203 Tilt Lock - Gas Strut Gen 2.5,PM57			EX00007	1.00	561.65	561.65			

PM57	XQ26AV	00013058	11/24/2018	GEN	39	499080B	BROHUR01	1505213	Tilt Lock - Gas Strut Gen 2.5,PM57		EX00007	-1.00	561.65	-561.65
PM57	XQ26AV	00013183	12/1/2018	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00013183	12/1/2018	CUMAE5	00	LABOUR	MECH1	Labour - Internal		1.50	85.00	127.50		
PM57	XQ26AV	00013183	12/1/2018	CUMAE5	00	LABOUR	APPREN	Labour - Internal		1.00	85.00	85.00		
PM57	XQ26AV	00013183	12/1/2018	CUMAE5	16	CON	YAT	Consumables			8.00	15.00	120.00	
PM57	XQ26AV	00013183	12/1/2018	CUMAE5				SERVICE COMPLETED						
								REPLACED FIRE EXTINGUISHER						
								SWITCHED AUX TO CONSTANT POWER						
PM57	XQ26AV	00013187	12/2/2018	GEN	39	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00013187	12/2/2018	GEN	00	LABOUR	MECH1	Labour - Internal		1.50	85.00	127.50		
PM57	XQ26AV	00013187	12/2/2018	GEN	03	MF70ZZD	YAT	DEEP CYCLE BATTERY			4.00	176.85	707.40	
PM57	XQ26AV	00013187	12/2/2018	GEN	16	CON	YAT	Consumables			6.00	15.00	90.00	
PM57	XQ26AV	00013187	12/2/2018	GEN				CALLED OUT AT 3.30PM ON SUNDAY ARVO TO GET TRUCK STARTED IN YARD						
								CHECKED STARTER MOTOR WIRES & BATTERY TERMINAL CABLES & CLAMPS						
								SOUNDED LIKE LOW VOLTAGE BATTERIES						
								REMOVED CLAMPS & LOAD TESTED BATTERIES - ALL FAILED						
								R&R ALL BATTERIES						
PM57	XQ26AV	00013418	12/14/2018	TYRES				STARTED TRUCK & PUT CAB BACK DOWN						
PM57	XQ26AV	00013418	12/14/2018	TYRES	15	33000051	BRIAUS01	EX00007312	BALANCE TBR,PM57		EX00007	0.00	25.00	0.00
PM57	XQ26AV	00013418	12/14/2018	TYRES	15	33000051	BRIAUS01	96404594	BALANCE TBR,PM57		EX00007	2.00	25.00	50.00
PM57	XQ26AV	00013484	12/15/2018	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00013484	12/15/2018	CUMAE5	00	LABOUR	MECH1	Labour - Internal		0.75	85.00	63.75		
PM57	XQ26AV	00013484	12/15/2018	CUMAE5	00	LABOUR	APPREN	Labour - Internal		1.00	85.00	85.00		
PM57	XQ26AV	00013484	12/15/2018	CUMAE5	16	CON	YAT	Consumables			4.00	15.00	60.00	
PM57	XQ26AV	00013484	12/15/2018	CUMAE5				SERVICE COMPLETED.						
								GRILL NEEDS REPAIRS						
								OIL LEAK REAR OF ENGINE						
								REPLACED BACK AXLE DRIVE SHOCKS						
PM57	XQ26AV	00013484	12/15/2018	CUMAE5	10	M85902	YAT	Shocky Drv. (Meritor) K'worth		2.00	83.59	167.18		
PM57	XQ26AV	00013454	12/15/2018	GEN	39	M85902	BROHUR01	EX00007326	Shocky Drv. (Meritor) K'worth,PM57		EX00007	0.00	81.77	0.00
PM57	XQ26AV	00013454	12/15/2018	GEN				PARTS ONLY						
PM57	XQ26AV	00013454	12/15/2018	GEN	39	M85902	BROHUR01	1521256	Shocky Drv. (Meritor) K'worth,PM57		EX00007	2.00	81.77	163.54
PM57	XQ26AV	00013862	1/10/2019	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00013862	1/10/2019	CUMAE5	00	LABOUR	MECH1	Labour - Internal		0.75	85.00	63.75		
PM57	XQ26AV	00013862	1/10/2019	CUMAE5	00	LABOUR	APPREN	Labour - Internal		0.75	85.00	63.75		
PM57	XQ26AV	00013862	1/10/2019	CUMAE5	13	82161/1	YAT	7 PIN LG RND METAL PLUG			1.00	5.77	5.77	
PM57	XQ26AV	00013862	1/10/2019	CUMAE5	16	CON	YAT	Consumables			4.00	15.00	60.00	
PM57	XQ26AV	00013862	1/10/2019	CUMAE5				SERVICE COMPLETED						
								REFITTED EBS PLUG AS REQUIRED						
								FITTED NEW TRAILER PLUG AS REQUIRED						
PM57	XQ26AV	00014111	1/21/2019	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00014111	1/21/2019	CUMBE5	01	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00014111	1/21/2019	CUMBE5	00	LABOUR	MECH1	Labour - Internal		3.00	85.00	255.00		
PM57	XQ26AV	00014111	1/21/2019	CUMBE5	00	LABOUR	MECH1	Labour - Internal		1.00	85.00	85.00		
PM57	XQ26AV	00014111	1/21/2019	CUMBE5	06	AF1969M	YAT	Air Filter			1.00	80.41	80.41	

PM57	XQ26AV	00014111	1/21/2019	CUMBE5	06	MK13555	YAT	FILTER KIT, OIL & FUEL FILTER, (E5)	1.00	82.00	82.00				
PM57	XQ26AV	00014111	1/21/2019	CUMBE5	40	3413005	YAT	OIL 15W-40, CK 4/E9	47.00	3.54	166.38				
PM57	XQ26AV	00014111	1/21/2019	CUMBE5	06	FS36401	YAT	Fuel Filter	1.00	17.15	17.15				
PM57	XQ26AV	00014111	1/21/2019	CUMBE5	WAITING ON INVOICE B&H SERVICE COMPLETED CHANGED OUT EXHAUST FLEX AFTER UTURBO ASREQUIRED CHANGED 3 X EXHAUST GASKETS AS REQUIRED										
PM57	XQ26AV	00014111	1/21/2019	CUMBE5	01	SSFBKEN127-335	BROHUR01	EX00007694	FLEX BELLOW,PM57			EX000007	0.00	270.75	0.00
PM57	XQ26AV	00014111	1/21/2019	CUMBE5	01	2866337	BROHUR01	EX00007694	Gasket, Exhaust Flex, K200,PM57			EX000007	0.00	25.72	0.00
PM57	XQ26AV	00014111	1/21/2019	CUMBE5	03	2866337	YAT	Gasket, Exhaust Flex, K200	1.00	25.72	25.72				
PM57	XQ26AV	00014111	1/21/2019	CUMBE5	01	2866337	BROHUR01	1542144	Gasket, Exhaust Flex, K200,PM57			EX000007	2.00	25.72	51.44
PM57	XQ26AV	00014111	1/21/2019	CUMBE5	01	SSFBKEN127-335	BROHUR01	1542144	FLEX BELLOW,PM57			EX000007	1.00	270.75	270.75
PM57	XQ26AV	00014491	2/6/2019	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00014491	2/6/2019	CUMAE5	00	LABOUR	MECH	Labour - Internal	1.50	85.00	127.50				
PM57	XQ26AV	00014491	2/6/2019	CUMAE5	16	CON	YAT	Consumables	3.00	15.00	45.00				
PM57	XQ26AV	00014491	2/6/2019	CUMAE5	SERVICE COMPLETED TENSIONED LOOSE GRILLE										
PM57	XQ26AV	00014491	2/6/2019	DEFECT	01	LABOUR	MECH	Labour	0.00	0.00	0.00				
PM57	XQ26AV	00014491	2/6/2019	DEFECT	Reported Defect :- Defect Code : 00002126 Defect Reference : WO13484 Date : 15/12/2018 Description of Defect : GRILL NEEDS REPAIRS COMPLETED										
PM57	XQ26AV	00014756	2/18/2019	TYRES	15	77000180	BRIAUS01	EX00008024	CASE STOCK 11-22.5,PM57			EX000008	0.00	20.00	0.00
PM57	XQ26AV	00014756	2/18/2019	TYRES	15	11002831	YAT	TYRE 11R22.5 146/143L M766	1.00	495.00	495.00				
PM57	XQ26AV	00014756	2/18/2019	TYRES	R&R TYRES										
PM57	XQ26AV	00014756	2/18/2019	TYRES	15	77000180	BRIAUS01	96594565	CASE STOCK 11-22.5,PM57			EX000008	-4.00	20.00	-80.00
PM57	XQ26AV	00014765	2/19/2019	GEN	39	13A0990	KENAUT01	EX00008046	Belt SLEEPER AIR STD,PM57			EX000008	0.00	21.20	0.00
PM57	XQ26AV	00014765	2/19/2019	GEN	39	LABEXT	KENAUT01	EX00008046	Labour External,PM57			EX000008	0.00	95.00	0.00
PM57	XQ26AV	00014765	2/19/2019	GEN	FOUND SLEEPER AIR NOT BLOWING COLD AIR. FOUND DRIVE BELTS SHREDDED. R&R BELTS. TESTED OK. CLEANED OUT ENGINE BAY. CLEANED AIR FILTERS & ADJUSTED IDLE										
PM57	XQ26AV	00014765	2/19/2019	GEN	39	LABEXT	KENAUT01	34487	Labour External,PM57			EX000008	1.50	95.00	142.50
PM57	XQ26AV	00014765	2/19/2019	GEN	39	13A0990	KENAUT01	34487	Belt SLEEPER AIR STD,PM57			EX000008	2.00	21.20	42.40
PM57	XQ26AV	00014863	2/25/2019	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00014863	2/25/2019	CUMAE5	00	LABOUR	MECH1	Labour - Internal	2.00	85.00	170.00				
PM57	XQ26AV	00014863	2/25/2019	CUMAE5	40	3413005	YAT	OIL 15W-40, CK 4/E9	5.00	3.54	17.70				
PM57	XQ26AV	00014863	2/25/2019	CUMAE5	16	CON	YAT	Consumables	7.00	15.00	105.00				
PM57	XQ26AV	00014863	2/25/2019	CUMAE5	SERVICE COMPLETED TOPPED UP ENGINE OIL CLEANED & LUBBED STEERING COLUMN LOCK GRILL BROKEN & NEEDS TO BE REMOVED & REPAIRED A/C LINE FROM CONDENSOR TO RECIEVER DRYER LEAKING REMOVED WHEEL NUTS										
PM57	XQ26AV	00014975	3/2/2019	GEN	39	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00014975	3/2/2019	GEN	00	LABOUR	MECH1	Labour - Internal	1.50	85.00	127.50				

PM57	XQ26AV	00014975	3/2/2019	GEN	16	CON	YAT	Consumables	5.00	15.00	75.00				
PM57	XQ26AV	00014975	3/2/2019	GEN	R&R SMASHED MIRROR GLASS (SUPPLIED BY DRIVER)										
PM57	XQ26AV	00015503	3/12/2019	GEN	39	PART	BRIVAL01	EX00008458	MISC HOSE & FITTING,PM57			EX00008	0.00	120.00	0.00
PM57	XQ26AV	00015503	3/12/2019	GEN	39	R134A	BRIVAL01	EX00008458	R134A, A/C GAS,PM57			EX00008	0.00	65.00	0.00
PM57	XQ26AV	00015503	3/12/2019	GEN	39	CON	BRIVAL01	EX00008458	Consumables			EX00008	0.00	10.00	0.00
									,PM57						
PM57	XQ26AV	00015503	3/12/2019	GEN	39	LABEXT	BRIVAL01	EX00008458	Labour External,PM57			EX00008	0.00	85.00	0.00
PM57	XQ26AV	00015503	3/12/2019	GEN	REMOVED U/S AC HOSE, ASSEMBLED & FITTED HOSE, CHARGED WITH GAS										
PM57	XQ26AV	00015503	3/12/2019	GEN	39	LABEXT	BRIVAL01	00000176	Labour External,PM57			EX00008	2.50	85.00	212.50
PM57	XQ26AV	00015503	3/12/2019	GEN	39	CON	BRIVAL01	00000176	Consumables			EX00008	1.00	10.00	10.00
									,PM57						
PM57	XQ26AV	00015503	3/12/2019	GEN	39	R134A	BRIVAL01	00000176	R134A, A/C GAS,PM57			EX00008	2.50	65.00	162.50
PM57	XQ26AV	00015503	3/12/2019	GEN	39	PART	BRIVAL01	00000176	MISC HOSE & FITTING,PM57			EX00008	1.00	120.00	120.00
PM57	XQ26AV	00015512	3/19/2019	GEN	39	LABEXT	VISMEC01	EX00008468	Labour External,PM57			EX00008	0.00	200.40	0.00
PM57	XQ26AV	00015750	3/19/2019	GEN	39	LABEXT	VISMEC01	EX00008575	Labour External,PM57			EX00008	0.00	0.00	0.00
PM57	XQ26AV	00015512	3/19/2019	GEN	39	CON	VISMEC01	EX00008468	Consumables			EX00008	0.00	6.00	0.00
									,PM57						
PM57	XQ26AV	00015750	3/19/2019	GEN	39	CON	VISMEC01	EX00008575	Consumables			EX00008	0.00	0.00	0.00
									,PM57						
PM57	XQ26AV	00015512	3/19/2019	GEN	39	ENVLEV	VISMEC01	EX00008468	ENVIRONMENTAL LEVY,PM57			EX00008	0.00	5.00	0.00
PM57	XQ26AV	00015750	3/19/2019	GEN	39	ENVLEV	VISMEC01	EX00008575	ENVIRONMENTAL LEVY,PM57			EX00008	0.00	0.00	0.00
PM57	XQ26AV	00015512	3/19/2019	GEN	AFTERTREATMENT LIGHT ON - FOUND DOSING PUMP WAS LOSING T'S PRIME. REMOVED THE INJECTOR & FOUNDIT WASN'T SPRAYING AS MUCH AS IT SHOULD. CLEANED THE LINES OUT & FLUSHED THEM. RETESTED & OK										
PM57	XQ26AV	00015750	3/19/2019	GEN	AFTERTREATMENT LIGHT ON - FOUND DOSING PUMP WAS LOSING IT'S PRIME. REMOVED THE INJECTOR & FOUND IT WASN'T SPRAYING AS MUCH AS IT SHOULD. CLEANED THE LINES OUT & FLUSHED THEM. RETESTED - OK										
PM57	XQ26AV	00015512	3/19/2019	GEN	39	ENVLEV	VISMEC01	1122669	ENVIRONMENTAL LEVY,PM57			EX00008	1.00	5.00	5.00
PM57	XQ26AV	00015512	3/19/2019	GEN	39	CON	VISMEC01	1122669	Consumables			EX00008	1.00	6.00	6.00
									,PM57						
PM57	XQ26AV	00015512	3/19/2019	GEN	39	LABEXT	VISMEC01	1122669	Labour External,PM57			EX00008	1.00	200.40	200.40
PM57	XQ26AV	00015541	3/22/2019	WARRANT	39	LABOUR	Labour - Internal		0.00	0.00	0.00				
PM57	XQ26AV	00015541	3/22/2019	WARRANT	CUMMINS EXTENDED WARRANTY NEW DATE 03 SEPT 2020 1,2000,000KMS										
PM57	XQ26AV	00015746	3/28/2019	TYRES	15	11001553	BRIAUS01	EX00008570	TYRE 295/80R22.5 152/148M BS R150,PM57			EX00008	0.00	494.00	0.00
PM57	XQ26AV	00015746	3/28/2019	TYRES	15	33000051	BRIAUS01	EX00008570	BALANCE TBR,M57			EX00008	0.00	25.00	0.00
PM57	XQ26AV	00015746	3/28/2019	TYRES	15	77000194	BRIAUS01	EX00008570	case stock 295/80-22.5,PM57			EX00008	0.00	20.00	0.00
PM57	XQ26AV	00015746	3/28/2019	TYRES	R&R TYRES STEER										
PM57	XQ26AV	00015746	3/28/2019	TYRES	15	77000194	BRIAUS01	3410434959	case stock 295/80-22.5,PM57			EX00008	-2.00	20.00	-40.00
PM57	XQ26AV	00015746	3/28/2019	TYRES	15	33000051	BRIAUS01	3410434959	BALANCE TBR,M57			EX00008	2.00	25.00	50.00
PM57	XQ26AV	00015746	3/28/2019	TYRES	15	11001553	BRIAUS01	3410434959	TYRE 295/80R22.5 152/148M BS R150,PM57			EX00008	2.00	494.00	988.00
PM57	XQ26AV	00015771	4/1/2019	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00015771	4/1/2019	CUMBE5	01	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00015771	4/1/2019	CUMBE5	00	LABOUR	MECH1	Labour - Internal		5.00	85.00	425.00			
PM57	XQ26AV	00015771	4/1/2019	CUMBE5	00	LABOUR	APPREN	Labour - Internal		5.00	85.00	425.00			
PM57	XQ26AV	00015771	4/1/2019	CUMBE5	06	MK13584	YAT	MAINTENANCE KIT		1.00	91.95	91.95			

PM57	XQ26AV	00015771	4/1/2019	CUMBE5	06	K37-1004	YAT	Water/Fuel Filter Seperator	1.00	26.11	26.11				
PM57	XQ26AV	00015771	4/1/2019	CUMBE5	40	3413005	YAT	OIL 15W-40, CK 4/E9	49.00	3.74	183.26				
PM57	XQ26AV	00015771	4/1/2019	CUMBE5	02	AIRBRAHOS	YAT	Air Brake Hose	6.00	6.51	39.06				
PM57	XQ26AV	00015771	4/1/2019	CUMBE5	11	12PK2380	YAT	Drive Belt, K200	1.00	68.86	68.86				
PM57	XQ26AV	00015771	4/1/2019	CUMBE5	11	6PK1590	YAT	Fan Belt	1.00	39.10	39.10				
PM57	XQ26AV	00015771	4/1/2019	CUMBE5	40	3380345	YAT	ENGINE OIL RX 50 MONO. SLEEPER AIR	1.00	4.26	4.26				
PM57	XQ26AV	00015771	4/1/2019	CUMBE5	11	6303-2RS	YAT	6303-2RS idler bearing	1.00	4.25	4.25				
PM57	XQ26AV	00015771	4/1/2019	CUMBE5	16	CON	YAT	Consumables	5.00	15.00	75.00				
PM57	XQ26AV	00015771	4/1/2019	CUMBE5	SERVICE COMPLETED EXTENDED AIRLINES, PRESSUREIZED INTERCOOLER & PIPING FOR BOOST LEAKS, CHECKED WASTE GATE OPERATION, FIXED FUEL LEAK/REPLACED FUEL LINE ON SLEEPER AIR, SERVICED SLEEPER AIR, CHANGED OVER STEERING WHEEL WITH 2ND HAND ON AS REQUIRED REPLACED BEARING IN IDLER (AC BELT) AS REQUIRED										
PM57	XQ26AV	00015845	4/1/2019	GEN	39	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00015845	4/1/2019	GEN	PART ONLY ADDED										
PM57	XQ26AV	00015845	4/1/2019	GEN	13	S91-1014-110	YAT	STEERING WHEEL KW	1.00	336.64	336.64				
PM57	XQ26AV	00015965	4/5/2019	GEN	39	LABEXT	BROHUR01	EX00008664	Labour External,PM57			EX00008	0.00	274.00	0.00
PM57	XQ26AV	00015965	4/5/2019	GEN	39	CON	BROHUR01	EX00008664	FITTING,PM57			EX00008	0.00	1.20	0.00
PM57	XQ26AV	00015965	4/5/2019	GEN	39	CON	BROHUR01	EX00008664	FITTING,PM57			EX00008	0.00	3.62	0.00
PM57	XQ26AV	00015965	4/5/2019	GEN	39	308935.515PAC	BROHUR01	EX00008664	CLUTCH KIT-ADVANTAGE,PM57			EX00008	0.00	1,441.45	0.00
PM57	XQ26AV	00015965	4/5/2019	GEN	39	K-4460-PAC	BROHUR01	EX00008664	CLUTCH KIT INC KW X SHAFTS,PM57			EX00008	0.00	394.55	0.00
PM57	XQ26AV	00015965	4/5/2019	GEN	39	E55-1129	BROHUR01	EX00008664	LEVER-CLUTCH CONTROL,PM57			EX00008	0.00	148.46	0.00
PM57	XQ26AV	00015965	4/5/2019	GEN	39	LABEXT	BROHUR01	EX00008664	FLYWHEEL MACHINED,PM57			EX00008	0.00	180.00	0.00
PM57	XQ26AV	00015965	4/5/2019	GEN	39	CON	BROHUR01	EX00008664	Consumables			EX00008	0.00	20.00	0.00
PM57	XQ26AV	00015965	4/5/2019	GEN	39	ENVLEV	BROHUR01	EX00008664	ENVIRONMENTAL LEVY,PM57			EX00008	0.00	10.00	0.00
PM57	XQ26AV	00015965	4/5/2019	GEN	B&H YATALA - REPLACED CLUTCH, MACHINE FLYWHEEL REPLACED INPUT SHAFT KIT * WORN CLUTCH LEVER DURING REPAIR FROM OIL LEAK										
PM57	XQ26AV	00015965	4/5/2019	GEN	39	ENVLEV	BROHUR01	1596185	ENVIRONMENTAL LEVY,PM57			EX00008	1.00	10.00	10.00
PM57	XQ26AV	00015965	4/5/2019	GEN	39	CON	BROHUR01	1596185	Consumables			EX00008	1.00	20.00	20.00
PM57	XQ26AV	00015965	4/5/2019	GEN	39	LABEXT	BROHUR01	1596185	FLYWHEEL MACHINED,PM57			EX00008	1.00	180.00	180.00
PM57	XQ26AV	00015965	4/5/2019	GEN	39	E55-1129	BROHUR01	1596185	LEVER-CLUTCH CONTROL,PM57			EX00008	1.00	148.46	148.46
PM57	XQ26AV	00015965	4/5/2019	GEN	39	K-4460-PAC	BROHUR01	1596185	CLUTCH KIT INC KW X SHAFTS,PM57			EX00008	1.00	394.55	394.55
PM57	XQ26AV	00015965	4/5/2019	GEN	39	308935.515PAC	BROHUR01	1596185	CLUTCH KIT-ADVANTAGE,PM57			EX00008	1.00	1,441.45	1,441.45
PM57	XQ26AV	00015965	4/5/2019	GEN	39	CON	BROHUR01	1596185	FITTING,PM57			EX00008	1.00	3.62	3.62
PM57	XQ26AV	00015965	4/5/2019	GEN	39	CON	BROHUR01	1596185	FITTING,PM57			EX00008	1.00	1.20	1.20
PM57	XQ26AV	00015965	4/5/2019	GEN	39	LABEXT	BROHUR01	1596185	Labour External,PM57			EX00008	1.00	274.00	274.00
PM57	XQ26AV	00016391	4/26/2019	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00016391	4/26/2019	CUMAE5	00	LABOUR	MECH1	Labour - Internal	4.50	85.00	382.50				
PM57	XQ26AV	00016391	4/26/2019	CUMAE5	00	LABOUR	APPREN	Labour - Internal	3.00	85.00	255.00				
PM57	XQ26AV	00016391	4/26/2019	CUMAE5	40	3413005	YAT	OIL 15W-40, CK 4/E9	6.00	3.54	21.24				
PM57	XQ26AV	00016391	4/26/2019	CUMAE5	13	K307-25	YAT	Bezel-Single Round	1.00	43.65	43.65				

PM57	XQ26AV	00016391	4/26/2019	CUMAE5	16	CON	YAT	Consumables		6.00	15.00	90.00		
PM57	XQ26AV	00016391	4/26/2019	CUMAE5	SERVICE COMPLETED BILLY - TOPPED UP ENGINE OIL REPLACED CHROME HEADLIGHT COVER DRIVERS SIDE OUTER LIGHT REPLACED MAIN AIR LINE OFF COMPRESSOR TO AIR DRYER AS REQUIRED REPAIRED DAMAGED PULL CORD FOR AIR TANK DRAIN VALVE REMOVED GRILL & REPAIRED DAMAGED BOTTOM LHS CORNER RPLACED P CLAMP ON COMPRESSOR HOSE REPLACED RUBBER PLUG INSERT ON FRONT OF ENGINE OIL AS LEAKING, WASHED DOWN & FITTED NEW PLUG KEIRAN - SERVICED SLEEPER AIR REPLACED OIL PRESSURE SWITCH RE FLOW OIL EXHAUST									
PM57	XQ26AV	00016391	4/26/2019	CUMAE5	03	3688113	YAT	PLUG GEAR COVER		1.00	44.42	44.42		
PM57	XQ26AV	00016391	4/26/2019	DEFECT	01	LABOUR	MECH	Labour	0.00	0.00	0.00			
PM57	XQ26AV	00016391	4/26/2019	DEFECT	Reported Defect :- Defect Code : 00002319 Defect Reference : WO14863 Date : 25/02/2019 Description of Defect : GRILL BROKEN & NEEDS TO BE REMOVED & REPAIRED									
PM57	XQ26AV	00016392	4/26/2019	ECO	01	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00016392	4/26/2019	ECO	00	LABOUR	APPREN	Labour - Internal	4.00	85.00	340.00			
PM57	XQ26AV	00016392	4/26/2019	ECO	00	LABOUR	MECH1	Labour - Internal	2.00	85.00	170.00			
PM57	XQ26AV	00016392	4/26/2019	ECO	00	LABOUR	MECH1	Labour - Internal	2.00	85.00	170.00			
PM57	XQ26AV	00016392	4/26/2019	ECO	40	10W50	YAT	HITECH SYNPLUS 10W50		0.00	5.40	0.00		
PM57	XQ26AV	00016392	4/26/2019	ECO	01	430.110	YAT	OIL PRESSURE SWITCH		1.00	45.00	45.00		
PM57	XQ26AV	00016392	4/26/2019	ECO	16	CON	YAT	Consumables		5.00	15.00	75.00		
PM57	XQ26AV	00016392	4/26/2019	ECO	SERVICE COMPLETED REPLACED OIL PRESSURE SWITCH REMOVED & CLEANED INJECTOR & COPPER WASHER REMOVED & CLEANED MUFFLER & EXHAUST									
PM57	XQ26AV	00016733	5/16/2019	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00016733	5/16/2019	CUMAE5	00	LABOUR	MECH1	Labour - Internal	0.75	85.00	63.75			
PM57	XQ26AV	00016733	5/16/2019	CUMAE5	13	9.1358.01	YAT	Lamp-Insert H3		1.00	71.82	71.82		
PM57	XQ26AV	00016733	5/16/2019	CUMAE5	40	3413005	YAT	OIL 15W-40, CK 4/E9		2.50	3.54	8.85		
PM57	XQ26AV	00016733	5/16/2019	CUMAE5	16	CON	YAT	Consumables		4.00	15.00	60.00		
PM57	XQ26AV	00016733	5/16/2019	CUMAE5	SERVICE COMPLETED REPALCED RHS HEADLIGHT GLOBE TOPPED UP ENGINE OIL CHECK UNI BOLTS									
PM57	XQ26AV	00017079	5/29/2019	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00017079	5/29/2019	CUMAE5	00	LABOUR	MECH1	Labour - Internal		1.00	85.00	85.00		
PM57	XQ26AV	00017079	5/29/2019	CUMAE5	00	LABOUR	APPREN	Labour - Internal		1.00	85.00	85.00		
PM57	XQ26AV	00017079	5/29/2019	CUMAE5	16	CON	YAT	Consumables		3.00	15.00	45.00		

PM57	XQ26AV	00017079	5/29/2019	CUMAE5	SERVICE COMPLETED							
PM57	XQ26AV	00017079	5/29/2019	DEFECT	ADJUSTED CLUTCH							
PM57	XQ26AV	00017079	5/29/2019	DEFECT	01 LABOUR MECH Labour	0.00	0.00	0.00				
					Reported Defect :-							
					Defect Code : 00002127							
					Defect Reference : WO13484							
					Date : 15/12/2018							
					Description of Defect :							
					OIL LEAK AT BACK OF ENGINE UP HIGH							
					COULDN'T FAULT							
PM57	XQ26AV	00017187	6/3/2019	CUMAE5	01 LABOUR Labour	0.00	0.00	0.00				
PM57	XQ26AV	00017187	6/3/2019	CUMBE5	01 LABOUR Labour	0.00	0.00	0.00				
PM57	XQ26AV	00017187	6/3/2019	CUMBE5	00 LABOUR MECH1 Labour - Internal	4.00	85.00	340.00				
PM57	XQ26AV	00017187	6/3/2019	CUMBE5	00 LABOUR MECH1 Labour - Internal	1.00	85.00	85.00				
PM57	XQ26AV	00017187	6/3/2019	CUMBE5	06 MK13584 YAT MAINTENANCE KIT		1.00	91.95	91.95			
PM57	XQ26AV	00017187	6/3/2019	CUMBE5	40 3413005 YAT OIL 15W-40, CK 4/E9		47.00	3.54	166.38			
PM57	XQ26AV	00017187	6/3/2019	CUMBE5	11 2866337 YAT Gasket, Exhaust Flex, K200		3.00	25.72	77.16			
PM57	XQ26AV	00017187	6/3/2019	CUMBE5	16 CON YAT Consumables		4.00	15.00	60.00			
PM57	XQ26AV	00017187	6/3/2019	CUMBE5	SERVICE COMPLETED							
					R&R LEAKING EXHAUST GASKET OFF FLEX & REPLACED GASKET AT MUFFLER							
					REPLACED RUBBER ON RADIATOR SUPPORT BAR ON TOP OF ENGINE							
PM57	XQ26AV	00017184	6/3/2019	GEN	39 LABOUR Labour	0.00	0.00	0.00				
PM57	XQ26AV	00017184	6/3/2019	GEN	00 LABOUR MECH1 Labour - Internal		0.75	85.00	63.75			
PM57	XQ26AV	00017184	6/3/2019	GEN	16 CON YAT Consumables		4.00	15.00	60.00			
PM57	XQ26AV	00017184	6/3/2019	GEN	CAB A/C FAN NOT WORKING - DIAGNOSED CAB A/C TO BE BURNT OUT FAN							
					REPLACED & TESTED NEW FAN							
					REASSEMBLED DASH							
PM57	XQ26AV	00017184	6/3/2019	GEN	13 BGK1T2M YAT Dust Blower Gun in cab			1.00	39.72	39.72		
PM57	XQ26AV	00017235	6/6/2019	GEN	39 LABOUR Labour	0.00	0.00	0.00				
PM57	XQ26AV	00017235	6/6/2019	GEN	03 A11-0851 YAT FAM MOTOR KW AC			1.00	259.52	259.52		
PM57	XQ26AV	00017235	6/6/2019	GEN	PARTS ONLY WO17184							
PM57	XQ26AV	00017294	6/7/2019	TYRES								
PM57	XQ26AV	00017294	6/7/2019	TYRES	15 LABOUR Labour	0.00	0.00	0.00				
PM57	XQ26AV	00017294	6/7/2019	TYRES	STEER TYRE ROTATION - BY TROY							
PM57	XQ26AV	00017817	6/24/2019	CUMAE5	01 LABOUR Labour	0.00	0.00	0.00				
PM57	XQ26AV	00017817	6/24/2019	CUMAE5	00 LABOUR MECH1 Labour - Internal		0.75	85.00	63.75			
PM57	XQ26AV	00017817	6/24/2019	CUMAE5	00 LABOUR MECH Labour - Internal		0.75	85.00	63.75			
PM57	XQ26AV	00017817	6/24/2019	CUMAE5	40 3413005 YAT OIL 15W-40, CK 4/E9			7.00	3.54	24.78		
PM57	XQ26AV	00017817	6/24/2019	CUMAE5	16 CON YAT Consumables			4.00	15.00	60.00		
PM57	XQ26AV	00017817	6/24/2019	CUMAE5	SERVICE COMPLETED							
					OPPED UP ENGINE OIL AS REQUIRED							
PM57	XQ26AV	00017911	6/28/2019	GEN	39 LABOUR Labour	0.00	0.00	0.00				
PM57	XQ26AV	00017911	6/28/2019	GEN	00 LABOUR APPREN Labour - Internal		4.00	85.00	340.00			
PM57	XQ26AV	00017911	6/28/2019	GEN	02 AIRBRAHOS YAT Air Brake Hose			6.00	3.44	20.64		
PM57	XQ26AV	00017911	6/28/2019	GEN	16 CON YAT Consumables			6.00	15.00	90.00		

PM57	XQ26AV	00017911	6/28/2019	GEN	AIR LINES RIPPED OF BETWEEN TRUCK & A TRAILER - DROVE TO BRISBANE PORT TO REPLACE AIR LINES THEN DROVE BACK						
PM57	XQ26AV	00019920	7/5/2019	WEICAL	00	LABOUR	Labour	0.00	0.00	0.00	
PM57	XQ26AV	00019920	7/5/2019	WEICAL	EXODAS YATALA						
					AIR GAUGE - 14.0						
					ADJUSTED - NA						
					WEIGHBRIDGE - 13.695						
PM57	XQ26AV	00018373	7/12/2019	CUMAE5	01	LABOUR	Labour	0.00	0.00	0.00	
PM57	XQ26AV	00018373	7/12/2019	CUMAE5	00	LABOUR	MECH1 Labour - Internal		2.50	85.00	212.50
PM57	XQ26AV	00018373	7/12/2019	CUMAE5	00	LABOUR	APPREN Labour - Internal		2.50	85.00	212.50
PM57	XQ26AV	00018373	7/12/2019	CUMAE5	40	3413005	YAT OIL 15W-40, CK 4/E9			4.00	3.54 14.16
PM57	XQ26AV	00018373	7/12/2019	CUMAE5	16	CON	YAT Consumables			6.00	15.00 90.00
PM57	XQ26AV	00018373	7/12/2019	CUMAE5	SERVICE COMPLETED						
					TOPPED UP ENGINE OIL WITH 4 LT						
					TUNED ENGINE						
PM57	XQ26AV	00018373	7/12/2019	TUNE	00	LABOUR	MECH Labour		0.00	0.00	0.00
PM57	XQ26AV	00018816	7/25/2019	CUMAE5	01	LABOUR	Labour	0.00	0.00	0.00	
PM57	XQ26AV	00018816	7/25/2019	CUMBE5	01	LABOUR	Labour	0.00	0.00	0.00	
PM57	XQ26AV	00018816	7/25/2019	CUMBE5	00	LABOUR	MECH1 Labour - Internal		5.00	85.00	425.00
PM57	XQ26AV	00018816	7/25/2019	CUMBE5	00	LABOUR	APPREN Labour - Internal		3.00	85.00	255.00
PM57	XQ26AV	00018816	7/25/2019	CUMBE5	08	WBK4SCHB	YAT W/Bearing Kit,Steer,K'worth			2.00	283.59 567.18
PM57	XQ26AV	00018816	7/25/2019	CUMBE5	02	KSMA2124715QP	YAT Kit Brake Shoe Steer MFS73			2.00	135.45 270.90
PM57	XQ26AV	00018816	7/25/2019	CUMBE5	06	MK13584	YAT MAINTENANCE KIT			1.00	91.95 91.95
PM57	XQ26AV	00018816	7/25/2019	CUMBE5	40	3413005	YAT OIL 15W-40, CK 4/E9			50.00	3.54 177.00
PM57	XQ26AV	00018816	7/25/2019	CUMBE5	16	CON	YAT Consumables			10.00	15.00 150.00
PM57	XQ26AV	00018816	7/25/2019	CUMBE5	SERVICE COMPLETED						
					FOUND RHS STEER HUB SEAL LEAKING						
					FOUND BEARINGS ABOUT TO FAIL						
					REPLACED ALL BEARINGS, SEALS & BRAKES						
					ADJUSTED CLUTCH						
PM57	XQ26AV	00019050	8/1/2019	GEN	39	LABOUR	Labour	0.00	0.00	0.00	
PM57	XQ26AV	00019050	8/1/2019	GEN	00	LABOUR	MECH1 Labour - Internal		0.75	85.00	63.75
PM57	XQ26AV	00019050	8/1/2019	GEN	08	1613CR	YAT CAP FRONT HUB			1.00	27.48 27.48
PM57	XQ26AV	00019050	8/1/2019	GEN	16	CON	YAT Consumables			3.00	15.00 45.00
PM57	XQ26AV	00019050	8/1/2019	GEN	LHS STEER HUB SEAL LEAKING - DUE TO CENTRE PLUG BLOWN OUT						
					JACKED UP AXLE TO CHECK WHEEL BEARING ADJUSTMENT & BRAKE ADJUSTMENT - ALL OK						
					REMOVED OLD CAP & GASKET & INSTALLED NEW CAP & GASKET						
					FILLED WITH OI & CLEANED						
PM57	XQ26AV	00019416	8/17/2019	CUMAE5	01	LABOUR	Labour	0.00	0.00	0.00	
PM57	XQ26AV	00019416	8/17/2019	CUMAE5	00	LABOUR	MECH1 Labour - Internal		0.50	85.00	42.50
PM57	XQ26AV	00019416	8/17/2019	CUMAE5	00	LABOUR	MECH Labour - Internal		0.50	85.00	42.50
PM57	XQ26AV	00019416	8/17/2019	CUMAE5	00	LABOUR	MECH1 Labour - Internal		0.50	85.00	42.50
PM57	XQ26AV	00019416	8/17/2019	CUMAE5	16	CON	YAT Consumables			4.00	15.00 60.00
PM57	XQ26AV	00019416	8/17/2019	CUMAE5	SERVICE COMPLETED						
PM57	XQ26AV	00019794	8/29/2019	CUMAE5	01	LABOUR	Labour	0.00	0.00	0.00	
PM57	XQ26AV	00019794	8/29/2019	CUMAE5	00	LABOUR	MECH1 Labour - Internal		6.00	85.00	510.00

PM57	XQ26AV	00019794	8/29/2019	CUMAE5	00	LABOUR MECH1	Labour - Internal	3.00	85.00	255.00							
PM57	XQ26AV	00019794	8/29/2019	CUMAE5	00	LABOUR APPREN	Labour - Internal	3.00	85.00	255.00							
PM57	XQ26AV	00019794	8/29/2019	CUMAE5	11	WBK3DCR	YAT Kit-WheelL 592/594/572/580		2.00	159.11	318.22						
PM57	XQ26AV	00019794	8/29/2019	CUMAE5	02	RDPBSK4707QP	YAT BRAKE SHOE KIT		2.00	64.54	129.08						
PM57	XQ26AV	00019794	8/29/2019	CUMAE5	16	CON	YAT Consumables		6.00	15.00	90.00						
PM57	XQ26AV	00019794	8/29/2019	CUMAE5	SERVICE COMPLETED REFITTED EBS PLUG REPLACED FRONT DRIVE BRAKE SHOES, DRUMS & BEARINGS A/C REPAIRS - CORRECT ELECT												
PM57	XQ26AV	00019794	8/29/2019	CUMAE5	02	DB190PDC	YAT Brake Drum, 10x 285		2.00	90.86	181.72						
PM57	XQ26AV	00019794	8/29/2019	CUMAE5	03	F69-1006-211	YAT A/C Compressor K200		1.00	391.90	391.90						
PM57	XQ26AV	00019794	8/29/2019	CUMAE5	03	25188998	YAT CORE EVAPORATOR ASSEMBLY		1.00	955.08	955.08						
PM57	XQ26AV	00019794	8/29/2019	CUMAE5	03	55300918	YAT THERMISTOR KW		1.00	101.12	101.12						
PM57	XQ26AV	00020556	8/29/2019	GEN	39	LABEXT	CORAUT01 EX00010876	Labour External,PM57				EX00010	0.00	105.00	0.00		
PM57	XQ26AV	00020556	8/29/2019	GEN	39	LABEXT	CORAUT01 EX00010876	Labour External,PM57				EX00010	0.00	105.00	0.00		
PM57	XQ26AV	00020556	8/29/2019	GEN	39	CON	CORAUT01 EX00010876	ORINGS,PM57				EX00010	0.00	6.00	0.00		
PM57	XQ26AV	00020556	8/29/2019	GEN	39	PART	CORAUT01 EX00010876	HOSE NO.10,PM57				EX00010	0.00	130.00	0.00		
PM57	XQ26AV	00020556	8/29/2019	GEN	39	PART	CORAUT01 EX00010876	HOSE NO. 08,PM57				EX00010	0.00	95.00	0.00		
PM57	XQ26AV	00020556	8/29/2019	GEN	39	SUND	CORAUT01 EX00010876	SUNDRIES,PM57				EX00010	0.00	18.50	0.00		
PM57	XQ26AV	00020556	8/29/2019	GEN	39	R134A	CORAUT01 EX00010876	R134A, A/C GAS,PM57				EX00010	0.00	160.00	0.00		
PM57	XQ26AV	00020556	8/29/2019	GEN	CORRECT ELECT - CHECK A/C CLUTCH ON COMPRESSOR BROKEN, RECOVER GAS RETURNED TO SITE FIT NEW HOSE, COUPLE FIT RECEIVER DRIER, COUPLE & PRESSURE TEST FOUND HOGH PRESSURE HOSE LEAKING REMOVE & MAKE UP NEW HOSE FIT & TEST VACUUM SYSTEM ADD OIL & DYE REGAS & TEST, FOUND TX VALVE BLOCKED, RECOVER GAS REMOVE EVAPORATOR REPLACE EVAPORATOR & TX VALVE (SUPPLIED BY CUSTOMER) REFIT & TEST VACUUM SYSTEM REGAS & TEST WORKING FINE												
PM57	XQ26AV	00020556	8/29/2019	GEN	39	R134A	CORAUT01 00016558	R134A, A/C GAS,PM57				EX00010	1.00	160.00	160.00		
PM57	XQ26AV	00020556	8/29/2019	GEN	39	SUND	CORAUT01 00016558	SUNDRIES,PM57				EX00010	1.00	18.50	18.50		
PM57	XQ26AV	00020556	8/29/2019	GEN	39	PART	CORAUT01 00016558	HOSE NO. 08,PM57				EX00010	1.00	95.00	95.00		
PM57	XQ26AV	00020556	8/29/2019	GEN	39	PART	CORAUT01 00016558	HOSE NO.10,PM57				EX00010	1.00	130.00	130.00		
PM57	XQ26AV	00020556	8/29/2019	GEN	39	CON	CORAUT01 00016558	ORINGS,PM57				EX00010	3.00	6.00	18.00		
PM57	XQ26AV	00020556	8/29/2019	GEN	39	LABEXT	CORAUT01 00016558	Labour External,PM57				EX00010	4.50	105.00	472.50		
PM57	XQ26AV	00020556	8/29/2019	GEN	39	LABEXT	CORAUT01 00016558	Labour External,PM57				EX00010	0.50	105.00	52.50		
PM57	XQ26AV	00020558	9/26/2019	CUMAE5	01	LABOUR	Labour	0.00	0.00	0.00							
PM57	XQ26AV	00020558	9/26/2019	CUMBE5	01	LABOUR	Labour	0.00	0.00	0.00							
PM57	XQ26AV	00020558	9/26/2019	CUMBE5	00	LABOUR APPREN	Labour - Internal	2.50	85.00	212.50							
PM57	XQ26AV	00020558	9/26/2019	CUMBE5	00	LABOUR MECH1	Labour - Internal	2.50	85.00	212.50							
PM57	XQ26AV	00020558	9/26/2019	CUMBE5	00	LABOUR MECH1	Labour - Internal	0.20	85.00	17.00							
PM57	XQ26AV	00020558	9/26/2019	CUMBE5	06	MK13584	YAT MAINTENANCE KIT		1.00	91.95	91.95						
PM57	XQ26AV	00020558	9/26/2019	CUMBE5	06	AF1969M	YAT Air Filter		1.00	78.73	78.73						

PM57	XQ26AV	00020558	9/26/2019	CUMBE5	40	3413005	YAT	OIL 15W-40, CK 4/E9	49.00	3.54	173.46				
PM57	XQ26AV	00020558	9/26/2019	CUMBE5	08	TRB68250	YAT	BUSH TORQUE ROD	2.00	40.00	80.00				
PM57	XQ26AV	00020558	9/26/2019	CUMBE5	16	CON	YAT	Consumables	4.00	15.00	60.00				
PM57	XQ26AV	00020558	9/26/2019	CUMBE5	SERVICE COMPLETED REPLACED TORQUE ROD BUSHES AS REQUIRED - BEN GREASED,ADJUSTED BRAKES, CHANGED OIL, CHANGED FUEL PIN ON, CHANGED OIL FILTER, AIR/OIL FILTER - BILLY										
PM57	XQ26AV	00022072	9/26/2019	ROTDRI	15	LABOUR	MECH	Labour	0.00	0.00	0.00				
PM57	XQ26AV	00022071	9/26/2019	STEROT	15	LABOUR	MECH	Labour	0.00	0.00	0.00				
PM57	XQ26AV	00020568	9/26/2019	TYRES											
PM57	XQ26AV	00020612	9/26/2019	TYRES	15	77000180	BRIAUS01	EX00010916	CASE STOCK 11-22.5,PM57			EX00010	0.00	20.00	0.00
PM57	XQ26AV	00020568	9/26/2019	TYRES	15	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00020612	9/26/2019	TYRES	15	33000051	BRIAUS01	EX00010916	BALANCE TBR,PM57			EX00010	0.00	30.00	0.00
PM57	XQ26AV	00020568	9/26/2019	TYRES	STEER & DRIVE TYRE ROTATION - DAVE										
PM57	XQ26AV	00020612	9/26/2019	TYRES	15	11002831	YAT	TYRE 11R22.5 146/143L M766	4.00	495.00	1,980.00				
PM57	XQ26AV	00020612	9/26/2019	TYRES	R&R TYRES DRIVE PLUS ROTATION ON DRIVE & STEER										
PM57	XQ26AV	00020612	9/26/2019	TYRES	15	33000051	BRIAUS01	97350494	BALANCE TBR,PM57			EX00010	2.00	30.00	60.00
PM57	XQ26AV	00020612	9/26/2019	TYRES	15	77000180	BRIAUS01	97350494	CASE STOCK 11-22.5,PM57			EX00010	-1.00	20.00	-20.00
PM57	XQ26AV	00021357	10/21/2019	WEICAL	00	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00021357	10/21/2019	WEICAL	AIR GAUGE READING: 16.000 ADJUSTED: 16.750 WEIGH BRIDGE: 16.300										
					Adjustment completed correctly.										
PM57	XQ26AV	00021250	10/23/2019	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00021250	10/23/2019	CUMAE5	00	LABOUR	MECH1	Labour - Internal	1.50	85.00	127.50				
PM57	XQ26AV	00021250	10/23/2019	CUMAE5	00	LABOUR	APPREN	Labour - Internal	1.50	85.00	127.50				
PM57	XQ26AV	00021250	10/23/2019	CUMAE5	13	9.1358.01	YAT	Lamp-Insert H3		1.00	71.82	71.82			
PM57	XQ26AV	00021250	10/23/2019	CUMAE5	03	275707	YAT	Valve Governor		1.00	76.32	76.32			
PM57	XQ26AV	00021250	10/23/2019	CUMAE5	40	3413005	YAT	OIL 15W-40, CK 4/E9	5.00	3.54	17.70				
PM57	XQ26AV	00021250	10/23/2019	CUMAE5	16	CON	YAT	Consumables	7.00	15.00	105.00				
PM57	XQ26AV	00021250	10/23/2019	CUMAE5	SERVICE COMPLETED REPALCED RHS HIGH BEAM GLOBE TIGHENED WALK PLATE BOLTS REPLACED GOVERNOR VALVE TOPPED UP ENGINE OIL										
PM57	XQ26AV	00021251	10/23/2019	CUMCE5	01	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00021251	10/23/2019	CUMCE5	00	LABOUR	MECH1	Labour - Internal		5.00	85.00	425.00			
PM57	XQ26AV	00021251	10/23/2019	CUMCE5	00	LABOUR	APPREN	Labour - Internal		4.00	85.00	340.00			
PM57	XQ26AV	00021251	10/23/2019	CUMCE5	06	LF637	YAT	Power Steer Filter LF637		1.00	26.11	26.11			
PM57	XQ26AV	00021251	10/23/2019	CUMCE5	40	3334800	YAT	Diff/Gear Oil 80W90 Castrol		33.00	6.96	229.68			
PM57	XQ26AV	00021251	10/23/2019	CUMCE5	40	3372765	YAT	Syntrans Gear Oil 75w/90		12.00	13.61	163.32			
PM57	XQ26AV	00021251	10/23/2019	CUMCE5	06	AC4001	YAT	AIR DRYER CARTRIDGE		1.00	69.95	69.95			
PM57	XQ26AV	00021251	10/23/2019	CUMCE5	06	A3380W1687	YAT	Filter Diff		1.00	19.71	19.71			
PM57	XQ26AV	00021251	10/23/2019	CUMCE5	06	17237	YAT	Filter Element Gearbox Eaton		1.00	29.82	29.82			
PM57	XQ26AV	00021251	10/23/2019	CUMCE5	06	ALLCOOL-WF	YAT	Cooling System Filter		1.00	30.63	30.63			

PM57	XQ26AV	00021251	10/23/2019	CUMCE5	03	5X1327	YAT	O RING		2.00	11.38	22.76				
PM57	XQ26AV	00021251	10/23/2019	CUMCE5	03	0337026240	YAT	WASHER - THRUST ECO PLUS		1.00	6.27	6.27				
PM57	XQ26AV	00021251	10/23/2019	CUMCE5	03	5.281X	YAT	1810 Uni Joint Spicer FR		2.00	80.57	161.14				
PM57	XQ26AV	00021251	10/23/2019	CUMCE5	16	CON	YAT	Consumables		10.00	15.00	150.00				
PM57	XQ26AV	00021251	10/23/2019	CUMCE5	SERVICE COMPLETED REPLACED THRUST WASHER & O-RINGS IN POWER DIVIDER REPLACED BOTH DRIVE SHAFT UNIS FITTED SPRING TO CLUTCH LINK TIGHTENED ALL WALK PLATE CLAMPS											
PM57	XQ26AV	00021252	10/23/2019	EXOINS	01	LABOUR	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00021252	10/23/2019	EXOINS	00	LABOUR	MECH1	Labour - Internal		0.50	85.00	42.50				
PM57	XQ26AV	00021252	10/23/2019	EXOINS	PASSED 1ST INSPECTION											
PM57	XQ26AV	00021659	10/29/2019	WEICAL	00	LABOUR	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00021662	10/29/2019	WEICAL	00	LABOUR	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00021659	10/29/2019	WEICAL	AIR GAUGE - 15.25 ADJUSTED - 15.00 WEIGHBRIDGE - 14.70 AIR GAUGE - 13.58 ADJUSTED - NA WEIGHBRIDGE - 13.30											
PM57	XQ26AV	00021662	10/29/2019	WEICAL												
PM57	XQ26AV	00022223	11/12/2019	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00022223	11/12/2019	CUMAE5	00	LABOUR	MECH1	Labour - Internal		1.00	85.00	85.00				
PM57	XQ26AV	00022223	11/12/2019	CUMAE5	00	LABOUR	APPREN	1.00 85.00 85.00								
PM57	XQ26AV	00022223	11/12/2019	CUMAE5	16	CON	YAT	4.00 15.00 60.00								
PM57	XQ26AV	00022223	11/12/2019	CUMAE5	14	235A12	YAT	LED AUTOLAMPS 235 SERIES		1.00	38.04	38.04				
PM57	XQ26AV	00022223	11/12/2019	CUMAE5	SERVICE COMPLETED. TIGHTENED BELLY BAR FITTED NEW D/G SIGNS TO BULLBAR FITTED NEW INDICTOR TO RHS BULLBAR											
PM57	XQ26AV	00022223	11/12/2019	CUMAE5	13	MSDGFLIP	YAT	Flip Sign Book Metal,DG signs		1.00	72.10	72.10				
PM57	XQ26AV	00022287	11/12/2019	gen	39	LABOUR	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00022287	11/12/2019	gen	00	LABOUR	MECH1	Labour - Internal		3.50	85.00	297.50				
PM57	XQ26AV	00022287	11/12/2019	gen	06	AF1969M	YAT	Air Filter		1.00	78.73	78.73				
PM57	XQ26AV	00022287	11/12/2019	gen	16	CON	YAT	Consumables		6.00	15.00	90.00				
PM57	XQ26AV	00022287	11/12/2019	gen	SERVICE COMPLETED. CHECKED GEAR STICK AND LINKAGES. FOUND THAT GEAR CABLES WERE STUFFED - REMOVED AND REPLACED BOTH GEAR SHIFT CABLES. CHECKED OPERATION - WORKING ALL GOOD. REPLACED AIR FITLER.											
PM57	XQ26AV	00022287	11/12/2019	gen	07	183-105-130	YAT	GEAR SHIFT CABLE		1.00	372.60	372.60				
PM57	XQ26AV	00022287	11/12/2019	gen	07	E92-1044-149	YAT	Cable Transmission		1.00	481.98	481.98				
PM57	XQ26AV	00022289	11/12/2019	STEROT	15	LABOUR	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00022289	11/12/2019	STEROT	STEER TYRE ROTATION COMPLETED.											
PM57	XQ26AV	00022368	11/12/2019	TYRSTE	15	77000194	BRIAUS01	EX00011622	case stock 295/80-22.5,PM57				EX00011	0.00	20.00	0.00
PM57	XQ26AV	00022368	11/12/2019	TYRSTE	15	33000051	BRIAUS01	EX00011622	BALANCE TBR,PM57				EX00011	0.00	30.00	0.00

PM57	XQ26AV	00022368	11/12/2019	TYRSTE	15	11001553	YAT	TYRE 295/80R22.5 152/148M BS R150	2.00	0.00	0.00					
PM57	XQ26AV	00022368	11/12/2019	TYRSTE	15	33000084	YAT	FIT TBR TYRE	2.00	0.00	0.00					
PM57	XQ26AV	00022368	11/12/2019	TYRSTE	R&R TYRES 1,2											
PM57	XQ26AV	00022368	11/12/2019	TYRSTE	15	77000194	BRIAUS01	97591026	case stock 295/80-22.5,PM57			EX00011	-2.00	20.00	-40.00	
PM57	XQ26AV	00022368	11/12/2019	TYRSTE	15	33000051	BRIAUS01	97591026	BALANCE TBR,PM57			EX00011	2.00	30.00	60.00	
PM57	XQ26AV	00022483	11/15/2019	GEN	39	D61-1004-002B	BROHUR01	EX00011696	STARTER MOTOR, DP60, PACCAR,PM57			EX00011	0.00	467.91	0.00	
PM57	XQ26AV	00022647	11/15/2019	GEN	39	CSP10484PX	BROHUR01	EX00011763	Reco Starter Motor, K/worth, Dual Post,PM57			EX00011	0.00	722.98	0.00	
PM57	XQ26AV	00022360	11/15/2019	GEN	39	LABOUR Labour			0.00	0.00	0.00					
PM57	XQ26AV	00022483	11/15/2019	GEN	39	D61-1004-002B	BROHUR01	1757364	STARTER MOTOR, DP60, PACCAR,PM57			EX00011	1.00	467.91	467.91	
PM57	XQ26AV	00022647	11/15/2019	GEN	39	CSP10484PX	BROHUR01	1757191	Reco Starter Motor, K/worth, Dual Post,PM57			EX00011	1.00	722.98	722.98	
PM57	XQ26AV	00022360	11/15/2019	GEN	00	LABOUR MECH1	Labour - Internal		5.00	85.00	425.00					
PM57	XQ26AV	00022360	11/15/2019	GEN	00	LABOUR APPREN	Labour - Internal		4.00	85.00	340.00					
PM57	XQ26AV	00022360	11/15/2019	GEN	16	CON	YAT	Consumables		10.00	15.00	150.00				
PM57	XQ26AV	00022360	11/15/2019	GEN	SERVICE COMPLETED.											
R+R STARTER MOTOR																
R+R RUBBER MOUNTS ON INTAKE PIPE.																
PM57	XQ26AV	00022360	11/15/2019	GEN	03	D61-1004-002B	YAT	STARTER MOTOR, DP60, PACCAR		1.00	467.91	467.91				
PM57	XQ26AV	00022427	11/19/2019	CUMAE5	01	LABOUR Labour			0.00	0.00	0.00					
PM57	XQ26AV	00022427	11/19/2019	CUMBE5	01	LABOUR Labour			0.00	0.00	0.00					
PM57	XQ26AV	00022427	11/19/2019	CUMBE5	00	LABOUR MECH1	Labour - Internal		2.00	85.00	170.00					
PM57	XQ26AV	00022427	11/19/2019	CUMBE5	16	CON	YAT	Consumables		8.00	15.00	120.00				
PM57	XQ26AV	00022427	11/19/2019	CUMBE5	40	3413005	YAT	OIL 15W-40, CK 4/E9		48.00	3.54	169.92				
PM57	XQ26AV	00022427	11/19/2019	CUMBE5	06	MK13584	YAT	MAINTENANCE KIT		1.00	91.95	91.95				
PM57	XQ26AV	00022427	11/19/2019	CUMBE5	CARRIED OUT "A" SERVICE.											
BLEW OUT RADIATOR.																
PM57	XQ26AV	00022567	11/22/2019	EXOINS	01	LABOUR Labour			0.00	0.00	0.00					
PM57	XQ26AV	00022567	11/22/2019	EXOINS	00	LABOUR MECH1	Labour - Internal		2.00	85.00	170.00					
PM57	XQ26AV	00022567	11/22/2019	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION - 1st ATTEMPT.											
PM57	XQ26AV	00022754	11/29/2019	CUMAE5	01	LABOUR Labour			0.00	0.00	0.00					
PM57	XQ26AV	00022754	11/29/2019	CUMAE5	00	LABOUR MECH1	Labour - Internal		1.00	85.00	85.00					
PM57	XQ26AV	00022754	11/29/2019	CUMAE5	00	LABOUR MECH1	0.75	85.00	63.75							
PM57	XQ26AV	00022754	11/29/2019	CUMAE5	16	CON	YAT	Consumables		4.00	15.00	60.00				
PM57	XQ26AV	00022754	11/29/2019	CUMAE5	14	1089	YAT	Load Light, Hella		2.00	25.46	50.92				
PM57	XQ26AV	00022754	11/29/2019	CUMAE5	40	3413005	YAT	OIL 15W-40, CK 4/E9		4.00	3.54	14.16				
PM57	XQ26AV	00022754	11/29/2019	CUMAE5	SERVICE COMPLETED.											
CARRIED OUT "A" SERVICE.																
FITTED LOAD LIGHTS x2.																
PM57	XQ26AV	00023222	12/20/2019	CUMAE5	01	LABOUR Labour			0.00	0.00	0.00					

PM57	XQ26AV	00023617	1/7/2020	GEN	13 K174-932 BROHUR01	EX00012232	PM57,PAD FUEL TANK KW	EX00012	0.00	23.33	0.00
PM57	XQ26AV	00023616	1/7/2020	GEN	SUPPLIED BY BROWN & HURLEY 07.01.2020						
					INVOICE # 1803169						
PM57	XQ26AV	00023617	1/7/2020	GEN	SUPPLIED BY BROWN & HURLEY 07.01.2020						
					INVOICE # 1803126						
PM57	XQ26AV	00023616	1/7/2020	GEN	13 K161-4515-515 BROHUR01	1803169	PM57,LINING FUEL TANK SUPPORT	EX00012	2.00	23.33	46.66
PM57	XQ26AV	00023617	1/7/2020	GEN	13 K174-932 BROHUR01	1803126	PM57,PAD FUEL TANK KW	EX00012	2.00	23.33	46.66
PM57	XQ26AV	00023661	1/8/2020	GEN	13 F35008SD BROHUR01	EX00012275	PM57,HT/S SUPER DUTY OEM KIT	EX00012	0.00	631.69	0.00
PM57	XQ26AV	00023661	1/8/2020	GEN	SUPPLIED BY BROWN & HURLEY 08.01.2020						
					INVOICE # 1803692						
PM57	XQ26AV	00023661	1/8/2020	GEN	13 F35008SD BROHUR01	1803692	PM57,HT/S SUPER DUTY OEM KIT	EX00012	1.00	631.69	631.69
PM57	XQ26AV	00023824	1/14/2020	ROTDRI	15 LABOUR Labour		0.00 0.00 0.00				
PM57	XQ26AV	00023824	1/14/2020	ROTDRI	DRIVE TYRE ROTATION COMPLETED.						
					COMPLETED BY BRIDGESTONE - DAVE 14.01.2020						
PM57	XQ26AV	00023823	1/14/2020	STEROT	15 LABOUR Labour		0.00 0.00 0.00				
PM57	XQ26AV	00023823	1/14/2020	STEROT	STEER TYRE ROTATION COMPLETED.						
					COMPLETED BY BRIDGESTONE - DAVE 14.01.2020						
PM57	XQ26AV	00023860	1/15/2020	GEN	15 33000085 BROHUR01	EX00012436	PM57,ROTATE TBR TYRE	EX00012	0.00	0.00	0.00
PM57	XQ26AV	00023925	1/15/2020	GEN	13 K174-932 BROHUR01	EX00012462	PM57,PAD FUEL TANK KW	EX00012	0.00	23.33	0.00
PM57	XQ26AV	00023860	1/15/2020	GEN	15 33000085 BROHUR01	EX00012436	PM57,ROTATE TBR TYRE	EX00012	0.00	0.00	0.00
PM57	XQ26AV	00023925	1/15/2020	GEN	SUPPLIED BY BROWN & HURLEY 15.01.2020						
					TAX ADJUSTMENT NOTE # 1809278						
					ORIGINAL INVOICE # 1803126						
PM57	XQ26AV	00023860	1/15/2020	GEN	15 33000051 BROHUR01	EX00012436	PM57,BALANCE TBR	EX00012	0.00	30.00	0.00
PM57	XQ26AV	00023925	1/15/2020	GEN	13 K174-932 BROHUR01	1809278	PM57,PAD FUEL TANK KW	EX00012	-2.00	23.33	-46.66
PM57	XQ26AV	00023860	1/15/2020	GEN	COMPLETED BY BRIDGESTONE 15.01.2020						
					INVOICE # 97912845						
PM57	XQ26AV	00023860	1/15/2020	GEN	15 33000085 BRIAUS01	97912845	PM57,ROTATE TBR TYRE	EX00012	0.00	0.00	0.00
PM57	XQ26AV	00023860	1/15/2020	GEN	15 33000085 BRIAUS01	97912845	PM57,ROTATE TBR TYRE	EX00012	0.00	0.00	0.00
PM57	XQ26AV	00023860	1/15/2020	GEN	15 33000051 BRIAUS01	97912845	PM57,BALANCE TBR	EX00012	2.00	30.00	60.00
PM57	XQ26AV	00023860	1/15/2020	GEN	15 33000051 BROHUR01	97912845	PM57,BALANCE TBR	EX00012	2.00	30.00	60.00
PM57	XQ26AV	00023860	1/15/2020	GEN	15 33000085 BROHUR01	97912845	PM57,ROTATE TBR TYRE	EX00012	2.00	0.00	0.00
PM57	XQ26AV	00023860	1/15/2020	GEN	15 33000085 BROHUR01	97912845	PM57,ROTATE TBR TYRE	EX00012	8.00	0.00	0.00
PM57	XQ26AV	00024074	1/15/2020	WEICAL	00 LABOUR Labour		0.00 0.00 0.00				
PM57	XQ26AV	00024074	1/15/2020	WEICAL	AIR GAUGE: 16.75						
					ADJUSTED: 0						
					WEIGHBRIDGE: 16.5						
					AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
PM57	XQ26AV	00024150	1/24/2020	CUMAE5	01 LABOUR Labour		0.00 0.00 0.00				
PM57	XQ26AV	00024150	1/24/2020	CUMAE5	SERVICE COMPLETED.						
PM57	XQ26AV	00024150	1/24/2020	CUMBE5	01 LABOUR Labour		0.00 0.00 0.00				

PM57	XQ26AV	00024150	1/24/2020	CUMBE5	SERVICE COMPLETED BY BILLY 24.01.2020											
					1KG FIRE EXTINGUISHER CHANGED OUT AS REQUIRED											
					FIND AND REPLACED 3/8 AIR HOSE FROM UNDER CAB ON RHT SIDE UP INTO DASH AS REQUIRED.											
					RUBBED THROUGH YELLOW HOSE AND PUT NEW JAW KIT IN TURNTABLE AS REQUIRED.											
PM57	XQ26AV	00024150	1/24/2020	CUMBE5	00	LABOUR	MECH1	Labour - Internal		3.50	85.00	297.50				
PM57	XQ26AV	00024150	1/24/2020	CUMBE5	40	3413005	YAT	OIL 15W-40, CK 4/E9			48.00	3.54	169.92			
PM57	XQ26AV	00024150	1/24/2020	CUMBE5	06	LF14000NN	YAT	Oil Filter (was LF9080)			1.00	39.00	39.00			
PM57	XQ26AV	00024150	1/24/2020	CUMBE5	06	FF5776	YAT	FF5776 Fuel Filter			1.00	42.00	42.00			
PM57	XQ26AV	00024150	1/24/2020	CUMBE5	06	FS36401	YAT	Fuel Filter			1.00	18.91	18.91			
PM57	XQ26AV	00024150	1/24/2020	CUMBE5	06	AS2474	YAT	Ad Blue filter Kenworth			1.00	11.61	11.61			
PM57	XQ26AV	00024150	1/24/2020	CUMBE5	13	SK3221/50Z	YAT	Turn Table Repair Kit			1.00	229.64	229.64			
PM57	XQ26AV	00024150	1/24/2020	CUMBE5	16	CON	YAT	Consumables			5.00	15.00	75.00			
PM57	XQ26AV	00024150	1/24/2020	DEFECT	01	LABOUR	MECH	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00024150	1/24/2020	DEFECT	Reported Defect :-											
					Defect Code : 00003600											
					Defect Reference : SDP39300											
					Date : 11/01/2020											
					Description of Defect :											
					ICE PACK LEAKING DIESEL											
					DEFECT CLEARED BY BILLY 24.01.2020											
					WAS ALREADY COMPLETED ON 16.01.2020											
PM57	XQ26AV	00024276	2/4/2020	GEN	39	LABOUR	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00024276	2/4/2020	GEN	REPAIR COMPLETED BILLY / KEIRAN 04.02.2020											
					SUCKED OUT WATER FROM FUEL TANK, DRAINED FUEL BOWL AS REQUIRED											
PM57	XQ26AV	00024276	2/4/2020	GEN	00	LABOUR	MECH1	Labour - Internal		0.75	85.00	63.75				
PM57	XQ26AV	00024276	2/4/2020	GEN	00	LABOUR	APPREN	Labour - Internal		0.75	85.00	63.75				
PM57	XQ26AV	00024276	2/4/2020	GEN	16	CON	YAT	Consumables			2.00	15.00	30.00			
PM57	XQ26AV	00024760	2/5/2020	GEN	13	LABEXT	NABQAN01	EX00012980	PM57,				EX00012	0.00	720.00	0.00
PM57	XQ26AV	00024760	2/5/2020	GEN	13	LABEXT	NABQAN01	EX00012980	PM57,SUBLET: AUTO ELECTRICIAN				EX00012	0.00	891.00	0.00
PM57	XQ26AV	00024760	2/5/2020	GEN	13	TRAVEL FEE	NABQAN01	EX00012980	PM57,				EX00012	0.00	1.15	0.00
PM57	XQ26AV	00024760	2/5/2020	GEN	16	CON	NABQAN01	EX00012980	PM57,				EX00012	0.00	35.36	0.00
PM57	XQ26AV	00024760	2/5/2020	GEN	COMPLETED BY A & D MOTORS 05.02.2020											
					INVOICE # 00034682											
PM57	XQ26AV	00024760	2/5/2020	GEN	16	CON	NABQAN01	00034682	PM57,				EX00012	1.00	35.36	35.36
PM57	XQ26AV	00024760	2/5/2020	GEN	13	TRAVEL FEE	NABQAN01	00034682	PM57,				EX00012	60.00	1.15	69.00
PM57	XQ26AV	00024760	2/5/2020	GEN	13	LABEXT	NABQAN01	00034682	PM57,SUBLET: AUTO ELECTRICIAN				EX00012	1.00	891.00	891.00
PM57	XQ26AV	00024760	2/5/2020	GEN	13	LABEXT	NABQAN01	00034682	PM57,				EX00012	1.00	720.00	720.00
PM57	XQ26AV	00024362	2/8/2020	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00024362	2/8/2020	CUMAE5	SERVICE COMPLETED BY BILLY 08.02.2020											
					RHT BRAKE DRIVE TYRE PUMPED ON ONLY HAD 60PSI IN IT.											
					TYRE FITTER WASN'T HERE, PARKED IN BAY FOR MONDAY.											
PM57	XQ26AV	00024362	2/8/2020	CUMAE5	00	LABOUR	MECH1	Labour - Internal		0.75	85.00	63.75				
PM57	XQ26AV	00024362	2/8/2020	CUMAE5	40	3413005	YAT	OIL 15W-40, CK 4/E9			1.50	3.54	5.31			

PM57	XQ26AV	00024362	2/8/2020	CUMAE5	16	CON	YAT	Consumables			4.00	15.00	60.00			
PM57	XQ26AV	00024694	2/24/2020	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00024694	2/24/2020	CUMAE5	SERVICE COMPLETED BY SEAN / BEN 24.02.2020											
PM57	XQ26AV	00024694	2/24/2020	CUMAE5	00	LABOUR	MECH1	Labour - Internal		0.75	85.00	63.75				
PM57	XQ26AV	00024694	2/24/2020	CUMAE5	00	LABOUR	APPREN	Labour - Internal		0.50	85.00	42.50				
PM57	XQ26AV	00024694	2/24/2020	CUMAE5	16	CON	YAT	Consumables			4.00	15.00	60.00			
PM57	XQ26AV	00024811	2/26/2020	GEN	39	LABOUR	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00024811	2/26/2020	GEN	REPAIR COMPLETED BY MICK 26.02.2020											
					REPLACED LHS WINDOW MODUAL											
					REPLACED LHS WINDOW REGULATOR											
					REPLACED A/C DEMISTER FAN											
PM57	XQ26AV	00024811	2/26/2020	GEN	00	LABOUR	MECH	Labour - Internal		3.00	85.00	255.00				
PM57	XQ26AV	00024811	2/26/2020	GEN	13	A11-0851	YAT	FAM MOTOR KW AC			1.00	259.52	259.52			
PM57	XQ26AV	00024811	2/26/2020	GEN	14	Q21-1051-002	YAT	MIRROR CONTROL SWITCH K200			1.00	155.35	155.35			
PM57	XQ26AV	00024811	2/26/2020	GEN	14	R21-1016	YAT	WINDOW CONTROL REGULATOR			1.00	574.67	574.67			
PM57	XQ26AV	00024811	2/26/2020	GEN	16	CON	YAT	Consumables			3.00	15.00	45.00			
PM57	XQ26AV	00024844	2/27/2020	GEN	13	R21-1016	BROHUR01	EX00013051	PM57,WINDOW CONTROL REGULATOR				EX00013	0.00	583.86	0.00
PM57	XQ26AV	00024844	2/27/2020	GEN	13	Q21-1051-002	BROHUR01	EX00013051	PM57,MIRROR CONTROL SWITCH K200				EX00013	0.00	174.77	0.00
PM57	XQ26AV	00024844	2/27/2020	GEN	SUPPLIED BY BROWN & HURLEY 27.02.2020											
PM57	XQ26AV	00024844	2/27/2020	GEN	INVOICE # 1844715											
PM57	XQ26AV	00024844	2/27/2020	GEN	13	Q21-1051-002	BROHUR01	1844715	PM57,MIRROR CONTROL SWITCH K200				EX00013	1.00	174.77	174.77
PM57	XQ26AV	00024844	2/27/2020	GEN	13	R21-1016	BROHUR01	1844715	PM57,WINDOW CONTROL REGULATOR				EX00013	2.00	583.86	1,167.72
PM57	XQ26AV	00024895	3/3/2020	DEFECT	01	LABOUR	MECH	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00024895	3/3/2020	DEFECT	DEFECT CLEARED BY MICK BURTON 03/03/2020.											
					Defect: 5828											
					Reported by: Mitch											
					"Ice pack service is due, stopped working"											
PM57	XQ26AV	00024895	3/3/2020	GEN	39	LABOUR	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00024895	3/3/2020	GEN	REPAIR COMPLETED.											
PM57	XQ26AV	00024895	3/3/2020	GEN	SERVICED SLEEPER AIR.											
PM57	XQ26AV	00024895	3/3/2020	GEN	00	LABOUR	MECH	Labour - Internal		1.00	85.00	85.00				
PM57	XQ26AV	00024895	3/3/2020	GEN	16	CON	YAT	Consumables			2.00	10.00	20.00			
PM57	XQ26AV	00024895	3/3/2020	GEN	40	10W50	YAT	HITECH SYNPLUS 10W50			1.00	9.25	9.25			
PM57	XQ26AV	00024895	3/3/2020	GEN	06	ED002175254-S	YAT	Air Filter Sleeper Air			1.00	53.50	53.50			
PM57	XQ26AV	00025142	3/11/2020	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00025142	3/11/2020	CUMAE5	SERVICE COMPLETED BY BILLY / KEIRAN / SEAN 11.03.2020											
					ADJUSTED BRAKES AND CHECKED UNDERNEATH											
					REPLACED UHF AERIAL											
					REPLACED DRIVERS SEAT											
PM57	XQ26AV	00025142	3/11/2020	CUMAE5	00	LABOUR	MECH1	Labour - Internal		0.50	85.00	42.50				

PM57	XQ26AV	00025142	3/11/2020	CUMAE5	00	LABOUR APPREN	Labour - Internal	0.50	85.00	42.50			
PM57	XQ26AV	00025142	3/11/2020	CUMAE5	00	LABOUR MECH1	Labour - Internal	3.00	85.00	255.00			
PM57	XQ26AV	00025142	3/11/2020	CUMAE5	16	CON	YAT Consumables		6.00	15.00	90.00		
PM57	XQ26AV	00025142	3/11/2020	CUMAE5	13	6860-875	YAT SEAT KW		1.00	3,100.00	3,100.00		
PM57	XQ26AV	00025142	3/11/2020	DEFECT	01	LABOUR MECH	Labour	0.00	0.00	0.00			
PM57	XQ26AV	00025142	3/11/2020	DEFECT	DEFECT # 5829 DRIVER SIDE ARIAL BASE BROKEN A SERVICE DUE DRIVER SEAT CUSHION IS STUFFED								
PM57	XQ26AV	00025142	3/11/2020	DEFECT	DEFECT CLEARED BY SEAN 11.03.2020 Reported Defect :- Defect Code : 00003847 Defect Reference : 5827 Date : 13/02/2020 Description of Defect : DRIVER SEAT CUSHION IS BROKEN - IN THE CENTRE NO CUSHION								
PM57	XQ26AV	00025128	3/11/2020	GEN	DEFECT CLEARED BY BILLY 11.03.2020 - SEAT REPAIRED BY SEAN								
PM57	XQ26AV	00025128	3/11/2020	GEN	15	33000096	BRIAUS01 EX00013185	PM57,PUNCTURE REPAIR TBR		EX00013	0.00	25.00	0.00
PM57	XQ26AV	00025128	3/11/2020	GEN	COMPLETED BY BRIDGESTONE 11.03.2020 INVOICE # 98222262								
PM57	XQ26AV	00025128	3/11/2020	GEN	15	33000096	BRIAUS01 98222262	PM57,PUNCTURE REPAIR TBR		EX00013	1.00	25.00	25.00
PM57	XQ26AV	00025358	3/18/2020	DEFECT	01	LABOUR MECH	Labour	0.00	0.00	0.00			
PM57	XQ26AV	00025358	3/18/2020	DEFECT	DEFECT # 5831 ELECTRIC MIRRORS DO NOT WORK / ADJUST MIRROR HEAT BUTTON NOT WORKING. NO LIGHT OR HEAT COMING OUT.								
PM57	XQ26AV	00025358	3/18/2020	DEFECT	DEFECT CLEARED BY MICK 18.03.2020 DEFECT # 5835 NO HOT AIR OR HEAT COMING OUT FROM AIRCON VENTS WHEN TURNED TO HOT, ONLY COLD AIR COMES OUT IN ALL TEMPERATURE SETTINGS.								
PM57	XQ26AV	00025358	3/18/2020	GEN	DEFECT CLEARED BY MICK 18.03.2020								
PM57	XQ26AV	00025358	3/18/2020	GEN	39	LABOUR	Labour	0.00	0.00	0.00			
PM57	XQ26AV	00025358	3/18/2020	GEN	REPAIR COMPLETED BY MICK / KEIRAN 18.03.2020								
PM57	XQ26AV	00025358	3/18/2020	GEN	REPLACED HEATER TAP UNDER TRUCK AND TURNED TAP ON BACK OF MOTOR ON REPLACED MIRROR SWITCH ON DRIVERS DOOR								
PM57	XQ26AV	00025358	3/18/2020	GEN	00	LABOUR MECH	Labour - Internal	0.50	85.00	42.50			
PM57	XQ26AV	00025358	3/18/2020	GEN	00	LABOUR APPREN	Labour - Internal	2.00	85.00	170.00			
PM57	XQ26AV	00025358	3/18/2020	GEN	14	Q21-1051-002	YAT MIRROR CONTROL SWITCH K200		1.00	174.77	174.77		
PM57	XQ26AV	00025358	3/18/2020	GEN	16	CON	YAT Consumables		4.00	15.00	60.00		
PM57	XQ26AV	00025479	3/19/2020	DEFECT	01	LABOUR MECH	Labour	0.00	0.00	0.00			

PM57	XQ26AV	00025479	3/19/2020	DEFECT	DEFECT # 5836 PLEASE INSPECT BATTERIES OR STARTER MOTOR AS ITS VERY VERY LAZY TO CRANK OVER. LAZY ENOUGH TO GET WORRIED IT WONT START									
					DEFECT CLEARED BY BILLY 19.03.2020 (LOAD TESTED BATTERIES - ALL TESTED GREEN, CLEANED TERMINALS, CHECKED TERMINALS ON STARTER - SEEM FINE)									
PM57	XQ26AV	00025479	3/19/2020	GEN	39	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00025479	3/19/2020	GEN	REPAIR COMPLETED BY BILLY 19.03.2020									
					REMOVED TERMINALS OFF BATTERIES AND LOAD TESTED EACH BATTERY AS REQUIRED ALL BATTERIES TESTED IN THE GREEN, CLEANED BATTERY TERMINALS AND TOP OF BATTERY POST AS REQUIRED CHECKED TERMINALS ON STARTER MOTOR FOR ANY LOOSE TERMINALS - ALL SEEMED TIGHT, STARTER MOTOR DOESN'T LOOK THAT OLD									
PM57	XQ26AV	00025479	3/19/2020	GEN	00	LABOUR	MECH1	Labour - Internal		1.00	85.00	85.00		
PM57	XQ26AV	00025479	3/19/2020	GEN	16	CON	YAT	Consumables			1.00	15.00	15.00	
PM57	XQ26AV	00025518	3/23/2020	GEN	15	33000518	BRIAUS01	EX00013308	REMOVAL: CUSTOMER REQUEST,PM57		EX00013	0.00	0.00	0.00
PM57	XQ26AV	00025518	3/23/2020	GEN	15	33000370	BRIAUS01	EX00013308	TYRE HELD FOR RUNOUT,PM57		EX00013	0.00	0.00	0.00
PM57	XQ26AV	00025518	3/23/2020	GEN	15	11001553	BRIAUS01	EX00013308	TYRE 295/80R22.5 152/148M BS R150,PM57		EX00013	0.00	0.00	0.00
PM57	XQ26AV	00025518	3/23/2020	GEN	15	33000084	BRIAUS01	EX00013308	FIT TBR TYRE,PM57		EX00013	0.00	0.00	0.00
PM57	XQ26AV	00025518	3/23/2020	GEN	15	33000051	BRIAUS01	EX00013308	BALANCE TBR,PM57		EX00013	0.00	30.00	0.00
PM57	XQ26AV	00025518	3/23/2020	GEN	COMPLETED BY BRIDGESTONE 23.03.2020									
PM57	XQ26AV	00025518	3/23/2020	GEN	INVOICE # 98283805									
PM57	XQ26AV	00025518	3/23/2020	GEN	15	33000051	BRIAUS01	98283805	BALANCE TBR,PM57		EX00013	2.00	30.00	60.00
PM57	XQ26AV	00025518	3/23/2020	GEN	15	33000084	BRIAUS01	98283805	FIT TBR TYRE,PM57		EX00013	2.00	0.00	0.00
PM57	XQ26AV	00025518	3/23/2020	GEN	15	11001553	BRIAUS01	98283805	TYRE 295/80R22.5 152/148M BS R150,PM57		EX00013	1.00	0.00	0.00
PM57	XQ26AV	00025518	3/23/2020	GEN	15	33000370	BRIAUS01	98283805	TYRE HELD FOR RUNOUT,PM57		EX00013	2.00	0.00	0.00
PM57	XQ26AV	00025518	3/23/2020	GEN	15	33000518	BRIAUS01	98283805	REMOVAL: CUSTOMER REQUEST,PM57		EX00013	2.00	0.00	0.00
PM57	XQ26AV	00025499	3/23/2020	STEROT	15	LABOUR	Labour		0.00	0.00	0.00			
PM57	XQ26AV	00025499	3/23/2020	STEROT	STEER TYRE ROTATION COMPLETED.									
					COMPLETED BY BRIDGESTONE - DAVE 23.03.2020									
PM57	XQ26AV	00025513	3/24/2020	GEN	13	P27-1187-002	BROHUR01	EX00013302	SWITCH- MIRROR MODULES,PM57		EX00013	0.00	125.21	0.00
PM57	XQ26AV	00025513	3/24/2020	GEN	13	47501	BROHUR01	EX00013302	GLOBE WEDGE 12V5W,PM57		EX00013	0.00	4.22	0.00
PM57	XQ26AV	00025513	3/24/2020	GEN	13	K092-335	BROHUR01	EX00013302	PANEL LIGHT CONTROL (dimmer switch),PM57		EX00013	0.00	219.06	0.00
PM57	XQ26AV	00025513	3/24/2020	GEN	13	K092-335	BROHUR01	1864036	PANEL LIGHT CONTROL (dimmer switch),PM57		EX00013	1.00	219.06	219.06
PM57	XQ26AV	00025513	3/24/2020	GEN	13	47501	BROHUR01	1864036	GLOBE WEDGE 12V5W,PM57		EX00013	1.00	4.22	4.22
PM57	XQ26AV	00025513	3/24/2020	GEN	13	P27-1187-002	BROHUR01	1864036	SWITCH- MIRROR MODULES,PM57		EX00013	1.00	125.21	125.21
PM57	XQ26AV	00025513	3/24/2020	GEN	SUPPLIED BY BROWN & HURLEY 24.03.2020									
					INVOICE # 1864036									
PM57	XQ26AV	00025717	3/25/2020	GEN	15	33000517	BRIAUS01	EX00013388	REMOVAL: CUSTOMER PULL POINT,PM57		EX00013	0.00	0.00	0.00

PM57	XQ26AV	00025717	3/25/2020	GEN	15	77000180	BRIAUS01	EX00013388	CASE STOCK 11-22.5,PM57	EX00013	0.00	20.00	0.00
PM57	XQ26AV	00025717	3/25/2020	GEN	15	99015526	BRIAUS01	EX00013388	RUNOUT TYRE,PM57	EX00013	0.00	0.00	0.00
PM57	XQ26AV	00025717	3/25/2020	GEN	15	33000084	BRIAUS01	EX00013388	FIT TBR TYRE,PM57	EX00013	0.00	0.00	0.00
PM57	XQ26AV	00025717	3/25/2020	GEN	COMPLETED BY BRIDGESTONE 25.03.2020								
					INVOICE # 98297079								
PM57	XQ26AV	00025717	3/25/2020	GEN	15	33000084	BRIAUS01	98297079	FIT TBR TYRE,PM57	EX00013	1.00	0.00	0.00
PM57	XQ26AV	00025717	3/25/2020	GEN	15	99015526	BRIAUS01	98297079	RUNOUT TYRE,PM57	EX00013	1.00	0.00	0.00
PM57	XQ26AV	00025717	3/25/2020	GEN	15	77000180	BRIAUS01	98297079	CASE STOCK 11-22.5,PM57	EX00013	-1.00	20.00	-20.00
PM57	XQ26AV	00025717	3/25/2020	GEN	15	33000517	BRIAUS01	98297079	REMOVAL: CUSTOMER PULL POINT,PM57	EX00013	1.00	0.00	0.00
PM57	XQ26AV	00025679	3/25/2020	WEICAL	00	LABOUR Labour			0.00	0.00	0.00		
PM57	XQ26AV	00025679	3/25/2020	WEICAL	AIR GAUGE: 15.50								
					ADJUSTED: 0.00								
					WEIGHBRIDGE: 15.20								
					AIR GAUGE CALIBRATION COMPLETED CORRECTLY.								
PM57	XQ26AV	00025710	3/28/2020	CUMAE5	01	LABOUR Labour			0.00	0.00	0.00		
PM57	XQ26AV	00025710	3/28/2020	CUMAE5	SERVICE COMPLETED.								
PM57	XQ26AV	00025710	3/28/2020	CUMBE5	01	LABOUR Labour			0.00	0.00	0.00		
PM57	XQ26AV	00025710	3/28/2020	CUMBE5	SERVICE COMPLETED BY BILLY / KEIRAN / SEAN 28.03.2020								
PM57	XQ26AV	00025710	3/28/2020	CUMBE5	00	LABOUR	MECH1	Labour - Internal			1.00	85.00	85.00
PM57	XQ26AV	00025710	3/28/2020	CUMBE5	00	LABOUR	APPREN	Labour - Internal			1.00	85.00	85.00
PM57	XQ26AV	00025710	3/28/2020	CUMBE5	00	LABOUR	MECH1	Labour - Internal			1.00	85.00	85.00
PM57	XQ26AV	00025710	3/28/2020	CUMBE5	06	AS2474	YAT	Ad Blue filter Kenworth			1.00	11.61	11.61
PM57	XQ26AV	00025710	3/28/2020	CUMBE5	06	LF14000NN	YAT	Oil Filter (was LF9080)			1.00	37.27	37.27
PM57	XQ26AV	00025710	3/28/2020	CUMBE5	06	FF5776	YAT	FF5776 Fuel Filter			1.00	42.00	42.00
PM57	XQ26AV	00025710	3/28/2020	CUMBE5	40	3413005	YAT	OIL 15W-40, CK 4/E9			49.00	3.54	173.46
PM57	XQ26AV	00025710	3/28/2020	CUMBE5	06	TRPCAF0001	YAT	TRP KW CAB AIR FILTER			1.00	21.78	21.78
PM57	XQ26AV	00025710	3/28/2020	CUMBE5	16	CON	YAT	Consumables			3.00	15.00	45.00
PM57	XQ26AV	00025710	3/28/2020	DEFECT	01	LABOUR	MECH	Labour			0.00	0.00	0.00
PM57	XQ26AV	00025710	3/28/2020	DEFECT	Reported Defect :-								
					Defect Code : 00003994								
					Defect Reference : 5834								
					Date : 18/03/2020								
					Description of Defect :								
					4000KM OFF FROM ITS NEXT SERVICE								
					DEFECT CLEARED BY BILLY 28.03.2020								
PM57	XQ26AV	00025966	4/5/2020	GEN	15	33000096	BRIAUS01	EX00013524	PUNCTURE REPAIR TBR,PM57	EX00013	0.00	25.00	0.00
PM57	XQ26AV	00025966	4/5/2020	GEN	COMPLETED BY BRIDGESTONE 05.04.2020								
					INVOICE # 98332533								
PM57	XQ26AV	00025966	4/5/2020	GEN	15	33000096	BRIAUS01	98332533	PUNCTURE REPAIR TBR,PM57	EX00013	1.00	25.00	25.00
PM57	XQ26AV	00026368	4/20/2020	GEN	13	K127-1116-01A	BROHUR01	EX00013716	Mudguard White,PM57	EX00013	0.00	52.15	0.00
PM57	XQ26AV	00026368	4/20/2020	GEN	13	82062/1	BROHUR01	EX00013716	7 PIN LGE ROUND METAL SKT,PM57	EX00013	0.00	7.12	0.00
PM57	XQ26AV	00026368	4/20/2020	GEN	13	PMDS1700	BROHUR01	EX00013716	DRESS STRIP S/S S/SAFE GUARD,PM57	EX00013	0.00	52.00	0.00

PM57	XQ26AV	00026368	4/20/2020	GEN	SUPPLIED BY BROWN & HURLEY 20.04.2020								
PM57	XQ26AV	00026368	4/20/2020	GEN	INVOICE # 1884008								
PM57	XQ26AV	00026368	4/20/2020	GEN	13 K127-1116-01A BROHUR01 1884008	Mudguard White,PM57	EX00013	4.00	52.15	208.60			
					13 PMDS1700 BROHUR01 1884008	DRESS STRIP S/S S/SAFE GUARD,PM57	EX00013	4.00	52.00	208.00			
PM57	XQ26AV	00026368	4/20/2020	GEN	13 82062/1 BROHUR01 1884008	7 PIN LGE ROUND METAL SKT,PM57	EX00013	25.00	7.12	178.00			
PM57	XQ26AV	00026453	4/23/2020	WEICAL	00 LABOUR Labour	0.00 0.00 0.00							
PM57	XQ26AV	00026453	4/23/2020	WEICAL	AIR GAUGE: 12.5 ADJUSTED: 11.5 WEIGHBRIDGE: 11.2								
PM57	XQ26AV	00026439	4/24/2020	CUMAE5	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.								
PM57	XQ26AV	00026439	4/24/2020	CUMAE5	01 LABOUR Labour	0.00 0.00 0.00							
					SERVICE COMPLETED BY KEIRAN / SEAN 24.04.2020								
					TOPPED UP ENGINE WITH 2.5L OF OIL INTO ENGINE REPLACED BOTH BUSHES IN FRONT LEFT TORQUE ROD BUSHES ADJUSTED WINDOW WASHERS REPLACED FUEL PUMP, FUEL HOSE AND CLEANED INJECTOR ADJUSTED CLUTCH								
PM57	XQ26AV	00026439	4/24/2020	CUMAE5	40 3413005 YAT OIL 15W-40, CK 4/E9	2.50 3.54 8.85							
PM57	XQ26AV	00026439	4/24/2020	CUMAE5	13 839310 YAT Torque Rod Bush	2.00 60.00 120.00							
PM57	XQ26AV	00026439	4/24/2020	CUMAE5	00 LABOUR APPREN Labour - Internal	1.50 85.00 127.50							
PM57	XQ26AV	00026439	4/24/2020	CUMAE5	00 LABOUR MECH1 Labour - Internal	1.50 85.00 127.50							
PM57	XQ26AV	00026439	4/24/2020	CUMAE5	16 CON YAT Consumables	5.00 15.00 75.00							
PM57	XQ26AV	00026439	4/24/2020	DEFECT	01 LABOUR MECH Labour	0.00 0.00 0.00							
PM57	XQ26AV	00026439	4/24/2020	DEFECT	DEFECT # 11855 ICE PACK NOT WORKING - LOST IT OIL								
PM57	XQ26AV	00026439	4/24/2020	DEFECT	DEFECT CLEARED BY SEAN 24.04.2020 DEFECT # 11856 A SERVICE DUE								
PM57	XQ26AV	00026439	4/24/2020	DEFECT	DEFECT CLEARED BY 24.04.2020 Reported Defect :- Defect Code : 00004191 Defect Reference : 11857 Date : 18/04/2020 Description of Defect : WINDOW WASHER NOT WORKING								
PM57	XQ26AV	00026450	4/24/2020	WEICAL	DEFECT CLEARED BY SEAN 24.04.2020								
PM57	XQ26AV	00026450	4/24/2020	WEICAL	00 LABOUR Labour	0.00 0.00 0.00							
					AIR GAUGE: 16.5 ADJUSTED: 0 WEIGHBRIDGE: 16.2								
					AIR GAUGE CALIBRATION COMPLETED CORRECTLY.								

PM57	XQ26AV	00026831	4/29/2020	WEICAL	00	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00026831	4/29/2020	WEICAL			AIR GAUGE: 13.5 ADJUSTED: 0 WEIGHBRIDGE: 13								
							AIR GAUGE CALIBRATION COMPLETED CORRECTLY.								
PM57	XQ26AV	00026949	5/11/2020	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00026949	5/11/2020	CUMAE5			SERVICE COMPLETED BY BILLY / BEN 11.05.2020								
PM57	XQ26AV	00026949	5/11/2020	CUMAE5	00	LABOUR	MECH1 Labour - Internal			0.75	85.00	63.75			
PM57	XQ26AV	00026949	5/11/2020	CUMAE5	00	LABOUR	APPREN Labour - Internal			0.75	85.00	63.75			
PM57	XQ26AV	00026949	5/11/2020	CUMAE5	40	3413005	YAT OIL 15W-40, CK 4/E9				2.00	3.54	7.08		
PM57	XQ26AV	00026949	5/11/2020	CUMAE5	16	CON	YAT Consumables				3.00	15.00	45.00		
PM57	XQ26AV	00026918	5/11/2020	ROTDRI	15	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00026918	5/11/2020	ROTDRI			DRIVE TYRE ROTATION COMPLETED.								
							COMPLETED BY BRIDGESTONE - JOHNNY 11.05.2020								
PM57	XQ26AV	00027071	5/15/2020	GEN	13	715-8016-006	BROHUR01 EX00014045	CONNECTOR ELBOW 1/4 - 3mm,PM57				EX00014	0.00	8.18	0.00
PM57	XQ26AV	00027071	5/15/2020	GEN			COMPLETED BY BROWN & HURLEY 15.05.2020								
							INVOICE # 1904789								
PM57	XQ26AV	00027117	5/15/2020	GEN	39	LABOUR	Labour		0.00	0.00	0.00				
PM57	XQ26AV	00027071	5/15/2020	GEN	13	715-8016-006	BROHUR01 1904789	CONNECTOR ELBOW 1/4 - 3mm,PM57				EX00014	2.00	8.18	16.36
PM57	XQ26AV	00027117	5/15/2020	GEN			REPAIR COMPLETED BY SEAN / BEN 15.05.2020								
							REMOVED WALK PLATE, G-BOX, INTERCOOLER HOSES, RADIATOR HOSES, OIL FILLER AND DIP STICK CABLES								
							REMOVED ENGINE, FITTED ALL HOSES AND COMPONENTS TO NEW ENGINE, REPLACED CLUTCH AND WASHED CHASSIS								
							FITTED NEW ENGINE, RAN ALL CABLES, HOSES, FITTED G-BOX AND DRIVE SHAFT WITH NEW UNI SHAFTS AND REPLACED ENGINE MOUNTS								
							REPLACED ALL 4 DRIVE GUARDS AND FLAPS								
							FITTED ENGINE OIL, COOLANT, POWER STEERING OIL								
							TEST DROVE, ADJUSTED CLUTCH AND GEAR STICK POSITION								
							WASHED AND CLEANED TRUCK								
PM57	XQ26AV	00027117	5/15/2020	GEN	00	LABOUR	MECH1 Labour - Internal			32.50	85.00	2,762.50			
PM57	XQ26AV	00027117	5/15/2020	GEN	00	LABOUR	APPREN Labour - Internal			32.50	85.00	2,762.50			
PM57	XQ26AV	00027117	5/15/2020	GEN	13	K127-1116-01A	YAT Mudguard White				4.00	52.15	208.60		
PM57	XQ26AV	00027117	5/15/2020	GEN	13	55150NAV	YAT 300MM RADIATOR HOSE PLIER				1.00	9.09	9.09		
PM57	XQ26AV	00027117	5/15/2020	GEN	13	HE8699	YAT Hump Hose				2.00	52.38	104.76		
PM57	XQ26AV	00027117	5/15/2020	GEN	13	HE8761XL	YAT Hump Hose 4 X 4.5 Long				1.00	54.10	54.10		
PM57	XQ26AV	00027117	5/15/2020	GEN	13	12PK2380	YAT Drive Belt, K200				1.00	68.86	68.86		
PM57	XQ26AV	00027117	5/15/2020	GEN	06	52520	YAT COOLANT PRO, H/DTY GREEN				60.00	5.28	316.80		
PM57	XQ26AV	00027117	5/15/2020	GEN	40	3413005	YAT OIL 15W-40, CK 4/E9				49.00	3.54	173.46		
PM57	XQ26AV	00027117	5/15/2020	GEN	16	CON	YAT Consumables				20.00	15.00	300.00		
PM57	XQ26AV	00027117	5/15/2020	GEN	13	5.281X	YAT 1810 Uni Joint Spicer FR				2.00	85.70	171.40		
PM57	XQ26AV	00027117	5/15/2020	GEN	13	308935.529PAC	YAT CLUTCH ADVANTAGE				1.00	1,522.80	1,522.80		

PM57	XQ26AV	00027117	5/15/2020	GEN	13	D13-1012	YAT	BUSHING-FRONT ENGINE	2.00	47.00	94.00					
PM57	XQ26AV	00027117	5/15/2020	GEN	13	K066-404	YAT	BUSHING-FRONT ENGINE	2.00	31.82	63.64					
PM57	XQ26AV	00027117	5/15/2020	GEN	13	D13-1001-4	YAT	BUSHING REAR ENGINE BARRY	2.00	120.00	240.00					
PM57	XQ26AV	00027117	5/15/2020	GEN	13	K066-421	YAT	BUSHING SNUBBR BAR	2.00	50.00	100.00					
PM57	XQ26AV	00027117	5/15/2020	GEN	13	52371.01	YAT	500HP CUMMINS ENGINE	1.00	#####	#####					
PM57	XQ26AV	00027125	5/16/2020	DEFECT	01	LABOUR MECH	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00027125	5/16/2020	DEFECT	DEFECT # 5839 BIG AIR LEAK AT REAR OF TRUCK ONLY WHEN THERE IS A TRAILER OR LOAD HOOKED ON, NOT BOBTAIL. TAKES 8 MINS TO LOSE ALL AIR AND DROP DOWN TO BUMP STOPS											
					DEFECT CLEARED BY SEAN 16.05.2020											
PM57	XQ26AV	00027125	5/16/2020	DEFECT	DEFECT # 5837 NEW ENGINE IS PERFECT AND FAULTLESS PYRO WENT UP TO 425 DEGREES ALL NIGHT BOOST KPA, NO MORE THAN 200 TEMPERATURES STAYED BELOW 90 DEGREES DEFECT # 5838 NO AIR CONDITIONING, MAY RE-GAS?											
PM57	XQ26AV	00027125	5/16/2020	DEFECT	DEFECT CLEARED BY SEAN 16.05.2020 (TO BE FIXED 18.05.2020)											
PM57	XQ26AV	00027125	5/16/2020	GEN	39	LABOUR	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00027125	5/16/2020	GEN	REPAIR COMPLETED BY SEAN / BEN 16.05.2020											
					R & R LHS 2nd DRIVE FRONT AIR BAG DIAGNOSED A/C ISSUE TO BE LOW GAS											
PM57	XQ26AV	00027125	5/16/2020	GEN	00	LABOUR MECH1	Labour - Internal		1.00	85.00	85.00					
PM57	XQ26AV	00027125	5/16/2020	GEN	00	LABOUR APPREN	Labour - Internal		0.50	85.00	42.50					
PM57	XQ26AV	00027125	5/16/2020	GEN	13	C81-1005	YAT	Air Bag, Drive K200		1.00	381.71	381.71				
PM57	XQ26AV	00027125	5/16/2020	GEN	16	CON	YAT	Consumables		3.00	15.00	45.00				
PM57	XQ26AV	00027158	5/18/2020	GEN	13	308935.515PAC	BROHUR01	EX00014077	CLUTCH KIT-ADVANTAGE,PM57				EX00014	0.00	1,522.80	0.00
PM57	XQ26AV	00027158	5/18/2020	GEN	COMPLETED BY BROWN & HURLEY 18.05.2020 INVOICE # 1907170											
PM57	XQ26AV	00027158	5/18/2020	GEN	13	308935.515PAC	BROHUR01	1907170	CLUTCH KIT-ADVANTAGE,PM57				EX00014	1.00	1,522.80	1,522.80
PM57	XQ26AV	00027352	5/20/2020	WEICAL	00	LABOUR	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00027352	5/20/2020	WEICAL	AIR GAUGE: 15.2 ADJUSTED: 15.5 WEIGHBRIDGE: 15.18											
					AIR GAUGE CALIBRATION COMPLETED CORRECTLY.											
PM57	XQ26AV	00027355	5/27/2020	GEN	16	CA93-114	BROHUR01	EX00014161	FEMALE CONNECTOR SEAL,PM57				EX00014	0.00	4.09	0.00
PM57	XQ26AV	00027355	5/27/2020	GEN	03	235	BROHUR01	EX00014161	KIT-UNLOADER,AIRDRYER,PM57				EX00014	0.00	48.18	0.00
PM57	XQ26AV	00027355	5/27/2020	GEN	03	6306-2RS2/C5GJB	BROHUR01	EX00014161	Bearing - Spigot,PM57				EX00014	0.00	30.91	0.00
PM57	XQ26AV	00027355	5/27/2020	GEN	03	70-250	BROHUR01	EX00014161	HOSE PUROSIL 2.50" 4 PLY,PM57				EX00014	0.00	29.16	0.00
PM57	XQ26AV	00027355	5/27/2020	GEN	03	PART	BROHUR01	EX00014161	HOUSE, PURSOIL 3" 4 PLY,PM57				EX00014	0.00	30.05	0.00
PM57	XQ26AV	00027355	5/27/2020	GEN	16	CA93-114	BROHUR01	1912477	FEMALE CONNECTOR SEAL,PM57				EX00014	40.00	4.09	163.60

PM57	XQ26AV	00027355	5/27/2020	GEN	03	235	BROHUR01	1912477	KIT-UNLOADER,AIRDRYER,PM57	EX00014	2.00	48.18	96.36
PM57	XQ26AV	00027355	5/27/2020	GEN	03	6306-2RS2/C5GJB	BROHUR01	1912477	Bearing - Spigot,PM57	EX00014	1.00	30.91	30.91
PM57	XQ26AV	00027355	5/27/2020	GEN	03	70-250	BROHUR01	1912477	HOSE PUROSIL 2.50" 4 PLY,PM57	EX00014	3.00	29.16	87.48
PM57	XQ26AV	00027355	5/27/2020	GEN	03	PART	BROHUR01	1912477	HOUSE, PURSOIL 3" 4 PLY,PM57	EX00014	3.00	30.05	90.15
PM57	XQ26AV	00027364	5/28/2020	GEN	13	5.281X	BROHUR01	EX00014187	1810 Uni Joint Spicer FR,PM57	EX00014	0.00	80.84	0.00
PM57	XQ26AV	00027364	5/28/2020	GEN	13	5.281X	BROHUR01	1915533	1810 Uni Joint Spicer FR,PM57	EX00014	2.00	80.84	161.68
PM57	XQ26AV	00027428	5/29/2020	CUMAE5	01	LABOUR MECH	Labour		0.50 85.00 42.50				
PM57	XQ26AV	00027428	5/29/2020	CUMAE5					SERVICE COMPLETED.				
									HAVE UPDATED SERVICE STICKER FOR "B" SERVICE - DUE AT 400,000KMS AS IT IS A NEW ENGINE.				
PM57	XQ26AV	00027428	5/29/2020	CUMAE5	00	LABOUR APPREN	Labour - Internal		0.50 85.00 42.50				
PM57	XQ26AV	00027428	5/29/2020	CUMAE5	16	CON	YAT Consumables			45.00			
PM57	XQ26AV	00027428	5/29/2020	DEFECT					DEFECT CLEARED BY SEAN M 29.05.2020				
									4Reported Defect :-				
									Defect Code : 00003540				
									Defect Reference : INTERNAL				
									Date : 07/01/2020				
									Description of Defect :				
									MONITOR				
									CHECK FUEL FOR WATER				
PM57	XQ26AV	00027428	5/29/2020	DEFECT					DEFECT CLEARED BY SEAN M 29.05.2020				
									Reported Defect :-				
									Defect Code : 00003995				
									Defect Reference : 5830				
									Date : 18/03/2020				
									Description of Defect :				
									ALL 17 GAUGES ARE FLICKERING LIKE A DISCO. CONSTANTLY ON/OFF				
PM57	XQ26AV	00027444	6/1/2020	GEN	03	52371.01	BROHUR01	EX00014208	500HP CUMMINS ENGINE,PM57	EX00014	0.00	#####	0.00
PM57	XQ26AV	00027444	6/1/2020	GEN	03	52371.01	BROHUR01	1917026	500HP CUMMINS ENGINE,PM57	EX00014	1.00	#####	#####
PM57	XQ26AV	00027565	6/3/2020	GEN	13	TRAVEL FEE	NABQAN01	EX00014296	Travel Fee to Breakdowns,PM57	EX00014	0.00	205.80	0.00
PM57	XQ26AV	00027565	6/3/2020	GEN	13	PART	NABQAN01	EX00014296	CARTRIDGE AIR DRYER,PM57	EX00014	0.00	140.91	0.00
PM57	XQ26AV	00027565	6/3/2020	GEN	13	TRAVEL FEE	NABQAN01	EX00014296	Travel Fee to Breakdowns,PM57	EX00014	0.00	1.40	0.00
PM57	XQ26AV	00027565	6/3/2020	GEN					COMPLETED BY KENWORTH MELBOURNE 03.06.2020				
									INVOICE # 939764				
									BREAKDOWN				
									TRAVEL TO SITE, INSPECT TRUCK FOUND LEAKING AIR AT AIR DRYER FILTER.				
									REMOVED AIR DRYER FILTER AND FOUND AIR FILTER O RING SPLIT FROM BEING OVER TIGHTENED				
									REPLACED AIR DRYER FILTER WITH NEW				
									TRAVELLED ROUND TRIP 10KMS				
PM57	XQ26AV	00027565	6/3/2020	GEN	13	TRAVEL FEE	NABQAN01	939764	Travel Fee to Breakdowns,PM57	EX00014	1.00	205.80	205.80
PM57	XQ26AV	00027565	6/3/2020	GEN	13	PART	NABQAN01	939764	CARTRIDGE AIR DRYER,PM57	EX00014	1.00	140.91	140.91
PM57	XQ26AV	00027565	6/3/2020	GEN	13	TRAVEL FEE	NABQAN01	939764	Travel Fee to Breakdowns,PM57	EX00014	10.00	1.40	14.00
PM57	XQ26AV	00027746	6/10/2020	CUMAE5	01	LABOUR	Labour		0.00 0.00 0.00				
PM57	XQ26AV	00027746	6/10/2020	CUMAE5					SERVICE COMPLETED.				

PM57	XQ26AV	00027746	6/10/2020	CUMBE5	01	LABOUR	Labour		0.00	0.00	0.00		
PM57	XQ26AV	00027746	6/10/2020	CUMBE5	SERVICE COMPLETED BY BILLY 10.06.2020								
					REPLACED FRONT LEFT DRIVE AIR BAG AS REQUIRED REPLACED RHT DRIVE FRONT DRIVE BACK AIRBAG, REPLACED BACK DRIVE LEFT AIRBAG AS REQUIRED REPLACED BACK DRIVE RHT SIDE BRAKE BOOSTER AS REQUIRED REPLACED BOTH BOTTOM STEPS ON DRIVERS SIDE AS THEY WERE BROKEN TIGHTENED UP BOTTOM AIR DRYER BOLTS AS REQUIRED								
PM57	XQ26AV	00027746	6/10/2020	CUMBE5	00	LABOUR	MECH1	Labour - Internal		5.00	85.00	425.00	
PM57	XQ26AV	00027746	6/10/2020	CUMBE5	40	3413005	YAT	OIL 15W-40, CK 4/E9			48.00	3.54	169.92
PM57	XQ26AV	00027746	6/10/2020	CUMBE5	06	MK13584	YAT	MAINTENANCE KIT			1.00	91.95	91.95
PM57	XQ26AV	00027746	6/10/2020	CUMBE5	13	CB3030-EB	YAT	Brake Booster 30/30			1.00	45.00	45.00
PM57	XQ26AV	00027746	6/10/2020	CUMBE5	13	FQ7789	YAT	AIRBAG KW			3.00	161.20	483.60
PM57	XQ26AV	00027746	6/10/2020	CUMBE5	16	CON	YAT	Consumables			4.00	15.00	60.00
PM57	XQ26AV	00027746	6/10/2020	DEFECT	01	LABOUR	MECH	Labour		0.00	0.00	0.00	
PM57	XQ26AV	00027746	6/10/2020	DEFECT	DEFECT # 5833 B SERVICE DUE								
					DEFECT CLEARED BY BILLY 10.06.2020								
PM57	XQ26AV	00027746	6/10/2020	DEFECT	DEFECT # 5841 REAR AIR BAGS LEAKING BADLY								
					DEFECT CLEARED BY BILLY 10.06.2020								
PM57	XQ26AV	00027746	6/10/2020	DEFECT	MONITOR - CHANGED OUT 3 AIRBAGS Reported Defect :- Defect Code : 00004406 Defect Reference : 5824 Date : 02/06/2020 Description of Defect : AIR BAGS LEAKING - SITS DOWN WITHIN 10 MINUTES AFTER SHUT DOWN. LOSES ALL AIR								
					DEFECT CLEARED BY BILLY 10.06.2020								
PM57	XQ26AV	00027746	6/10/2020	DEFECT	(CHANGED OUT 3 DRIVE AIR BAGS, REPLACED LEAKING BOOSTER, TIGHTENED UP BOTTOM BOLTS FOR AIR DRYER) Reported Defect :- Defect Code : 00004407 Defect Reference : 5825 Date : 02/06/2020 Description of Defect : WINDOW WASHER NOT WORKING								
					DEFECT CLEARED BY BILLY 10.06.2020								
PM57	XQ26AV	00027746	6/10/2020	DEFECT	(COULDN'T FAULT - WERE WORKING WHEN IT CAME IN) DEFECT # 5842 WINDOW WASHER NOT WORKING								
					DEFECT CLEARED BY BILLY 10.06.2020								
					(COULDN'T FAULT)								

PM57	XQ26AV	00027759	6/11/2020	GEN	15	33000517	BRIAUS01	EX00014394	REMOVAL: CUSTOMER PULL POINT,PM57			EX00014	0.00	0.00	0.00	
PM57	XQ26AV	00027759	6/11/2020	GEN	15	77000180	BRIAUS01	EX00014394	CASE STOCK 11-22.5,PM57			EX00014	0.00	20.00	0.00	
PM57	XQ26AV	00027759	6/11/2020	GEN	15	11002831	BRIAUS01	EX00014394	TYRE 11R22.5 146/143L M766,PM57			EX00014	0.00	0.00	0.00	
PM57	XQ26AV	00027759	6/11/2020	GEN	15	33000084	BRIAUS01	EX00014394	FIT TBR TYRE,PM57			EX00014	0.00	0.00	0.00	
PM57	XQ26AV	00027759	6/11/2020	GEN	COMPLETED BY BRIDGESTONE 11.06.2020											
					INVOICE # 98647146											
PM57	XQ26AV	00027759	6/11/2020	GEN	15	33000084	BRIAUS01	98647146	FIT TBR TYRE,PM57			EX00014	4.00	0.00	0.00	
PM57	XQ26AV	00027759	6/11/2020	GEN	15	11002831	BRIAUS01	98647146	TYRE 11R22.5 146/143L M766,PM57			EX00014	1.00	0.00	0.00	
PM57	XQ26AV	00027759	6/11/2020	GEN	15	77000180	BRIAUS01	98647146	CASE STOCK 11-22.5,PM57			EX00014	-3.00	20.00	-60.00	
PM57	XQ26AV	00027759	6/11/2020	GEN	15	33000517	BRIAUS01	98647146	REMOVAL: CUSTOMER PULL POINT,PM57			EX00014	4.00	0.00	0.00	
PM57	XQ26AV	00027754	6/11/2020	ROTDRI	15	LABOUR Labour			0.00	0.00	0.00					
PM57	XQ26AV	00027754	6/11/2020	ROTDRI	DRIVE TYRE ROTATION COMPLETED.											
PM57	XQ26AV	00027753	6/11/2020	STEROT	COMPLETED BY BRIDGESTONE - DAVE 11/06/20											
					15	LABOUR Labour			0.00	0.00	0.00					
PM57	XQ26AV	00027753	6/11/2020	STEROT	STEER TYRE ROTATION COMPLETED.											
PM57	XQ26AV	00027857	6/17/2020	GEN	COMPLETED BY BRIDGESTONE - DAVE 11/6/20											
					03	BROHUR01	1933539	C/N FOR INV 1917026	0.00	#####	#####					
PM57	XQ26AV	00027859	6/17/2020	GEN	03	BROHUR01	1933539R	reversal of c/n	0.00	0.00	#####					
PM57	XQ26AV	00028290	6/30/2020	CUMAE5	01	LABOUR Labour			0.00	0.00	0.00					
PM57	XQ26AV	00028290	6/30/2020	CUMAE5	SERVICE COMPLETED.											
PM57	XQ26AV	00028290	6/30/2020	CUMAE5	service completed by sean + duane 30/06/20											
PM57	XQ26AV	00028290	6/30/2020	CUMAE5	00	LABOUR mech1	Labour - Internal		0.50	85.00	42.50					
PM57	XQ26AV	00028290	6/30/2020	CUMAE5	00	LABOUR mech1	Labour - Internal		1.00	85.00	85.00					
PM57	XQ26AV	00028290	6/30/2020	CUMAE5	16	con	YAT Consumables			4.00	15.00	60.00				
PM57	XQ26AV	00028290	6/30/2020	DEFECT	01	LABOUR MECH	Labour		0.00	0.00	0.00					
PM57	XQ26AV	00028290	6/30/2020	DEFECT	DEFECT CLEARED.											
					30/06/20 by sean											
					Reported Defect :-											
					Defect Code : 00004400											
					Defect Reference : 11858											
					Date : 18/04/2020											
					Description of Defect :											
					- SHORT IN DASH LIGHTS											
					- ENGINE OIL TEMP NOT WORKING											
PM57	XQ26AV	00028290	6/30/2020	DEFECT	Reported Defect :-											
					Defect Code : 00004435											
					Defect Reference : 5840											
					Date : 10/06/2020											
					Description of Defect :											
					ENGINE OIL TEMP GAUGE NOT WORKING											
PM57	XQ26AV	00028690	7/15/2020	GEN	13	PART	NABQAN01	EX00014706	JOST 37 HANDLE BAR,PM57			EX00014	0.00	190.00	0.00	
PM57	XQ26AV	00028690	7/15/2020	GEN	13	PART	NABQAN01	EX00014706	JOST JSK 37 JAW KIT,PM57			EX00014	0.00	350.00	0.00	
PM57	XQ26AV	00028690	7/15/2020	GEN	13	CON	NABQAN01	EX00014706	CONSUMABLES,PM57			EX00014	0.00	15.00	0.00	

PM57	XQ26AV	00028690	7/15/2020	GEN	13	PART	NABQAN01	EX00014706	JOST LOCKING BAR,PM57	EX00014	0.00	357.00	0.00
PM57	XQ26AV	00028690	7/15/2020	GEN	13	LABEXT	NABQAN01	EX00014706	LABOUR EXTERNAL,PM57	EX00014	0.00	400.00	0.00
PM57	XQ26AV	00028690	7/15/2020	GEN	13	LABEXT	NABQAN01	1965	LABOUR EXTERNAL,PM57	EX00014	1.00	400.00	400.00
PM57	XQ26AV	00028690	7/15/2020	GEN	13	PART	NABQAN01	1965	JOST LOCKING BAR,PM57	EX00014	1.00	357.00	357.00
PM57	XQ26AV	00028690	7/15/2020	GEN	13	CON	NABQAN01	1965	CONSUMABLES,PM57	EX00014	1.00	15.00	15.00
PM57	XQ26AV	00028690	7/15/2020	GEN	13	PART	NABQAN01	1965	JOST JSK 37 JAW KIT,PM57	EX00014	1.00	350.00	350.00
PM57	XQ26AV	00028690	7/15/2020	GEN	13	PART	NABQAN01	1965	JOST 37 HANDLE BAR,PM57	EX00014	1.00	190.00	190.00
PM57	XQ26AV	00028741	7/17/2020	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00		
PM57	XQ26AV	00028741	7/17/2020	CUMAE5		SERVICE COMPLETED.							
PM57	XQ26AV	00028741	7/17/2020	CUMBE5	00	LABOUR	MECH1	Labour - Internal			2.00	85.00	170.00
PM57	XQ26AV	00028741	7/17/2020	CUMBE5		SERVICE COMPLETED BY SEAN, KEIRAN AND MICK 17.07.2020							
						ADJUSTED TURNTABLE (MICK).							
PM57	XQ26AV	00028741	7/17/2020	CUMBE5	00	LABOUR	APPREN	Labour - Internal			1.00	85.00	85.00
PM57	XQ26AV	00028741	7/17/2020	CUMBE5	00	LABOUR	MECH	Labour - Internal			2.00	85.00	170.00
PM57	XQ26AV	00028741	7/17/2020	CUMBE5	16	CON	YAT	Consumables			5.00	15.00	75.00
PM57	XQ26AV	00028741	7/17/2020	CUMBE5	06	MK13584	YAT	MAINTENANCE KIT			1.00	91.95	91.95
PM57	XQ26AV	00028741	7/17/2020	CUMBE5	40	3413005	YAT	OIL 15W-40, CK 4/E9			48.00	3.54	169.92
PM57	XQ26AV	00028767	7/18/2020	DEFECT		DEFECT CLEARED BY SEAN 18.07.2020							
						DEFECT: 5844							
						REPORTED BY: JIMMY							
						"ICE PACK NEEDS SERVICING. NOT STARTING".							
PM57	XQ26AV	00028767	7/18/2020	ECO	00	LABOUR	MECH1	Labour			1.00	85.00	85.00
PM57	XQ26AV	00028767	7/18/2020	ECO		SERVICE COMPLETED BY SEAN 18.07.2020							
PM57	XQ26AV	00028767	7/18/2020	ECO	16	CON	YAT	Consumables			4.00	15.00	60.00
PM57	XQ26AV	00028767	7/18/2020	ECO	40	10W50	YAT	HITECH SYNPLUS 10W50			1.10	9.25	10.18
PM57	XQ26AV	00028767	7/18/2020	ECO	06	ED2175254-S	YAT	AIR FILTER SLEEPER AIR			1.00	53.50	53.50
PM57	XQ26AV	00029120	7/28/2020	GEN	39	LABEXT	BROHUR01	EX00014918	Labour External,PM57	EX00014	0.00	279.44	0.00
PM57	XQ26AV	00029120	7/28/2020	GEN	39	K251-571	BROHUR01	EX00014918	Receiver Drier, K200,PM57	EX00014	0.00	63.50	0.00
PM57	XQ26AV	00029120	7/28/2020	GEN	39	K207-965-6	BROHUR01	EX00014918	O-RING - 3X,PM57	EX00014	0.00	1.35	0.00
PM57	XQ26AV	00029120	7/28/2020	GEN	39	R134A	BROHUR01	EX00014918	R134A, A/C GAS,PM57	EX00014	0.00	150.00	0.00
PM57	XQ26AV	00029120	7/28/2020	GEN	39	ENVLEV	BROHUR01	EX00014918	ENVIRONMENTAL LEVY,PM57	EX00014	0.00	5.00	0.00
PM57	XQ26AV	00029120	7/28/2020	GEN	39	CON	BROHUR01	EX00014918	MISC. CONSUMABLES,PM57	EX00014	0.00	5.00	0.00

PM57	XQ26AV	00029120	7/28/2020	GEN	REPAIR COMPLETED BY B+H YATALA 28.07.2020							
					INV: 1965872							
					CHECK FOR LEAKS.							
					FOUND STAINS FROM A/C HOSE FROM CONDENSOR TO RECEIVER DRYER.							
					HOOK UP GAUGES AND RECOVER GAS.							
					PRESSURE TEST AND FOUND LEAKS COMING FROM FITTING AT CONDENSOR.							
					REMOVE FITTING AND FOUND O-RING DAMAGED.							
					REPLACE O-RING, PRESSURE TEST AGAIN AND CHECK FOR LEAKS.							
					REPLACE RECEIVER DRYER.							
					VACUUM DOWN SYSTEM AND FILL WITH GAS AND DYE.							
					TEST OPERATION							
PM57	XQ26AV	00029120	7/28/2020	GEN	39 CON BROHUR01 1965872	MISC. CONSUMABLES,PM57	EX00014	1.00	5.00	5.00		
PM57	XQ26AV	00029120	7/28/2020	GEN	39 ENVLEV BROHUR01 1965872	ENVIRONMENTAL LEVY,PM57	EX00014	1.00	5.00	5.00		
PM57	XQ26AV	00029120	7/28/2020	GEN	39 R134A BROHUR01 1965872	R134A, A/C GAS,PM57	EX00014	1.00	150.00	150.00		
PM57	XQ26AV	00029120	7/28/2020	GEN	39 K207-965-6 BROHUR01 1965872	O-RING - 3X,PM57	EX00014	1.00	1.35	1.35		
PM57	XQ26AV	00029120	7/28/2020	GEN	39 K251-571 BROHUR01 1965872	Receiver Drier, K200,PM57	EX00014	1.00	63.50	63.50		
PM57	XQ26AV	00029120	7/28/2020	GEN	39 LABEXT BROHUR01 1965872	Labour External,PM57	EX00014	1.00	279.44	279.44		
PM57	XQ26AV	00029163	7/29/2020	STEROT	STEER TYRE ROTATION COMPLETED.							
					COMPLETED BY BRIDGESTONE - DAVE - 29.07.2020							
PM57	XQ26AV	00029261	8/3/2020	CUMAE5	01 LABOUR MECH1 Labour			1.00	85.00	85.00		
PM57	XQ26AV	00029261	8/3/2020	CUMAE5	SERVICE COMPLETED BY SEAN 03.08.2020							
					REPLACED FIRE EXTINGUISHER.							
PM57	XQ26AV	00029261	8/3/2020	CUMAE5	16 CON YAT Consumables			4.00	15.00	60.00		
PM57	XQ26AV	00029261	8/3/2020	DEFECT	DEFECT CLEARED BY SEAN 03.08.2020							
					Defect: 5845							
					Reported by:Jimmy							
					"A" service overdue".							
PM57	XQ26AV	00029380	8/5/2020	GEN	15 33000085 BRIAUS01 EX00015079	ROTATE TBR TYRE,PM57	EX00015	0.00	0.00	0.00		
PM57	XQ26AV	00029380	8/5/2020	GEN	15 33000051 BRIAUS01 EX00015079	BALANCE TBR,PM57	EX00015	0.00	30.00	0.00		
PM57	XQ26AV	00029380	8/5/2020	GEN	15 33000051 BRIAUS01 98944531	BALANCE TBR,PM57	EX00015	2.00	30.00	60.00		
PM57	XQ26AV	00029380	8/5/2020	GEN	15 33000085 BRIAUS01 98944531	ROTATE TBR TYRE,PM57	EX00015	2.00	0.00	0.00		
PM57	XQ26AV	00029415	8/12/2020	CUMAE5	01 LABOUR MECH1 Labour - Internal			1.50	85.00	127.50		
PM57	XQ26AV	00029415	8/12/2020	CUMAE5	SERVICE COMPLETED BY SEAN 12.08.2020							
					REPLACED RHS LOADLIGHT							
					REMOVED 1X NUMBER PLATE LIGHT (FAULTY)							
PM57	XQ26AV	00029415	8/12/2020	CUMAE5	14 1089 YAT Load Light, Hella			1.00	25.46	25.46		
PM57	XQ26AV	00029415	8/12/2020	CUMAE5	16 CON YAT Consumables			5.00	15.00	75.00		

PM57	XQ26AV	00029874	8/24/2020	DEFECT	DEFECT CLEARED BY SEAN 24.08.2020													
					Defect: 5846 Reported by: Jimmy													
PM57	XQ26AV	00029874	8/24/2020	GEN	Aircon fan not working (cab).													
PM57	XQ26AV	00029874	8/24/2020	GEN	39	LABOUR	MECH1	Labour	2.00	85.00	170.00							
					REPAIR COMPLETED BY SEAN 24.08.2020													
PM57	XQ26AV	00029874	8/24/2020	GEN	FOUND A/C BLOWER MOTOR TO BE FAULTY, R+R BLOWER MOTOR.													
PM57	XQ26AV	00029874	8/24/2020	GEN	16	CON	YAT	Consumables		3.00	15.00	45.00						
PM57	XQ26AV	00030032	8/31/2020	CUMAE5	01	A11-0851	YAT	FAM MOTOR KW AC		1.00	270.00	270.00						
PM57	XQ26AV	00030032	8/31/2020	CUMAE5	01	LABOUR	MECH1	Labour	1.50	85.00	127.50							
					SERVICE COMPLETED BY JESSE 31/0/2020													
					CARRIED OUT "A" SERVICE ON TRUCK. FULL CHECK OVER. TOPPED UP COOLANT & ENGINE OIL, TIGHTENED UP COOLANT HOSE, REFITTED LOOSE AIR HOSE BACK ONTO BOOSTER.													
PM57	XQ26AV	00030032	8/31/2020	CUMAE5	BRAKES WERE A LONG WAY OUT OF ADJUSTMENT.													
PM57	XQ26AV	00030032	8/31/2020	CUMAE5	16	CON	YAT	Consumables		5.00	15.00	75.00						
PM57	XQ26AV	00030032	8/31/2020	CUMAE5	40	3413005	YAT	OIL 15W-40, CK 4/E9		4.00	3.54	14.16						
PM57	XQ26AV	00030032	8/31/2020	CUMAE5	06	54505	YAT	WYNN'S GREEN COOLANT		6.00	3.39	20.34						
PM57	XQ26AV	00030027	8/31/2020	GEN	39	P21-1029	BROHUR01	EX00015380	CONTROL ENGINE IDLER TIMER,PM57				EX00015	0.00	177.75	0.00		
PM57	XQ26AV	00030070	8/31/2020	GEN	39	TRAVEL FEE	NABQAN01	EX00015399	Travel Fee to Breakdowns,PM57				EX00015	0.00	0.00	0.00		
PM57	XQ26AV	00030027	8/31/2020	GEN	39	P21-1029	BROHUR01	1991644	CONTROL ENGINE IDLER TIMER,PM57				EX00015	1.00	177.75	177.75		
PM57	XQ26AV	00030060	8/31/2020	GEN	39	LABOUR MECH1	Labour - Internal		0.50	85.00	42.50							
PM57	XQ26AV	00030070	8/31/2020	GEN	39	LABEXT	NABQAN01	EX00015399	COMPUTER HOOK UP,PM57				EX00015	0.00	0.00	0.00		
PM57	XQ26AV	00030060	8/31/2020	GEN	REPAIR COMPLETED SEAN 31/08/2020.													
PM57	XQ26AV	00030070	8/31/2020	GEN	R+R TURBO TIMER													
PM57	XQ26AV	00030060	8/31/2020	GEN	39	CALL OUT FEE	NABQAN01	EX00015399	CALL OUT,PM57				EX00015	0.00	0.00	0.00		
PM57	XQ26AV	00030070	8/31/2020	GEN	16	CON	YAT	Consumables		2.00	15.00	30.00						
PM57	XQ26AV	00030060	8/31/2020	GEN	39	LABEXT	NABQAN01	EX00015399	Labour External,PM57				EX00015	0.00	0.00	0.00		
PM57	XQ26AV	00030070	8/31/2020	GEN	14	P21-1029	YAT	CONTROL ENGINE IDLER TIMER		1.00	177.75	177.75						
PM57	XQ26AV	00030070	8/31/2020	GEN	39	CON	NABQAN01	EX00015399	Consumables				EX00015	0.00	0.00	0.00		
PM57	XQ26AV	00030070	8/31/2020	GEN	39	ENVLEV	NABQAN01	EX00015399	ENVIRONMENTAL LEVY,PM57				EX00015	0.00	0.00	0.00		
PM57	XQ26AV	00030070	8/31/2020	GEN	39	ROUNDING	NABQAN01	EX00015399	ROUNDING,PM57				EX00015	0.00	0.00	0.00		

PM57	XQ26AV	00030070	8/31/2020	GEN	Repaired By: MACKAY TRUCK PARTS & REPAIRS 31/08/2020.						
					BREAKDOWN 30/08/2020 - TRUCK WONT START OR RUN: TRAVELLED TO PAGET, CONNECTED LAPTOP, FOUND NO ACTIVE OR INACTIVE FAULT CODES. JACKED OVER CAB & CHECKED WIRING HARNESS, UNABLE TO FIND ANY LOOSE OR BROKEN CONNECTIONS. CHECKED BATTERY TERMINALS & FUSES, ALL OK. DISCONNECTED BATTERIES & RECONNECTED, TRUCK STARTED, RAN OK. WENT TO TURN VEHICLE OFF, WOULD NOT TURN OFF. INSPECTED & FOUND TURBO TIMER FAULTY. REMOVED DASH, FOUND TRUCK CONNECTION INTO TURBO TIMER UNPLUGGED, MADE UP WIRE AND BRIDGE OUT THE BOTTOM 2 WIRES ON PLUG, TAPPED IT IN SO VEHICLE WOULD TURN OFF WITH THE KEY. DID NOT HAVE PARTS IN STOCK. TRAVELLED HOME.						
PM57	XQ26AV	00030155	9/7/2020	DEFECT	DEFECT CLEARED BY JESSE 07/09/2020.						
					CARRIED OUT SERVICE. REPLACED ALL FILTERS & LET MOTOR RUN. DID NOT CUT OUT.						
					Defect Date: 06/09/2020. Reported By: JIMMY Defect #: 5848 Defect Deatails:- ICE PACK NOT WORKING. STARTS BUT WONT RUN.						
PM57	XQ26AV	00030155	9/7/2020	ECO	01 LABOUR MECH1 Labour	0.50	85.00	42.50			
PM57	XQ26AV	00030155	9/7/2020	ECO	SERVICE COMPLETED BY JESSE & BEN 07/09/2020.						
PM57	XQ26AV	00030155	9/7/2020	ECO	00 LABOUR APPREN Labour - Internal	0.50	85.00	42.50			
PM57	XQ26AV	00030155	9/7/2020	ECO	16 CON YAT Consumables		4.00	15.00	60.00		
PM57	XQ26AV	00030155	9/7/2020	ECO	06 ED0037300960 YAT Fuel Filter (Sleeper Air)		1.00	28.77	28.77		
PM57	XQ26AV	00030155	9/7/2020	ECO	06 0021751550 YAT Eco Oil Filter Cartridge		1.00	25.22	25.22		
PM57	XQ26AV	00030155	9/7/2020	ECO	06 ED2175254-S YAT AIR FILTER SLEEPER AIR		1.00	53.50	53.50		
PM57	XQ26AV	00030376	9/14/2020	CUMAE5	01 LABOUR Labour	0.00	0.00	0.00			
PM57	XQ26AV	00030376	9/14/2020	CUMAE5	SERVICE COMPLETED.						
PM57	XQ26AV	00030376	9/14/2020	CUMBE5	01 LABOUR MECH1 Labour	2.00	85.00	170.00			
PM57	XQ26AV	00030376	9/14/2020	CUMBE5	SERVICE COMPLETED BY SEAN + KEIRAN 14.09.2020						
PM57	XQ26AV	00030376	9/14/2020	CUMBE5	00 LABOUR APPREN Labour - Internal	2.00	85.00	170.00			
PM57	XQ26AV	00030376	9/14/2020	CUMBE5	16 CON YAT Consumables		5.00	15.00	75.00		
PM57	XQ26AV	00030376	9/14/2020	CUMBE5	06 MK13584 YAT MAINTENANCE KIT		1.00	91.95	91.95		
PM57	XQ26AV	00030376	9/14/2020	CUMBE5	06 FS36401 YAT Fuel Filter		1.00	18.91	18.91		
PM57	XQ26AV	00030376	9/14/2020	CUMBE5	40 3413005 YAT OIL 15W-40, CK 4/E9		50.00	3.54	177.00		
PM57	XQ26AV	00030376	9/14/2020	DEFECT	DEFECT CLEARED BY SEAN 14.09.2020						
					"COULDN'T FAULT"						
					Defect: 5850 Reported by: Jimmy						
					Window washer not working						

PM57	XQ26AV	00030376	9/14/2020	DEFECT	DEFECT CLEARED BY SEAN 14.09.2020										
					Defect: 5849 Reported by: Jimmy										
					"B" service										
PM57	XQ26AV	00030586	9/23/2020	GEN	39	P27-1187-002	BROHUR01	EX00015633	SWITCH- MIRROR MODULES,PM57			EX00015	0.00	125.70	0.00
PM57	XQ26AV	00030586	9/23/2020	GEN	39	P27-1187-002	BROHUR01	2010469	SWITCH- MIRROR MODULES,PM57			EX00015	1.00	125.70	125.70
PM57	XQ26AV	00030841	9/29/2020	CUMAE5	01	LABOUR MECH1	Labour		1.50	85.00	127.50				
PM57	XQ26AV	00030841	9/29/2020	CUMAE5	SERVICE COMPLETED BY JESSE 29.09.2020										
					DRIVER'S SIDE WINDSCREEN CHIPPED CHANGED WIPER BLADES CARRIED OUT "A" SERVICE										
PM57	XQ26AV	00030841	9/29/2020	CUMAE5	16	CON	YAT	Consumables		4.00	15.00	60.00			
PM57	XQ26AV	00030841	9/29/2020	CUMAE5	13	WW710R8-10	YAT	WIPER REFILL 8MM RUBBER BACKED		2.00	30.91	61.82			
PM57	XQ26AV	00031092	10/6/2020	GEN	39	CSP03002	CUMMIN01	EX00015903	Warranty Plus Cover, Cummins,PM57			EX00015	0.00	6,436.00	0.00
PM57	XQ26AV	00031092	10/6/2020	GEN	CUMMINS EXTENDED WARRANTY PURCHASED 06.10.2020										
					ESN: 80232968										
					5 YEARS 1,200,000 KM 18,000 HOURS 600,000 LITRES										
					COVERAGE END DATE 14.05.2025										
PM57	XQ26AV	00031092	10/6/2020	GEN	39	CSP03002	CUMMIN01	8718383	Warranty Plus Cover, Cummins,PM57			EX00015	1.00	6,436.00	6,436.00
PM57	XQ26AV	00031292	10/12/2020	CUMAE5	01	LABOUR MECH1	Labour - Internal		1.00	85.00	85.00				
PM57	XQ26AV	00031292	10/12/2020	CUMAE5	SERVICE COMPLETED BY MICK & KEIRAN 12.10.2020										
					REPLACED ALL 4 BATTERIES REPLACED AIRBAG ON REAR AXLE (FRONT RHS) ADJUSTED & LUBRICATED RIDE HEIGHT VALVES										
PM57	XQ26AV	00031292	10/12/2020	CUMAE5	00	LABOUR APPREN	Labour - Internal		2.50	85.00	212.50				
PM57	XQ26AV	00031292	10/12/2020	CUMAE5	16	CON	YAT	Consumables		5.00	15.00	75.00			
PM57	XQ26AV	00031292	10/12/2020	CUMAE5	14	MF70ZZDT	YAT	BATTERY DEEP CYCLE & TRUCK		4.00	155.19	620.76			
PM57	XQ26AV	00031292	10/12/2020	CUMAE5	10	C81-1005	YAT	Air Bag, Drive K200		1.00	381.71	381.71			
PM57	XQ26AV	00031293	10/12/2020	ECO	01	LABOUR APPREN	Labour - Internal		0.75	85.00	63.75				
PM57	XQ26AV	00031293	10/12/2020	ECO	SERVICE COMPLETED BY KEIRAN 12.10.2020.										
					CLEANED INJECTOR. FITTED 2 X VENTS IN CAB										
PM57	XQ26AV	00031293	10/12/2020	ECO	16	CON	YAT	Consumables		4.00	15.00	60.00			
PM57	XQ26AV	00031293	10/12/2020	ECO	06	ED002175254-S	YAT	Air Filter Sleeper Air		1.00	53.50	53.50			
PM57	XQ26AV	00031293	10/12/2020	ECO	40	10W50	YAT	HITECH SYNPLUS 10W50		1.00	9.25	9.25			
PM57	XQ26AV	00031803	10/27/2020	CUMAE5	01	LABOUR MECH1	Labour		1.50	85.00	127.50				

PM57	XQ26AV	00031803	10/27/2020	CUMAE5	SERVICE COMPLETED.						
					REPAIRED GRILL						
					TOPPED UP OIL IN SLEEPER AIR						
PM57	XQ26AV	00031803	10/27/2020	CUMAE5	INDICTOR STALK NEEDS REPLACING						
PM57	XQ26AV	00031803	10/27/2020	CUMAE5	00 LABOUR APPREN Labour - Internal	1.50	85.00	127.50			
PM57	XQ26AV	00031803	10/27/2020	DEFECT	16 CON YAT Consumables		5.00	15.00	75.00		
					DEFECT CLEARED.						
					DEFECT CLEARED BY SEAN 27/10/20						
					#04351						
					REPORTED BY - JIMMY						
					WINDOW WASHER NEEDS FIXING ITS NOT WORKING CANNOT SEE AT NIGHT WHEN CAR LIGHTS ARE						
PM57	XQ26AV	00031803	10/27/2020	DEFECT	COMING AT ME						
					DEFECT CLEARED BY SEAN 27/10/20						
					#04352						
					REPORTED BY JIMMY						
PM57	XQ26AV	00031803	10/27/2020	DEFECT	ICE PACK KEEPS STOPPING						
					DEFECT CLEARED BY SEAN 27/10/20						
					#04353						
					REPORTED BY JIMMY						
PM57	XQ26AV	00031978	11/2/2020	GEN	A SERVICE DUE						
PM57	XQ26AV	00031978	11/2/2020	GEN	39 LABOUR APPREN Labour	1.00	85.00	85.00			
					REPAIR COMPLETED BY KEIRAN 02/11/20						
					PRESSURE CHECKED SYSTEM						
					LEAKY HOSE ON HEATER CORE						
PM57	XQ26AV	00031978	11/2/2020	GEN	TIGHTENED HOSE CLAMP						
PM57	XQ26AV	00032197	11/9/2020	CUMAE5	16 CON YAT Consumables		2.00	15.00	30.00		
PM57	XQ26AV	00032197	11/9/2020	CUMAE5	01 LABOUR Labour	0.00	0.00	0.00			
PM57	XQ26AV	00032197	11/9/2020	CUMBE5	SERVICE COMPLETED.						
PM57	XQ26AV	00032197	11/9/2020	CUMBE5	00 LABOUR MECH1 Labour	2.00	85.00	170.00			
PM57	XQ26AV	00032197	11/9/2020	CUMBE5	SERVICE COMPLETED.						
					FITTED NEW EBS PLUG						
					REPLACED FAULTY INDICATOR STALK						
					REPLACED RHS INNER HIGH BEAM BULB						
PM57	XQ26AV	00032197	11/9/2020	CUMBE5	REPLACED RHS AERIAL						
PM57	XQ26AV	00032197	11/9/2020	CUMBE5	00 LABOUR APPREN Labour - Internal	1.00	85.00	85.00			
PM57	XQ26AV	00032197	11/9/2020	CUMBE5	16 CON YAT Consumables		5.00	15.00	75.00		
PM57	XQ26AV	00032197	11/9/2020	CUMBE5	14 82196 YAT EBS Plug, 7 pin 12/24v		1.00	42.39	42.39		

PM57	XQ26AV	00032197	11/9/2020	CUMBE5	14	2026LED	YAT	LED Side Indicator	1.00	18.05	18.05
PM57	XQ26AV	00032197	11/9/2020	CUMBE5	06	MK13584	YAT	MAINTENANCE KIT	1.00	91.95	91.95
PM57	XQ26AV	00032197	11/9/2020	CUMBE5	40	3413005	YAT	OIL 15W-40, CK 4/E9	48.00	7.24	347.52
PM57	XQ26AV	00032197	11/9/2020	DEFECT	Reported Defect :- Defect Code : 00005318 Defect Reference : 04354 Date : 08/11/2020 Description of Defect : B SERVICE DUE						
PM57	XQ26AV	00032197	11/9/2020	DEFECT	DEFECT CLEARED BY SEAN Reported Defect :- Defect Code : 00005319 Defect Reference : 04355 Date : 08/11/2020 Description of Defect : ABS PLUG MISSING						
PM57	XQ26AV	00032197	11/9/2020	DEFECT	DEFECT CLEARED BY SEAN Reported Defect :- Defect Code : 00005320 Defect Reference : 04356 Date : 08/11/2020 Description of Defect : WINDOW WASHER NOT WORKING						
PM57	XQ26AV	00032197	11/9/2020	DEFECT	DEFECT CLEARED BY SEAN Reported Defect :- Defect Code : 00005321 Defect Reference : 04356 Date : 08/11/2020 Description of Defect : UHF AERIAL BROKEN						
PM57	XQ26AV	00032609	11/23/2020	CUMAE5	DEFECT CLEARED BY SEAN						
PM57	XQ26AV	00032609	11/23/2020	CUMAE5	00	LABOUR MECH1	Labour		4.00	85.00	340.00
					SERVICE COMPLETED BY SEAN						
					REPLACED A/C FAN						
					REPLACED LHS STEER HUBSEAL, CLEANED BEARINGS, BRAKES, HUBS AND FITTED NEW OIL						
PM57	XQ26AV	00032609	11/23/2020	CUMAE5	16	CON	YAT	Consumables	5.00	15.00	75.00
PM57	XQ26AV	00032609	11/23/2020	CUMAE5	06	25189003	YAT	FAN BLOWER ASSEMBLY, K200	1.00	392.60	392.60
PM57	XQ26AV	00032609	11/23/2020	CUMAE5	11	4373003501	YAT	HUB SEAL- SAF	1.00	31.35	31.35
PM57	XQ26AV	00032609	11/23/2020	CUMAE5	06	TRPCAF0001	YAT	TRP KW CAB AIR FILTER	1.00	21.78	21.78

PM57	XQ26AV	00032609	11/23/2020	DEFECT	Reported Defect :- Defect Code : 00005430 Defect Reference : 04358 Date : 22/11/2020 Description of Defect : A SERVICE OVER DUE								
PM57	XQ26AV	00032609	11/23/2020	DEFECT	DEFECT CLEARED BY SEAN Reported Defect :- Defect Code : 00005431 Defect Reference : 04359 Date : 22/11/2020 Description of Defect : AIRCON NOT WORKING, FAN WON'T START								
PM57	XQ26AV	00032609	11/23/2020	DEFECT	DEFECT CLEARED BY SEAN Reported Defect :- Defect Code : 00005433 Defect Reference : 04357 Date : 10/11/2020 Description of Defect : ELECTRICAL ISSUE, LIGHTS DIM AND GO BRIGHT WITH HAZZARDS ON AND IN TRAVEL AS WELL								
PM57	XQ26AV	00032614	11/23/2020	GEN	DEFECT CLEARED BY SEAN								
PM57	XQ26AV	00032614	11/23/2020	GEN	39	202-841	BROHUR01	EX00016680	Wiper Control Stalk,PM57	EX00016	0.00	352.00	0.00
					39	25189003	BROHUR01	EX00016680	FAN BLOWER ASSEMBLY, K200,PM57	EX00016	0.00	392.60	0.00
PM57	XQ26AV	00032614	11/23/2020	GEN	39	25189011	BROHUR01	EX00016680	Air Filter-Cabin,PM57	EX00016	0.00	44.96	0.00
PM57	XQ26AV	00032614	11/23/2020	GEN	39	25189011	BROHUR01	2056516	Air Filter-Cabin,PM57	EX00016	6.00	44.96	269.76
PM57	XQ26AV	00032614	11/23/2020	GEN	39	25189003	BROHUR01	2056516	FAN BLOWER ASSEMBLY, K200,PM57	EX00016	1.00	392.60	392.60
PM57	XQ26AV	00032614	11/23/2020	GEN	39	202-841	BROHUR01	2056516	Wiper Control Stalk,PM57	EX00016	1.00	352.00	352.00
PM57	XQ26AV	00032950	12/4/2020	GEN	90	CSP03002	CUMMIN01	EX00016854	Warranty Plus Cover, Cummins,PM57	EX00016	0.00	6,436.00	0.00
PM57	XQ26AV	00032950	12/4/2020	GEN	90	CSP03002	CUMMIN01	0815729	Warranty Plus Cover, Cummins,PM57	EX00016	-1.00	6,436.00	-6,436.00
PM57	XQ26AV	00032868	12/7/2020	CUMAE5	00	LABOUR APPREN	Labour		2.00	85.00	170.00		
PM57	XQ26AV	00032868	12/7/2020	CUMAE5	SERVICE COMPLETED BY KEIRAN/BEN								
					REPLACED RH REAR SHOCK ABSORBER AS IT HAD SNAPPED REPLACED RH REAR TORQUE ROD BUSHES REWIRED NUMBER PLATE LIGHT AS THERE WAS NO POWER REPLACED GEARSTICK RUBBER BOOT TOPPED UP COOLANT BOTTLE (GREEN) COMPLETED SLEEPER AIR SERVICE								
PM57	XQ26AV	00032868	12/7/2020	CUMAE5	00	LABOUR APPREN	Labour - Internal		2.00	85.00	170.00		
PM57	XQ26AV	00032868	12/7/2020	CUMAE5	16	CON	YAT	Consumables		4.00	15.00	60.00	
PM57	XQ26AV	00032868	12/7/2020	CUMAE5	12	M85902	YAT	Shocky Drv. (Meritor) K'worth		1.00	92.73	92.73	
PM57	XQ26AV	00032868	12/7/2020	CUMAE5	11	839310	YAT	Torque Rod Bush		2.00	86.32	172.64	

PM57	XQ26AV	00032868	12/7/2020	DEFECT	Reported Defect :- Defect Code : 00005519 Defect Reference : 04363 Date : 06/12/2020 Description of Defect : RUBBER GEAR SHIFT BOOT IS RIPPED, FUMES AND HOT AIR FROM MOTOR GETTING INTO CAB									
PM57	XQ26AV	00032868	12/7/2020	DEFECT	DEFECT CLEARED BY MICK Reported Defect :- Defect Code : 00005520 Defect Reference : 04364 Date : 06/12/2020 Description of Defect : WINDOW WASHER NEEDS REPAIRING, DOESNT WORK AT ALL. CANT SEE OUT WINDOWS WHEN COVERED IN BUGS AND STUFF									
PM57	XQ26AV	00032868	12/7/2020	DEFECT	COULD NOT FAULT DEFECT CLEARED BY MICK Reported Defect :- Defect Code : 00005521 Defect Reference : 04361 Date : 06/12/2020 Description of Defect : A SERVICE DUE COOLANT BOTTLE EMPTY USED 10 L									
PM57	XQ26AV	00032868	12/7/2020	DEFECT	COOLANT OVER FULL DEFECT CLEARED BY MICK Reported Defect :- Defect Code : 00005522 Defect Reference : 04362 Date : 06/12/2020 Description of Defect : ICE PACK STOP STARTING									
PM57	XQ26AV	00032868	12/7/2020	ECO	DEFECT CLEARED BY MICK 00 LABOUR APPREN Labour 0.25 85.00 21.25									
PM57	XQ26AV	00032868	12/7/2020	ECO	SERVICE COMPLETED BY BEN									
PM57	XQ26AV	00032868	12/7/2020	ECO	16	CON	YAT	Consumables		1.00	15.00	15.00		
PM57	XQ26AV	00032868	12/7/2020	ECO	06	ED2175254-S	YAT	AIR FILTER SLEEPER AIR		1.00	53.50	53.50		
PM57	XQ26AV	00032868	12/7/2020	ECO	40	10W50	YAT	HITECH SYNPLUS 10W50		1.00	9.25	9.25		
PM57	XQ26AV	00032969	12/7/2020	TYRSTE	15	33000520	BRIAUS01	EX00016872	REMOVAL: IRR WEAR OR ALIGNMENT, ODO 1536127	EX00016	0.00	0.00	0.00	
PM57	XQ26AV	00032969	12/7/2020	TYRSTE	15	77000194	BRIAUS01	EX00016872	case stock 295/80-22.5, ODO 1536127	EX00016	0.00	20.00	0.00	
PM57	XQ26AV	00032969	12/7/2020	TYRSTE	15	11001553	BRIAUS01	EX00016872	TYRE 295/80R22.5 152/148M BS R150, ODO 1536127	EX00016	0.00	0.00	0.00	
PM57	XQ26AV	00032969	12/7/2020	TYRSTE	15	33000084	BRIAUS01	EX00016872	FIT TBR TYRE, ODO 1536127	EX00016	0.00	0.00	0.00	
PM57	XQ26AV	00032969	12/7/2020	TYRSTE	15	33000084	BRIAUS01	85039944	FIT TBR TYRE, ODO 1536127	EX00016	2.00	0.00	0.00	
PM57	XQ26AV	00032969	12/7/2020	TYRSTE	15	11001553	BRIAUS01	85039944	TYRE 295/80R22.5 152/148M BS R150, ODO 1536127	EX00016	1.00	0.00	0.00	

PM57	XQ26AV	00032969	12/7/2020	TYRSTE	15	77000194	BRIAUS01	85039944	case stock 295/80-22.5, ODO 1536127	EX00016	-2.00	20.00	-40.00
PM57	XQ26AV	00032969	12/7/2020	TYRSTE	15	33000520	BRIAUS01	85039944	REMOVAL: IRR WEAR OR ALIGNMENT, ODO 1536127	EX00016	2.00	0.00	0.00
PM57	XQ26AV	00033696	12/10/2020	GEN	39	LAB	BROHUR01	EX00017276	Labour,XQ26AV	EX00017	0.00	181.25	0.00
PM57	XQ26AV	00033696	12/10/2020	GEN	39	CON	BROHUR01	EX00017276	Consumables ,PM57	EX00017	0.00	5.00	0.00
PM57	XQ26AV	00033696	12/10/2020	GEN	39	ENVLEV	BROHUR01	EX00017276	ENVIRONMENTAL LEVY,PM57	EX00017	0.00	5.00	0.00
PM57	XQ26AV	00033696	12/10/2020	GEN	39	ENVLEV	BROHUR01	2071797	ENVIRONMENTAL LEVY,PM57	EX00017	1.00	5.00	5.00
PM57	XQ26AV	00033696	12/10/2020	GEN	39	CON	BROHUR01	2071797	Consumables ,PM57	EX00017	1.00	5.00	5.00
PM57	XQ26AV	00033696	12/10/2020	GEN	39	LAB	BROHUR01	2071797	Labour,XQ26AV	EX00017	1.00	181.25	181.25
PM57	XQ26AV	00033110	12/14/2020	DEFECT					Reported Defect :- Defect Code : 00005581 Defect Reference : 04367 Date : 13/12/2020 Description of Defect : TRAILER PLUG HAS BROKEN PIN				
PM57	XQ26AV	00033110	12/14/2020	GEN					DEFECT CLEARED BY MICK 00				
PM57	XQ26AV	00033110	12/14/2020	GEN					LABOUR APPREN Labour 0.50 85.00 42.50				
PM57	XQ26AV	00033110	12/14/2020	GEN					REPAIR COMPLETED BY BEN				
PM57	XQ26AV	00033110	12/14/2020	GEN					REPLACED TRAILER ELECTRICAL PLUG ON BACK OF TRUCK 16				
PM57	XQ26AV	00033160	12/16/2020	GEN	39	CON	YAT	Consumables			3.00	15.00	45.00
PM57	XQ26AV	00033160	12/16/2020	GEN	39	PART	BROHUR01	EX00016982	GENERAL PART CODE,PM57	EX00016	0.00	44.96	0.00
PM57	XQ26AV	00033160	12/16/2020	GEN	39	PART	BROHUR01	2076098	GENERAL PART CODE,PM57	EX00016	-6.00	44.96	-269.76
PM57	XQ26AV	00033248	12/21/2020	CUMAE5	00	LABOUR	MECH1	Labour	2.50 85.00 212.50				
PM57	XQ26AV	00033248	12/21/2020	CUMAE5					SERVICE COMPLETED SEAN AND KEIRAN				
PM57	XQ26AV	00033248	12/21/2020	CUMAE5					ADJUSTED CLUTCH				
PM57	XQ26AV	00033248	12/21/2020	CUMAE5					REPLACED BROKEN SHOCK IN SEAT				
PM57	XQ26AV	00033248	12/21/2020	CUMAE5					*CHECK ON ICE PACK ON B SERVICE 00				
PM57	XQ26AV	00033248	12/21/2020	CUMAE5	16	CON	YAT	Consumables	1.00 85.00 85.00				
PM57	XQ26AV	00033248	12/21/2020	DEFECT					4.00 15.00 60.00				
									Reported Defect :- Defect Code : 00005625 Defect Reference : 04368 Date : 20/12/2020 Description of Defect : A SERVICE OVER DUE ICE PACK NEEDS SERVICE				
									DEFECT CLEARED BY SEAN				

PM57	XQ26AV	00033248	12/21/2020	DEFECT	Reported Defect :- Defect Code : 00005626 Defect Reference : 04369 Date : 20/12/2020 Description of Defect : DRIVERS SEAT IS BROKEN, WHEN YOU GO OVER ANY BUMPS IT JUST GOES STRAIGHT TO THE FLOOR				DEFECT CLEARED BY SEAN			
PM57	XQ26AV	00033333	12/29/2020	DEFECT	Reported Defect :- Defect Code : 00005627 Defect Reference : WO33248 Date : 22/12/2020 Description of Defect : CHECK ON ICE PACK ON B SERVICE				DEFECT CLEARED BY MICK			
PM57	XQ26AV	00033333	12/29/2020	ECO	00	LABOUR APPREN	Labour		0.75	85.00	63.75	
PM57	XQ26AV	00033333	12/29/2020	ECO	SERVICE COMPLETED BY BEN							
PM57	XQ26AV	00033333	12/29/2020	ECO	16	CON	YAT	Consumables		1.00	15.00	15.00
PM57	XQ26AV	00033333	12/29/2020	ECO	06	ED2175254-S	YAT	AIR FILTER SLEEPER AIR		1.00	53.50	53.50
PM57	XQ26AV	00033333	12/29/2020	ECO	40	10W50	YAT	HITECH SYNPLUS 10W50		1.00	9.25	9.25
PM57	XQ26AV	00033333	12/29/2020	GEN	00	LABOUR APPREN	Labour		0.50	85.00	42.50	
PM57	XQ26AV	00033333	12/29/2020	GEN	REPAIR COMPLETED BY BEN							
PM57	XQ26AV	00033333	12/29/2020	GEN	REPLACED RHS REAR AIRBAG							
PM57	XQ26AV	00033333	12/29/2020	GEN	00	LABOUR MECH1	Labour - Internal		0.50	85.00	42.50	
PM57	XQ26AV	00033594	1/11/2021	CUMAE5	16	CON	YAT	Consumables		2.00	15.00	30.00
PM57	XQ26AV	00033594	1/11/2021	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00	
PM57	XQ26AV	00033594	1/11/2021	CUMBE5	SERVICE COMPLETED.							
PM57	XQ26AV	00033594	1/11/2021	CUMBE5	00	LABOUR MECH1	Labour		2.00	85.00	170.00	
PM57	XQ26AV	00033594	1/11/2021	CUMBE5	REPLACED WIPER BLADES							
PM57	XQ26AV	00033594	1/11/2021	CUMBE5	LOAD TESTED BATTERIES							
PM57	XQ26AV	00033594	1/11/2021	CUMBE5	REPLACED LOAD LIGHT SWITCH							
PM57	XQ26AV	00033594	1/11/2021	CUMBE5	00	LABOUR APPREN	Labour - Internal		2.00	85.00	170.00	
PM57	XQ26AV	00033594	1/11/2021	CUMBE5	16	CON	YAT	Consumables		4.00	15.00	60.00
PM57	XQ26AV	00033594	1/11/2021	CUMBE5	06	MK13584	YAT	MAINTENANCE KIT		1.00	91.95	91.95
PM57	XQ26AV	00033594	1/11/2021	CUMBE5	06	FS19764	YAT	Element 10 Micron		1.00	28.18	28.18
PM57	XQ26AV	00033594	1/11/2021	CUMBE5	40	3413005	YAT	OIL 15W-40, CK 4/E9		48.00	5.15	247.20
PM57	XQ26AV	00033594	1/11/2021	CUMBE5	11	WW600B8B	YAT	WIPER BLADE 600x8mm B-FIX		2.00	21.77	43.54
PM57	XQ26AV	00033594	1/11/2021	CUMBE5	14	P27-1084-016	YAT	SWITCH-ROCKER LOADING LIGHT		1.00	67.78	67.78

PM57	XQ26AV	00033594	1/11/2021	DEFECT	Reported Defect :- Defect Code : 00005730 Defect Reference : 04373 Date : 11/01/2021 Description of Defect : 4K OVER FOR B SWRVCE NEW WIPER BLADES DRIVERS SIDE WORK LIGHT NOT WORKING				
PM57	XQ26AV	00033896	1/18/2021	WEICAL	DEFFECT CLEARED BY SEAN AIR GAUGE: 11100 ADJUSTED: 16900 WEIGHBRIDGE: 16410				
PM57	XQ26AV	00033914	1/18/2021	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. AIR GAUGE: 14700 ADJUSTED: 15250 WEIGHBRIDGE: 14750				
PM57	XQ26AV	00034029	1/22/2021	CUMCE5	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. 00 LABOUR MECH1 Labour	4.00	85.00	340.00	
PM57	XQ26AV	00034029	1/22/2021	CUMCE5	SERVICE COMPLETED BY SEAN AND KEIRAN				
					REMOVED POWER DIVIDER AND REPLACED THRUST WASHER AND O RINGS REPLACED UNI JOINT REAR OF FRONT DRIVE SHAFT REPLACED BLWN BULBS IN DASH REPLACED LHS HIGHBEAM BULB				
PM57	XQ26AV	00034029	1/22/2021	CUMCE5	00 LABOUR APPREN	4.00	85.00	340.00	
PM57	XQ26AV	00034029	1/22/2021	CUMCE5	16 CON YAT Consumables		6.00	15.00	90.00
PM57	XQ26AV	00034029	1/22/2021	CUMCE5	06 WF2127 YAT ES Water Filter		1.00	42.07	42.07
PM57	XQ26AV	00034029	1/22/2021	CUMCE5	06 LF637 YAT Power Steer Filter LF637		1.00	27.02	27.02
PM57	XQ26AV	00034029	1/22/2021	CUMCE5	06 A-3380W1687 YAT DIFF FILTER		1.00	19.71	19.71
PM57	XQ26AV	00034029	1/22/2021	CUMCE5	06 T224P YAT Turbo 2000 Air dryer		1.00	169.25	169.25
PM57	XQ26AV	00034029	1/22/2021	CUMCE5	06 TRPCAF0001 YAT TRP KW CAB AIR FILTER		1.00	21.78	21.78
PM57	XQ26AV	00034029	1/22/2021	CUMCE5	06 17237 YAT Filter Element Gearbox Eaton		1.00	31.31	31.31
PM57	XQ26AV	00034029	1/22/2021	CUMCE5	40 3334800 YAT Diff/Gear Oil 80W90 Castrol		33.00	6.96	229.68
PM57	XQ26AV	00034029	1/22/2021	CUMCE5	40 3372765 YAT Syntrans Gear Oil 75w-90		12.00	13.61	163.32
PM57	XQ26AV	00034029	1/22/2021	CUMCE5	11 5X1327 YAT O RING		2.00	12.31	24.62
PM57	XQ26AV	00034029	1/22/2021	CUMCE5	11 5.281X YAT 1810 Uni Joint Spicer FR		1.00	82.73	82.73
PM57	XQ26AV	00034029	1/22/2021	DEFECT	01 LABOUR MECH Labour	0.00	0.00	0.00	
PM57	XQ26AV	00034029	1/22/2021	DEFECT	DEFECT CLEARED.				
PM57	XQ26AV	00034029	1/22/2021	DEFECT	00 LABOUR MECH1 Labour	1.00	85.00	85.00	
PM57	XQ26AV	00034029	1/22/2021	EXOINS					

PM57	XQ26AV	00034029	1/22/2021	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1									
PM57	XQ26AV	00034441	2/8/2021	WEICAL	INSPECTION COMPLETED BY SEAN AIR GAUGE: 14500 ADJUSTED: 14555 WEIGHBRIDGE: 14230									
PM57	XQ26AV	00034559	2/9/2021	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. AIR GAUGE: 17000 ADJUSTED: 17500 WEIGHBRIDGE: 17000									
PM57	XQ26AV	00034624	2/15/2021	CUMAE5	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. 00 LABOUR APPREN Labour 1.00 85.00 85.00									
PM57	XQ26AV	00034624	2/15/2021	CUMAE5	SERVICE COMPLETED BY KEIRAN									
PM57	XQ26AV	00034624	2/15/2021	CUMAE5	16 CON YAT Consumables 3.00 15.00 45.00									
PM57	XQ26AV	00034624	2/15/2021	DEFECT	Reported Defect :- Defect Code : 00005908 Defect Reference : 04375 Date : 14/02/2021 Description of Defect : A SERVICE PAST DUE									
PM57	XQ26AV	00034624	2/15/2021	DEFECT	DEFECT CLEARED BY SEAN Reported Defect :- Defect Code : 00005909 Defect Reference : 04376 Date : 14/02/2021 Description of Defect : ICE PACK NEEDS SERVICE KEEPS STOPPING, BLOWING WARM AIR									
PM57	XQ26AV	00034624	2/15/2021	ECO	DEFECT CLEARED BY SEAN 00 LABOUR MECH1 Labour 1.50 85.00 127.50									
PM57	XQ26AV	00034624	2/15/2021	ECO	SERVICE COMPLETED SEAN									
PM57	XQ26AV	00034624	2/15/2021	ECO	CLEANED INJECTOR REPLACED BELTS									
PM57	XQ26AV	00034624	2/15/2021	ECO	16 CON YAT Consumables 5.00 15.00 75.00									
PM57	XQ26AV	00034624	2/15/2021	ECO	40 3413005 YAT OIL 15W-40, CK 4/E9 1.00 6.90 6.90									
PM57	XQ26AV	00034624	2/15/2021	ECO	06 ED2175254-S YAT AIR FILTER SLEEPER AIR 1.00 53.50 53.50									
PM57	XQ26AV	00034624	2/15/2021	ECO	11 78-629 YAT BELT 2.00 69.42 138.84									
PM57	XQ26AV	00035006	2/19/2021	GEN	39 LAB BDSMEC01 EX00017834 Labour,XQ26AV EX00017 0.00 95.00 0.00									
PM57	XQ26AV	00035006	2/19/2021	GEN	39 LAB BDSMEC01 00050324 Labour,XQ26AV EX00017 1.00 95.00 95.00									
PM57	XQ26AV	00035559	3/8/2021	CUMAE5	00 LABOUR APPREN Labour 1.50 85.00 127.50									

PM57	XQ26AV	00035559	3/8/2021	CUMAE5	SERVICE COMPLETED BY BEN AND MICK					
					TENSIONED VERY LOOSE BELLY BAR BOLTS					
					TENSIONED TRAILER LIGHT PLUG PINS					
PM57	XQ26AV	00035559	3/8/2021	CUMAE5	00 LABOUR MECH Labour - Internal	1.50	85.00	127.50		
PM57	XQ26AV	00035559	3/8/2021	CUMAE5	16 CON YAT Consumables		4.00	15.00	60.00	
PM57	XQ26AV	00035559	3/8/2021	DEFECT	Reported Defect :- Defect Code : 00006033 Defect Reference : 04378 Date : 06/03/2021 Description of Defect : ICE PACK KEEPS STOPPING					
					DEFECT CLEARED BY SEAN 08.03.21					
PM57	XQ26AV	00035559	3/8/2021	DEFECT	Reported Defect :- Defect Code : 00006034 Defect Reference : 04379 Date : 06/03/2021 Description of Defect : TRAILER LIGHT PLUG NEEDS FIXING KEEPS SHORTING OUT FUSE AND PINS ARE LOSE					
					DEFECT CLEARED BY SEAN 08.03.21					
PM57	XQ26AV	00035774	3/15/2021	GEN	00 LABOUR MECH Labour	0.75	85.00	63.75		
PM57	XQ26AV	00035774	3/15/2021	GEN	REPAIR COMPLETED. BY MICK					
					REPLACED WIPER BLADES					
					REPAIRED WASHERS					
PM57	XQ26AV	00035774	3/15/2021	GEN	16 CON YAT Consumables			4.00	15.00	60.00
PM57	XQ26AV	00036066	3/22/2021	CUMAE5	01 LABOUR Labour	0.00	0.00	0.00		
PM57	XQ26AV	00036066	3/22/2021	CUMAE5	SERVICE COMPLETED.					
PM57	XQ26AV	00036066	3/22/2021	CUMBE5	00 LABOUR APPREN Labour	1.00	85.00	85.00		
PM57	XQ26AV	00036066	3/22/2021	CUMBE5	SERVICE COMPLETED BY KEIRAN AND BEN					
PM57	XQ26AV	00036066	3/22/2021	CUMBE5	00 LABOUR APPREN 1.00 85.00 85.00					
PM57	XQ26AV	00036066	3/22/2021	CUMBE5	16 CON YAT Consumables			4.00	15.00	60.00
PM57	XQ26AV	00036066	3/22/2021	CUMBE5	06 MK13584 YAT MAINTENANCE KIT			1.00	97.85	97.85
PM57	XQ26AV	00036066	3/22/2021	CUMBE5	40 3413005 YAT OIL 15W-40, CK 4/E9			47.00	6.90	324.30
PM57	XQ26AV	00036066	3/22/2021	DEFECT	Reported Defect :- Defect Code : 00006139 Defect Reference : 04382 Date : 21/03/2021 Description of Defect : ICE PACK NOT WORKING WON'T START AT ALL/NORMAL ENGINE OIL USED IN IT, RUN FOR 1 1/2 TIMES THEN STOPPED					
					DEFECT CLEARED BY SEAN 22.03.21					

PM57	XQ26AV	00036066	3/22/2021	DEFECT	Reported Defect :- Defect Code : 00006140 Defect Reference : 04381 Date : 21/03/2021 Description of Defect : B SERVICE DUE											
PM57	XQ26AV	00036066	3/22/2021	ECO	DEFECT CLEARED BY SEAN 22.03.21											
PM57	XQ26AV	00036066	3/22/2021	ECO	00	LABOUR	APPREN	Labour	0.75	85.00	63.75					
PM57	XQ26AV	00036066	3/22/2021	ECO	SERVICE COMPLETED BY BEN											
PM57	XQ26AV	00036066	3/22/2021	ECO	16	CON	YAT	Consumables		3.00	15.00	45.00				
PM57	XQ26AV	00036066	3/22/2021	ECO	40	3413005	YAT	OIL 15W-40, CK 4/E9		1.00	6.90	6.90				
PM57	XQ26AV	00036378	3/30/2021	DEFECT	Reported Defect :- Defect Code : 00006168 Defect Reference : 04385 Date : 29/03/2021 Description of Defect : ENG OIL TEMP NOT WORKING AFTER TREATMENT LIGHT BEEN ON ALL DAY											
PM57	XQ26AV	00036378	3/30/2021	DEFECT	DEFECT CLEARED BY SEAN 30.03.21											
					Reported Defect :- Defect Code : 00006169 Defect Reference : 04384 Date : 27/03/2021 Description of Defect : SPOT LIGHTS KEEP GOING OUT, FUSE IS OK/THEY COME AND GO OUT ALL THE TIME, PS NOT WORKING AT ALL NOW											
PM57	XQ26AV	00036378	3/30/2021	GEN	DEFECT CLEARED BY SEAN 30.03.21											
PM57	XQ26AV	00036378	3/30/2021	GEN	00	LABOUR	APPREN	Labour	7.00	85.00	595.00					
					REPAIR COMPLETED BY KEIRAN											
					MULTIPLE AFTER TREAT CODES, HAD 9.7V AT THE PLUG, REMOVED WIRING, CLEANED ALL WATER FROM WIRING, RESEALED LOOM AND JOINS, DID NOT FIND ANY COROSION, REPLACED NOX SENSOR WITH SECOND HAND STOCK, LIGHT WENT OUT TRACED FOR POWER THROUGH ALL OF THE CIRCUIT, FOUND WIRES HAD BURNT OUT BEHIND FUSE, MOVED TO 4TH ACROSS 3RD UP COMPLETED FULL ADBLUE FLUSH PLUGGED ENGINE OIL TEMP PLUG BACK IN											
PM57	XQ26AV	00036378	3/30/2021	GEN	16	CON	YAT	Consumables		6.00	15.00	90.00				
PM57	XQ26AV	00036378	3/30/2021	GEN	06	5264404	YAT	Connector Kit for Ad Blue inline filter		1.00	70.32	70.32				
PM57	XQ26AV	00036470	4/1/2021	TYRES	15	77000194	BRIAUS01	EX00018415	case stock 295/80-22.5,PM57				EX00018	0.00	20.00	0.00
PM57	XQ26AV	00036470	4/1/2021	TYRES	15	33000051	BRIAUS01	EX00018415	BALANCE TBR,PM57				EX00018	0.00	30.00	0.00
PM57	XQ26AV	00036470	4/1/2021	TYRES	15	33000051	BRIAUS01	85651003	BALANCE TBR,PM57				EX00018	2.00	30.00	60.00
PM57	XQ26AV	00036470	4/1/2021	TYRES	15	77000194	BRIAUS01	85651003	case stock 295/80-22.5,PM57				EX00018	-2.00	20.00	-40.00
PM57	XQ26AV	00036438	4/6/2021	CUMAE5	00	LABOUR	APPREN	Labour	1.50	85.00	127.50					

PM57	XQ26AV	00036438	4/6/2021	CUMAE5	SERVICE COMPLETED BY KEIRAN										
					DRIVER STATES SLEEPER AIR IS USING OIL, DRAINED REMAINDER OF OIL, FLUSHED WITH ENGINE OIL, NOTICED OIL ABOVE STEM WHEN LOOKING THROUGH AIR FILTER, HAS A LOT OF BLOW BY										
PM57	XQ26AV	00036438	4/6/2021	CUMAE5	16	CON	YAT	Consumables	5.00	15.00	75.00				
PM57	XQ26AV	00036438	4/6/2021	CUMAE5	40	3413005	YAT	OIL 15W-40, CK 4/E9	2.00	3.54	7.08				
PM57	XQ26AV	00036798	4/13/2021	GEN	39	LAB	QUAWIND01	EX00018546	Labour,XQ26AV			EX00018	0.00	268.18	0.00
PM57	XQ26AV	00036798	4/13/2021	GEN	39	LAB	QUAWIND01	5230	Labour,XQ26AV			EX00018	1.00	268.18	268.18
PM57	XQ26AV	00037239	4/16/2021	GEN	39	PART	BRIAIR01	EX00018743	GENERAL PART CODE,XQ26AV			EX00018	0.00	69.64	0.00
PM57	XQ26AV	00037239	4/16/2021	GEN	39	PART	BRIAIR01	EX00018743	GENERAL PART CODE,XQ26AV			EX00018	0.00	4.27	0.00
PM57	XQ26AV	00037239	4/16/2021	GEN	39	PART	BRIAIR01	EX00018743	GENERAL PART CODE,XQ26AV			EX00018	0.00	45.30	0.00
PM57	XQ26AV	00037239	4/16/2021	GEN	39	FREIGHT	BRIAIR01	EX00018743	Freight ,XQ26AV			EX00018	0.00	16.00	0.00
PM57	XQ26AV	00037239	4/16/2021	GEN	39	FREIGHT	BRIAIR01	152407	Freight ,XQ26AV			EX00018	1.00	16.00	16.00
PM57	XQ26AV	00037239	4/16/2021	GEN	39	PART	BRIAIR01	152407	GENERAL PART CODE,XQ26AV			EX00018	1.00	45.30	45.30
PM57	XQ26AV	00037239	4/16/2021	GEN	39	PART	BRIAIR01	152407	GENERAL PART CODE,XQ26AV			EX00018	1.00	4.27	4.27
PM57	XQ26AV	00037239	4/16/2021	GEN	39	PART	BRIAIR01	152407	GENERAL PART CODE,XQ26AV			EX00018	1.00	69.64	69.64
PM57	XQ26AV	00037120	4/23/2021	CUMAE5	00	LABOUR MECH1	Labour		1.25	85.00	106.25				
PM57	XQ26AV	00037120	4/23/2021	CUMAE5	SERVICE COMPLETED BY RYAN AND MICK										
					TENSIONED LOOSE LHS UPPER SHOCKY (STEER)										
PM57	XQ26AV	00037120	4/23/2021	CUMAE5	00	LABOUR MECH	Labour - Internal		1.00	85.00	85.00				
PM57	XQ26AV	00037120	4/23/2021	CUMAE5	16	CON	YAT	Consumables		2.00	15.00	30.00			
PM57	XQ26AV	00037120	4/23/2021	CUMAE5	40	3413005	YAT	OIL 15W-40, CK 4/E9		1.00	3.54	3.54			
PM57	XQ26AV	00037120	4/23/2021	CUMAE5	11	WW600B8B	YAT	WIPER BLADE 600x8mm B-FIX		2.00	23.52	47.04			
PM57	XQ26AV	00037120	4/23/2021	DEFECT	Reported Defect :- Defect Code : 00006273 Defect Reference : 04387 Date : 22/04/2021 Description of Defect : A SERVICE OVER DUE										
					DEFECT CLEARED BY MICK 23.04.21										
PM57	XQ26AV	00037120	4/23/2021	DEFECT	Reported Defect :- Defect Code : 00006272 Defect Reference : 04388 Date : 22/04/2021 Description of Defect : NEW WIPER BLADES AND DRIVERS SIDE WASHER JET IS BLOCKED, ONLY WORKING ON BOTTOM HALF OF WINDSCREEN										
					DEFECT CLEARED BY MICK 23.04.21										
PM57	XQ26AV	00037120	4/23/2021	DEFECT	Reported Defect :- Defect Code : 00005041 Defect Reference : WO30841 Date : 29/09/2020 Description of Defect : DRIVER'S SIDE WINDSCREEN CHIPPED										

PM57	XQ26AV	00037355	5/4/2021	DEFECT	Reported Defect :- Defect Code : 00006325 Defect Reference : 04392 Date : 03/05/2021 Description of Defect : ENG OIL TEMP NOT WORKING AGAIN								
PM57	XQ26AV	00037355	5/4/2021	DEFECT	DEFECT CLEARED BY RYAN 04052021 Reported Defect :- Defect Code : 00006326 Defect Reference : 04391 Date : 03/05/2021 Description of Defect : AFTER TREAT ON FOR LAST 2 DAYS								
PM57	XQ26AV	00037355	5/4/2021	DEFECT	DEFECT CLEARED BY RYAN 04052021 Reported Defect :- Defect Code : 00006253 Defect Reference : 04382 Date : 21/03/2021 Description of Defect : ICE PACK NOT WORKING WON'T START AT ALL/NORMAL ENGINE OIL USED IN IT, RUN FOR 1 1/2 TIMES THEN STOPPED								
PM57	XQ26AV	00037453	5/4/2021	GEN	DEFECT CLEARED BY RYAN 04052021								
PM57	XQ26AV	00037355	5/4/2021	GEN	39	2894943RX	BROHUR01	EX00018873	NOX SENSOR, KENWORTH,XQ26AV	EX00018	0.00	819.09	0.00
PM57	XQ26AV	00037453	5/4/2021	GEN	00	LABOUR MECH1	Labour		5.00 85.00 425.00				
PM57	XQ26AV	00037453	5/4/2021	GEN	39	2872298D	BROHUR01	EX00018873	CORE CHARGE FOR NOX SENSOR.,PM57	EX00018	0.00	370.00	0.00
PM57	XQ26AV	00037355	5/4/2021	GEN	REPAIR COMPLETED BY RYAN NOTICED THAT THE ENGINE OIL TEMP SENSOR CABLE CONNECTOR WAS MISSING AND THE SENSOR WAS NOT SECURE ORDERED A NEW SENSOR AND CONNECTOR, REPLACED THE SENSOR AND CONNECTOR NOTICED THAT THE AFTER TREATMENT SENSOR WAS BROKEN, ORDERED A NEW SENSOR AND REPLACED IT NOTICED THAT THE SLEEPER AIR HOUR COUNTER WASN'T RESET, RESET THE COUNTER AND STARTED THE SLEEP ENGINE CHECKED THE OIL, EVERYTHING LOOKED AS IT SHOULD BE FOUND A BLOWN FUSE AND NOTICED THAT THE TRAILER PLUG WAS A LITTLE BIT WORN AND THE CABLES WERE A LITTLE BIT DAMAGED, CUT THE DAMAGED CABLE SETION AND ASSEMBLED A NEW 7 PIN PLUG								
PM57	XQ26AV	00037453	5/4/2021	GEN	39	2872298D	BROHUR01	2176563	CORE CHARGE FOR NOX SENSOR.,PM57	EX00018	1.00	370.00	370.00
PM57	XQ26AV	00037355	5/4/2021	GEN	16	CON	YAT Consumables		4.00 15.00 60.00				
PM57	XQ26AV	00037453	5/4/2021	GEN	39	2894943RX	BROHUR01	2176563	NOX SENSOR, KENWORTH,XQ26AV	EX00018	1.00	819.09	819.09
PM57	XQ26AV	00037355	5/4/2021	GEN	14	2894943RX	YAT	NOX SENSOR, KENWORTH	1.00 819.09 819.09				
PM57	XQ26AV	00037844	5/10/2021	GEN	39	P28-1048	BROHUR01	EX00019064	RADIO ALPINE AM/FM,XQ26AV	EX00019	0.00	287.44	0.00
PM57	XQ26AV	00037844	5/10/2021	GEN	39	P28-1048	BROHUR01	2180560	RADIO ALPINE AM/FM,XQ26AV	EX00019	1.00	287.44	287.44

PM57	XQ26AV	00037471	5/11/2021	GEN	39	LAB	BROHUR01	EX00018897	Labour,XQ26AV	EX00018	0.00	435.01	0.00
PM57	XQ26AV	00037471	5/11/2021	GEN	39	CON	BROHUR01	EX00018897	Consumables ,PM57	EX00018	0.00	5.00	0.00
PM57	XQ26AV	00037471	5/11/2021	GEN	39	ENVLEV	BROHUR01	EX00018897	ENVIRONMENTAL LEVY,PM57	EX00018	0.00	5.00	0.00
PM57	XQ26AV	00037471	5/11/2021	GEN	39	ENVLEV	BROHUR01	2181199	ENVIRONMENTAL LEVY,PM57	EX00018	1.00	5.00	5.00
PM57	XQ26AV	00037471	5/11/2021	GEN	39	CON	BROHUR01	2181199	Consumables ,PM57	EX00018	1.00	5.00	5.00
PM57	XQ26AV	00037471	5/11/2021	GEN	39	LAB	BROHUR01	2181199	Labour,XQ26AV	EX00018	1.00	435.01	435.01
PM57	XQ26AV	00037628	5/12/2021	TYRES	15	33000051	BRIAUS01	EX00018934	BALANCE TBR,PM57	EX00018	0.00	30.00	0.00
PM57	XQ26AV	00037628	5/12/2021	TYRES	15	33000051	BRIAUS01	85862496	BALANCE TBR,PM57	EX00018	2.00	30.00	60.00
PM57	XQ26AV	00037697	5/15/2021	GEN	39	PART	BROHUR01	EX00018981	GENERAL PART CODE 320.102,XQ26AV	EX00018	0.00	24.81	0.00
PM57	XQ26AV	00037697	5/15/2021	GEN	39	PART	BROHUR01	EX00018981	GENERAL PART CODE 0-0828905-1,XQ26AV	EX00018	0.00	0.38	0.00
PM57	XQ26AV	00037697	5/15/2021	GEN	39	PART	BROHUR01	EX00018981	GENERAL PART CODE 0-0925595-2,XQ26AV	EX00018	0.00	0.38	0.00
PM57	XQ26AV	00037697	5/15/2021	GEN	39	PART	BROHUR01	EX00018981	GENERAL PART CODE 963040-3,XQ26AV	EX00018	0.00	6.27	0.00
PM57	XQ26AV	00037697	5/15/2021	GEN	39	PART	BROHUR01	2185234	GENERAL PART CODE 963040-3,XQ26AV	EX00018	1.00	6.27	6.27
PM57	XQ26AV	00037697	5/15/2021	GEN	39	PART	BROHUR01	2185234	GENERAL PART CODE 0-0925595-2,XQ26AV	EX00018	2.00	0.38	0.76
PM57	XQ26AV	00037697	5/15/2021	GEN	39	PART	BROHUR01	2185234	GENERAL PART CODE 0-0828905-1,XQ26AV	EX00018	2.00	0.38	0.76
PM57	XQ26AV	00037697	5/15/2021	GEN	39	PART	BROHUR01	2185234	GENERAL PART CODE 320.102,XQ26AV	EX00018	1.00	24.81	24.81
PM57	XQ26AV	00037782	5/17/2021	GEN	39	LAB	ATHYD01	EX00019015	Labour,XQ26AV	EX00019	0.00	110.00	0.00
PM57	XQ26AV	00037782	5/17/2021	GEN	39	PART	ATHYD01	EX00019015	GENERAL PART CODE,XQ26AV	EX00019	0.00	48.26	0.00
PM57	XQ26AV	00037782	5/17/2021	GEN	39	PART	ATHYD01	00050155	GENERAL PART CODE,XQ26AV	EX00019	1.00	48.26	48.26
PM57	XQ26AV	00037782	5/17/2021	GEN	39	LAB	ATHYD01	00050155	Labour,XQ26AV	EX00019	2.50	110.00	275.00
PM57	XQ26AV	00037944	5/24/2021	CUMAE5	# TURN TABLE HEAD TO BE REPLACED ASAP								
FITTED NHVR STICKER													
CHECKED MOVEMENT IN STEERING WHEEL - NEEDS ONE STEERING COLUMN SHAFT													
SERVICE COMPLETED BY RYAN 24/05/2021													
PM57	XQ26AV	00037944	5/24/2021	CUMAE5	00	LABOUR MECH1	Labour - Internal		2.00	85.00	170.00		
PM57	XQ26AV	00037944	5/24/2021	CUMAE5	16	CON	YAT Consumables			3.00	15.00	45.00	
PM57	XQ26AV	00037944	5/24/2021	CUMAE5	06	AF1969M	YAT Air Filter			1.00	81.91	81.91	
PM57	XQ26AV	00037944	5/24/2021	CUMAE5	06	MK13584	YAT MAINTENANCE KIT			1.00	97.85	97.85	
PM57	XQ26AV	00037944	5/24/2021	CUMAE5	40	3413005	YAT OIL 15W-40, CK 4/E9			48.00	3.54	169.92	
PM57	XQ26AV	00037944	5/24/2021	CUMBE5	01	LABOUR Labour			0.00	0.00	0.00		
PM57	XQ26AV	00037944	5/24/2021	CUMBE5	SERVICE COMPLETED.								
PM57	XQ26AV	00037944	5/24/2021	DEFECT	01	LABOUR MECH	Labour		0.00	0.00	0.00		
PM57	XQ26AV	00037944	5/24/2021	DEFECT	DEFECT CLEARED.								
PM57	XQ26AV	00037944	5/24/2021	DEFECT	DEFECT CLEARED.								
PM57	XQ26AV	00037845	5/24/2021	GEN	39	Q21-1051-002	BROHUR01	EX00019066	MIRROR CONTROL SWITCH K200,XQ26AV	EX00019	0.00	172.23	0.00

PM57	XQ26AV	00038196	5/24/2021	GEN	39	PART	BROHUR01	EX00019192	GENERAL PART CODE,XQ26AV	EX00019	0.00	2,017.76	0.00
PM57	XQ26AV	00037845	5/24/2021	GEN	39	Q21-1051-002	BROHUR01	2191353	MIRROR CONTROL SWITCH K200,XQ26AV	EX00019	1.00	172.23	172.23
PM57	XQ26AV	00037851	5/24/2021	GEN	00	LABOUR MECH1	Labour		1.00	85.00	85.00		
PM57	XQ26AV	00037857	5/24/2021	GEN	00	LABOUR MECH1	Labour		1.00	85.00	85.00		
PM57	XQ26AV	00038196	5/24/2021	GEN	39	PART	BROHUR01	2191363	GENERAL PART CODE,XQ26AV	EX00019	1.00	2,017.76	2,017.76
PM57	XQ26AV	00037851	5/24/2021	GEN	REPAIR COMPLETED BY SEAN								
DIAGNOSE ISSUE TO BE FAULTY DOOR CONTRIL MODULE													
R&R DOOR CONTROLLER													
PM57	XQ26AV	00037857	5/24/2021	GEN	REPAIR COMPLETED BY SEAN								
R&R WORN OUT TURNTABLE													
CHECKED ADJUSTMENT AND GREASED TOP													
PM57	XQ26AV	00037851	5/24/2021	GEN	16	CON	YAT	Consumables			2.00	15.00	30.00
PM57	XQ26AV	00037857	5/24/2021	GEN	16	CON	YAT	Consumables			3.00	15.00	45.00
PM57	XQ26AV	00037851	5/24/2021	GEN	14	Q21-1051-002	YAT	MIRROR CONTROL SWITCH K200			1.00	172.23	172.23
PM57	XQ26AV	00037857	5/24/2021	GEN	13	JSK37CZ/WP	YAT	CAST GREASE T/TABLE			1.00	2,000.00	2,000.00
PM57	XQ26AV	00038369	6/8/2021	CUMAE5	00	LABOUR APPREN	Labour		1.50	85.00	127.50		
PM57	XQ26AV	00038369	6/8/2021	CUMAE5	SERVICE COMPLETED BY KEIRAN								
TOPPED UP ENGINE OIL BOTTLES (6L)													
REPLACED RH SPOT LIGHT AS IT WAS U/S													
PM57	XQ26AV	00038369	6/8/2021	CUMAE5	16	CON	YAT	Consumables			4.00	15.00	60.00
PM57	XQ26AV	00038369	6/8/2021	CUMAE5	40	3413005	YAT	OIL 15W-40, CK 4/E9			6.00	3.54	21.24
PM57	XQ26AV	00038369	6/8/2021	DEFECT	Reported Defect :- Defect Code : 00006505 Defect Reference : 04396 Date : 07/06/2021 Description of Defect : ICE PACK NEEDS SERVICE REFILLED OIL 3 TIMES THIS WEEK OIL BOTTLE NEEDS REFILLING								
PM57	XQ26AV	00038369	6/8/2021	DEFECT	DEFECT CLEARED BY SEAN 08.06.21 Reported Defect :- Defect Code : 00006506 Defect Reference : 04397 Date : 07/06/2021 Description of Defect : PASSENGER SIDE MIRROW NEEDS RE-TIGHTENING, KEEPS MOVING IN								
PM57	XQ26AV	00038369	6/8/2021	DEFECT	DEFECT CLEARED BY SEAN 08.06.21 Reported Defect :- Defect Code : 00006507 Defect Reference : 04395 Date : 07/06/2021 Description of Defect : A SERVICE DUE								
DEFECT CLEARED BY SEAN 08.06.21													

PM57	XQ26AV	00038369	6/8/2021	ECO	00	LABOUR APPREN	Labour	1.00	85.00	85.00				
PM57	XQ26AV	00038369	6/8/2021	ECO		SERVICE COMPLETED BY KEIRAN								
						ADJUSTED BELTS								
						CLEANED MOTOR								
PM57	XQ26AV	00038369	6/8/2021	ECO	16	CON	YAT	Consumables	3.00	15.00	45.00			
PM57	XQ26AV	00038369	6/8/2021	ECO	06	ED2175254-S	YAT	AIR FILTER SLEEPER AIR	1.00	53.50	53.50			
PM57	XQ26AV	00038369	6/8/2021	ECO	40	3413005	YAT	OIL 15W-40, CK 4/E9	1.00	3.54	3.54			
PM57	XQ26AV	00038691	6/21/2021	GEN	00	LABOUR APPREN	Labour	3.00	85.00	255.00				
PM57	XQ26AV	00038691	6/21/2021	GEN		REPAIR COMPLETED KEIRAN								
						DROVE TO SPRINGWOOD, ROSE JOINT ON GEAR BOX WAS BROKEN. DROVE BACK TO WORK THEN BACK TO TRUCK, SWAPPED OUT SHIFT BAR HOUSING AND REQUESTED FOR THE TRUCK TO COME BACK TO THE YARD								
PM57	XQ26AV	00038691	6/21/2021	GEN	16	CON	YAT	Consumables	7.00	15.00	105.00			
PM57	XQ26AV	00038896	6/23/2021	GEN	39	25189003	BROHUR01	EX00019511	FAN BLOWER ASSEMBLY, K200,XQ26AV	EX00019	0.00	438.75	0.00	
PM57	XQ26AV	00038896	6/23/2021	GEN	39	25189003	BROHUR01	2217281	FAN BLOWER ASSEMBLY, K200,XQ26AV	EX00019	1.00	438.75	438.75	
PM57	XQ26AV	00038955	6/28/2021	CUMAE5	00	LABOUR MECH1	Labour	1.00	85.00	85.00				
PM57	XQ26AV	00038955	6/28/2021	CUMAE5		SERVICE COMPLETED BY KEIRAN AND SEAN								
						REPLACED LH REAR TORQUE ROD BUSH								
						REPLACED SEALS AND BUSHES IN GBOX TOWER AND RE-FITTED								
PM57	XQ26AV	00038955	6/28/2021	CUMAE5	00	LABOUR APPREN	Labour - Internal	1.50	85.00	127.50				
PM57	XQ26AV	00038955	6/28/2021	CUMAE5	16	CON	YAT	Consumables	4.00	15.00	60.00			
PM57	XQ26AV	00038955	6/28/2021	CUMAE5	11	839310	YAT	Torque Rod Bush	2.00	62.00	124.00			
PM57	XQ26AV	00038955	6/28/2021	DEFECT		Reported Defect :-								
						Defect Code : 00006605								
						Defect Reference : 04398								
						Date : 19/06/2021								
						Description of Defect :								
						A SERVICE AND ICE PACK								
						DEFECT CLEARED BY MICK 28.06.2021								
PM57	XQ26AV	00038955	6/28/2021	DEFECT		Reported Defect :-								
						Defect Code : 00006420								
						Defect Reference : 04386								
						Date : 12/04/2021								
						Description of Defect :								
						ICE PACK OUT OF OIL								
						NEEDS ENGINE REBUILD								
						DEFECT CLEARED BY MICK 28.06.2021								
PM57	XQ26AV	00038955	6/28/2021	ECO	00	LABOUR APPREN	Labour	1.00	85.00	85.00				
PM57	XQ26AV	00038955	6/28/2021	ECO		SERVICE COMPLETED.								
PM57	XQ26AV	00038955	6/28/2021	ECO	16	CON	YAT	Consumables	4.00	16.00	64.00			
PM57	XQ26AV	00038955	6/28/2021	ECO	06	ED2175254-S	YAT	AIR FILTER SLEEPER AIR	1.00	53.50	53.50			
PM57	XQ26AV	00038955	6/28/2021	ECO	40	10W50	YAT	HITECH SYNPLUS 10W50	1.00	9.25	9.25			

PM57	XQ26AV	00039125	6/28/2021	TYRES	15	77000180	BRIAUS01	EX00019596	CASE STOCK 11-22.5,PM57	EX00019	0.00	20.00	0.00
PM57	XQ26AV	00039125	6/28/2021	TYRES	15	77000180	BRIAUS01	86111299	CASE STOCK 11-22.5,PM57	EX00019	-2.00	20.00	-40.00
PM57	XQ26AV	00039130	6/29/2021	GEN	39	PART	BROHUR01	EX00019602	GENERAL PART CODE,XQ26AV	EX00019	0.00	260.48	0.00
PM57	XQ26AV	00039130	6/29/2021	GEN	39	PART	BROHUR01	2221631	GENERAL PART CODE,XQ26AV	EX00019	1.00	260.48	260.48
PM57	XQ26AV	00039228	6/30/2021	GEN	39	LAB	BDSMEC01	EX00019623	Labour,XQ26AV	EX00019	0.00	570.00	0.00
PM57	XQ26AV	00039228	6/30/2021	GEN	39	PART	BDSMEC01	EX00019623	SIZE 6 FITTING,PM57	EX00019	0.00	20.00	0.00
PM57	XQ26AV	00039228	6/30/2021	GEN	39	PART	BDSMEC01	EX00019623	SIZE 8 FITTING,PM57	EX00019	0.00	12.00	0.00
PM57	XQ26AV	00039228	6/30/2021	GEN	39	PART	BDSMEC01	EX00019623	SIZE 6 HOSE 1M,PM57	EX00019	0.00	15.00	0.00
PM57	XQ26AV	00039228	6/30/2021	GEN	39	PART	BDSMEC01	EX00019623	AC GAS,PM57	EX00019	0.00	110.00	0.00
PM57	XQ26AV	00039228	6/30/2021	GEN	39	CON	BDSMEC01	EX00019623	Consumables	EX00019	0.00	30.00	0.00
PM57	XQ26AV	00039228	6/30/2021	GEN	39	CON	BDSMEC01	00036671	,PM57				
PM57	XQ26AV	00039228	6/30/2021	GEN	39	PART	BDSMEC01	00036671	Consumables	EX00019	1.00	30.00	30.00
PM57	XQ26AV	00039228	6/30/2021	GEN	39	PART	BDSMEC01	00036671	,PM57				
PM57	XQ26AV	00039228	6/30/2021	GEN	39	PART	BDSMEC01	00036671	AC GAS,PM57	EX00019	0.75	110.00	82.50
PM57	XQ26AV	00039228	6/30/2021	GEN	39	PART	BDSMEC01	00036671	SIZE 6 HOSE 1M,PM57	EX00019	1.00	15.00	15.00
PM57	XQ26AV	00039228	6/30/2021	GEN	39	PART	BDSMEC01	00036671	SIZE 8 FITTING,PM57	EX00019	1.00	12.00	12.00
PM57	XQ26AV	00039228	6/30/2021	GEN	39	PART	BDSMEC01	00036671	SIZE 6 FITTING,PM57	EX00019	1.00	20.00	20.00
PM57	XQ26AV	00039228	6/30/2021	GEN	39	LAB	BDSMEC01	00036671	Labour,XQ26AV	EX00019	1.00	570.00	570.00
PM57	XQ26AV	00039332	7/5/2021	CUMAE5	00	LABOUR APPREN	Labour		1.00	85.00	85.00		
PM57	XQ26AV	00039332	7/5/2021	CUMAE5		SERVICE COMPLETED BY BEN							
PM57	XQ26AV	00039332	7/5/2021	CUMAE5		TOPPED UP ENGINE OIL (5L)							
PM57	XQ26AV	00039332	7/5/2021	CUMAE5	16	CON	YAT	Consumables			3.00	15.00	45.00
PM57	XQ26AV	00039332	7/5/2021	CUMAE5	40	3413005	YAT	OIL 15W-40, CK 4/E9			5.00	3.77	18.85
PM57	XQ26AV	00039857	7/19/2021	CUMAE5	01	LABOUR	Labour		0.00	0.00	0.00		
PM57	XQ26AV	00039857	7/19/2021	CUMAE5		SERVICE COMPLETED.							
PM57	XQ26AV	00039857	7/19/2021	CUMBE5	00	LABOUR MECH1	Labour			2.50	85.00	212.50	
PM57	XQ26AV	00039857	7/19/2021	CUMBE5		SERVICE COMPLETED BY SEAN AND BEN							
PM57	XQ26AV	00039857	7/19/2021	CUMBE5		TOPPED UP ENGINE COOLANT (2L)							
PM57	XQ26AV	00039857	7/19/2021	CUMBE5		REPALCED LHS BULLBAR INDICATOR							
PM57	XQ26AV	00039857	7/19/2021	CUMBE5		ADJUSTED TURNTABLE							
PM57	XQ26AV	00039857	7/19/2021	CUMBE5		R&R RHS FRONT DRIVE AIRBAG							
PM57	XQ26AV	00039857	7/19/2021	CUMBE5	00	LABOUR APPREN	Labour - Internal			2.50	85.00	212.50	
PM57	XQ26AV	00039857	7/19/2021	CUMBE5	16	CON	YAT	Consumables			5.00	15.00	75.00
PM57	XQ26AV	00039857	7/19/2021	CUMBE5	06	MK13584	YAT	MAINTENANCE KIT			1.00	97.85	97.85
PM57	XQ26AV	00039857	7/19/2021	CUMBE5	06	FS36401	YAT	Fuel Filter			1.00	19.09	19.09
PM57	XQ26AV	00039857	7/19/2021	CUMBE5	40	3413005	YAT	OIL 15W-40, CK 4/E9			49.00	3.77	184.73
PM57	XQ26AV	00039857	7/19/2021	CUMBE5	14	235A12	YAT	LED AUTOLAMPS 235 SERIES			1.00	38.04	38.04
PM57	XQ26AV	00039857	7/19/2021	CUMBE5	11	C81-1005	YAT	Air Bag, Drive K200			1.00	333.77	333.77

PM57	XQ26AV	00040077	7/26/2021	DEFECT	Reported Defect :- Defect Code : 00006756 Defect Reference : 07984 Date : 25/07/2021 Description of Defect : ICE PACK NEEDS SERVICE									
PM57	XQ26AV	00040077	7/26/2021	DEFECT	DEFECT CLEARAED BY SEAN 26.07.2021 Reported Defect :- Defect Code : 00006757 Defect Reference : 07982 Date : 25/07/2021 Description of Defect : CHECK DRIVERS SIDE FRONT WINDOW									
PM57	XQ26AV	00040077	7/26/2021	GEN	DEFECT CLEARAED BY SEAN 26.07.2021 00 LABOUR appren Labour 2.00 85.00 170.00									
PM57	XQ26AV	00040077	7/26/2021	GEN	REPAIR COMPLETED BY KEIRAN									
					REPLACED ISRI DRIVERS SEAT SHOCK AS IT HAD SNAPPED LOAD TESTED BATTERIES, OK, CLEANED TERMINALS AND CHECKED ALL WIRES TO STARTER MOTOR WERE TIGHT, STARTS OK NOW REPLACED GAURD B RATCHET ON RH FRONT GAURD									
PM57	XQ26AV	00040077	7/26/2021	GEN	DRIVERS WINDSCREEN CRACKED BADLY 16 CON YAT Consumables 5.00 15.00 75.00									
PM57	XQ26AV	00040112	7/29/2021	TYRES	15	33000051	BRIAUS01	EX00019988	BALANCE TBR,PM57		EX00019	0.00	30.00	0.00
PM57	XQ26AV	00040112	7/29/2021	TYRES	15	33000051	BRIAUS01	86271555	BALANCE TBR,PM57		EX00019	2.00	30.00	60.00
					Total for Asset #####									
					Total for Report #####									

Report Options:

Sort By	- AssetCode
Starting Asset Code	- PM57
To	- PM57
Starting Registration	-
To	-
Starting Operations No	-
To	-
From: Work Order Location	-
To	-
From: Work Order Date	- 01/01/1901
To	- 31/12/9999
From: Completion Date	-
To	-
From: RM Category Code	-
To	-
Starting Category Code	-
To	-
Starting Owned By	-
To	-
Starting Based By	-
To	-
Starting Location	-
To	-
Assets For	- All Assets
Include Disposed Assets	- no
Warranty Items Only	- no
Include Non Active Assets	- no
Exclude Estimates	- no
Fleet Assets Only	- no
Service Code	-
Task Code	-
Mechanic Code	-
Product Code	-
Warehouse	-
WO Supplier Code	-
Include All	- yes
Labour	- yes
Parts	- yes
Supplies	- yes
Tyres	- yes