EK12-12

2491740 Alberta Ltd.

Box 1079


Onoway AB TOE 1V0

admin@firedupblasting.ca

GST/HST Registration No.: 735529745

RT0001







#### BILL TO

Titan Specialized Hauling LTD

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
1031	29/06/2023	\$12,361.65	29/06/2023	Due on receipt	

DATE	ACTIVITY	TAX	QTY	RATE	AMOUNT
	Sales Kenworth C500 Cab Hood, Hood Slides and Grill Surround	GST	83	115.00	9,545.00
	Body Repair and Repaint				
	Sales Paint and Material	GST	1	1,467.00	1,467.00
	Sales Windshield 2 Pcs, Rubber and Install	GST	1	761.00	761.00
			SUBTOTAL	ı	11,773.00
			GST @ 5%	i	588.65
			TOTAL		12,361.65
			BALANCE	DUE	\$12,361.65

#### TAX SUMMARY

NET	TAX	RATE
11,773.00	588.65	GST @ 5%

### 336239 Alberta Ltd O/A Dave's Diesel Repair

11491 - 261 ST.

Acheson, AB. T7X 6C6

Phone: (780) 962-1264 Fax: (780)-962-6230

www.davesdieselrepair.com G.S.T. Number: R106157043

### Invoice

Bill To Titan Specializing Hauling

Plate AB C15 CAT HEAD Description VIN Odometer 1

# 251

**Business Fax** 

**Business** Cell

Cell

Email

Email

Invoice # 51606

Work Order # 63946

Purchase Order # 251 Dale Service Advisor MM2303

Technician NF1202

CAT 3406, E/ACERT

Technician: NF1202 / Service Advisor: MM2303

Invoice Date 6/21/2023 1:29 PM Appointment 5/12/2023 12:09 PM Promised 6/23/2023 2:09 PM

### Concern

ISSUES / CONCERNS / INSTRUCTIONS. -

MAGNAFLUX FOR CRACKS AND PRESSURE TEST. CALL DALE @ 780-517-2559 WITH FINDINGS. COSTING ADDED TO ASSEMBLE GOLD KIT IN CUSTOMER SUPPLIED BLOCK.

- DALE AUTHORIZED MOUNTING THE REAR STRUCTURE TO BLOCK. JUNE 13TH 9:00 AM MARK

#### Service

CH007- Tank Clean Dismantle Head. Put All Valves, Springs and Keepers in Basket. Clean He Labor Technician: GG2212 / Service Advisor: MM2303	ead and Parts in Ta	nk. Rinse and Prep R ——— Sub	eady for Work. \$185.00 *G
CH012- Magnaflux (Includes Cleaning & Buffing) Clean & Buff Head to be able to Magnaflux Cylinder Head (Powder Detect Labor Technician: GG2212 / Service Advisor: MM2303 97F / 07-1022/ 96F/10026/10028 - 1" END BRUSH Technician: NF1202 / Service Advisor: MM2303	ion) 1 Unit	\$29.16 / Unit Sub	\$295.00 *G \$29.16 G \$324.16
CH015- Pressure Test Cylinder Head Install Head on Test Equipment. Heat Head 190f. Check for Leaks. Labor Technician: GG2212 / Service Advisor: MM2303		Sub —	\$324.16 \$395.00 *G
CH100- Injector Tubes (CAT)  Remove Injector Tubes. Clean Cylinder Head. Reinstall New O-rings and Labor Technician: LM1807 / Service Advisor: MM2303  SBI-240-1006RT - O-RING, INJECTOR TUBE, UPPER,	Tubes and Reinsta 6 Unit	II. \$7.47 / Unit	\$370.00 *G \$44.82 G

CAT166-2904 - O-RING, INJECTOR SLEEVE, MIDDLE, CAT 3406 E / ACERT	6 Unit	\$12.86 / Unit	\$77.16 G
Technician: NF1202 / Service Advisor: MM2303			
SBI-240-1006RB - O-RING, INJECTOR TUBE, LOWER, CAT 3406, E/ACERT	6 Unit	\$3.75 / Unit	\$22.50 G
Technician: NF1202 / Service Advisor: MM2303			
		Sub	\$514.48
CH200- Guides (RE&RE) 12 EXHAUST			
Remove Guides. Install New Guides. Hone To Fit. Labor			\$185.00 *G
Technician: GG2212 / Service Advisor: MM2303			<b>V</b>
SBI-140-3007 - GUIDE, VALVE, CAT 3406 E/ACERT	11 Unit	\$8.43 / Unit	\$92.73 G
Technician: NF1202 / Service Advisor: MM2303		<b>*</b>	•
SBI-140-3007+2 - GUIDE, VALVE, CAT 3406, E/ACERT,	1 Unit	\$8.43 / Unit	\$8.43 G
.002 OVERSIZE		•	
Technician: NF1202 / Service Advisor: MM2303			
		Sub	\$286.16
CH220- Valve Job		6 11 B IE	11
Remove ALL Valves. Clean and Inspect. Replace IF Required. Grind Val	ives & Seats. Meas	ure Guides, Reuse IF	Useable. Install
New Seals. Measure ALL Valves Springs. Adjust/Install. Inspect Rotator(	(S).		\$1,250.00 *G
Technician: LM1807 / Service Advisor: MM2303			Ψ1,200.00 Θ
SBI-122-1373 - SEAL, VALVE STEM, POSITIVE, CAT 3406	24 Unit	\$5,36 / Unit	\$128.64 G
Technician: NF1202 / Service Advisor: MM2303	2	<b>V</b> 0.001.0	<b>*</b>
SBI-121-1000 - LOCK (KEEPER), VALVE, CAT, ALL 3400	48 Unit	\$0.46 / Unit	\$22.08 G
SERIES & 3208		*	<b>,</b>
Technician: NF1202 / Service Advisor: MM2303			
22617-6 / N60012-906 - O-RING, ORB	1 Unit	\$0.42 / Unit	\$0.42 G
Technician: NF1202 / Service Advisor: MM2303			
N5409-02 - FITTING, 1/8" NPT COUNTER SUNK PLUG	3 Unit	\$1.50 / Unit	\$4.50 G
Technician: NF1202 / Service Advisor: MM2303		<b></b>	•=
CAT8T2822 - *RECORDER Technician: NF1202 / Service Advisor: MM2303	1 Unit	\$7.48 / Unit	\$7.48 G
rechnician. Nr 1202 / Service Advisor. Mini2303		Sub	\$1,413.12
		duc	\$1,413.1Z
CH300- Resurface (Deck Surface)			
Resurface Deck Side of Cylinder Head			
Labor			\$380.00 *G
Technician: LM1807 / Service Advisor: MM2303			
		Sub —	\$380.00
		Sub	\$380.00
CH400- Replace Cam Bearing(s).		Sub	\$380.00
Replace Cam Bearing(s).		Sub	
		Sub	\$380.00 \$250.00 *G
Replace Cam Bearing(s). Labor Technician: LM1807 / Service Advisor: MM2303	7 Unit		\$250.00 *G
Replace Cam Bearing(s). Labor	7 Unit	<b>Sub</b> \$69.99 / Unit	
Replace Cam Bearing(s). Labor Technician: LM1807 / Service Advisor: MM2303 462-134-5251/216-5582 - BUSHING, CAM, 3406 E/ACERT	7 Unit		\$250.00 *G
Replace Cam Bearing(s). Labor Technician: LM1807 / Service Advisor: MM2303 462-134-5251/216-5582 - BUSHING, CAM, 3406 E/ACERT	7 Unit	\$69.99 / Unit	\$250.00 *G \$489.93 G
Replace Cam Bearing(s). Labor Technician: LM1807 / Service Advisor: MM2303 462-134-5251/216-5582 - BUSHING, CAM, 3406 E/ACERT Technician: NF1202 / Service Advisor: MM2303  CB007- Tank Clean, Buff & Wash	7 Unit	\$69.99 / Unit	\$250.00 *G \$489.93 G
Replace Cam Bearing(s). Labor Technician: LM1807 / Service Advisor: MM2303 462-134-5251/216-5582 - BUSHING, CAM, 3406 E/ACERT Technician: NF1202 / Service Advisor: MM2303  CB007- Tank Clean, Buff & Wash Tank Clean Block, Buff & Wash Engine Block to Prep for Rebuild.	7 Unit	\$69.99 / Unit	\$250.00 *G \$489.93 G \$739.93
Replace Cam Bearing(s). Labor Technician: LM1807 / Service Advisor: MM2303 462-134-5251/216-5582 - BUSHING, CAM, 3406 E/ACERT Technician: NF1202 / Service Advisor: MM2303  CB007- Tank Clean, Buff & Wash Tank Clean Block, Buff & Wash Engine Block to Prep for Rebuild. Labor	7 Unit	\$69.99 / Unit	\$250.00 *G \$489.93 G
Replace Cam Bearing(s). Labor Technician: LM1807 / Service Advisor: MM2303 462-134-5251/216-5582 - BUSHING, CAM, 3406 E/ACERT Technician: NF1202 / Service Advisor: MM2303  CB007- Tank Clean, Buff & Wash Tank Clean Block, Buff & Wash Engine Block to Prep for Rebuild. Labor Technician: GG2212 / Service Advisor: MM2303		\$69.99 / Unit Sub	\$250.00 *G \$489.93 G <b>\$739.93</b> \$595.00 *G
Replace Cam Bearing(s). Labor Technician: LM1807 / Service Advisor: MM2303 462-134-5251/216-5582 - BUSHING, CAM, 3406 E/ACERT Technician: NF1202 / Service Advisor: MM2303  CB007- Tank Clean, Buff & Wash Tank Clean Block, Buff & Wash Engine Block to Prep for Rebuild. Labor Technician: GG2212 / Service Advisor: MM2303 CAT100-7399 - *PLUG	7 Unit 1 Unit	\$69.99 / Unit	\$250.00 *G \$489.93 G \$739.93
Replace Cam Bearing(s). Labor Technician: LM1807 / Service Advisor: MM2303 462-134-5251/216-5582 - BUSHING, CAM, 3406 E/ACERT Technician: NF1202 / Service Advisor: MM2303  CB007- Tank Clean, Buff & Wash Tank Clean Block, Buff & Wash Engine Block to Prep for Rebuild. Labor Technician: GG2212 / Service Advisor: MM2303 CAT100-7399 - *PLUG Technician: NF1202 / Service Advisor: MM2303	1 Unit	\$69.99 / Unit Sub  \$20.01 / Unit	\$250.00 *G \$489.93 G <b>\$739.93</b> \$595.00 *G \$20.01 G
Replace Cam Bearing(s). Labor Technician: LM1807 / Service Advisor: MM2303 462-134-5251/216-5582 - BUSHING, CAM, 3406 E/ACERT Technician: NF1202 / Service Advisor: MM2303  CB007- Tank Clean, Buff & Wash Tank Clean Block, Buff & Wash Engine Block to Prep for Rebuild. Labor Technician: GG2212 / Service Advisor: MM2303 CAT100-7399 - *PLUG		\$69.99 / Unit Sub	\$250.00 *G \$489.93 G <b>\$739.93</b> \$595.00 *G
Replace Cam Bearing(s). Labor Technician: LM1807 / Service Advisor: MM2303 462-134-5251/216-5582 - BUSHING, CAM, 3406 E/ACERT Technician: NF1202 / Service Advisor: MM2303  CB007- Tank Clean, Buff & Wash Tank Clean Block, Buff & Wash Engine Block to Prep for Rebuild. Labor Technician: GG2212 / Service Advisor: MM2303 CAT100-7399 - *PLUG Technician: NF1202 / Service Advisor: MM2303 BD1312 / 892.150016 - PAINT. AEROSOL CAT YELLOW	1 Unit	\$69.99 / Unit Sub  \$20.01 / Unit	\$250.00 *G \$489.93 G <b>\$739.93</b> \$595.00 *G \$20.01 G
Replace Cam Bearing(s). Labor Technician: LM1807 / Service Advisor: MM2303 462-134-5251/216-5582 - BUSHING, CAM, 3406 E/ACERT Technician: NF1202 / Service Advisor: MM2303  CB007- Tank Clean, Buff & Wash Tank Clean Block, Buff & Wash Engine Block to Prep for Rebuild. Labor Technician: GG2212 / Service Advisor: MM2303 CAT100-7399 - *PLUG Technician: NF1202 / Service Advisor: MM2303 BD1312 / 892.150016 - PAINT. AEROSOL CAT YELLOW	1 Unit	\$69.99 / Unit Sub  \$20.01 / Unit \$22.12 / Unit	\$250.00 *G \$489.93 G \$739.93 \$595.00 *G \$20.01 G \$44.24 G
Replace Cam Bearing(s). Labor Technician: LM1807 / Service Advisor: MM2303 462-134-5251/216-5582 - BUSHING, CAM, 3406 E/ACERT Technician: NF1202 / Service Advisor: MM2303  CB007- Tank Clean, Buff & Wash Tank Clean Block, Buff & Wash Engine Block to Prep for Rebuild. Labor Technician: GG2212 / Service Advisor: MM2303 CAT100-7399 - *PLUG Technician: NF1202 / Service Advisor: MM2303 BD1312 / 892.150016 - PAINT. AEROSOL CAT YELLOW Technician: NF1202 / Service Advisor: MM2303	1 Unit	\$69.99 / Unit Sub  \$20.01 / Unit \$22.12 / Unit	\$250.00 *G \$489.93 G \$739.93 \$595.00 *G \$20.01 G \$44.24 G
Replace Cam Bearing(s). Labor Technician: LM1807 / Service Advisor: MM2303 462-134-5251/216-5582 - BUSHING, CAM, 3406 E/ACERT Technician: NF1202 / Service Advisor: MM2303  CB007- Tank Clean, Buff & Wash Tank Clean Block, Buff & Wash Engine Block to Prep for Rebuild. Labor Technician: GG2212 / Service Advisor: MM2303 CAT100-7399 - *PLUG Technician: NF1202 / Service Advisor: MM2303 BD1312 / 892.150016 - PAINT. AEROSOL CAT YELLOW Technician: NF1202 / Service Advisor: MM2303	1 Unit	\$69.99 / Unit Sub  \$20.01 / Unit \$22.12 / Unit	\$250.00 *G \$489.93 G \$739.93 \$595.00 *G \$20.01 G \$44.24 G

7/4/2023 1:33 PM Invoice #51606 Page 2 of 4

Technician: GG2212 / Service Advisor: MM2303		Sub	\$185.00
CB300- Re-Surface Engine Block De-Grease Block & Prep for Re-Surfacing. Install Block On Re-Surfacer. Re Labor	-Surface Block	<b>.</b>	\$595.00 *G
Technician: LM1807 / Service Advisor: MM2303		Sub _	\$595.00
CRK- 005 Crankshaft, Tank Clean Put Crankshaft in Hot Tank Labor			\$75.00 <b>*</b> G
Technician: JC1607 / Service Advisor: MM2303		Sub _	\$75.00
CRK- 010 Crankshaft, Magnaflux Clean Crankshaft, Hoist Crank onto Mag Machine. Check for Cranks. Labor	1 Unit	\$100.00 / Unit	\$100.00 G
Technician: NF1202 / Service Advisor: MM2303		Sub _	\$100.00
CRK- 015 Crankshaft, Check for Straightness Install Crankshaft on V-Blocks. Labor			\$100.00*G
Technician: JC1607 / Service Advisor: MM2303		Sub _	\$100.00
CRK- 020 Crankshaft, Polish		300	\$100.00
Install Crankshaft on Lathe, and Polish. Labor Technician: LM1807 / Service Advisor: MM2303			\$185.00 *G
Technician. Elvi 1007 7 Gervice Advisor. WiW2505			
		Sub	\$185.00
CA200- Engine, Cat PUT TOGETHER CAT SHORT BLOCK WITH CUSTO	OMERS BLOC		•
INSPECTIONS. USING CAT GOLD KIT.  Rear Structure Disassembly and Tare Down of Short Block	OMERS BLOC		•
INSPECTIONS. USING CAT GOLD KIT.  Rear Structure Disassembly and Tare Down of Short Block Technician: JB2304 / Service Advisor: MM2303 Labor	DMERS BLOC		R THERE
INSPECTIONS. USING CAT GOLD KIT. Rear Structure Disassembly and Tare Down of Short Block Technician: JB2304 / Service Advisor: MM2303 Labor Technician: EJ98 / Service Advisor: MM2303 Labor	OMERS BLOC		<b>R THERE</b> \$849.75 *G
INSPECTIONS. USING CAT GOLD KIT. Rear Structure Disassembly and Tare Down of Short Block Technician: JB2304 / Service Advisor: MM2303 Labor Technician: EJ98 / Service Advisor: MM2303 Labor Technician: JC1607 / Service Advisor: MM2303 CAT10R9923 - ENGINE KIT, GOLD, MXS, NXS	OMERS BLOC		\$849.75 *G \$2,039.40 *G \$339.90 *G
INSPECTIONS. USING CAT GOLD KIT. Rear Structure Disassembly and Tare Down of Short Block Technician: JB2304 / Service Advisor: MM2303 Labor Technician: EJ98 / Service Advisor: MM2303 Labor Technician: JC1607 / Service Advisor: MM2303 CAT10R9923 - ENGINE KIT, GOLD, MXS, NXS Technician: NF1202 / Service Advisor: MM2303 CAT6V6609 - ORING		K AND CRANK AFTE	\$849.75 *G \$2,039.40 *G \$339.90 *G
INSPECTIONS. USING CAT GOLD KIT. Rear Structure Disassembly and Tare Down of Short Block Technician: JB2304 / Service Advisor: MM2303 Labor Technician: EJ98 / Service Advisor: MM2303 Labor Technician: JC1607 / Service Advisor: MM2303 CAT10R9923 - ENGINE KIT, GOLD, MXS, NXS Technician: NF1202 / Service Advisor: MM2303 CAT6V6609 - ORING Technician: NF1202 / Service Advisor: MM2303 CAT238-5080 - SEAL, O-RING	1 Unit	<b>K AND CRANK AFTE</b> \$12,200.00 / Unit	\$849.75 *G \$2,039.40 *G \$339.90 *G \$12,200.00 G
INSPECTIONS. USING CAT GOLD KIT. Rear Structure Disassembly and Tare Down of Short Block Technician: JB2304 / Service Advisor: MM2303 Labor Technician: EJ98 / Service Advisor: MM2303 Labor Technician: JC1607 / Service Advisor: MM2303 CAT10R9923 - ENGINE KIT, GOLD, MXS, NXS Technician: NF1202 / Service Advisor: MM2303 CAT6V6609 - ORING Technician: NF1202 / Service Advisor: MM2303 CAT238-5080 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT165-6170/4N0999 - *BLOCK PLUG	1 Unit 2 Unit	\$12,200.00 / Unit	\$849.75 *G \$2,039.40 *G \$339.90 *G \$12,200.00 G \$2.94 G
INSPECTIONS. USING CAT GOLD KIT. Rear Structure Disassembly and Tare Down of Short Block Technician: JB2304 / Service Advisor: MM2303 Labor Technician: EJ98 / Service Advisor: MM2303 Labor Technician: JC1607 / Service Advisor: MM2303 CAT10R9923 - ENGINE KIT, GOLD, MXS, NXS Technician: NF1202 / Service Advisor: MM2303 CAT6V6609 - ORING Technician: NF1202 / Service Advisor: MM2303 CAT238-5080 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT165-6170/4N0999 - *BLOCK PLUG Technician: NF1202 / Service Advisor: MM2303 CAT126-4935/4N0641 - *OIL COOLER BONNET GASKET	1 Unit 2 Unit 6 Unit	\$12,200.00 / Unit \$1.47 / Unit \$9.03 / Unit	\$849.75 *G \$2,039.40 *G \$339.90 *G \$12,200.00 G \$2.94 G \$54.18 G
INSPECTIONS. USING CAT GOLD KIT. Rear Structure Disassembly and Tare Down of Short Block Technician: JB2304 / Service Advisor: MM2303 Labor Technician: EJ98 / Service Advisor: MM2303 Labor Technician: JC1607 / Service Advisor: MM2303 CAT10R9923 - ENGINE KIT, GOLD, MXS, NXS Technician: NF1202 / Service Advisor: MM2303 CAT6V6609 - ORING Technician: NF1202 / Service Advisor: MM2303 CAT238-5080 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT165-6170/4N0999 - *BLOCK PLUG Technician: NF1202 / Service Advisor: MM2303 CAT126-4935/4N0641 - *OIL COOLER BONNET GASKET Technician: NF1202 / Service Advisor: MM2303 CAT214-7566 - SEAL, O-RING	1 Unit 2 Unit 6 Unit 3 Unit	\$12,200.00 / Unit \$1.47 / Unit \$9.03 / Unit \$12.73 / Unit	\$849.75 *G \$2,039.40 *G \$339.90 *G \$12,200.00 G \$2.94 G \$54.18 G \$38.19 G
INSPECTIONS. USING CAT GOLD KIT. Rear Structure Disassembly and Tare Down of Short Block Technician: JB2304 / Service Advisor: MM2303 Labor Technician: EJ98 / Service Advisor: MM2303 Labor Technician: JC1607 / Service Advisor: MM2303 CAT10R9923 - ENGINE KIT, GOLD, MXS, NXS Technician: NF1202 / Service Advisor: MM2303 CAT6V6609 - ORING Technician: NF1202 / Service Advisor: MM2303 CAT238-5080 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT165-6170/4N0999 - *BLOCK PLUG Technician: NF1202 / Service Advisor: MM2303 CAT126-4935/4N0641 - *OIL COOLER BONNET GASKET Technician: NF1202 / Service Advisor: MM2303 CAT214-7566 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT214-7566 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT033-6027 - O-RING	1 Unit 2 Unit 6 Unit 3 Unit 1 Unit	\$12,200.00 / Unit \$1.47 / Unit \$9.03 / Unit \$12.73 / Unit \$15.34 / Unit	\$849.75 *G \$2,039.40 *G \$339.90 *G \$12,200.00 G \$2.94 G \$54.18 G \$38.19 G \$15.34 G
INSPECTIONS. USING CAT GOLD KIT. Rear Structure Disassembly and Tare Down of Short Block Technician: JB2304 / Service Advisor: MM2303 Labor Technician: EJ98 / Service Advisor: MM2303 Labor Technician: JC1607 / Service Advisor: MM2303 CAT10R9923 - ENGINE KIT, GOLD, MXS, NXS Technician: NF1202 / Service Advisor: MM2303 CAT6V6609 - ORING Technician: NF1202 / Service Advisor: MM2303 CAT238-5080 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT165-6170/4N0999 - *BLOCK PLUG Technician: NF1202 / Service Advisor: MM2303 CAT126-4935/4N0641 - *OIL COOLER BONNET GASKET Technician: NF1202 / Service Advisor: MM2303 CAT214-7566 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT214-7566 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT033-6027 - O-RING Technician: NF1202 / Service Advisor: MM2303 CAT238-5081 - SEAL, O-RING	1 Unit 2 Unit 6 Unit 3 Unit 1 Unit 1 Unit	\$12,200.00 / Unit \$1.47 / Unit \$9.03 / Unit \$12.73 / Unit \$15.34 / Unit \$6.87 / Unit	\$849.75 *G \$2,039.40 *G \$339.90 *G \$12,200.00 G \$2.94 G \$54.18 G \$38.19 G \$15.34 G \$6.87 G
INSPECTIONS. USING CAT GOLD KIT.  Rear Structure Disassembly and Tare Down of Short Block Technician: JB2304 / Service Advisor: MM2303 Labor Technician: EJ98 / Service Advisor: MM2303 Labor Technician: JC1607 / Service Advisor: MM2303 CAT10R9923 - ENGINE KIT, GOLD, MXS, NXS Technician: NF1202 / Service Advisor: MM2303 CAT6V6609 - ORING Technician: NF1202 / Service Advisor: MM2303 CAT238-5080 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT165-6170/4N0999 - *BLOCK PLUG Technician: NF1202 / Service Advisor: MM2303 CAT126-4935/4N0641 - *OIL COOLER BONNET GASKET Technician: NF1202 / Service Advisor: MM2303 CAT214-7566 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT033-6027 - O-RING Technician: NF1202 / Service Advisor: MM2303 CAT238-5081 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT238-5081 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT238-5081 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT238-5081 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT100-7399 - *PLUG	1 Unit 2 Unit 6 Unit 3 Unit 1 Unit 1 Unit 1 Unit	\$12,200.00 / Unit \$1.47 / Unit \$9.03 / Unit \$12.73 / Unit \$15.34 / Unit \$6.87 / Unit \$7.60 / Unit	\$849.75 *G \$2,039.40 *G \$339.90 *G \$12,200.00 G \$2.94 G \$54.18 G \$38.19 G \$15.34 G \$6.87 G \$7.60 G
INSPECTIONS. USING CAT GOLD KIT. Rear Structure Disassembly and Tare Down of Short Block Technician: JB2304 / Service Advisor: MM2303 Labor Technician: EJ98 / Service Advisor: MM2303 Labor Technician: JC1607 / Service Advisor: MM2303 CAT10R9923 - ENGINE KIT, GOLD, MXS, NXS Technician: NF1202 / Service Advisor: MM2303 CAT6V6609 - ORING Technician: NF1202 / Service Advisor: MM2303 CAT238-5080 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT165-6170/4N0999 - *BLOCK PLUG Technician: NF1202 / Service Advisor: MM2303 CAT126-4935/4N0641 - *OIL COOLER BONNET GASKET Technician: NF1202 / Service Advisor: MM2303 CAT214-7566 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT033-6027 - O-RING Technician: NF1202 / Service Advisor: MM2303 CAT238-5081 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303 CAT238-5081 - SEAL, O-RING Technician: NF1202 / Service Advisor: MM2303	1 Unit 2 Unit 6 Unit 3 Unit 1 Unit 1 Unit 1 Unit 1 Unit	\$12,200.00 / Unit \$1.47 / Unit \$9.03 / Unit \$12.73 / Unit \$15.34 / Unit \$6.87 / Unit \$7.60 / Unit \$9.41 / Unit	\$849.75 *G \$2,039.40 *G \$339.90 *G \$12,200.00 G \$2.94 G \$54.18 G \$38.19 G \$15.34 G \$6.87 G \$7.60 G \$9.41 G

Sub \$15,624.72

CA688- Structure, Rear

Remove Drive-line, Remove Transmission, Clutch and Flywheel. Remove Oil Pan, Support Engine. Disconnect Batteries, Remove Starter, Remove Flywheel Housing. Replace Gasket and Seals, Replace Plug/O-Ring or Frost Plug. Reassemble. Adjust Clutch.

Labor Technician: EJ98 / Service Advisor: MM2303

CAT285-3200 - GASKET KIT, REAR STRUCTURE, BXS,

1 Unit

\$426.90 / Unit

C...

\$426.90 G

\$1 106 70

MXS, NXS

Technician: NF1202 / Service Advisor: MM2303

	Sui	, \$1,100.70
Total Parts		\$13,914.67
Total Labor		<u>\$8,953.85</u>
Total Before Taxes & Miscellaneous Charges		\$22,868.52
(*) Shop Supplies		\$895.39 G
(G) Canadian Goods and Services Tax (GST)	5 %	\$1,188.20
Grand Total		\$24,952.11

Titan Specialized Hauling (Lehman, Darron) charged \$24,952.11 to Account - 1346 - Titan Specializing Hauling - Net 30 Days

G.S.T. Number: R106157043

Terms: Cash or Credit Card unless arrangements made when work order is started. Interest on all overdue accounts shall be charged at 42.58% per annum (3% per month) & storage charges in the Sum of \$25.00 per day.Core must be returned within 30 days after the purchase, together with the original invoice copy to be eligible for the core credit. All parts return will be subject to 25% restocking charge.

I have read and understand the above terms and agree to be bound thereby.  I hereby acknowledge my indebtedness in the amount of above Invoice Total, or otherwise specified here as \$						
Signature						

## 336239 Alberta Ltd O/A Dave's Diesel Repair



11491 - 261 ST, Acheson, AB. T7X 6C6

Phone: (780) 962-1264 Fax: (780)-962-6230

www.davesdieselrepair.com G.S.T. Number: R106157043

### Invoice

Bill To Titan Specializing Hauling

Business Fax
Business
Cell
Cell
Email
Email

Invoice # 51778
Work Order # 64468
Purchase Order # 251 (DALE)
Service Advisor Jordan Szybunka
Technician JJJS1001

Invoice Date 7/11/2023 3:59 PM Appointment 7/11/2023 1:04 PM Promised 7/11/2023 3:04 PM

Service			
CA200- Engine, Cat			2
CAT348-3681 - GASKET KIT, FRONT STRUCTURE	1 Unit	\$1,373.29 / Unit	\$1,373.29 G
GASKET, (BXS, MXS, NXS)			
Technician: JJJS1001 / Service Advisor: Jordan Szybunka	* * * * *	04 474 00 414 11	#0.700.00.C
CAT0R9449/161-4113 - PUMP, OIL	1 Unit	\$1,474.63 / Unit	\$2,763.82 G
* Includes \$1,289.19 core charge. Technician: JJJS1001 / Service Advisor: Jordan Szybunka			
	4.11-24	¢4.754.00 / LI=!+	¢2 569 66 C
CAT10R8660/10R3326 - WATER PUMP * Includes \$814.66 core charge.	1 Unit	\$1,754.00 / Unit	\$2,568.66 G
Technician: JJJS1001 / Service Advisor: Jordan Szybunka			
7C3039/2W1008 - OIL COOLER	1 Unit	\$1,258.77 / Unit	\$1,258.77 G
Technician: JJJS1001 / Service Advisor: Jordan Szybunka	1 Offic	ψ1,230.777 Offit	ψ1,230.77 G
CORE CHARGE - *** NOTE, CORE RETURNS MUST BE	1 Unit	\$250.00 / Unit	\$250.00 G
ACCOMPANIED BY A COPY OF ORIGINAL INVOICE ***	i Onit	Ψ230.00 / Offit	Ψ230.00 Ο
Technician: JJJS1001 / Service Advisor: Jordan Szybunka			
CAT321-4324/234-5004 - HARNESS	1 Unit	\$382.00 / Unit	\$382.00 G
ASSY(REAR,MXS/NXS)	AMOUNT COLOR		
Technician: JJJS1001 / Service Advisor: Jordan Szybunka			
CAT321-4323/234-5003 - HARNESS	1 Unit	\$500.80 / Unit	\$500.80 G
ASSY(FRONT,MXS/NXS)			
Technician: JJJS1001 / Service Advisor: Jordan Szybunka			
CAT6V0128 - SEAL	2 Unit	\$4.10 / Unit	\$8.20 G
Technician: JJJS1001 / Service Advisor: Jordan Szybunka			
CAT234-3118 - TUBE	1 Unit	\$175.64 / Unit	\$175.64 G
Technician: JJJS1001 / Service Advisor: Jordan Szybunka			
		Sub	\$9,281.18
Total Parts			\$9,281.18
Total Labor		_	\$0.00
Total Before Taxes & Miscellaneous Charges			\$9,281.18
(G) Canadian Goods and Services Tax (GST)		5 %	\$464.06
Grand Total		•	\$9,745.24



Dash Mechanical

Box 6389

Edson, Alberta. T7E 1T8

Phone: 780-723-2119 Fax: 780-723-2151

All your heavy truck and trailer needs

INVOICE

38582

GST 884677113RT0001

TITAN SPECIALIZED HAULING LTD

**Business** Cell

Printed Date: 03/23/2023

Work Completed: 03/23/2023

Lic #: H42410

2007 Kenworth - C500B - Caterpillar C-15 ADEM A4/ACERT EPA04 6 ( Odometer In: 391829

Unit #: 251

VIN #: 1XKCPBTX8 7R995053

Engine Hrs In: 19585.0

Engine Hours Out: 19585.0

				Engine riis iii . 19303.0	Lingine Flours Out.	10000.0
Part Description	Qty	Sale	Ext	Labor Description	Hours	Ext
Injector Cup	6.00	58.80	352.80	Replace injector cups	7.00	980.00
Injector Cup O-Ring Kit	6.00	48.19	289.14	1		
Injector O-Ring Kit	6.00	54.32	325.92		rings and hold down	
Injector Hold Down Bolt	6.00	8.00	48.00	bolts  Replace broken VVA head and one mount s	stud	
Rad Flush	4.00	10.00	40.00	[1] 전 10 10 10 10 10 10 10 10 10 10 10 10 10		
Coolant /Lt	24.00	6.25	150.00	** camshaft starting to flake and will need to	be replaced before too	
VVA Head	1.00	3,459.89	3,459.89			
Core Loss	1.00	420.00	420.00	Adjust valves Flush cooling system three times and fill wit	h new coolant	
VVA Stud	1.00	31.92	31.92	,	IT New Coolant	
Rocker Arm (used)	1.00	100.00	100.00			
Shop Supplies			98.00			

[Payments - ]

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. We will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond our control. Vehicle subject to storage fees after 30 Days at a rate of \$25/Day

Please make cheques payable to DASH MECHANICAL (Edson)

Account balance paid by Credit Card subject to 3% charge.

\*invoices payable net 30 days. Service charge of 2% per month. Applicable to overdue accounts. Vehicle Received: 2023-03-13

Signature Date

Labor: 980.00 Parts: 5,315.67 Sub: 6,295.67 Tax: 314.78 \$6,610.45 Total: Bal Due: \$6,610.45

Customer Number: 137

DOUG SPREEN ENTERPRISES LTD. 6682-15 Avenue Edson, AB T7E 1S3 (780) 712-5715

ORDER NO	DEPT	DATE apri	12712023,
Sitan Space	alized Hauling Ital.	TO /	
ADDRESS			
SHIPPING DATE VI	TERMS	TAX REG NO	SALESPERSON
	Respirators	man hear on dech	
	Restaceween as	rds on agelis	
	Ripair gacks t.	members on club.  eds on goples  build up a onn ass  mo for truck # 5	as
	on walking bea	ms for truck # 3	251
	7		
	22 % Lon	no @ 130,00	\$ 2925 00
		1	
			6-57 \$146 25
796234 SIGNAT	TURE	LIC NO	TOTAL \$3071 25
Blueline DC151	SALES	ORDER	TOTAL 23071 25

Date April 27/23 Luie's Contracting Inc.  Box 7017 Edson, AB. T7E 1V3  Cell: (780) 712-1988 Phone: (780) 723-4037	P.O. No.		
Name		INVOICE	
Address		2356	
DATE DESCRIPTION	HOURS	PRICE	TOTAL
Replace torque and support on center diff	5	120 90	60000
April 18 replace broke spiders on certer axle	41/2		54000
unit (251)	7/2		340
worth as deal removal and repairs.			
April 13-8 mil 14-2 April 17-21/2 spil 18-3/2	21.5		258000
PRINTED BY TRAIL PRINTING GST# 84446 9346 RT0001 SUB TOTAL			
PRINTED BY TRAIL PRINTING GST# 84446 9346 RT0001 SUB TOTAL			372000
GST			18600
Signature TOTAL			3906

## DOUG SPREEN ENTERPRISES LTD. 6682-15 Avenue Edson, AB T7E 1S3 (780) 712-5715

ORDER NO	DEPT DATE May	26(2	02.	2.
sold to Sitan Sp	Tore a lease of Hauling & Rot			
ADDRESS	ADDRESS			
SHIPPING DATE	VIA TERMS TAX REG. NO.	SALESPER	SON	
1	0000			
	replace frame on small cless,			
	Replace frame on small cless, replace surriging light box, 4 repair wasts for truck # 251.			
	81/2 hours @ 130,00	\$	1105	00
		-		
		7	C	25
	11	518	22	2
796240	SIGNATURE LIC NO TO	TAK	1160	25
Blueline' 00151	SALES ORDER			Blueline® 201



PH: (780)573-7676

FAX: (780)573-7676

POST OFFICE BOX 6130 BONNYVILLE, AB T9N 2G7 (4700 - 70 Street) WWW.OVERDRIVEHEAVYDUTY.COM

Branch: 01

Repair Order: 45271 Customer:

Total Invoice: \$1,320.88 \*\*\*COD\*\*\*

\*\* Reprint \*\* Invoice: 01S45271.02 Date / Hour: 3/9/2023 2:33:04PM

Page 1 of 2

Bill To:

TITAN SPECIALIZED HAULING

Ship To: TITAN SPECIALIZED HAULING

Office Phone: Shop Phone: Home Phone:

Work:

Shop:

Customer P/O:

Open Date: 03/09/2023

Salesperson: Terri-Lyn

Add User: Stacy

Unit Number: 251

Model Year: 2007

Make/Model: Kenworth C500B

Type: Heavy Duty

VIN: 1XKCPBTX87R995053

Meter: 391809 Kilometers

ECM Reading: 19571

Task:

22-2201

Cooling System Diagnose

Department: Service

Completion Date: 03/09/2023

Complaint: - PRESSURE IN COOLING SYSTEM DIAGNOSE AND ADVISE Correction: 3/9/2023 9:32:32 AM 1078 REMOVED RESERVOIR CAP ON UNIT

DIESEL IN COOLING SYSTEM

COOLING SYSTEM GETTING PRESSURED BY FUEL SYSTEM

REPLACE INJECTOR CUPS AND SWOLLEN HOSES

REPLACE AIR COMPRESSOR HOSE BETWEEN TURBO AND HARD PIPE FOR AIR COMPRESSOR INTAKE

HOOKED UP WITH CAT ET AND CHECKED CODES NO ACTIVE CODES PRINTED SUMMARY AND ENTERED ENGINE COMPONENT INFORMATION

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Price
		Т	ask 1 Subtotals	Parts:		\$0.00
			1.32	Labor:		\$211.13
				Task 1 Subtotals		\$211.13

Task: 2 22-2202 Complaint: \*\*\*\*PATCH REPAIR\*\*\*\*

Cooling System Repair

Department: Service

- REPLACE COOLANT LINES THAT LOOK QUESTIONABLE

- REPLACE COOLANT, AND INSTALLA CATCH JUG TO CATCH OVERFLOWING COOLANT/DIESEL MIXTURE

Correction: 3/9/2023 12:06:03 PM 1078 REMOVED LOWER RAD HOSE AND LOWER 3 IN HOSE COMING OFF WATER PUMP

REMOVED UPPER RAD HOSE AND COOLANT SHUNT LINE

GAVE TO PARTS AS SAMPLE INSTALLED NEW COOLANT HOSES

3/9/2023 1:36:53 PM 1078 PRESSURE TESTED COOLING SYSTEM

HOSES THAT WERE REMOVED NOT LEAKING FAILED PRESSURE TEST DUE TO LEAKING CUPS

VAC FILLED COOLING SYSTEM

INSTALLED CATCH JUG FOR RAD OVERFLOW LINE IN PASSENGER SIDE FRONT WHEEL WELL

				•	5	Extended
Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Price
	ADD 16834	ANTIFREEZE (EXT-LIFE)	EACH	13.0	\$15.91	\$206.83
	FTG 121A	HEX PIPE PLUG (1/8")	EACH	1.0	\$1.18	\$1.18
	HOS 5515250	SIL HTR HOSE (2-1/2")	FOOT	2.0	\$43.96	\$87.92
	HOS 5515300	SIL HTR HOSE (3")	FOOT	2.0	\$53.79	\$107.58
	HOS 5526038X50	SIL HTR HOSE (3/8")	FOOT	3.0	\$4.67	\$14.01
	HOS CT350LTRP	C/T CLAMP (2-3/4"-3-5/8")	EACH	2.0	\$18.71	\$37.42



PH: (780)573-7676

FAX: (780)573-7676

# POST OFFICE BOX 6130 BONNYVILLE, AB T9N 2G7 (4700 - 70 Street) WWW.OVERDRIVEHEAVYDUTY.COM

\*\* Reprint \*\*

Invoice: 01S45271.02

Date / Hour: 3/9/2023 2:33:04PM

Repair Order: 45271

Customer: Branch: 01

Total Invoice: \$1,320.88

\*\*\*COD\*\*\*

Page 2 of 2

	:11	Ta	

TITAN SPECIALIZED HAULING

Ship To: TITAN SPECIALIZED HAULING

Office Phone: Shop Phone: Home Phone:

Work:			Shop:						
Customer P/O:	Customer P/O: Open Date: 03/09/2023		3/09/2023	Completio	n Date: 03/	09/2023			
Add User: Stacy				Salesp	erson: Te	rri-Lyn			
HOS ETM6		HOSE	CLAMP (0.56"-0.88")		EACH	2.0		\$2.45	\$4.90
				Task 2 Subtotals	3	Parts:			\$459.84
					3.10	Labor:			\$495.84
						Task 2 Subtotals			\$955.68
	E ELECTRICAL PROB TTCHES ARE SCREW	ING UP UNDER	THE PASSENGER DOO		T START	200	rtment:	Service	
CLEANED B	ATTERY TERMINALS								
Supp. Part		Descr	iption / Ref Number		U/M	Quantity		Price	Extended Price
				Task 3 Subtotals	;	Parts:			\$0.00
					0.57	Labor			\$91.17
						Task 3 Subtotals			\$91.17
GST/HST Number:									
Detail Tax Info:						Total Parts:			\$459.84
GST No. 853645372		-	\$62.90	4.99		Total Labor:			\$798.14
		Total:	\$62.90		Inv	oice Subtotal:		\$	1,257.98
						Total Tax:			\$62.90
						Total Invoice:		\$1,	320.88
Payment Method	Terms		<u>Due Date</u>						
***COD***	COD		3/9/2023						

PLEASE PAY INVOICE, NO STATEMENT WILL BE ISSUED. NET 30 DAYS, 2% INTEREST CHARGED ON OVERDUE ACCOUNT I acknowledge:

- (1) Receipt & indebtedness of the goods & services supplied on behalf of the billing customer.
- (2) Overdrive may conduct a registry search for VIN verification on the unit outlined above if required for collection purposes on unpaid invoices related to the unit.
- (3) With any wheel removal, it is the customer's responsibility to have the wheels re-torqued within 150 km of invoiced meter reading, by a qualified technician.
- (4) With any U-Bolt removal, it is the customer's responsibility to have the U-bolts re-torqued within 5000 km of invoiced meter reading, by a qualified technician.

2	30 /		
1 / Jun	Luie's Contracting Inc.		
Date July 5/ 2	Box 7017 Edson, AB. T7E 1V3	P.O. No.	
110	Cell: (780) 712-1988 Phone: (780) 723-4037		
T: t	20 1 1 2/1 1		
Name /	in representation of the training	INV	OICE
Address			
		23	860

DATE DESCRIPTION	HOURS	PRICE	TOTAL
Moy 20 emit 251 t repair crashs, replace autor sould walk duck Ru	5		60000
Just amit TL 920 - upan cracks, replace	7		840 00
unit 14854 - upone tool fore suplace	41		49200
fine 21-1", fine 22-6 fine 23-1, fine 26-9  fine 27-8"2 fine 28-9, fine 29-6"2  PRINTED BY TRAL PRINTING GST# 84449 9346 RT0001  SUB TOTAL	,		6360
Signature Val. TOTAL			318 00



### Invoice

### **BulletProof Coatings Ltd**

6812 4th Avenue Edson AB T7E1X1 7807120443 Bulletproofcoatingsltd@outlook.com

# BILL TO Titan Specialized Hauling Ltd.



Invoice #	526
Date	Aug 25, 2023
Due date	Sep 24, 2023

Item	Quantity	Price	Amount
Fender coating	1	\$3,500.00	\$3,500.00
Payment Instruction	Su	btotal	\$3,500.00
E-TRANSFER @ bulletproofcoatings/ltd@outlook.com Mailed chegue or call for chegue to be picked up	TAI	K (5%)	\$175.00
mountain an automatical activities and promote alle		Total	\$3,675.00
	Amou	nt Due	
		5	3,675.00

We have moved to 6812 4th avenue for cheques please send to new address thank you!

Date	80) 723-4037	P.O. No.	INVOICE 2474	
DATE DESCRIPTION		HOURS	PRICE	TOTAL
enit 251		3/2		4900
repair fuel tak				170
PRINTED BY TRAIL PRINTING GST# 84446 9346 RT0001	SUB TOTAL			1100 000
	GST			245
Signature Karuth ( )	TOTAL	-		51450



1646881 Alberta Ltd

o/a Trail Tire (Edson)

BOX 6245

EDSON AB T7E 1T7

Phone: 7807280024 Fax: 7807280014

e-mail: edson@trailtire.com

OA Trail 1ire (Edson) DATE: 23 Sep 28 GST REG#: 840399901RT0001 PST REG#: INVOICE IN81146 (Copy)

SOLD TO:

TITAN SPECIALIZED HAULING LTD.



CONTACT:

MOBILE: **BUSINESS:** 

EMAIL:

HOME:

FAX:

COLOUR		VEHICLE DES	SCRIPTIO	N		PLATE	UNIT	<b>"#</b>	TAG	ODO IN
WHITE 2007 Kenworth C500B C500 6, 14.6L (				no plate	no u	nit		101		
VIN VEHICLE OPTIONS						ADV	ODO AUTH			
95053									tb	101
TIME IN		PROMISED		TERMS	GST EXE	MPT#		P.O.		ODO OUT
2:52 PM		1101111022		Net 30 days		1011-1011			RUCK 2	101
QTY	П	EM		DESCRIPTION	RIPTION		WARR	N	ET	EXT.PRICE
1 8 8 8	SC TK3356 OTRTL CO14 WT		SERVIC TECH 1 20TT SMALL 24" CHANG KB WHEEL	rOrder IN80925: CE CALL KB ETFN U H1 W/TUBE & FLAP 12  OTR TIRE RECYCLING FEE RIN EOVER 1200, 1300, 1400 24/5  TORQUE LA E RETURN AFTER 50 KM FOR A	M 8" TO				105.00 849.50 40.00 115.00 N/C	105.00 6796.00 320.00 920.00 N/C
1	SS		Payme	Supplies nt Method: OnAccount=8612.0 you for your business.	63				61.50	61.50
BILL TO	Conditions:								PARTS:	6796.0

I promise to pay the amount due upon completion of the work. I request the above work to be done and the above materials to be supplied and installed, if applicable, on the following conditions. I acknowledge the lien of the operator for the value of the work done and materials supplied. I authorize you, your agents or independent contractors to drive my vehicle for the purpose of inspection, repairs, or installations. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for. I give permission for my vehicle to be towed and impounded at my expense if left unresolved for over five days.

Store Policy:

Returns must be accompanied by original sales invoice; Special order items are non-refundable; All 12-volt and electronic parts are non-refundable; Integra Tire is not responsible for vehicles left overnight. Thank you for your patronage! Signature

6796.00 PARTS: LABOUR: 1025.00 OTHER: 381.50 8202.50 SUB-TOTAL: 410.13 GST/HST: PST: N/C

8612.63

TOTAL:

Name Address			P.O. No.	INVOICE 2376	;
DATE	DESCRIPTION		HOURS	PRICE	TOTAL
System	it 612. epais cracks in tro	ilizan.	11/2		1380
syst2-7 i	it 264.	of size	7		480 000
April 16-6 12 ce	nit (251) It til end of dade 1	to the proper	6/2		780
PRINTED BY TRAIL PRIN	TING GST# 84446 9346 RT0001	SUB TOTAL GST			26400

Signature

TOTAL