

HIGHWAY 10 EAST YORKTON, SK S3N 2X3 306-782-4313 truckproz@sasktel.net www.truckproz.com

Please make cheques payable to: 101076904 Sask Ltd

Remit payment to: Box 1059 Yorkton, SK S3N 2X3

EE24-5

Invoice: 01S13842

Date / Hour: 2025-05-05 8:43:30AM

Repair Order: 13842

Customer: Branch: 1

Total Invoice: \$2,943.61

Charge

Page 1 of 3

Bill To:

Task:

90400

Complaint: RHS WIPER BLADE WORN OUT.

Correction: REMOVED AND REPLACED WIPER BLADE.

YORKTON CONCRETE 2012 LTD

Ship To: YORKTON CONCRETE 2012 LTD

	W	ork:	Shop:				
Customer P/O: UNIT 16		NIT 16	Charris CME/	ADOWS Orig	R/O: 0 Completion	on Date: 05/0	1/2025
Unit N	lumber	: 16	Model Year: 2015	Make/Mo	odel: MACK GU714		
Туре:	TRUC	K	VIN: 1M2AX20C9FM001165	Meter: 2	215374 Kilometers		
ask:	1	0211	TANDEM/TRIDRIVE SAFETYINSPECTION		Department:	SERVIC	E
Supp.	Part		Description / Ref Number	U/M	Quantity	Price	Extended Price
				Subtotals	Parts:		\$0.00
				3.00	Labor:		\$465.00
					Task 1 Subtotals		\$465.00
	•		INSTALL REFLECTORS / REFLECTIVE TAPE FLECTORS GONE.		Department:	SERVIC	E
Corn Supp.	Part	LEANEU SURFAC	CE AREA ON REAR OF TRUCK AND INSTALLED NEW REFLECTORS. Description / Ref Number	U/M	Quantity	Price	Extende Pric
	Т	RL98176R	RED STICK ON REFLECTOR	EA	2.0	\$3.42	\$6.8
			Task 2 S	Subtotals	Parts:		\$6.84
				0.30	Labor:		\$46.50
			•		Task 2 Subtotals		\$53.34
Task:	3		REMOVE AND REPLACE AIR BAG R BAG CORDS BREAKING. B BAG WORN OUT.		Department:	SERVIC	E
Com	47 ection: C	UT AIR LINES, RE	EMOVED AIR BAGS, LIFTED FRAME AND SET NEW AIR BAGS IN PLA				
Com	47 ection: C	UT AIR LINES, RE				Price	Extended Price
Corre	41 ection: C H. Part	UT AIR LINES, RE	EMOVED AIR BAGS, LIFTED FRAME AND SET NEWAIR BAGS IN PLA FITTINGS, RECONNECTED AIR LINES AND AIRED UP TRUCK, LEAK (CHÉCKED, NO LE	AKS.	Price \$236.03	Pric
Corre	ection: C H. Part	UT AIR LINES, RI ARDWARE AND I	EMOVED AIR BAGS, LIFTED FRAME AND SET NEWAIR BAGS IN PLA FITTINGS, RECONNECTED AIR LINES AND AIRED UP TRUCK, LEAK O Description / Ref Number	CHÉCKED, NO LE U/M	AKS. Quantity		Pric \$472.0
Corre	41 ection: C H. Part 9	UT AIR LINES, RE ARDWARE AND I	EMOVED AIR BAGS, LIFTED FRAME AND SET NEWAIR BAGS IN PLA FITTINGS, RECONNECTED AIR LINES AND AIRED UP TRUCK, LEAK O Description / Ref Number MACK AIRBAG (#21217038)	CHÉCKED, NO LE U/M EA	AKS. Quantity 2.0	\$236.03	\$472.0 \$472.0
Corre	41 ection: C H. Part 9	UT AIR LINES, RI ARDWARE AND I 865 3R81/2FLW	EMOVED AIR BAGS, LIFTED FRAME AND SET NEWAIR BAGS IN PLA FITTINGS, RECONNECTED AIR LINES AND AIRED UP TRUCK, LEAK O Description / Ref Number MACK AIRBAG (#21217038) 1/2 GRADE 8 FLAT WASHER	CHÉCKED, NO LE U/M EA EA	AKS. Quantity 2.0 4.0	\$236.03 \$0.25	\$472.0 \$472.0 \$1.0 \$13.0
Corre	Part 9	UT AIR LINES, RI ARDWARE AND I 865 GR81/2FLW C14726B	EMOVED AIR BAGS, LIFTED FRAME AND SET NEW AIR BAGS IN PLA FITTINGS, RECONNECTED AIR LINES AND AIRED UP TRUCK, LEAK O Description / Ref Number MACK AIRBAG (#21217038) 1/2 GRADE 8 FLAT WASHER 3/8 PTC X 1/4 NPT TEE	U/M EA EA	AKS. Quantity 2.0 4.0 1.0	\$236.03 \$0.25 \$13.02	

Quantity Price U/M Supp. Part Description / Ref Number Price 20" TRICO FORCE BLADE 25200 \$20.38 EΑ 1.0 \$20.38 Task 4 Subtotals Parts: \$20.38

WINDSHIELD WIPER /WASHER REPAIR

Task 3 Subtotals

2.00

0.30

** See Last Page for Invoice Total **

Department: SERVICE

\$508.33

\$310.00

\$818.33

Extended

\$46.50

Parts:

Labor:

Labor:

Task 3 Subtotals



HIGHWAY 10 EAST YORKTON, SK S3N 2X3 306-782-4313 truckproz@sasktel.net www.truckproz.com

Please make cheques payable to: 101076904 Sask Ltd

Remit payment to: Box 1059 Yorkton, SK S3N 2X3

Invoice: 01S13842

Date / Hour: 2025-05-05 8:43:30AM

Repair Order: 13842

Customer: Branch: 1

Total Invoice: \$2,943.61

Charge

Page 2 of 3

Bill To:

YORKTON CONCRETE 2012 LTD

Ship To: YORKTON CONCRETE 2012 LTD

	Work:		Shop:				
Custome	er P/O:	UNIT 16	UNIT 16 Charris	CMEADOWS	Orig R/O:	0 Completion Da	te: 2025-05-01
					Task	4 Subtotals	\$66.88
ask:	5	90300	BODY REPAIR		-	Department: S	ERVICE
Task:	5	90300				Depart	ment: S
	OU BOX	ON RHS L	DOSE TO MOUNTS - REMOVE BOX AND	MOUNTS AS PER CUSTOMER			
Comp	ction: T	DRCHED BOLTS ANI	DOSE TO MOUNTS - REMOVE BOX AND D REMOVED TOOLBOX, PLACED ITEMS ED BOLTS INTO HOLES.		BOX BRACKI	ET BOLTS AND REMOVED	•

Supp.	Part		Description / Ref Number	U/M	Quantity	Price	Price
		FDRW	FENDER WASHER	EA	4.0	\$1.10	\$4.40
		GR85/8B	5/8 GRADE 8 BOLT	EA	4.0	\$6.65	\$26.60
		GR85/8FLW	5/8 GRADE 8 FLAT WASHER	EA	8.0	\$0.96	\$7.68
		STL5/8LN	5/8 STEEL LOCK NUT (NC)	EA	4.0	\$1.16	\$4.64
			1	ask 5 Subtotals	Parts:		\$43.32
				1.00	Labor:	\$	\$155.00
					Task 5 Subtotals		198.32

Task: 6 90300 BODY REPAIR Department: S	SERVICE
---	---------

Complaint: LHS HOOD GUIDE/SPRING MOUNT MISSING.

Correction: CUSTOMER WILL REPAIR.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Price
	20802371	MACK LHS HOOD GUIDE	EA	1.0	\$144.66	\$144.66
	82392414	MACK GU HOOD SPRING	EA	1.0	\$114.55	\$114.55
	FR7	FREIGHT		1.0	\$20.00	\$20.00
			Task 6 Subtotals	Parts:		\$259.21
			0.00	Labor:		\$0.00
				Miscellaneous:		\$20.00
				Task 6 Subtotals		\$279.21

Task: 7 30900 REMOVE AND REPLACE BELTS / IDLER / TENSIONER Department: SERVICE

Complaint: ALTERNATOR BELT MISSING A RIB.

Correction: REMOVED FAN BELT, PULLED ALTERNATOR BELT OFF AND PULLED OUT BOTTOM OF ENGINE BAY. ORDERED NEW A/C BELT.
INSTALLED NEW ALTERNATOR BELT AND REINSTALLED FAN BELT, ENSURED EVERYTHING WAS STRAIGHT AND RAN PROPERLY,
STARTED TRUCK AND MADE SURE BELTS WERE RUNNING CORRECTLY, ALL GOOD.

Supp.	Part	Description / Ref Number	U/	M	Quantity	Price	Price
	23961760	MACK BELT	EA	4	1.0	\$111.09	\$111.09
	FR7	FREIGHT			1.0	\$20.00	\$20.00
			Task 7 Subtotals		Parts:		\$111.09
			•	1.00	Labor:		\$155.00
					Miscellaneous:		\$20.00
					Task 7 Subtotals		\$286.09

Task: 8 16250 REPAIR FENDER(S)

Complaint: RHS FRONT FENDER PLATE CRACKED AND LOOSE.

Department: SERVICE



HIGHWAY 10 EAST YORKTON, SK S3N 2X3 306-782-4313 truckproz@sasktel.net www.truckproz.com

Please make cheques payable to: 101076904 Sask Ltd

Remit payment to: Box 1059 Yorkton, SK S3N 2X3

Invoice: 01S13842

Date / Hour: 2025-05-05 8:43:30AM

Repair Order: 13842 Customer: Branch: 1

Total Invoice: \$2,943.61 ****Charge****

Page 3 of 3

Bill To:

Charge

YORKTON CONCRETE 2012 LTD

Ship To: YORKTON CONCRETE 2012 LTD

Work:		Shop:						
Customer P/O:	UNIT 16	Charris	CMEADOWS	Orig	R/O: 0	Completion Da	ıte: 2	025-05-01
	DRILLED HOLES IN PLATE TO BACK OF FENDER	TO BOLT BEHIND FENDER TO PRE R.	EVENT FURTHER CRA	ACKING, DR	ILLED HOLES IN F	ENDER AND		
Supp. Part		Description / Ref Number		U/M	Quantity		Price	1 1100
			Task 8 Subtot	als	Parts:			\$0.00
				0.80	Labor:			\$124.00
					Task 8 Subtotals			\$124.00
Task: 9 9050 Complaint: RHS WIN		ND REPLACE GLASS			Depa	artment: S	ERVI	Œ
	GLASS - CRYSTAL GLASS R	EMOVED AND REPLACED RHS WI	NDSHIELD.					Extended
Supp. Part		Description / Ref Number		U/M	Quantity		Price	1 7100
SLGLAS	S	REPLACED RHS WINDSHIEL	_		1.0	\$	298.64	\$298.64
			Task 9 Subtot		Parts:			\$0.00
				0.00	Labor:			\$0.00
					Miscellaneous:			\$298.64
					Task 9 Subtotals			\$298.64
Detail Tax Info:					Total Parts:			\$949.17
GST# 817668478RT00 PST	01	\$134.05 \$128.60	8.40		Total Labor:		\$	1,302.00
Sales Tax		\$0.00		Total I	Miscellaneous:			\$338.64
	Total:	\$262.65			OP SUPPLIES:			\$91.15
				lnv	oice Subtotal:		\$	2,680.96
					Total Tax:			\$262.65
					Total Invoice:		\$2	,943.61
Payment Method	<u>Terms</u>	<u>Due Date</u>						

ALL PARTS WITH CORE CHARGE ARE SUBJECT TO CHARGE BACK PENDING VENDOR INSPECTION *** WARRANTY ITEMS SUBJECT TO CHARGEBACK PENDING VENDOR CLAIM & REJECTION**

2025-06-04

NET 30

^{***} ANY WHEEL OR U-BOLT THAT HAS BEEN REMOVED OR REPLACED, NEEDS TO BE RETORQUED TO SPEC. IT IS CUSTOMER RESPONSIBILTY TO MAKE SURE THAT THIS IS DONE AT THE CORRECT INTERVAL***

^{**} NO RETURNS ON INSTALLED ELECTRICAL COMPONENTS ***

^{* 101076904} SASK LTD IS NOT RESPONSIBLE TO ENSURE COMPLIANCE OF REGIONAL REGULATIONS *

CAB CARD TAX EXEMPTIONS ALLOWED: PENDING CHARGES TO YOU AT ANY DATE; SHOULD THE TAXING AUTHORITY DETERMINE THAT ABOVE GOODS ARE TAXABLE. PST CREDITS WILL NOT ISSUED ONCE THEY HAVE BEEN PAID.
#817668478RT0001