

VERSATILE





PO Box 743, Highway 16 East, Lloydminster SK S9V 1C1 • www.novlanbros.com GST# 10980 4724 RT0001

Phone: (306) 825-6141 • Fax: (306) 825-9896 • Toll Free: 1-877-344-4433


SO # 302231

SERVICE ORDER CUSTOMER COPY



AKS

User



Advisor	Damond Souster	Promised	07/29/2022 11:00 PM	Tag#
Shop	S1	Opened	07/29/2022 3:15 PM	Location
Priority		Cashiered	08/18/2022 2:09 PM	PO#

Licens	е	Odom In 1294	Odom Out 1294	In Service Date	Stock No
Year	Make	Mode	el	Model Number	Colour
2022	JOB	MISC	JOB		
Vehicle	D No	Sellin	ng Dealer	Extended Warranty	Delivery Date
//					
Engine				Fleet #	

Request	Description					Job	CSR	Status	
MISC	REPLACE KNIVES	S AND GUARDS				1	DCS	Original	
Labour	Description						Type	Amount	
MISC	LABOUR						CA	1,200.00	
Part		Description	Shp	Bin	Type		Price	Amount	
86615982BDS		GUARD	61	NWALL	CSO		18.50	1,128.50	
MCD 118302		*GUARD RH	1	1325	CSO		32.75	32.75	
MCD 118301		*GUARD LH	1	1323	CSO		32.75	32.75	
MCD 124344		* SPCL GUARD	1	I132	CSO		38.37	38.37	
MCD 124338		* SPCL GUARD	1	I144	CSO		45.56	45.56	
MCD 118499		*GUIDE PACK OF 25	2	J317	CSO		6.73	13.46	
MCD 118154		BOLT	2	DR07R6	CSO		0.45	0.90	
MCD 129297		WEARPLATE	1	J213	CSO		19.68	19.68	
86521606		NUT FLANGE	2	DR01R1	CSO		0.41	0.82	
N716		NUT	10	BOLTBN	CSO		0.18	1.80	
MCD 120558		BOLT SPECIAL	10	DR18R4	CSO		2.84	28.40	
MCD 118345		*GUARD	6	1221	CSO		28.39	170.34	
Rate	179.00		F	Parts Total				1,513.33	
Correction	- Removed knife c	utter bars from each side of header	L	abour Total				1,200.00	
	- Removed all gua		F	Request Sub	o-total			2,713.33	
		Joney Doe guerde							

- Removed all guards
 - Installed all new Honey Bee guards
 - Replaced one plastic skid plate
 - Put new knife sections together using Macdon kit
 - Put old knife head on new cutter bar (both sides)
 - Slid cutter bars back into each side
 - Bent guards straight
 - Put pins back in cutter bar heads
 - Set knife hold downs to specified gap
 - Set center guard to specified gap
 - Cleaned up, put old guards in boxes
 - Ran knife, was heating up in several spots
 - Ran a string along guard tips and bent the guards straight
 - Cutter bars were heating up on each end, found that the knife was too low
 - Adjusted pivot arm upwards and retightened
 - Ran again, did not heat up
 - Checked hold down gaps again
 - Cleaned up and put old parts on header canvases

Request	Description	Job	CSR	Status
MISC	REPLACE RH DRAPER	2	DCS	Original
			_	
Labour	Description		Type	Amount

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE ACCOMPANYING WORK ORDER.



VERSATILE





PO Box 743, Highway 16 East, Lloydminster SK S9V 1C1 • www.novlanbros.com GST# 10980 4724 RT0001

Phone: (306) 825-6141 • Fax: (306) 825-9896 • Toll Free: 1-877-344-4433

SO # 302231

Printed

SERVICE ORDER CUSTOMER COPY




Page

132.00

225.00

357.00

AKS



07/11/2025 8:45:52 AM

Advisor Damond Souster Promised 07/29/2022 11:00 PM Tag# Shop 07/29/2022 3:15 PM Location Opened **Priority** 08/18/2022 2:09 PM PO# Cashiered

Licens	e	Odom In 1294	Odom Out 1294	In Service Date	Stock No
Year 2022	Make JOB	Mode MISC		Model Number	Colour
Vehicle ID No Selling Dealer		Extended Warranty	Delivery Date		
Engine	•			Fleet #	

Parts Total

Labour Total

Request Sub-total

User

Part	Description	Shp	Bin	Туре	Price	Amount
MCD 220638	DRAPER 35F	1	UPPR05	CSO	1,436.20	1,436.20
MCD 132451	SET SCREW	1	DR37R4	CSO	6.20	6.20
MCD 255410	ROLLER - D	1	P275	CSO	833.21	833.21
MCD 120058	ARM ROLLER SUPPORT	1	K432	CSO	39.15	39.15
47471	KEY WOODRUFF	1	DR10R3	CSO	6.35	6.35
Rate	179.00		Parts Total			2,321.11
Correction	- Loosened draper tension		Labour Total			562.50
	- Removed draper canvas		Request Sul	o-total		2,883.61

- Ran new canvas in the deck and did up
- Tensioned new canvas
- Ran header and shortly after RH draper quit turning
- Inspected and found drive roller was not turning
- Removed drive motor to find key way was sheered and new roller was needed
- Undid the draper canvas and removed the drive roller
- Support bracket was broke as well
- Put new roller in along with support bracket
- Installed new key way into the motor and reinstalled the motor
- Did canvas back up and re tension
- Ran header again to verify repair

Request	Description				Job	CSR	Status
MISC	FLOAT CYLINDER DOESN'T MOVE FULLY				3	DCS	Original
Labour	Description					Type	Amount
MISC	LABOUR					CA	150.00
Rate	179.00		Labour Total				150.00
Correction	 Blew chaff out of arms and verified that the float cylinder was moving wasn't reading properly Adjusted left and right sensors so that they read the same value 	g fully just	Request Sul	o-total			150.00
Request	Description				Job	CSR	Status
MISC	HEADER HEIGHT LINKAGE DISCONNECTED				4	DCS	Original
Labour MISC	Description LABOUR					Type CA	Amount 225.00
Part	Description	Shp	Bin	Type	F	Price	Amount
MCD 183846	KIT - SENSOR HALL EFFECT	1		CSO	10	04.92	104.92
MCD 163676	SUPPORT SENSOR	1		CSO	2	27.08	27.08

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE ACCOMPANYING WORK ORDER.

Rate

179.00



VERSATILE





PO Box 743, Highway 16 East, Lloydminster SK S9V 1C1 • www.novlanbros.com GST# 10980 4724 RT0001

Phone: (306) 825-6141 • Fax: (306) 825-9896 • Toll Free: 1-877-344-4433




SO # 302231

SERVICE ORDER CUSTOMER COPY



Page

AKS



Advisor Damond Souster Promised 07/29/2022 11:00 PM Tag# Shop 07/29/2022 3:15 PM Location Opened **Priority** 08/18/2022 2:09 PM PO# Cashiered

Licens	e	Odom In 1294	Odom Out 1294	In Service Date	Stock No		
Year 2022	Make JOB	Mode		Model Number	Colour		
2022 JOB MISC JOB Vehicle ID No Selling Dealer		Extended Warranty	Delivery Date				
// Engine	•		Fleet #				

User

Correction

- Header height linkage was missing sensor mounting bracket and sensor that bolt to the header lift cylinder
- Ordered bracket and sensor
- Attached new sensor to bracket then attached the assembly to the lift cylinder
- Hooked up the linkage
- Verified header height sensor was reading and return to cut was working properly

Request	Description				Job	CSR	Status
MISC	CHECK A/C (MIGHT HAVE A LEAKING HOSE)				5	DCS	Original
Labour	Description					Type	Amount
MISC	LABOUR					CA	756.00
Part	Description	Shp	Bin	Type		Price	Amount
MCD 183273	RECEIVER D	1	M972	CSO	1	27.25	127.25
MCD 109617	COMPRESSOR	1	M932	CSO	8	329.91	829.91
FREON	R134A	5	XXXXXX	CSO		46.00	230.00
Rate	179.00		Parts Total				1,187.16
Correction	- Checked A/C found system was low		Labour Total				756.00
	Evacuated system and performed leak test Leak test failed		Request Sul	o-total			1,943.16
	 Hooked up nitrogen bottle and pressurised system 						

- Found relief valve on back of compressor was popped and leaking by
- Replaced compressor and receiver dryer
- Performed another leak test and it passed
- Filled system back up with 5 lbs of freon and checked that it was working
- Wasn't performing well but found condenser and rad were plugged
- Blew the rads out and retested
- A/C was now blowing cold air

Total Invoice	8,753.27
GST	416.82
Sub-Total	8,336.45
Supplies	289.35
Parts	5,153.60
Labour	2,893.50

CHEQUE 8,753.27

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE ACCOMPANYING WORK ORDER.