



TAX INVOICE

MFC Contractors

Invoice Date
18 Jan 2023

Invoice Number
INV-1930

Reference
330 EXCAVATOR

ABN
35 651 028 081

MM Diesel Pty Ltd
2 Jopling St
BALLAN VIC 3342
AUSTRALIA
Email:
mmdiesels1@gmail.com
Mobile: 0448 662 920

Description	Quantity	Unit Price	GST	Amount AUD
330 EXCAVATOR- Travel to rokewood wind farm to hithich 330lc excavator faulty air-conditioning Check system found broken wire to pump remove damaged sections and test ok Check hino water truck air-conditioning system found faulty compressor ZEU-573 Check air-conditioning system on bomag BW213d roller check pressures low adjust belt and leak test regas check operation fair may need evaporator cleaned Check air-conditioning system on proquip r292 cat cp533e roller clean cab filters and blow out evaporator check pressures ok	1.00	1,000.00	10%	1,000.00
			Subtotal	1,000.00
			TOTAL GST 10%	100.00
			TOTAL AUD	1,100.00
			Less Amount Paid	1,100.00
			AMOUNT DUE AUD	0.00

Due Date: 1 Feb 2023

PLEASE NOTE TERMS & PAYMENT DETAILS:

Invoices are due for payment 14 days following the issue date, we thank you for your business.

PAYMENT DETAILS:

Payments can be made via direct deposit.

Direct Deposit

Bendigo Bank Account Name: MM Diesels Pty Ltd

BSB: 633 000 Account: 184712891

Please note late payments may incur administration and late payment fees.



PAYMENT ADVICE

To: MM Diesel Pty Ltd
2 Jopling St
BALLAN VIC 3342
AUSTRALIA
Email: mmdiesels1@gmail.com
Mobile: 0448 662 920

Customer MFC Contractors
Invoice Number INV-1930

Amount Due **0.00**
Due Date 1 Feb 2023

Amount Enclosed

Enter the amount you are paying above



- o ABN: 18132176008
- o P.O.Box 143 brown hill, victoria, australia, 3350
- o Ph/fax: 03 53344333
- o Mobile: 0437 831643

Risk assessment, Hazard identification And Control

Company: MFC Contractors Plant No. N/A

Plant Make & Model: 2006 Hino Water Truck

VIN No: JHDFM1JRPXXX10160 Registration: ZEU573

Hour meter reading/ odometer: 242,584km

Date: 25th July 2022

Assessor: Stuart Parry

A handwritten signature in black ink, appearing to read 'S Parry', is written over a large, faint, grey watermark of the AusPlant Enterprises logo.

Note:

- The ASSESSMENT WITHIN IS A GUIDE, IDENTIFYING HAZARDS ASSOCIATED WITH THE PLANT SPECIFICALLY. Work place hazards have not been identified.
- A job safety analysis (J.s.a) is required to identify work place hazards.
- Plant operators must observe and adhere to the. J.s.a when operating plant.



General information:

The owner/ operator of the plant/ equipment assessed should also perform regular inspections as recommended in the Operation and Maintenance Manual. All procedures and control methods are to be maintained to required levels to reduce the level of risk to any person. Where modifications, alterations or additions are made to the plant/ equipment the control methods and assessment should be clearly identified. The Risk Assessment, Hazard Identification and Control report should be completed on a regular basis for good practice. An independent report should be completed annually.

Disclaimer:

The Risk Assessment, Hazard Identification and Control report within provides the relevant assessment information required by the Company identified for the Plant/ Equipment also identified. This assessment/ report does not eliminate the Owner/ Operator from their responsibilities in maintaining the plant / equipment as outlined in the OH & S Regulations. The distribution or copying of this document for the benefit of a third party is prohibited. The assessment/ report within will be deemed null and void if the plant/ equipment has been modified, altered or has had additional components fitted. If there are hazards identified that require urgent action, this must be completed within 21 days from the date displayed, failure to comply will also deem this assessment/ report null and void.



HAZARD	RISK IDENTIFIED			CONTROL METHODS IMPLEMENTED	FURTHER CONTROLS IMPLEMENTED	DATE OF HAZARD RECTIFICATION
	YES	NO	N/A			
1/ Can anyone's body parts or clothing become entangled with parts in motion.	✓			Fan Guard Installed Warnings in O & M Manual	Warning decals fitted	
2/ Can a person be crushed due to:						
2a/ Material falling off water truck?	✓			Driver Competent Warning in O & M Manual		
2b/ Lack of capacity for truck to be slowed, stopped or immobilized?	✓			Park Brake Fitted Regular checks carried out		
2c/ The water truck tipping or rolling over?	✓			Warning in O& M Manual Operator to assess conditions		
2d/ Parts of the water truck collapsing?	✓			Operator to maintain vehicle Warning in O & M Manual		
2e/ Being thrown off or under water truck?	✓			Seat belt provided for occupants Warning in O & M Manual		
2f/ Becoming trapped between plant or fixed structures.	✓			Reverse Alarm fitted Warning in O & M Manual	Warning decals fitted	
3/ Entanglement. Can any person become entangled in moving parts ?	✓			Guarding fitted Warning decals fitted Warning in O & M Manual		



HAZARD	RISK IDENTIFIED			CONTROL METHODS IMPLEMENTED	FURTHER CONTROLS IMPLEMENTED	DATE OF HAZARD RECTIFICATION
	YES	NO	N/A			
4/ Can anyone be cut, stabbed, punctured or struck due to:						
4a/ Coming in contact with sharp or flying object ?	✓			Warning in O & M Manual		
4b/ Coming in contact with moving part when testing, inspecting, operating, maintenance or cleaning ?	✓			Warning decals fitted Warning in O & M Manual		
4c/ Mobility of the water truck?	✓			Reverse Alarm fitted Clear working environment Warning in O & M Manual	Revolving light fitted	
4d/ Uncontrolled or unexpected movement of plant?	✓			Park Brake fitted Regular check braking by driver. Operator competent		
5/ Can any person fall or slip due to :						
5a/ Inadequate work platform, floor or walking surface ?	✓			Non Slip surfaces are provided Warning decals fitted		
5b/ Lack of adequate stairs or steps ?	✓			Grab Rails & Slip resistant steps provided. Warning decals fitted		
5c/ Inadequate grab rails, hand or guard rails ?	✓			Grab, Hand and Guard rails provided Warning decals fitted		
5d/ Inadequate cleaning of plant operating environment ?	✓			Driver to ensure clean working environment		



HAZARD	RISK IDENTIFIED			CONTROL METHODS IMPLEMENTED	FURTHER CONTROLS IMPLEMENTED	DATE OF HAZARD RECTIFICATION
	YES	NO	N/A			
6/ Can body parts be sheared between parts of truck?	✓			Warning decals fitted Warning in O & M Manual		
7/ Can a person be burnt when contacting moving parts or the surface of the truck?	✓			Warning decals fitted Warning in O & M Manual	Protection provided with guarding	
8/ Can a person be effected by fluids under high pressure ?	✓			Relief valves fitted, operator to inspect. Warning decals fitted	Sufficient guarding fitted	
9/ Can a person be injured by electric shock or burnt due to ?						
9a/ Truck contacting with electrical conductors ?	✓			Warning decal in cabin Warning in O & M Manual		
9b/ Truck operating to close to electrical conductors ?	✓			As Above		
9c/ Overloading electrical circuit of water truck?	✓			All circuits protected by fuses		
9d/ Damaged wiring and or switches ?	✓			Driver to maintain condition of wiring. Warning in O & M Manual		
10/ Can a person be injured by an explosion triggered by the operation of the truck?	✓			Warning decals fitted near battery Warning in O & M Manual	Batteries secured in compartment	



HAZARD	RISK IDENTIFIED			CONTROL METHODS IMPLEMENTED	FURTHER CONTROLS IMPLEMENTED	DATE OF HAZARD RECTIFICATION
	YES	NO	N/A			
11/ Can a person be effected by or injured due to :						
11a/ Fumes ?	✓			Exhaust directed away from cabin		
11b/ Noise ?	✓			Cabin meets all standards Refer to Noise Report		
12/ Does the operator of plant provide or acknowledge :						
12a/ Having the required certificate or qualification to operate the water truck?	✓			Driver to show competency or provide competence card, license		
12b/ Read, understand and accessibility of Operator Manual for water truck?	✓			O & M manual supplied Driver understands the Operating requirements		
12c/ Requirements for Pre-Start checks ?	✓			Daily routine checks carried out and available	Record Book supplied and in cabin	
12d/ Correct servicing and maintenance of water truck?	✓			Records maintained by company and available upon request		
13/ Can anyone be injured due to insufficient knowledge of Operation and Safety Information ?	✓			O & M Manual tethered to seat and accessible to operator Warning decals fitted suggesting knowledge of plant operation		



**Matthew Mullane**2 Jopling Street
Ballan Vic 3342
AustraliaPhone: 0448662920
ABN: 93 113 870 069

Invoice: IV00000003956

Tax Invoice

Invoice date: 23/08/2021

Bill to:MFC Contractors
314 Ballan Daylesford Rd
Ballan Vic 3342
Australia**Due:**

06/09/2021

Purchase Order:

ZEU573

ITEM	DESCRIPTION		UNITS	UNIT PRICE (ex GST)	TAX TYPE	AMOUNT (ex GST)
Labour	ZEU573 241923kms INSPECT AIR ISSUE, FIND TO BE FAULTY FOOT VALVE, REMOVE AND REPLACE.	Hrs	3	100.00	GST	300.00
1G6530	Foot Brake Valve	Qty	1	475.00	GST	475.00

Sub-Total (ex GST): \$775.00
GST: \$77.50
Total (inc GST): \$852.50
Amount Paid: \$0.00
AMOUNT DUE: \$852.50

Notes**How to Pay** Due 06/09/2021**Bank Deposit via EFT**

Bank: Bendigo Bank
Name: MM Diesels Pty Ltd
BSB: 633000
AC#: 184712891
Ref#: IV00000003956



TAX INVOICE

MFC Contractors

Invoice Date
15 Feb 2023

Invoice Number
INV-2025

Reference
ZEU573 HINO

ABN
35 651 028 081

MM Diesel Pty Ltd
2 Jopling St
BALLAN VIC 3342
AUSTRALIA
Email:
mmdiesels1@gmail.com
Mobile: 0448 662 920

Description	Quantity	Unit Price	GST	Amount AUD
ZEU573 HINO- TRAVEL TO ROKEWOOD WIND FARM TO HINO WATER TRUCK, FAULTY AIR CONDITIONING COMPRESSOR, REMOVE AND REPLACE COMPRESSOR AND DRYER, REFILL SUPPLY NEW IDLER PULLEY, REGAS AND LEAK TEST	1.00	900.00	10%	900.00
			Subtotal	900.00
			TOTAL GST 10%	90.00
			TOTAL AUD	990.00

Due Date: 1 Mar 2023

PLEASE NOTE TERMS & PAYMENT DETAILS:

Invoices are due for payment 14 days following the issue date, we thank you for your business.

PAYMENT DETAILS:

Payments can be made via direct deposit.

Direct Deposit

Bendigo Bank Account Name: MM Diesels Pty Ltd

BSB: 633 000 Account: 184712891

Please note late payments may incur administration and late payment fees.

PAYMENT ADVICE

To: MM Diesel Pty Ltd
2 Jopling St
BALLAN VIC 3342
AUSTRALIA
Email: mmdiesels1@gmail.com
Mobile: 0448 662 920

Customer MFC Contractors

Invoice Number INV-2025

Amount Due 990.00

Due Date 1 Mar 2023

Amount Enclosed

Enter the amount you are paying above



TAX INVOICE

MFC Contractors

Invoice Date
25 Nov 2022

Invoice Number
INV-1691

Reference
SUPPLY - ZEU573

ABN
35 651 028 081

MM Diesel Pty Ltd
2 Jopling St

BALLAN VIC 3342
AUSTRALIA

Email:
mmdiesels1@gmail.com
Mobile: 0448 662 920

Description	Quantity	Unit Price	GST	Amount AUD
CLAMP - EXHAUST PIPE	1.00	38.00	10%	38.00
CLAMP - EXHAUST PIPE	3.00	76.00	10%	228.00
			Subtotal	266.00
			TOTAL GST 10%	26.60
			TOTAL AUD	292.60

Due Date: 9 Dec 2022

PLEASE NOTE TERMS & PAYMENT DETAILS:

Invoices are due for payment 14 days following the issue date, we thank you for your business.

PAYMENT DETAILS:

Payments can be made via direct deposit.

Direct Deposit

Bendigo Bank Account Name: MM Diesels Pty Ltd

BSB: 633 000 Account: 184712891

Please note late payments may incur administration and late payment fees.

PAYMENT ADVICE

Customer MFC Contractors

Invoice Number INV-1691

Amount Due **292.60**

Due Date 9 Dec 2022

Amount Enclosed

Enter the amount you are paying above

To: MM Diesel Pty Ltd
2 Jopling St
BALLAN VIC 3342
AUSTRALIA
Email: mmdiesels1@gmail.com
Mobile: 0448 662 920



TAX INVOICE

MFC Contractors

Invoice Date
7 Mar 2023

Invoice Number
INV-2126

Reference
ZEU573

ABN
35 651 028 081

MM Diesel Pty Ltd
2 Jopling St

BALLAN VIC 3342
AUSTRALIA

Email:
mmdiesels1@gmail.com
Mobile: 0448 662 920

Description	Quantity	Unit Price	GST	Amount AUD
COMPRESSOR AIR COND	1.00	1,200.00	10%	1,200.00
			Subtotal	1,200.00
			TOTAL GST 10%	120.00
			TOTAL AUD	1,320.00
			Less Amount Paid	1,320.00
			AMOUNT DUE AUD	0.00

Due Date: 21 Mar 2023

PLEASE NOTE TERMS & PAYMENT DETAILS:

Invoices are due for payment 14 days following the issue date, we thank you for your business.

PAYMENT DETAILS:

Payments can be made via direct deposit.

Direct Deposit

Bendigo Bank Account Name: MM Diesels Pty Ltd

BSB: 633 000 Account: 184712891

Please note late payments may incur administration and late payment fees.

PAYMENT ADVICE

Customer MFC Contractors

Invoice Number INV-2126

Amount Due 0.00

Due Date 21 Mar 2023

Amount Enclosed

Enter the amount you are paying above

To: MM Diesel Pty Ltd
2 Jopling St
BALLAN VIC 3342
AUSTRALIA
Email: mmdiesels1@gmail.com
Mobile: 0448 662 920