



Work Order

WINDREM

Vehicle Code: 77

Work Order #: 31919
 Issued: 2025-01-09 7:50 AM
 Status: Completed
 Date: 2025-01-09
 Employee: GARNET
 Name: MILES
 Page #: 1

Year:	2016	Alt. Vehicle ID:	
Make:	INTERNATIONAL	WO Type:	
Model:	DF677	Est. Downtime:	
License No:	AZ 26443	Hour Estimate:	
VIN #:	3HTNUAPT9GN733606	Reference No:	
Meter:	1: 1213463 2: 0	Requested By:	
Meter Type:	Kilom Hours	Reason:	
Transmission:		Delay Code:	
Engine:	CUMMINS ISX 15		
Engine Serial #:			

Work Order Notes:

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

REPAIR:
 REPLACED ALL 3 BATTERIES BECAUSE TRUCK WAS CRANKING SLOW AND IT DIDNT HOLD A LOAD TEST AND CLEANED ALL CABLE ENDS

Services Performed

Service Code	Description	Technician	Actual Hours	Hours	Cost
4005	ELEC - BATTERY CHK	GARNET		0.25	\$12.50
	COMMENT				
4006	ELEC - BATTERY REPLACE	GARNET		0.75	\$37.50
	COMMENT				
Total Service				1.00	\$50.00

Parts Used

Part Number	Part Description	Service Code	Quantity	Cost (each)	Total
FLTBTGA31SS	BATTERY, SCREW TOP, GRP31S	4006	3.00	\$139.99	\$419.97
Total Parts					\$419.97
Total Parts and Service					\$469.97

WINDREM



Work Order

Vehicle Code: 77

Year: 2016
 Make: INTERNATIONAL
 Model: DF677
 License No: AZ 26443
 VIN #: 3HTNUAPT9GN733606
 Meter: 1: 1193110 2: 0
 Meter Type: Kilom Hours
 Transmission:
 Engine: CUMMINS ISX 15
 Engine Serial #:

Alt. Vehicle ID:
 WO Type:
 Est. Downtime:
 Hour Estimate:
 Reference No:
 Requested By:
 Reason:
 Delay Code:

Work Order #: 31622
 Issued: 2024-09-25 4:53 PM
 Status: Completed
 Date: 2024-10-22
 Employee:
 Name:
 Page #: 1

Vendor: WINS
 Name: Winslow Gerolamy Mo
 Address: 1018 Lansdowne Stre
 City/State: Peterborough ON

Work Order Notes:

REPAIR:
 REPLACE ENGINE HARNESS (FAILED ENGINE TO BODY HARNESS INTERCONNECT)

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

Services Performed

Service Code	Description	Technician	Actual Hours	Hours	Cost
4000	ELEC - MISC			1.00	\$0.00
	COMMENT				
Total Service				1.00	\$0.00

Parts Used

Part Number	Part Description	Service Code	Quantity	Cost (each)	Total
OUTSIDE SERVICE	WIRING HARNESS REPLACEMENT	4000	1.00	\$4,054.72	\$4,054.72
Total Parts					\$4,054.72
Total Parts and Service					\$4,054.72



Work Order

WINDREM

Vehicle Code: 77

Work Order #: 31623
 Issued: 2024-09-24 6:30 AM
 Status: Completed
 Date: 2024-10-23
 Employee:
 Name:
 Page #: 1

Year:	2016	Alt. Vehicle ID:	
Make:	INTERNATIONAL	WO Type:	WARRANTY
Model:	DF677	Est. Downtime:	
License No:	AZ 26443	Hour Estimate:	
VIN #:	3HTNUAPT9GN733606	Reference No:	
Meter:	1: 1196745 2: 0	Requested By:	
Meter Type:	Kilom Hours	Reason:	
Transmission:		Delay Code:	
Engine:	CUMMINS ISX 15		
Engine Serial #:			

Vendor: WINS
 Name: Winslow Gerolamy Mo
 Address: 1018 Lansdowne Stre
 City/State: Peterborough ON

Work Order Notes:

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

DIAGNOSE STEERING SHAFT CLUNKS : SLIP SHAFT BINDING AND BEARING WORN - RE&RE STEERING SHAFT WARRANTY)

DIAGNOSE ENGINE WARNING LIGHT ON: HIGH EXHAUST GAS TEMP INDICATOR - WIRING HARNESS REPLACED ON WO 454252

FAULTY WIRING FOR FUEL PRESSURE SENSOR - BILLING FOR DIAGNOSIS, CONNECTOR, TERMINAL, ETC

DIAGNOSE ENGINE OIL LEAK: POS INNER FRONT COVER (FOUND SPLIT) - HAD TO DRILL OUT 8 BROKEN BOLTS THROUGH RAD , FRONT COBER & BLOCK

DIAGNOSE OIL PRESSURE GAUGE NOT WORKING - FOUND OIL LEAKING OUT SENDER UNIT - SENDER REPLACED

INV 454228

Services Performed

<u>Service Code</u>	<u>Description</u>	<u>Technician</u>	<u>Actual Hours</u>	<u>Hours</u>	<u>Cost</u>
6018	CHASSIS - STEERING			1.00	\$0.00
	COMMENT				
5037	ENGINE- SENSOR			1.00	\$0.00
	COMMENT				
4000	ELEC - WIRING			1.00	\$0.00
	COMMENT				
Total Service				3.00	\$0.00

Parts Used

<u>Part Number</u>	<u>Part Description</u>	<u>Service Code</u>	<u>Quantity</u>	<u>Cost (each)</u>	<u>Total</u>
OUTSIDE SERVICE	NON WARRANTY SERV & PARTS	0100	1.00	\$3,950.26	\$3,950.26
Total Parts					\$3,950.26
Total Parts and Service					\$3,950.26

WINDREM



Work Order

Vehicle Code: 77

Year:	2016	Alt. Vehicle ID:	
Make:	INTERNATIONAL	WO Type:	
Model:	DF677	Est. Downtime:	
License No:	AZ 26443	Hour Estimate:	
VIN #:	3HTNUAPT9GN733606	Reference No:	
Meter:	1: 1246976 2: 0	Requested By:	
Meter Type:	Kilom Hours	Reason:	
Transmission:		Delay Code:	
Engine:	CUMMINS ISX 15		
Engine Serial #:			

Work Order #:	32772
Issued:	2025-06-25 10:27 AM
Status:	Completed
Date:	2025-06-26
Employee:	CODY
Name:	FRY
Page #:	1

Work Order Notes:

Codes for outlet NOX sensor

Replaced outlet NOX sensor

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

Services Performed

<u>Service Code</u>	<u>Description</u>	<u>Technician</u>	<u>Actual Hours</u>	<u>Hours</u>	<u>Cost</u>
5037	ENGINE- SENSOR	CODY		0.50	\$0.00
	COMMENT				
				Total Service	0.50 \$0.00

Parts Used

<u>Part Number</u>	<u>Part Description</u>	<u>Service Code</u>	<u>Quantity</u>	<u>Cost (each)</u>	<u>Total</u>
4326869rx	NOX SENSOR		1.00	\$982.07	\$982.07
				Total Parts	\$982.07
				Total Parts and Service	\$982.07



Work Order

WINDREM

Vehicle Code: 77

Work Order #:	33116
Issued:	2025-09-04 8:38 AM
Status:	Completed
Date:	2025-09-04
Employee:	HAYDN
Name:	MARKLAND
Page #:	1

Year:	2016	Alt. Vehicle ID:	
Make:	INTERNATIONAL	WO Type:	
Model:	DF677	Est. Downtime:	
License No:	AZ 26443	Hour Estimate:	
VIN #:	3HTNUAPT9GN733606	Reference No:	
Meter:	1: 1262622 2: 0	Requested By:	
Meter Type:	Kilom Hours	Reason:	
Transmission:		Delay Code:	
Engine:	CUMMINS ISX 15		
Engine Serial #:			

Work Order Notes:

Engine light on for failed NOX

- Replaced sensor and cleared codes

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

Services Performed

Service Code	Description	Technician	Actual Hours	Hours	Cost
0100	MISC REPAIRS	HAYDN		0.50	\$0.00
COMMENT					
Total Service				0.50	\$0.00

Parts Used

Part Number	Part Description	Service Code	Quantity	Cost (each)	Total
4326869rx	NOX SENSOR		1.00	\$982.07	\$982.07
Total Parts					\$982.07
Total Parts and Service					\$982.07

WINDREM



Work Order

Vehicle Code: 77

Year:	2016	Alt. Vehicle ID:	
Make:	INTERNATIONAL	WO Type:	
Model:	DF677	Est. Downtime:	
License No:	AZ 26443	Hour Estimate:	
VIN #:	3HTNUAPT9GN733606	Reference No:	
Meter:	1: 1279487 2: 0	Requested By:	
Meter Type:	Kilom Hours	Reason:	
Transmission:		Delay Code:	
Engine:	CUMMINS ISX 15		
Engine Serial #:			

Work Order #:	33306
Issued:	2025-09-15 9:03 AM
Status:	Completed
Date:	2025-09-17
Employee:	CODY
Name:	FRY
Page #:	1

Work Order Notes:
 Tested DEF doser for valume and spray pattern
 Replaced DEF doser
 Replaced coolant line for DEF doser
 Replaced coolant pipe from water pump to EGR cooler

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

Services Performed

<u>Service Code</u>	<u>Description</u>	<u>Technician</u>	<u>Actual Hours</u>	<u>Hours</u>	<u>Cost</u>
5036	ENGINE- DEF/ DPF	CODY		5.00	\$0.00
	COMMENT				
				Total Service	5.00 \$0.00

Parts Used

<u>Part Number</u>	<u>Part Description</u>	<u>Service Code</u>	<u>Quantity</u>	<u>Cost (each)</u>	<u>Total</u>
5532478cum	WATER BYPASS TUBE		1.00	\$367.19	\$367.19
2888173nx	INJECTOR, DOSER		1.00	\$927.99	\$927.99
4037152c1	7.5mm Tube		1.00	\$297.55	\$297.55
3990967c1	TUBE, ASS'Y, DEF	5036	1.00	\$349.66	\$349.66
Total Parts					\$1,942.39
Total Parts and Service					\$1,942.39

WINDREM



Work Order

Vehicle Code: 77

Year:	2016	Alt. Vehicle ID:	
Make:	INTERNATIONAL	WO Type:	
Model:	DF677	Est. Downtime:	
License No:	AZ 26443	Hour Estimate:	
VIN #:	3HTNUAPT9GN733606	Reference No:	
Meter:	1: 1208863 2: 0	Requested By:	
Meter Type:	Kilom Hours	Reason:	
Transmission:		Delay Code:	
Engine:	CUMMINS ISX 15		
Engine Serial #:			

Work Order #:	31757
Issued:	2024-12-16 5:17 PM
Status:	Completed
Date:	2024-12-16
Employee:	HAYDN
Name:	MARKLAND
Page #:	1

Work Order Notes:

RAD CAP NOT HOLDING PPRESSION (FIXED)
CLUTCH SWITCH BROKEN OFF (FIXED)

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

Services Performed

<u>Service Code</u>	<u>Description</u>	<u>Technician</u>	<u>Actual Hours</u>	<u>Hours</u>	<u>Cost</u>
5014	ENGINE - RADIATOR CAP	HAYDN		0.25	\$12.50
	COMMENT				
2003	DRIVE TRAIN - CLUTCH ADJ	HAYDN		0.75	\$37.50
	COMMENT				
Total Service				1.00	\$50.00

Parts Used

<u>Part Number</u>	<u>Part Description</u>	<u>Service Code</u>	<u>Quantity</u>	<u>Cost (each)</u>	<u>Total</u>
3578833C3	CAP,RAD	5014	1.00	\$48.45	\$48.45
2041792C91	SWITCH,CLUTCH,SAFETY	4000	1.00	\$339.88	\$339.88
Total Parts					\$388.33
Total Parts and Service					\$438.33

WINDREM



Work Order

Vehicle Code: 77

Year:	2016	Alt. Vehicle ID:	
Make:	INTERNATIONAL	WO Type:	WARRANTY
Model:	DF677	Est. Downtime:	
License No:	AZ 26443	Hour Estimate:	
VIN #:	3HTNUAPT9GN733606	Reference No:	
Meter:	1: 118223 2: 0	Requested By:	
Meter Type:	Kilom Hours	Reason:	
Transmission:		Delay Code:	
Engine:	CUMMINS ISX 15		
Engine Serial #:			

Work Order #:	31254
Issued:	2024-07-30 3:55 PM
Status:	Completed
Date:	2024-08-22
Employee:	
Name:	
Page #:	1

Vendor:	WINS
Name:	Winslow Gerolamy Mo
Address:	1018 Lansdowne Stre
City/State:	Peterborough ON

Work Order Notes:

DATE COMPLETED

RELEASED BY - (SIGNATURE REQUIRED)

DIAGNOSE TRANS POPPING OUT OF GEAR - MAINSHAFT BEARING FAILED
 REMOVED TRANSMISSION INSTALLED ULT POWER TRAIN PART UDULTPTN3780
 REPLACED BALL BEARING, GASKET SHIFT TOWER, OTHER GASKETS
 PRE ROAD TEST (NOT FOR USE WITH CATASTROPHIC FAILURE)
 REPLACE PTO COVER AND GASKET
 REPLACED ALL FAILED PARTS, INSTALLED NEW CLUTCH AND CLUTCH BRAKE ONTO TRANS.
 RECONNECT DRIVE SHAFT, RECONNECT CLUTCH LINKAGE, SET CLUTCH BRAKE TO 1-1/2, FILL TRANS WITH FLUID

DIAGNOSE DIFFERENTIAL LEAK - BROKEN RING GEAR BOLTS
 R&R DIFF CARRIER ASSEMBLY AND/OR REPLACE
 UDULTPTN2590 ULT POWER TRAIN PARTS OR LABOUR
 INSTALL GASKETS, MAG PLUG & 75w90
 REBUILD FRONT DIFF AND REPLACE REAR DIFF DUE TO METAL CHUNKS COMING OUT
 REPAIR DOG HOUSE LOOSE (CAB)

ROAD TEST TO CHECK OPERATION - SENSORS NOT HOOKED UP
 OIL TEMP GAUGE NOT READING PROPERLY ON DASH
 AXLE TEMP GAUGES NOT READ AT ALL
 ENGINE OIL TEMP READING PROPERLY IN CUMMINS
 AXLE TEMP SENSORS NOT HOOKED UP

REPAIR DASH GAUGES NOT LIGHTING UP - FOUND 4 INSTRUMENT BULBS OUT

DIAGNOSE STEERING SHAFT PLAY - SHAFT NOT GREASED IN SOME TIME
 GREASED SHAFT AND MOST PLAY IS GONE

REPAIR FOR CLUTCH SLIPPING - CLUTCH BEARING FAILED
 REPLACED CLUTCH
 CLUTCH RELEASE BEARING FAILED

REPAIR LOOSE HOOD MIRROR - FOUND NOTHING WRONG WITH MIRRORS

Services Performed

Service Code	Description	Technician	Actual Hours	Hours	Cost
2001	DRIVE TRAIN - TRANS R&R			1.00	\$0.00
	COMMENT				
2006	DRIVE TRAIN - U JOINT			1.00	\$0.00
	COMMENT				
2009	DRIVE TRAIN - DIFFERENTIAL			1.00	\$0.00
	COMMENT				

WINDREM

Work Order

Vehicle Code: 77

Year: 2016
 Make: INTERNATIONAL
 Model: DF677
 License No: AZ 26443
 VIN #: 3HTNUAPT9GN733606
 Meter: 1: 118223 2: 0
 Meter Type: Kilom Hours
 Transmission:
 Engine: CUMMINS ISX 15
 Engine Serial #:

Alt. Vehicle ID:
 WO Type: WARRANTY
 Est. Downtime:
 Hour Estimate:
 Reference No:
 Requested By:
 Reason:
 Delay Code:

Work Order #: 31254
 Issued: 2024-07-30 3:55 PM
 Status: Completed
 Date: 2024-08-22
 Employee:
 Name:
 Page #: 2

Vendor: WINS
 Name: Winslow Gerolamy Mo
 Address: 1018 Lansdowne Stre
 City/State: Peterborough ON

2004	DRIVE TRAIN - CLUTCH R&R	RELEASED BY - (SIGNATURE REQUIRED)	\$0.00
	COMMENT		
6018	CHASSIS - STEERING	1.00	\$0.00
	COMMENT		
Total Service		5.00	\$0.00

Parts Used

<u>Part Number</u>	<u>Part Description</u>	<u>Service Code</u>	<u>Quantity</u>	<u>Cost (each)</u>	<u>Total</u>
OUTSIDE SERVICE	SERVICE AND PARTS NOT COVERED	0120	1.00	\$1,082.01	\$1,082.01
Total Parts					\$1,082.01
Total Parts and Service					\$1,082.01