

Inter-Rail Transport 1405 90th Avenue Edmonton, Alberta, T6P 0C8 CA 7804647046

Work Order Number: Invoice Number:

PO Number:

WORK ORDER

WORK ORDER DETAILS

Scheduled Start Date:

Actual Start Date:

Issue Date:

Fri, May 30, 2025

8:56 AM

1017

2018 Kenworth W900

VIN/SN:

Operator:

Type:

Group:

Odometer:

Secondary Meter:

License Plate:

1XKWD40X9JR994698

17,698hr (voided meter)

E37411 N/A

Semi Truck

Heavy Duty

943,395km

IRT/

Expected Completion Date:

Actual Completion Date:

Repair Priority Class:

Tue, Jun 3, 2025

Fri, May 30, 2025

4 days

Non-Scheduled

Completed

Issued By:

Duration:

Status:

Assigned to:

Brayden Harper

SHOP1

Vendor:

Labels:

Date on Bill / Invoice:

Repair Type:

LINE ITEMS

Labor

\$400.00

Parts

Subtotal

Item

17 Truck labor

10 hrs

\$0.00

\$400.00 \$400.00

Brayden Harper (Contact)

\$40.00

#1037 · 18 - Lamps/Reflectors Canister light passenger side

PARTS (not linked to a Service Task)

Subtotal Quantity **Unit cost** Part \$1,748.48 \$1,748.48 5484117CUM (Part) · Inter-Rail Transport 1 ea Engine Hamess \$248.46 \$248.46 1 ea **■** 5461 \$96CUM (Part) · Inter-Rail Transport SENSOR, TEMPERATURE



-Engine codes// Unit has had re-occurring wiring codes 2288 and 2272, the engine harness had been attempted to be repaired twice now. Remove and replace engine harness. -RHS air filter canister light. Driver supplied light and i swapped it out.

Subtotal	\$2,396.94
Labor	\$400.00
Parts	\$1,996.94
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$2,396.94





Inter-Rail Transport 1405 90th Avenue Edmonton, Alberta, T6P 0C8 CA 7804647046

Work Order Number:

1XKWD40X9JR994698

942,967km (voided meter)

17,684hr (voided meter)

#6044

Invoice Number: PO Number:

WORK ORDER

WORK ORDER DETAILS

Issue Date:

Mon, May 26, 2025

8:25 AM

1017

2018 Kenworth W900

Scheduled Start Date:

Actual Start Date:

Expected Completion Date:

Actual Completion Date:

Thu, May 29, 2025

11:02 AM

Operator:

Type:

Group:

Odometer:

Secondary Meter:

License Plate:

VIN/SN:

N/A

IRT/

E37411

Semi Truck

Heavy Duty

Thu, Jun 5, 2025

10:33 AM

6 days 23 hrs 31 mins

Repair Priority Class:

Scheduled

Status:

Duration:

Completed

Issued By:

SHOP2

Assigned to

Cody McKinnon

Vendor:

Labels:

Date on Bill / Invoice:

Repair Type:

LINE ITEMS

Item

Labor

Parts

Subtotal

17 Truck labor

\$630.00

\$0.00

\$630.00

Cody McKinnon (Contact)

15.75 hrs

\$40.00

\$630.00

#1017 · 12 - Fuel Systems Problem with DEF.

PARTS (not linked to a Service Task)

Part	Quantity	Unit cost	Subtotal
085471WMA (Part) · Inter-Rail Transport DEF FILTER REPLACEMENT KIT	1 ea	\$26.68	\$26.68
4388376CUM (Part) · Inter-Rail Transport KIT, AFTERTREATMENT INJ	1 ea	\$57.48	\$57.48



Part			Qua	ntity	Unit cost	Subtotal
**		71CUM (Part) · Inter-Rail Transport TERTREATMENT INJ		1 ea	\$42.44	\$42.44
Ħ		38 (Part) · Inter-Rail Transport ns Serpentine Belt		1 ea	\$29.39	\$29.39
Ħ		10X (Part) · Inter-Rail Transport Main Fan Drive Belt		1 ea	\$86.17	\$86.17
#		Part) · Inter-Rail Transport ler pulley bearing		1 ea	\$26.75	\$26.75
Ħ		Part) · Inter-Rail Transport ler pulley bearing		1 ea	\$26.75	\$26.75
**	-	Part) · Inter-Rail Transport nsioner Bearings		1 ea	\$10.70	\$10.70
===	•	Part) · Inter-Rail Transport nsioner Bearings		1 ea	\$10.20	\$10.20
Ħ	6303 (Part) · Inter-Rail Transport Her pulley bearing		1 ea	\$25.40	\$25.40
**		350 (Part) · Inter-Rail Transport		1 ea	\$2,538.64	\$2,538.64
Ħ	28802	15 (Part) · Inter-Rail Transport C Gasket		1 ea	\$26.73	\$26.73
**	PHS-2	236 (Part) · Inter-Rail Transport * OD GEAR CLAMP		1 ea	\$9.74	\$9.74
DESC	CRIPTIC	N	SUMMARY			
Drain	red coo	d truck had DEF pressure issues and DPF can ash load codes ant removed step to replace the filter in the doser valve, replaced	Subtotal			\$3,547.07
remo	ove tank	in the pump and replaced the filter in the DEF tank (had to from truck) most of the lines were very stuck and took a lot of spart Replaced DPF caps with brand new one filled truck back	Labor Parts			\$630.00 \$2,917.07

time to take apart. Replaced DPF cans with brand new one, filled truck back up with coolant and pressure tested + put truck on a burn checked for any codes and there was none. Noticed big air leak coming from truck with key on when i pulled in, found the air fitting to be loose on the fan hub, snipped line and put new nut and furrel fixed air leak, also noticed that the fan belt was in bad shape barley hanging on (2 ribs missing fully and cracks through the belt) Removed both belts and checked pulleys and tensioners all 3 were dry, removed them all and replaced all the bearings in them installed 2 new belts and tested operation

Subtotal	\$3,547.07
Labor	\$630.00
Parts	\$2,917.07
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$3,547.07





Inter-Rail Transport 1405 90th Avenue Edmonton, Alberta, T6P 0C8 CA 7804647046

Work Order Number: Invoice Number: PO Number: #2273

WORK ORDER

WORK ORDER DETAILS

Issue Date:

Mon, Feb 5, 2024

8:10 AM

1017

2018 Kenworth W900

Scheduled Start Date:

Actual Start Date:

Mon, Feb 5, 2024

MA 00:8

VIN/SN: License Plate:

Operator:

Type:

Group:

Odometer:

Secondary Meter:

1XKWD40X9JR994698

E37411 N/A

- ----

Expected Completion Date:

Actual Completion Date:

Wed, Feb 7, 2024

12:00 PM

Duration:

2 days 4 hrs 0 mins

Repair Priority Class:

Scheduled

Status:

Completed

Issued By:

SHOP1

Assigned to:

Troy Proskiw

Vendor:

Labels:

Date on Bill / Invoice:

Repair Type:

LINE ITEMS

785,981km

Semi Truck

Heavy Duty

IRT/

14,918hr (voided meter)

tem	ı			Labor	Parts	Subtotal
•	07 Er		and approve of the second of	\$260.00	\$0.00	\$260.00
	±	Troy Proskiw (Contact)	6.5 hrs \$40.00			\$260.00
•	15 P	eventative Maintenance 1507 B - PM		\$60.00	\$0.00	\$60.0
	•	Troy Proskiw (Contact)	1.5 hrs \$40.00			\$60.0
	12 R	ear Axle		\$120.00	\$0.00	\$120.0
	•	Troy Proskiw (Contact)	3 hrs \$40.00			\$120.0
	05 E	ectrical		\$40.00	\$0.00	\$40.0
	•	Troy Proskiw (Contact)	1 hr \$40.00			\$40.0



Part			Quantity	Unit cost	Subtotal
	lf1400 Oil Filte	Dnnflg (Part) · Inter-Rail Transport r	1 ea	\$44.00	\$44.00
#		72FLG (Part) · Inter-Rail Transport ater Seperator (K37-1029)	1 ea	\$29.82	\$29.82
===	FF582 Fuel Fi	5NNFLG (Part) · Inter-Rail Transport ter	1 ea	\$56.75	\$56.75
21	15w40	(Part) · Inter-Rail Transport Oil	42 L	\$3.96	\$166.32
Ħ		3ETN (Part) · Inter-Rail Transport 0 - Diff Differential Output Nut And Seal	1 ea	\$111.54	\$111.54
		4ETN (Part) · Inter-Rail Transport T SHAFT KIT D46-170HP	1 ea	\$402.50	\$402.50
Ħ		13RXCUM (Part) · Inter-Rail Transport LE, ELECTRONIC ECM	1 ea	\$3,386.14	\$3,386.14
**		014 (Part) · Inter-Rail Transport Calibration	1 ea	\$225.88	\$225.88

DESCRIPTION

engine- derate code for exhaust gas pressure, found to no be reading correctly 50.00 in hg, removed sensor and drilled out port and cleaned, replaced sensor, light still on, ran unit up to temp still reading same, checked voltage 5 volts, checked from plug to ecm, found to test good, ran head light through wiring checked good, unplugged all sensors that share ground with sensor, no change, removed ecm and installed ecm from 1014, exhaust gas now reading correctly, sent out ecm and go new one programed, installed on unit, found engine hours to not be reading correctly, but exhaust gas now reading correctly all checks good pmb- service due, changed oil and filters, fuel filters greased unit, checked and adjusted tire pressures, checked over unit repairs needed rear axle- found 1st diff output shaft end to be cracked right off, removed drive shaft, removed seal, removed snap ring and shaft, pushed off bearings and pushed onto new shaft, cleaned bearings and housing pre lubed bearings, and installed shaft, seated race and installed snap ring, installed new seal, installed yok with new nut and red lock tight, torqued to spec, installed drive line and torqued to spec, cleaned off oil and filled diff, found diff to be out of oil, let mike know, sent on test drive all checks good electrical-d/s work light not working, found ground to be bad, repaired all checks good - drilled and mounted rear facing bumper lights, wired in and tested all checks good

SUMMARY

Subtotal	\$4,902.95
Labor	\$480.00
Parts	\$4.422.95
Labor Markup	+ \$0.00 (0.0%)
Parts Markup	+ \$0.00 (0.0%)
Warranty Credits	- \$0.00 (Fixed)
Discount	- \$0.00 (0.0%)
Tax	+\$0.00 (0.0%)
Total	\$4,902.95

