

Quick Shift Heavy Duty Mechanical

38314 Range Road 281
Red Deer County, Alberta, T4E 1X8
(587) 802 - 8811



4027-2
Invoice: INV-S-318

Issue date: Jul 23, 2025
Due date: Aug 22, 2025

Bill To

Black Hand Transport Inc

Remit payment to

Quick Shift Heavy Duty Mechanical
38314 Range Road 281
Red Deer County, Alberta T4E 1X8
(587) 802 - 8811

Unit	Vin	Vehicle	Mileage	Eng Hrs
BHT007	1XPXD49X0AD105172	2010 Peterbilt 389L	1,965,854	44,190
Service Order	Terms	Due date	Customer PO	Authorizer
S-318	Net 30	Aug 22, 2025	BHT007	

Description	Quantity	Rate	Amount
CHECK 5TH WHEEL			
CHECKED 5TH WHEEL FOR DAMAGE , REQUIRES REBUILD KIT.	0.25	\$110.00	\$27.50
		Parts Total	\$0.00
		Labor Total	\$27.50
		Line Total	\$27.50
REPLACE 5TH WHEEL PART AND ADJUST			
ADJUSTMENT ROD BENT	0.75	\$110.00	\$82.50
SAFRK351AL - HOLLAND 5TH WHEEL REBUILD KIT	1	\$745.61	\$745.61
		Parts Total	\$745.61
		Labor Total	\$82.50
		Line Total	\$828.11
		Labor	\$110.00
		Parts	\$745.61
		Shop supplies	\$5.50
		Subtotal	\$861.11
		GST (5%)	\$43.07
		Total	\$904.18
		Payments	
		Balance	\$904.18

Quick Shift Heavy Duty Mechanical

38314 Range Road 281
Red Deer County, Alberta, T4E 1X8
(587) 802 - 8811



Invoice: INV-S-299

Issue date: Jul 14, 2025

Due date: Aug 13, 2025

Bill To

Black Hand Transport Inc

Remit payment to

Quick Shift Heavy Duty Mechanical
38314 Range Road 281
Red Deer County, Alberta T4E 1X8
(587) 802 - 8811

Unit	Vin	Vehicle	Mileage	Eng Hrs
BHT007	1XPXD49X0AD105172	2010 Peterbilt 389L	1,965,396	44,182
Service Order	Terms	Due date	Customer PO	Authorizer
S-299	Net 30	Aug 13, 2025	BHT007	

Description	Quantity	Rate	Amount
TRUCK RUNNING ROUGH DIAGNOSE			
CHECKED UNIT OUTSIDE FOR ROUGH RUNNING ENGINE. REPLACED LEAKING FRONT COVER PLUG THAT WAS LEAKING. BRING UNIT INSIDE AND UNIT NOW RUNNING SMOOTHLY. HOOK UP LAPTOP AND FOUND INACTIVE CODES : 2311 : ELECTRONIC FUEL INJECTION CONTROL VALVE CIRCUIT - CONDITION EXISTS 0553 : INJECTOR METERING RAIL 1 PRESSURE 0272 : ENGINE FUEL PUMP PRESSURIZING ASSEMBLY 1 CURCUIT SHORTED TO HIGH			
START BY CHECKING ELECTRICAL PLUG AT COMMON RAIL PRESSURE SENSOR . REMOVE LOOM OFF SENSOR PIGTAIL AND FOUND WIRING DAMAGED AT SENSOR END / LOOSE BODY ON SENSOR . REMOVE ZIP TIES AND PIGTAIL FROM FUEL PUMP SOLENOID. REMOVED FUEL PUMP SOLENOID FROM BACK OF PUMP AND TEST USING MULTIMETER. FOUND SOLENOID RESISTANCE JUMPING FROM 4 OHMS TO 200 OHMS WHEN YOU WIGGLE SOLENOID. ORDER NEW RAIL PRESSURE SENSOR AND FUEL PUMP SOLENOID .			
INSTALLED NEW PUMP SOLENOID AND COMMON RAIL SENSOR. RUN UNIT AND CHECK VOLTAGES / COMMANDS FOR FUEL SYTEM INCLUDING COMMANDED AND ACTUAL FUEL PRESSURE. REV UP ENGINE THROUGH FULL RPM RANGE AND FOUND COMMANDED AND ACTUAL FUEL PSI RANGE MATCHING WITHOUT PRESSURE DROPS.			
3688113 - CUMMINS GEAR COVER PLUG	3	\$100.00	\$300.00
2897581 - COMMON FUEL RAIL PRESSURE SENSOR FOR CUMMINS ISX	1	\$21.02	\$21.02
	1	\$284.04	\$284.04

4307411RX - ELECTRONIC FUEL CONTROL ACTUATOR CUMMINS ISX
ENGINE

1 \$473.62 \$473.62

Parts Total \$778.68
Labor Total \$300.00
Line Total \$1,078.68

CHECK CLUTCH BRAKE

REMOVE COVER AND CHECK CLUTCH BRAKE. ADJUST CLUTCH AND GREASE
RELEASE BEARING

0.5 \$100.00 \$50.00

Parts Total \$0.00
Labor Total \$50.00
Line Total \$50.00

Labor \$350.00
Parts \$778.68
Shop supplies \$17.50
Subtotal \$1,146.18
GST (5%) \$57.31
Total \$1,203.49
Payments
Balance \$1,203.49

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

Customer signature: _____

Printed name: _____ Date: _____

783511140 RT0001

Software Powered by ShopView

Quick Shift Heavy Duty Mechanical

38314 Range Road 281
Red Deer County, Alberta, T4E 1X8
(587) 802 - 8811



Invoice: INV-S-286

Issue date: Jul 11, 2025

Due date: Aug 10, 2025

Bill To

Black Hand Transport Inc

Remit payment to

Quick Shift Heavy Duty Mechanical
38314 Range Road 281
Red Deer County, Alberta T4E 1X8
(587) 802 - 8811

Unit	Vin	Vehicle	Mileage	Eng Hrs
BHT007	1XPXD49X0AD105172	2010 Peterbilt 389L	1,962,659	44,132
Service Order	Terms	Due date	Customer PO	Authorizer
S-286	Net 30	Aug 10, 2025	BHT007	

Description	Quantity	Rate	Amount
SERVICE/INSPECT/GREASE TRUCK			
INSPECT, SERVICE & GREASE TRUCK			
TAKE OUT HL003 AND BRING IN UNIT 007	2	\$100.00	\$200.00
		Parts Total	\$0.00
		Labor Total	\$200.00
		Line Total	\$200.00
REPLACE DRIVE AXLE #2 P.S. BRAKE POT			
INTERNAL LEAK			
REMOVED OLD LEAKY BRAKE POT, GRABBED NEW ONE, RECLOCK NEW			
BRAKE POT, CUT ROD TO LENGHT, INSTALL BRAKE POT, TRANSFER AIR			
FITTINGS OVER REINSTALL HOSES, CHECK STROKE, RESET SLACK ADJUSTER	1	\$100.00	\$100.00
FLT3030SCB20 - Chamber, Brake 30/30 (Universal Cut to Fit 8" Rod No Yoke)	1	\$39.11	\$39.11
Brake Chamber- Service/Parking, Rear Drum.			
		Parts Total	\$39.11
		Labor Total	\$100.00
		Line Total	\$139.11
REPAIR DRIVE AXLE #2 D.S. STROKE / SLACK			
AUTO SLACK ADJUSTER NOT SET PROPERLY	0.25	\$100.00	\$25.00
		Parts Total	\$0.00
		Labor Total	\$25.00
		Line Total	\$25.00
ADJUST CLUTCH			
CLUTCH OUT OF ADJUSTMENT			
ADJUSTED CLUTCH GAP	0.5	\$100.00	\$50.00
		Parts Total	\$0.00

		Labor Total	\$50.00
		Line Total	\$50.00
LUBE SHOCKER PASS VALVE			
BINDS WHEN TRYING TO USE IT / NOT FUNCTIONING PROPERLY			
SPRAYED LITHIUM GREASE ALL OVER, TESTED	0.25	\$100.00	\$25.00
		Parts Total	\$0.00
		Labor Total	\$25.00
		Line Total	\$25.00
RECONNECTED 5TH SLIDER AIR HOSE			
DISCONNECTED, SITTING LOOSE BY DRIVE YOKE	0.1	\$100.00	\$10.00
		Parts Total	\$0.00
		Labor Total	\$10.00
		Line Total	\$10.00
REPAIR #2 DRIVE AXLE D.S. ABS MODULATOR			
BYPASSING	0	\$100.00	\$0.00
		Parts Total	\$0.00
		Labor Total	\$0.00
		Line Total	\$0.00
		Labor	\$410.00
		Parts	\$39.11
		Shop supplies	\$20.50
		Subtotal	\$469.61
		GST (5%)	\$23.49
		Total	\$493.10
		Payments	
		Balance	\$493.10

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

Customer signature: _____

Printed name: _____ **Date:** _____

783511140 RT0001

Software Powered by ShopView

Quick Shift Heavy Duty Mechanical

38314 Range Road 281
Red Deer County, Alberta, T4E 1X8
(587) 802 - 8811



Invoice: INV-S-280

Issue date: Jul 5, 2025

Due date: Aug 4, 2025

Bill To

Black Hand Transport Inc
38314 Range Road 281
Red Deer County, Alberta T4E 1X8

Remit payment to

Quick Shift Heavy Duty Mechanical
38314 Range Road 281
Red Deer County, Alberta T4E 1X8
(587) 802 - 8811

Unit	Vin	Vehicle	Mileage	Eng Hrs
BHT007	1XPXD49X0AD105172	2010 Peterbilt 389L	1,965,396	44,182
Service Order	Terms	Due date	Customer PO	Authorizer
S-280	Net 30	Aug 4, 2025	BHT007	

Description	Quantity	Rate	Amount
RE AND RE ALTERNATOR (WEEKEND) NOT CHARGING/SHOWS LOW VOLTAGE/REPLACE REMOVED AND REPLACED ALTERNATOR - SATURDAY CALL OUT (WARRANTY - ORIGINAL ALTERNATOR P/N 135140 - CAME FROM GLOVERS MAY 7-2025 INV 445100) (REPLACEMENT ALTERNATOR INV 449697 - COVERED VIA WARRANTY - \$0 COST FLTAL136170P - ALTERNATOR	3 1	\$100.00 \$0.00	\$300.00 \$0.00
	Parts Total		\$0.00
	Labor Total		\$300.00
	Line Total		\$300.00
	Labor		\$300.00
	Parts		\$0.00
	Shop supplies		\$15.00
	Subtotal		\$315.00
	GST (5%)		\$15.75
	Total		\$330.75
	Payments		
	Balance		\$330.75

Customer		Date		VIN
#007		March 15		
Odometer	1328592	Engine Hours	23565	
Hours	Repairs Completed			Parts company and Inv #
	Dig - Engine thrown on road on #3 - remove Engine & Trans - remove Engine & trans from Dodge truck #9 - Dress Engine prior to install - front main, Rear main, Rear structure - HP Fuel pump, Transfer Pump, pan - Swap required components to fit #007 - Motor mounts, water plumbing - Remove Emissions - install PDE - Install Engine into #007 - swap Required Trans parts - install Pyro, Air plumbing - Take unit to truck for Port Harners, and Delete - Truck back - will not go into gear - - repair slave pin in trans - clean up wiring & fuel plumbing - repair small coolant leaks as Req - Test Drive OK - water in fuel not mixed in - Repair/Rebuild Light Bar harness, Red light, Signal - Aux light harness green			
Initials	Rewrite both same ^{signal} original ^{new} mirrors Replace LHS corner			Date Completed