



CITY SPRING & AXLE LTD.
 3260 PARSONS ROAD
 EDMONTON, AB T6N-1B3
 Phone: (780) 463-4291
 Fax: (780) 461-3460

489101 mi
 25337 HR

B08-2
 MAY

Service Invoice

Page	1
Invoice #	4091991
Inv Date	09/14/22
Cust P/O	KALVIN

Sold To:
 Eagle Terrace Transport
 (1472906 Alberta Ltd)
 16221 123 Ave NW
 Edmonton, AB T5V 1N9
 Phone: (780) 453-6227
 Fax: (780) 452-9376

Ship To: 00000
 Eagle Terrace Transport
 (1472906 Alberta Ltd)
 16221 123 Ave NW
 Edmonton, AB T5V 1N9
 Phone: (780) 453-6227
 Fax: (780) 452-9376
 Contact:

Make: PETERBILT	Model: TRI	Year: ?	License:	Kilometers:	Unit: 0108353
Order Date: 09/08/22	Order: 0108353	Slsn: HS	Loc: 01	Freight: Collect	Terms: 30 DAYS
Ship Date: 09/14/22	Via:				

Code	Description	U/M	Qty	Price	Extension
MS	CHECK REAR SUSPENSION AND ADVISE.				
M1751	PB WEAR PAD WITH BOLTS, ETC.	EA	6	112.90	677.40
75-125-00	PETERBILT T/L SPRING	EA	6	223.96	1,343.76
500.351	BOLT/ROLLER KIT PETE AIR TRAC	EA	6	46.06	276.36
UB136	1X36 U-BOLT 4"SR	EA	12	51.57	618.84
UW1	1" U-BOLT WASHER	EA	24	1.17	28.08
DN1	DEEP NUT 1" - GR8 -	EA	24	2.83	67.92
LNC16MM	16MM LOCKNUT METRIC 10.9	EA	12	2.66	31.92
03-02730-002	SHIM PETE FOR AXLE SEAT .138	EA	5	31.00	155.00
M828	U-BOLT TOP PLATE PETERBILT	EA	2	37.55	75.10
HB8-58X2NC	BOLT	EA	6	4.54	27.24
LN58NC	5/8 COARSE THREAD STOVER LOCK	EA	6	1.28	7.68
FW916	9/16" FLAT WASHER	EA	12	0.42	5.04
TRB6185M	Torque Rod Bushing Metal Outer	EA	2	26.96	53.92
HN12NC	HEX NUT 1/2" NC	EA	6	0.20	1.20
LW12	1/2 LOCKWASHER	EA	6	0.17	1.02
FW12	1/2 FLAT WASHER	EA	6	0.12	0.72
401754	BUSHING	EA	2	3.00	6.00
HN34NC	HEX NUT 3/4" NC	EA	2	0.72	1.44
LW34	3/4 LOCKWASHER	EA	2	0.24	0.48
	Subtotal Parts				3,379.12

info@cityspring.com

www.cityspring.com

1-800-661-3843

Unit 02



CITY SPRING & AXLE LTD.
 3260 PARSONS ROAD
 EDMONTON, AB T6N-1B3
 Phone: (780) 463-4291
 Fax: (780) 461-3460

Service Invoice

Page	2
Invoice #	4091991
Inv Date	09/14/22
Cust P/O	KALVIN

Sold To:
 Eagle Terrace Transport
 (1472906 Alberta Ltd)
 16221 123 Ave NW
 Edmonton, AB T5V 1N9
 Phone: (780) 453-6227
 Fax: (780) 452-9376

Ship To: 00000
 Eagle Terrace Transport
 (1472906 Alberta Ltd)
 16221 123 Ave NW
 Edmonton, AB T5V 1N9
 Phone: (780) 453-6227
 Fax: (780) 452-9376
 Contact:

Make: PETERBILT	Model: TRI	Year: ?	License:	Kilometers:	Unit: 0108353
Order Date: 09/08/22	Order: 0108353	Slspn: HS	Loc: 01	Freight: Collect	
Ship Date: 09/14/22	Via:			Terms: 30 DAYS	

Code	Description	U/M	Qty	Price	Extension
1000	INSPECT REAR SUSPENSION AND REPLACE ALL SPRINGS WITH NEW WEAR PADS AND FRONT ROLLERS.	Reg	12.00	130.00	1,560.00
1000	JACKUP FRONT END OF UNIT AND PUT ON STANDS REMOVE TIRES AND RIMS. INSTALL NEW TIRES & RIMS	Reg	1.00	0.00	0.00
3002	TAKE OFF STANDS AND TORQUE WHEELS TO SPEC SHOP SUPPLIES	Reg	1.00	98.50	98.50
	Subtotal Labour				1,658.50
	Subtotal for CHECK REAR SUSPENSION AND				5,037.62

info@cityspring.com

www.cityspring.com

1-800-661-3843



MD TRUCK REPAIR

30 - 54108 RR 280
SPRUCE GROVE, AB
T7X 3V3
780-452-7975

mdtruck@telus.net

GST/HST No. 873857411

INVOICE

Date	Invoice #
13/06/2022	20832

P.O. #

Customer Name
1472906 ALBERTA LTD. 16221 - 123 AVENUE NW EDMONTON, AB T5V 1N9

Make	Year	Unit #	Odometer	Serial No.
Peterbilt Eng. Ser. 79602564	2014	02	467799 km	1XPTP4EXXDD197147

Item	Qty	Description	Rate	Amount
		June 3, 2022 installed test ecm for customer to try		
		June 13, 2022 hooked up computer to check for fault codes found injector driver solenoid driver 2, 1, 3 current below normal removed and replaced #1, #2 and #3 injectors and tubes with used ones replaced fuel pressure relief valve and tested pressure still dropping to 0 in less than 1 minute removed and replaced fuel pump head, actuator and tappets ran and checked fuel pressure again; holdin at 11000 psi test drove truck; no engine lights on or fuel issues		
Shop Supplies		Shop Supplies	8.00%	198.72
Parts	1	3686370 wiring harness	302.99	302.99
Parts	1	3687334PX nitrogen oxide sensor	833.98	833.98
Parts	1	2882570 rocker lever shaft	319.17	319.17
Parts	1	2882571 rocker lever shaft	320.26	320.26
Parts	6	2892986 compression spring	15.84	95.04
Parts	6	3413129 check valve	109.31	655.86
15W40	45	oil	4.50	202.50
LF14000NN	1	Cummins oil filter	50.35	50.35
5825NN	1	fuel filter	61.45	61.45
36401	1	fuel separator	33.50	33.50
Parts	1	06-00984 tie rod end	70.49	70.49
Parts	1	06-01150-385 clutch link	39.42	39.42
Parts	1	J21270-14 elastomeric rod end	60.28	60.28
A/C Recharge	1	A/C Re-charge	125.00	125.00
Diagnostics	1	diagnostics computer charge	100.00	100.00
R134A	2.75	freon	12.50	34.37
Parts	1	4307195 pressure relief valve	487.53	487.53
Parts	1	4984382 sealing washer	11.76	11.76

MD Truck Repair accepts no responsibility for vehicles, equipment, or contents left on the premises. Also, this company accepts no responsibility for lost income, towing expenses, or any other expenses deemed to result from repairs made to vehicles or equipment. No warranty claim or labour can exceed the amount paid for the same parts and labour as itemized on this work order. Warranty for parts is the responsibility of the manufacturer. Interest will be charged on all invoices due past 30 days at the rate of 24% per annum calculated monthly.

Total

I hereby acknowledge my indebtedness to be \$ _____

DATE: _____ X _____



MD TRUCK REPAIR

30 - 54108 RR 280
SPRUCE GROVE, AB
T7X 3V3
780-452-7975

mdtruck@telus.net

GST/HST No. 873857411

INVOICE

Date	Invoice #
13/06/2022	20832

P.O. #

Customer Name
1472906 ALBERTA LTD. 16221 - 123 AVENUE NW EDMONTON, AB T5V 1N9

Make	Year	Unit #	Odometer	Serial No.
Peterbilt Eng. Ser. 79602564	2014	02	467799 km	1XPTP4EXXDD197147

Item	Qty	Description	Rate	Amount
Labour	18	<p>June 2, 2022</p> <p>checked for engine light on hooked up computer and printed off eem data; checked for fault codes found codes 1885; aftertreatment 1 intake nox sensor circuit voltage below normal or shorted code 0324, injector solenoid drive cyl 3 circuit below normal or open circuit code 0322, 0331; injetor solenoid circuit cyl1, cyl 2 circuit current below normal or open circuit found injector harness terminal full of oil at engine harness connector removed air piping and valve cover inspected camshaft; okay found jake rockers not staying in detents; worn out removed engine harness terminals from ecm; dry, no oil; reinstalled terminals replaced injector plate wiring harness removed and replaced nox sensor removed front and rear rocker shaft assemblies installed new rocker shafts, check valves and springs reinstalled assemblies and set all valves, and jakes reinstalled valve cover and air piping cleared all codes serviced truck changed engine oil & filters checked a/c operaiton hooked up identifier to check for freon hooked up a/c machine and recovered freon vacuum and leak tested; okay re-charged system and tested checked clutch free pedal found clutch pedal has too much free play removed clutch rod to adjust; hyme joints worn out installed longer rod and two new hyme joints adjusted rod for correct free pedal checked clutch brake ran engine and tested; okay</p>	138.00	2,484.00

MD Truck Repair accepts no responsibility for vehicles, equipment, or contents left on the premises. Also, this company accepts no responsibility for lost income, towing expenses, or any other expenses deemed to result from repairs made to vehicles or equipment. No warranty claim or labour can exceed the amount paid for the same parts and labour as itemized on this work order. Warraanity for parts is the responsibility of the manufacturer. Interest will be charged on all invoices due past 30 days at the rate of 24% per annum calculated monthly.

Total

Unit 02

I hereby acknowledge my indebtedness to be \$ _____

DATE: _____ X _____



MD TRUCK REPAIR

30 - 54108 RR 280
SPRUCE GROVE, AB
T7X 3V3
780-452-7975

mdtruck@telus.net

GST/HST No. 873857411

INVOICE

Date	Invoice #
13/06/2022	20832

P.O. #

Customer Name
1472906 ALBERTA LTD. 16221 - 123 AVENUE NW EDMONTON, AB T5V 1N9


Make	Year	Unit #	Odometer	Serial No.
Peterbilt Eng. Ser. 79602564	2014	02	467799 km	1XPTP4EXXDD197147

Item	Qty	Description	Rate	Amount
Parts	3	3347939 o-ring seal	4.12	12.36
Parts	3	2872717 injector seal	5.60	16.80
Parts	3	4984152 o-ring seal	3.99	11.97
Parts	1	4307411NX fuel control actuator	378.16	378.16
Parts	2	4359134 pump tappet	162.57	325.14
Parts	1	2872661RX fuel pump head	2,297.07	2,297.07
Parts	1	2872513 fuel pump gasket	32.76	32.76
Parts	1	2872663 fuel pump gasket	26.04	26.04
Parts	2	3963988 sealing washer	5.75	11.50
Parts	2	3963990 sealing washer	4.68	9.36
		GST On Sales	5.00%	480.39

MD Truck Repair accepts no responsibility for vehicles, equipment, or contents left on the premises. Also, this company accepts no responsibility for lost income, towing expenses, or any other expenses deemed to result from repairs made to vehicles or equipment. No warranty claim or labour can exceed the amount paid for the same parts and labour as itemized on this work order. Warranty for parts is the responsibility of the manufacturer. Interest will be charged on all invoices due past 30 days at the rate of 24% per annum calculated monthly.

Total	\$10,088.22
--------------	--------------------

I hereby acknowledge my indebtedness to be \$ _____ DATE: _____ X _____



MD TRUCK REPAIR

30 - 54108 RR 280
SPRUCE GROVE, AB
T7X 3V3
780-452-7975

mdtruck@telus.net

GST/HST No. 873857411

INVOICE

Date	Invoice #
22/04/2022	20703

P.O. #

Customer Name
1472906 ALBERTA LTD. 16221 - 123 AVENUE NW EDMONTON, AB T5V 1N9

Make	Year	Unit #	Odometer	Serial No.
Peterbilt	2013	823	456033 km	1XPTP4EXXDD197147

Item	Qty	Description	Rate	Amount
Labour	6	removed and replaced right center drive axle brakepot removed and replaced rear drive axle abs modulator valve assembly replaced right rear drive axle service brake hose from valve to brakepot replaced left taillight replaced one rear facing breather light on right side removed and replaced left steer axle slack adjuster and clevis pin greased and set brake removed stubshaft from back to front differential and pulled yoke removed pinion seal, cleaned surface and yoke installed new pinion seal and reinstalled yoke and stubshaft	138.00	828.00
Shop Supplies		Shop Supplies	8.00%	66.24
Truck Inspect...	1	Alberta Safety Inspection	250.00	250.00
FGI3030	1	brakepot	52.75	52.75
HABA8	1.5	1/2" air brake hose	1.65	2.47
110DC	1	1/2" x 3/8" pipe bushing	0.82	0.82
14928C	2	1/2" x 3/8" coupler (brakepot)	6.45	12.90
X115D	1	1/2" 90 deg street elbow	4.35	4.35
210737	1	pinion seal	37.19	37.19
Parts	1	K1289130R abs modulator valve	309.30	309.30
Parts	1	40010155 slack adjuster	122.84	122.84
3050	1	2" led red marker light	7.58	7.58
4050	1	4" red led light	20.88	20.88
		GST On Sales	5.00%	85.77

MD Truck Repair accepts no responsibility for vehicles, equipment, or contents left on the premises. Also, this company accepts no responsibility for lost income, towing expenses, or any other expenses deemed to result from repairs made to vehicles or equipment. No warranty claim or labour can exceed the amount paid for the same parts and labour as itemized on this work order. Warranty for parts is the responsibility of the manufacturer. Interest will be charged on all invoices due past 30 days at the rate of 24% per annum calculated monthly.

Total	\$1,801.09
--------------	-------------------

I hereby acknowledge my indebtedness to be \$ _____ DATE: _____ X _____