

DO2-22
SEP

Spectrum Industrial Automatics Ltd.

RR 1, Site 1, Box 9
27312 - 84, TWP 394 Aspelund
Blackfalds, Alberta T0M 0J0
Canada

78

INVOICE

Invoice No.: 7032
Date: Aug 25, 2015
Ship Date: Aug 25, 2015
Page: 1
Re: Order No. 15090

Sold to:

R.P.T.L.

PO BOX 122
WHITECOURT, AB T7S 1N3

Ship to:

RPTL TRUCKING LTD.

PO BOX 122
WHITECOURT, AB T7S 1N3

Business No.: 88776 3019 RT0001

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
	T-8	1.0	1995 KENWORTH, VIN: 1XKCDR0X4SR940629 MODEL: C500, LIC: J-76681, HOURS: 4208.9 -NO REVERSE	G		
ST0201-6EA	9C5D	3.0	1/8 DUAL WALL SHRINK TUBE	G	2.01	6.03
23019308	1E2H	1.0	Solenoid	G	248.79	248.79
23013114	9A3C	1.0	O-Ring	G	2.04	2.04
23040196	BRD5	1.0	GASKET	G	6.06	6.06
23017225	BRD4	1.0	GASKET	G	28.62	28.62
P170737	2A2	1.0	Filter (MC8200FDN8Z), incl enviro	G	112.51	112.51
D241	8A4A	1.0	O-RING, VITON	G	7.10	7.10
DEXRON	FLUID	30.0	Fluid, incl enviro	G	7.88	236.40
T501		4.0	Ties, 14" H.D.	G	0.39	1.56
808S-T	STKRM	2.0	LOOM, 1/2"	G	0.90	1.80
66-9939EA	9C5D	1.0	3/16" D.W. SHRINK TUBE	G	1.84	1.84
LABOUR	HOUR	22.0	LABOUR TO :TROUBLESHOT CAUSE OF NO REVERSE- CAN FEEL SHIFT ENGAGE BUT WON'T MOVE, TRY TO CONNECT LAPTOP=WON'T CONNECT, TRY PRO-LINK=ALSO NO CONNECTION, UNABLE TO LOCATE PLUG IN TOWER. REMOVE REVERSE SIGNAL & CHECK PRESSURE=OK, SPlice DDL INTO ECU= FOUND SOFT FAIL CODE 31, CHECK DRIVELINE MOVEMENT THROUGH SHIFTS= R NONE, CHECK FWD & REAR PRESSURE SWITCHES=OK, TEST DRIVE=1ST SHIFTS UP TO 3RD & LOCKUP STAYS ON TOO LONG. UNWRAP HARNESS TO ELIMINATE 2ND SHIFTER HARNESS, REPAIRED & RESPLICED WIRES TO J3 PLUG=CODE STILL PRESENT, ADD TEMP TEST SWITCH, CHECK SOLENOIDS RESISTANCE=OK, CHECK WIRE RESISTANCE=OK, CHECK FOR SHORT TO GROUND & ALL OTHER SHORTS, DRAIN & REMOVE PAN, INSPECT WIRES=OKTEST ALL SOLENOIDS IN V/B=C SOLENOID DOES NOT CLOSE=REPLACED.	G	129.50	2,849.00

Terms: Net 30. Due Sep 24, 2015.

Comment: CHANGE FILTERS AFTER OVERHAUL @ 200 HRS/8000KLMS , ALL GOODS
REMAIN OUR PROPERTY UNTILL PAID IN FULL

Continue...

RR 1, Site 1, Box 9
27312 - 84, TWP 394 Aspelund
Blackfalds, Alberta T0M 0J0
Canada

Invoice No.: 7032
Date: Aug 25, 2015
Ship Date: Aug 25, 2015
Page: 2
Re: Order No. 15090

PO BOX 122
WHITECOURT, AB T7S 1N3

Item No.	Unit	Quantity	Description	Tax	Unit Price	Amount
SS		0.1	REWRAP, RETIE & ROUTE ALL WIRING. CLEAN FILTER, REINSTALL V/B & PREP & INSTALL PAN, C/O EXTERNAL FILTER , FILL W/FLUID. TEST DRIVE AS REQUIRED=OK, CHECK OIL HOT=OK, CHECK FOR LEAKS=MAIN PSI LINE TO PTO LEAKS-CUSTOMER ADVISE AS PER CUSTOMER REQUEST: REOPEN TOWER & CHECK N-START=N SAFETY SWITCH ON PRIMARY SHIFTER, HAS 2 N SAFETY RELAYS, ATTACH SEC. SHIFTER RELAY WIRE TO PRIMARY SHIFTER, REWRAP & REASSEMBLE TOWER Shop Supplies **NOTE: LEAK AT MAIN PSI LINE REG SHOP RATE 136.50/HR G - GST 5.00% GST	G G G G	2,849.00	284.90 189.34
Spectrum Industrial Automatics Ltd. GST: #88776 3019						
Shipped By: _____ Tracking Number: _____ Terms: Net 30. Due Sep 24, 2015. Comment: CHANGE FILTERS AFTER OVERHAUL @ 200 HRS/8000KLMS , ALL GOODS REMAIN OUR PROPERTY UNTILL PAID IN FULL Sold By: STAFFORD, RYAN					Total Amount	3,975.99