

Denwood MOTORS Wainwright

CHEV - BUICK - CHEV & GMC TRUCKS
2202 - 14TH AVENUE, WAINWRIGHT, AB T9W 1L2

SMALL TRUCK

PHONE: (780) 842-4459

TOLL FREE:

1-877-842-CHEV (2438)

FAX: (780) 842-4760

www.denwoodmotors.com

G.S.T. # 101349082 RT

INVOICE ORIGINAL

Work Order

#207003

Brothers HDD

July 21, 2025

Svc. Adv Miller, Tyrel

Cust.Ph. (780) 875-8845

Tag#

Page 1 of 2

07/21/2025 16:39:46

To: Brothers HDD

2002 23rd Ave

Wainwright
T9W 0B8

AB

UNIT # 622

Year: 2022 Veh Id: 37372 Unit #: 37372

Make: Chevrolet

License #:

Model: Silverado 3500 SRW 4WD LT

Odo. In: 159,338

Colour: SUMMIT WHITE

Odo. Out:

V.I.N.#: 1GC4YTEY9NF307195

Next Service: 7/21/2025

Date In: 07/21/2025

In Service Date: 06/07/2022

Out: 07/21/2025

Cases: 2

Ext. War - - (mo /) - D: \$0.00

Promised Time: 07/21/2025 05:00:00 PM Call When Ready: No

Case: 1 A/C isn't blowing real cold

Quantity Description/Correction

1.00 13418808 - SEAL-A/C CMPR HOSE

Price Total

\$4.92 \$4.92

\$377.50 \$377.50

- A/C isn't blowing real cold - Tech Story - recovered 0.60kg, should have 0.70kg. charged, tested a/c with sniffer, found leak at a/c seals of lines going into compressor, recovered a/c. swapped seals. recharged.
- Tech Comments: recovered 0.60kg, should have 0.70kg. charged, tested a/c with sniffer, found leak at a/c seals of lines going into compressor, recovered a/c. swapped seals. recharged.
- Completed by: Jackson, Brett
- Shop Supplies - Retail

\$41.53 \$41.53

Misc \$41.53 Labour \$377.50 Parts \$4.92 Prepaid Parts Amt: \$0.00 Case Total: \$423.95

Case: 2 Check all trailer wiring

Quantity Description/Correction

Price Total

\$0.00 \$0.00

- Check all trailer wiring - Tech Story - checked wiring, wiring is good, everything works from inbox and bumper plugs.

Misc \$0.00 Labour \$0.00 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$0.00

\$0.00

SCANNED



11204 Alaska Road, Fort St John, BC V1J 5T5
Phone: 250-785-8005 • Toll Free: 1-800-811-1555 • Fax: 250-785-5122
www.murraygmc.com



CHEVROLET • BUICK • GMC
"Automotive Excellence is our Guarantee"

Monday - Friday 7:30am - 5:00pm • Saturday 9:00am - 5:00pm

SO # 485473

WJT
#622

SERVICE INVOICE CUSTOMER COPY

LOF w/o # 000131



Printed 02/12/2025 9:52:25 AM

User 512 Page 1

Customer No BROTHERS HDD PO BOX 10796 RPO 10 LLOYDMINSTER, AB T9V 3A8 Home Cell Email Bus (780) 875-8845 Today Term Debit Card	Advisor TAMMY Shop S1 Priority Promised 09/03/2024 5:00 PM Opened 09/03/2024 9:06 AM Cashiered 09/04/2024 4:01 PM Tag# 4543 Location PO # License #622 Odom In 122185 Odom Out 122187 In Service Date 06/07/2022 Stock No Year 2022 Make CHEVROLET Model SILVERADO 3500 HD Model Number CK30943 Colour Vehicle ID No 1GC4YTEY9NF307195 Selling Dealer Extended Warranty Delivery Date Engine DURAMAX 6.6L TURBO-DIESEL V8, Fleet #
--	--

Request	Description	Job	CSR	Status
29	Customer reports a solid check engine light - power reduced, SES Light is on at time of check in. Please check and advise	1	493	Original
Labour	Description	Type	Amount	
29	Customer reports a solid check engine light - power reduced. Please check and advise	CHT	199.95	
Technician	161 -			
Cause	excessively dirty air filter			
Correction	no ses light and no codes set at thsi time road test vehicle and low power and p0101 set checked and found air filter is bad and collapsing replaced air filter cleared codes road test and verfiied proper operation			
		Labour Total	199.95	
		Request Sub-total	199.95	

Request	Description	Job	CSR	Status
01TRUVIDEO	Truvideo	2	493	Original
Labour	Description	Type	Amount	
01TRUVIDEO	Truvideo	C	0.00	
Technician	161 -			
Cause	1			
Correction	1			

Request	Description					Job	CSR	Status
58	Product Safety Recall (N232426400): Tailgate May Open Unexpectedly (Release Date 2024-2-1)					3	493	Original
Labour	Description					Type	Amount	
9107323	Liftgate Exterior Release Switch Replacement	Shp	SL	Bin	Type	Price		
Part	Description	1		02B06	W4			
85734717	SWITCH							
loc.								
Technician	376 -							
Cause	Labor Operation							
	9107323							
	Liftgate Exterior Release Switch Replacement							
	Standard Tailgate							
	0.3							

PRINT NAME: _____

CUSTOMER SIGNATURE: _____

☐ DEBIT ☐ CHARGE ☐ CASH ☐ VISA ☐ MC ☐ AMEX INITIALS _____

Thank you for your Business!



IMPORTANT: All wheels must be retorqued within 100-150 kms. Its is our policy that all wheels be torqued to manufacturers specification at all times. We will provide retorquing at no extra charge within the kilometers listed above.

IMPORTANT NOTES: you may receive a questionnaire from General Motors in the next few days. If for any reason you cannot grade us completely satisfied, please contact our Service Manager at 250-785-8005

Due to environmental regulations there is a normal fee for the collection and disposal of hazardous materials. Example: oil filters, engine oil, glycol, transmission fluid, etc.

GST# 898953120RT0001



11204 Alaska Road, Fort St John, BC V1J 5T5
Phone: 250-785-8005 • Toll Free: 1-800-811-1555 • Fax: 250-785-5122
www.murraygmc.com



CHEVROLET • BUICK • GMC
"Automotive Excellence is our Guarantee"

Monday - Friday 7:30am - 5:00pm • Saturday 9:00am - 5:00pm

SO # 485473

SERVICE INVOICE CUSTOMER COPY



Printed 02/12/2025 9:52:25 AM

User 512 Page 2

Customer No

BROTHERS HDD
PO BOX 10796 RPO 10
LLOYDMINSTER, AB T9V 3A8

Home Cell Email Bus Today (780) 875-8845

Term Debit Card

Advisor TAMMY Promised 09/03/2024 5:00 PM Tag# 4543
Shop S1 Opened 09/03/2024 9:06 AM Location
Priority Cashiered 09/04/2024 4:01 PM PO #

License #622 Odom In 122185 Odom Out 122187 In Service Date 06/07/2022 Stock No
Year 2022 Make CHEVROLET Model SILVERADO 3500 HD Model Number CK30943 Colour
Vehicle ID No 1GC4YTEY9NF307195 Selling Dealer Extended Warranty Delivery Date
Engine DURAMAX 6.6L TURBO-DIESEL V8, Fleet #

Correction replaced switch and verified repair

also found:
both plate bulbs out

Request	Description	Job	CSR	Status			
01GMDSYN	Diesel Synthetic 5w/40 0% oil life remaining	4	493	Original			
Labour	Description	Type	Amount				
01GMDSYN	Diesel Synthetic 5w/40 0% oil life remaining	CGW	39.59				
Part	Description	Shp	SL	Bin	Type	Price	Amount
12735811	FILTER	1		05D04	CGMQS	13.25	13.25
19368503	OIL	2		BULK	CROIL	59.52	119.04
Technician	577 -			Parts Total			132.29
Cause	Customer requested LOF			Labour Total			39.59
Correction	Completed Lube, Oil and Filter change			Request Sub-total			171.88

Request	Description	Job	CSR	Status			
01GMZZ8	Pollen Filter- Inspect pollen filter - please replace per customer request	5	493	Original			
Labour	Description	Type	Amount				
01GMZZ8	Pollen Filter- Inspect pollen filter	CGW	20.30				
Part	Description	Shp	SL	Bin	Type	Price	Amount
13508023	FILTER	1		05A03	CROQS	39.65	39.65
Technician	577 -			Parts Total			39.65
Cause	Inspected			Labour Total			20.30
Correction	replaced			Request Sub-total			59.95

Request	Description	Job	CSR	Status			
01GMZZ-AIR	Inspect air filter - please replace per customer request	6	493	Original			
Labour	Description	Type	Amount				
01GMZZ-AIR	Inspect air filter	CGW	0.00				
Part	Description	Shp	SL	Bin	Type	Price	Amount
85614334	ELEMENT	1		05B06	CROQS	67.06	67.06
Technician	161 -			Parts Total			67.06
Cause	Inspected			Request Sub-total			67.06

PRINT NAME: _____

CUSTOMER SIGNATURE: _____

☐ DEBIT ☐ CHARGE ☐ CASH ☐ VISA ☐ MC ☐ AMEX INITIALS _____

Thank you for your Business!



IMPORTANT: All wheels must be retorqued within 100-150 kms. Its is our policy that all wheels be torqued to manufacturers specification at all times. We will provide retorquing at no extra charge within the kilometers listed above.

IMPORTANT NOTES: you may receive a questionnaire from General Motors in the next few days. If for any reason you cannot grade us completely satisfied, please contact our Service Manager at 250-785-8005

Due to environmental regulations there is a normal fee for the collection and disposal of hazardous materials. Example: oil filters, engine oil, glycol, transmission fluid, etc.

GST# 898953120RT0001



11204 Alaska Road, Fort St John, BC V1J 5T5
Phone: 250-785-8005 • Toll Free: 1-800-811-1555 • Fax: 250-785-5122
www.murraygmc.com



CHEVROLET • BUICK • GMC
"Automotive Excellence is our Guarantee"

Monday - Friday 7:30am - 5:00pm • Saturday 9:00am - 5:00pm

SO # 485473

SERVICE INVOICE CUSTOMER COPY



Printed 02/12/2025 9:52:25 AM

User 512 Page 3

Customer No

BROTHERS HDD
PO BOX 10796 RPO 10
LLOYDMINSTER, AB T9V 3A8

Home (780) 875-8845
Cell Today
Email

Term Debit Card

Advisor TAMMY Promised 09/03/2024 5:00 PM Tag# 4543
Shop S1 Opened 09/03/2024 9:06 AM Location
Priority Cashiered 09/04/2024 4:01 PM PO #

License	Odom In	Odom Out	In Service Date	Stock No
#622	122185	122187	06/07/2022	
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 3500 HD	CK30943	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1GC4YTEY9NF307195				
Engine	Fleet #			
DURAMAX 6.6L TURBO-DIESEL V8,				

Correction Replaced air filter

Request	Description	Job	CSR	Status			
01GMZZ91	Wynn's Diesel Fuel Induction Service	7	493	Original			
Labour	Description		Type	Amount			
01GMZZ91	Wynn's Diesel Fuel Induction Service		C	254.20			
Part	Description	Shp	SL	Bin	Type	Price	Amount
W71032K	DIESEL EGR KIT	1		BULK4	CGOOD	120.75	120.75
Technician	161 -			Parts Total			120.75
Cause	service			Labour Total			254.20
Correction	performed diesel induction service			Request Sub-total			374.95

Request	Description	Job	CSR	Status
19GMZZ01	Customer reports "Service Brake Pad Monitor" message showing on dash. Please inspect and advise.	8	493	Original
Labour	Description	Type	Amount	
19GMZZ01	Customer reports "Service Brake Pad Monitor" message showing on dash. Please inspect and advise.	CGW	0.00	
Technician	376 -			
Cause	rear pads sensor connector not seated			
Correction	c116b 56 set rear brake pad wear sensor too many transitions current pads all 10mm removed wheel and washed out mud for access to connector found connector not seated properly cleaned and lubed connector and reinstalled still causing code to return checked sensor circuit 1 to 2 found while moving harness it would go from 0.3 ohms to OL recommend replacing pad sensor			

Request	Description	Job	CSR	Status
0602501	No Charge Brake Inspection Promo - GM offer - Save up to \$120 on GM brake pads and rotors	9	493	Original
Labour	Description	Type	Amount	
0602501	No Charge Brake Inspection Promo - GM offer - Save up to \$120 on GM brake pads and rotors	C	0.00	
Technician	999 -			

Request	Description	Job	CSR	Status
01GMFFD17	Fuel Filter Replacement Diesel 2017 and newer - supply and install diesel fuel filter	10	493	Original
Labour	Description	Type	Amount	

PRINT NAME: _____

CUSTOMER SIGNATURE: _____

☐ DEBIT ☐ CHARGE ☐ CASH ☐ VISA ☐ MC ☐ AMEX INITIALS _____

Thank you for your Business!



IMPORTANT: All wheels must be retorqued within 100-150 kms. It is our policy that all wheels be torqued to manufacturers specification at all times. We will provide retorquing at no extra charge within the kilometers listed above.

IMPORTANT NOTES: you may receive a questionnaire from General Motors in the next few days. If for any reason you cannot grade us completely satisfied, please contact our Service Manager at 250-785-8005

Due to environmental regulations there is a normal fee for the collection and disposal of hazardous materials. Example: oil filters, engine oil, glycol, transmission fluid, etc.

GST# 898953120RT0001



CHEVROLET • BUICK • GMC
"Automotive Excellence is our Guarantee"

11204 Alaska Road, Fort St John, BC V1J 5T5
Phone: 250-785-8005 • Toll Free: 1-800-811-1555 • Fax: 250-785-5122
www.murraygmc.com



Monday - Friday 7:30am - 5:00pm • Saturday 9:00am - 5:00pm

SO # 485473

SERVICE INVOICE CUSTOMER COPY



Printed 02/12/2025 9:52:25 AM

User 512 Page 4

Customer No

BROTHERS HDD
PO BOX 10796 RPO 10
LLOYDMINSTER, AB T9V 3A8

Home Bus (780) 875-8845
Cell Today
Email

Term Debit Card

Advisor TAMMY Promised 09/03/2024 5:00 PM Tag# 4543
Shop S1 Opened 09/03/2024 9:06 AM Location
Priority Cashiered 09/04/2024 4:01 PM PO #

License #622	Odom In 122185	Odom Out 122187	In Service Date 06/07/2022	Stock No
Year 2022	Make CHEVROLET	Model SILVERADO 3500 HD	Model Number CK30943	Colour
Vehicle ID No 1GC4YTEY9NF307195	Selling Dealer	Extended Warranty	Delivery Date	
Engine DURAMAX 6.6L TURBO-DIESEL V8,	Fleet #			

01GMFFD17	Fuel Filter Replacement Diesel 2017 and newer - supply and install diesel fuel filter	CGW	49.95
Part 13539108	Description FILTER KI	Shp 1 SL 05E03 Bin CGOOD	Price 63.25 Amount 63.25
Technician 161 -		Parts Total	63.25
Cause Supply and install diesel fuel filter		Labour Total	49.95
Correction Supplied and installed diesel fuel filter reset fuel filter		Request Sub-total	113.20

Request 19GMZ	Description replace rear brake pad wear sensor	Job 11	CSR 493	Status Approved
Labour 19GMZ	Description replace rear brake pad wear sensor		Type CGW	Amount 110.97
Part 84571660	Description SENSOR	Shp 1 SL 03D08 Bin CGOOD	Price 29.25	Amount 29.25
Technician 376 -		Parts Total		29.25
Cause replace rear brake pad wear sensor		Labour Total		110.97
Correction replace rear brake pad wear sensor verified repair		Request Sub-total		140.22

Request 01GMZZBULB	Description replace license plate bulbs	Job 12	CSR 493	Status Approved
Labour 01GMZZBULB	Description replace license plate bulbs		Type C	Amount 73.98
Part 13503401	Description BULB	Shp 2 SL BC Bin CGOOD	Price 3.75	Amount 7.50
Technician 376 -		Parts Total		7.50
Cause replace license plate bulbs		Labour Total		73.98
Correction replace license plate bulbs		Request Sub-total		81.48

PRINT NAME: _____

CUSTOMER SIGNATURE: _____

☐ DEBIT ☐ CHARGE ☐ CASH ☐ VISA ☐ MC ☐ AMEX INITIALS _____

Thank you for your Business!



IMPORTANT: All wheels must be retorqued within 100-150 kms. It is our policy that all wheels be torqued to manufacturers specification at all times. We will provide retorquing at no extra charge within the kilometers listed above.

IMPORTANT NOTES: you may receive a questionnaire from General Motors in the next few days. If for any reason you cannot grade us completely satisfied, please contact our Service Manager at 250-785-8005

Due to environmental regulations there is a normal fee for the collection and disposal of hazardous materials. Example: oil filters, engine oil, glycol, transmission fluid, etc.

GST# 898953120RT0001



CHEVROLET • BUICK • GMC
"Automotive Excellence is our Guarantee"

11204 Alaska Road, Fort St John, BC V1J 5T5
Phone: 250-785-8005 • Toll Free: 1-800-811-1555 • Fax: 250-785-5122
www.murraygmc.com



Monday - Friday 7:30am - 5:00pm • Saturday 9:00am - 5:00pm

SO # 485473

SERVICE INVOICE
CUSTOMER COPY



Printed 02/12/2025 9:52:25 AM

User 512 Page 5

Customer No

BROTHERS HDD
PO BOX 10796 RPO 10
LLOYDMINSTER, AB T9V 3A8

Home Bus (780) 875-8845
Cell Today
Email

Term Debit Card

Advisor	TAMMY	Promised	09/03/2024 5:00 PM	Tag#	4543
Shop	S1	Opened	09/03/2024 9:06 AM	Location	
Priority		Cashiered	09/04/2024 4:01 PM	PO #	

License	Odom In	Odom Out	In Service Date	Stock No
#622	122185	122187	06/07/2022	
Year	Make	Model	Model Number	Colour
2022	CHEVROLET	SILVERADO 3500 HD	CK30943	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1GC4YTEY9NF307195				
Engine	DURAMAX 6.6L TURBO-DIESEL V8, Fleet #			

Labour	748.94
Parts	459.75
Supplies	89.87
Sub-Total	1,298.56
GST	64.93
PST	90.90
Total Invoice	1,454.39
Debit Card	1,454.39



PRINT NAME: _____

CUSTOMER SIGNATURE: _____

☐ DEBIT ☐ CHARGE ☐ CASH ☐ VISA ☐ MC ☐ AMEX INITIALS _____

Thank you for your Business!



IMPORTANT: All wheels must be retorqued within 100-150 kms. It is our policy that all wheels be torqued to manufacturers specification at all times. We will provide retorquing at no extra charge within the kilometers listed above.

IMPORTANT NOTES: you may receive a questionnaire from General Motors in the next few days. If for any reason you cannot grade us completely satisfied, please contact our Service Manager at 250-785-8005

Due to environmental regulations there is a normal fee for the collection and disposal of hazardous materials. Example: oil filters, engine oil, glycol, transmission fluid, etc.

GST# 898953120RT0001