

X16-1
SEP

Edge Fleet Maintenance (1998) Ltd.
PO Box 519
Embley AB T0H 3S0
80-532-8911
edgefleet@hotmail.com
GST Registration No.: 881387625RT0001

Invoice

BILL TO

SHADOW RATHOLE DRILLING LTD.

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
13306	13/07/2026	\$4,252.48	12/08/2026	Net 30	

UNIT #
592

VIN#
1NPFX40XX7889826

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
CVIP HEAVY TRUCK	CVIP HEAVY TRUCK CVIP #8700986	1	445.00	445.00
*CVIP/WHEEL REMOVAL	CVIP WHEEL REMOVAL .8/HR	7	123.20	862.40
				Subtotal: 1,307.40
	Replace reflective tape at drill as required.			
HOP RATE	SHOP RATE	0.50	154.00	77.00
*REF18806	REFLECTIVE TAPE/FT	7	1.04	7.28
				Subtotal: 84.28
	Replace A/C belt. Confirm idlers/pulleys.			
SHOP RATE	SHOP RATE	0.50	154.00	77.00
*638K6BLT	BELT	1	31.73	31.73
				Subtotal: 108.73
	Replace left side steer axle wheel seal. Clean as required. Assemble. Re-seal.			
SHOP RATE	SHOP RATE	2	154.00	308.00
*3828064	WHEEL SET, FRONT AXLE	1	114.48	114.48
*3303009	AXLE GASKET 6H STEM2110	1	4.28	4.28
*75W90MOB/L	75W90SYN MOBIL/L	1.50	15.73	23.60
EHC-L	ENVIRONMENTAL CHARGE	1.50	0.12	0.18
DISPOSAL FEE	DISPOSAL FEE/L	1.50	0.06	0.09
*BRAKLEEN	*BRAKLEEN	1.50	9.59	14.39
*C-031-100	5/16 X 1 NC BOLT	6	0.82	4.92
*5/16LW	5/16 LOCK WASHER	6	0.05	0.30
				Subtotal: 470.24
	Install (3x) rebound pads at springs (both sides).			

Thank you for choosing Edge Fleet. We appreciate your business.

If paying by e-transfer please use edgefleet@hotmail.com. We accept credit cards with 3% processing fee.

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
SHOP RATE	SHOP RATE	2	154.00	308.00
*M17416	SPRING BUMPER PAD	3	76.18	228.54
FREIGHT	FREIGHT	1	27.50	27.50
				Subtotal: 564.04
	Replace (3x) air bags, axle #2 left side, axle 33 both sides. Severe corrosion at mount hardware-additional time required.			
SHOP RATE	SHOP RATE	4	154.00	616.00
*AS8813P	AIRSPRING	3	138.19	414.57
*G381024080804	*#8 MNPT RUN TEE FITTING	1	66.10	66.10
				Subtotal: 1,096.67
	Repair beacon lamp operation-(3x) no operation. Disassemble. Clean connectors-(rotating), lube. Assemble. Verify.			
SHOP RATE	SHOP RATE	0.75	154.00	115.50
				Subtotal: 115.50
	Install anti-sail bracket, axle #2 right side.			
SHOP RATE	SHOP RATE	0.50	154.00	77.00
*ANTISAIL	ANTI-SAIL BRACKET	1	14.81	14.81
C-038-150	3/8 X 1 1/2 GR8 NC BOLT	3	0.31	0.93
3/8LN	3/8 LOCK NUT	3	0.15	0.45
*3/8FNDW	3/8 FLAT FENDER WASHER	4	0.12	0.48
				Subtotal: 93.67
	Inspect/repair positive air shut-off valve/seized. Lube. Free-up.			
SHOP RATE	SHOP RATE	0.50	154.00	77.00
				Subtotal: 77.00
SHOP SUPPLIES	MISC. SUPPLIES	1	132.44	132.44
				Subtotal: 132.44
	TORQUE WHEELS			

UNIT LIC# CFX7308

KMS 373877

HRS 14852

RE-TORQUE WHEELS @ 100 KMS

SUBTOTAL

GST @ 5%

TOTAL

BALANCE DUE

4,049.97

202.51

4,252.48

\$4,252.48

Thank you for choosing Edge Fleet. We appreciate your business.

If paying by e-transfer please use edgefleet@hotmail.com. We accept credit cards with 3% processing fee.

Bear Creek Maintenance Ltd

1-712016 Range Road 72A
 County of Grande Prairie #1, AB
 T8W 5H5, CA
 bearcr01@gmail.com
 (780) 814-2335



Invoice: 11821
Date: 8/15/2024

Bill To
 Shadow Rathole Drilling LTD

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
4923	Net 30	9/14/2024	Jason		Kinch, Marvin	592

Item	Description	Quantity	Rate	Amount
Complaint: Truck (4 Axle) - C Inspection				
Cause: Customer request				
Labor	Inspection / Truck / Truck (4 Axle) - C Inspection - Completed: 8/15/2024			\$329.00
			Subtotal	\$329.00
Complaint: 1.1. Accelerator Pedal/Throttle Actuator				
Cause: Fuel pedal roller worn				
(Procedure)				
Labor	Correction: Engine / Fuel / Replaced throttle roller and pin - Completed: 8/15/2024			\$28.50
Parts	KIT- ROLLER	1.00000	\$25.632	\$25.63
			Subtotal	\$54.13
Complaint: 3A.16. S-Cam Drum Brake System				
Cause: Slack adjuster pins tight				
(Procedure)				
Labor	Correction: Chassis / Air Brake / Sprayed down and freed up the slack adjuster pins. - Completed: 8/15/2024			\$55.50
			Subtotal	\$55.50
Complaint: 3A.14. Brake Chamber				
Cause: #2 and #3 left pushrod a little long				
(Procedure)				
Labor	Correction: Chassis / Air Brake / Adjusted pushrod travel and double checked operations of the slacks - Completed: 8/16/2024			\$33.00
			Subtotal	\$33.00

Item	Description	Quantity	Rate	Amount
Complaint: 5.3. Horn				
Cause: Electric horn does not work				
(Procedure)				
Labor	Correction: Chassis / Instrument & Controls / Plugged the horn back in. - Completed: 8/15/2024			\$15.00
Subtotal				\$15.00
Complaint: 6.1. Required Lamps				
Cause: Right side beacon has one bulb not working				
(Procedure)				
Labor	Correction: Chassis / Lighting & Electrical / Cleaned up a bad connection on a bulb on the right beacon. - Completed: 8/15/2024			\$34.50
Subtotal				\$34.50
Complaint: 8.3. Air-Suspended Cab				
Cause: Cab air bag mount plates are starting to come apart.				
(Procedure)				
Labor	Correction: Chassis / Suspension / Removed Huck bolts that were seized in and drilled out holes, installed new bolts with lock nuts and washers. Cleaned out all corrosion between mounts. - Completed: 8/16/2024			\$642.00
Parts	5/16 FLATWASHER GR 8	12.00000	\$0.0566	\$0.68
Parts	5/16 NYLOCK NUT	6.00000	\$0.138	\$0.83
Parts	5/16 X 1 1/2 BOLT GR 8 NC	6.00000	\$0.278	\$1.67
Subtotal				\$645.18
Unit: 592 VIN: 1NPFX40XX7N889826			Labor	\$1,137.50
2007 Peterbilt 378			Parts	\$28.81
Chassis: 373,876 Kilometers			Shop/Field Supplies	\$68.25
Engine: 14,848 Hours			Pre-Charge Subtotal	\$1,234.56
			GST	\$61.73
			(5% of \$1,234.56)	
			Total	\$1,296.29
			Payments & Credits	\$0.00
			Balance Due	\$1,296.29

All parts and labour are Net 30 days. After 30 days 2% interest will be charged per month (26.824% per annum)

Warranty on parts are warranted by parts supplier.

E-transfers accepted : bearc01@gmail.com



**Shadow Rathole Drilling
LTD**

Truck (4 Axle) - C Inspection
Completed Date: 8/15/2024
Unit: 592 VIN: 1NPFX40XX7N889826
Year/Make/Model: 2007 Peterbilt 378
Chassis Kilometers: 373,876 Kilometers (8/12/2024)
Engine Hours: 14,848 Hours (8/12/2024)
Service Order: 4923

Bear Creek Maintenance Ltd
 1-712016 Range Road 72A
 County of Grande Prairie #1, AB T8W 5H5, CA
 bearcrc01@gmail.com

Inspection:

Procedure	Result	Procedure	Result	Procedure	Result
1. 1.1. Accelerator Pedal/Throttle Actuator	Defective; Defect Corrected On: 8/19/2024	2. 1.2. Exhaust System	Satisfactory	3. 1.3. Emission Control Systems and Devices	N/A
4. 1.4. Drive Shaft	Satisfactory	5. 1.5. Clutch and Clutch Pedal	Satisfactory	6. 1.6. Engine/Transmission Mount	Satisfactory
7. 1.7. Engine/Shut Down	Satisfactory	8. 1.8. Engine Start Safety Feature	Satisfactory	9. 1.9. Gear Position Indicator	Satisfactory
10. 1.10. Engine or Accessory Drive Belt	Satisfactory	11. 1.11. Hybrid Electric Vehicle & Electric Vehicle Power Train System	N/A	12. 1.12. Gasoline or Diesel Fuel System	Satisfactory
13. 1.13. Pressurized or Liquefied Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*	N/A	14. A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System	N/A	15. A.2. Compressed Natural Gas (CNG) Fuel System	N/A
16. A.3. Liquefied Natural Gas (LNG) Fuel System	N/A	17. 2.1. Suspension & Frame Attachments	Satisfactory	18. 2.2. Axle Attaching & Tracking Components	Satisfactory
19. 2.3. Axle & Axle Assembly	Satisfactory	20. 2.4. Spring & Spring Attachment	Satisfactory	21. 2.5. Air Suspension	Satisfactory
22. 2.6. Self-Steer and Controlled-Steer Axle	N/A	23. 2.7. Shock Absorber/Strut Assembly	Satisfactory	24. 3H.1. Hydraulic System Components	N/A
25. 3H.2. Brake Pedal/Actuator	N/A	26. 3H.3. Vacuum Assist (Boost) System	N/A	27. 3H.4. Hydraulic Assist (Boost) System	N/A
28. 3H.5. Air Assist (Boost) System	N/A	29. 3H.6. Air-Over-Hydraulic Brake System	N/A	30. 3H.11. Brake System Indicator Lamps	N/A
31. 3H.12. Drum Brake System Components	N/A	32. 3H.13. Disc Brake System Components	N/A	33. 3H.14. Mechanical Parking Brake	N/A
34. 3H.15. Spring-Applied Air-Released Parking Brake	N/A	35. 3H.16. Spring-Applied Hydraulic-Released Parking Brake	N/A	36. 3H.17. Anti-Lock Brake System (ABS)	N/A
37. 3H.18. Stability Control System	N/A	38. 3H.19. Brake Performance	N/A	39. 3A.1. Air Compressor	Satisfactory
40. 3A.2. Air Supply System	Satisfactory	41. 3A.4. Air Tank	Satisfactory	42. 3A.5. Air Tank Check Valves	Satisfactory
43. 3A.6. Brake Pedal/Actuator	Satisfactory	44. 3A.7. Treadle Valve and Trailer Hand Valve	Satisfactory	45. 3A.8. Brake Valves & Controls	Satisfactory
46. 3A.9. Proportioning, Inversion or Modulation Valve	Satisfactory	47. 3A.10. Towing Vehicle (Tractor) Protection System	N/A	48. 3A.11. Parking Brake & Emergency Application	Satisfactory

49. 3A.13. Air System Components	Satisfactory	50. 3A.14. Brake Chamber	Defective; Defect Corrected On: 8/19/2024	51. 3A.15. Drum Brake System Components	Satisfactory
52. 3A.16. S-Cam Drum Brake System	Defective; Defect Corrected On: 8/19/2024	53. 3A.17. Brake Shoe Travel (Wedge Brakes)	N/A	54. 3A.18. Disc Brake System Components	N/A
55. 3A.19. Anti-Lock Brake System (ABS)	Satisfactory	56. 3A.21. Stability Control System	N/A	57. 3A.23. Brake Performance	N/A
58. 4.1. Steering Control and Linkage	Satisfactory	59. 4.2. Power Steering System (Hydraulic and Electric)	Satisfactory	60. 4.3. Steering Operation (Active Steer Axle)	Satisfactory
61. 4.4. Kingpin	Satisfactory	62. 4.5. Self-Steer and Controlled-Steer Axle	N/A	63. 5.1. Fire Extinguisher	Satisfactory
64. 5.2. Hazard Warning Kit	Satisfactory	65. 5.3. Horn	Defective; Defect Corrected On: 8/19/2024	66. 5.5. Speedometer	Satisfactory
67. 5.6. Odometer	Satisfactory	68. 5.7. Windshield Wiper/Washer	Satisfactory	69. 5.8. Heater & Windshield Defroster	Satisfactory
70. 5.9. Fuel-Burning Auxiliary Heater	N/A	71. 5.10. Chain/"Headache" Rack	Satisfactory	72. 5.11. Auxiliary Controls and Devices	Satisfactory
73. 5.12. Auxiliary Drive Controls	N/A	74. 6.1. Required Lamps	Defective; Defect Corrected On: 8/19/2024	75. 6.2. Reflex Reflector	Satisfactory
76. 6.3. Retro-Reflective Marking	Satisfactory	77. 6.4. Instrument Panel Lamps	Satisfactory	78. 6.5. Headlamp Aim	Satisfactory
79. 7.1. Wiring	Satisfactory	80. 7.2. Battery	Satisfactory	81. 7.3. Trailer Cord (output to towed vehicle)	N/A
82. 8.1. Hood or Engine Enclosure	Satisfactory	83. 8.2. Tilt Cab	N/A	84. 8.3. Air-Suspended Cab	Defective; Defect Corrected On: 8/19/2024
85. 8.4. Cab and Passenger-Vehicle Body	Satisfactory	86. 8.5. Cargo Body	Satisfactory	87. 8.6. Frame, Rails & Mounts	Satisfactory
88. 8.7. Unitized Body Elements	Satisfactory	89. 8.8. Cab or Cargo Door	Satisfactory	90. 8.9. Cargo Tank or Vessel	N/A
91. 8.10. Body, Device or Equipment Attached or Mounted to the	Satisfactory	92. 8.11. Refrigeration/Heater Unit Fuel System (Reefer or Auxiliary Power Unit (APU))	N/A	93. 8.12. Bumper	Satisfactory
94. 8.13. Windshield	Satisfactory	95. 8.14. Side Windows	Satisfactory	96. 8.15. Rear Window	N/A
97. 8.16. Interior Sun Visor	Satisfactory	98. 8.17. Exterior Windshield Sun Visor	Satisfactory	99. 8.18. Rear-View Mirror	Satisfactory
100. 8.19. Seat	Satisfactory	101. 8.20. Seat Belt/Occupant Restraint	Satisfactory	102. 8.21. Fender/Mud Flap	Satisfactory
103. 8.24. Aerodynamic Device & Attachment	N/A	104. 9.1. Tire Tread Depth	Satisfactory	105. 9.2. Tire Tread Condition	Satisfactory
106. 9.3. Tire Sidewall & Manufacturer Markings	Satisfactory	107. 9.4. Tire Inflation Pressure	Satisfactory	108. 9.5. Wheel Hub	Satisfactory

109. 9.6. Wheel Bearing	Satisfactory	110. 9.7. Wheel/Rim (Applies to all wheel types)	Satisfactory	111. 9.8. Multi-Piece Wheel/Rim	N/A
112. 9.9. Spoke Wheel/Demountable Rim System	N/A	113. 9.10. Disc Wheel System	Satisfactory	114. 9.11. Wheel Fasteners (Nuts, Bolts and Studs)	Satisfactory
115. 10.1. Hitch Assembly, Structure & Attaching Components	N/A	116. 10.2. Secondary Attachment (Safety Chain or Cable)	N/A	117. 10.3. Pintle Hook, Pin Hitch, or Coupler Hitch	N/A
118. 10.4. Ball Type Hitch	N/A	119. 10.5. Roll-Coupling Hitch	N/A	120. 10.6. Automated Coupling Device	N/A
121. 10.7. Fifth Wheel Coupler	N/A	122. 10.8. Oscillating Fifth Wheel Coupler	N/A		

Technician: Robbyn Troup**Digital Signature:** Robbyn Troup**Date:** 8/15/2024

Bear Creek Maintenance Ltd

1-712016 Range Road 72A
 County of Grande Prairie #1, AB
 T8W 5H5, CA
 bearcr01@gmail.com
 (780) 814-2335



Invoice: 10931

Date: 7/13/2023

Bill To

Shadow Rathole Drilling LTD

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
4028	Net 30	8/12/2023	Jason		Troup, Robbyn	592

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: Truck (4 Axle) - A Inspection**Cause:** Customer request

Labor	Inspection / Truck / Truck (4 Axle) - A Inspection - Completed: 7/24/2023			\$329.00
-------	---	--	--	----------

Subtotal \$329.00**Complaint:** Remove tires and /or dust shields for inspection**Cause:** As required for A inspection

(Inspection)

Labor	Correction:			\$720.00
-------	--------------------	--	--	----------

Chassis / Tire & Wheels / Removed and installed tires for inspection. -
 Completed: 7/17/2023

Subtotal \$720.00**Complaint:** 3A.16. S-Cam Drum Brake System**Cause:** 4L S cam bracket is loose, 3R S cam bracket is broken.

(Procedure)

Labor	Correction:			\$270.00
-------	--------------------	--	--	----------

Chassis / Air Brake / Tightened the loose bracket and replaced the broken one.
 - Completed: 7/14/2023

Parts	STRAP-BRAC KET REINFORCEME	1.00000	\$36.648	\$36.65
-------	----------------------------	---------	----------	---------

Parts	5/16 X 2 1/4 BOLT GR 8 NC	1.00000	\$0.30	\$0.30
-------	---------------------------	---------	--------	--------

Parts	5/16 FLATWASHER GR 8	2.00000	\$0.076	\$0.15
-------	----------------------	---------	---------	--------

Parts	5/16 NYLOCK NUT	1.00000	\$0.136	\$0.14
-------	-----------------	---------	---------	--------

Subtotal \$307.24**Complaint:** 5.3. Horn**Cause:** Electric horn doesn't work.

(Procedure)

Item	Description	Quantity	Rate	Amount
Labor	Correction: Chassis / Chassis / Plugged the horn in. - Completed: 7/13/2023			\$27.00
Subtotal				\$27.00

Complaint: 6.1. Required Lamps**Cause:** Right bumper light not working, right headlight marker light not working, left air cleaner light 50%

(Procedure)

Labor	Correction: Chassis / Lighting & Electrical / Repaired bad grounds on bumper lamp, and also right headlamp marker, left air cleaner lamp replaced. - Completed: 7/17/2023			\$253.50
Parts	LED- 2" RD CLEARANCE- AMBER	1.00000	\$10.43	\$10.43
Parts	MISC. ELECTRICAL	1.00000	\$3.25	\$3.25
Subtotal				\$267.18

Complaint: 8.18. Rear-View Mirror**Cause:** Right mirror is foggy.

(Procedure)

Labor	Correction: Chassis / Chassis / Replaced the right mirror and wired it in. - Completed: 7/14/2023			\$120.00
Parts	MIRRO, WC, 7"X16", SS, HEAT/LIGHT OR STYLE	1.00000	\$56.155	\$56.16
Parts	MISC ELECTRICAL	1.00000	\$4.98	\$4.98
Subtotal				\$181.14

Complaint: 8.21. Fender/Mud Flap**Cause:** Right fender bolts loose

(Procedure)

Labor	Correction: Chassis / Frame / Tightened up bolts, had to replaced one. - Completed: 7/13/2023			\$42.00
Parts	GRADE 5 3/8 X 1 1/4 NC	1.00000	\$0.294	\$0.29
Parts	GR 5 3/8 FLATWASHER	2.00000	\$0.084	\$0.17
Parts	3/8 LOCKNUT	1.00000	\$0.60	\$0.60
Subtotal				\$43.06

Complaint: 9.5. Wheel Hub**Cause:** Both front wheel bearings need to be adjusted.

1L hub cap plug hard.

(Procedure)

Item	Description	Quantity	Rate	Amount
Labor	Correction: Chassis / Chassis / Plugged the horn in. - Completed: 7/13/2023			\$27.00
Subtotal				\$27.00

Complaint: 6.1. Required Lamps**Cause:** Right bumper light not working, right headlight marker light not working, left air cleaner light 50%

(Procedure)

Labor	Correction: Chassis / Lighting & Electrical / Repaired bad grounds on bumper lamp, and also right headlamp marker, left air cleaner lamp replaced. - Completed: 7/17/2023			\$253.50
Parts	LED- 2" RD CLEARANCE- AMBER	1.00000	\$10.43	\$10.43
Parts	MISC. ELECTRICAL	1.00000	\$3.25	\$3.25
Subtotal				\$267.18

Complaint: 8.18. Rear-View Mirror**Cause:** Right mirror is foggy.

(Procedure)

Labor	Correction: Chassis / Chassis / Replaced the right mirror and wired it in. - Completed: 7/14/2023			\$120.00
Parts	MIRRO, WC, 7"X16", SS, HEAT/LIGHT OR STYLE	1.00000	\$56.155	\$56.16
Parts	MISC ELECTRICAL	1.00000	\$4.98	\$4.98
Subtotal				\$181.14

Complaint: 8.21. Fender/Mud Flap**Cause:** Right fender bolts loose

(Procedure)

Labor	Correction: Chassis / Frame / Tightened up bolts, had to replaced one. - Completed: 7/13/2023			\$42.00
Parts	GRADE 5 3/8 X 1 1/4 NC	1.00000	\$0.294	\$0.29
Parts	GR 5 3/8 FLATWASHER	2.00000	\$0.084	\$0.17
Parts	3/8 LOCKNUT	1.00000	\$0.60	\$0.60
Subtotal				\$43.06

Complaint: 9.5. Wheel Hub**Cause:** Both front wheel bearings need to be adjusted.

1L hub cap plug hard.

(Procedure)

Item	Description	Quantity	Rate	Amount
Labor	Correction: Chassis / Chassis / Removed the 1L hub cap and found they were at their best adjustment. Put the hub cap back on and filled it up. Replaced the 1L hub cap plug. - Completed: 7/13/2023			\$48.00
Parts	HUB CAP VENT PLUG- LARGE	1.00000	\$7.125	\$7.13
Parts	HUBCAP- GASKET- STD. 6-HOLE	1.00000	\$2.62881	\$2.63
Parts	HUB OIL/QUART/946 ML	1.00000	\$12.43953	\$12.44
	Subtotal			\$70.20

Unit: 592 VIN: 1NPFX40XX7N889826
 2007 Peterbilt 378
 Chassis: 373,580 Kilometers
 Engine: 14,663 Hours

Labor	\$1,809.50
Parts	\$135.32
Shop/Field Supplies	\$79.99
Pre-Charge Subtotal	\$2,024.81
GST (5% of \$2,024.81)	\$101.24
Total	\$2,126.05
Payments & Credits	\$0.00
Balance Due	\$2,126.05

GST# 838850253

All parts and labour are Net 30 days. After 30 days 2% interest will be charged per month (26.824% per annum)

Warranty on parts are warranted by parts supplier.

E-transfers accepted : beacr01@gmail.com



**Shadow Rathole Drilling
LTD**

Truck (4 Axle) - A Inspection

Completed Date: 7/24/2023

Unit: 592 VIN: 1NPFX40XX7N889826

Year/Make/Model: 2007 Peterbilt 378

Chassis Kilometers: 373,580 Kilometers (7/13/2023)

Engine Hours: 14,663 Hours (8/26/2022)

Service Order: 4028

Bear Creek Maintenance Ltd

1-712016 Range Road 72A

County of Grande Prairie #1, AB T8W 5H5, CA

bearcr01@gmail.com

Inspection:

Procedure	Result	Procedure	Result	Procedure	Result
1. 1.1. Accelerator Pedal/Throttle Actuator	Satisfactory	2. 1.2. Exhaust System	Satisfactory	3. 1.3. Emission Control Systems and Devices	N/A
4. 1.4. Drive Shaft	Satisfactory	5. 1.5. Clutch and Clutch Pedal	Satisfactory	6. 1.6. Engine/Transmission Mount	Satisfactory
7. 1.7. Engine/Shut Down	Satisfactory	8. 1.8. Engine Start Safety Feature	N/A	9. 1.9. Gear Position Indicator	Satisfactory
10. 1.10. Engine or Accessory Drive Belt	Satisfactory	11. 1.11. Hybrid Electric Vehicle & Electric Vehicle Power Train System	N/A	12. 1.12. Gasoline or Diesel Fuel System	Satisfactory
13. 1.13. Pressurized or Liquefied Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*	N/A	14. A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System	N/A	15. A.2. Compressed Natural Gas (CNG) Fuel System	N/A
16. A.3. Liquefied Natural Gas (LNG) Fuel System	N/A	17. 2.1. Suspension & Frame Attachments	Satisfactory	18. 2.2. Axle Attaching & Tracking Components	Satisfactory
19. 2.3. Axle & Axle Assembly	Satisfactory	20. 2.4. Spring & Spring Attachment	Satisfactory	21. 2.5. Air Suspension	Satisfactory
22. 2.6. Self-Steer and Controlled-Steer Axle	N/A	23. 2.7. Shock Absorber/Strut Assembly	Satisfactory	24. 3H.1. Hydraulic System Components	N/A
25. 3H.2. Brake Pedal/Actuator	N/A	26. 3H.3. Vacuum Assist (Boost) System	N/A	27. 3H.4. Hydraulic Assist (Boost) System	N/A
28. 3H.5. Air Assist (Boost) System	N/A	29. 3H.6. Air-Over-Hydraulic Brake System	N/A	30. 3H.11. Brake System Indicator Lamps	N/A
31. 3H.12. Drum Brake System Components	N/A	32. 3H.13. Disc Brake System Components	N/A	33. 3H.14. Mechanical Parking Brake	N/A
34. 3H.15. Spring-Applied Air-Released Parking Brake	N/A	35. 3H.16. Spring-Applied Hydraulic-Released Parking Brake	N/A	36. 3H.17. Anti-Lock Brake System (ABS)	N/A
37. 3H.18. Stability Control System	N/A	38. 3H.19. Brake Performance	N/A	39. 3A.1. Air Compressor	Satisfactory
40. 3A.2. Air Supply System	Satisfactory	41. 3A.4. Air Tank	Satisfactory	42. 3A.5. Air Tank Check Valves	Satisfactory
43. 3A.6. Brake Pedal/Actuator	Satisfactory	44. 3A.7. Treadle Valve and Trailer Hand Valve	Satisfactory	45. 3A.8. Brake Valves & Controls	Satisfactory
46. 3A.9. Proportioning, Inversion or Modulation Valve	Satisfactory	47. 3A.10. Towing Vehicle (Tractor) Protection System	Satisfactory	48. 3A.11. Parking Brake & Emergency Application	Satisfactory



Shadow Rathole Drilling
LTD

Truck (4 Axle) - A Inspection
Completed Date: 7/24/2023
Unit: 592 VIN: 1NPFX40XX7N889826
Year/Make/Model: 2007 Peterbilt 378
Chassis Kilometers: 373,580 Kilometers (7/13/2023)
Engine Hours: 14,663 Hours (8/26/2022)
Service Order: 4028

Bear Creek Maintenance Ltd
 1-712016 Range Road 72A
 County of Grande Prairie #1, AB T8W 5H5, CA
 bearcr01@gmail.com

Inspection:

Procedure	Result	Procedure	Result	Procedure	Result
1. 1.1. Accelerator Pedal/Throttle Actuator	Satisfactory	2. 1.2. Exhaust System	Satisfactory	3. 1.3. Emission Control Systems and Devices	N/A
4. 1.4. Drive Shaft	Satisfactory	5. 1.5. Clutch and Clutch Pedal	Satisfactory	6. 1.6. Engine/Transmission Mount	Satisfactory
7. 1.7. Engine/Shut Down	Satisfactory	8. 1.8. Engine Start Safety Feature	N/A	9. 1.9. Gear Position Indicator	Satisfactory
10. 1.10. Engine or Accessory Drive Belt	Satisfactory	11. 1.11. Hybrid Electric Vehicle & Electric Vehicle Power Train System	N/A	12. 1.12. Gasoline or Diesel Fuel System	Satisfactory
13. 1.13. Pressurized or Liquefied Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*	N/A	14. A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System	N/A	15. A.2. Compressed Natural Gas (CNG) Fuel System	N/A
16. A.3. Liquefied Natural Gas (LNG) Fuel System	N/A	17. 2.1. Suspension & Frame Attachments	Satisfactory	18. 2.2. Axle Attaching & Tracking Components	Satisfactory
19. 2.3. Axle & Axle Assembly	Satisfactory	20. 2.4. Spring & Spring Attachment	Satisfactory	21. 2.5. Air Suspension	Satisfactory
22. 2.6. Self-Steer and Controlled-Steer Axle	N/A	23. 2.7. Shock Absorber/Strut Assembly	Satisfactory	24. 3H.1. Hydraulic System Components	N/A
25. 3H.2. Brake Pedal/Actuator	N/A	26. 3H.3. Vacuum Assist (Boost) System	N/A	27. 3H.4. Hydraulic Assist (Boost) System	N/A
28. 3H.5. Air Assist (Boost) System	N/A	29. 3H.6. Air-Over-Hydraulic Brake System	N/A	30. 3H.11. Brake System Indicator Lamps	N/A
31. 3H.12. Drum Brake System Components	N/A	32. 3H.13. Disc Brake System Components	N/A	33. 3H.14. Mechanical Parking Brake	N/A
34. 3H.15. Spring-Applied Air-Released Parking Brake	N/A	35. 3H.16. Spring-Applied Hydraulic-Released Parking Brake	N/A	36. 3H.17. Anti-Lock Brake System (ABS)	N/A
37. 3H.18. Stability Control System	N/A	38. 3H.19. Brake Performance	N/A	39. 3A.1. Air Compressor	Satisfactory
40. 3A.2. Air Supply System	Satisfactory	41. 3A.4. Air Tank	Satisfactory	42. 3A.5. Air Tank Check Valves	Satisfactory
43. 3A.6. Brake Pedal/Actuator	Satisfactory	44. 3A.7. Treadle Valve and Trailer Hand Valve	Satisfactory	45. 3A.8. Brake Valves & Controls	Satisfactory
46. 3A.9. Proportioning, Inversion or Modulation Valve	Satisfactory	47. 3A.10. Towing Vehicle (Tractor) Protection System	Satisfactory	48. 3A.11. Parking Brake & Emergency Application	Satisfactory

49. 3A.13. Air System Components	Satisfactory	50. 3A.14. Brake Chamber	Satisfactory	51. 3A.15. Drum Brake System Components	Satisfactory
52. 3A.16. S-Cam Drum Brake System	Defective; Defect Corrected On: 7/25/2023	53. 3A.17. Brake Shoe Travel (Wedge Brakes)	N/A	54. 3A.18. Disc Brake System Components	N/A
55. 3A.19. Anti-Lock Brake System (ABS)	Satisfactory	56. 3A.21. Stability Control System	N/A	57. 3A.23. Brake Performance	N/A
58. 4.1. Steering Control and Linkage	Satisfactory	59. 4.2. Power Steering System (Hydraulic and Electric)	Satisfactory	60. 4.3. Steering Operation (Active Steer Axle)	N/A
61. 4.4. Kingpin	Satisfactory	62. 4.5. Self-Steer and Controlled-Steer Axle	N/A	63. 5.1. Fire Extinguisher	Satisfactory
64. 5.2. Hazard Warning Kit	Satisfactory	65. 5.3. Horn	Defective; Defect Corrected On: 7/25/2023	66. 5.5. Speedometer	Satisfactory
67. 5.6. Odometer	Satisfactory	68. 5.7. Windshield Wiper/Washer	Satisfactory	69. 5.8. Heater & Windshield Defroster	Satisfactory
70. 5.9. Fuel-Burning Auxiliary Heater	N/A	71. 5.10. Chain/"Headache" Rack	Satisfactory	72. 5.11. Auxiliary Controls and Devices	Satisfactory
73. 5.12. Auxiliary Drive Controls	N/A	74. 6.1. Required Lamps	Defective; Defect Corrected On: 7/25/2023	75. 6.2. Reflex Reflector	Satisfactory
76. 6.3. Retro-Reflective Marking	Satisfactory	77. 6.4. Instrument Panel Lamps	Satisfactory	78. 6.5. Headlamp Aim	Satisfactory
79. 7.1. Wiring	Satisfactory	80. 7.2. Battery	Satisfactory	81. 7.3. Trailer Cord (output to towed vehicle)	N/A
82. 8.1. Hood or Engine Enclosure	Satisfactory	83. 8.2. Tilt Cab	N/A	84. 8.3. Air-Suspended Cab	Satisfactory
85. 8.4. Cab and Passenger-Vehicle Body	Satisfactory	86. 8.5. Cargo Body	N/A	87. 8.6. Frame, Rails & Mounts	Satisfactory
88. 8.7. Unitized Body Elements	Satisfactory	89. 8.8. Cab or Cargo Door	Satisfactory	90. 8.9. Cargo Tank or Vessel	N/A
91. 8.10. Body, Device or Equipment Attached or Mounted to the	Satisfactory	92. 8.11. Refrigeration/Heater Unit Fuel System (Reefer or Auxiliary Power Unit (APU))	N/A	93. 8.12. Bumper	Satisfactory
94. 8.13. Windshield	Satisfactory	95. 8.14. Side Windows	Satisfactory	96. 8.15. Rear Window	N/A
97. 8.16. Interior Sun Visor	Satisfactory	98. 8.17. Exterior Windshield Sun Visor	Satisfactory	99. 8.18. Rear-View Mirror	Defective; Defect Corrected On: 7/25/2023
100. 8.19. Seat	Satisfactory	101. 8.20. Seat Belt/Occupant Restraint	Satisfactory	102. 8.21. Fender/Mud Flap	Defective; Defect Corrected On: 7/25/2023
103. 8.24. Aerodynamic Device & Attachment	N/A	104. 9.1. Tire Tread Depth	Satisfactory	105. 9.2. Tire Tread Condition	Satisfactory

106. 9.3. Tire Sidewall & Manufacturer Markings	Satisfactory	107. 9.4. Tire Inflation Pressure	Satisfactory	108. 9.5. Wheel Hub	Defective; Defect Corrected On: 7/25/2023
109. 9.6. Wheel Bearing	Satisfactory	110. 9.7. Wheel/Rim (Applies to all wheel types)	Satisfactory	111. 9.8. Multi-Piece Wheel/Rim	N/A
112. 9.9. Spoke Wheel/Demountable Rim System	N/A	113. 9.10. Disc Wheel System	Satisfactory	114. 9.11. Wheel Fasteners (Nuts, Bolts and Studs)	Satisfactory
115. 10.1. Hitch Assembly, Structure & Attaching Components	N/A	116. 10.2. Secondary Attachment (Safety Chain or Cable)	N/A	117. 10.3. Pintle Hook, Pin Hitch, or Coupler Hitch	N/A
118. 10.4. Ball Type Hitch	N/A	119. 10.5. Roll-Coupling Hitch	N/A	120. 10.6. Automated Coupling Device	N/A
121. 10.7. Fifth Wheel Coupler	N/A	122. 10.8. Oscillating Fifth Wheel Coupler	N/A		

Technician: Marvin Kinch

Digital Signature: Marvin Kinch

Date: 7/24/2023

106. 9.3. Tire Sidewall & Manufacturer Markings

Satisfactory

107. 9.4. Tire Inflation Pressure

Satisfactory

108. 9.5. Wheel Hub

Defective;
Defect
Corrected On:
7/25/2023

109. 9.6. Wheel Bearing

Satisfactory

110. 9.7. Wheel/Rim (Applies to all wheel types)

Satisfactory

111. 9.8. Multi-Piece Wheel/Rim

N/A

112. 9.9. Spoke
Wheel/Demountable Rim
System

N/A

113. 9.10. Disc Wheel System

Satisfactory

114. 9.11. Wheel Fasteners
(Nuts, Bolts and Studs)

Satisfactory

115. 10.1. Hitch Assembly,
Structure & Attaching
Components

N/A

116. 10.2. Secondary
Attachment (Safety Chain or
Cable)

N/A

117. 10.3. Pintle Hook, Pin
Hitch, or Coupler Hitch

N/A

118. 10.4. Ball Type Hitch

N/A

119. 10.5. Roll-Coupling Hitch

N/A

120. 10.6. Automated Coupling
Device

N/A

121. 10.7. Fifth Wheel Coupler

N/A

122. 10.8. Oscillating Fifth
Wheel Coupler

N/A

Technician: Marvin Kinch

Digital Signature: Marvin Kinch

Date: 7/24/2023

Edge Fleet Maintenance (1998) Ltd.

PO BOX 519
WEMBLEY, AB
T0H 3S0
Ph: 780-532-8911

E-mail: edgefleet@hotmail.com

INVOICE #
9391
DATE
13/10/2022

BILL TO:

SHADOW RATHOLE DRILLING LTD.

				PO #	UNIT	
					592	
TERMS	RATE	SERIAL #	LICENCE#	ODOMETER	HOURS	
Net 30	\$135/HR	1NPFX40XX7N889826	CFX7308	372077 KMS	14731 HRS	
Item	Description			Qty	Rate	Amount
	Perform full service on unit. Change oil and fuel filters. Check all levels. Grease and lubricate throughout. As per list check into back up light issue. Check wiring etc. All seems to be ok but found switch defective. No switch available. Order in and will go to Shadow yard to install when part comes in. As requested check into air leak under cab. Remove floor boards etc. Soap down all accessible fittings and lines etc. No able to locate leak at this time.					
SHOP RATE	SHOP RATE			4.5	135.00	607.50
LF140000	OIL FILTER/LG			1	86.97	86.97
EHC-LG	ENVIRONMENTAL CHARGE			1	1.00	1.00
BF7760	FILTER/SM			1	24.29	24.29
EHC-SM	ENVIRONMENTAL CHARGE			1	0.50	0.50
BF7766	FILTER-LG			1	28.34	28.34
EHC-LG	ENVIRONMENTAL CHARGE			1	1.00	1.00
ROTT41540/L	ROTELLA T4 15W40/L			40	6.98	279.20
EHC-L	ENVIRONMENTAL CHARGE			40	0.10	4.00
DISPOSAL FEE	DISPOSAL FEE/L			40	0.15	6.00
WNTRGRS	WINTER GREASE			3	8.00	24.00
SUPPLIES	MISC SUPPLIES				12.15	12.15
	SUB-TOTAL					1,074.95
	NOTE found some oil starting to weep around pinion seal on rear of tranny.					
	GST On Sales				5.00%	53.75

THANK YOU FOR CHOOSING EDGE.
IF YOU'RE HAPPY TELL OTHERS. IF YOU'RE NOT PLEASE TELL US.

Subtotal	\$1,074.95
GST	\$53.75
Total	\$1,128.70

GST/HST No.

881387625

Edge Fleet Maintenance (1998) Ltd.

PO BOX 519
WEMBLEY, AB
T0H 3S0
Ph: 780-532-8911

E-mail: edgefleet@hotmail.com

INVOICE #
9402
DATE
20/10/2022

BILL TO:

SHADOW RATHOLE DRILLING LTD.

				PO #	UNIT	
					592	
TERMS	RATE	SERIAL #	LICENCE#	ODOMETER	HOURS	
Net 30	\$135/HR	N889826	CFX7308	372757 KMS	14747 HRS	
Item	Description			Qty	Rate	Amount
FIELD RATE 091221 SUPPLIES	Drive to Shadow yard. Replace auxiliary switch and test lights. Good.			0.75	135.00	101.25
	FIELD RATE			1	155.86	155.86
	AUX SWITCH				4.05	4.05
	MISC SUPPLIES					261.16
	SUB-TOTAL					13.06
	GST On Sales				5.00%	

THANK YOU FOR CHOOSING EDGE.
IF YOU'RE HAPPY TELL OTHERS. IF YOU'RE NOT PLEASE TELL US.

Subtotal	\$261.16
GST	\$13.06
Total	\$274.22

GST/HST No. 881387625

Edge Fleet Maintenance (1998) Ltd.

PO BOX 519
WEMBLEY, AB
T0H 3S0
Ph: 780-532-8911

E-mail: edgefleet@hotmail.com

INVOICE #
9233
DATE
18/08/2022

BILL TO:
SHADOW RATHOLE DRILLING LTD.

				PO #	UNIT	
					592	
TERMS	RATE	SERIAL #	LICENCE#	ODOMETER	HOURS	
Net 30	\$135/HR	1NPFX40XX7N889826	CFX7308	369804 KMS	14638 HRS	
Item	Description			Qty	Rate	Amount
SHOP RATE	Rearrange and tie up all brakepot lines which were rubbing on frame and diffs.			0.5	135.00	67.50
	SHOP RATE					67.50
	SUB-TOTAL					
SHOP RATE	Replace #1 right side dustshield. Had to use torch to remove all bolts.			0.75	135.00	101.25
	SHOP RATE			1	228.13	228.13
	DUST SHIELD KIT					329.38
314167	SUB-TOTAL					
	Replace #3 right side dustshield. Had to use torch to remove all bolts.			0.75	135.00	101.25
	SHOP RATE			1	47.30	47.30
973953	DUSTSHIELD REAR EATON					148.55
	SUB-TOTAL					
	Replace #2 right side airbag.			1.25	135.00	168.75
SHOP RATE	SHOP RATE			1	166.14	166.14
	AIR BAG			1	3.73	3.73
	BRA 1468-8C			1	2.63	2.63
559069	1/2 X 3/8 NPT REDUCER					341.25
	SUB-TOTAL					
	Right side hood cable missing lock retaining ring.			0.25	135.00	33.75
SHOP RATE	SHOP RATE			1	1.15	1.15
	RETAINING RING					34.90
	SUB-TOTAL				14.18	14.18
SUPPLIES	MISC SUPPLIES					14.18
	SUB-TOTAL				5.00%	46.79
	GST On Sales					
				Subtotal		\$935.76
				GST		\$46.79
				Total		\$982.55

THANK YOU FOR CHOOSING EDGE.
IF YOU'RE HAPPY TELL OTHERS. IF YOU'RE NOT PLEASE TELL US.

THANK YOU FOR CHOOSING EDGE.
IF YOU'RE HAPPY TELL OTHERS. IF YOU'RE NOT PLEASE TELL US.

Bear Creek Maintenance Ltd

1-712016 Range Road 72A
 County of Grande Prairie #1, AB
 T8W 5H5, CA
 bearcr01@gmail.com
 (780) 814-2335



Invoice: 10211

Date: 7/8/2022

Bill To

Shadow Rathole Drilling LTD

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
3311	Net 30	8/7/2022	Jason		Troup, Robbyn	592

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: Truck (4 Axle) - C Inspection**Cause:** Customer request

Labor	Inspection / Truck / Truck (4 Axle) - C Inspection - 7/8/2022			\$329.00
			Subtotal	\$329.00

Complaint: 8.13. Windshield**Cause:** Drivers side windshield cracked

(Procedure)

Labor	Correction: Chassis / Chassis / Got windshield replaced - 7/6/2022			\$0.00
Parts	D/S WINDSHIELD INSTALLED	1.00000	\$204.75	\$204.75
			Subtotal	\$204.75

Complaint: 8.18. Rear-View Mirror**Cause:** Mirror, passengers side convex

(Procedure)

Labor	Correction: Chassis / Chassis / Removed mirror and cab post cover at outside, then removed inside dash parts to gain access to wiring for mirror, replaced mirror and wired it in and put all related parts back on that were removed. - 7/12/2022			\$258.64
Parts	MIRROR, CONVEX, 8" CENTRE, HEATED, SS	1.00000	\$44.875	\$44.88
Parts	MISC ELECTRICAL	1.00000	\$3.87	\$3.87
			Subtotal	\$307.39

Complaint: 1.4. Drive Shaft**Cause:** Nuts loose on yokes

(Procedure)

Item	Description	Quantity	Rate	Amount
Labor	Correction: Inspection / Truck / Tightened loose transmission and steady bearing yoke nuts. - 7/7/2022			\$61.00
Subtotal				\$61.00

Complaint: Service unit - change oil and filter, fuel filter, check/replace air filter, grease unit and check all fluid levels

Cause: Customer request

(Inspection)

Labor	Correction: Inspection / Truck / Service unit - change oil and filter, fuel filter, replaced air filters, greased unit and checked all fluid levels - 7/12/2022			\$351.36
Parts	FILTER	1.00000	\$21.0375	\$21.04
Parts	FILTER + EHC charge for each BF7766	1.00000	\$26.625	\$26.63
Parts	HIGH EFFICIENCY DUAL-FLOW LUBE SPIN-ON + EHC charge for each BD50000	1.00000	\$50.22596	\$50.23
Parts	FILTER AIR	2.00000	\$75.90	\$151.80
Parts	15W40 CK4 liter	44.00000	\$7.54803	\$332.11
Parts	TRUCK GREASE	1.00000	\$15.50	\$15.50
Subtotal				\$948.67

Complaint: Repair air conditioning on the drill

Cause: Customer request

(Inspection)

Labor	Correction: Chassis / Air Conditioning & Heating / Removed side cover off engine and replaced A/C belt, also had to remove adjustor and then clean up threads and then install adjuster again and tighten up A/C compressor, filled with freon as it was low and tested system and temp coming out of vent was 50 degrees F. - 7/12/2022			\$717.36
Parts	R134A REFRIGERANT	2.20000	\$18.1776	\$39.99
Parts	13AV1245 AUTO V-BELT	1.00000	\$29.244	\$29.24
Subtotal				\$786.59

Complaint: 2.2. Axle Attaching & Tracking Components

Cause: Torque rod bolts loose #2

(Procedure)

Labor	Correction: Chassis / Frame / Removed old bolts, installed new bolts - 7/6/2022			\$96.38
Subtotal				\$96.38

Complaint: 6.1. Required Lamps

Item	Description	Quantity	Rate	Amount
Cause: Beacon lamps - both sides				
Front bumper signal - left side				
Right side signal in headlamp assy				
Mirror lamp on right side dim				
Cab/sleeper aux lamps - bulb burnt				
(Procedure)				
Labor	Correction:			\$451.40
	Chassis / Lighting & Electrical / Cleaned up contacts for beacon lamps			
	Rewired front bumper lamp found wiring fault			
	Signal lamp assembly at head lamps were a bad ground and one faulty bulb			
	Cleaned up ground on mirror lamps			
	Replaced bulbs for aux lamps - 7/12/2022			
Parts	BULB	1.00000	\$0.88751	\$0.89
Parts	LED- 2" RD CLEARANCE- AMBER	2.00000	\$9.10	\$18.20
Parts	MISC ELECTRICAL	1.00000	\$4.98	\$4.98
Subtotal				\$475.47

Complaint: 9.5. Wheel Hub**Cause:** #1 right hubcap vent plugged

(Procedure)

Labor	Correction:			\$23.18
	Chassis / Tire & Wheels / Cleaned out breather plug. - 7/6/2022			
Subtotal				\$23.18

Complaint: 1.8. Engine Start Safety Feature**Cause:** Oil leak at turbo

(Procedure)

Labor	Correction:			\$95.16
	Engine / Exhaust / Removed fitting for oil pressure, replaced o-ring, installed and tested - 7/7/2022			
Parts	#6 FLAT FACE O-RING	1.00000	\$0.39446	\$0.39
Parts	#4 ORB O-RING	1.00000	\$0.588	\$0.59
Subtotal				\$96.14

Complaint: 3A.2. Air Supply System**Cause:** Air leak under cab

(Procedure)

Labor	Correction:			\$53.68
	Chassis / Air Brake / Tightened up fitting under the cab - 7/12/2022			
Subtotal				\$53.68

Complaint: 7.1. Wiring**Cause:** Wiring rubbing on output yoke #2 axle

Item	Description	Quantity	Rate	Amount
(Procedure)				
Labor	Correction:			\$59.78
	Chassis / Lighting & Electrical / Shortened wires that were not being used and shrink tubed off, as wires were rubbing on driveline and not being used. - 7/6/2022			
Subtotal				\$59.78

Complaint: 8.1. Hood or Engine Enclosure**Cause:** Hood mounts worn

(Procedure)

Labor	Correction:			\$373.32
	Chassis / Chassis / Replaced hood mount rubbers and adjusted hood - 7/12/2022			
Parts	LOWER HOOD BUSH KIT	1.00000	\$51.5625	\$51.56
Parts	HOOD BUSHING	4.00000	\$15.4375	\$61.75
Subtotal				\$486.63

Complaint: 9.4. Tire Inflation Pressure**Cause:** 3RI and 4RI missing valve caps

(Procedure)

Labor	Correction:			\$0.00
	Chassis / Tire & Wheels / Installed new valve caps - 7/6/2022			
Parts	VALVE CAP - METAL - HIGH HEAT	2.00000	\$0.686	\$1.37
Subtotal				\$1.37

Unit: 592 VIN: 1NPFX40XX7N889826

2007 Peterbilt 378

Chassis: 367,391 Kilometers**Engine:** 14,565 Hours

			Labor	\$2,870.26
			Parts	\$1,059.77
			Shop Supplies	\$79.99
			Pre Tax Total	\$4,010.02
			GST (5.0000% of \$4,010.02)	\$200.50
			Total	\$4,210.52
			Payments & Credits	\$0.00
			Balance Due	\$4,210.52

GST# 838850253

All parts and labour are Net 30 days. After 30 days 2% interest will be charged per month (26.824% per annum)

Warranty on parts are warranted by parts supplier.



**Shadow Rathole Drilling
LTD**

Truck (4 Axle) - C Inspection

Completed Date: 7/8/2022

Unit: 592 VIN: 1NPFX40XX7N889826

Year/Make/Model: 2007 Peterbilt 378

Chassis Kilometers: 367,391 Kilometers (7/6/2022)

Engine Hours: 14,565 Hours (7/6/2022)

Service Order: 3311

Bear Creek Maintenance Ltd

1-712016 Range Road 72A

County of Grande Prairie #1, AB T8W 5H5, CA

bearcr01@gmail.com

Inspection:

Procedure	Result	Procedure	Result	Procedure	Result
1. 1.1. Accelerator Pedal/Throttle Actuator	Satisfactory	2. 1.2. Exhaust System	Satisfactory	3. 1.3. Emission Control Systems and Devices	N/A
4. 1.4. Drive Shaft	Defective; Defect Corrected On: 7/12/2022	5. 1.5. Clutch and Clutch Pedal	Satisfactory	6. 1.6. Engine/Transmission Mount	Satisfactory
7. 1.7. Engine/Shut Down	Satisfactory	8. 1.8. Engine Start Safety Feature	Defective; Defect Corrected On: 7/12/2022	9. 1.9. Gear Position Indicator	N/A
10. 1.10. Engine or Accessory Drive Belt	Satisfactory	11. 1.11. Hybrid Electric Vehicle & Electric Vehicle Power Train System	N/A	12. 1.12. Gasoline or Diesel Fuel System	Satisfactory
13. 1.13. Pressurized or Liquefied Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*	N/A	14. A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System	N/A	15. A.2. Compressed Natural Gas (CNG) Fuel System	N/A
16. A.3. Liquefied Natural Gas (LNG) Fuel System	N/A	17. 2.1. Suspension & Frame Attachments	Satisfactory	18. 2.2. Axle Attaching & Tracking Components	Defective; Defect Corrected On: 7/12/2022
19. 2.3. Axle & Axle Assembly	Satisfactory	20. 2.4. Spring & Spring Attachment	Satisfactory	21. 2.5. Air Suspension	Satisfactory
22. 2.6. Self-Steer and Controlled-Steer Axle	N/A	23. 2.7. Shock Absorber/Strut Assembly	Satisfactory	24. 3H.1. Hydraulic System Components	N/A
25. 3H.2. Brake Pedal/Actuator	N/A	26. 3H.3. Vacuum Assist (Boost) System	N/A	27. 3H.4. Hydraulic Assist (Boost) System	N/A
28. 3H.5. Air Assist (Boost) System	N/A	29. 3H.6. Air-Over-Hydraulic Brake System	N/A	30. 3H.11. Brake System Indicator Lamps	N/A
31. 3H.12. Drum Brake System Components	N/A	32. 3H.13. Disc Brake System Components	N/A	33. 3H.14. Mechanical Parking Brake	N/A
34. 3H.15. Spring-Applied Air-Released Parking Brake	N/A	35. 3H.16. Spring-Applied Hydraulic-Released Parking Brake	N/A	36. 3H.17. Anti-Lock Brake System (ABS)	N/A
37. 3H.18. Stability Control System	N/A	38. 3H.19. Brake Performance	N/A	39. 3A.1. Air Compressor	Satisfactory

40. 3A.2. Air Supply System	Defective; Defect Corrected On: 7/12/2022	41. 3A.4. Air Tank	Satisfactory	42. 3A.5. Air Tank Check Valves	Satisfactory
43. 3A.6. Brake Pedal/Actuator	Satisfactory	44. 3A.7. Treadle Valve and Trailer Hand Valve	Satisfactory	45. 3A.8. Brake Valves & Controls	Satisfactory
46. 3A.9. Proportioning, Inversion or Modulation Valve	Satisfactory	47. 3A.10. Towing Vehicle (Tractor) Protection System	Satisfactory	48. 3A.11. Parking Brake & Emergency Application	Satisfactory
49. 3A.13. Air System Components	Satisfactory	50. 3A.14. Brake Chamber	Satisfactory	51. 3A.15. Drum Brake System Components	Satisfactory
52. 3A.16. S-Cam Drum Brake System	Satisfactory	53. 3A.17. Brake Shoe Travel (Wedge Brakes)	N/A	54. 3A.18. Disc Brake System Components	N/A
55. 3A.19. Anti-Lock Brake System (ABS)	Satisfactory	56. 3A.21. Stability Control System	N/A	57. 3A.23. Brake Performance	N/A
58. 4.1. Steering Control and Linkage	Satisfactory	59. 4.2. Power Steering System (Hydraulic and Electric)	Satisfactory	60. 4.3. Steering Operation (Active Steer Axle)	Satisfactory
61. 4.4. Kingpin	Satisfactory	62. 4.5. Self-Steer and Controlled-Steer Axle	N/A	63. 5.1. Fire Extinguisher	Satisfactory
64. 5.2. Hazard Warning Kit	Satisfactory	65. 5.3. Horn	Satisfactory	66. 5.5. Speedometer	Satisfactory
67. 5.6. Odometer	Satisfactory	68. 5.7. Windshield Wiper/Washer	Satisfactory	69. 5.8. Heater & Windshield Defroster	Satisfactory
70. 5.9. Fuel-Burning Auxiliary Heater	Satisfactory	71. 5.10. Chain/"Headache" Rack	Satisfactory	72. 5.11. Auxiliary Controls and Devices	Satisfactory
73. 5.12. Auxiliary Drive Controls	N/A	74. 6.1. Required Lamps	Defective; Defect Corrected On: 7/12/2022	75. 6.2. Reflex Reflector	Satisfactory
76. 6.3. Retro-Reflective Marking	Satisfactory	77. 6.4. Instrument Panel Lamps	Satisfactory	78. 6.5. Headlamp Aim	Satisfactory
79. 7.1. Wiring	Defective; Defect Corrected On: 7/12/2022	80. 7.2. Battery	Satisfactory	81. 7.3. Trailer Cord (output to towed vehicle)	N/A
82. 8.1. Hood or Engine Enclosure	Defective; Defect Corrected On: 7/12/2022	83. 8.2. Tilt Cab	N/A	84. 8.3. Air-Suspended Cab	Satisfactory
85. 8.4. Cab and Passenger-Vehicle Body	Satisfactory	86. 8.5. Cargo Body	Satisfactory	87. 8.6. Frame, Rails & Mounts	Satisfactory
88. 8.7. Unitized Body Elements	N/A	89. 8.8. Cab or Cargo Door	Satisfactory	90. 8.9. Cargo Tank or Vessel	N/A
91. 8.10. Body, Device or Equipment Attached or Mounted to the	Satisfactory	92. 8.11. Refrigeration/Heater Unit Fuel System (Reefer or Auxiliary Power Unit (APU))	N/A	93. 8.12. Bumper	Satisfactory
94. 8.13. Windshield	Defective; Defect Corrected On: 7/12/2022	95. 8.14. Side Windows	Satisfactory	96. 8.15. Rear Window	N/A

97. 8.16. Interior Sun Visor	Satisfactory	98. 8.17. Exterior Windshield Sun Visor	Satisfactory	99. 8.18. Rear-View Mirror	Defective; Defect Corrected On: 7/12/2022
100. 8.19. Seat	Satisfactory	101. 8.20. Seat Belt/Occupant Restraint	Satisfactory	102. 8.21. Fender/Mud Flap	Satisfactory
103. 8.24. Aerodynamic Device & Attachment	N/A	104. 9.1. Tire Tread Depth	Satisfactory	105. 9.2. Tire Tread Condition	Satisfactory
106. 9.3. Tire Sidewall & Manufacturer Markings	Satisfactory	107. 9.4. Tire Inflation Pressure	Defective; Defect Corrected On: 7/12/2022	108. 9.5. Wheel Hub	Defective; Defect Corrected On: 7/12/2022
109. 9.6. Wheel Bearing	Satisfactory	110. 9.7. Wheel/Rim (Applies to all wheel types)	Satisfactory	111. 9.8. Multi-Piece Wheel/Rim	N/A
112. 9.9. Spoke Wheel/Demountable Rim System	N/A	113. 9.10. Disc Wheel System	Satisfactory	114. 9.11. Wheel Fasteners (Nuts, Bolts and Studs)	Satisfactory
115. 10.1. Hitch Assembly, Structure & Attaching Components	N/A	116. 10.2. Secondary Attachment (Safety Chain or Cable)	N/A	117. 10.3. Pintle Hook, Pin Hitch, or Coupler Hitch	N/A
118. 10.4. Ball Type Hitch	N/A	119. 10.5. Roll-Coupling Hitch	N/A	120. 10.6. Automated Coupling Device	N/A
121. 10.7. Fifth Wheel Coupler	N/A	122. 10.8. Oscillating Fifth Wheel Coupler	N/A		

Technician: Robbyn Troup

Digital Signature: Robbyn Troup

Date: 7/8/2022

Hymark Refrigeration Ltd.

22-721022 Range Road 54
Fairmont, Alberta T8X 4G8
Canada
Tel: (780) 512-6015
ADMIN@HYMARKREFRIGERATION.CA
WWW.HYMARKREFRIGERATION.CA



INVOICE TO

Shadow Rathole Drilling Ltd.

Invoice: 013909

Date: Feb 11, 2022

Terms: Net 30. Due Mar 13, 2022.

Business No.: 772838082RT0001

QTY	UNIT	ACTIVITY	RATE	AMOUNT
		UNIT#592		
		DROVE TO LOCATION INSTALLED NEW 5KW GC HEATER ON TRUCK VERIFIED OPERATION.		
4	Hr	Labour 2 Guys @ \$165.00/Hr	165.00	660.00
1		Truck Charge	25.00	25.00
1	Each	Shop Supplies	15.00	15.00
1		5 KW GC HEATER	1,300.00	1,300.00
		Subtotal:		2,000.00
		G - GST 5%		
		GST/HST		100.00

THANK YOU FOR YOUR BUSINESS

PAYMENT TERMS:

A FINANCE CHARGE OF 2% WILL BE ADDED ON ALL BALANCES OVER 30 DAYS FROM INVOICE DATE,
A FURTHER FEE OF 2% PER MONTH WILL APPLY TO ALL INVOICES AFTER 60 DAYS FROM INVOICE DATE.

PAYMENT OPTIONS:

E-TRANSFER: ADMIN@HYMARKREFRIGERATION.CA - INCLUDE INVOICE # IN COMMENTS
CHEQUE TO ADDRESS ABOVE - INCLUDE INVOICE NUMBER IN COMMENTS
CREDIT CARD: ONLY ACCEPTED FOR BALANCES UNDER \$2000.00 - A 3% FEE WILL BE ADDED TO THE INVOICE
IF THE METHOD OF PAYMENT YOU WOULD PREFER TO USE IS NOT LISTED PLEASE GIVE US A CALL AND WE WILL DO OUR BEST TO ACCOMMODATE YOU

Total Amount	2,100.00
Amount Owing	2,100.00