

W48-1
SEP

1111543 AB LTD.
O/A BBR TRUCKING
55 BLUEBERRY DR.
WHITECOURT, AB T7S 1R4
780-778-4041
GST # 860879873 RT0001

NOTRE NUMÉRO OUR NUMBER	618741
DATE	MAR 18 / 26
COMMANDE DU CLIENT CUSTOMER'S ORDER	

VENDU À SOLD TO	PHILIP LEWIS
ADRESSE ADDRESS	CONTRACTING

LIVRÉ À SHIP TO	
ADRESSE ADDRESS	

N° D'IMP. DE TAXE TAX REG. NO.	VENDEUR SALESPERSON	FAS FOB	CONDITIONS TERMS	VIA
-----------------------------------	------------------------	------------	---------------------	-----

FACTURE - INVOICE

QUANTITÉ QUANTITY	DESCRIPTION	PREX PRICE	MONTANT AMOUNT
6 HRS	REMOVE BROKEN IDLER STUD	100 00	600 00
	REPLACE BEARINGS IN BELT IDLER		
	REPLACE BELT TENSION IDLER		
	UNIT #		
	SHIPPING	40 00	40 00
	SHOP SUPPLIES		30 00
	GST		33 50
	TOTAL		703 50

Blueline DCB37

© Blueline®, 2010

Paid e-transfer
Mar 23/2025

JBS Mechanical Inc
 Box 353
 3469 -33 Street
 Whitecourt Alberta T7S 1N5
 jbsmechanical.service@gmail.com
 GST/HST No. 828463240

Invoice



JBS Mechanical Inc.
1-780-779-6759

Invoice #	Date
44996	10/31/2025

P.O. No.	Terms
	Net 30

Invoice To

Philip Lewis Contracting

Location	Work Order #	Make/Model	Unit Number
Shop	16753	2007 WS	004

Item	Description of Item	Bin	Qty	Rate	Amount
Wheel Alignme...	Hooked up alignment machine Perform Scan, Found unit toed out 1/4"		1	300.00	300.00
Regular Time	Adjust tie rod, set to 1/8th inch toed in		0.75	140.00	105.00
Shop Supplies	8% of Base Labour		1	13.20	13.20
	VIN:5KJJALAV27PY65442 License plate:G-46295 KM:9449 Hours:23309				
Customer Signature _____		2% Interest charged on overdue invoices			

If we have had your wheels off re-tourque within 100 km's.
 Flat rate charges may be subjected to a 75% increase for siezed or aftermarket parts.
 A 25% increase in flat rate labor charge may occur due to excessive mud or snow on units.
 Parts warranty subject to manufactures approval.
 If customer does not request old parts back they will be disposed of by JBS Mechanical.
 No return on electrical components or special order parts.
UNAUTHORIZED ENGINE MODIFICATIONS OR DPF DELETES DO NOT QUALIFY FOR WARRANTY

Subtotal	\$418.20
GST/HST	\$20.91
Total	\$439.11
Payment	\$0.00
Balance Due	\$439.11

Poster 1

844167 Alberta Ltd o/a Lorcon Contracting

PO Box 718
Whitecourt, Alberta T7S 1N7
Canada

INVOICE

Invoice No.: 35877
Date: 21/04/2025
Ship Date:
Page: 1
Re: Order No.

Sold to:
Phillip Lewis Contracting

Ship to:
Phillip Lewis Contracting

Business No.: 865109185

Quantity	Unit	Description	Tax	Unit Price	Amount
1	CVIP	Tridem Lead Trailer, Load King, Unit #17A	G	285.00	285.00
1	CVIP	Tandem Pup Trailer, Load King, Unit #17B	G	250.00	250.00
1	CVIP	Tandem Truck, Westernstar, Unit#004 KMS: 16003.7 HRS:23116	G	300.00	300.00
2	Hrs	Supply shop service in order to complete CVIP on tandem axle truck, including the removal and reinstallation of tires in order to measure brakes/drums.	G	130.00	260.00
1	Each	Shop Supplies	G	13.00	13.00
		G - GST 5% GST			55.40
Shipped By: Tracking Number:				Total Amount	1,163.40
Comment:					
Sold By:					

LORCON CONTRACTING

Work Order

Company: PLC Date: April/23/25

Unit #: 004 Make/Model: Western star

Vin#: _____ Kms: 1603.7 Hrs: 23116 APR23 10:54AM

Work Done CVip Tandem truck

APR23 1:01PM

Parts Used _____

Completed by _____

email transfer sent

DJ Mechanical
Box 2586
Whitecourt, AB T7S 2A1, CA
darcy@djmechanical.net
(780) 779-7088

DJ Mechanical
(780) 779-7088

Invoice: **INV-9105**
Date: **28/11/2024**

Dec 27/2024
\$11,469.13

Bill To
Philip Lewis Contracting

P: 780 706 4389

Remit Payment To
DJ Mechanical
Box 2586
Whitecourt, AB T7S 2A1, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
SO-10126	Net 30	28/12/2024	Blaine Lewis		004

Item	Description	Quantity	Rate	Amount
Complaint: Diagnose engine pushing coolant				
Cause: Customer request				
Labor	Correction: Engine / Overhaul / Set up pressure guage on coolant resevoir. Add coolant. Start engine, pressure guage immediately climbed to 20 PSI. Shut down engine. TW - Created: 12/11/2024 Completed: 28/11/2024 - Assigned tech(s): Tyson Wiltse	1.50000	\$150.00	\$225.00
Subtotal				\$225.00

Complaint: R&R engine head

Cause: Customer request

(Inspection)

Labor	Correction: Engine / Overhaul / Remove turbo and manifold, remove valve cover, disconnect everything from head, remove rocker assembly, remove head bolts and rig up head for removal. Assist with measuring liner protrusion. AB Disassemble rocker assembly and clean AB Install new lower gasket, spacer plate and head gasket, and head, clean head bolt and torque head, AB Zip tie the VVA and injector harness up neatly. Install new valve cover gaskets. Install valve covers, found two of the threaded holes to be missing threads. - Assigned tech(s): Aidan Burns, Daniel Bisson, Korbyn Droesse, Tyson Wiltse	28.70000	\$150.00	\$4,305.00
-------	---	----------	----------	------------

Item	Description	Quantity	Rate	Amount
	So drilled them out and install a cat threaded insert. TW			
	Install injectors, rockers and VVA. Torque and perform valve set, install turbo and exhaust manifold, rebuild coolant diverter valve, install lines and hoses, install charge air piping and cold air intake, install rad brace, drain engine oil and begin to top up coolant and oil. AB			
	Test drive unit and check for leaks, coolant diverter valve found to be too loose, tighten and verify leak no longer active.			
	Top up coolant. AB - Created: 18/11/2024 Completed: 28/11/2024			
Parts	o-ring kit, injector	6.00000	\$56.579	\$339.47
Parts	spacer plate .003 undersize	1.00000	\$732.375	\$732.38
Parts	gasket kit	1.00000	\$3,284.868	\$3,284.87
Parts	hose	1.00000	\$32.175	\$32.18
Parts	SHELL ROTELLA T4 15W40 18.9L	2.00000	\$149.99	\$299.98
Parts	DELO 50/50 Coolant	24.00000	\$12.99	\$311.76
Parts	Filter AS-LU	1.00000	\$69.107	\$69.11
Parts	HEATER HOSE 5/8" HI-MILER	1.00000	\$7.92	\$7.92
Parts	thread insert	1.00000	\$64.96	\$64.96
	Subtotal			\$9,447.63
Complaint: set up and measure liner protrusion				
Cause: Customer request				
(Inspection)				
Labor	Correction:	5.00000	\$150.00	\$750.00
	Engine / Pistons / Get all tooling clean everything and set up to measure liner protrusion.			
	Measure liner protrusion following step by step through SIS procedure. KD. AB.			
	Measurements:			
	Cylinder one- 0.0035			
	Cylinder two- 0.0035			
	Cylinder three-0.0020			
	Cylinder four-0.0035			
	Cylinder five-0.0037			
	Cylinder six-0.0030			
	made decision to put in .003" thinner spacer plate - Created: 18/11/2024			
	Completed: 28/11/2024 - Assigned tech(s): Korbyn Droeese			
Parts	3/4X3 Bolt	6.00000	\$4.392	\$26.35
	Subtotal			\$776.35
	freight	1.00	\$39.00	\$39.00
	freightb	1.00	\$35.00	\$35.00

Unit: 004 VIN: 5KJJALAV27PY65442
License Plate: (Alberta) G-46295
2007 Western Star Trucks 4900
Chassis: 734,486 Kilometres

Labor	\$5,280.00
Parts	\$5,168.98
Shop Supplies	\$400.00
Pre-Charge Subtotal	\$10,848.98
freight	\$39.00
freightb	\$35.00
GST (5% of \$10,922.98)	\$546.15
Total	\$11,469.13
Payments & Credits	\$0.00
Balance Due	\$11,469.13

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice.

Customer Signature: _____

Printed Name: _____ Date: _____