

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3318	NHVAS label	26/02/2026	26/02/2026			0	2888	Internal Workshop label been ordered waiting on arrival to place on truck	\$0.00
R-3317	fire extinguisher	26/02/2026	26/02/2026			0	2887	Internal Workshop extinguisher ordered	\$0.00
R-3316	Tarp switch	26/02/2026	26/02/2026			0	2886	Internal Workshop notified mechanic	\$0.00
R-3315	tailgate	26/02/2026	26/02/2026			0	2885	Internal Workshop notified mechanic	\$0.00
R-3314	leak oil	26/02/2026	26/02/2026			0	2884	Internal Workshop notified mechanic	\$0.00
R-3312	parker lights	26/02/2026	26/02/2026			0	2883	Internal Workshop notified mechanic	\$0.00
R-3311	horn	26/02/2026	26/02/2026			0	2882	Internal Workshop notified mechanic	\$0.00
R-3310	water washer	26/02/2026	26/02/2026			0	2881	Internal Workshop notified mechanic	\$0.00
R-3308	buzzer	26/02/2026	26/02/2026			0	2880	Internal Workshop notified mechanic	\$0.00
R-3306	buzzer	26/02/2026	26/02/2026			0	2879	Internal Workshop notified mechanic	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3192	Tarp	19/02/2026	19/02/2026			0	2816		\$0.00
R-3191	windscreen	19/02/2026	19/02/2026			0	2815		\$0.00
R-3190	engine light	19/02/2026	19/02/2026			0	2814		\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3615	BRAKES	02/04/2026	27/01/2026	429,315	0	0		<p>Blue Collar Diesel Brake Shoe Replacement was carried out on all drive positions, brake shoes were assembled as per OEM procedure correct brake adjustment was carried out once all brake shoes were on and wheels were assembled and torqued to the correct specifications. Ride height valve was replaced due to excessive air exhaust when truck is running or turned off, ride height on cab was also exhaust air these were causing air tanks to Excessivly drain. Conduct a full trailer service in accordance with the attached Blue collar Diesel service sheet, ensuring all maintenance, inspection, and safety requirements are met. This includes a comprehensive assessment of the braking</p>	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	Hours Closed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
								<p>system, suspension, electrical and lighting components, tires, and overall structural integrity as outlined in the service sheet. Identify and address any issues, perform necessary adjustments or repairs, and document all findings to maintain compliance with operational and safety standards.</p>	

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3393	Transmission	09/12/2025	09/12/2025	923,996	0	0		Blue Collar Diesel Attended breakdown, inspected vehicle for shifting faults - found excessive air leak at secondary air tank. Removed and replaced valve, once valve was replaced road tested vehicle - no shifting faults occurred and air leak no longer audible. Connected Eaton software, no active faults showing - multiple inactive faults for wheel speed / spin sensors.	\$622.74 1883
R-3542	air leak	20/03/2026	22/10/2025	914,499	0	0		Internal Workshop installed new drain locks and new fitting	\$0.00
S-1922	B - 50k	08/10/2025	08/10/2025	912,994 58,429	0	0		Internal Workshop Completed "B" Service	\$0.00
R-3001	Hydraulics	16/09/2025	16/09/2025	890,628	0	0		jonnty Tightened the leaking hydraulic valve on truckhoist	\$0.00
S-1639	A - 10k	16/09/2025	16/09/2025	890,628 10,601	0	0		Internal Workshop A SERVICE	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3002	Breakdown	15/09/2025	15/09/2025	890,599	2	0		jonnty Found out the alternator belt tensioner let go. Put a secondhand tensioner in the truck tested all ok.	\$0.00

Generated at: 29/05/2026, 1:51:53 pm