

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-3572	tarp motor	23/03/2026	23/03/2026	106,263		0		Removed and replaced tarp motor and called auto electricians to look at a fuse problem that causes this.	\$0.00
R-3245	tyres	23/02/2026	23/02/2026			0	2831		\$0.00
S-1708	A - 10k	02/12/2025	02/12/2025	94,867 9,692		0			\$0.00
S-1707	A - 10k	15/10/2025	15/10/2025	85,175 3,910		0			\$0.00
S-1706	B - 50k	18/06/2025	18/06/2025	81,265 19,078		0			\$0.00
T-409	Steer	07/05/2025	07/05/2025	74,093		0		Orkhan Combe Patch RH 2nd axle steer tyre + inflate + tension	\$0.00
R-2155	Airbag	05/05/2025	05/05/2025	73,766		0		Ely Cameron Remove + replace RHF airbag with new	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
T-408	Drive	05/05/2025	05/05/2025	73,766		0		Orkhan Combe Remove + replace first axle drive tyres with new + tension Remove + replace LH middle drive tyres with new + tension	\$0.00
S-1705	A - 10k	22/04/2025	22/04/2025	71,676 9,489		0			\$0.00
T-397	Drive	22/04/2025	22/04/2025	71,676		0		Orkhan Combe Patch repair RH inner 2nd axle drive tyre + inflate + tension	\$0.00
R-2083	beacon	09/04/2025	27/03/2025	66,872	0	0		Internal Workshop Warranty work - NJL auto lec to repair issue with light. light repaired and works correctly	\$0.00
R-1992	Lights	13/03/2025	13/03/2025	62,601	0	0		Internal Workshop - Diagnose blow park light fuse. - Replace fuse + test all okay	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-1970	TYRE	12/03/2025	12/03/2025	62,581	0	0		Internal Workshop Strip and patch flat tyre tension wheel nuts	\$0.00
R-1979	bolts	11/03/2025	11/03/2025	63,482	0	0		Internal Workshop - Replace 10x m10 bolts ib tipper frames + tighten - Check all remaining bolts for tightness	\$0.00
S-1429	B - 50k	08/03/2025	08/03/2025	62,187 37,541	0	0		Internal Workshop - B Service completed - Fuel Bowl cracked. - Remove + replace fuel bowl with new,	\$0.00
R-1901	Brakes	04/03/2025	04/03/2025	61,901	0	0		Internal Workshop Increase governor pressure as directed by gilbert and roach as pressure is set low from factory Increase ABS safety valve pressure	\$0.00

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-1749	puncture	08/02/2025	08/02/2025	57,207	0	0		Internal Workshop plug tyre L/H inner plug tyre R/H Outer	\$0.00
R-1622	seat belt	22/01/2025	22/01/2025	543,303	0	0	823, 837, 853		\$0.00
S-1012	A - 10k	15/01/2025	15/01/2025	54,154 29,508	0	0		Internal Workshop A service complete.	\$0.00
S-966	A - 10k	15/01/2025	15/01/2025	54,154 29,508		0		Ely Cameron A service Completed.	\$0.00

Generated at: 29/05/2026, 1:40:54 pm