NorthView Service Ltd.
Box 70
Benito, MB R0L 0C0, CA
billing@northviewservice.ca
(204) 539-2382

Invoice: 8460

Date: 13/9/2024

Bill To
Larry Terhorst

P: 204-734-4814

Remit Payment To
Mailing Address
Box 70
Benito, MB R0L 0C0, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
6843	COD	13/9/2024	Larry Terhorst		Popoff, Larry	2006 Freightliner

Item	Description	Quantity	Rate	Amount
Complaint: Coolant leak-Radiator				
Cause: customer request				
Labor	**Correction:** Engine / Cooling / Pressure tested and the rad is leaking. Removed and replaced rad and bottom rad mount. Some bolts seized due to rust	8.28000	$142.00	$1,175.76
Parts	Radiator-New - 613RA032	1.00000	$1,359.575	$1,359.58
Parts	Insulator - 28847-1	1.00000	$95.7299	$95.73
Parts	Constant Torque Clamp 3" SS Band and Screw - WUR549.0300	3.00000	$18.12	$54.36
Parts	Nemco 50/50 Red Premixed HD Coolant 205L - 5147-205	8.00000	$4.70458	$37.64
Parts	Freight for part delivery - NVS-FREIGHT	1.00000	$123.613	$123.61
			Subtotal	$2,846.68
Complaint: Air Conditioner Service (r134a)				
Cause: Customer request				
Labor	**Correction:** Chassis / Air Conditioning & Heating / Performed Vacuum, Leak Test-passed- Filled System to Specifications	0.84500	$142.00	$119.99
Parts	R134A Refridgerant, Freon, per pound - R134A	3.50000	$48.95	$171.33
			Subtotal	$291.32
	Noticed an air leak behind the dash when the brakes applied	1.00	$0.00	$0.00

Unit: 2006 Freightliner (Blue Tandem) **VIN:** 1FUJA6CVX6LV27085
License Plate: (MB) GMY 316
2006 Freightliner Columbia 120
Chassis: 1,137,476 Kilometers

Labor	$1,295.75
Parts	$1,842.25
Materials Used	$84.22
Pre-Charge Subtotal	$3,222.22
Noticed an air leak behind the dash when the brakes applied	$0.00
GST (5% of $3,222.22)	$161.11
PST (7% of $3,222.22)	$225.56
Total	$3,608.89
Payments & Credits	$3,608.89
Balance Due	$0.00

Payment Information

Date Created	Date Applied	Payment #	Method	Reference #	Amount
13/9/2024	13/9/2024	100203795	MasterCard	06584z	$3,608.89

GST: 703802918RT0001

Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that NorthView Service Ltd. makes no warranties of any kind unless expressed in writing. I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that NorthView Service Ltd. is not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. NorthView Service Ltd. is not responsible for damages from freezing due to lack of antifreeze. All wheels that have been removed MUST BE RETORQUED AT OR BEFORE 100KM.

PAY INVOICE (https://link.clover.com/urlshortener/hWr9mX)