CRESTVIEW
CHRYSLER DODGE JEEP RAM

601 Albert St Regina SK CA S4R 2P4 www.crestviewchrysler.ca
+1(306) 525 - 5411

Customer Pay Invoice
$8,238.61

RO# : [redacted] Tag# : [redacted]
Check-In: Wed Nov 13, 2024 I 8:38 AM

[redacted]

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2019 Ram 2500
3C6UR5TL2*KG598415*
132,555 Km In / 132,565 Km Out
In Service: 2019-07-15

Service Advisor
Kevin Brooks
84

1.	MPI	MULTIPOINT INSPECTION	Customer Pay	$0.00
	1.multipoint inspection			
	MPI -MULTIPOINT INSPECTION		Labor	$0.00
	1. mpi			
2.	ELEDIAG	Power running boards inop	Customer Pay	$0.00
	1.see case 10			
	ELEDIAG -Report on electrical concern		Labor	$0.00
	1. see case 10			
3.	ELEDIAG	Report on service park assist message coming on	Customer Pay	$0.00
	1.see case 11			
	ELEDIAG -Report on electrical concern		Labor	$0.00
	1. see case 11			
4.	MISCTRM	lower front air dam broken	Customer Pay	$0.00
	1.see case 8			
	MISCTRM -Inspect/Diage trim concern		Labor	$0.00
	1. see case 8			
5.	LAMP	rear liscense plate lamp out	Customer Pay	$0.00
	1.see case 11			

© Tekion Corp 2024

LAMP -Replace bulb — Labor $0.00

1. see case 11

6. DSLDIAG — perform service light on — Customer Pay $0.00

1.see case 7

DSLDIAG -DEISEL CONCERN — Labor $0.00

1. see case 7

7. EGR — Perform 6.7l EGR service and replace ccv filter — Customer Pay $1,974.40

Tags: Recommendation

1.perform service light on

EGR -Perform 6.7l EGR service — Labor $1,277.50

1. performed egr service. replaced ccv filter. cleaned all egr components and installed new gaskets. topped up coolant.

Parts $696.90

68005184AA - GASKET EGR VALVE 2 - $48.30
68005256AA - GASKET THROTTLE BODY 1 - $26.05
68005465AA - GASKET NONE 2 - $25.80
68026986AA - GASKET NONE 1 - $48.00
68086261AA - O RING NONE 3 - $124.65
68175339AC - ANTIFREEZ COOLANT 2 - $80.30
68206031AA - GASKET EGR COOLER 1 - $64.80
68002433AC - BREATHER CRANKCASE 1 - $279.00

8. MISCTRIM — replace front lower air dam — Customer Pay $371.00

Tags: Recommendation

1.lower air dam broken

MISCTRIM -Inspect/Diage body concern — Labor $195.00

1. replaced front bumper lower air dam as it was broken

Parts $176.00

68384301AB - AIR DAM FRONT 1 - $176.00

Part Note: stk

9. **MISCTRM** tighten shifter — Customer Pay $97.50

Tags: Recommendation

1.shifter very loose

MISCTRM -Inspect/Diage trim concern — Labor $97.50

1. tightened shifter as it was very loose. verified proper operation

10. **MISCTRIM** replace drivers side running board motor — Customer Pay $1,192.50

Tags: Recommendation

1.diagnose on power board inop. found motor to be very weak

MISCTRIM -Inspect/Diage body concern — Labor $292.50

1. replaced drivers side running board motor as it was weak and binding. tested. proper operation at this time.

Parts $900.00

68461641AB - MOTOR POWER RUNNING BOARD 1 - $900.00 SOR

Part Note: reddeer

11. **ELEDIAG** replace rear park assist wiring harness. also replace 4 rear park assist sensors and valances — Customer Pay $1,577.65

Tags: Recommendation

1.multiple broken connectors for park assist and license plate assemblies. found stones to have beat up wiring harness and park assist sensors

ELEDIAG -Report on electrical concern — Labor $780.00

1. replaced rear park assist/license plate light wiring harness assembly. replaced right and left lower valances as the sensor mounting brackets were broken off. installed 4 new park assist sensors. tested. proper operation at this time.

Parts $797.65

68451135AA - VALANCE REAR 1 - $73.60

Part Note: stk

6MK25TZZAA - SENSOR PARK ASSIST 4 - $244.80

52112732AE - WIRING REAR BUMPER 1 - $411.00 SOR

68451134AA - VALANCE REAR 1 - $68.25 SOR

Part Note: reddeer

© Tekion Corp 2024

12. MISCTRIM replace lower grille insert thats broken — Customer Pay $917.16

Tags: Recommendation

1.grill insert broken

MISCTRIM -Inspect/Diage body concern — Labor $767.56

1. removed front bumper. replaced front lower grille insert as it was broken

Parts — $149.60

68384294AA - GRILLE LOWER 1 - $149.60

13. FBRAKE REPLACE FRONT BRAKE PADS AND ROTORS — Customer Pay $1,014.52

1.Front brake pads at 1/32 and fail Sask safety

FBRAKE -REPLACE FRONT BRAKE PADS — Labor $429.00

1. Replaced front brake pads and rotors, serviced brake calipers

Parts — $585.52

1BP00268AB - PAD KIT FRONT DISC BRAKE 1 - $90.40

780736R - Rotor 2 - $495.12 SOR

14. ALIGN WHEEL ALIGNMENT — Customer Pay $179.95

1.Alignment out of spec and failed Sask safety inspection

ALIGN -WHEEL ALIGNMENT — Labor $179.95

1. Performed 2 Wheel Alignment

15. MISCTRM repair liscence plate bracket — Customer Pay $97.50

1.left rear license plate bracket broken

MISCTRM -Inspect/Diage trim concern — Labor $97.50

1. resecured left rear license plate bracket assembly. tested. proper operation

Additional Fees	Sale Amount
ENV - Enviro fees	$0.00
TTF - Tire fees	$0.00
FUEL - Fuel charges	$0.00

© Tekion Corp 2024

CRESTVIEW
CHRYSLER DODGE JEEP RAM

Customer Pay Invoice
$8,238.61

RO# : [redacted]

Labor	$4,116.51
Parts	$3,305.67
Sublet Labor	$0.00
Sublet Parts	$0.00
Fees	$0.00
Discounts	$0.00
Tax - GST	$371.10
Tax - PST	$445.33
Deductible	$0.00
Invoice Total	**$8,238.61**

RO External Notes: [redacted]

SA Notes

[redacted]

Mode Of Communication	Previous Estimate	Revised Estimate	Date and Time
Call	$719.83	$8,057.87	Tue Nov 19, 2024 at 12:03 PM

Note
app

TERMS: Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order. Any warranties on the product sold hereby are those made by the manufacturer.

DISCLAIMER OF WARRANTIES: The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Mopar parts warrants 24 months on defects and workmanship for parts & labour on dealer installed retail date of purchase or the installation date by installer. Any limitation contained herein does not apply where prohibited by law.

X
Customer Signature

Date

G/HST Reg # 719412207RT0001

© Tekion Corp 2024