Summary Details				
Vehicle Body Type	Excavator	**No. of Cylinders:**		
Make:	Hyundai	**Engine No. :**	22297253	
Model:	R210lC-9 (21-TONNE)	**VIN /Chassis No.**	HHKHZ601CJ0002867	
Colour:	Yellow	**Mass:**	21000 (21 Tonne)	
Registration No.	**NA** (33760C)	**GVM or GTM/GCM:**	21000	
Year of Manufacture:	Old Limited Use Only	**Rows of Wheels / No. of Tyres:**		
Insurance:	NA	**Configuration:**		
Driver:	License Class LE	**Risk Assessment:**	Excavator Hyundai_(21T)	

Vehicle Maintenance Log

Date of Invoice	Mileage / Odometer	Repairs / Maintenance Details Work Performed	Performed by	Cost	Docket / Invoice #
05/31/2021		500hr service	Porter Equipment Australia Pty Ltd.	$ 1,360.22	INV0049621
01/04/2022		Service 3000hr	Shauns mobile mechanical	$ 1,257.65	INV5670
04/30/2022	3230Hrs	Supply and fit auger	Porter Equipment Australia Pty Ltd.	$ 23,319.65	INV0054680
06/14/2022	3350HRS	Replace broken hydrolic hose	Truck and bus	$ 127.26	INV00027631
06/14/2022		Top up hydrolic oil	MB Oil and batteries	$ 300.15	INV5929
06/14/2022		Quick relese fitting for auger	Truck and bus	$ 328.26	INV00027615
09/11/2024	Hour Meter: 5545	Full Service and Repairs. Change out oils, filters, valve set etc as necessary. Replace belts as necessary	Bringing Better Business Pty. Ltd.	$ 4,840.00	INV00009812
10/23/2024		Seal Assy-Floating / Master Pin / Start Key.	Porter Equipment Australia Pty Ltd.	$ 1,309.57	IN0201048

Vehicle Maintenance Log

Date of Invoice	Mileage / Odometer	Repairs / Maintenance Details Work Performed	Performed by	Cost	Docket / Invoice #
10/30/2024		Dust Seal, Bolt Track, Nut Track, Master Pin.	Porter Equipment Australia Pty Ltd.	$ 140.60	IN0201362
11/12/2024		Final Drive Repairs - Consumables including Oils - Contractor Tech Hydraulic Press - Labour including travel for parts returned for Credit.	Bringing Better Business Pty. Ltd.	$ 3,535.40	INV00009923
02/20/2025		Replace front windscreen	Porter Equipment Australia Pty Ltd.	$ 1,153.68	INV0078062
04/07/2025		Fit UHF	Mike Hepple	$ 851.40	INV08226
07/01/2025		Removed and replaced 2 perished hoses from engine to oil filter housing. Tested machine fully functional.	PIRTEK RFG Holdings Pty Ltd	$ 1,328.77	EL-T00046029
11/24/2025		Remove and replace the faulty alternator. Remove and replace the leaking fuel water separator. Remove and replace the faulty fuel level sender.	Porter Equipment Australia Pty Ltd.	$ 1,884.54	INV0085534
06/12/2026		21T Excavator / Site Move From Mt. Baiker to Virginia	Tom Dimitropoulos Pty Ltd t/as TOM'S Low Loaders & Transport	$ 690.80	INV-IV157553
06/26/2026		20T Excavator / Site move From: 405 Martins Road, Green Fieds SA. To: 1213 Old Port Wakefield Road, Virginia.	Tom Dimitropoulos Pty Ltd t/as TOM'S Low Loaders & Transport	$ 715.00	INV-IV158060
08/05/2026		21T Excavator / Site Move From Mt. Baiker to Virginia	Tom Dimitropoulos Pty Ltd t/as TOM'S Low Loaders & Transport	$ 660.00	INV-IV159682
10/29/2026		21T Excavator / Site Move From Port Wakefield Road, Virginia To Lot 2 Jobson Road, Bolivar SA	Tom Dimitropoulos Pty Ltd t/as TOM'S Low Loaders & Transport	$ 771.10	INV-163489

Vehicle Maintenance Log

Date of Invoice	Mileage / Odometer	Repairs / Maintenance Details Work Performed	Performed by	Cost	Docket / Invoice #


Notes

Notes

Notes