Repair Order Detail

RO:	RO07-0329066	**Status:**	CLOSED	**Repair Class:**	SCHEDULED
Shop:	SAL	SALINA SHOP		**Repair Site:**	FACILITY
Unit:	B1351	PETERBILT 579 MX13 14X+ 10SPM FLEX AIR BENDIX CAS (auction)		**Opened:**	6/9/2023
Domicile:	SAL	**Make:**	PTRBL	**Completed:**	6/12/2023
Cost Cntr:	901	**Model:**	579	**Odometer:**	215,822
License:	Z079213	**Year:**	2022		
VIN:	1XPBDP9X1ND796388	**In Service:**	9/20/2021		

Section: 1	**Priority:** 2	**Complaint:**	NEEDS INSPEC	**Rep Reason:**	DRIVERREPORT
Component:	023-001	**Cmp Descrip:**	Control Assembly - Mechanical, Clutch		
War Type:	EXTENDED	**Unit War:**	None		
Comments:	{\rtf1\ansi\deff0{\fonttbl{\f0\fnil MS Sans Serif;}} {\colortbl ;\red0\green0\blue0;} \viewkind4\uc1\pard\cf1\lang1033\f0\fs16				

Comment

Date	Comment Text
6/9/2023	pulled the pump and pto off tranny removed tranny and replaced clutch it was slipping installed tranny and put pto and
6/9/2023	pump back on filled with oil put everything back together [PAG300]

Labor

Date	Mechanic	Description	Hours	Rate	Total
6/9/2023	PAG300	Control Assembly - Mechanical, Clutc, WORN OUT, REPLACED NEW	8.22	85.00	698.70

Part

Date	Part ID	Description	After Mkt	Qty	Unit Price	Total
6/9/2023	308925-25	Clutch Assembly, 2050 Torque lb-ft		1.00	1064.28	1,064.28
6/12/2023	SS1	Shop Supplies		1.00	18.30	18.30
6/12/2023	75W90 SYN TRANS	Oil - Manual Transmission (new p/n for 50W)		5.00	37.57	187.85

Task Details

© 2015-2026 Trimble Inc. All rights reserved. Unauthorized duplication, copying, or use prohibited.

Repair Order Detail


Section: 2	**Priority:** 5	**Complaint:**	LEAKING	**Rep Reason:**	INSPECTION
Component:	056-001	**Cmp Descrip:**	Power Take Off		
War Type:	NO WARRANTY	**Unit War:**	None		
Comments:	{\rtf1\ansi\deff0{\fonttbl{\f0\fnil\fcharset0 MS Sans Serif;}{\f1\fnil MS Sans Serif;}} {\colortbl ;\red0\green0\blue0;}				

Part

Date	Part ID	Description	After Mkt		Qty	Unit Price	Total
6/9/2023	J4001-539	Ball Switch - N/O PTO indicator 2-wire CPI, pre-wired with plug			1.00	79.39	79.39

Task Details

Totals Repair Order RO07-0329066	
US$ - United States Dollars	
Total Parts Issued:	8.00
Total Labor Hours:	8.22
Total Part Charges:	1,349.82
Total Labor Charges:	698.70
Total Tax Charges:	0.00
Total Fee Charges:	0.00
Total Service Charges:	0.00
Repair Total:	**2,048.52**



© 2015-2026 Trimble Inc. All rights reserved. Unauthorized duplication, copying, or use prohibited.