NorthView Service Ltd.
Box 70
Benito, MB R0L 0C0, CA
billing@northviewservice.ca
(204) 539-2382

NORTHVIEW SERVICE

Invoice: 7568

Date: 26/3/2024

Bill To
Larry Terhorst

P: 204-734-4814

Remit Payment To
Mailing Address
Box 70
Benito, MB R0L 0C0, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
6269	COD	26/3/2024	Larry Terhorst		Popoff, Larry	1995 Freightliner

Item	Description	Quantity	Rate	Amount
Complaint: Replace the clutch assembly				
Cause: customer request				
Labor	**Correction:** Chassis / Chassis / Lifted box and put in box support. Drained oil out of transmission. Removed all 4 air tanks to allow clearance to remove the transmission. Labeled the lines. All the mounting bolts for tanks were seized and required heat for removal. Driveshaft bolts had to be cut as they were seized and rounded off as someone tried to remove in the past. Had to heat bolts to remove the pump off the PTO. Re-surfaced flywheel and installed a new pilot bearing Installed clutch/pressure plate assembly Installed a clutch install kit into the transmission Installed a new rear crank seal Filled trans. with new oil and made necessary adjustments	20.28000	$142.00	$2,879.76
Parts	Mobil Synthetic 50 Transmission Oil, 18.9L - Mobil 122207	18.00000	$14.76311	$265.74
Parts	Rear crankshaft seal kit - PAI36062	1.00000	$115.70	$115.70
Parts	Flywheel Refaced - PERL	1.00000	$448.784	$448.78
Parts	Clutch Install Input Kit - FUL K2468	1.00000	$458.419	$458.42
Parts	Clutch Assembly - FLTC10839174	1.00000	$1,298.23	$1,298.23
			Subtotal	$5,466.63

Unit: 1995 Freightliner (Tandem) **VIN:** 2FUY3MDB0SA676784
License Plate: DXD 502 mb
1995 Freightliner FLD112
Chassis: 214,009 Kilometers

Labor	$2,879.76
Parts	$2,586.87
Materials Used	$151.19
Pre-Charge Subtotal	$5,617.82
GST (5% of $5,617.82)	$280.89
PST (7% of $5,617.82)	$393.25
Total	$6,291.96
Payments & Credits	$6,291.96
Balance Due	$0.00

Payment Information

Date	Payment #	Method	Reference #	Amount
27/3/2024	5884130	MasterCard	07429z	$6,291.96

GST: 703802918RT0001

Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that NorthView Service Ltd. makes no warranties of any kind unless expressed in writing. I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that NorthView Service Ltd. is not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. NorthView Service Ltd. is not responsible for damages from freezing due to lack of antifreeze. All wheels that have been removed MUST BE RETORQUED AT OR BEFORE 100KM.

PAY INVOICE (https://link.clover.com/urlshortener/hWr9mX)