CRESTVIEW
CHRYSLER DODGE JEEP RAM

601 Albert St Regina SK CA S4R 2P4 www.crestviewchrysler.ca
+1(306) 525 - 5411

Customer Pay Invoice
$3,480.89

RO# : [redacted] Tag# : [redacted]
Check-In: Thu Nov 28, 2024 | 7:04 AM

Customer
[redacted]

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2019 Ram 2500 Diesel (6.7L)
3C6UR5TL2*KG598415*
132,968 Km In / 132,975 Km Out
In Service: 2019-07-15

Service Advisor
Kevin Brooks
84

1.	MISCTRM	Body Systems/Trim Concern (Non-Electrical) [Replace rear bumper]	Customer Pay	$0.00

1.see section 4

MISCTRM -Inspect/Diage trim concern — Labor $0.00

1. section 4 for bumper replacement

2.	ELEDIAG	Electrical/Non PCM Flashes Concern [Pass side power running board inop]	Customer Pay	$0.00

1.section 5 for running board motor

ELEDIAG -Report on electrical concern — Labor $0.00

1. section 5 for running board motor

3.	MPI	Multi-point inspection	Internal Pay	$0.00

1.multipoint

MPI -MULTIPOINT INSPECTION — Labor $0.00

1. mpi

4.	MISCTRM	replace rear bumper	Customer Pay	$1,732.50

Tags: Recommendation

1.dented

MISCTRM -Inspect/Diage trim concern — Labor $585.00

1. replaced rear bumper as it was dented

© Tekion Corp 2024

Parts $1,147.50

68576316AA - BUMPER STEP 1 - $1,147.50 SOR

5. **ELEDIAG** **replace pass side power running board motot** **Customer Pay** **$637.50**

Tags: Recommendation

1.defective

ELEDIAG -Report on electrical concern Labor $292.50

1. replaced right power running board motor. tested. proper operation

Parts $345.00

68461640AB - MOTOR POWER RUNNING BOARD 1 - $345.00

6. **BATTERY** **report on weak batteries** **Customer Pay** **$0.00**

1.batteries to be weak

BATTERY -Inspect/Diag battery concern Labor $0.00

1. tested batteries. batteries weak. see section 9

7. **ELEDIAG** **report on weak heater fan** **Customer Pay** **$0.00**

1.see section 8

ELEDIAG -Report on electrical concern Labor $0.00

1. see section 8

8. **CABIN** **REPLACE CABIN AIR FILTER** **Customer Pay** **$99.95**

Tags: Recommendation

1.cabin filter put in sideways and all crumpled

CABIN -REPLACE CABIN AIR FILTER Labor $59.95

1. replaced cabin air filter. installed bg frigi fresh anti bacterial spray

Parts $40.00

BG7083 - A/c Fresh 1 - $11.12

68535623AA - FILTER CABIN AIR 1 - $28.88

9. **QBATTERY** replace both batteries — Customer Pay $661.00

Tags: Recommendation

1.both batteries weak

QBATTERY -Test and replace battery — Labor $195.00

1. replaced both batteries as they were weak.

Parts — $466.00

BA94R765AB - BATTERY STORAGE 2 - $466.00

Additional Fees	Sale Amount
ENV - Enviro fees	$0.00
FUEL - Fuel charges	$0.00
TTF - Tire fees	$0.00
HAZ - HAZARDOUS MATERIAL	$5.00

Labor	$1,132.45
Parts	$1,998.50
Sublet Labor	$0.00
Sublet Parts	$0.00
Fees	$5.00
Discounts	$0.00
Tax - GST	$156.79
Tax - PST	$188.15
Deductible	$0.00
Invoice Total	**$3,480.89**

RO External Notes:[redacted]

SA Notes

[redacted]

Mode Of Communication	Previous Estimate	Revised Estimate	Date and Time
Call	$3,288.37	$4,024.79	Mon Dec 2, 2024 at 08:24 AM

Note
app

© Tekion Corp 2024

CRESTVIEW
CHRYSLER DODGE JEEP RAM

Customer Pay Invoice
$3,480.89
RO# : [redacted]

TERMS: Indebtedness is hereby acknowledged for the "Total Charges" being all or the balance owing to repairs, parts & accessories described in this work order. Any warranties on the product sold hereby are those made by the manufacturer.

DISCLAIMER OF WARRANTIES: The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Mopar parts warrants 24 months on defects and workmanship for parts & labour on dealer installed retail date of purchase or the installation date by installer. Any limitation contained herein does not apply where prohibited by law.

X
Customer Signature

Date

G/HST Reg # 719412207RT0001

© Tekion Corp 2024