EquipmentName	Workshop	Description	CompletionComments	DateDone	DistanceDone	Division	Rego	Supplier	EquipmentType
1060	Wodonga - Workshop	trailer ABS light stays on		07/08/2026	809816	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Trailer ABS Light Stays On		07/08/2026	809816	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	ABS SOCKET DAMAGED. NEEDS REPLACING.		07/08/2026	809816	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	trailer abs light staying on changed trailers from 563/570 to 666/667		07/08/2026	809816	LHB	XV02YL	Wodonga Workshop	P/MOVER
			Brakes are good						
			Hub seal fine						
1060	Wodonga - Workshop	Left side steer bub oil level needs checking	Suspected leaking out of cap wiped done- mointor	18/07/2026	786780	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Wiper blades need replacing		18/07/2026	786780	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Tyres\TP1+2		11/07/2026	783701	LHB	XV02YL	BORDER BANDAG PTY LTD	P/MOVER
			Labour- Mobile- Breakdown						
			Travelled to Coonabarabran NSW						
			Inspected clutch issue						
			Found splinned linkage on cross shaft						
			missing						
			Checked around town for missing part						
			Discussed with shops in dubbo for						
			availability						
			Found similar part in Coona						
		DrivLine\CLUTCH	Fitted to truck						
1060	Wodonga - Workshop	WW134662	Clutch workine fin	30/06/2026	776416	LHB	XV02YL	WARREGO TRANSPORT REPAIRS	P/MOVER
			repaired slack adjuster repaired damaged clutch shaft						
1060	Wodonga - Workshop	INSPECT CLUTCH FREE-TRAVEL ADJUSTER AND REPLACE IF REQUIRED	SMc	27/06/2026	774690	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	L/H steer hub leaking oil.	Hub cab was weeoine not hub seal. cleaned hub cap. replaced rubber bune in hub cap.	20/06/2026	768671	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	After Treat Light On Dash	Pluaeed comouter in to truck & checked for fault codes. found fault code for NOX sensor active. lacked over cabin removed batterv box. checked after treatment fuse in batterv box. all aood. checked loom had no rub marks. checked for aower at NOX sensor. had aood aower & earth at oluz. refitted batty box cover & lc	20/06/2026	768671	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Coolabah Bunk Cooler Not Working	Bunk cooler was repaired by Tim @ Mechtrical	20/06/2026	768671	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Check Over Coolabah Bunk Cooler	Bunk cooler was repaired by Tim @ Mechtrical	20/06/2026	768671	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	VehService\AS A Service		13/06/2026	767679	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	REPLACE LH STEER HUB SEAL FOUND IN SERVICE		13/06/2026	767679	LHB	XV02YL	Wodonga Workshop	P/MOVER
			replaced side rear view mirror						
1060	Wodonga - Workshop	Body\MIRRORS	completed by KR SMc	30/05/2026	755543	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Clutch Needs Adjusting	completed by SMc KR	30/05/2026	755543	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Steering\WHEEL BRGS		11/05/2026	746817	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Front drive brakes getting low		11/05/2026	746817	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	VehService\BS B Service		09/05/2026	750550	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Insp\ANN INSP To Complete R/W within 12 months	completed by TP,JS	03/05/2026	743606	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	VehService\AS A Service	completed by TP,JS	03/05/2026	743606	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Exhaust Clamp On Muffler Broken	Jacked Over Cabin, Removed Old Exhaust Clamp, Fitted New Exhaust Clamp, Started & Tested, All Good, Lowered Cabin, Put Truck Back Into Service.	21/04/2026	733962	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	VehService\AS A Service	Completed by TP	11/04/2026	728191	LHB	XV02YL	Wodonga Workshop	P/MOVER
			* Customer contacted dealership technician with information regarding breakdown						
			* Customer advised of alternator issue						
			* Technician travelled to breakdown location, Corowa, NSW						
			* Jacked cab over for access						
			* Checked electrical routing & confirmed alternator not charging						
			* Removed components for access						
			* Removed alternator & pulley off						
			* Installed original pulley to replacement alternator						
			* installed replacement alternator						
			* Aligned & tensioned all components to specification						
			* Check alternator output & confirmed charging						
			* Test, confirmed & quality checked repair						
			* Lowered cab & returned truck to service						
1060	Wodonga - Workshop	Alternator light coming ON.	* Technician secured dealership & returned home	17/03/2026	739584	LHB	XV02YL	Wodonga Workshop	P/MOVER
			Check the operation of the MT Data unit. Found the unit was tracking						
			correctly but the dvr was not working. Plugged a monitor into the dvr						
			unit to check the cameras, found the unit was not seeing a hhd.						
			Remove and replaced the hhd and formatted it. Test, the dvr is now						
			working correctly. Plugged into the guardian unit to check for any faults.						
			Could not connect to the guardian unit, reset the unit and set it up correctly.						
			Found the ffc was not working. Unplugged and plugged a test ffc in, the						
			ffc is now working. Remove the required panels and replaced the ffc correctly.						
			Test, the ffc is working and the guardian unit has no faults. Put the						
		DrCabElect\GPS							
1060	Wodonga - Workshop	MT DATA & GUARDIAN ISSUES	truck back together	17/03/2026	717191	LHB	XV02YL	ARKON AUTO ELECTRICAL	P/MOVER
1060	Wodonga - Workshop	Lh cab ram leak at fittings/supply and return hoses		17/03/2026	715523	LHB	XV02YL	Wodonga Workshop	P/MOVER
		Horton very low							
		Dip stick wheep							
1060	Wodonga - Workshop		Tightened clamp	17/03/2026	715523	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Lh cab ram leaking fittings and supply/return hose		17/03/2026	715523	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	VehService\AS A Service		17/03/2026	715523	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Rubber boot around gear stick ,is split and is letting hot air.	Previously completed	17/03/2026	715523	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Horton low	Add 4hrs time-mitch	16/03/2026	715523	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	front and rear diff leaks	SMc completed	03/03/2026	709884	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	diffs leaking nhvr said fix it	SMc completed	03/03/2026	709884	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	coolabah not working	SMc completed	03/03/2026	709884	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	coolabah not working	SMc completed	03/03/2026	709884	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Rear diff housing leakine	SMc completed	03/03/2026	709884	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Power dividor movement	SMc completed	03/03/2026	709884	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Crown & Pinion need to be adjusted.	SMc completed	03/03/2026	709884	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Electrical Fault [Brake light's on when using Exhaust brake] They stay on.	SMc	03/03/2026	709884	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	steer tyres	been replaced SMc	03/03/2026	709884	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Bunk cooler Not working.	SMc	03/03/2026	709884	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	drive tyres	SMc	03/03/2026	709884	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	service	Brakes FL 7D ML 5D RL5D FR 7D MR 5D RR5D	24/02/2026	707987	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	VehService\AS A Service	All other faults previously listed	24/02/2026	707987	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Slight Play in jaws		24/02/2026	707987	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Tyres\TP9+10	tyre fitters to fit the new tyres fitted to 1036 to 1060 - SHAUN	11/02/2026	706323	LHB	XV02YL	BORDER BANDAG PTY LTD	P/MOVER
1060	Wodonga - Workshop	Tyres\TP5+6	tyre fitters to fit the new tyres fitted to 1036 to 1060 - SHAUN	11/02/2026	706323	LHB	XV02YL	BORDER BANDAG PTY LTD	P/MOVER
1060	Wodonga - Workshop	Tyres\TP11+12	tyre fitters to fit the new tyres fitted to 1036 to 1060 - SHAUN	11/02/2026	706323	LHB	XV02YL	BORDER BANDAG PTY LTD	P/MOVER
1060	Wodonga - Workshop	Tyres\TP7+8	tyre fitters to fit the new tyres fitted to 1036 to 1060 - SHAUN	11/02/2026	706323	LHB	XV02YL	BORDER BANDAG PTY LTD	P/MOVER
1060	Wodonga - Workshop	Tyres\RUN OUT POS 5-6. 7-8. 9-10 + 11-12		06/02/2026	701060	LHB	XV02YL	BORDER BANDAG PTY LTD	P/MOVER
1060	Wodonga - Workshop	Tyres\TP1+2		06/02/2026	701060	LHB	XV02YL	BORDER BANDAG PTY LTD	P/MOVER
1060	Wodonga - Workshop	VehService\AS A Service		06/02/2026	697658	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	check steer tyres		06/02/2026	697658	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Batteries need to be changed or replaced.	Loade	06/02/2026	697658	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	check turntable movement		06/02/2026	697658	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Front shocker's need to be taken off checked & replaced if no good.	Shocks are serviceable	06/02/2026	697658	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	DriCabRep\WINDSCREEN Left and Right side needs replacing	PO #WW093883	27/01/2026	690756	LHB	XV02YL	AUTOTEK AUSTRALIA	P/MOVER
1060	Wodonga - Workshop	seat leaking air	fix air leak	13/01/2026	682069	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	VehService\AS A Service		01/01/2026	688873	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Uni need's replacing.	ok ,minimal play	05/12/2025	670265	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Tail shaft unis need to be reolace	minimal play	05/12/2025	670265	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	DASH AIR VENTS FLOPPING AROUND.	completed	05/12/2025	670265	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	REAR IN DRIVER'S SEAT	completed	05/12/2025	670265	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	VehService\AS A Service	completed	05/12/2025	670265	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	VehService\BS B Service	completed	05/12/2025	670265	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Manifold gaskets leaking	inspected ok	05/12/2025	670265	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Diff pinion orings	weeping	05/12/2025	670265	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Debug Radiator & Intercooler		03/11/2025	648533	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Lining on rear wall and passenger side ceilling in bunk falling down		31/10/2025	648000	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	HEAD LINING LHS ABOVE BUNK FALLING DOWN		31/10/2025	648000	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Hard To Get Out Of Gear When Stopped Check Clutch Adjustment		31/10/2025	648000	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Loose Grill		31/10/2025	648000	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	A Service		31/10/2025	648000	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	SOMETHING GOING ON WITH CLUTCH. HARD TO GET OUT OF GEAR WHEN STOPPE	ADJUSTED CLUTCH. MONITOR.	31/10/2025	648000	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	VehService\AS A Service		31/10/2025	648000	LHB	XV02YL	Wodonga Workshop	P/MOVER
		A Service							
1060	Wodonga - Workshop	Serviced @ 649.149 Klms		13/10/2025	639131	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	VehService\AS A Service		12/09/2025	624068	LHB	XV02YL	Wodonga Workshop	P/MOVER
		Replace Leaking Brake Booster L/H Rear Axle.							
1060	Wodonga - Workshop	(Warrego Transport Repairs P/O: WW096857)		09/09/2025	622334	LHB	XV02YL	WARREGO TRANSPORT REPAIRS	P/MOVER
1060	Wodonga - Workshop	Tyres\TP11+12	CAPS REPLACED - 2 NEW TYRES	14/08/2025	611300	LHB	XV02YL	BORDER BANDAG PTY LTD	P/MOVER
1060	Wodonga - Workshop	Tyres\RUN OUT POS 9		14/08/2025	611300	LHB	XV02YL	BORDER BANDAG PTY LTD	P/MOVER
1060	Wodonga - Workshop	VehService\BS		13/08/2025	608544	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	LH cab ram hoses leaking		21/07/2025	604357	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Coolant filter leaking		21/07/2025	604357	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	VehService\AS A Service		21/07/2025	604357	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Tyres\TP11+12		30/06/2025	587019	LHB	XV02YL	BORDER BANDAG PTY LTD	P/MOVER
1060	Wodonga - Workshop	Tyres\TP9+10		30/06/2025	587019	LHB	XV02YL	BORDER BANDAG PTY LTD	P/MOVER
1060	Wodonga - Workshop	VehService\AS A Service		30/06/2025	587019	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	SERVICE		30/06/2025	587019	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	Tyres\TP06 CALL OUT		16/06/2025	587019	LHB	XV02YL	BORDER BANDAG PTY LTD	P/MOVER

		Engine\CATTUNEUP .The following engine tune up as per manufacturer specification included: . * Removed & check air intake for restrictions * Check radiator for oil indicating compression or oil leaks * Removed rocker cover to access internal components * Check top end components * Adjust valve clearance to specification * Set all parameters to specification * Install rocker cover & components complete * Check & adjust all belts Pressure test CAC * Test, confirm & quality check engine operation							
1060	Wodonga - Workshop	* Comolete ECM download DriCabRep\HOUSEKEEP REPORTS BUNK WALL LINING & ROOF LINING FALLING OFF . * Inspected & confirmed fault * Refit wall & roof lining * Secured all in position			05/06/2025	577773	LHB	XV02YL	PACCAR PARTS FLEET SERVICES P/MOVER
1060	Wodonga - Workshop	* All ok			05/06/2025	577773	LHB	XV02YL	PACCAR PARTS FLEET SERVICES P/MOVER
1060	Wodonga - Workshop	VehService\CS C Service			05/06/2025	577773	LHB	XV02YL	PACCAR PARTS FLEET SERVICES P/MOVER
1060	Wodonga - Workshop	C SERVICE			05/06/2025	577773	LHB	XV02YL	PACCAR PARTS FLEET SERVICES P/MOVER
1060	Wodonga - Workshop	DriveLine\WHEEL BRGS Found wheel bearings worn - Replaced			05/06/2025	577773	LHB	XV02YL	PACCAR PARTS FLEET SERVICES P/MOVER
		Elect\TRL LIGHTS Callout - trailer lights Callout after hours. Travel to vehicle & return. Check trailer lights not working after suzi lead got pulled out & Greenfreight mechanic had repaired. Check fuses & relays, check wiring diagnose all powers to trailer plug but no earth. Diagnose & repair earth wire in trailer plug insulation not stripped before putting wire into trailer plug. Re-assemble &							
1060	Wodonga - Workshop	test			29/05/2025	577129	LHB	XV02YL	ARKON AUTO ELECTRICAL P/MOVER
1060	Wodonga - Workshop	REPAIRED ELECTRICAL LEAD.			29/05/2025	580036	LHB	XV02YL	Wodonga Workshop P/MOVER
		Replace Steer Tyres, Due To R/H Steer Starting To Delaminate.							
1060	Wodonga - Workshop	(Border Bandag P/O: WW094431)			22/05/2025	577129	LHB	XV02YL	BRIDGESTONE AUSTRALIA P/L P/MOVER
1060	Wodonga - Workshop	STEERING WHEEL COVER FRAYING.			01/05/2025	566034	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	VehService\AS A Service			01/05/2025	566034	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	Insp\ANN INSP To Complete R/W within 12 months			01/05/2025	566034	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	Door seals leaking			08/04/2025	555245	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	gear box temp not working	Driver monitor		08/04/2025	555245	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	C SERVICE DUE AT 420,000			08/04/2025	555245	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	FLUID LEAKING FROM LINES ON CABIN LIFTING RAM.			08/04/2025	555245	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	LHS WINDOW WILL NOT GO UP AND DOWN.			08/04/2025	555245	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	FRONT DIFF LEAKING.			08/04/2025	555245	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonaa - Workshop	VehService\AS A Service			08/04/2025	555245	LHB	XV02YL	Wodonaa Workshop P/MOVER
1060	Wodonaa - Workshop	REIRED REVERSE ALARM.			01/04/2025	544995	LHB	XV02YL	Wodonaa Workshop P/MOVER
1060	Wodonga - Workshop	VehService\AS A Service			26/03/2025	544995	LHB	XV02YL	Wodonga Workshop P/MOVER
			Topped up engine oil by 2 litres.						
			Moved volt gauge terminal to a powered post on the alternator.						
1060	Wodonga - Workshop	VehService\AS A Service	Reolaced blown dash aauge alobes.		06/03/2025	537912	LHB	XV02YL	Wodonaa Workshop P/MOVER
1060	Wodonga - Workshop	Vault gauge not working	Fitted terminal to powered post on alternator		06/03/2025	537912	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	SOME GLOBES NOT WORKING IN DASH GAUGES.	Replaced fuel and trans gauge globes		06/03/2025	537912	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	VOLTMETER NOT WORKING.	Fitted terminal to powered post		06/03/2025	537912	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	GEARBOX PRESSURE LIGHT FLASHING ON/OFF.	Previously completed		06/03/2025	537912	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	lights out on fuel, engine, oil temp gauge	Replaced blown globes		06/03/2025	537912	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	alternator light on and off randomly	Previously completed		06/03/2025	537912	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	ALTERNATOR LIGHT FLASHING ON/OFF.	Alternator previously replaced		06/03/2025	537912	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	VehService\AS	REPLACED TRANSMISSION PRESSURE SWITCH. TOPPED UP TRANSMISSION- 7L.		19/02/2025	530996	LHB	XV02YL	Wodonga Workshop P/MOVER
1060	Wodonga - Workshop	Replace Steer Tyres. (Hunter Regional Tyres P/O: WW092140)			12/02/2025	517652	LHB	XV02YL	BEAUREPAIRES P/MOVER
1060	Wodonga - Workshop	INSPECTED REPORTED OIL LEAKS. FOUND NO SIGN OF OIL LEAKING BUT FOUND OIL			09/02/2025	528194	LHB	XV02YL	Wodonga Workshop P/MOVER
		- INSPECT VEHICLE FOR REPORTED CHARGING FAULT AFTER REQUIRING JUMPSTART, FOUND STARTER MOTOR EARTH WIRES NOT CONNECTED CAUSING DAMAGE TO EARTH POST, FIT TEMPORARY NUT TO SECURE WIRES, RECOMMEND RENEWAL OF STARTER MOTOR. - NOTE: CUMMINS WODONGA ARRIVED UNANNOUNCED AT 3PM TO RENEW STARTER UNDER WARRANTY, (RTCM FINISH AT 4PM), SUPPLIED SHED FLOOR & HOISTS TO ASSIST WITH RENEWAL, CUMMINS COMPLETED JOB AT 5.30PM.							
1060	Wodonga - Workshop				04/02/2025	768976	LHB	XV02YL	Wodonga Workshop P/MOVER
			The following breakdown repair for Greenfreight Logging Pty Ltd, to a K200 Kenworth Truck, vin#6F5000000MA471029, registration#XV02YL & number fleet number#1060 included: . * Customer contacted dealership regarding breakdown * Customer advised of oil pressure light &strop engine light on * Technician sourced additional parts * Travelled to breakdown location, Wangaratta, Vic * Check electrical routing * Connected diagnostic tooling * Oil pressure fault code evident * Removed/replaced oil pressure sensor * Started truck & warning light went out * Returned truck to service						
1060	Wodonga - Workshop	Check Engine Fault Codes, Repair Faults. (TCTC P/O: WW091715)	* Technician returned home		01/02/2025	511575	LHB	XV02YL	TWIN CITY TRUCK CENTRE - OLD P/MOVER
		B Service							
1060	Wodonga - Workshop	Serviced @ 515,036 Klms			19/01/2025	512209	LHB	XV02YL	Wodonaa Workshop P/MOVER
		Engine Pressurizing Cooling System, Head Gasket. (Cummins Wodonga Warranty) (Parts Supplied By TCTC P/O: WW091718)							
1060	Wodonga - Workshop	Engine Replaced @ 515,036 Klms	Engine block replaced due to metal to soft for counter bore repair, Head cylinder replaced due to burnt valves, Turbo Charger replaced, Clutch replaced & Install kit fitted.		16/01/2025	690756	LHB	XV02YL	CUMMINS SOUTH PACIFIC P/L P/MOVER
1060	Wodonga - Workshop	Replace Turbo. (Cummins Wodonga P/O: WW091271)	Turbo Replaced By Cummins Wodonga		16/01/2025	690756	LHB	XV02YL	CUMMINS SOUTH PACIFIC P/L P/MOVER
		A Service.							
1060	Wodonga - Workshop	Serviced @ 505979 Klms.			10/12/2024	505979	LHB	XV02YL	Wodonga Workshop P/MOVER
		Engine\ALT BREAKDOWN REPAIR The following breakdown repair for Greenfreight Logging Pty Ltd, to a K200 Kenworth Truck, vin#6F5000000MA471029, registration#XV02YL & number fleet number#1060 included: . * Customer contacted dealership regarding breakdown * Customer advised of alternator light comes on dash & volt gauge reads 10v * Customer advised he would meet technician at dealership * Technician travelled to dealership at 255 Mckoy St, Wodonga * Unlocked dealership & run truck into inspection bay * Inspected to diagnose repair * Started truck & checked volt gauge - confirmed only reading 10v * Jacked cab over for access * Checked battery voltage - 12.5v * Check wiring, connections & components - no failure evident * Start truck again & check alternator charging - confirmed 13.9v * Follow wiring diagnostics * Located new fuse link area had broken from a few places though * Disconnect wiring * Removed/replaced fuse link * Connected wiring up again, test & confirmed repair * Returned truck to service							
1060	Wodonga - Workshop	* Technician secured dealership & returned home			27/11/2024	488257	LHB	XV02YL	PACCAR PARTS FLEET SERVICES P/MOVER
1060	Wodonaa - Workshop	Tyres\TP5+6			18/10/2024	466459	LHB	XV02YL	BEAUREPAIRES P/MOVER
1060	Wodonaa - Workshop	Tyres\TP9+10			18/10/2024	466459	LHB	XV02YL	BEAUREPAIRES P/MOVER
1060	Wodonaa - Workshop	Tyres\TP3+4			18/10/2024	466459	LHB	XV02YL	BEAUREPAIRES P/MOVER
1060	Wodonaa - Workshop	Tyres\TP7+8			18/10/2024	466459	LHB	XV02YL	BEAUREPAIRES P/MOVER
		Engine Tune.							
1060	Wodonga - Workshop	(Cummins Wodonaa P/O: WW089259)			12/10/2024	512209	LHB	XV02YL	CUMMINS SOUTH PACIFIC P/L P/MOVER
1060	Wodonaa - Workshop	VehService\AS			19/09/2024	454856	LHB	XV02YL	Wodonaa Workshop P/MOVER
1060	Wodonga - Workshop	Truck Won't Start. (Elite Diesel's P/O: WW088806)			19/09/2024	454856	LHB	XV02YL	ELITE DIESEL REPAIRS P/MOVER
1060	Wodonga - Workshop	Check Alternator Charge Rate Replace If Required. (Gilbert & Roach Newcastle P/O			11/09/2024	512209	LHB	XV02YL	PACCAR PARTS FLEET SERVICES P/MOVER
1060	Wodonga - Workshop	VehService\AS			03/09/2024	454856	LHB	XV02YL	Wodonga Workshop P/MOVER

			* Carried out brake test - unable to fault * Inspected steer brake components * Found RH steer brakes sitting incorrectly in drum * Ballast steer axle & removed RH wheel end equipment * Inspected & found incorrect brake shoes fit * Also found due to incorrect shoes fit, damage caused to brake drum * Removed & replaced brake shoes with correct shoes * Replaced brake drum * Refit all wheel end equipment * Aligned & tensioned all to specifications * Inspected LH brake components * Found slack adjuster faulty * Removed & replaced slack adjuster * Tensioned all components							
1060	Wodonga - Workshop	Truck Darting Off To The Right Under Braking. (TCTC P/O: WW088472)	* Test operations - All ok, fault no longer present. * Test & confirmed fault * Inspected all components * Found linkage bolt in chassis front right of engine fallen out * Installed replacement bolt & tensioned * Adjusted clutch	29/08/2024	441834	LHB	XV02YL	TWIN CITY TRUCK CENTRE - OLD	P/MOVER	
1060	Wodonga - Workshop	Driver Lost Clutch Pedal, Clutch Linkage. (TCTC P/O: WW088472)	* Test operations - All ok, fault no longer present.	29/08/2024	441834	LHB	XV02YL	TWIN CITY TRUCK CENTRE - OLD	P/MOVER	
1060	Wodonga - Workshop	VehService\AS		10/08/2024	432216	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Check Volt Gauge Fuse At Alternator	Blown fuse at alternator replaced and upgraded	10/08/2024	432216	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Tyres\TP1+2		02/08/2024	424134	LHB	XV02YL	BEAUREPAIRES	P/MOVER	
1060	Wodonga - Workshop	TRUCK PULLING TO THE RIGHT UNDER BRAKES.		17/07/2024	417779	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	VehService\AS		17/07/2024	417779	LHB	XV02YL	Wodonga Workshop	P/MOVER	
		OIL LEAK: FOUND POWER STEERING LEAK AT RESERVOIR. REFITTED TOP SEAL CORRECTLY.								
1060	Wodonga - Workshop	TESTED.OK.		02/07/2024	419687	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	VehService\AS		18/06/2024	404402	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	SERVICE.		18/06/2024	404402	LHB	XV02YL	Wodonga Workshop	P/MOVER	
			414421 ks							
1060	Wodonga - Workshop	C Service		18/06/2024	414421	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A SERVICE DUE.		18/06/2024	404402	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	LIGHT OUT IN ENGINE OIL PRESSURE GAUGE. VehService\BS		18/06/2024	404402	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Serviced @ 414421 Klms		18/06/2024	404408	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	VehService\AS		23/05/2024	391451	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	CHECKED TESTED AND REP[LACED BATTERIES. STARTED AND CHECKED CHARGE SY!		01/05/2024	393170	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		12/04/2024	389298	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	one of the pulleys on the front of the engine is making a very loud squeking noice t		12/04/2024	389298	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	RHS STEER AXLE SPRING APPEARS TO HAVE SAGGED.	TCTC	12/04/2024	389298	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	CANNOT CALIBRATE DRIVE WEIGHT GAUGE.		12/04/2024	389298	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job NOX sensor. Customer reports Nox sensor is faulty. Inspected and found blocked injector and pump. Plugged in ecm using cummins quick serve found multiple codes for Nox & and adblue, follow trouble shooting steps found the adblue injector was blocked as well as the pump. Clean adblue system, replace adblue sender O Ring & filter, clear codes, test		12/04/2024	389298	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	drive, codes now clear. Cannot claim under warranty. DURING EOWI, LOCATED CRACKED FAN BELT .		19/03/2024		LHB	XV02YL	Albury Workshop	P/MOVER	
1060	Wodonga - Workshop	* Removed/replaced fan belt as required		19/03/2024		LHB	XV02YL	Albury Workshop	P/MOVER	
1060	Wodonga - Workshop	B Service As Per Attached Checklist Left windscreen cracked		16/03/2024	375859	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	albury auto screens PO WW084829		16/03/2024	375859	LHB	XV02YL	Wodonga Workshop	P/MOVER	
			flushed all lines and injector, check flow rate - all good.							
1060	Wodonga - Workshop	after treat light coming on	Checked wirine at NOX sensor & Volataae all aood	16/03/2024	375859	LHB	XV02YL	Woodonea Workshop	P/MOVER	
1060	Wodonga - Workshop	A service		16/03/2024	375859	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	RHS STEER AXLE SPRING APPEARS TO HAVE SAGGED.		16/03/2024	375859	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	CANNOT CALIBRATE DRIVE WEIGHT GAUGE. CANNOT CALIBRATE DRIVE AXLE WEIGHT GAUGE.		16/03/2024	375859	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	PARTS ORDERED.		16/03/2024	375859	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Take download at first service		16/03/2024	375859	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		16/03/2024	375859	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A SERVICE.		29/02/2024	366001	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		29/02/2024	366001	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		29/02/2024	366001	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Tyre Position 1 + 2		26/02/2024		LHB	XV02YL	Albury Workshop	P/MOVER	
1060	Wodonga - Workshop	REPLACED CRACKED LH WINDSCREEN.		03/02/2024	351891	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		03/02/2024	351891	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	CANNOT CALIBRATE DRIVE AXLE WEIGHT GAUGE.		03/02/2024	351891	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	RESEAL FRONT DIFF.		03/02/2024	351891	LHB	XV02YL	Woodonea Workshop	P/MOVER	
1060	Wodonga - Workshop	Take download at first service		03/02/2024	351891	LHB	XV02YL	Woodonea Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		03/02/2024	351891	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Perform laser wheel alignment		18/01/2024		LHB	XV02YL	Albury Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		20/12/2023	338401	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	RESEAL FRONT DIFF.		20/12/2023	338401	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	OVERDUE FOR A SERVICE.		20/12/2023	338401	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		20/12/2023	338401	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		07/12/2023	328306	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	BOTH STEER AXLE HUBS LEAKING OIL.		07/12/2023	328306	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		07/12/2023	328306	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		29/11/2023	409910	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonea - Workshop	A Service As Per Attached Checklist		29/11/2023	409910	LHB	XV02YL	Woodonea Workshop	P/MOVER	
1060	Wodonea - Workshop	Tightened Both Steer Hub Cap Bolts & Topped Up Hub Oils		28/11/2023		LHB	XV02YL	Woodonea Workshop	P/MOVER	
1060	Wodonea - Workshop	CLUTCH PEADL BEARING PROBLEM.	TCTC	18/11/2023	318296	LHB	XV02YL	Woodonea Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		18/11/2023	318296	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		18/11/2023	318296	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Tyre Position 1 + 2		07/11/2023		LHB	XV02YL	Albury Workshop	P/MOVER	
1060	Wodonga - Workshop	B Service As Per Attached Checklist		25/10/2023	304154	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job Check Cooling System Pressurising (Cummins Laverton)		25/10/2023	304154	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Purchase Order Number: WW081766		18/10/2023	409910	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist	TIGHTENED LH STEER HUB CAP.	17/10/2023	299429	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		17/10/2023	299429	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist	TIGHTENED EXHAUST STACK.	19/09/2023	28352	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		19/09/2023	28352	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		01/09/2023	273722	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	CHECK FUEL ECONOMY (SEEMS TO BE USING A BIT MORE)		01/09/2023	273722	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Take download at first service		01/09/2023	273722	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonea - Workshop	Check And Test Alternator		01/09/2023	273722	LHB	XV02YL	Woodonea Workshop	P/MOVER	
1060	Wodonea - Workshop	Record Check Results As Attached To This Job		01/09/2023	273722	LHB	XV02YL	Woodonea Workshop	P/MOVER	
1060	Wodonga - Workshop	1-10		01/09/2023		LHB	XV02YL	Albury Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		15/08/2023	262714	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	ADJUST CLUTCH.		15/08/2023	262714	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Adjust Clutch		15/08/2023	262714	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job Torn Suzzie Leads (Elite Diesel)		15/08/2023	262714	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Purchase Order Number: WWO80175		09/08/2023	409910	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		27/07/2023	409910	LHB	XV02YL	Woodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		27/07/2023	409910	LHB	XV02YL	Woodonga Workshop	P/MOVER	
			- Raise and support axle - Remove wheel, hub and oil soaked shoes. - Clean and inspect bearings, ok. - Fit new shoes and refit hub with new seal. - Refit wheel and adjust bearings. - Lower axle and tension all components.							
1060	Albury - Workshop	EPLACE FAILED LH STEER HUB SEAL.	- Too uo hub oil. - Drain small amount of oil from both diffs and inspect for debris, none found. - Inspect magnetic plugs for debris, all ok. - Inspect input and output shaft for play, all ok. - No evidence of failure found.	18/07/2023	237073	LHB	XV02YL	Albury Workshoo	P/MOVER	
1060	Albury - Workshop	CUSTOMER REPORTS FRONT DIFF OIL SAMPLE CAME BACK WITH HIGH IRON INDICA	- Take new oil sample and recommend monitor.	18/07/2023	237073	LHB	XV02YL	Albury Workshop	P/MOVER	
1060	Albury - Workshop	ENGINE TUNE UP.		18/07/2023	237073	LHB	XV02YL	Albury Workshop	P/MOVER	
			- Check electrical routing - Check wiring looms, switches, contacts & components - Check & load test batteries - Batteries below specification - Removed/replaced batteries							
		Check And Test Batteries	- Adjusted, aligned & installed terminals - Re check electrical routings							
1060	Albury - Workshop	VEHICLE SLOW TO CRANK	Test, confirm & quality check repair	18/07/2023	237073	LHB	XV02YL	Albury Workshop	P/MOVER	

			CARRIED OUT ENGINE TUNE AND CHECK INTERNAL COMPONENTS IN TOP OF ENGINE AS REQUIRED .The following engine tune up as per manufacturer specification included: . - Removed rocker cover to access internal components - Check top end components - Adjust valve clearance to specification - Set all parameters to specification - Install rocker cover & components complete - Test, confirm & quality check engine operation							
1060	Albury - Workshop	Tune Engine Repair Maxi Brake Air Leak (G&S Diesel)	- Complete ECM download	18/07/2023	237073	LHB	XV02YL	Albury Workshop	P/MOVER	
1060	Wodonga - Workshop	Purchase Order Number: WW079518		11/07/2023	409910	LHB	XV02YL	Wodonga Workshop	P/MOVER	
		C Service As Per Attached Checklist								
1060	Wodonga - Workshop	Carried out A, B & C Truck service as per Greenfreight service sheet schedule	REMAINDER OF C INCLUDING ENGINE TUNE NOT CARRIED OUT AS VEHICLE NEEDED TO RETURN TO SERVICE*	20/06/2023	237073	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Tune Engine		20/06/2023	237073	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Adjust Clutch		20/06/2023	237073	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	CHECK FUEL ECONOMY (SEEMS TO BE USING A BIT MORE)		20/06/2023	237073	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Check And Test Alternator		20/06/2023	237073	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Check And Test Batteries		20/06/2023	237073	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Take download at first service		20/06/2023	237073	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		20/06/2023	237073	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		07/06/2023	230934	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Check And Test Alternator		07/06/2023	230934	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Check And Test Batteries		07/06/2023	230934	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		07/06/2023	230934	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		23/05/2023	221924	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		23/05/2023	221924	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Tyre Position 9 + 10		16/05/2023		LHB	XV02YL	Albury Workshop	P/MOVER	
1060	Wodonga - Workshop	Tyre Position 7 + 8		16/05/2023		LHB	XV02YL	Albury Workshop	P/MOVER	
1060	Wodonga - Workshop	Tyre Position 5 + 6		16/05/2023		LHB	XV02YL	Albury Workshop	P/MOVER	
1060	Wodonga - Workshop	Tyre Position 3 + 4		16/05/2023		LHB	XV02YL	Albury Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		05/05/2023	211043	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	BUNK A/C STILL NOT WORKING.	CONNECTED POWER AND EARTH CABLES UP FOR DC TO DC CHARGER TO POWER UP COOLABAH. TESTED.	05/05/2023	211043	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		05/05/2023	211043	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Tyre Position 1 + 2		22/04/2023		LHB	XV02YL	Albury Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		06/04/2023	196490	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		06/04/2023	196490	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		04/04/2023	194607	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		04/04/2023	194607	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	IGNORE		04/04/2023		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	ALTERNATOR LIGHT ON DASH FLICKERS ON AND OFF.		04/04/2023		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	BUNK A/C / ALTERNATOR PROBLEM STILL NOT RESOLVED. REPLACE CRACKED LH WINDSCREEN.		04/04/2023		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	GREENFREIGHT TO ARRANGE REPLACE CRACKED LH WINDSCREEN. Fitted at TCTC by Autotek.		04/04/2023		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	PO# WW077617		03/04/2023	409910	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	REPLACE CRACKED LH WINDSCREEN.		16/03/2023	183707	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	B Service As Per Attached Checklist		16/03/2023	183707	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job alternator light staying on		16/03/2023	183707	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	ainslie rd somerton melbourne	oaccar assitt	06/03/2023	408848	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		03/03/2023	177440	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Replaced Faulty Waste Gate Actuator		03/03/2023	177440	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		03/03/2023	177440	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Replaced LH Spotter Mirror		21/02/2023		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist	ADDED 4L ENGINE OIL.	09/02/2023	163055	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		09/02/2023	163055	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist	REATTACHED STEERING WHEEL TILT CABLE.	20/01/2023	151035	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		20/01/2023	151035	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	ADJUSTABLE STEERING STARTING TO SEIZE UP.	ADJUSTED AND LUBED CABLE AND STRUT.	29/12/2022	142979	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	FIX CAB AIRCON (REFIT BATTERY)	REPAIRED AT HTT.	29/12/2022	142979	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Central locking doesn't work properly	RESET MODULE. NO FAULT FOUND.	29/12/2022	142979	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		16/12/2022	137242	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		16/12/2022	137242	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Tyre Position 1 + 2		25/11/2022		LHB	XV02YL	Albury Workshop	P/MOVER	
1060	Wodonga - Workshop	B Service As Per Attached Checklist		23/11/2022	123908	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		23/11/2022	123908	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	B Service As Per Attached Checklist		09/11/2022	112991	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Adjust Clutch		09/11/2022	112991	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		09/11/2022	112991	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		18/10/2022	954462	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job Suzi Leads pulled off Elite Diesel To Attend		18/10/2022	954462	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	PO# WW074491		07/10/2022	409710	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		07/10/2022	87503	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		07/10/2022	87503	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Wheel alignment (Pulls badly to the left)		26/09/2022	408997	LHB	XV02YL	Wodonga Workshop	P/MOVER	
			Truck sent to Hume Truck Technics							
1060	Wodonga - Workshop	Bunk A/C not working.	Refer Job # 391810	26/09/2022	408997	LHB	XV02YL	Wodonga Workshop	P/MOVER	
			Truck sent to Hume Truck Technics							
1060	Wodonga - Workshop	Wheel Alignment required	Refer Job # 391811	26/09/2022	408997	LHB	XV02YL	Wodonga Workshop	P/MOVER	
			Truck sent to Hume Truck Technics							
1060	Wodonga - Workshop	BUNK AIRCON NOT WORKING.	Refer Job # 391810	26/09/2022	408997	LHB	XV02YL	Wodonga Workshop	P/MOVER	
			Truck sent to Hume Truck Technics							
1060	Wodonga - Workshop	TRUCK NEEDS WHEEL ALIGNMENT.	Refer Job # 391811	26/09/2022	408997	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	WHEEL ALIGNMENT.	Truck sent to Hume Truck Technics	26/09/2022	408997	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Jump start Coolibah (Refer Dean Salmon)	Truck sent to Hume Truck Technics	26/09/2022	408997	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		16/09/2022	72963	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		16/09/2022	72963	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Tyre rotation and balance		08/09/2022		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	B Service As Per Attached Checklist	Engine Oil Sample SIF # 42627878	02/09/2022	62371	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		02/09/2022	62371	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist		19/08/2022	51450	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		19/08/2022	51450	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A Service As Per Attached Checklist	ADJUSTED CLUTCH.	05/08/2022	40638	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Record Check Results As Attached To This Job		05/08/2022	40638	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	adjust clutch		27/07/2022		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	A service		22/07/2022	29456	LHB	XV02YL	Wodonga Workshop	P/MOVER	
			Faulty Alternator.							
		Truck will not start	New Alternator fitted and batteries replaced.							
1060	Wodonga - Workshop	PACCAR Assist called to attend.	All covered under warranty.	08/07/2022		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	CHECK ENGINE LIGHT ON.	CODE FOR LOW POWER. CHECKED ALTERNATOR OUTPUT. 13.82V. CHECKED OUTPUT AT BATTERIES. 12.8V. TCTC TO INVESTIGATE FURTHER.	07/07/2022	18233	LHB	XV02YL	Wodonga Workshop	P/MOVER	
			* Removed/replaced engine filter & oil, specification used in parts section below. * Check all engine operation & components * Removed/replaced transmission oil filter * Check all hydraulic lines fitting & level lubricant levels to specification * Removed/replaced power steering filter & gasket * Removed/replaced differential oil, specification used in parts section below. * Removed/replaced fuel filter * Check cooling system & pressure test * Check all belts, idler pulleys, fan, shrouds & adjust to specification * Check all electrical routing, wiring looms, switches, sensors & components * Check all wheel equipment & steering components * Check all braking & adjust to specification * Check clutching & adjust to specification * Check all suspension components * Check all internal cabin operation, components & adjust to specification * Check all external cabin components & adjust to specification * Check windscreen washers, wipers, refill & test operation * Lubricate, adjust relevant components as required * Re torque all fitting & fixtures * Wash vehicle complete							
1060	Wodonga - Workshop	First service	* Road test, confirm & quality check	07/07/2022	14125	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	move LH mirror		23/06/2022		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Measure truck and trailers and move turntable back one hole.		17/06/2022		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	supoiv and fit fire extinauisher		16/06/2022	500	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Take download at first service		04/06/2022	821	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Carrv out vehicle Pre Deliverv		04/06/2022	821	LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Modifv drive guards to suit 275 size tyres Supply and install new low profile turntable Supply part 6621290038 G36 grease Top 50mm 200kNB Assembly to suit G36		27/05/2022		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	series		27/05/2022		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	TCTC SUPPLY CLEANING PRDUCTS , FIRST AID KIT, FIRE EXTINGUISHER		12/05/2022		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Tyre Position 9 + 10		06/05/2022		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Tyre Position 7 + 8		06/05/2022		LHB	XV02YL	Wodonga Workshop	P/MOVER	
1060	Wodonga - Workshop	Tyre Position 5 + 6		06/05/2022		LHB	XV02YL	Wodonga Workshop	P/MOVER	

1060	Wodonga - Workshop	Tyre Position 3 + 4	06/05/2022	LHB	XV02YL	Wodonga Workshop	P/MOVER
1060	Wodonga - Workshop	change 10tyres to suit work	06/05/2022	LHB	XV02YL	Wodonga Workshop	P/MOVER