EquipmentName	Description	CompletionComments	DateDone	DistanceDone	Division	Rego	Supplier	EquipmentType
1029	VehService\CS C Service		07/08/2026	1316059	HCU	XV318Z	G & S DIESEL SERVICE	P/MOVER
		CARRY OUT REPAIR AS REQUIRED CUT OFF OLD BOLTS FOR TANK CROSS OVER FIT NEW BOLTS & TIGHTEN						
1029	Body\DAMAGE	TOP UP ENGINE OI	17/07/2026	1145432	HCU	XV318Z	G & S DIESEL SERVICE	P/MOVER
1029	Engine\OIL LEAK		17/07/2026	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
		R&R AIR SUZI COILS & FITTINGS CHECK ENGINE OIL & TYRE PRESSURE						
1029	Elect\SUZI COIL	G & S DIESEL Last time we did steers on this truck We left off a 0 on the speedo. On the invoice it read 121102. I spoke with shaun and got his speedo reading from that time and it should of read 1211020.	22/06/2026	1145432	HCU	XV318Z	G & S DIESEL SERVICE	P/MOVER
1029	Tyres\TP1+2	2X TURNTABLE FOOT BUSHES REPLACE TURNTABLE FOOT BUSHES REPLACE 3 MUDGUARDS ADJUST 2ND AXLE R/H SIDE WHEEL BEARINGS REPLACE 2ND AXLE L/H SIDE HUB SEAL REMOVE 3RD AXLE L/H SIDE HUB & REPLACE ROTOR CHECK CALIPER REPLACE HUB SEAL RE-INSTALL HUB & ALL ATTACHMENTS REPLACE 3RD AXLE BRAKES REPLACE NUMBER PLATE LIGHTS	19/06/2026	1145432	HCU	XV318Z	BORDER BANDAG PTY LTD	P/MOVER
1029	Chassis\FIFTH WHEE	BRAKE TEST 12X BRACKET GUARDS 3X RED GUARDS REPLACE TURNTABLE FOOT BUSHES REPLACE 3 MUDGUARDS ADJUST 2ND AXLE R/H SIDE WHEEL BEARINGS REPLACE 2ND AXLE L/H SIDE HUB SEAL REMOVE 3RD AXLE L/H SIDE HUB & REPLACE ROTOR CHECK CALIPER REPLACE HUB SEAL RE-INSTALL HUB & ALL ATTACHMENTS REPLACE 3RD AXLE BRAKES REPLACE NUMBER PLATE LIGHTS	11/06/2026	1145432	HCU	XV318Z	G & S DIESEL SERVICE	P/MOVER
1029	Body\MUDGUARDS	BRAKE TEST 1X ROTOR 1X BRAKE PAD SET REPLACE TURNTABLE FOOT BUSHES REPLACE 3 MUDGUARDS ADJUST 2ND AXLE R/H SIDE WHEEL BEARINGS REPLACE 2ND AXLE L/H SIDE HUB SEAL REMOVE 3RD AXLE L/H SIDE HUB & REPLACE ROTOR CHECK CALIPER REPLACE HUB SEAL RE-INSTALL HUB & ALL ATTACHMENTS REPLACE 3RD AXLE BRAKES REPLACE NUMBER PLATE LIGHTS BRAKE TEST	11/06/2026	1145432	HCU	XV318Z	G & S DIESEL SERVICE	P/MOVER
1029	Brakes\BRK ROTOR		11/06/2026	1145432	HCU	XV318Z	G & S DIESEL SERVICE	P/MOVER
		R&R DOOR LATCH R&R NEW STRIKER						
1029	DriCabRep\DOOR LOCK	ADJUST DOOR HINGE	02/06/2026	1145432	HCU	XV318Z	G & S DIESEL SERVICE	P/MOVER
1029	DriCabRep\SEAT	R&R SEAT BELT FLEET #1029 INSPECT/ DIAGNOSE EXCESS OIL IN R/H SIDE AXLE RIM JACK UP & REMOVE TYRES/ INSPECT (SWEATING AROUND WHEEL SPEED RING, BRAKE ROTOR WARPED & BRAKE PADS GETTING LOW) REMOVE HUB & BRAKE ASSEMBLY SPLIT ROTOR FROM HUB R&R INNER BEARING & CONE R&R HUB SEALS & WHEEL SPEED SENSORING FIT HUB & FIT BRAKE ASSY W/ NEW PADS R&R PADS ON L/H SIDE 2ND AXLE ADJUST WHEEL BEARING ADJUST BRAKES	02/06/2026	1145432	HCU	XV318Z	G & S DIESEL SERVICE	P/MOVER
1029	Brakes\BRK ROTOR	BRAKE TEST - OKAY	15/05/2026	1145432	HCU	XV318Z	G & S DIESEL SERVICE	P/MOVER
1029	Engine\START MOTR	REPLACE STARTER MOTOR	01/04/2026	1145432	HCU	XV318Z	G & S DIESEL SERVICE	P/MOVER
1029	DriCabRep\SEAT	REPLACE SEAT BELT BUCKLE	01/04/2026	1145432	HCU	XV318Z	G & S DIESEL SERVICE	P/MOVER
1029	Body\WIPERS	REPLACE WIPER BLADES DEFECT ABS LEAD REPLACE ABS LEAD CHECK WIRING FROM TRUCK	01/04/2026	1145432	HCU	XV318Z	G & S DIESEL SERVICE	P/MOVER
1029	Elect\ABS	TOP UP ENGINE OIL	14/03/2026	1145432	HCU	XV318Z	G & S DIESEL SERVICE	P/MOVER
1029	Elect\ELECT P&W	REVERSE SQUAWKER	27/02/2026	1145432	HCU	XV318Z	G & S DIESEL SERVICE	P/MOVER
1029	VehService\AS	completed 1214516	20/02/2026	1214516	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	VehService\BS	SMc completed at 1214516 km	20/02/2026	1214516	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Annual Inspection B SERVICE DUE.	SMc completed 1214516	20/02/2026	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	DIFF SERVICE DUE.	SMc completed	20/02/2026	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	speedo showing wrong reading. Shows 100kph but actual speed is 95kph		16/02/2026	1137092	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	-ALL WARNING LIGHTS CAME BACK ON AGAIN.		16/02/2026	1137092	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	All dash warning light's are ON.		16/02/2026	1137092	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	CODE: DRIVING / BRAKING CONDITIONS CHANGED Truck Braking @ 50% Efficent. ZR1 CODE ON DASH - BRAKE LIGHT & TRANS SHIFT FAULT & HILL START ASSIST INOP CONNECTED DIAGNOSTIC COMPUTER FOUND CODE FOR TRANSMISSION FOLLOWED TROUBLESHOOTING STEPS CHECKED F39 FUSE FOR TRANSMISSION - OK CHECKED POWER AT A7 X 18.15/1 - NO POWER FOUND CHECKED FUSES IN PDM - FOUND 30AMP FUSE BLOWN INSPECTED ALL WIRING - NO SHORTS FOUND RECOMMEND TRAILERS BE INVESTIGATED FOR SHORT IN EBS SYSTEM BLOWING FUSE- REPEAT FAILURE- SAME		16/02/2026	1137092	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	FAULT OCCURED LAST MONTH.		16/02/2026	1137092	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	Lot's of warning light's.		16/02/2026	1137092	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	Tyres\TP1+2		04/02/2026	1145432	HCU	XV318Z	BORDER BANDAG PTY LTD	P/MOVER
1029	Jump start Truck.		02/02/2026	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER

		DROVE FROM OAKS ESTATE TO DT CBR FOR PARTS AND XENTRY						
		DROVE TO YASS SERVICE CENTER						
		CARRIED OUT QUICK TEST						
		AC, TCM, AND SRS MODULES OFFLINE						
		INSPECTED WIRING HARNEDD, FOUND SHORT ON MCM AND HARNESS, REPAIRED HARNESS						
		CHECKED ALL POWER AND EARTHS TCM 21 PIN PLUG						
		NO POWER PIN 4 (CIRCUIT 15)						
		CHECKED POWER AT FUSE 36, NO POWER						
		BRIDGED POWER FROM FUSE 18 TO FUSE 36						
		POWER NOW AT A5.X1.21/4.						
		REFIT PLUG						
		TCM BACK ONLINE ABLE TO START VEHICLE						
		UNHOOKED TRAILERS SO CUSTOMER COULD SWAP TRUCKS						
		ACM OFFLINE						
		CHECKED ALL POWER AND EARTHS ACM 21 PIN PLUG						
		NO POWER A PIN 16						
		NO POWER FUSE 9						
		CONNECTED POWER TO FUSE 9, STILL NO POWER AT ACM 21/16						
		RAN NEW WIRE FROM TCM 21/4 TO ACM 21/16						
		ACM NOW ONLINE						
		CLEARED ALL FAULT CODES						
		NO ACTIVE CODES						
		BRIDGED WIRES AT SSAM, FUSE 18 TO FUSE 36						
		ONLY TEMPORARY REPAIR						
	DAIMLER TRUCKS- BREAKDOWN.	CUSTOMER ABLE TO DRIVE VEHICLE ANBD WILL TAKE TO DT ALBURY						
	DAIMLER TRUCKS CANBERRA CALLED TO BREAKDOWN AT YASS.	DROVE BACK TO DT CBR TO RETURN XENTRY						
1029	TEMPORARILY REPAIRED. DAIMLER TRUCKS ALBURY TO COMPLETE REPAIRS.		24/01/2026	1145432	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	secure right hand taillight assembly		22/01/2026	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	replace rear right hand gaurd		22/01/2026	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	R/H rear guard broken.		22/01/2026	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Right Side Back Mud Guard Broken		22/01/2026	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	tighten gaurd bracket		22/01/2026	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Check For Coolant Leak & Repair. (Daimler Albury P/O: WW089151)		15/11/2025	1145432	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
	Replace Broken Torque Rod (V-Rod)							
1029	(Parts Supplied By Daimler Albury P/O: WW097695		04/11/2025	1145432	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	→LEFT TAIL LIGHTS HANGING		14/10/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	→MUDGUARDS BROKEN		14/10/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Mud Guard Broken		14/10/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	No Brake Lights Works On Any Trailer Hooked		28/08/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	No Brake Lights Works On Any Trailer Hooked		28/08/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	mudguard needs replacement		12/08/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Needs guards		12/08/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	RH REAR GUARD TORN		12/08/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPLACE RR MUDGUARD.	REPAIRED GUARD AND LIGHT BRACKET	12/08/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Tyres\TP9+10		06/08/2025	1145432	HCU	XV318Z	BORDER BANDAG PTY LTD	P/MOVER
1029	Tyres\TP11+12		06/08/2025	1145432	HCU	XV318Z	BORDER BANDAG PTY LTD	P/MOVER
1029	tail left indicator malfunction		24/07/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Tail light's malfunctioning ,Left side.		24/07/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
		-blown parker and low beam globes						
		-blown indicator globe causing indicators to flash fast						
		-load resistor wiring repaired						
		-rear left combination lights wired incorrectly, repaired as required						
1029	Left tail light's not working.	-twincity trailer brake patch job had blown fuse, replaced and tested, trailer brake light working but brings fault on dash when brake is applied	24/07/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	→NO BRAKE LIGHTS WITH ANY TRAILER.		24/07/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	→NO LEFT INDICATORS WITH ANY TRAILER.		24/07/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Tyres\TP7+8		21/07/2025	1145432	HCU	XV318Z	BORDER BANDAG PTY LTD	P/MOVER
1029	Tyres\TP5+6		21/07/2025	1145432	HCU	XV318Z	BORDER BANDAG PTY LTD	P/MOVER
1029	Replace LHR guard	Lhr rear guard not replaced just ziptied together as instructed by supporvisor	04/07/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	CUT FLAP OFF GUARD.		17/06/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Make Up Trailer Light Plug Adaptor Heavy Duty To Light Duty.	Made up a new trailer light adaptor & tested.	15/05/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
	Elect\TRL LIGHTS							
	*Brake lights to trailer							
	* traction control loght							
	* warning lights on dash							
	* not selecting auto gears							
	Checked codes. Found heaps of communication error codes. Cleared							
	and took for test drive. Dash lights didn't come back. Checked brake lights.							
	Found no brake lights in trailer base. Followed wiring but could not find any							
	wiring issues. Got diagrams but could not find module. Need more time.							
	Wired in aftermarket relay for brake lights. Tested. Need vehicle back							
1029	for further diagnosis.		12/05/2025	1145432	HCU	XV318Z	ARKON AUTO ELECTRICAL	P/MOVER
1029	NO BRAKE LIGHTS ON ANY TRAILER HOOKED, BUT BRAKE LIGHTS WORK ONLY ON PRIME MOVER.		10/05/2025	1147801	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	→NO BRAKE LIGHTS WITH ANY TRAILER HOOKED, BUT WORKS ON PRIME MOVER ONLY.		10/05/2025	1147801	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	No Brake Lights With Any Trailers		10/05/2025	1147801	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	trailer brake lights doesnt work with any trailers but works on prime mover		10/05/2025	1147801	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	BRAKE LIGHTS DOESN'T WORK WITH ANY TRAILERS.	ARKON WIRED IN AFTERMARKET RELAY TO BY-PASS ISSUE IN BCM.	10/05/2025	1147801	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	No Brake Lights On Trailers, Indicators come on when brakes applied.	Check & Tested Electrical Suzie Lead, Removed Ends & Checked They Were Wired Correctly, All Good Checked Power Output Of Socket On Truck Found To Be Wired Incorrectly.	09/05/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	BRAKE LIGHTS NOT WORKING ON ANY TRAILERS HOOKED UP. BUT WORK ON PRIME MOVER.	Hooked different truck up, lights ok ,brake light fault in previous truck	09/04/2025	1145432	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	-ELECTRIC CABLE MALFUNCTION, BRAKE LIGHTS ALWAYS ON BOTH TRAILERS.	#453413.	22/03/2025	1140385	HCU	XV318Z	Wodonga Workshop	P/MOVER
		TESTED. WORKING.						
1029	R/H Fog Light Not Working	K.RYAN ½ HOUR LABOUR.	22/03/2025	1140385	HCU	XV318Z	Wodonga Workshop	P/MOVER
		REPAIRED.						
1029	RIGHT SIDE LIGHT MOUNT KNOCKED OFF. NEEDS TO BE REPLACED.	K.RYAN ½ HOUR LABOUR.	22/03/2025	1140385	HCU	XV318Z	Wodonga Workshop	P/MOVER
		TESTED. WORKING.						
1029	-LEFT FRONT INDICATOR AND LEFT TAIL LIGHT NOT WORKING.	K.RYAN ½ HOUR LABOUR.	22/03/2025	1140385	HCU	XV318Z	Wodonga Workshop	P/MOVER
		TESTED. WORKING.						
1029	Front left hand indicator not working.	K.RYAN ½ HOUR LABOUR.	22/03/2025	1140385	HCU	XV318Z	Wodonga Workshop	P/MOVER
		TESTED. WORKING.						
1029	Left Front Indicator, Globe Broke	K.RYAN ½ HOUR LABOUR.	22/03/2025	1140385	HCU	XV318Z	Wodonga Workshop	P/MOVER
		DIAGNOSED AND REPLACED FAULTY RELAY.						
1029	→ELECTRIC CABLE MALFUNCTION- BRAKE LIGHTS ALWAYS STAYS ON BOTH TRAILERS.	K.RYAN 1 HOUR LABOUR.	22/03/2025	1140385	HCU	XV318Z	Wodonga Workshop	P/MOVER
		TESTED. WORKING.						
1029	No indicator on front passenger side .	K.RYAN ½ HOUR LABOUR.	22/03/2025	1140385	HCU	XV318Z	Wodonga Workshop	P/MOVER
		TESTED. WORKING.						
1029	No taillight's on left side.	K.RYAN ½ HOUR LABOUR.	22/03/2025	1140385	HCU	XV318Z	Wodonga Workshop	P/MOVER
		TESTED. WORKING.						
1029	WARNING LIGHTS, INDICATORS LEFT AND LEFT TAIL LIGHTS NOT WORKING.	K.RYAN ½ HOUR LABOUR.	22/03/2025	1140385	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	WALK RAMP FLOOR BENT		13/03/2025	1140385	HCU	XV318Z	Wodonga Workshop	P/MOVER
		REPLACED SQUASHED PLUG.						
1029	ELECTRIC CABLE SQUASHED.	K.RYAN 1 HOUR LABOUR.	12/03/2025	1140385	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPLACE MALE ELEC PLUG.		12/03/2025	1140385	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Tyres\Puncture PO 7		11/03/2025	1140385	HCU	XV318Z	BEAUREPAIRES	P/MOVER
1029	Tyres\TP1+2		06/03/2025	1140385	HCU	XV318Z	BEAUREPAIRES	P/MOVER
	RH DOOR WON'T OPEN FROM OUTSIDE.							
1029	-REMOVED DOOR PANEL AND HANDLE MECHANISM. FOUND BROKEN PINS. DRILLED AND FITTED A ROLL PIN TO SUIT. REASSEMBLED DOOR AND TESTED. OK.		28/02/2025	1138807	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Broken mudguard's on both side's.	REPLACED RF GUARD AND CHEVRON SIGN.	19/02/2025	1134989	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Left side mudguard second axle rubbing against tyre.		11/02/2025	1134989	HCU	XV318Z	Wodonga Workshop	P/MOVER
		FOG LIGHT INOP - PINS BROKEN AT PLUG						
		REMOVE AND REPLACE DAMAGED PINS FROM PREVIOUS DIAGNOSIS						
1029	REPAIR FOG LIGHT.	TESTED OPERATION - OK	29/01/2025	1134989	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
		CODE ON DASH - BRAKE LIGHT & TRANS SHIFT FAULT & HILL START ASSIST INOP						
		CONNECTED DIAGNOSTIC COMPUTER						
		CHECKED CODES						
		REMOVED DASH PANEL COVER TO ACCESS EBS MODULE						
		TESTED POWER TO GROUNDS - FOUND 12V						
		TESTED AT SSAM - 12V						
		CHECK ALL FUSES AS CHASSIS POWER DISTRIBUTION BLOCK.						
		FOUND BLOWN 30A FUSE- MAIN POWER FEED FOR ABS AND TCM CONTROL.						
		CHECK FOR CAUSE OF BLOWN FUSE.						
		FOUND CORROSION ON TRUCK SIDE EBS PLUG SHORTING OUT PINS.						
		CLEAN AND REFIT						
		REMOVE AND REPLACE FUSE.						
1029	Transmission Fault.	CLEARED CODES AND CHECKED OPERATION-OK	29/01/2025	1134989	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER

1029	CODE:BRAKE LIGHT FAULTY		29/01/2025	1134989	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	CODE: TRANSMISSION		29/01/2025	1134989	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
		Checked and confirmed multiple faults within the lighting system. Checked circuit breaker and fuses. Found one of the main fuses for the light system blown. Replaced and had some of the lights working again. Checked the non-working ones. Left hand tail light show sign of overheating, connection are loose, right hand side tail light missing some led, one side marker globe dead, park light on driver side light assembly blown and driver side fog light missing its globe and its plug. Replaced and repaired when possible. Stop light were working fine when truck came in but had a message on the dash about a fault on them. Wired in load resistors on tail and stop lights circuits to get rid of the dash message.						
1029	Repair Electrical Fault In L/H Indicator & Stop Tail Light. (Arkon Auto Electrical P/O: WW091095)	Tested correct operation.	24/12/2024	1129157	HCU	XV318Z	ARKON AUTO ELECTRICAL	P/MOVER
1029	CODE: BLOWN GLOBE IN FRONT	Fitted new globe Still not working	16/12/2024	1126236	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	front blinker light not working one yellow light sitting on the seat so you can fix	fitted new globe still Not working	16/12/2024	1126236	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	LHF Indircator Globe Blown.		16/12/2024	1126236	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	VehService\AS	COMPLETED AT DAIMLER TRUCKS ALBURY- BRAKE % NOT PROVIDED	15/11/2024	1123711	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	B Service	COMPLETED AT DAIMLER TRUCKS ALBURY- BRAKE % NOT PROVIDED	15/11/2024	1123711	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Engine Coolant Leak Top R/H/S Engine		26/09/2024	81660	HCU	XV318Z	Wodonga Workshop	P/MOVER
		INSTALL NEW ENGINE HUB FAN CONFIRM DIAGNOSIS AFTER FAN HSPEED FAULT NOTED ON PREVIOUS BREAKDOWN INVOICE- TO BE CONFIRMED. CHECKED FAN SPEED ACTUAL VALUES-LOW CHECK FAN OPERATION- FOUND TO BE SPINNING FREE ON HUB- NO RESISTNACE FROM VISCOUS HUB-LIKLEY BEEN CAUSING OVERHEATNG ISSUES. REMOVED FAN SHROUD AND MOVE COOLANT HOSES OUT OF THE WAY FOR ACCESS. REMOVE DRIVE BELT TO HUB AND UNBOLT FAN FROM VISCOUS HUB. UNBOLT HUB FROM DRIVE. REMVOE AND REPLACE HUB- REASSEMBLE IN REVRSE ORDER.						
	Fault Code Engine Fan [as Advised by Mechanic at Daimler Trucks Laverton, from Breakdown 8/8/24.							
	(Repair carried out by Daimler Trucks Albury P/O: WW088312)	CHECK FAN TYPE PARAMETERISATION IN MCM-OK						
1029		TEST DRIVE TO CONFRIM OPERATION-OK	24/08/2024	62610	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	Blown Radiator Hose (Daimler Somerton Attended Booked Through Daimler Trucks Albury P/O: WW088028)		08/08/2024	57757	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	Brakes\BREAKDOWN	Called Adrian (driver), 0414890715, he advised complete - EBS fault in trailers was setting off safety switch in trailer - cleared codes	19/06/2024	29753	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	TRUCK WON'T CHANGE DOWN TO 2ND REAR WHEN STOPPED.		15/06/2024	28392	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	ADAPTIVE CRUISE CONTROL NOT WORKING.		15/06/2024	28392	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	ABS FAULTY. PILLING TO LHS UNDER BRAKING & SKIDDING TRAILERS ON LHS.	KMs 1069311	15/06/2024	28392	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	TRUCK WON'T GO ABOVE 2OKM/H.		11/06/2024	25817	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	D RATING.		11/06/2024	25817	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	ADBLUE SYSTEM FAULTY.		11/06/2024	25817	HCU	XV318Z	DAIMLER TRUCKS ALBURY	P/MOVER
1029	DROP OFF DAILMLER.		27/04/2024	10278	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	TRANS SELECTOR SWITCH/ SELECTOR STALK FAULTY.		17/04/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Fix electronic connector to fog light\run light		17/04/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
		1040000KM SERVICE - INSP - $339.46 CARRIED OUT INSPECTION SERVICE PER CHECKLIST. INSPECTED ALL STEERING, SUSPENSION AND BRAKE COMPONENTS. CHECKED ALL OIL AND FLUID LEVELS - TOPPED UP TRANS OIL. CHECKED ALL DRIVE BELTS AND COOLING SYSTEM. CHECKED ALL CHASSIS COMPONENTS AND GREASED ALL LUBE POINTS. CHECKED ALL CABIN, ELECTRICAL AND BATTERIES.						
1029	Service As Per Attached Checklist	WASHED DOWN.	17/04/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	BRAKE LIGHT FAULT ON DASH.		17/04/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Record Check Results As Attached To This Job *MT Data upgrade Old Unit: 4120001787 New unit: 4604007725 vin: WDB9634242022836 4 Phone number: 0417134233 WIFI pin : 7907 Located unit underthe dashboard. Removed old antennas, pasenger side trims and leather panels. Checked wirings and old unit operation (tablet wasn't setup with the old unit so paired it. Mounted new antennas and ran cables to the unit.		17/04/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Called MT Data and finish setup.		17/04/2024	8427	HCU	XV318Z	Albury Workshop	P/MOVER
1029	Tyre Position 1 + 2		19/03/2024		HCU	XV318Z	Albury Workshop	P/MOVER
1029	REWIRE PLUG TO 5 PIN.		26/01/2024		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REWIRE PLUG TA 5 PIN.		26/01/2024	995011	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	No Indicators To Trailer	REWIRED ADAPTOR LEAD TO SUIT.	26/01/2024	995011	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	UNHOOKED. DROPPED OFF DAIMLER.		03/01/2024	994960	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Carry out internal Road Worthy as per check list		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPLACE BROKEN TAIL LIGHT FASCIA.		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPLACE WORN THROUGH RHR MUDGUARD.		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPAIR DAMAGE TO RH & LH FUEL TANK BRACKETS.		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPLACE WIPER BLADES.		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPLACE BROKEN WINDSCREEN. (BIRD STRIKE)		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Move Deck Plate Forward		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Repair Red Suzi Coil		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPAIR DAMAGE TO LH FUEL TANK BRACKET. (DAMAGE CAUSED BY ANIMAL STRTIKE)		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	BRACKET BETWEEN FUEL TANKS AT BOTTOM OF TANKS IS BROKEN.		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPLACE BROKEN AIR LINE (BLUE SUZI)		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	ENG EXH LEAK WHEN UNDER LOAD.		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	LH INDICATOR FAULTY.		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	NEED TO MOVE POGO FORWARD AS FOULING ON CNR OF TRAILER WHEN TURNING.		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	LH INDICATOR TO TRAILERS NOT WORKING.		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
	RH FUEL TANK J BRACKET DAMAGED.							
1029	" " " TANK STRAP DAMAGED.		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPAIR AIR LINE.		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Record Check Results As Attached To This Job		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Service As Per Attached Checklist		02/01/2024	37154	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	fit run outs to drives		02/12/2023	980234	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Windscreen Replacement		02/12/2023		HCU	XV318Z	Albury Workshop	P/MOVER
1029	Pressure Check		04/10/2023		HCU	XV318Z	Albury Workshop	P/MOVER
1029	Carry out internal Road Worthy as per check list		29/07/2023	909724	HCU	XV318Z	Wodonga Workshop	P/MOVER
		880,000KM SERVICE - B + INSP CHANGE ENGINE OIL AND FILTER CHANGE FUEL FILTERS INSPECT ALL DRIVE LINE OILS AND FLUIDS INSPECT ALL DRIVE LINE BELTS AND COOLING SYSTEM CHECK ALL LIGHTS, CABIN ELECTRICALS AND BATTERIES CHECK CHASSIS, SUSPENSION AND BRAKE COMPONENTS GREASE ALL LUBE POINTS							
1029	Service As Per Attached Checklist	WASH VEHICLE	29/07/2023	909724	HCU	XV318Z	Wodonga Workshop	P/MOVER
	RH FUEL TANK J BRACKET DAMAGED.							
1029	" " " TANK STRAP DAMAGED.		29/07/2023	909724	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	LH INDICATOR FAULTY.		29/07/2023	909724	HCU	XV318Z	Wodonga Workshop	P/MOVER
		LIGHT FAULTS ON DASH INSPECT TO FIND RH CLEARANCE LIGHT MISSING AND RHF ROOF LIGHT BROKEN REMOVE AND REPLACE RH VISOR ROOF LIGHT - BROKEN DUE TO ACCIDENT DAMAGE QUOTE REPLACEMENT PARTS FOR SIDE CLEARANCE LIGHT, REMOVE AND REPLACE RH CLEARANCE LIGHT							
1029	REPLACE BROKEN FRONT CLEARANCE LIGHT. (RHS ON SUNVISOR)	TEST OPERATION BOOST LEAK INSPECT TO FIND INTERCOOLER SPLIT LOWER BULL BAR, DRAIN COOLANT REMOVE TOP RADIATOR HOSE REMOVE BOOST HOSES REMOVE FRONT GRILLE	29/07/2023	909724	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPAIR AIRLINE TO TRAILER (BLUE)	UNDO CONDENSOR, MOVE OUT OF WAY LIGHT FAULTS ON DASH INSPECT TO FIND RH CLEARANCE LIGHT MISSING AND RHF ROOF LIGHT BROKEN REMOVE AND REPLACE RH VISOR ROOF LIGHT - BROKEN DUE TO ACCIDENT DAMAGE QUOTE REPLACEMENT PARTS FOR SIDE CLEARANCE LIGHT, REMOVE AND REPLACE RH CLEARANCE LIGHT	29/07/2023	909724	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	EXH GAS AFTER TREAT FAULT CODE.	TEST OPERATION	29/07/2023	909724	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPAIR AIR LINE.		29/07/2023	909724	HCU	XV318Z	Wodonga Workshop	P/MOVER

		PARK BRAKE ALARM INOP INSPECT TO FIND PARK BRAKE ALARM HORN OPEN CIRCUIT TEST OPERATION - NO HORN AUDIBLE TEST VOLTAGE @ HORN - 24V						
1029	PARK BRAKE ALARM NOT WORKING.	REPLACE HORN	29/07/2023	909724	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	NEED TO MOVE POGO FORWARD AS FOULING ON CNR OF TRAILER WHEN TURNING.		29/07/2023	909724	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	LH INDICATOR TO TRAILERS NOT WORKING.		29/07/2023	909724	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	ELECT SUZI COIL STRETCHED. NEED TO SHORTEN LEAD BETWEEN POGO & BACK OF CAB.		29/07/2023	909724	HCU	XV318Z	Wodonga Workshop	P/MOVER
		UNBOLT INTERCOOLER, LIFTED IT OUT LIFT IN NEW INTERCOOLER, FIT BOLTS REFIT CONDENSOR, GRILLE AND TOP RADIATOR HOSES						
1029	PLEASE CHECK FOR COOLANT LEAK.	REFILLED RADIATOR WITH	29/07/2023	909724	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Tyre Position 11 + 12		26/07/2023		HCU	XV318Z	Albury Workshop	P/MOVER
1029	Tyre Position 9 + 10		26/07/2023		HCU	XV318Z	Albury Workshop	P/MOVER
	BRAKE WEAR LIGHT ON DASH INSPECT TO FIND FRONT DRIVE BRAKES WORN OUT JACK UP FRONT DRIVE AXLE REMOVE BOTH SIDE WHEELS RELEASE PARK BRAKE BACK OFF BRAKE CALIPHERS REMOVE WORN BRAKE PADS CHECK CALIPHER SLIDE, ALL OK MEASURE BRAKE ROTOR, 39MM ON BOTH SIDES FIT NEW BRAKE PADS AND ADJUST CLEARANCE REFIT WHEELS AND TENSION LOWER AXLE							
1029	TEST DRIVE, ALL OK		25/07/2023	905595	HCU	XV318Z	Albury Workshop	P/MOVER
1029	Tyre Position 1		25/07/2023		HCU	XV318Z	Albury Workshop	P/MOVER
1029	Tyre Position 2		25/07/2023		HCU	XV318Z	Albury Workshop	P/MOVER
1029	1-10		23/06/2023		HCU	XV318Z	Albury Workshop	P/MOVER
1029	Drop off to Daimler		15/06/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Tyre Position 1 + 2		22/03/2023		HCU	XV318Z	Albury Workshop	P/MOVER
	CHECK FLASHERS N/W TRAVEL TO DEPOT. CHECK NO RHS FLASHERS. DISMANTLE TRAILER PLUG. LOCATE SHORTING AND RECTIFY							
1029	REASSEMBLE AND TEST OPERATION		01/03/2023		HCU	XV318Z	Albury Workshop	P/MOVER
1029	PICKED UP DAIMLER.		25/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	SERVICE DUE.		02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	NO BRAKE LIGHTS TO TRAILERS.		02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	TRACTION CONTROL LIGHT ON		02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	FRONT WHEELS GOT VERY HOT.		02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	DRIVE & BRAKE CODE.		02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	TRANS FAULTY CODE.		02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	WHEN BRAKE LIGHT ON TRUCK ACTIVATED, FAULT CODE ON DASH TRAILER REVERSE LIGHT FAULT. (THIS OCCURS WHEN H/LIGHTS ARE ON)	TRAILER ISSUE.	02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	CHECK ENGINE FOR NOISY BEARING.		02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPLACE BROKEN R/H VISOR CLEAR LIGHT.		02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	CHECK ENG FOR BEARING SQUEAL NOISE.		02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	ADJUST R/H H/L. (ON LOW BEAM NEEDS TO GO UP)		02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	FAULT ON DASH DISPLAUY (UNEVEN BRAKE PAD WEAR)		02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	DRIVER'S SEAT NEEDS REPLACING.		02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPLACE WIPER BLADES. speedo needs recalibrating (shows 100kms but only doing 97km's		02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	To be checked at next service.		02/02/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	NO TRAILER LIGHTS. CONFIRMED PROBLEM IN TRUCK. Coolant leak Daimler attended to repair	RESET BREAKER.	31/01/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Contract Maintenance.. Coolant leak		04/01/2023		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	CHECK ENGINE FOR NOISY BEARING.		10/12/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPLACE BROKEN R/H VISOR CLEAR LIGHT.		10/12/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	CHECK ENG FOR BEARING SQUEAL NOISE. (DAIMLER)		10/12/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	RH CLEARANCE LIGHT NOT WORKING.		10/12/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	ADJUST R/H H/L. (ON LOW BEAM NEEDS TO GO UP) (DAIMLER)		10/12/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	FAULT ON DASH DISPLAUY (UNEVEN BRAKE PAD WEAR) (DAIMLER)		10/12/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	DRIVER'S SEAT NEEDS REPLACING. (DAIMLER)		10/12/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Tyre Position 9 + 10		28/10/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Tyre Position 7 + 8		28/10/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Tyre Position 5 + 6		28/10/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Tyre Position 3 + 4		28/10/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	replace suzi leads SECURE TRANS COOLER LINES, BATTERY CABLES FOUND LINES INSECURE DUE TO MISSING BOLTS AND CABLE TIES. REMOVED BATTERIES FOR ACCESS. SECURED ALL CABLES WITH CABLE TIES AND FITTED SECURING BOLT TO TRANS COOLER LINES.	elite diesel Poww074731	24/10/2022	37139	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	ALL OK.		21/10/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	DROP OFF DAIMLER. Service As Per Attached Checklist		16/10/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Serviced By Daimler		06/10/2022	769397	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Engine mounts replaced.		06/10/2022	769397	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Compressor resealed.		06/10/2022	769397	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Battery Box mount bracket replaced.		06/10/2022	769397	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Steer Axle and Rear Brake pads replaced.		06/10/2022	769397	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	HOOKED UP TS41/542. MOVED TO SHED.		16/09/2022	752251	HCU	XV318Z	Wodonga Workshop	P/MOVER
		Travel to Greenfreight Wodonga, pulled the cover off of B-trailer to check wiring behind the trailer bases. Inspect wiring and removed wires 1 by 1 to find the cause of the park lights on the trailers dropping out. Found the reverse wire in the heavy-duty plug was also powering up with the park lights and when connected it would short out and turn the lights off. Found the power to the black wire was on the truck side and didn't need to be connected. Removed wiring out of the trailer base on the truck. Put the truck back together and return to the						
1029	Trailer light issue	workshop.	16/09/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	NO TRAILER LIGHTS. Right hand indicator inoperative.	TRAVELLED TO BOWSER. REPLACED TRAILER LIGHT LEAD. RETURNED TO DEPOT. LIGHTS NOT WORKING AGAIN. INSPECTED ALL LIGHTS AND LEADS ON BOTH TRAILERS. NO FAULT. CONNECTED 960 TC	14/09/2022	750553	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Arkon on site to investigate.		24/08/2022	37037	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	ELECTRICAL SHORT. WITH LIGHTS ON, BRAKE LIGHT IS ACTIVATING L/H INDICATOR LIGHTS ON TRAILERS.	FOUND EXPOSED AND MELTED WIRING ON TRAILER.	24/08/2022	37037	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	REPLACE WIPER BLADES.		24/08/2022	37037	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Pressure Check		11/08/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	supply and fit 2tyres		11/08/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Service As Per Attached Checklist Replace Windscreen Done at Albury Autoscreens workshop	Refer to Attached report serviced by Daimler Albury.	13/07/2022	717800	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	PO#WW072062		27/05/2022	37037	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	RH LOW BEAM NOT WORKING. Travel to Greenfreight Wodonga, check tablet for correct operation of unit. Tablet couldn't see tracking unit. Locate tracking unit, found unit was not powering up. Disconnect and test power, earth and ignition to unit. Plug back in and unit still didn't power up. Open unit and replaced sd card, test. Unit turned on and connected to tablet. Called MT Data to check operation	REPLACED HEADLIGHT.	20/05/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	on there end, all is working correctly.		23/04/2022	677862	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	CHECK RH INDICATOR FAULT TO TRAILER. INDICATOR TO TRAILER INTERMITTENTLY STOPS. GEAR SELECT PROBLEM STILL OCCURING.	INSPECTED PLUG. SECURED CABLE TO SUZI. REPLACED SPLIT MAZI HOSE SUZI.	15/04/2022	673483	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Refer Job # 377446. GEAR SELECT PROBLEM STILL OCCURING.		05/04/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	CHECK FOR GEAR SELECTION PROBLEM. WHEN IN AUTO MODE GEARBOX WILL SOMETIMES NEUTRALIZE BETWEEN 5&7. MAYBE AIR PRESS PROBLEM. (PLS ADVISE DAIMLER TRUCKS ALB) LH mirror cover missing	New Gearbox installed by Daimler Albury.	05/04/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	R& R mirror and wiring LH front drive top hat cover missing. Removed 5 wheel nuts Fitted new hub cover		05/04/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Refitted and tensioned wheel nuts to spec		05/04/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	Replace broken fog light (RH), fitted new mounts		05/04/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	DROP OFF DAIMLER		27/02/2022	649799	HCU	XV318Z	Wodonga Workshop	P/MOVER
1029	MOVED IAP AS PER SHANNON'S REQUEST.		24/02/2022	648073	HCU	XV318Z	Wodonga Workshop	P/MOVER

	REPLACE POGO STICK								
	REMOVE CHECKER PLATE WALK WAY								
	DRILLED HOLE IN CHECKER PLATE TO FIT POGO STICK								
	FIT NEW POGO STICK								
	TIGHTEN NUT ON POGO STICK TO CHECKER PLATE								
1029	INSTALL CHECKER PLATE WITH POGO STICK AND INSPECT - ALL OK		16/02/2022	643699	HCU	XV318Z	Rosewood Workshop	P/MOVER	
1029	DROP OFF DAIMLER.		16/02/2022	643699	HCU	XV318Z	Rosewood Workshop	P/MOVER	
1029	Carry out internal Road Worthy as per check list		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	RH CAB MARKER LIGHT NOT WORKING		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	L/H/R BRAKE LIGHT NOT WORKING.		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Service Due.		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Service As Per Attached Checklist		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	DRIVER'S SEAT NEEDS REPLACING.		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	"EGR COOLER" COOLANT LINE TO HEADER TANK LEAKING BAD.		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	"FRONT VISCOUS" FAN BELT REQUIRES REPLACING		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	PLS FIT AIRLINE POGO STICK TO STOP AIR/ELEC LINES FROM DRAGGING ON WALK PLATE.		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	TRUCK HAS EGR FAULT		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	TOP HAT STYLE HUB COVER BROKEN		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Right Hand stop light not working.		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Needs Pogo pole fitted to hold air/elect lines.		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Replace left hand outter mirror cover		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Left turn globe blown.		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Fir Air/Electrical Pogo Stick.		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
	damage to RH fog light/day run light (rear of housing broken due to kangaroo strike)								
1029	side light fault code when lights not switched on		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	bunk cooler not working (water pump not pumping)		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	speedo needs recalibrating (shows 100kms but only doing 97km's	To be checked at next service.	15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Refit missing chassis plate.		15/02/2022	634137	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	DROP OFF DAIMLER		29/01/2022	635711	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Front viscas belt needs replacing.		28/01/2022		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	supply and fit 2tyres		16/01/2022	631235	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	REPLACED BLOWN LH HEADLIGHT GLOBE		08/01/2022	626241	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	DROP OFF AND PICK UP FROM DAIMLER ALBURY.		19/12/2021	616670	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Service As Per Attached Checklist		18/11/2021	589248	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Service As Per Attached Checklist	DROP OFF AT DAIMLER. PICK UP FROM DAIMLER.	14/11/2021	593952	HCU	XV318Z	Wodonga Workshop	P/MOVER	
	DROP OFF TO DAIMLER- PICKUP GRAHAM								
1029	PICKUP DAIMLER- DROP OFF GRAHAM		31/10/2021		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Pressure Check		26/10/2021	582365	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	POS 1,2		26/10/2021	582365	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	WHEEL BALANCE		19/10/2021	576273	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Replace blown L/H headlight globe.	Refer Job# 355485	29/09/2021	566731	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Left H/L globe blown.	Change Left Hand headlight.	29/09/2021	566731	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Replace blown right hand headlight globe.	Removed and replaced R/H headlight globe due to being blown.	04/09/2021	552290	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	presuure maintenance POS 3-10		28/08/2021	547969	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	supply and fit 2 tyres		28/08/2021	547969	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Service As Per Attached Checklist		24/08/2021	544381	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029			24/08/2021		HCU	XV318Z	Wodonga Workshop	P/MOVER	
	Move truck.								
1029	Park Truck.		13/08/2021	538561	HCU	XV318Z	Wodonga Workshop	P/MOVER	
		2 x 50 x 25 lengths of RHS							
1029	Make up walk plate chassis mounts and fit walk plates.	Don Sparks PO# WW066384	13/08/2021	538561	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Refit chassis walk plate.	Refer Job # 349254	07/08/2021		HCU	XV318Z	Wodonga Workshop	P/MOVER	
		Attempted to repair walk plate.							
1029	Refit missing chassis plate.	Needs to have Right hand side cut to suit.	07/08/2021		HCU	XV318Z	Wodonga Workshop	P/MOVER	
		Blown Right hand tail light.							
1029	Rear brake light blown.	Removed and Replaced and tested.	29/07/2021	529386	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Service As Per Attached Checklist		15/07/2021	524186	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Service As Per Attached Checklist		15/07/2021	524186	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Pick up from Daimler - Dropped Graham off		11/07/2021		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Drop truck off to Daimler.		10/07/2021		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Right Hand head light U/S	Replaced globe.	28/05/2021	500192	HCU	XV318Z	Wodonga Workshop	P/MOVER	
	replace both rear guards and bring truck to shed and park up at trailers and adjust guards								
1029	including smoko and clean up		14/05/2021	491788	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Service As Per Attached Checklist		08/05/2021		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Left Hand Head light globe blown.		08/05/2021		HCU	XV318Z	Wodonga Workshop	P/MOVER	
	Please Fit Park Brake Alarm.								
1029	New horn needed. Please Fit Park Brake Alarm.	damiler Poww063553	13/04/2021		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Tyre Position 5 + 6		31/03/2021	466368	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Tyre Position 3 + 4		31/03/2021	466368	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	replace 2 tyres		24/02/2021	445876	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	replace 2 tyres		24/02/2021	445876	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	replace 2 tyres		24/02/2021	445876	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	RH low beam blown		23/02/2021		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	alternator warning light on	Daimler assist contacted arranging repair	19/02/2021	441662	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Service As Per Attached Checklist	completed at Daimler Albury	14/02/2021	454629	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	fit run out unrepairable puncture		01/02/2021	432809	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	inspected tyre found nail - call Beaurepairs hotline		01/02/2021		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	LH H/L globe blown	removed and replaced L/H low/high beam globe	12/01/2021	421566	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	diagnose and repair viesa (replace water pump)		16/12/2020	411308	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	drop at Tristar		06/12/2020		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	pick up truck at Tristar		06/12/2020		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Service As Per Attached Checklist	Daimler trucks Albury completed	06/12/2020	405000	HCU	XV318Z	Wodonga Workshop	P/MOVER	
		check for leak and drop at Daimler Albury							
1029	adblue system has fault show on dash and leaking adblue	pick up from Daimler	01/12/2020		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Job Added From Invoice		25/11/2020	394052	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Job Added From Invoice		25/11/2020	394052	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Job Added From Invoice		25/11/2020	394052	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	replace blown RHS H/L globe		01/11/2020	385436	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	replace RH headlight globe		01/11/2020		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	move turntable back one hole and measure length	completed	29/10/2020	382903	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	replace decals on wind deflectors	Deanos sings to carry out work P/O WW058899	17/10/2020		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	replace LH rear guard	completed	16/10/2020	374792	HCU	XV318Z	Wodonga Workshop	P/MOVER	
	inspected damaged fuel sender will need replacing when at tristar next								
1029	replaced broken walkplate lock and refit front walk plate	completed- but been hit again- need higher turntable	16/10/2020	374792	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	drop off sign shop		16/10/2020		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	check over spare turntable base for a standard to replace low profile. Need to order a standard base plate as all low profile		15/10/2020		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	handover meeting		15/10/2020		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	NEED TO ORDER RHS MIRROR MOTOR	borttom mirror doesn't move by control	06/10/2020	275548	HCU	XV318Z	Wodonga Workshop	P/MOVER	
	RH steer leaf spring rusty and top leaf spring is bent								
1029	inspected by Graham and Dean		06/10/2020	375517	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	annual inspection	Carry out annual inspection	06/10/2020	375517	HCU	XV318Z	Wodonga Workshop	P/MOVER	
		daimler albury Poww058560							
		replaced damaged fuel sender unit							
		electical plug that goes into the unit needs replacing							
1029	fuel sender unit	one of the fuel hose is damaged also needs replacing next service	02/10/2020	375585	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	speedo needs recalibrating (shows 100kms but only doing 97km's		01/10/2020	374524	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	tail shaft cover/safety plate needs refitting		01/10/2020	374524	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	diesel level display faulty (fuel gauge not working)		01/10/2020	374524	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	align drive belt	incorrectly aligned by tech, rework	26/09/2020	361643	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	check and rectify brake pedal rubber worn	wear and tear	26/09/2020	361643	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	check and rectify a/c hose chaffing	grill tabs and radiator shroud chaffing on a/c line modified	26/09/2020	361643	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	check and rectify cab shocker leaking	internal material defect on front cabin shockers, RH shocker leaking oilk. Jack cabin up and remove front panelm remove both front shockers and replace torque shocker bolts when under load, test driv	26/09/2020	361643	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	S&F replacement		26/09/2020	361643	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	check and rectify air leaks from EAPU unit	internal defect on EAPU, remove airlines and charge air line from EAPU, remove unit and fittings, refit fittings into new EAPU and fit new unit. Refit airlines and charge. Build up air pressureand check o	26/09/2020	361643	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	carry out inspection		26/09/2020	361643	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	check and rectify rear guards damaged	remove and replaced rear guards	26/09/2020	361643	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	perform wheel alignment	sent vehicle for wheel alignmen, damage code 40201ZD	26/09/2020	361643	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	check alarm under bunk		26/09/2020	361643	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	check and rectify drivers seat valve faulty	result of material defect of valve block, remove lower seat trim and support seat, remove seat height valve and fit new valve, refitall air lines and clips as removed. Refit trim and test operation ok.	26/09/2020	361643	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	check and rectify side clearance light N/W	blown globe	26/09/2020	361643	HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	pick up truck from Tristar (truck had been picked up already)		20/09/2020		HCU	XV318Z	Wodonga Workshop	P/MOVER	
	pick up from tri star								
1029	waited at border check point		20/09/2020		HCU	XV318Z	Wodonga Workshop	P/MOVER	
1029	Service As Per Attached Checklist		20/09/2020	382823	HCU	XV318Z	Wodonga Workshop	P/MOVER	

1029	needs 8lts of oil	FILLED DURING THE SERVICE	20/09/2020	382823	HCU	XV31BZ	Wodonga Workshop	P/MOVER
	drop 1029 off at Tristar for service and repairs							
1029	truck neutralized as I left the yard to drop truck off a tristar		19/09/2020		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	ATTEND BREAKDOWN - NOT SELECTING GEARS TRAVEL TO BREAKDOWN AT GREENFREIGHT YARD CONNECT DIAGNOSTIC COMPUTER AND CHECK CODES FOUND EBS AND TCM FAULTS FC		19/09/2020	369237	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	fitted new ABS lead		19/09/2020	369237	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		28/08/2020	0	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	replace RH ligth bracket	replace bracket	28/08/2020	361968	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	brake light faulty comes on	repair wiring to tail light	28/08/2020	361968	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	alarm under bunk, unknown source or reason		21/08/2020		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	air valve in seat faulty		21/08/2020		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	NEED TO ORDER SIDE CLEARANCE LIGHT		21/08/2020		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	R/H/S clearance lights bracket still not replaced as per 111829 11/7/19		06/08/2020		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	R/H/S external mirror still needs repairs (loose and shakes)		06/08/2020		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	R/H/S reflector/cleanrace light still requires correct bracket on fuel tank		06/08/2020		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	rattle in R/H/S door (top of door)		06/08/2020		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	R/H/S door blind will not stay down	RR's Pre Jan 2020 (system clean up) 04/08/20	06/08/2020		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	windscreen replacement from Obriens and Albury Daimler tristar		25/07/2020		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	completed at Daimler truck and bus albury	performed 320,000Kms service with valve resetm wiper blades replaced, brake pads replaced on axle 1 ,2 ,3	31/05/2020	321745	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	completed at Daimler truck and Bus		31/05/2020	321745	HCU	XV31BZ	Wodonga Workshop	P/MOVER
		-supply missing steer hub cap and fit to vehicle						
		-investigate reported loose tread plate, found tread plate on fuel tank had moved, loosen fuel tank straps, loosen tread plate from brackets, retensioned tread plate, tightened brackets, retension fuel						
1029	A service completed at Daimler trucks albury	tank straps	28/04/2020	286472	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	as per check list awaiting on service p/work		28/04/2020	286472	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		15/04/2020	1234	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		15/04/2020	276038	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		15/04/2020	276038	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		15/04/2020	276038	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	B SERVICE AS PER CHECLIST- TO ALIGN IT BACK TO SERVICE PLAN- AWAITING ON P/WORK		28/02/2020	240000	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	AS PER CHECKLIST		28/02/2020	240000	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	inspect & adjust turntable		27/02/2020	246288	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		06/02/2020	221143	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		06/02/2020	221143	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		06/02/2020	221143	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		06/02/2020	221143	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		31/01/2020	0	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	fix RH light and wire		29/01/2020		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	need to order RH side marker ligth	hartwigs for parts POww051175	24/01/2020		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	reposition RH tank step and remove rear tank step handle from RH side and mount onto front of LH tank step		11/01/2020	208925	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	CARRY OUT B SERVICE AT HARWIGS		04/01/2020	202768	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	AS PER CHECK LIST		04/01/2020	202768	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		28/12/2019	191007	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		28/12/2019	191007	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Swap turntable to low profile		14/12/2019	188257	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		12/12/2019	0	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	SWAP T/TABLE FROM 937		10/12/2019	183432	HCU	XV31BZ	Wodonga Workshop	P/MOVER
		HOOK A TRAILER UP TO T/207						
		& MEASURE						
1029	SPILT B TRAILER ON TO FANCE	1.62 METERS OVERLENGHT	10/12/2019	183432	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	replace fastener in walking plate		07/12/2019	182210	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	replace bolts fuel tanks		07/12/2019	182210	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	R/H/S clearance lights bracket still not replaced as per 111829 11/7/19		26/11/2019	171230	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	fuel tank strap R/H/S missing retaining bolt = replace and reposition fuel tank		26/11/2019	171230	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	no trailer lights		26/11/2019	171230	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	toolbox L/H/S release broken		26/11/2019	171230	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	checker plate fastener missing plate removed		26/11/2019	171230	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	PICK UP FROM HARTWIGS		24/11/2019	171230	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		23/11/2019	165880	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	A SERVICE CARRIED OUT BY HARTWIGS		17/11/2019	171214	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	AS PER CEHECKLIST		17/11/2019	171214	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		29/09/2019	117230	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	A SERVICE CARRIED OUT BY HARTWIGS		24/09/2019	121234	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	WHEEL ALIGNMENT CARRIED OUT BY HTT (MONDAY 23/9/2019)		24/09/2019	121234	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	AS PER CHECK LIST		24/09/2019	121234	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	L/H/S headlight blown		24/09/2019	121634	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	DROP OFF TO HUME TRUCK TEKNICS	PICK UP FROM HTT	24/09/2019	121634	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	fit new suzy coil bar (mark 3)		13/09/2019		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	changed RH headlight globe		06/09/2019	109893	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		01/09/2019	96620	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Service As Per Attached Checklist	RNR BOOK SIGNED OFF AND ENGINE TUNE	30/07/2019	64900	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	NEED TO ORDER SIDE CLEARANCE LIGHT		30/07/2019	64900	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	NEED TO ORDER RHS MIRROR MOTOR		30/07/2019	64900	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	AS PER CHECK LIST		30/07/2019	64900	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	light issues	HARTWIGS AH CALL OUT TO REPAIR ISSUE	25/06/2019	12038	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Issues with ABS lights not working- fault was coming from the trailers		25/06/2019	1502	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		20/06/2019	0	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Service As Per Attached Checklist		15/06/2019	36931	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029			15/06/2019	36931	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	fit rear-cab bar		12/06/2019		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		04/06/2019	0	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	fabricate air line bracket, for back of cab on prime mover		24/05/2019		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	pick up from Hartwigs		18/05/2019	18095	HCU	XV31BZ	Wodonga Workshop	P/MOVER
	drop off to Hartwigs for repairs							
1029	(front end has a gallop)		18/05/2019	18079	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	reposition suzi coils and repair		30/04/2019		HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		11/04/2019	0	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		11/04/2019	0	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		19/03/2019	0	HCU	XV31BZ	Wodonga Workshop	P/MOVER
1029	Job Added From Invoice		19/02/2019	0	HCU	XV31BZ	Wodonga Workshop	P/MOVER