Exodas Pty Ltd



Work Order History

| Asset | Registration | Work | Work Order | Service | RM | Task | Employee | Product | | W/H | Supplier | Invoice |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 2850 | 07/07/2016 | TRA | 1 | LABOUR | MECH | Labour | | | | |
| RPS25 | 989QWX | 2851 | 07/18/2016 | TRA | 1 | LABOUR | MECH | Labour | | | | |
| RPS25 | 989QWX | 2852 | 08/25/2016 | TRA | 1 | LABOUR | MECH | Labour | | | | |
| RPS25 | 989QWX | 2852 | 08/25/2016 | TRB | 1 | LABOUR | MECH | Labour | | | | |
| RPS25 | 989QWX | 2853 | 09/08/2016 | TRA | 1 | LABOUR | MECH | Labour | | | | |
| RPS25 | 989QWX | 2854 | 09/19/2016 | TRA | 1 | LABOUR | MECH | Labour | | | | |
| RPS25 | 989QWX | 2855 | 10/04/2016 | TRA | 1 | LABOUR | MECH | Labour | | | | |
| RPS25 | 989QWX | 2856 | 11/03/2016 | TRA | 1 | LABOUR | MECH | Labour | | | | |
| RPS25 | 989QWX | 2857 | 11/28/2016 | TRA | 1 | LABOUR | MECH | Labour | | | | |
| RPS25 | 989QWX | 2857 | 11/28/2016 | TRB | 1 | LABOUR | MECH | Labour | | | | |
| RPS25 | 989QWX | 2858 | 12/19/2016 | TRA | 1 | LABOUR | MECH | Labour | | | | |
| RPS25 | 989QWX | 2859 | 01/18/2017 | TRA | 1 | LABOUR | MECH | Labour | | | | |
| RPS25 | 989QWX | 2860 | 01/30/2017 | TRA | 1 | LABOUR | MECH | Labour | | | | |
| RPS25 | 989QWX | 3033 | 02/27/2017 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | | |
| RPS25 | 989QWX | 3033 | 02/27/2017 | TRA | 16 | CON | | YAT | Consumables | | | |
| RPS25 | 989QWX | 3033 | 02/27/2017 | TRA | CERVICE COMPLETED. WHEEL BEARING ADJUSTMENT CHECKED. | | | | | | | |
| RPS25 | 989QWX | 3525 | 04/10/2017 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | | |
| RPS25 | 989QWX | 3525 | 04/10/2017 | TRA | 16 | CON | | YAT | Consumables | | | |
| RPS25 | 989QWX | 3942 | 05/08/2017 | TYRES | 15 | STRFIT | | TYRMOR01 | | EX00001466 | | Strip & Fit, |
| RPS25 | 989QWX | 3942 | 05/08/2017 | TYRES | 15 | TYRDIS | | TYRMOR01 | | EX00001466 | | Tyre Disposal, |
| RPS25 | 989QWX | 3942 | 05/08/2017 | TYRES | 15 | STRFIT | | TYRMOR01 | | 12703 | | Strip & Fit, |
| RPS25 | 989QWX | 3942 | 05/08/2017 | TYRES | 15 | TYRDIS | | TYRMOR01 | | 12703 | | Tyre Disposal, |
| RPS25 | 989QWX | 4151 | 05/19/2017 | TRA | 1 | LABOUR | Labour | | | | | 0 |
| RPS25 | 989QWX | 4151 | 05/19/2017 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | | |
| RPS25 | 989QWX | 4151 | 05/19/2017 | TRA | 0 | LABOUR | TRADEA | Labour - Internal | | | | |
| RPS25 | 989QWX | 4151 | 05/19/2017 | TRA | 16 | CON | | YAT | Consumables | | | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | L2 NEEDS TYRES INNER IS SCALLOPED & OUTER IS SPLIT THROUGH TO CORDS REPLACED ALL SLACK ADJUSTERS GREASED NIPPLES OPENED TOOL BOX AND DISABLED LOCKS | | | | | | |
| RPS25 | 989QWX | 4151 | 05/19/2017 | TRA | FIRE EXT N/A | | | | | | |
| RPS25 | 989QWX | 4173 | 05/22/2017 | GEN | 15 | ZFIT | | TYRMOR01 | EX00001613 | TYRE FITTING, | |
| RPS25 | 989QWX | 4173 | 05/22/2017 | GEN | 15 | ZFIT | | TYRMOR01 | 12954 | TYRE FITTING, | |
| RPS25 | 989QWX | 5018 | 05/25/2017 | FRIVANA | 1 | LABOUR | Labour | | | 0 | |
| RPS25 | 989QWX | 5018 | 05/25/2017 | FRIVANA | ZERO DOLLAR WORK ORDER CREATED TO BRING SERVICING INTO LINE WITH QTK RECORDS 12/07/2017 | | | | | | |
| RPS25 | 989QWX | 5019 | 05/25/2017 | FRIVCAL | 1 | LABOUR | Labour | | | 0 | |
| RPS25 | 989QWX | 5019 | 05/25/2017 | FRIVCAL | ZERO DOLLAR WORK ORDER CREATED TO BRING SERVICING INTO LINE WITH QTK RECORDS 12/07/2017 | | | | | | |
| RPS25 | 989QWX | 4483 | 05/31/2017 | GEN | 35 | 130 | | QTKGRO01 | EX00001779 | ANNUAL SERVICE PERFORMED, | |
| RPS25 | 989QWX | 4483 | 05/31/2017 | GEN | 35 | 130 | | QTKGRO01 | SI-099157 | ANNUAL SERVICE PERFORMED, | |
| RPS25 | 989QWX | 4338 | 06/01/2017 | TYRES | 15 | 33000084 | | BRIAUS01 | EX00001705 | FIT TBR TYRE,NO CHARGE | |
| RPS25 | 989QWX | 4338 | 06/01/2017 | TYRES | 15 | 77000180 | | BRIAUS01 | EX00001705 | CASE STOCK 11-22.5,CREDIT | |
| RPS25 | 989QWX | 4338 | 06/01/2017 | TYRES | 15 | 33000084 | | BRIAUS01 | 4.42E+09 | FIT TBR TYRE,NO CHARGE | |
| RPS25 | 989QWX | 4338 | 06/01/2017 | TYRES | 15 | 77000180 | | BRIAUS01 | 4.42E+09 | CASE STOCK 11-22.5,CREDIT | |
| RPS25 | 989QWX | 4472 | 06/12/2017 | DEFECT | 1 | LABOUR | MECH | Labour | | | |
| RPS25 | 989QWX | 4472 | 06/12/2017 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 4472 | 06/12/2017 | TRA | 0 | LABOUR | TRADEA | Labour - Internal | | | |
| RPS25 | 989QWX | 4472 | 06/12/2017 | TRA | 16 | CON | | YAT | Consumables | | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 15142 | 06/16/2017 | BEARPK | 0 | LABOUR | MECH | Labour - Internal | | | |
| RPS25 | 989QWX | 4572 | 06/16/2017 | DEFECT | 1 | LABOUR | MECH | Labour | | | |
| RPS25 | 989QWX | 4573 | 06/16/2017 | DEFECT | 1 | LABOUR | MECH | Labour | | | |
| RPS25 | 989QWX | 4572 | 06/16/2017 | EXOINS | 1 | LABOUR | MECH | Labour | | | |
| RPS25 | 989QWX | 4572 | 06/16/2017 | EXOINS | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 4573 | 06/16/2017 | GEN | 39 | 2.57E+08 | | BROHUR01 | EX00001844 | Hub Seal, BPW, Eco Plus, | |
| RPS25 | 989QWX | 4573 | 06/16/2017 | GEN | 39 | 2.57E+08 | | BROHUR01 | 1142166 | Hub Seal, BPW, Eco Plus, | |
| RPS25 | 989QWX | 4573 | 06/16/2017 | TRA | 1 | LABOUR | MECH | Labour | | | |
| RPS25 | 989QWX | 4573 | 06/16/2017 | TRC | 1 | LABOUR | MECH | Labour | | | |
| RPS25 | 989QWX | 4573 | 06/16/2017 | TRC | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 4573 | 06/16/2017 | TRC | 0 | LABOUR | TRADEA | Labour - Internal | | | |
| RPS25 | 989QWX | 4573 | 06/16/2017 | TRC | 31 | ASA93-112 | | YAT | Air Fitting Bulkhead (Female) | | |
| RPS25 | 989QWX | 4573 | 06/16/2017 | TRC | 31 | ASA93-109 | | YAT | AirFitting Bulkhead (Male)1/2" | | |
| RPS25 | 989QWX | 4573 | 06/16/2017 | TRC | 11 | 2.57E+08 | | YAT | Hub Seal, BPW, Eco Plus | | |
| RPS25 | 989QWX | 4573 | 06/16/2017 | TRC | 2 | AIRBRAHOS | | YAT | Air Brake Hose | | |
| RPS25 | 989QWX | 4573 | 06/16/2017 | TRC | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 5141 | 07/20/2017 | TRA | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 5141 | 07/20/2017 | TRB | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 5141 | 07/20/2017 | TRB | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 5141 | 07/20/2017 | TRB | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 5141 | 07/20/2017 | TRB | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 5141 | 07/20/2017 | TRB | ADJUSTED WHEEL BEARINGS RETENSIO NED HUB CAPS REPAIRED TAIL GATE LIFTER FITTED FUEL TAG FAULT SLIP WORK - TOOL BOX ALREADY REPAIRED & A/C GAS LEAK ALREADY REPAIRED | | | | | | |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 5202 | 07/24/2017 | TRA | 1 | LABOUR | Labour | | | | | 0 |
| RPS25 | 989QWX | 5202 | 07/24/2017 | TRB | 1 | LABOUR | Labour | | | | | 0 |
| RPS25 | 989QWX | 5202 | 07/24/2017 | TRB | 0 | LABOUR | MECH1 | Labour - Internal | | | | |
| RPS25 | 989QWX | 5202 | 07/24/2017 | TRB | 16 | CON | | YAT | Consumables | | | |
| RPS25 | 989QWX | 5202 | 07/24/2017 | TRB | SERVICE COMPLETED. | | | | | | | |
| RPS25 | 989QWX | 5738 | 08/31/2017 | TRA | 1 | LABOUR | Labour | | | | | 0 |
| RPS25 | 989QWX | 5738 | 08/31/2017 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | | |
| RPS25 | 989QWX | 5738 | 08/31/2017 | TRA | 16 | CON | | YAT | Consumables | | | |
| RPS25 | 989QWX | 5738 | 08/31/2017 | TRA | FITTED REGO LABEL AND MAINTENANCE LABEL. | | | | | | | |
| RPS25 | 989QWX | 5738 | 08/31/2017 | TRA | 0 | LABOUR | MECH | Labour - Internal | | | | |
| RPS25 | 989QWX | 5992 | 09/14/2017 | TRA | 1 | LABOUR | MECH1 | Labour | | | | |
| RPS25 | 989QWX | 5992 | 09/14/2017 | TRB | 1 | LABOUR | MECH1 | Labour | | | | |
| RPS25 | 989QWX | 5992 | 09/14/2017 | TRB | 0 | LABOUR | MECH1 | Labour - Internal | | | | |
| RPS25 | 989QWX | 5992 | 09/14/2017 | TRB | 16 | CON | | YAT | Consumables | | | |
| RPS25 | 989QWX | 5992 | 09/14/2017 | TRB | SERVICE COMPLETED. | | | | | | | |
| RPS25 | 989QWX | 6015 | 09/15/2017 | TYRES | 15 | 33000241 | | BRIAUS01 | | EX00002713 | SCRAP TYRES TBR,RP25 | |
| RPS25 | 989QWX | 6015 | 09/15/2017 | TYRES | 15 | TYRRUN | | YAT | Tyre Runouts | | | |
| RPS25 | 989QWX | 6015 | 09/15/2017 | TYRES | FITTED 1X STEER RUN OUT. | | | | | | | |
| RPS25 | 989QWX | 6015 | 09/15/2017 | TYRES | 15 | 33000084 | | YAT | FIT TBR TYRE | | | |
| RPS25 | 989QWX | 6015 | 09/15/2017 | TYRES | 15 | 33000351 | | YAT | NWR N CASE - STAKED | | | |
| RPS25 | 989QWX | 6015 | 09/15/2017 | TYRES | 15 | 33000241 | | BRIAUS01 | | 4.42E+09 | SCRAP TYRES TBR,RP25 | |
| RPS25 | 989QWX | 6035 | 09/19/2017 | TYRES | | | | | | | | |
| RPS25 | 989QWX | 6035 | 09/19/2017 | TYRES | 15 | LABOUR | Labour | | | | | 0 |
| RPS25 | 989QWX | 6035 | 09/19/2017 | TYRES | 15 | 33000188 | | YAT | B FLEET PRESSURE CHECK | | | |
| RPS25 | 989QWX | 6035 | 09/19/2017 | TYRES | TYRES PRESSURE CHECKED. | | | | | | | |
| RPS25 | 989QWX | 6364 | 10/10/2017 | TRA | 1 | LABOUR | Labour | | | | | 0 |
| RPS25 | 989QWX | 6364 | 10/10/2017 | TRB | 1 | LABOUR | TRADEA | Labour | | | | |
| RPS25 | 989QWX | 6364 | 10/10/2017 | TRB | 16 | con | | YAT | Consumables | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 6364 | 10/10/2017 | TRB | COMPLETED. INSPECTED ALL SPRING EYE BUSHES, WHEEL BEARINGS, KING PIN. CHECKED TRAILER INTERNAL AND THE TAIL GATE LIFT. NO FAULTS FOUND. CHECKED WHEEL ALIGNMENT AND NO FAULT FOUND. FRIFGE DUE FOR | | | | | |
| RPS25 | 989QWX | 6581 | 10/20/2017 | FRIVANA | 1 | CON | QTKGRO01 | EX00003065 | Consumables ,RP25 |
| RPS25 | 989QWX | 6581 | 10/20/2017 | FRIVANA | 1 | LABEXT | QTKGRO01 | EX00003065 | Labour External,RP25 |
| RPS25 | 989QWX | 6581 | 10/20/2017 | FRIVANA | SERVICE COMPLETED BY QTK. | | | | |
| RPS25 | 989QWX | 6581 | 10/20/2017 | FRIVANA | 1 | LABEXT | QTKGRO01 | SI-108346 | Labour External,RP25 |
| RPS25 | 989QWX | 6581 | 10/20/2017 | FRIVANA | 1 | CON | QTKGRO01 | SI-108346 | Consumables ,RP25 |
| RPS25 | 989QWX | 8024 | 01/25/2018 | GEN | 39 | 15W40 | JC&SL01 | EX00004000 | ENGINE OIL,RP25 |
| RPS25 | 989QWX | 8024 | 01/25/2018 | GEN | 39 | COO | JC&SL01 | EX00004000 | Coolant Allcool K/worth ,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 8024 | 01/25/2018 | GEN | 39 | CON | | JC&SL01 | EX00004000 | Consumables ,RP25 |
| RPS25 | 989QWX | 8024 | 01/25/2018 | GEN | 39 | LABEXT | | JC&SL01 | EX00004000 | Labour External,RP25 |
| RPS25 | 989QWX | 8024 | 01/25/2018 | GEN | | SERVICE/INSPECTION COMPLETED BY JC & SL REFRIGERATION. CUSTOMER TO MONITOR ALGAE BUILD UP IN THE FUEL TANKS. | | | | |
| RPS25 | 989QWX | 8024 | 01/25/2018 | GEN | 39 | LABEXT | | JC&SL01 | 8129 | Labour External,RP25 |
| RPS25 | 989QWX | 8024 | 01/25/2018 | GEN | 39 | CON | | JC&SL01 | 8129 | Consumables ,RP25 |
| RPS25 | 989QWX | 8024 | 01/25/2018 | GEN | 39 | COO | | JC&SL01 | 8129 | Coolant Allcool K/worth ,RP25 |
| RPS25 | 989QWX | 8024 | 01/25/2018 | GEN | 39 | 15W40 | | JC&SL01 | 8129 | ENGINE OIL,RP25 |
| RPS25 | 989QWX | 7963 | 01/25/2018 | TRA | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 7963 | 01/25/2018 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | |
| RPS25 | 989QWX | 7963 | 01/25/2018 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 7963 | 01/25/2018 | TRA | 2 | AIRBRAHOS | | YAT | Air Brake Hose | |
| RPS25 | 989QWX | 7963 | 01/25/2018 | TRA | 16 | CON | | YAT | Consumables | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 7963 | 01/25/2018 | TRA | SERVICE COMPLETED. REPLACED 6 METRES OF BRAKE HOSE. TENSIONED S CAM BUSH BOLTS. | | | | | |
| RPS25 | 989QWX | 8695 | 03/09/2018 | WARRANT | | 39 | LABOUR | Labour - Internal | | 0 |
| RPS25 | 989QWX | 8695 | 03/09/2018 | WARRANT | TRAILER SALES ROCKLEA REPAIRED THE INTERNAL WATER LEAK ALONG THE LHS. | | | | | |
| RPS25 | 989QWX | 9069 | 04/05/2018 | DEFECT | Defect :- Defect Code : 00000577 Defect Reference : MRT 6315 MRT Date : 10/10/2017 Description of Defect : TRAILER VERY LOOSE ON THE ROAD. PUSHES THE PRIME MOVER AROUND ALL NEW BUSHES FITTED | 1 | LABOUR | MECH | Labour | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 9069 | 04/05/2018 | TRA | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 9069 | 04/05/2018 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 9069 | 04/05/2018 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 9069 | 04/05/2018 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 9069 | 04/05/2018 | TRA | SERVICE COMPLETED. | | | | | | |
| RPS25 | 989QWX | 9207 | 04/09/2018 | GEN | 39 | COO | | JC&SL01 | | EX00004755 | Coolant Allcool K/worth ,RP25 |
| RPS25 | 989QWX | 9207 | 04/09/2018 | GEN | 39 | SUND | | JC&SL01 | | EX00004755 | SUNDRIES, |
| RPS25 | 989QWX | 9207 | 04/09/2018 | GEN | 39 | LABEXT | | JC&SL01 | | EX00004755 | Labour External,RP25 |
| RPS25 | 989QWX | 9207 | 04/09/2018 | GEN | REFRIGERATION CARRIED OUT REPAIRS AT THEIR CRESTMEAD SITE. DIAGNOSED FAILED EVAPORATOR FAN CENTRE. CODES CLEARED, NO FAN FITTED, TRAILER HAD TO GO FOR LOADING. SENT BACK IN TO SERVICE AS PER INSTRUCTI | | | | | | |
| RPS25 | 989QWX | 9207 | 04/09/2018 | GEN | 39 | LABEXT | | JC&SL01 | | 8410 | Labour External,RP25 |
| RPS25 | 989QWX | 9207 | 04/09/2018 | GEN | 39 | SUND | | JC&SL01 | | 8410 | SUNDRIES, |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | Coolant<br>Allcool<br>K/worth |
| RPS25 | 989QWX | 9207 | 04/09/2018 | GEN | 39 | COO | JC&SL01 | 8410 | ,RP25 |
| RPS25 | 989QWX | 9189 | 04/11/2018 | TYRES | 15 | 33000241 | BRIAUS01 | EX00004734 | SCRAP TYRES TBR,RP25 |
| RPS25 | 989QWX | 9189 | 04/11/2018 | TYRES | 15 | 77000232 | BRIAUS01 | EX00004734 | CASE STOCK 11R22.5 ECOPIA, |
| RPS25 | 989QWX | 9189 | 04/11/2018 | TYRES | 15 | 33000084 | YAT | FIT TBR TYRE | |
| RPS25 | 989QWX | 9189 | 04/11/2018 | TYRES | 15 | 33000355 | YAT | NWR N CASE - WORN TOO FAR | |
| RPS25 | 989QWX | 9189 | 04/11/2018 | TYRES | 15 | TYRRUN | YAT | Tyre Runouts | |
| RPS25 | 989QWX | 9189 | 04/11/2018 | TYRES | 15 | 11001464 | YAT | TYRE 11R22.5 148/145L 16 BS R187 | |
| RPS25 | 989QWX | 9189 | 04/11/2018 | TYRES | 15 | 33000241 | BRIAUS01 | 4.42E+09 | SCRAP TYRES TBR,RP25 |
| RPS25 | 989QWX | 9189 | 04/11/2018 | TYRES | 15 | 77000232 | BRIAUS01 | 4.42E+09 | CASE STOCK 11R22.5 ECOPIA, |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | 15W40 | JC&SL01 | EX00004787 | ENGINE OIL,RP25 |
| | | | | | | | | | Coolant<br>Allcool<br>K/worth |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | COO | JC&SL01 | EX00004787 | , |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | Nov-42 | JC&SL01 | EX00004787 | FUEL FILTER, FRIDGE MOTOR, |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | Nov-82 | JC&SL01 | EX00004787 | OIL FILTER, FRIDGE MOTOR, |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | 119300 | JC&SL01 | EX00004787 | QTK Fridge A/Filter EMI 3000, |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | 78-1886 | JC&SL01 | EX00004787 | FAN BLOWER MOTOR 14V, |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | COIL | JC&SL01 | EX00004787 | COIL CLEAN, EVAPORATOR/CONDENSOR, |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | SUND | JC&SL01 | EX00004787 | SUNDRIES, |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | LABEXT | JC&SL01 | EX00004787 | Labour External, |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | SERVICE AND REPAIRS COMPLETED BY JC & SL REFRIGERATION. S/F A NEW BLOWER MOTOR. | | | | |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | LABEXT | JC&SL01 | 8422 | Labour External, |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | SUND | JC&SL01 | 8422 | SUNDRIES, |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | COIL | JC&SL01 | 8422 | COIL CLEAN, EVAPORATOR/CONDENSOR, |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | 78-1886 | JC&SL01 | 8422 | FAN BLOWER MOTOR 14V, |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | 119300 | JC&SL01 | 8422 | QTK Fridge A/Filter EMI 3000, |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | Nov-82 | JC&SL01 | 8422 | OIL FILTER, FRIDGE MOTOR, |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | Nov-42 | JC&SL01 | 8422 | FUEL FILTER, FRIDGE MOTOR, |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | | Coolant Allcool K/worth |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | COO | | JC&SL01 | | 8422 | , |
| RPS25 | 989QWX | 9270 | 04/12/2018 | FRIVANSE | 1 | 15W40 | | JC&SL01 | | 8422 | ENGINE OIL,RP25 |
| RPS25 | 989QWX | 9692 | 05/03/2018 | TRA | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 9692 | 05/03/2018 | TRB | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 9692 | 05/03/2018 | TRB | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 9692 | 05/03/2018 | TRB | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 9692 | 05/03/2018 | TRB | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 9692 | 05/03/2018 | TRB | SERVICE COMPLETED. CHECKED ALL WHEEL BEARING. RHF AXLE RING & LOCK TAB. | | | | | | |
| RPS25 | 989QWX | 9633 | 05/09/2018 | TRA | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 9633 | 05/09/2018 | TRB | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 9633 | 05/09/2018 | TRB | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 9633 | 05/09/2018 | TRB | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 9633 | 05/09/2018 | TRB | SERVICE COMPLETED. | | | | | | |
| RPS25 | 989QWX | 10032 | 05/30/2018 | TYRES | | | | | | | |
| RPS25 | 989QWX | 10032 | 05/30/2018 | TYRES | 15 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 10032 | 05/30/2018 | TYRES | 15 | 33000188 | | YAT | B FLEET PRESSURE CHECK | | |
| RPS25 | 989QWX | 10258 | 05/31/2018 | FRIVANA | 1 | SUND | | JC&SL01 | | EX00005409 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 10258 | 05/31/2018 | FRIVANA | 1 | LABEXT | | JC&SL01 | | EX00005409 | Labour External,RP25 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 10258 | 05/31/2018 | FRIVANA | JC & SL REFRIGERATION COMPLETED THE SERVICE/REPAIRS. HEATER CIRCUIT WAS NOT WORKING REMOVED, CLEANED CONTACTS, REFITTED, TESTED AND ALL OK. | | | | | | |
| RPS25 | 989QWX | 10258 | 05/31/2018 | FRIVANA | | 1 | LABEXT | | JC&SL01 | 8596 | Labour External,RP25 |
| RPS25 | 989QWX | 10258 | 05/31/2018 | FRIVANA | | 1 | SUND | | JC&SL01 | 8596 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 10194 | 06/07/2018 | TRA | | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 10194 | 06/07/2018 | TRA | | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 10194 | 06/07/2018 | TRA | | 0 | LABOUR | TRADEA | Labour - Internal | | |
| RPS25 | 989QWX | 10194 | 06/07/2018 | TRA | | 16 | CON | | YAT Consumables | | |
| RPS25 | 989QWX | 10194 | 06/07/2018 | TRA | SERVICE COMPLETED. REPAIRED POGO RAIL, 2 SECTIONS. | | | | | | |
| RPS25 | 989QWX | 10374 | 06/11/2018 | GEN | | 39 | SUND | | JC&SL01 | EX00005476 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 10374 | 06/11/2018 | GEN | | 39 | LABEXT | | JC&SL01 | EX00005476 | Labour External,RP25 |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 10374 | 06/11/2018 | GEN | JC&SL REFRIGERATION CALLED TOO SITE, CODE 15. DIAGNOSED BAD GROUND CIRCUIT. CLEANED TERMINAL AND RECONNECTED. | | | | | | | |
| RPS25 | 989QWX | 10374 | 06/11/2018 | GEN | | 39 | SUND | | JC&SL01 | | 8635 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 10374 | 06/11/2018 | GEN | | 39 | LABEXT | | JC&SL01 | | 8635 | Labour External,RP25 |
| RPS25 | 989QWX | 10548 | 06/26/2018 | TYRES | | | | | | | | |
| RPS25 | 989QWX | 10548 | 06/26/2018 | TYRES | | 15 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 10548 | 06/26/2018 | TYRES | | 15 | 33000188 | | YAT | B FLEET PRESSURE CHECK | | |
| RPS25 | 989QWX | 10638 | 07/02/2018 | TRA | | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 10638 | 07/02/2018 | TRA | | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 10638 | 07/02/2018 | TRA | | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 10638 | 07/02/2018 | TRA | | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 10638 | 07/02/2018 | TRA | SERVICE COMPLETED. TIGHTENED BOTH AIR TANKS. FITTED SAFETY LATCH TO FRIDGE DOOR. | | | | | | | |
| RPS25 | 989QWX | 10638 | 07/02/2018 | TRA | | 13 | 37-41-295-60 | | YAT | HOOD HOLD DOWN LATCH | | |
| RPS25 | 989QWX | 11017 | 07/09/2018 | FRIVANA | | 1 | COO | | JC&SL01 | | EX00005839 | Coolant Allcool K/worth ,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 11017 | 07/09/2018 | FRIVANA | 1 | SUND | | JC&SL01 | EX00005839 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 11017 | 07/09/2018 | FRIVANA | 1 | LABEXT | | JC&SL01 | EX00005839 | Labour External,RP25 |
| RPS25 | 989QWX | 11017 | 07/09/2018 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 11017 | 07/09/2018 | FRIVANA | 1 | LABEXT | | JC&SL01 | 8741 | Labour External,RP25 |
| RPS25 | 989QWX | 11017 | 07/09/2018 | FRIVANA | 1 | SUND | | JC&SL01 | 8741 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 11017 | 07/09/2018 | FRIVANA | 1 | COO | | JC&SL01 | 8741 | Coolant Allcool K/worth ,RP25 |
| RPS25 | 989QWX | 11017 | 07/09/2018 | GEN | 39 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 10858 | 07/16/2018 | DEFECT | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 10858 | 07/16/2018 | DEFECT | Reported Defect :- Defect Code : 00001506 Defect Reference : 05752 Date : 13/07/2018 Description of Defect : TAILGATE LOADER WONT SLIDE FORWARD OR BACK WITHOUT JAMMING ON THE CHASSIS. NEW MAGNETIC VALVE FITTED. | | | | | |
| RPS25 | 989QWX | 10858 | 07/16/2018 | GEN | 39 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 10858 | 07/16/2018 | GEN | 39 | PART | | QTKGRO01 | EX00005735 | VALVE, TAILGATE,RP25 |
| RPS25 | 989QWX | 10858 | 07/16/2018 | GEN | 0 | LABOUR | MECH | Labour - Internal | | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 10858 | 07/16/2018 | GEN | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 10858 | 07/16/2018 | GEN | REPAIRED TAILGAT LIFTER FUNCTION. | | | | | | |
| RPS25 | 989QWX | 10858 | 07/16/2018 | GEN | 39 | PART | | QTKGRO01 | | SI-126243 | VALVE, TAILGATE,RP25 |
| RPS25 | 989QWX | 10931 | 07/19/2018 | DEFECT | 1 | LABOUR | MECH | Labour | | | |
| RPS25 | 989QWX | 10931 | 07/19/2018 | DEFECT | Reported Defect :- Defect Code : 00001506 Defect Reference : 05752 Date : 13/07/2018 Description of Defect : TAILGATE LOADER WONT SLIDE FORWARD OR BACK WITHOUT JAMMING ON THE CHASSIS. REPAIRED ON 16TH JULY 2018 | | | | | | |
| RPS25 | 989QWX | 10932 | 07/19/2018 | EXOINS | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 10932 | 07/19/2018 | EXOINS | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 10932 | 07/19/2018 | EXOINS | PASSED | | | | | | |
| RPS25 | 989QWX | 10931 | 07/19/2018 | TRA | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 10931 | 07/19/2018 | TRB | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 10931 | 07/19/2018 | TRC | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 10931 | 07/19/2018 | TRC | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 10931 | 07/19/2018 | TRC | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 11117 | 07/23/2018 | GEN | 39 | SUND | | JC&SL01 | | EX00005912 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 11117 | 07/23/2018 | GEN | 39 | LABEXT | | JC&SL01 | | EX00005912 | Labour External,RP25 |
| RPS25 | 989QWX | 11117 | 07/23/2018 | GEN | ALARM 15, UNIT WOULD NOT COMMUNICATE FOR DOWNLOAD LOCATED FAULT IN WIRING IN CONTROL BOX, REPAIR WIRING, DOWNLOAD UNIT, CHECK OUT A | | | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 11117 | 07/23/2018 | GEN | 39 | LABEXT | | JC&SL01 | 8783 | Labour External,RP25 |
| RPS25 | 989QWX | 11117 | 07/23/2018 | GEN | 39 | SUND | | JC&SL01 | 8783 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 11350 | 08/06/2018 | GEN | 39 | SUND | | JC&SL01 | EX00006063 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 11350 | 08/06/2018 | GEN | 39 | LABEXT | | JC&SL01 | EX00006063 | Labour External,RP25 |
| RPS25 | 989QWX | 11350 | 08/06/2018 | GEN | A SERVICE COMPLETED BY JC & SL ALARM 15 - LOST POWER, RELAY FAULT, TO MONITOR - MICK | | | | | |
| RPS25 | 989QWX | 11350 | 08/06/2018 | GEN | 39 | LABEXT | | JC&SL01 | 8827 | Labour External,RP25 |
| RPS25 | 989QWX | 11350 | 08/06/2018 | GEN | 39 | SUND | | JC&SL01 | 8827 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 11473 | 08/20/2018 | GEN | 39 | LABEXT | | VAWAUS01 | EX00006139 | Labour External,RP25 |
| RPS25 | 989QWX | 11473 | 08/20/2018 | GEN | 39 | CON | | VAWAUS01 | EX00006139 | CONSUMABLES/ENVIRO CHARGES,RP25 |
| RPS25 | 989QWX | 11473 | 08/20/2018 | GEN | 39 | 3.48E+09 | | VAWAUS01 | EX00006139 | BPW - A/BAG D36,RP25 |
| RPS25 | 989QWX | 11473 | 08/20/2018 | GEN | R&R LHS & RHS FRONT AIRBAGS | | | | | |
| RPS25 | 989QWX | 11473 | 08/20/2018 | GEN | 39 | 3.48E+09 | | VAWAUS01 | Q14632 | BPW - A/BAG D36,RP25 |
| RPS25 | 989QWX | 11473 | 08/20/2018 | GEN | 39 | CON | | VAWAUS01 | Q14632 | CONSUMABLES/ENVIRO CHARGES,RP25 |
| RPS25 | 989QWX | 11473 | 08/20/2018 | GEN | 39 | LABEXT | | VAWAUS01 | Q14632 | Labour External,RP25 |
| RPS25 | 989QWX | 11591 | 08/28/2018 | EXOINS | 1 | LABOUR | Labour | | | 0 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | PASSED 2ND INSPECTION - REGO LABEL NO ONGER REQUIRED | | | | | |
| | | | | | FAILED 1ST INSPECTION - REGO LABEL | | | | | |
| RPS25 | 989QWX | 11591 | 08/28/2018 | EXOINS | EXPIRED | | | | | |
| RPS25 | 989QWX | 11590 | 08/28/2018 | TRA | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 11590 | 08/28/2018 | TRB | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 11590 | 08/28/2018 | TRC | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 11590 | 08/28/2018 | TRC | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 11590 | 08/28/2018 | TRC | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 11590 | 08/28/2018 | TRC | 16 | CON | | YAT | Consumables | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 11590 | 08/28/2018 | TRC | COMPLETED PIECE MISSING INSIDE VERY FRONT OF VAN BELOW MESH LIGHT PLUG NEEDS REPLACING ON FRONT OF TRAILER, STILL WORKING THE CLIP IS LOOSE REGO LABEL HAS EXPIRED - NEED TO ORDER A | | | | | |
| RPS25 | 989QWX | 11790 | 08/29/2018 | FRIVANA | | 1 | PART | JC&SL01 | EX00006335 | SR2 INTERFACE BOARD NEWX,RP25 |
| RPS25 | 989QWX | 11790 | 08/29/2018 | FRIVANA | | 1 | SUND | JC&SL01 | EX00006335 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 11790 | 08/29/2018 | FRIVANA | | 1 | LABEXT | JC&SL01 | EX00006335 | Labour External,RP25 |
| RPS25 | 989QWX | 11790 | 08/29/2018 | FRIVANA | FRIDGE A SERVICE COMPLETED R&R INTERFACE BOARD | | | | | |
| RPS25 | 989QWX | 11790 | 08/29/2018 | FRIVANA | | 1 | PART | JC&SL01 | 8913 | SR2 INTERFACE BOARD NEWX,RP25 |
| RPS25 | 989QWX | 11790 | 08/29/2018 | FRIVANA | | 1 | SUND | JC&SL01 | 8913 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 11790 | 08/29/2018 | FRIVANA | | 1 | LABEXT | JC&SL01 | 8913 | Labour External,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 11986 | 09/18/2018 | GEN | | 39 | COO | | JC&SL01 | EX00006464 | Coolant Allcool K/worth ,RP25 |
| RPS25 | 989QWX | 11986 | 09/18/2018 | GEN | | 39 | SS70ZZM | | JC&SL01 | EX00006464 | Battery 12v,RP25 |
| RPS25 | 989QWX | 11986 | 09/18/2018 | GEN | | 39 | SUND | | JC&SL01 | EX00006464 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 11986 | 09/18/2018 | GEN | | 39 | LABEXT | | JC&SL01 | EX00006464 | Labour External,RP25 |
| RPS25 | 989QWX | 11986 | 09/18/2018 | GEN | CODE 61 - FOUND BATTERY HAD LOW VOLTAGE, R&R FAULTY BATTERY FOUND AIR FILTER BRACKET BROKEN OFF MOUNT, FABRICATED NEW BRACKET, TIGHTENED BELTS, TOPPED UP COOLANT, RAN PRE TRIP | | | | | | |
| RPS25 | 989QWX | 11986 | 09/18/2018 | GEN | | 39 | LABEXT | | JC&SL01 | 8958 | Labour External,RP25 |
| RPS25 | 989QWX | 11986 | 09/18/2018 | GEN | | 39 | SUND | | JC&SL01 | 8958 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 11986 | 09/18/2018 | GEN | | 39 | SS70ZZM | | JC&SL01 | 8958 | Battery 12v,RP25 |
| RPS25 | 989QWX | 11986 | 09/18/2018 | GEN | | 39 | COO | | JC&SL01 | 8958 | Coolant Allcool K/worth ,RP25 |
| RPS25 | 989QWX | 12043 | 09/27/2018 | DEFECT | | 1 | LABOUR | MECH | Labour | | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 12043 | 09/27/2018 | DEFECT | Reported Defect :- Defect Code : 00001629 Defect Reference : W/O1350 Date : 06/08/2018 Description of Defect : ALARM 15 - LOST POWER, RELAY FAULT, TO MONITOR - MICK . COULDN'T FAULT |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 12043 | 09/27/2018 | DEFECT | Defect :- Defect Code : 00001724 Defect Reference : W/O11590 Date : 28/08/2018 Description of Defect : LIGHT PLUG NEEDS REPLACING ON FRONT OF TRAILER, STILL WORKING THE CLIP IS LOOSE REPLACED |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 12043 | 09/27/2018 | DEFECT | Reported Defect :- Defect Code : 00001723 Defect Reference : W/O11590 Date : 28/08/2018 Description of Defect : PIECE MISSING INSIDE VERY FRONT OF VAN BELOW MESH COULDN'T FAULT |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 12043 | 09/27/2018 | DEFECT | Reported Defect :- Defect Code : 00001725 Defect Reference : W/O11590 Date : 28/08/2018 Description of Defect : REGO LABEL HAS EXPIRED - NEED TO ORDER A NEW ONE NOT REQUIRED | | | | | | |
| RPS25 | 989QWX | 12043 | 09/27/2018 | TRA | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 12043 | 09/27/2018 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 12043 | 09/27/2018 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 12043 | 09/27/2018 | TRA | 13 | 82062 | | YAT | 7 | Pin Female Trailer Plug | |
| RPS25 | 989QWX | 12043 | 09/27/2018 | TRA | 16 | CON | | YAT | | Consumables | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 12043 | 09/27/2018 | TRA | SERVICE COMPLETED REPLACED LIGHT PLUG REPAIRED WARNING LIGHT ON TAIL GATE LIFTER | | | | | |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | 15W40 | JC&SL01 | EX00006555 | ENGINE OIL,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | PART | JC&SL01 | EX00006555 | BELT,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | 78-0629 | JC&SL01 | EX00006555 | SB series fridge motor fanbelt,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | 78-0603 | JC&SL01 | EX00006555 | SB Series Fridge motor fanbelt,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | Nov-82 | JC&SL01 | EX00006555 | OIL FILTER, FRIDGE MOTOR,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | Nov-42 | JC&SL01 | EX00006555 | FUEL FILTER, FRIDGE MOTOR,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | 119300 | JC&SL01 | EX00006555 | QTK Fridge A/Filter EMI 3000,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | COIL | JC&SL01 | EX00006555 | COIL CLEAN, EVAPORATOR/CONDENSOR,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | SUND | JC&SL01 | EX00006555 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | LABEXT | JC&SL01 | EX00006555 | Labour External,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | SERVICE COMPLETED CHANGED ALL FILTERS, OILS & FLUIDS | | | | | |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | LABEXT | JC&SL01 | 8986 | Labour External,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | SUND | JC&SL01 | 8986 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | COIL | JC&SL01 | 8986 | COIL CLEAN, EVAPORATOR/CONDENSOR,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | 119300 | JC&SL01 | 8986 | QTK Fridge A/Filter EMI 3000,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | Nov-42 | JC&SL01 | 8986 | FUEL FILTER, FRIDGE MOTOR,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | Nov-82 | JC&SL01 | 8986 | OIL FILTER, FRIDGE MOTOR,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | 78-0603 | JC&SL01 | 8986 | SB Series Fridge motor fanbelt,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | 78-0629 | JC&SL01 | 8986 | SB series fridge motor fanbelt,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | PART | JC&SL01 | 8986 | BELT,RP25 |
| RPS25 | 989QWX | 12133 | 09/28/2018 | FRIVANSE | | 1 | 15W40 | JC&SL01 | 8986 | ENGINE OIL,RP25 |
| RPS25 | 989QWX | 12100 | 09/28/2018 | TYRES | | 15 | 77000180 | BRIAUS01 | EX00006539 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 12100 | 09/28/2018 | TYRES | | 15 | 11001464 | YAT | TYRE 11R22.5 148/145L 16 BS R187 | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 12100 | 09/28/2018 | TYRES | R&R TYRES | | | | | | |
| RPS25 | 989QWX | 12100 | 09/28/2018 | TYRES | 15 | 77000180 | | BRIAUS01 | | 96146006 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 12457 | 10/22/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | EX00006776 | Labour External,RP25 |
| RPS25 | 989QWX | 12457 | 10/22/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | EX00006776 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 12457 | 10/22/2018 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 12457 | 10/22/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | 18324 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 12457 | 10/22/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | 18324 | Labour External,RP25 |
| RPS25 | 989QWX | 12551 | 10/26/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | EX00006833 | Labour External,RP25 |
| RPS25 | 989QWX | 12551 | 10/26/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | EX00006833 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 12551 | 10/26/2018 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 12551 | 10/26/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | 18349 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 12551 | 10/26/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | 18349 | Labour External,RP25 |
| RPS25 | 989QWX | 12735 | 11/02/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | EX00006923 | Labour External,RP25 |
| RPS25 | 989QWX | 12735 | 11/02/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | EX00006923 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 12735 | 11/02/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | 18415 | Labour External,RP25 |
| RPS25 | 989QWX | 12735 | 11/02/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | 18415 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 12786 | 11/12/2018 | TRA | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 12786 | 11/12/2018 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 12786 | 11/12/2018 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 12786 | 11/12/2018 | TRA | SERVICE COMPLETED REPLACED 2X RUBBED THROUGH BRAKE HOSES | | | | | | |
| RPS25 | 989QWX | 12969 | 11/13/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | EX00007038 | Labour External,RP25 |
| RPS25 | 989QWX | 12969 | 11/13/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | EX00007038 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 12969 | 11/13/2018 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 12969 | 11/13/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | 18516 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 12969 | 11/13/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | 18516 | Labour External,RP25 |
| RPS25 | 989QWX | 12799 | 11/13/2018 | TYRES | 15 | 77000180 | | BRIAUS01 | | EX00006964 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 12799 | 11/13/2018 | TYRES | 15 | 11001464 | | YAT | TYRE 11R22.5 148/145L 16 BS R187 | | |
| RPS25 | 989QWX | 12799 | 11/13/2018 | TYRES | R&R TYRES | | | | | | |
| RPS25 | 989QWX | 12799 | 11/13/2018 | TYRES | 15 | 77000180 | | BRIAUS01 | | 96292256 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 13217 | 11/26/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | EX00007183 | Labour External,RP25 |
| RPS25 | 989QWX | 13217 | 11/26/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | EX00007183 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 13217 | 11/26/2018 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 13217 | 11/26/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | 18621 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 13217 | 11/26/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | 18621 | Labour External,RP25 |
| RPS25 | 989QWX | 13386 | 12/04/2018 | FRIVANA | 1 | R404A | | RIXREF01 | | EX00007287 | GAS R404A,RP25 |
| RPS25 | 989QWX | 13386 | 12/04/2018 | FRIVANA | 1 | PART | | RIXREF01 | | EX00007287 | DRIVE,RP25 |
| RPS25 | 989QWX | 13386 | 12/04/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | EX00007287 | Labour External,RP25 |
| RPS25 | 989QWX | 13386 | 12/04/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | EX00007287 | SUNDRIES,P25 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 13386 | 12/04/2018 | FRIVANA | SERVICE COMPLETED R&R OIL PUMP DRIVE KEY REPLACED DRIVE TOPPED GAS | | | | | | |
| RPS25 | 989QWX | 13386 | 12/04/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | 18700 | SUNDRIES,P25 |
| RPS25 | 989QWX | 13386 | 12/04/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | 18700 | Labour External,RP25 |
| RPS25 | 989QWX | 13386 | 12/04/2018 | FRIVANA | 1 | PART | | RIXREF01 | | 18700 | DRIVE,RP25 |
| RPS25 | 989QWX | 13386 | 12/04/2018 | FRIVANA | 1 | R404A | | RIXREF01 | | 18700 | GAS R404A,RP25 |
| RPS25 | 989QWX | 13645 | 12/12/2018 | FRIVANA | 1 | PART | | RIXREF01 | | EX00007410 | MANIFOLD GASKET,RP25 |
| RPS25 | 989QWX | 13645 | 12/12/2018 | FRIVANA | 1 | PART | | RIXREF01 | | EX00007410 | TAPPET COVER GASKET,RP25 |
| RPS25 | 989QWX | 13645 | 12/12/2018 | FRIVANA | 1 | PART | | RIXREF01 | | EX00007410 | INJECTOR PUMP ORING,RP25 |
| RPS25 | 989QWX | 13645 | 12/12/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | EX00007410 | Labour External,RP25 |
| RPS25 | 989QWX | 13645 | 12/12/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | EX00007410 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 13645 | 12/12/2018 | FRIVANA | SERVICE COMPLETED R&R MANIFOLD GASKET, TAPPET COVER GASKET, INJECTOR PUMP ORING | | | | | | |
| RPS25 | 989QWX | 13645 | 12/12/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | 18741 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 13645 | 12/12/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | 18741 | Labour External,RP25 |
| RPS25 | 989QWX | 13645 | 12/12/2018 | FRIVANA | 1 | PART | | RIXREF01 | | 18741 | INJECTOR PUMP ORING,RP25 |
| RPS25 | 989QWX | 13645 | 12/12/2018 | FRIVANA | 1 | PART | | RIXREF01 | | 18741 | TAPPET COVER GASKET,RP25 |
| RPS25 | 989QWX | 13645 | 12/12/2018 | FRIVANA | 1 | PART | | RIXREF01 | | 18741 | MANIFOLD GASKET,RP25 |
| RPS25 | 989QWX | 13395 | 12/12/2018 | TRA | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 13395 | 12/12/2018 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 13395 | 12/12/2018 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 13395 | 12/12/2018 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 13395 | 12/12/2018 | TRA | 13 | FQ0211 | | YAT | MUDGUARD OFFSET MOUNTING BRACKET | | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 13395 | 12/12/2018 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 13395 | 12/12/2018 | TRA | SERVICE COMPLETED REPLACED FRONT AXLE MUD FLAP HOLDER AS REQUIRED | | | | | | |
| RPS25 | 989QWX | 13655 | 12/14/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | EX00007413 | Labour External,RP25 |
| RPS25 | 989QWX | 13655 | 12/14/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | EX00007413 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 13655 | 12/14/2018 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 13655 | 12/14/2018 | FRIVANA | 1 | SUND | | RIXREF01 | | 18847 | SUNDRIES,RP25 |
| RPS25 | 989QWX | 13655 | 12/14/2018 | FRIVANA | 1 | LABEXT | | RIXREF01 | | 18847 | Labour External,RP25 |
| RPS25 | 989QWX | 14278 | 01/18/2019 | FRIVANA | 1 | LABEXT | | BRIVAL01 | | EX00007734 | Labour External,RP25 |
| RPS25 | 989QWX | 14278 | 01/18/2019 | FRIVANA | 1 | CON | | BRIVAL01 | | EX00007734 | Consumables,RP25 |
| RPS25 | 989QWX | 14278 | 01/18/2019 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 14278 | 01/18/2019 | FRIVANA | 1 | CON | | BRIVAL01 | | 47 | Consumables,RP25 |
| RPS25 | 989QWX | 14278 | 01/18/2019 | FRIVANA | 1 | LABEXT | | BRIVAL01 | | 47 | Labour External,RP25 |
| RPS25 | 989QWX | 14147 | 01/22/2019 | DEFECT | 1 | LABOUR | MECH | Labour | | | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 14147 | 01/22/2019 | DEFECT | Reported Defect :- Defect Code : 00002018 Defect Reference : INTERNAL Date : 16/11/2018 Description of Defect : LONG VEHICLE SIGN TO BE FITTED FITTED |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 14147 | 01/22/2019 | DEFECT | Reported Defect :- Defect Code : 00002170 Defect Reference : 12186 Date : 04/01/2019 Description of Defect : ALARM 3 - ZONE 2 ALARM 11 - ZONE 2 COULDN'T FAULT |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 14147 | 01/22/2019 | DEFECT | Reported Defect :- Defect Code : 00002235 Defect Reference : 12186 Date : 04/01/2019 Description of Defect : ALARM 3 ZONE 2 ALARM 11 ZONE 2 COULDN'T FAULT | | | | | | |
| RPS25 | 989QWX | 14147 | 01/22/2019 | TRA | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 14147 | 01/22/2019 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 14147 | 01/22/2019 | TRA | 13 | C1XT009-2EM | | YAT | LONG VEHICLE, METAL SIGN | | |
| RPS25 | 989QWX | 14147 | 01/22/2019 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 14147 | 01/22/2019 | TRA | SERVICE COMPLETED MADE & FITTED LONG VEHICLE SIGN BRACKETS & SIGNS | | | | | | |
| RPS25 | 989QWX | 14499 | 01/23/2019 | FRIVANA | 1 | FLECHE | | BRIVAL01 | | EX00007880 | FLEET CHECK LABOUR/CONS,RP25 |
| RPS25 | 989QWX | 14499 | 01/23/2019 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 14499 | 01/23/2019 | FRIVANA | 1 | FLECHE | | BRIVAL01 | | 75 | FLEET CHECK LABOUR/CONS,RP25 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | 1 | 45-2699 | | BRIVAL01 | | EX00007808 | ALTERNATOR 120A NO FAN,RP25 |
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | 1 | 78-629 | | BRIVAL01 | | EX00007808 | BELT,RP25 |
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | 1 | 78-603 | | BRIVAL01 | | EX00007808 | SB Fridge Fan belt,RP25 |
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | 1 | 78-1360 | | BRIVAL01 | | EX00007808 | ALTERNATOR BELT FRIDGE,RP25 |
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | 1 | CON | | BRIVAL01 | | EX00007808 | Consumables,RP25 |
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | 1 | LABEXT | | BRIVAL01 | | EX00007808 | Labour External,RP25 |
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | 13 | 91-0372 | | YAT | CLAMP TUBE, FRIDGE MOTOR | | |
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | 40 | 3413005 | | YAT | OIL 15W-40, CK 4/E9 | | |
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | SERVICE COMPLETED R&R ALL BELTS, U/S NOISY ALTERNATOR CALIBRATED UNIT | | | | | | |
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | 1 | LABEXT | | BRIVAL01 | | 72 | Labour External,RP25 |
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | 1 | CON | | BRIVAL01 | | 72 | Consumables,RP25 |
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | 1 | 78-1360 | | BRIVAL01 | | 72 | ALTERNATOR BELT FRIDGE,RP25 |
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | 1 | 78-603 | | BRIVAL01 | | 72 | SB Fridge Fan belt,RP25 |
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | 1 | 78-629 | | BRIVAL01 | | 72 | BELT,RP25 |
| RPS25 | 989QWX | 14385 | 01/23/2019 | FRIVANSE | 1 | 45-2699 | | BRIVAL01 | | 72 | ALTERNATOR 120A NO FAN,RP25 |
| RPS25 | 989QWX | 14577 | 01/30/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00007913 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 14588 | 01/30/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00007917 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 14577 | 01/30/2019 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 14588 | 01/30/2019 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 14577 | 01/30/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 85 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 14588 | 01/30/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 89 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 14336 | 02/01/2019 | GEN | 39 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 14336 | 02/01/2019 | GEN | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 14336 | 02/01/2019 | GEN | 0 | LABOUR | MECH | Labour - Internal | | | |
| RPS25 | 989QWX | 14336 | 02/01/2019 | GEN | 13 | 24059BX | | YAT | SOLENOID | | |
| RPS25 | 989QWX | 14336 | 02/01/2019 | GEN | 16 | CON | | YAT | Consumables | | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 14336 | 02/01/2019 | GEN | DIAGNOSED & REPAIRED CHARGING SYSTEM FOR TAIL GATE LIFTER MODIFIED LONG VEHICLE SIGN MOUNTS & FITTED ROAD TRAIN SIGNS | | | | | | |
| RPS25 | 989QWX | 15574 | 02/08/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00008492 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15574 | 02/08/2019 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 15574 | 02/08/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 105 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15923 | 03/04/2019 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 15053 | 03/06/2019 | TRA | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 15053 | 03/06/2019 | TRB | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 15053 | 03/06/2019 | TRB | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 15053 | 03/06/2019 | TRB | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 15053 | 03/06/2019 | TRB | 13 | B310-30KG-PP | | YAT | WEIGH GAUGE,TRI AXLE,W/LGE AIR BAG. PUSH/PULL SWITCH | | |
| RPS25 | 989QWX | 15053 | 03/06/2019 | TRB | 14 | MF70ZZD | | YAT | DEEP CYCLE BATTERY | | |
| RPS25 | 989QWX | 15053 | 03/06/2019 | TRB | 16 | CON | | YAT | Consumables | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 15053 | 03/06/2019 | TRB | COMPLETED REPAIRED METAL COVER INSIDE VAN ON LHS (RE RIVETED AS REQUIRED) ADJUSTED ALL WHEEL BEARINGS AS RQEUIRED REPLACED TAIL GATE LIFT BATTERIES AS REQUIRED FITTED WEIGHT GAUGE AS | | | | | |
| RPS25 | 989QWX | 15282 | 03/07/2019 | TYRES | | 15 | 77000180 | BRIAUS01 | EX00008293 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 15282 | 03/07/2019 | TYRES | | 15 | 11001464 | YAT | TYRE 11R22.5 148/145L 16 BS R187 | |
| RPS25 | 989QWX | 15282 | 03/07/2019 | TYRES | R&R TYRES | | | | | |
| RPS25 | 989QWX | 15282 | 03/07/2019 | TYRES | | 15 | 77000180 | BRIAUS01 | 96655493 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 15354 | 03/08/2019 | FRIVANA | | 1 | 78-1362 | BRIVAL01 | EX00008373 | EVAPORTAOR FAN,RP25 |
| RPS25 | 989QWX | 15392 | 03/08/2019 | FRIVANA | | 1 | LABCON | BRIVAL01 | EX00008383 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15354 | 03/08/2019 | FRIVANA | | 1 | CON | BRIVAL01 | EX00008373 | Consumables ,RP25 |
| RPS25 | 989QWX | 15392 | 03/08/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 15354 | 03/08/2019 | FRIVANA | | 1 | LABEXT | BRIVAL01 | EX00008373 | Labour External,RP25 |
| RPS25 | 989QWX | 15392 | 03/08/2019 | FRIVANA | | 1 | LABCON | BRIVAL01 | 168 | LABOUR & CONSUMABLES,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 15354 | 03/08/2019 | FRIVANA | SERVICE COMPLETED FOUND WITH ERROR CODE 112 - TRACED TO U/S EVAP FAN IN ZONE 2 - REPLACED | | | | | |
| RPS25 | 989QWX | 15354 | 03/08/2019 | FRIVANA | 1 | LABEXT | BRIVAL01 | 160 | Labour External,RP25 | |
| RPS25 | 989QWX | 15354 | 03/08/2019 | FRIVANA | 1 | CON | BRIVAL01 | 160 | Consumables ,RP25 | |
| RPS25 | 989QWX | 15354 | 03/08/2019 | FRIVANA | 1 | 78-1362 | BRIVAL01 | 160 | EVAPORTAOR FAN,RP25 | |
| RPS25 | 989QWX | 15767 | 03/20/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00008578 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 15767 | 03/20/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 15767 | 03/20/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | 218 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 0 | LABCON | BRIVAL01 | EX00008598 | LABOUR & CONSUMABLES,RP25 - HOURS 20738 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00008643 | LABOUR & CONSUMABLES,RP25, HOURS 20652 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | 243 | LABOUR & CONSUMABLES,RP25, HOURS 20652 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 0 | LABCON | BRIVAL01 | 252 | LABOUR & CONSUMABLES,RP25 - HOURS 20738 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00008807 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00008808 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | 285 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | 286 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00009293 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00009294 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | 417 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | 416 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00009445 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00009449 | LABOUR & CONSUMABLES,RP25, 20872.0 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00009476 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00009477 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | 312 | LABOUR & CONSUMABLES,RP25, 20872.0 | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 308 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 464 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 450 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00009561 | LABOUR & CONSUMABLES,RP25, 20963.0 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00009562 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00009583 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 403 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 333 | LABOUR & CONSUMABLES,RP25, 20963.0 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00009584 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 479 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 478 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00009747 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00009748 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 539 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 540 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00009965 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 574 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00010118 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 631 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00010209 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 654 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00010376 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00010398 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00010475 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 721 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00010591 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00010595 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 743 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 785 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 690 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 15812 | 03/27/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 698 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 16243 | 04/02/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 15838 | 04/02/2019 | TRA | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 15838 | 04/02/2019 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 15838 | 04/02/2019 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | |
| RPS25 | 989QWX | 15838 | 04/02/2019 | TRA | 16 | CON | | YAT | Consumables | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 15838 | 04/02/2019 | TRA | SERVICE COMPLETED REFITTED TAILGATE MARKER LIGHT FITTED REFLECTORS TO REAR WELDED UP TAILGATE LIFTER HINGES | | | | | |
| RPS25 | 989QWX | 16253 | 04/03/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 17370 | 04/08/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 17406 | 04/12/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 17259 | 04/22/2019 | GEN | | 39 | CON | BRIVAL01 | EX00009381 | Consumables,RP25 |
| RPS25 | 989QWX | 17259 | 04/22/2019 | GEN | | 39 | LABEXT | BRIVAL01 | EX00009381 | Labour External,RP25 |
| RPS25 | 989QWX | 17259 | 04/22/2019 | GEN | BVR - FOUND UNIT WITH CODE 112 EVAPORATOR FAN CIRCUIT REPAIRED RUBBED FAN MOTOR HARNESS | | | | | |
| RPS25 | 989QWX | 17259 | 04/22/2019 | GEN | | 39 | LABEXT | BRIVAL01 | 300 | Labour External,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 17259 | 04/22/2019 | GEN | 39 | CON | | BRIVAL01 | 300 | Consumables,RP25 |
| RPS25 | 989QWX | 17676 | 04/29/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 17615 | 05/01/2019 | GEN | 39 | CON | | BRIVAL01 | EX00009548 | Consumables,RP25 |
| RPS25 | 989QWX | 17615 | 05/01/2019 | GEN | 39 | LABEXT | | BRIVAL01 | EX00009548 | Labour External,RP25 |
| RPS25 | 989QWX | 17615 | 05/01/2019 | GEN | BVR - FOUND RETURN AIR SENSOR NOT READING, R&R SENSOR | | | | | |
| RPS25 | 989QWX | 17615 | 05/01/2019 | GEN | 39 | LABEXT | | BRIVAL01 | 322 | Labour External,RP25 |
| RPS25 | 989QWX | 17615 | 05/01/2019 | GEN | 39 | CON | | BRIVAL01 | 322 | Consumables,RP25 |
| RPS25 | 989QWX | 17689 | 05/21/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 17027 | 05/21/2019 | GEN | 39 | LABEXT | | FLEWRI01 | EX00009215 | S&I FULL COLOUR WRAP TO TRAILER SIDES,RP25 |
| RPS25 | 989QWX | 17027 | 05/21/2019 | GEN | 39 | LABEXT | | FLEWRI01 | EX00009215 | REMOVE HARDWARE FROM DOOR, INSTALL WRAP & REINSTALL HARDWARE,RP2 |
| RPS25 | 989QWX | 17027 | 05/21/2019 | GEN | FLEET WRITE - WRAP TRAILER FOR SLIM DUSTY CENTRE | | | | | |
| RPS25 | 989QWX | 17027 | 05/21/2019 | GEN | 39 | LABEXT | | FLEWRI01 | INV-6432 | REMOVE HARDWARE FROM DOOR, INSTALL WRAP & REINSTALL HARDWARE,RP2 |
| RPS25 | 989QWX | 17027 | 05/21/2019 | GEN | 39 | LABEXT | | FLEWRI01 | INV-6432 | S&I FULL COLOUR WRAP TO TRAILER SIDES,RP25 |
| RPS25 | 989QWX | 17622 | 05/26/2019 | GEN | 39 | 40-0974 | | BRIVAL01 | EX00009555 | GRADED SENSOR,RP25 |
| RPS25 | 989QWX | 17622 | 05/26/2019 | GEN | 39 | CON | | BRIVAL01 | EX00009555 | Consumables,RP25 |
| RPS25 | 989QWX | 17622 | 05/26/2019 | GEN | 39 | LABEXT | | BRIVAL01 | EX00009555 | Labour External,RP25 |
| RPS25 | 989QWX | 17622 | 05/26/2019 | GEN | BVR - UNIT FOUND WITH CODE ZONE 2 DISCHARGE & RETURN AIR SENSOR - TRACED TO SENSOR ON RETURN NOT GRADED CORRECTLY, REPLCED U/S DISCHARG | | | | | |
| RPS25 | 989QWX | 17622 | 05/26/2019 | GEN | 39 | 40-0974 | | BRIVAL01 | 396 | GRADED SENSOR,RP25 |
| RPS25 | 989QWX | 17622 | 05/26/2019 | GEN | 39 | CON | | BRIVAL01 | 396 | Consumables,RP25 |
| RPS25 | 989QWX | 17622 | 05/26/2019 | GEN | 39 | LABEXT | | BRIVAL01 | 396 | Labour External,RP25 |
| RPS25 | 989QWX | 17023 | 05/27/2019 | DEFECT | 1 | LABOUR | MECH | Labour | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 17023 | 05/27/2019 | DEFECT | Reported Defect :- Defect Code : 00002525 Defect Reference : 03708 Date : 04/05/2019 Description of Defect : FAULT CODE 3 &11 ZONE 2 | | | | | |
| RPS25 | 989QWX | 17136 | 05/27/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 17023 | 05/27/2019 | TRA | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 17023 | 05/27/2019 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 17023 | 05/27/2019 | TRA | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 17023 | 05/27/2019 | TRA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 17149 | 05/28/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 17475 | 06/03/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 17488 | 06/04/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 17731 | 06/10/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 17756 | 06/11/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 17608 | 06/18/2019 | TRA | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 17608 | 06/18/2019 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 17608 | 06/18/2019 | TRA | 2 | ABH8 | | YAT | AIR BRAKE HOSE TRAILER | |
| RPS25 | 989QWX | 17608 | 06/18/2019 | TRA | 16 | CON | | YAT | Consumables | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 17608 | 06/18/2019 | TRA | SERVICE COMPLETED FITTED FIRE EXTINGUISHER & BRACKET REPLACED 2 X DAMAGED AIR LINES (BRAKE HOSE) AS REQUIRED | | | | | |
| RPS25 | 989QWX | 18127 | 06/24/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 18137 | 06/25/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 17859 | 06/25/2019 | TYRES | 15 | 77000180 | BRIAUS01 | EX00009653 | CASE STOCK 11-22.5,RP25 | |
| RPS25 | 989QWX | 17859 | 06/25/2019 | TYRES | 15 | 11001464 | YAT | TYRE 11R22.5 148/145L 16 BS R187 | | |
| RPS25 | 989QWX | 17859 | 06/25/2019 | TYRES | R&R TYRES POS 31,32 | | | | | |
| RPS25 | 989QWX | 17859 | 06/25/2019 | TYRES | 15 | 77000180 | BRIAUS01 | 96993780 | CASE STOCK 11-22.5,RP25 | |
| RPS25 | 989QWX | 18628 | 07/08/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 18657 | 07/09/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 18703 | 07/15/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 18720 | 07/16/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00009959 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 18720 | 07/16/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00009960 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 18720 | 07/16/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00009964 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 18720 | 07/16/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 18720 | 07/16/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | 581 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 18720 | 07/16/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | 575 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 18720 | 07/16/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | 577 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 18999 | 07/30/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 19233 | 08/02/2019 | GEN | 39 | LABEXT | DJTRAN01 | EX00010221 | Labour External,RP25 | |
| RPS25 | 989QWX | 19233 | 08/02/2019 | GEN | 39 | PART | DJTRAN01 | EX00010221 | BATTERY TRP,RP25 | |
| RPS25 | 989QWX | 19233 | 08/02/2019 | GEN | DJ MORGANS - R&R BATTERY WITH NEW | | | | | |
| RPS25 | 989QWX | 19233 | 08/02/2019 | GEN | 39 | PART | DJTRAN01 | 13786 | BATTERY TRP,RP25 | |
| RPS25 | 989QWX | 19233 | 08/02/2019 | GEN | 39 | LABEXT | DJTRAN01 | 13786 | Labour External,RP25 | |
| RPS25 | 989QWX | 19219 | 08/06/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 19515 | 08/12/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 19536 | 08/13/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00010375 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 19536 | 08/13/2019 | FRIVANA | SERVICE COMPLETED | | | | | |
| RPS25 | 989QWX | 19536 | 08/13/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | 693 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 19362 | 08/13/2019 | TYRES | 15 | 77000180 | BRIAUS01 | EX00010277 | CASE STOCK 11-22.5,RP25 | |
| RPS25 | 989QWX | 19362 | 08/13/2019 | TYRES | 15 | 11001464 | YAT | TYRE 11R22.5 148/145L 16 BS R187 | | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 19362 | 08/13/2019 | TYRES | R&R TYRES POS 21,22,23,24,29,30 PLUS ROTATION | | | | | | |
| RPS25 | 989QWX | 19362 | 08/13/2019 | TYRES | | 15 | 77000180 | | BRIAUS01 | 97151269 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 19628 | 08/20/2019 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 19783 | 08/26/2019 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 19670 | 08/26/2019 | TRA | | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 19670 | 08/26/2019 | TRA | | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 19670 | 08/26/2019 | TRA | | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 19670 | 08/26/2019 | TRA | | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 19670 | 08/26/2019 | TRA | SERVICE COMPLETED REPAIRED 3 x F TRACK RAILS REPLACED BOTH FRONT MUDFLAPS & REPAIRED RHS ANTISAIL BRACKET | | | | | | |
| RPS25 | 989QWX | 19990 | 08/27/2019 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 19892 | 08/29/2019 | FRIVANSE | | 1 | LABEXT | | BRIVAL01 | EX00010556 | Labour External,RP25 |
| RPS25 | 989QWX | 19892 | 08/29/2019 | FRIVANSE | | 1 | 119299 | | BRIVAL01 | EX00010556 | AIR FILTER, EMI 3000,RP25 |
| RPS25 | 989QWX | 19892 | 08/29/2019 | FRIVANSE | | 1 | CON | | BRIVAL01 | EX00010556 | Consumables,RP25 |
| RPS25 | 989QWX | 19892 | 08/29/2019 | FRIVANSE | SERVICE COMPLETED BY BVR CALIBRATED UNIT R&R AIR FILTER | | | | | | |
| RPS25 | 989QWX | 19892 | 08/29/2019 | FRIVANSE | | 40 | 3413005 | | YAT | OIL 15W-40, CK 4/E9 | |
| RPS25 | 989QWX | 19892 | 08/29/2019 | FRIVANSE | | 1 | CON | | BRIVAL01 | 744 | Consumables,RP25 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 19892 | 08/29/2019 | FRIVANSE | 1 | 119299 | | BRIVAL01 | | 744 | AIR FILTER, EMI 3000,RP25 |
| RPS25 | 989QWX | 19892 | 08/29/2019 | FRIVANSE | 1 | LABEXT | | BRIVAL01 | | 744 | Labour External,RP25 |
| RPS25 | 989QWX | 19800 | 08/30/2019 | GEN | 39 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 19800 | 08/30/2019 | GEN | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 19800 | 08/30/2019 | GEN | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 19800 | 08/30/2019 | GEN | BOLT MISSING FROM LANDING LEG HANDLE - REPLACED HANDLE BOLT | | | | | | |
| RPS25 | 989QWX | 20048 | 09/02/2019 | FRIVANA | SERVICE COMPLETED | | | | | | |
| RPS25 | 989QWX | 20218 | 09/09/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00010733 | LABOUR & CONSUMABLES,RP25, 21565 |
| RPS25 | 989QWX | 20218 | 09/09/2019 | FRIVANA | Service Completed | | | | | | |
| RPS25 | 989QWX | 20218 | 09/09/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 827 | LABOUR & CONSUMABLES,RP25, 21565 |
| RPS25 | 989QWX | 20109 | 09/09/2019 | TYRES | 15 | 77000180 | | BRIAUS01 | | EX00010642 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 20109 | 09/09/2019 | TYRES | 15 | 11001464 | | YAT | TYRE 11R22.5 148/145L 16 BS R187 | | |
| RPS25 | 989QWX | 20109 | 09/09/2019 | TYRES | R&R TYRES POS 23/24 | | | | | | |
| RPS25 | 989QWX | 20109 | 09/09/2019 | TYRES | 15 | 77000180 | | BRIAUS01 | | 97252845 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 20236 | 09/10/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00010734 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 20236 | 09/10/2019 | FRIVANA | Service Completed BVR | | | | | | |
| RPS25 | 989QWX | 20236 | 09/10/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 834 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 20320 | 09/13/2019 | GEN | 39 | LABEXT | | BRIVAL01 | | EX00010752 | Labour External,RP25 |
| RPS25 | 989QWX | 20320 | 09/13/2019 | GEN | 39 | CON | | BRIVAL01 | | EX00010752 | Consumables,RP25 |
| RPS25 | 989QWX | 20320 | 09/13/2019 | GEN | BVR - UNIT HAD FAULTY SCREEN - HAD NO POWER GOING TO HMI FITTED NEW HMI (SUPPLIED) | | | | | | |
| RPS25 | 989QWX | 20320 | 09/13/2019 | GEN | 13 | 8452372 | | YAT | HMI 3 & GASKET WEST NEWX | | |
| RPS25 | 989QWX | 20320 | 09/13/2019 | GEN | 39 | CON | | BRIVAL01 | | 845 | Consumables,RP25 |
| RPS25 | 989QWX | 20320 | 09/13/2019 | GEN | 39 | LABEXT | | BRIVAL01 | | 845 | Labour External,RP25 |
| RPS25 | 989QWX | 20146 | 09/16/2019 | TRA | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 20146 | 09/16/2019 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 20146 | 09/16/2019 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 20146 | 09/16/2019 | TRA | 16 | CON | YAT | Consumables | |
| | | | | COMPLETED TIGHTENED ALL S-CAM BUSH MOUNTS FIND AIR LEAK AROUND MIDDLE AXLE & REPAIR CUT OFF OLD BATTERY TERMINALS & REPLACED AS REQUIRED INTERIOR OF TRAILER REAR SIDE DOOR | | | | | |
| RPS25 | 989QWX | 20146 | 09/16/2019 | TRA | STARTING | | | | |
| RPS25 | 989QWX | 20695 | 09/16/2019 | TRC | 39 | LABEXT | DIESER01 | EX00010983 | Labour External,RP25 |
| RPS25 | 989QWX | 20695 | 09/16/2019 | TRC | 39 | LABEXT | DIESER01 | EX00010983 | Labour External,RP25 |
| RPS25 | 989QWX | 20695 | 09/16/2019 | TRC | 39 | LABEXT | DIESER01 | EX00010983 | Labour External,RP25 |
| RPS25 | 989QWX | 20695 | 09/16/2019 | TRC | 39 | LABEXT | DIESER01 | EX00010983 | Labour External,RP25 |
| RPS25 | 989QWX | 20695 | 09/16/2019 | TRC | 39 | CON | DIESER01 | EX00010983 | Consumables,RP25 |
| RPS25 | 989QWX | 20695 | 09/16/2019 | TRC | 39 | CON | DIESER01 | EX00010983 | Consumables,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | COMPLETED C AND D SERVICE REMOVE INSPECT AND REPLACE WHEEL BEARINGS REPLACE 1ST AND 2ND AXLE SHOCKS (3RD AXLE REQUIRE REPLACEMENT) REPLACE DOCK BUMP STOPS REPLACE REAR REFLECTORS |
| RPS25 | 989QWX | 20695 | 09/16/2019 | TRC | S-CAMS | | | | | |
| RPS25 | 989QWX | 20695 | 09/16/2019 | TRC | 39 | CON | | DIESER01 | 24641 | Consumables ,RP25 |
| RPS25 | 989QWX | 20695 | 09/16/2019 | TRC | 39 | CON | | DIESER01 | 24641 | Consumables ,RP25 |
| RPS25 | 989QWX | 20695 | 09/16/2019 | TRC | 39 | LABEXT | | DIESER01 | 24641 | Labour External,RP25 |
| RPS25 | 989QWX | 20695 | 09/16/2019 | TRC | 39 | LABEXT | | DIESER01 | 24641 | Labour External,RP25 |
| RPS25 | 989QWX | 20695 | 09/16/2019 | TRC | 39 | LABEXT | | DIESER01 | 24641 | Labour External,RP25 |
| RPS25 | 989QWX | 20695 | 09/16/2019 | TRC | 39 | LABEXT | | DIESER01 | 24641 | Labour External,RP25 |
| RPS25 | 989QWX | 20343 | 09/17/2019 | EXOINS | 1 | LABOUR | Labour | | | 0 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 20343 | 09/17/2019 | EXOINS | 2ND INSPECTION BY DIESEL SERVICES FAILED 1ST INSPECTION * AIR SYSTEM/SUSPENSION - REPLACED FRONT & MIDDLE AXLE SHOCK ABSORBERS & REAR AXLE AIRBAG * REFELCTORS - REPLACED * | | | | | |
| RPS25 | 989QWX | 20185 | 09/17/2019 | GEN | 39 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 20185 | 09/17/2019 | GEN | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 20185 | 09/17/2019 | GEN | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 20185 | 09/17/2019 | GEN | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 20185 | 09/17/2019 | GEN | GUARD RIPPED OFF - REPLACED WITH 2ND HAND GUARD & 2ND HAND SUPPORT BRACKET | | | | | |
| RPS25 | 989QWX | 20341 | 09/17/2019 | TRA | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 20341 | 09/17/2019 | TRB | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 20341 | 09/17/2019 | TRC | 1 | LABOUR | Labour | | | 0 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | BY DIESEL SERVICES CLEAN & INSPECT WHEEL BEARINGS , REPLACED ALL AXLE WHEEL BEARINGS REPLACED FRONT & MIDDLE AXLE SHOCK ABSORBERS REPLACED REAR AXLE AIRBAGS REPLACED KING PIN REPLACED BOTH | | | | | |
| RPS25 | 989QWX | 20341 | 09/17/2019 | TRC | REAR | | | | | |
| RPS25 | 989QWX | 22259 | 09/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00011558 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 22259 | 09/27/2019 | FRIVANA | SERVICE COMPLETED BVR 24.09.2019 | | | | | |
| RPS25 | 989QWX | 22259 | 09/27/2019 | FRIVANA | 1 | LABCON | BRIVAL01 | 902 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 22256 | 09/27/2019 | GEN | 39 | LAB | BRIVAL01 | EX00011555 | Labour,RP25 | |
| RPS25 | 989QWX | 22256 | 09/27/2019 | GEN | 39 | CON | BRIVAL01 | EX00011555 | Consumables,RP25 | |
| RPS25 | 989QWX | 22256 | 09/27/2019 | GEN | 39 | 78-1362 | BRIVAL01 | EX00011555 | EVAPORTAOR FAN,RP25 | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 22256 | 09/27/2019 | GEN | UNIT HAD CODE 112 FOUND FAULTY ZONE 2 FAN IN BACK REMOVED AND REPLACED UNSERVICEABLE FAN UNIT RUN ON TEST PRETRIP PASSED | | | | | | |
| RPS25 | 989QWX | 22256 | 09/27/2019 | GEN | 39 | 78-1362 | | BRIVAL01 | | 904 | EVAPORTAOR FAN,RP25 |
| RPS25 | 989QWX | 22256 | 09/27/2019 | GEN | 39 | CON | | BRIVAL01 | | 904 | Consumables ,RP25 |
| RPS25 | 989QWX | 22256 | 09/27/2019 | GEN | 39 | LAB | | BRIVAL01 | | 904 | Labour,RP25 |
| RPS25 | 989QWX | 20965 | 09/30/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00011120 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 20965 | 09/30/2019 | FRIVANA | SERVICE COMPLETED BVR 30.09.2019 | | | | | | |
| RPS25 | 989QWX | 20965 | 09/30/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 938 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 20737 | 10/08/2019 | TRA | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 20737 | 10/08/2019 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 20737 | 10/08/2019 | TRA | 16 | CON | | YAT | Consumables | | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 20737 | 10/08/2019 | TRA | COMPLETED CRACKED WHERE FRIDGE FLOOR MEETS CHASSIS SCUFF BAND NEAR SIDE DOOR U/S SOME MISSING, STARTING TO DAMAGE SIDE WALL F TRACK SEPERATING FROM WALL RUST BUILT UP BEHIND TRACK |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 21008 | 10/15/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00011141 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 21008 | 10/15/2019 | FRIVANA | SERVICE COMPLETED 14.10.2019 | | | | | |
| RPS25 | 989QWX | 21008 | 10/15/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 1015 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 21064 | 10/18/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00011156 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 21064 | 10/18/2019 | FRIVANA | SERVICE COMPLETED BVR 15.10.2019 | | | | | |
| RPS25 | 989QWX | 21064 | 10/18/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 1030 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 21350 | 10/22/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00011267 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 21350 | 10/22/2019 | FRIVANA | SERVICE COMPLETED BVR 21.10.2019 | | | | | |
| RPS25 | 989QWX | 21350 | 10/22/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 1043 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 22215 | 10/29/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00011551 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 22215 | 10/29/2019 | FRIVANA | SERVICE COMPLETED BVR 28.10.2019 | | | | | |
| RPS25 | 989QWX | 22215 | 10/29/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 1083 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 21863 | 11/05/2019 | DEFECT | 1 | LABOUR | MECH | Labour | | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 21863 | 11/05/2019 | DEFECT | Reported Defect :- Defect Code : 00002978 Defect Reference : WO20737 Date : 08/10/2019 Description of Defect : F TRACK SEPERATING FROM WALL RUST BUILT UP BEHIND TRACK |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 21863 | 11/05/2019 | DEFECT | Reported Defect :- Defect Code : 00002980 Defect Reference : WO20737 Date : 08/10/2019 Description of Defect : CRACK IN CHASSIS RAIL NEAR AIR TANK BETWEEN AXLE 2 & 3 |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 21863 | 11/05/2019 | DEFECT | Reported Defect :- Defect Code : 00002981 Defect Reference : WO20737 Date : 08/10/2019 Description of Defect : CRACKS AT LANDING LEGS |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 21863 | 11/05/2019 | DEFECT | Reported Defect :- Defect Code : 00002976 Defect Reference : WO20737 Date : 08/10/2019 Description of Defect : CRACKED WHERE FRIDGE FLOOR MEETS CHASSIS |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 22250 | 11/05/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00011553 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 22250 | 11/05/2019 | FRIVANA | SERVICE COMPLETED BVR 05.11.2019 | | | | | |
| RPS25 | 989QWX | 22250 | 11/05/2019 | FRIVANA | 1 | LABCON | | BRIVAL01 | 1122 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 21863 | 11/05/2019 | TRA | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 21863 | 11/05/2019 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 21863 | 11/05/2019 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | |
| RPS25 | 989QWX | 21863 | 11/05/2019 | TRA | 0 | LABOUR | TRADEA | Labour - Internal | | |
| RPS25 | 989QWX | 21863 | 11/05/2019 | TRA | 16 | CON | | YAT | Consumables | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 21863 | 11/05/2019 | TRA | SERVICE COMPLETED RIVET POGO RAIL BACK TO WALL RIVET WARNING LIGHTS ON TAIL GATE LOADER BACK ONTO TAIL GATE | | | | | |
| RPS25 | 989QWX | 23079 | 11/07/2019 | FVPRE | | 1 | LABCON | BRIVAL01 | EX00011987 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 23079 | 11/07/2019 | FVPRE | SERVICE COMPLETED BY BVR 05.11.2019 | | | | | |
| RPS25 | 989QWX | 23079 | 11/07/2019 | FVPRE | | 1 | LABCON | BRIVAL01 | 1144 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 23318 | 11/26/2019 | FVPRE | FRIDGE VAN PRE-CHECK COMPLETED<br><br>PRE-CHECK COMPLETED BY BVR . | | | | | |
| RPS25 | 989QWX | 23920 | 12/09/2019 | FRIVANA | | 1 | LABCON | BRIVAL01 | EX00012460 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 23920 | 12/09/2019 | FRIVANA | SERVICE COMPLETED BY BVR 03.12.2019 | | | | | |
| RPS25 | 989QWX | 23920 | 12/09/2019 | FRIVANA | | 1 | LABCON | BRIVAL01 | 1287 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 22961 | 12/09/2019 | TRA | | 1 | LABOUR | Labour | | 0 |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 22961 | 12/09/2019 | TRA | COMPLETED BY BEN 09.12.19<br><br>CARRIED OUT A SERVICE REPLACED LEAKING AIR HOSE - 2ND AXLE REPLACED MUD FLAP ON 1ST AXLE LHS AND STRAIGHTEN MOUNTING BRACKET GREASED TAIL GATE DRILLED OUT AND REPLACED LOOSE |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 22961 | 12/09/2019 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 22961 | 12/09/2019 | TRA | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 22961 | 12/09/2019 | TRA | 13 | ASB18 | | YAT | Anti Sail Bracket 18" | |
| RPS25 | 989QWX | 27628 | 12/20/2019 | FVPRE | SERVICE COMPLETED BY BVR 17.12.2019 | | | | | |
| RPS25 | 989QWX | 27673 | 12/20/2019 | FVPRE | 1 | LABCON | | BRIVAL01 | EX00014314 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 27673 | 12/20/2019 | FVPRE | 1 | LABCON | | BRIVAL01 | 1360 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 23239 | 12/20/2019 | GEN | 13 | LABEXT | | BRIVAL01 | EX00012047 | ,RP25 |
| RPS25 | 989QWX | 23239 | 12/20/2019 | GEN | 16 | CON | | BRIVAL01 | EX00012047 | RP25, |
| RPS25 | 989QWX | 23239 | 12/20/2019 | GEN | 13 | 78-1360 | | BRIVAL01 | EX00012047 | RP25,ALTERNATOR BELT FRIDGE |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 23239 | 12/20/2019 | GEN | COMPLETED BY BVR 17.12.19 INVOICE # 00001357<br><br>REPLACED ALTERNATOR BELT DUE TO CRACKING TIGHTENED AND SECURED LOOSE PANELS UNIT RUN ON TEST PRETRIP PASSED |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 23239 | 12/20/2019 | GEN | 13 | 78-1360 | BRIVAL01 | 1357 | RP25,ALTERNATOR BELT FRIDGE |
| RPS25 | 989QWX | 23239 | 12/20/2019 | GEN | 16 | CON | BRIVAL01 | 1357 | RP25, |
| RPS25 | 989QWX | 23239 | 12/20/2019 | GEN | 13 | LABEXT | BRIVAL01 | 1357 | ,RP25 |
| RPS25 | 989QWX | 23864 | 01/15/2020 | FVGEN | 13 | PART | BRIVAL01 | EX00012441 | RP25,TK LIGHT |
| RPS25 | 989QWX | 23864 | 01/15/2020 | FVGEN | 13 | CON | BRIVAL01 | EX00012441 | RP25, |
| RPS25 | 989QWX | 23864 | 01/15/2020 | FVGEN | 13 | LABEXT | BRIVAL01 | EX00012441 | RP25, |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 23864 | 01/15/2020 | FVGEN | COMPLETED BY BVR 15.01.2020 INVOICE # 00001465<br><br>UNIT FOUND WITH FAULTY STATUS LIGHT MOUNTED AND WIRED NEW LIGHT ADJUSTED LOOSE PANELS UNIT RUN ON TEST PRE TRIP PASSED | | | | | | |
| RPS25 | 989QWX | 23864 | 01/15/2020 | FVGEN | | 13 | LABEXT | | BRIVAL01 | 1465 | RP25, |
| RPS25 | 989QWX | 23864 | 01/15/2020 | FVGEN | | 13 | CON | | BRIVAL01 | 1465 | RP25, |
| RPS25 | 989QWX | 23864 | 01/15/2020 | FVGEN | | 13 | PART | | BRIVAL01 | 1465 | RP25,TK LIGHT |
| RPS25 | 989QWX | 24019 | 01/21/2020 | TRA | | 1 | LABOUR | Labour | | | 0 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | COMPLETED BY SEAN / BILLY 21.01.2020 | | | | | | |
| RPS25 | 989QWX | 24019 | 01/21/2020 | TRA | REPLACED EXPIRED FIRE EXTINGUISHER FITTED FRIDGE DOOR SAFETY LATCH REEPLACED GREASE NIPPLE ON TAILGATE LIFTER TIGHTENED 2 x REAR AIR BAG | | | | | | |
| RPS25 | 989QWX | 24019 | 01/21/2020 | TRA | | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 24019 | 01/21/2020 | TRA | | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 24019 | 01/21/2020 | TRA | | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 24484 | 01/25/2020 | WEICAL | | 0 | LABOUR | Labour | | | 0 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | AIR GAUGE: 8.75 ADJUSTED : 9.5 WEIGHBRIDGE: 9.1 | | | | | |
| RPS25 | 989QWX | 24484 | 01/25/2020 | WEICAL | AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | | |
| RPS25 | 989QWX | 25265 | 02/05/2020 | FVPRE | | 1 | LABCON | BRIVAL01 | EX00013225 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 25265 | 02/05/2020 | FVPRE | SERVICE COMPLETED BY BVR 29.01.2020 | | | | | |
| RPS25 | 989QWX | 25265 | 02/05/2020 | FVPRE | | 1 | LABCON | BRIVAL01 | 1563 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 24516 | 02/12/2020 | FVGEN | | 16 | CON | BRIVAL01 | EX00012832 | RP25, |
| RPS25 | 989QWX | 24516 | 02/12/2020 | FVGEN | | 13 | LABEXT | BRIVAL01 | EX00012832 | RP25, |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 24516 | 02/12/2020 | FVGEN | COMPLETED BY BVR 12.02.2020 INVOICE # 00001607<br><br>UNIT RAN OUT OF FUEL REFUELLED AND PRIMED UNIT CLEANED FUEL SCREEN UNIT RUN ON TEST PRETRIP PASSED | | | | | |
| RPS25 | 989QWX | 24516 | 02/12/2020 | FVGEN | 13 | LABEXT | | BRIVAL01 | 1607 | RP25, |
| RPS25 | 989QWX | 24516 | 02/12/2020 | FVGEN | 16 | CON | | BRIVAL01 | 1607 | RP25, |
| RPS25 | 989QWX | 25151 | 02/13/2020 | FVPRE | 1 | LABCON | | BRIVAL01 | EX00013196 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 25542 | 02/13/2020 | FVPRE | 1 | LABCON | | BRIVAL01 | EX00013331 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 25151 | 02/13/2020 | FVPRE | SERVICE COMPLETED BY BVR 10.02.2020 | | | | | |
| RPS25 | 989QWX | 25542 | 02/13/2020 | FVPRE | SERVICE COMPLETED BY BVR 10.02.2020 | | | | | |
| RPS25 | 989QWX | 25151 | 02/13/2020 | FVPRE | 1 | LABCON | | BRIVAL01 | 1624 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 25332 | 02/18/2020 | FVPRE | 1 | LABCON | | BRIVAL01 | EX00013255 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 25332 | 02/18/2020 | FVPRE | SERVICE COMPLETED BY BVR 11.02.2020 | | | | | |
| RPS25 | 989QWX | 24700 | 02/24/2020 | TRA | 1 | LABOUR | Labour | | | 0 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 24700 | 02/24/2020 | TRA | SERVICE COMPLETED BY SEAN / KEIRAN / BEN 24.02.2020<br><br>REPLACED REAR REFLECTORS LOAD TESTED BATTERIES CHECKED AND GREASED TAIL GATELOADER | | | | | | |
| RPS25 | 989QWX | 24700 | 02/24/2020 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 24700 | 02/24/2020 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 24700 | 02/24/2020 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 24700 | 02/24/2020 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 24806 | 02/26/2020 | FVGEN | 13 | 78-603 | | BRIVAL01 | | EX00013015 | RP25,SB Fridge Fan belt |
| RPS25 | 989QWX | 24806 | 02/26/2020 | FVGEN | 13 | 78-629 | | BRIVAL01 | | EX00013015 | RP25,BELT |
| RPS25 | 989QWX | 24806 | 02/26/2020 | FVGEN | 16 | CON | | BRIVAL01 | | EX00013015 | RP25, |
| RPS25 | 989QWX | 24806 | 02/26/2020 | FVGEN | 13 | LABEXT | | BRIVAL01 | | EX00013015 | RP25, |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 24806 | 02/26/2020 | FVGEN | COMPLETED BY BVR 26.02.2020 INVOICE # 00001718<br><br>REPLACED UNSERVICEABLE MAIN DRIVE BELTS ADJUSTED OTHER BELTS UNIT RUN ON TEST PRETRIP PASSED | | | | | |
| RPS25 | 989QWX | 24806 | 02/26/2020 | FVGEN | 13 | LABEXT | BRIVAL01 | 1718 | RP25, | |
| RPS25 | 989QWX | 24806 | 02/26/2020 | FVGEN | 16 | CON | BRIVAL01 | 1718 | RP25, | |
| RPS25 | 989QWX | 24806 | 02/26/2020 | FVGEN | 13 | 78-629 | BRIVAL01 | 1718 | RP25,BELT | |
| RPS25 | 989QWX | 24806 | 02/26/2020 | FVGEN | 13 | 78-603 | BRIVAL01 | 1718 | RP25,SB Fridge Fan belt | |
| RPS25 | 989QWX | 25783 | 03/17/2020 | FVPRE | 1 | LABCON | BRIVAL01 | EX00013455 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 25783 | 03/17/2020 | FVPRE | SERVICE COMPLETED BY BVR 16.03.2020 | | | | | |
| RPS25 | 989QWX | 25783 | 03/17/2020 | FVPRE | 1 | LABCON | BRIVAL01 | 1818 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 25797 | 03/19/2020 | FVPRE | 1 | LABCON | BRIVAL01 | EX00013456 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 25797 | 03/19/2020 | FVPRE | SERVICE COMPLETED BY BVR 17.03.2020 | | | | | |
| RPS25 | 989QWX | 25797 | 03/19/2020 | FVPRE | 1 | LABCON | BRIVAL01 | 1850 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 25569 | 03/24/2020 | GEN | 15 | 33000517 | BRIAUS01 | EX00013333 | REMOVAL: CUSTOMER PULL POINT,RP25 | |
| RPS25 | 989QWX | 25569 | 03/24/2020 | GEN | 15 | 77000180 | BRIAUS01 | EX00013333 | CASE STOCK 11-22.5,RP25 | |
| RPS25 | 989QWX | 25569 | 03/24/2020 | GEN | 15 | 11001464 | BRIAUS01 | EX00013333 | TYRE 11R22.5 148/145L 16 BS R187,RP25 | |
| RPS25 | 989QWX | 25569 | 03/24/2020 | GEN | 15 | 33000084 | BRIAUS01 | EX00013333 | FIT TBR TYRE,RP25 | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | COMPLETED BY BRIDGESTONE 24.03.2020 | | | | | | |
| RPS25 | 989QWX | 25569 | 03/24/2020 | GEN | INVOICE # 98290871 | | | | | | |
| RPS25 | 989QWX | 25569 | 03/24/2020 | GEN | | 15 | 33000084 | | BRIAUS01 | 98290871 | FIT TBR TYRE,RP25 |
| RPS25 | 989QWX | 25569 | 03/24/2020 | GEN | | 15 | 11001464 | | BRIAUS01 | 98290871 | TYRE 11R22.5 148/145L 16 BS R187,RP25 |
| RPS25 | 989QWX | 25569 | 03/24/2020 | GEN | | 15 | 77000180 | | BRIAUS01 | 98290871 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 25569 | 03/24/2020 | GEN | | 15 | 33000517 | | BRIAUS01 | 98290871 | REMOVAL: CUSTOMER PULL POINT,RP25 |
| RPS25 | 989QWX | 25758 | 03/31/2020 | TRA | | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 25758 | 03/31/2020 | TRA | SERVICE COMPLETED. | | | | | | |
| RPS25 | 989QWX | 25758 | 03/31/2020 | TRB | | 1 | LABOUR | Labour | | | 0 |
| | | | | | SERVICE COMPLETED BY BILLY 31.03.2020 | | | | | | |
| RPS25 | 989QWX | 25758 | 03/31/2020 | TRB | FITTED BREAKDOWN KIT AS REQUIRED . | | | | | | |
| RPS25 | 989QWX | 25758 | 03/31/2020 | TRB | | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 25758 | 03/31/2020 | TRB | | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 26075 | 04/07/2020 | FVPRE | | 1 | LABCON | | BRIVAL01 | EX00013584 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 26075 | 04/07/2020 | FVPRE | SERVICE COMPLETED BY BVR 31.03.2020 | | | | | | |
| RPS25 | 989QWX | 26075 | 04/07/2020 | FVPRE | | 1 | LABCON | | BRIVAL01 | 1948 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 26154 | 04/13/2020 | FVGEN | | 13 | CON | | BRIVAL01 | EX00013618 | Consumables ,RP25 |
| RPS25 | 989QWX | 26154 | 04/13/2020 | FVGEN | | 13 | LABEXT | | BRIVAL01 | EX00013618 | Labour External,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 26154 | 04/13/2020 | FVGEN | COMPLETED BY BVR 13.04.2020 INVOICE # 00001986<br><br>UNIT WAS FOUND WITH CODES TRACED TO LOOSE PLUGS IN BOARD CLEANED AND REGREASED PLUGS FLUSHED UNIT DRAIN HOSES UNIT RUN ON TEST PRETRIP PASSED | | | | | |
| RPS25 | 989QWX | 26154 | 04/13/2020 | FVGEN | 13 | LABEXT | BRIVAL01 | 1986 | Labour External,RP25 | |
| RPS25 | 989QWX | 26154 | 04/13/2020 | FVGEN | 13 | CONsumables | BRIVAL01 | 1986 | ,RP25 | |
| RPS25 | 989QWX | 26237 | 04/16/2020 | FVPRE | 1 | LABCON | BRIVAL01 | EX00013659 | LABOUR & CONSUMABLES,RP25 | HOURS = 22624 |
| RPS25 | 989QWX | 26254 | 04/16/2020 | FVPRE | 1 | LABCON | BRIVAL01 | EX00013660 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 26237 | 04/16/2020 | FVPRE | SERVICE COMPLETED BY BVR 06.04.2020 | | | | | |
| RPS25 | 989QWX | 26254 | 04/16/2020 | FVPRE | SERVICE COMPLETED BY BVR 07.04.2020 | | | | | |
| RPS25 | 989QWX | 26237 | 04/16/2020 | FVPRE | 1 | LABCON | BRIVAL01 | 2032 | LABOUR & CONSUMABLES,RP25 | HOURS = 22624 |
| RPS25 | 989QWX | 26254 | 04/16/2020 | FVPRE | 1 | LABCON | BRIVAL01 | 2031 | LABOUR & CONSUMABLES,RP25 | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 26812 | 05/02/2020 | WEICAL | 0 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 26812 | 05/02/2020 | WEICAL | AIR GAUGE: 20 ADJUSTED : 0 WEIGHBRIDGE: 19.64 | | | | | | |
| RPS25 | 989QWX | 26812 | 05/02/2020 | WEICAL | AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | | | |
| RPS25 | 989QWX | 26751 | 05/05/2020 | TRA | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 26751 | 05/05/2020 | TRA | SERVICE COMPLETED BY SEAN / KEIRAN 05.05.2020 | | | | | | |
| RPS25 | 989QWX | 26751 | 05/05/2020 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 26751 | 05/05/2020 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 26751 | 05/05/2020 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 26857 | 05/07/2020 | GEN | 15 | 33000517 | | BRIAUS01 | | EX00013941 | REMOVAL: CUSTOMER PULL POINT,RP25 |
| RPS25 | 989QWX | 26857 | 05/07/2020 | GEN | 15 | 33000085 | | BRIAUS01 | | EX00013941 | ROTATE TBR TYRE,RP25 |
| RPS25 | 989QWX | 26857 | 05/07/2020 | GEN | 15 | 77000180 | | BRIAUS01 | | EX00013941 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 26857 | 05/07/2020 | GEN | 15 | 11001464 | | BRIAUS01 | | EX00013941 | TYRE 11R22.5 148/145L 16 BS R187,RP25 |
| RPS25 | 989QWX | 26857 | 05/07/2020 | GEN | 15 | 33000084 | | BRIAUS01 | | EX00013941 | FIT TBR TYRE,RP25 |
| RPS25 | 989QWX | 26857 | 05/07/2020 | GEN | COMPLETED BY BRIDGESTONE 07.05.2020 INVOICE # 98447175 | | | | | | |
| RPS25 | 989QWX | 26857 | 05/07/2020 | GEN | 15 | 33000084 | | BRIAUS01 | | 98447175 | FIT TBR TYRE,RP25 |
| RPS25 | 989QWX | 26857 | 05/07/2020 | GEN | 15 | 11001464 | | BRIAUS01 | | 98447175 | TYRE 11R22.5 148/145L 16 BS R187,RP25 |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 26857 | 05/07/2020 | GEN | 15 | 77000180 | BRIAUS01 | 98447175 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 26857 | 05/07/2020 | GEN | 15 | 33000085 | BRIAUS01 | 98447175 | ROTATE TBR TYRE,RP25 |
| RPS25 | 989QWX | 26857 | 05/07/2020 | GEN | 15 | 33000517 | BRIAUS01 | 98447175 | REMOVAL: CUSTOMER PULL POINT,RP25 |
| RPS25 | 989QWX | 27099 | 05/13/2020 | FVPRE | 1 | LABCON | BRIVAL01 | EX00014060 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 27099 | 05/13/2020 | FVPRE | SERVICE COMPLETED BY BVR 05.05.2020 | | | | |
| RPS25 | 989QWX | 27099 | 05/13/2020 | FVPRE | 1 | LABCON | BRIVAL01 | 2252 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 27198 | 05/15/2020 | FVPRE | 1 | LABCON | BRIVAL01 | EX00014101 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 27198 | 05/15/2020 | FVPRE | SERVICE COMPLETED BY BVR 11.05.2020 | | | | |
| RPS25 | 989QWX | 27198 | 05/15/2020 | FVPRE | 1 | LABCON | BRIVAL01 | 2283 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 27461 | 05/31/2020 | FRIVANB | 1 | 10-417 | BRIVAL01 | EX00014211 | Filter Service Kit, Fridge Motor, SLX-400,RP25 |
| RPS25 | 989QWX | 27461 | 05/31/2020 | FRIVANB | 1 | 40-974 | BRIVAL01 | EX00014211 | GRADED AIR SENSOR,RP25 |
| RPS25 | 989QWX | 27461 | 05/31/2020 | FRIVANB | 1 | 45-2256 | BRIVAL01 | EX00014211 | ALTERNATOR 65 AMP,RP25 |
| RPS25 | 989QWX | 27461 | 05/31/2020 | FRIVANB | 16 | CON | BRIVAL01 | EX00014211 | Consumab les ,RP25 |
| RPS25 | 989QWX | 27461 | 05/31/2020 | FRIVANB | 1 | LABEXT | BRIVAL01 | EX00014211 | Labour External,RP25 |
| RPS25 | 989QWX | 27461 | 05/31/2020 | FRIVANB | ED BY BVR 31.05.2020 INVOICE # 00002415 UNIT FOUND WITH SENSOR CODES REMOVE AND REPLACE UNSERVICEABLE SENSOR ALSO FOUND ALTERNATOR TO BE WORN (STARTER RINGS) REMOVE AND REPLACE | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 27461 | 05/31/2020 | FRIVANB | 1 | 10-417 | | BRIVAL01 | 2415 | Filter Service Kit, Fridge Motor, SLX-400,RP25 |
| RPS25 | 989QWX | 27461 | 05/31/2020 | FRIVANB | 1 | 40-974 | | BRIVAL01 | 2415 | GRADED AIR SENSOR,RP25 |
| RPS25 | 989QWX | 27461 | 05/31/2020 | FRIVANB | 1 | 45-2256 | | BRIVAL01 | 2415 | ALTERNATOR 65 AMP,RP25 |
| RPS25 | 989QWX | 27461 | 05/31/2020 | FRIVANB | 16 | CON | | BRIVAL01 | 2415 | Consumab les ,RP25 |
| RPS25 | 989QWX | 27461 | 05/31/2020 | FRIVANB | 1 | LABEXT | | BRIVAL01 | 2415 | Labour External,RP25 |
| RPS25 | 989QWX | 27454 | 06/01/2020 | TRA | 1 | LABOUR | Labour | | | 0 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | COMPLETED BY BILLY / BEN 01.06.2020<br><br>REPLACED 1 x BRAKE HOSE ON FRONT AXLE AS REQUIRED FITTED CHAIN ON TOOLBOX DOOR AS REQUIRED LOAD TESTED BATTERIES AS REQUIRED, TESTED OK | | | | | | |
| RPS25 | 989QWX | 27454 | 06/01/2020 | TRA | TAIL GATE | | | | | | |
| RPS25 | 989QWX | 27454 | 06/01/2020 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 27454 | 06/01/2020 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 27454 | 06/01/2020 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 28894 | 06/11/2020 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00014819 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 28894 | 06/11/2020 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 2512 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 28894 | 06/11/2020 | FRIVANA | SERVICE COMPLETED BVR | | | | | | |
| RPS25 | 989QWX | 27895 | 06/18/2020 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00014429 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 27895 | 06/18/2020 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 2432 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 28162 | 06/24/2020 | FRIVANA | SERVICE COMPLETED BVR 16/06/2020 | | | | | | |
| RPS25 | 989QWX | 28450 | 06/24/2020 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00014519 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 28450 | 06/24/2020 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 2574 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 28824 | 07/07/2020 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00014808 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 28824 | 07/07/2020 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 2675 | LABOUR & CONSUMABLES,RP25 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 28824 | 07/07/2020 | FRIVANA | SERVICE COMPLETED BVR | | | | | | |
| RPS25 | 989QWX | 28848 | 07/09/2020 | FRIVANA | | 1 | LABCON | | BRIVAL01 | EX00014812 | LABOUR & CONSUMABLES,RP25, HOURS 23753 |
| RPS25 | 989QWX | 28848 | 07/09/2020 | FRIVANA | | 1 | LABCON | | BRIVAL01 | 2699 | LABOUR & CONSUMABLES,RP25, HOURS 23753 |
| RPS25 | 989QWX | 28848 | 07/09/2020 | FRIVANA | SERVICE COMPLETED BVR | | | | | | |
| RPS25 | 989QWX | 28952 | 07/13/2020 | DEFECT | | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 28952 | 07/13/2020 | DEFECT | | | | | | | |
| RPS25 | 989QWX | 28952 | 07/13/2020 | DEFECT | DEFECT CLEARED. | | | | | | |
| RPS25 | 989QWX | 28952 | 07/13/2020 | ROTDRI | | 15 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 28952 | 07/13/2020 | ROTDRI | DRIVE TYRE ROTATION COMPLETED. COMPLETED BY BRIDGESTONE - | | | | | | |
| RPS25 | 989QWX | 28952 | 07/13/2020 | TYRES | | | | | | | |
| RPS25 | 989QWX | 28952 | 07/13/2020 | TYRES | | 15 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 28952 | 07/13/2020 | TYRES | | 15 | 11002831 | | YAT | TYRE 11R22.5 146/143L M766 | |
| RPS25 | 989QWX | 28584 | 07/14/2020 | FRIVANA | | 1 | LABOUR | MECH1 | Labour | | |
| RPS25 | 989QWX | 28584 | 07/14/2020 | FRIVANA | REPLACED LHS TOP MARK LAMP REPLACED LHS MARK LAMP | | | | | | |
| RPS25 | 989QWX | 28584 | 07/14/2020 | FRIVANA | | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 28584 | 07/14/2020 | FRIVANA | | 14 | 91622 | | YAT | LED Marker light. Amber. Narva | |
| RPS25 | 989QWX | 28584 | 07/14/2020 | FRIVANA | | 14 | 91700BL | | YAT | Clearance Light, LED Amber, Narva | |
| RPS25 | 989QWX | 28585 | 07/14/2020 | GEN | | 39 | LABOUR | MECH1 | Labour | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 28585 | 07/14/2020 | GEN | REPAIR COMPLETED - 14.07.2020 BY DUANE<br><br>DRILLED AND CUTE HOLES IN LIFTER FIT PLATES AND BOLT DOWN FIT HAND RAILS FIT HOOKS TO HOLD RAILS TO BACK OF DOORS. | | | | | |
| RPS25 | 989QWX | 28585 | 07/14/2020 | GEN | | 16 | CON | | YAT | Consumables |
| RPS25 | 989QWX | 28579 | 07/14/2020 | TRA | | 1 | LABOUR | MECH1 | Labour - Internal | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 28579 | 07/14/2020 | TRA | SERVICE COMPLETED 14.07.20 BY DUANE<br><br>** REPLACED LHS TOP FRONT MARK LAMP ** REPLACED LHS MARK LAMP | | | | | |
| RPS25 | 989QWX | 28579 | 07/14/2020 | TRA | | 16 | CON | YAT | Consumables | |
| RPS25 | 989QWX | 28579 | 07/14/2020 | TRA | | 14 | 91622 | YAT | LED Marker light. Amber. Narva | |
| RPS25 | 989QWX | 28608 | 07/15/2020 | FRIVANA | | 1 | LABCON | BRIVAL01 | EX00014678 | LABOUR & CONSUMABLES,RP25, HOURS 23181 |
| RPS25 | 989QWX | 28608 | 07/15/2020 | FRIVANA | | 1 | LABCON | BRIVAL01 | 2576 | LABOUR & CONSUMABLES,RP25, HOURS 23181 |
| RPS25 | 989QWX | 28608 | 07/15/2020 | FRIVANA | SERVICE COMPLETED BVR | | | | | |
| RPS25 | 989QWX | 28862 | 07/16/2020 | FRIVANA | | 1 | LABCON | BRIVAL01 | EX00014813 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 28862 | 07/16/2020 | FRIVANA | | 1 | LABCON | BRIVAL01 | 2759 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 28862 | 07/16/2020 | FRIVANA | SERVICE COMPLETED BVR | | | | | |
| RPS25 | 989QWX | 28927 | 07/17/2020 | GEN | | 39 | LABEXT | KENAUT01 | EX00014832 | Labour External,RP25 |
| RPS25 | 989QWX | 28927 | 07/17/2020 | GEN | | 39 | PART | KENAUT01 | EX00014832 | SIDE MARKER LIGHT AMBER LED 9 TO 33V,RP25 |
| RPS25 | 989QWX | 28927 | 07/17/2020 | GEN | | 39 | PART | KENAUT01 | EX00014832 | CONDUIT TUBING HEAVY DUTY ID10 OD12,RP25 |
| RPS25 | 989QWX | 28927 | 07/17/2020 | GEN | | 39 | PART | KENAUT01 | EX00014832 | 3MM TWIN CORE RED/BLACK,RP25 |
| RPS25 | 989QWX | 28927 | 07/17/2020 | GEN | | 39 | PART | KENAUT01 | 41208 | 3MM TWIN CORE RED/BLACK,RP25 |
| RPS25 | 989QWX | 28927 | 07/17/2020 | GEN | | 39 | PART | KENAUT01 | 41208 | CONDUIT TUBING HEAVY DUTY ID10 OD12,RP25 |
| RPS25 | 989QWX | 28927 | 07/17/2020 | GEN | | 39 | PART | KENAUT01 | 41208 | SIDE MARKER LIGHT AMBER LED 9 TO 33V,RP25 |
| RPS25 | 989QWX | 28927 | 07/17/2020 | GEN | | 39 | LABEXT | KENAUT01 | 41208 | Labour External,RP25 |
| RPS25 | 989QWX | 29510 | 08/03/2020 | GEN | | 1 | LABCON | BRIVAL01 | EX00015172 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 29510 | 08/03/2020 | GEN | FLEET CHECK COMPLETED BY BVR 03.08.2020 | | | | | |
| RPS25 | 989QWX | 29510 | 08/03/2020 | GEN | | 1 | LABCON | BRIVAL01 | 2957 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 29467 | 08/04/2020 | GEN | | 1 | LABCON | BRIVAL01 | EX00015146 | LABOUR & CONSUMABLES,RP25 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 29467 | 08/04/2020 | GEN | FLEET CHECK COMPLETED BY BVR 04.08.2020 | | | | | | |
| RPS25 | 989QWX | 29467 | 08/04/2020 | GEN | 1 | LABCON | | BRIVAL01 | | 2988 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 29631 | 08/17/2020 | GEN | 39 | LABOUR | APPREN | Labour | | | |
| RPS25 | 989QWX | 29631 | 08/17/2020 | GEN | REPAIR COMPLETED. 13/08/2020 Kieran<br><br>Repair 2 air brake hoses above from left booster will need new air lines LH middle air bag leaking | | | | | | |
| RPS25 | 989QWX | 29631 | 08/17/2020 | GEN | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 29829 | 08/18/2020 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00015315 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 29829 | 08/18/2020 | FRIVANA | SERVICE COMPLETED BVR | | | | | | |
| RPS25 | 989QWX | 29829 | 08/18/2020 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 3020 | LABOUR & CONSUMABLES,RP25 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 30088 | 09/02/2020 | DEFECT | CLEARED BY JESSE 02.09.2020<br><br>"ALREADY HAS NEW AIR LINES @ TIME OF SERVICE".<br><br>Reported Defect :- Defect Code : 00004813 Defect Reference : WO29631 Date : 13/08/2020 Description of Defect : | | | | | | |
| RPS25 | 989QWX | 30172 | 09/02/2020 | FVPRE | | 39 | LABCON | | BRIVAL01 | EX00015436 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 30172 | 09/02/2020 | FVPRE | | 39 | LABCON | | BRIVAL01 | 3200 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 30088 | 09/02/2020 | TRA | | 1 | LABOUR | MECH1 | Labour | | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 30088 | 09/02/2020 | TRA | COMPLETED BY JESSE + BEN 02.09.2020<br><br>REAR INTERNAL MOTOR CAGE BREAKING AWAY FROM ROOF. STEEL PROTECTOR ON FRONT WALL FOR HOSE BREAKING AWAY TOP LHS CORNER - ALL THE WAY TO | | | | | | |
| RPS25 | 989QWX | 30088 | 09/02/2020 | TRA | | 0 | LABOUR | APPREN | Labour - Internal | | |
| RPS25 | 989QWX | 30088 | 09/02/2020 | TRA | | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 30351 | 09/11/2020 | FVPRE | FRIDGE VAN PRE-CHECK COMPLETED<br><br>PRE-CHECK COMPLETED BY BVR. | 39 | LABCON | | BRIVAL01 | EX00015511 | LABOUR & CONSUMABLES,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 30351 | 09/11/2020 | FVPRE | 39 | LABCON | BRIVAL01 | 3246 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 30459 | 09/17/2020 | FVPRE | 39 | LABCON | BRIVAL01 | EX00015571 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 30459 | 09/17/2020 | FVPRE | FRIDGE VAN PRE-CHECK COMPLETED<br><br>PRE-CHECK COMPLETED BY BVR. | | | | |
| RPS25 | 989QWX | 30459 | 09/17/2020 | FVPRE | 39 | LABCON | BRIVAL01 | 3346 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 30968 | 09/30/2020 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00015841 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 30986 | 09/30/2020 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00015842 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 30968 | 09/30/2020 | FRIVANA | 1 | LABCON | BRIVAL01 | 3499 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 30986 | 09/30/2020 | FRIVANA | 1 | LABCON | BRIVAL01 | 3472 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 31098 | 10/07/2020 | DEFECT | DEFECT CLEARED BY JESSE 07.10.2020<br><br>"REPLACED"<br><br>Reported Defect :- Defect Code : 00004814 Defect Reference : WO29631 Date : 13/08/2020 Description of Defect : LH middle air bag leaking | | | | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 31098 | 10/07/2020 | DEFECT | CLEARED BY JESSE 07.10.2020<br><br>Reported Defect :- Defect Code : 00004884 Defect Reference : WO30088 Date : 02/09/2020 Description of Defect : STEEL PROTECTOR ON FRONT WALL FOR HOSE BREAKING | | | | |
| RPS25 | 989QWX | 31097 | 10/07/2020 | EXOINS | | 1 | LABOUR | MECH1 | Labour |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 31097 | 10/07/2020 | EXOINS | VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT #1<br><br>INSPECTION COMPLETED BY JESSE YOUNG 07.10.2020 | | | | |
| RPS25 | 989QWX | 31098 | 10/07/2020 | TRA | 1 | LABOUR | Labour | | 0 |
| RPS25 | 989QWX | 31098 | 10/07/2020 | TRA | SERVICE COMPLETED. | | | | |
| RPS25 | 989QWX | 31098 | 10/07/2020 | TRB | 1 | LABOUR | Labour | | 0 |
| RPS25 | 989QWX | 31098 | 10/07/2020 | TRB | SERVICE COMPLETED. | | | | |
| RPS25 | 989QWX | 31098 | 10/07/2020 | TRC | 1 | LABOUR | MECH1 | Labour | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 31098 | 10/07/2020 | TRC | COMPLETED BY JESSE 07.10.2020<br><br>REPLACE AIR HOSE UNDER TRAILER - 5M INSPECTED TAIL LIFT BATTERIES LOAD TEST + CHECKED - CHARGE SITTING @ 13.3 VOLTS REPLACED LHS CENTRE AXLE AIR BAG |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 31098 | 10/07/2020 | TRC | 0 | LABOUR | APPREN | Labour - Internal | |
| RPS25 | 989QWX | 31098 | 10/07/2020 | TRC | 16 | CON | | YAT | Consumables |
| RPS25 | 989QWX | 31098 | 10/07/2020 | TRC | 10 | SP0022M | | YAT | AIRBAG BELLOWS BPW D36 AFTERMARKET |
| RPS25 | 989QWX | 31311 | 10/08/2020 | TYRES | 15 | 33000517 | | BRIAUS01 | EX00016003 | REMOVAL: CUSTOMER PULL POINT, |
| RPS25 | 989QWX | 31311 | 10/08/2020 | TYRES | 15 | 33000085 | | BRIAUS01 | EX00016003 | ROTATE TBR TYRE, |
| RPS25 | 989QWX | 31311 | 10/08/2020 | TYRES | 15 | 77000180 | | BRIAUS01 | EX00016003 | CASE STOCK 11-22.5, |
| RPS25 | 989QWX | 31311 | 10/08/2020 | TYRES | 15 | PART | | BRIAUS01 | EX00016003 | GENERAL PART CODE,11R22.5 148/145L FS FS567 |
| RPS25 | 989QWX | 31311 | 10/08/2020 | TYRES | 15 | 33000084 | | BRIAUS01 | EX00016003 | FIT TBR TYRE, |
| RPS25 | 989QWX | 31311 | 10/08/2020 | TYRES | 15 | 33000084 | | BRIAUS01 | 99265285 | FIT TBR TYRE, |
| RPS25 | 989QWX | 31311 | 10/08/2020 | TYRES | 15 | PART | | BRIAUS01 | 99265285 | GENERAL PART CODE,11R22.5 148/145L FS FS567 |
| RPS25 | 989QWX | 31311 | 10/08/2020 | TYRES | 15 | 77000180 | | BRIAUS01 | 99265285 | CASE STOCK 11-22.5, |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 31311 | 10/08/2020 | TYRES | 15 | 33000085 | BRIAUS01 | 99265285 | ROTATE TBR TYRE, |
| RPS25 | 989QWX | 31311 | 10/08/2020 | TYRES | 15 | 33000517 | BRIAUS01 | 99265285 | REMOVAL: CUSTOMER PULL POINT, |
| RPS25 | 989QWX | 31653 | 10/21/2020 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00016141 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 31653 | 10/21/2020 | FRIVANA | 1 | LABCON | BRIVAL01 | 3689 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 31737 | 10/22/2020 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00016161 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 31737 | 10/22/2020 | FRIVANA | 1 | LABCON | BRIVAL01 | 3693 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 31846 | 10/27/2020 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00016223 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 31846 | 10/27/2020 | FRIVANA | 1 | LABCON | BRIVAL01 | 3721 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 32046 | 11/03/2020 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00016314 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 32046 | 11/03/2020 | FRIVANA | 1 | LABCON | BRIVAL01 | 3825 | LABOUR & CONSUMABLES,RP25 |
| | | | | | Reported Defect :- Defect Code : 00002979 Defect Reference : WO20737 Date : 08/10/2019 Description of Defect : REAR DOOR SEALS NOT THE BEST<br><br>NEED TO BE REPLACED U/S | | | | |
| RPS25 | 989QWX | 32384 | 11/16/2020 | DEFECT | DEFECT CLEARED | | | | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 32384 | 11/16/2020 | DEFECT | Reported Defect :- Defect Code : 00002919 Defect Reference : WO20146 Date : 16/09/2019 Description of Defect : INTERIOR OF TRAILER REAR SIDE DOOR STARTING TO CRACK<br><br>DEFECT CLEARED BY SEAN |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 32384 | 11/16/2020 | DEFECT | Reported Defect :- Defect Code : 00005081 Defect Reference : WO31098 Date : 08/10/2020 Description of Defect : FEMALE SEAL TO BE REPLACED - NONE IN STOCK<br><br>DEFECT CLEARED BY SEAN | | | | |
| RPS25 | 989QWX | 32384 | 11/16/2020 | TRA | | 0 | LABOUR | MECH1 | Labour |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | SERVICE COMPLETED SEAN<br><br>REPACED FEMALE RUBBER SEAL ON FRONT OF TRAILER<br><br>FITTED RHS SAFETY RAIL AND HANGERS FOR BOTH HANDRAIL | | | | | | |
| RPS25 | 989QWX | 32384 | 11/16/2020 | TRA | | 0 | LABOUR | APPREN | Labour - Internal | | |
| RPS25 | 989QWX | 32384 | 11/16/2020 | TRA | | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 32470 | 11/18/2020 | FRIVANA | | 1 | LABCON | | BRIVAL01 | EX00016585 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 32470 | 11/18/2020 | FRIVANA | | 1 | LABCON | | BRIVAL01 | 3983 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 32483 | 11/19/2020 | GEN | | 39 | LABEXT | | VAWAUS01 | EX00016623 | LABOUR - REPAIR TRAILER,RP25 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 32483 | 11/19/2020 | GEN | COMPLETED BY VAWDREY QLD 19.11.2020<br><br>INV: Q20826<br><br>REMOVE + REFIT LHS AND RHS REAR DOORS TO CARRY OUT REPAIRS R+R REAR DOOR SEALS AS REQUIRED CARRY OUT FIBREGLASS REPAIRS | | | | | | |
| RPS25 | 989QWX | 32483 | 11/19/2020 | GEN | 39 | LABEXT | | VAWAUS01 | Q20826 | LABOUR - REPAIR TRAILER,RP25 |
| RPS25 | 989QWX | 33393 | 01/04/2021 | TRA | 0 | LABOUR | APPREN | Labour | | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 33393 | 01/04/2021 | TRA | COMPLETED BY BEN AND SEAN<br><br>REPALCED AIR LINES ON LHS MODULE AND FRONT AXEL BOOSTER REAR AXEL LEFT AND RIGHT FRONT OF HANGER MEETS CHASSIS IS CRACKED AND SAME FOR MIDDLE LHS REPLACED 1M OF FIT |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 33393 | 01/04/2021 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | |
| RPS25 | 989QWX | 33393 | 01/04/2021 | TRA | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 33590 | 01/08/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00017163 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 34295 | 01/08/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00017545 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 33590 | 01/08/2021 | FRIVANA | SERVICE COMPLETED BY BVR 04/01/2021. | | | | | |
| RPS25 | 989QWX | 34295 | 01/08/2021 | FRIVANA | SERVICE COMPLETED BY BVR 05/01/2021. | | | | | |
| RPS25 | 989QWX | 33590 | 01/08/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | 4437 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 34295 | 01/08/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | 4438 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 33762 | 01/12/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00017307 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 33777 | 01/12/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00017308 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 33796 | 01/12/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00017309 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 33762 | 01/12/2021 | FRIVANA | SERVICE COMPLETED BY BVR ON 08/01/2021. | | | | | |
| RPS25 | 989QWX | 33777 | 01/12/2021 | FRIVANA | SERVICE COMPLETED BY BVR ON 06/01/2021. | | | | | |
| RPS25 | 989QWX | 33796 | 01/12/2021 | FRIVANA | SERVICE COMPLETED BY BVR ON 07/01/2021. | | | | | |
| RPS25 | 989QWX | 33762 | 01/12/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | 4491 | LABOUR & CONSUMABLES,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 33777 | 01/12/2021 | FRIVANA | 1 | LABCON | BRIVAL01 | 4492 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 33796 | 01/12/2021 | FRIVANA | 1 | LABCON | BRIVAL01 | 4493 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 33901 | 01/12/2021 | GEN | 39 | LAB | KIMMAR01 | EX00017370 | Labour,RP25 |
| | | | | | COMPLETED BY KIM MARTIN TRAILERS INV 72896<br><br>REMOVE AIR, ELECTRICS ,BATTERY CABLES AND FUEL LINES FROM FRONT OF TRAILER AND FRIDGE MOTOR TO REAR OF SKID PLATE OXY CUT AND DUMO EXISTING | | | | | |
| RPS25 | 989QWX | 33901 | 01/12/2021 | GEN | BOLT IN | | | | |
| RPS25 | 989QWX | 33901 | 01/12/2021 | GEN | 39 | LAB | KIMMAR01 | 72896 | Labour,RP25 |
| RPS25 | 989QWX | 33943 | 01/21/2021 | TYRES | 15 | 77000180 | BRIAUS01 | EX00017404 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 33943 | 01/21/2021 | TYRES | 15 | 77000180 | BRIAUS01 | 85265928 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 34220 | 01/25/2021 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00017510 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 34220 | 01/25/2021 | FRIVANA | SERVICED COMPLETED BY BVR 20/01/2021. | | | | |
| RPS25 | 989QWX | 34220 | 01/25/2021 | FRIVANA | 1 | LABCON | BRIVAL01 | 4662 | LABOUR & CONSUMABLES,RP25 |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 34453 | 02/08/2021 | DEFECT | Reported Defect :- Defect Code : 00005365 Defect Reference : WO32384 Date : 16/11/2020 Description of Defect : REAR DOOR AND SEAL NEED TO BE REPLACED U/S<br><br>DEFECT CLEARED BY SEAN 08.02.21 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 34453 | 02/08/2021 | DEFECT | Defect :- Defect Code : 00005683 Defect Reference : 04372 Date : 01/01/2021 Description of Defect : AIR HOUSE ON FRONT LEFT BRAKE BOOSTER FIXED BUT AIRLINE NEXT TO REPAIR IS READY TO LET GO. SPARE | | | | | |
| RPS25 | 989QWX | 35272 | 02/08/2021 | FRIVANA | 1 | LABCON | BRIVAL01 | EX00017969 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 35272 | 02/08/2021 | FRIVANA | SERVICE COMPLETED BY BVR 04/02/2021. | | | | | |
| RPS25 | 989QWX | 35272 | 02/08/2021 | FRIVANA | 1 | LABCON | BRIVAL01 | 4824 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 34768 | 02/08/2021 | FVGEN | 39 | CON | BRIVAL01 | EX00017763 | Consumables ,RP25 | |
| RPS25 | 989QWX | 34768 | 02/08/2021 | FVGEN | 39 | LAB | BRIVAL01 | EX00017763 | Labour,RP25 | |
| RPS25 | 989QWX | 34768 | 02/08/2021 | FVGEN | SERVICE COMPLETED BY BVR 04/02/2021. | | | | | |
| RPS25 | 989QWX | 34768 | 02/08/2021 | FVGEN | 39 | LAB | BRIVAL01 | 4815 | Labour,RP25 | |
| RPS25 | 989QWX | 34768 | 02/08/2021 | FVGEN | 39 | CON | BRIVAL01 | 4815 | Consumables ,RP25 | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 34453 | 02/08/2021 | TRA | 0 | LABOUR | MECH1 | Labour | | | |
| | | | | | SERVICE COMPLETED BY SEAN | | | | | | |
| | | | | | REPALCED FAULTY FRIDGE BATTERY FIXED AIRLINES TO FRONT | | | | | | |
| RPS25 | 989QWX | 34453 | 02/08/2021 | TRA | AXLE | | | | | | |
| RPS25 | 989QWX | 34453 | 02/08/2021 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 35378 | 02/25/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00017980 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 35378 | 02/25/2021 | FRIVANA | SERVICE COMPLETED BY BVR 22/02/2021. | | | | | | |
| RPS25 | 989QWX | 35378 | 02/25/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 5014 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 35741 | 03/08/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00018130 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 35741 | 03/08/2021 | FRIVANA | SERVICE COMPLETED BY BVR 05/03/2021. | | | | | | |
| RPS25 | 989QWX | 35741 | 03/08/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 5224 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 35861 | 03/17/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00018196 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 35861 | 03/17/2021 | FRIVANA | SERVICE COMPLETED BY BVR 15/03/2021 | | | | | | |
| RPS25 | 989QWX | 35861 | 03/17/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 5284 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 36080 | 03/23/2021 | TRA | 0 | LABOUR | APPREN | Labour | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 36080 | 03/23/2021 | TRA | SERVICE COMPLETED BY KEIRAN<br><br>REPAIRED TAILGATE FLAP (REWELDED HINGE) CLEANED OUT TROLLEY STOPPERS REPLACED FIRE EXTINGUISHER | | | | | |
| RPS25 | 989QWX | 36080 | 03/23/2021 | TRA | | 16 | CON | YAT | Consumables | |
| RPS25 | 989QWX | 36664 | 03/31/2021 | FRIVANSE | | 1 | LABCON | BRIVAL01 | EX00018485 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 36664 | 03/31/2021 | FRIVANSE | SERVICE COMPLETED BY BVR 31.03.2021 | | | | | |
| RPS25 | 989QWX | 36664 | 03/31/2021 | FRIVANSE | | 1 | LABCON | BRIVAL01 | 5529 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 36842 | 04/14/2021 | FRIVANA | | 1 | LABCON | BRIVAL01 | EX00018571 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 36842 | 04/14/2021 | FRIVANA | SERVICE COMPLETED BY BVR 07/04/2021 | | | | | |
| RPS25 | 989QWX | 36842 | 04/14/2021 | FRIVANA | | 1 | LABCON | BRIVAL01 | 5607 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 36762 | 04/14/2021 | FRIVANB | | 39 | 91-7709 | BRIVAL01 | EX00018539 | VIBRATION MOUNT,RP25 |
| RPS25 | 989QWX | 36762 | 04/14/2021 | FRIVANB | | 39 | 10-417 | BRIVAL01 | EX00018539 | FILTER KIT (FRIDGE MOTOR),RP25 |
| RPS25 | 989QWX | 36762 | 04/14/2021 | FRIVANB | | 39 | CON | BRIVAL01 | EX00018539 | Consumables,RP25 |
| RPS25 | 989QWX | 36762 | 04/14/2021 | FRIVANB | | 39 | LAB | BRIVAL01 | EX00018539 | Labour,RP25 |
| RPS25 | 989QWX | 36762 | 04/14/2021 | FRIVANB | SERVICE COMPLETED BY BVR 10/04/2021 | | | | | |
| RPS25 | 989QWX | 36762 | 04/14/2021 | FRIVANB | | 39 | LAB | BRIVAL01 | 5612 | Labour,RP25 |
| RPS25 | 989QWX | 36762 | 04/14/2021 | FRIVANB | | 39 | CON | BRIVAL01 | 5612 | Consumables,RP25 |
| RPS25 | 989QWX | 36762 | 04/14/2021 | FRIVANB | | 39 | 10-417 | BRIVAL01 | 5612 | FILTER KIT (FRIDGE MOTOR),RP25 |
| RPS25 | 989QWX | 36762 | 04/14/2021 | FRIVANB | | 39 | 91-7709 | BRIVAL01 | 5612 | VIBRATION MOUNT,RP25 |
| RPS25 | 989QWX | 37423 | 05/06/2021 | TRA | | 1 | LABOUR | Labour | | 0 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 37423 | 05/06/2021 | TRA | SERVICE COMPLETED. | | | | | | |
| RPS25 | 989QWX | 37423 | 05/06/2021 | TRB | 0 | LABOUR | MECH1 | Labour | | | |
| | | | | | SERVICE COMPLETED BY SEAN AND BEN | | | | | | |
| RPS25 | 989QWX | 37423 | 05/06/2021 | TRB | R&R FRIDGE BATTERY | | | | | | |
| RPS25 | 989QWX | 37423 | 05/06/2021 | TRB | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 37423 | 05/06/2021 | TRB | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 37423 | 05/06/2021 | TRB | 14 | N70 BATTERY | | YAT | N70 BATTERY | | |
| RPS25 | 989QWX | 37544 | 05/11/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00018847 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 37544 | 05/11/2021 | FRIVANA | SERVICE COMPLETED BY BVR 07/05/2021 | | | | | | |
| RPS25 | 989QWX | 37544 | 05/11/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 5904 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 37648 | 05/17/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00018924 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 37648 | 05/17/2021 | FRIVANA | SERVICE COMPLETED BY BVR 10/05/2021 | | | | | | |
| RPS25 | 989QWX | 37648 | 05/17/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 5930 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 37745 | 05/19/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00019012 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 37745 | 05/19/2021 | FRIVANA | SERVICE COMPLETED BY BVR 13/05/2021 | | | | | | |
| RPS25 | 989QWX | 37745 | 05/19/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 5966 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 37721 | 05/19/2021 | FVGEN | 39 | 44-9181 | | BRIVAL01 | | EX00019008 | SPEED SOLENOID,RP25 |
| RPS25 | 989QWX | 37721 | 05/19/2021 | FVGEN | 39 | CON | | BRIVAL01 | | EX00019008 | Consumables,RP25 |
| RPS25 | 989QWX | 37721 | 05/19/2021 | FVGEN | 39 | LAB | | BRIVAL01 | | EX00019008 | Labour,RP25 |
| RPS25 | 989QWX | 37721 | 05/19/2021 | FVGEN | SERVICE COMPLETED BY BVR 13/05/2021 | | | | | | |
| RPS25 | 989QWX | 37721 | 05/19/2021 | FVGEN | 39 | LAB | | BRIVAL01 | | 5962 | Labour,RP25 |
| RPS25 | 989QWX | 37721 | 05/19/2021 | FVGEN | 39 | CON | | BRIVAL01 | | 5962 | Consumables,RP25 |
| RPS25 | 989QWX | 37721 | 05/19/2021 | FVGEN | 39 | 44-9181 | | BRIVAL01 | | 5962 | SPEED SOLENOID,RP25 |
| RPS25 | 989QWX | 37869 | 05/21/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00019076 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 37896 | 05/21/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00019077 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 37869 | 05/21/2021 | FRIVANA | SERVICE COMPLETED BY BVR 17/05/2021 | | | | | | |
| RPS25 | 989QWX | 37896 | 05/21/2021 | FRIVANA | SERVICE COMPLETED BY BVR 18/05/2021 | | | | | | |
| RPS25 | 989QWX | 37869 | 05/21/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 5997 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 37896 | 05/21/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 5998 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 37869 | 05/21/2021 | FVGEN | 0 | LABOUR | MECH | Labour - Internal | | | |
| RPS25 | 989QWX | 37920 | 05/25/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00019082 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 37920 | 05/25/2021 | FRIVANA | SERVICE COMPLETED BY BVR 19/05/2021 | | | | | | |
| RPS25 | 989QWX | 37920 | 05/25/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 6017 | LABOUR & CONSUMABLES,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 38180 | 05/25/2021 | TYRES | 15 | 77000180 | | BRIAUS01 | EX00019172 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 38180 | 05/25/2021 | TYRES | 15 | 77000180 | | BRIAUS01 | 85932449 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 38083 | 05/31/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00019120 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 38083 | 05/31/2021 | FRIVANA | SERVICE COMPLETED BY BVR 27/05/2021 | | | | | |
| RPS25 | 989QWX | 38083 | 05/31/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | 6137 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 38143 | 06/01/2021 | TRA | 0 | LABOUR | MECH1 | Labour | | |
| RPS25 | 989QWX | 38143 | 06/01/2021 | TRA | SERVICE COMPLETED BY SEAN AND KEIRAN<br><br>REPLACED MALE FITTING AT FRONT OF TRAILER | | | | | |
| RPS25 | 989QWX | 38143 | 06/01/2021 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | |
| RPS25 | 989QWX | 38143 | 06/01/2021 | TRA | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 38590 | 06/16/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00019362 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 38590 | 06/16/2021 | FRIVANA | SERVICE COMPLETED BY BVR 11/06/2021 | | | | | |
| RPS25 | 989QWX | 38590 | 06/16/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | 6318 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 39020 | 06/24/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00019550 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 39020 | 06/24/2021 | FRIVANA | SERVICE COMPLETED BY BVR 17.06.2021 | | | | | |
| RPS25 | 989QWX | 39020 | 06/24/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | 6339 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | LAB | | TRASAL01 | EX00019524 | Labour,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | WG0210 | | TRASAL01 | EX00019524 | LAMINATING RESIN SUMMER/WINTER,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | WG1945 | | TRASAL01 | EX00019524 | CHOPPEDSTRAND MATTING 450 CSM,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | PART | | TRASAL01 | EX00019524 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | 50339 | | TRASAL01 | EX00019524 | Hinge, Trailer door (Maxicube),RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | W01661- | | TRASAL01 | EX00019524 | 3/16 AVDEL RIVET,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | WI97965 | | TRASAL01 | EX00019524 | SIKAFLEX 221 GREY 600G,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | H00033 | | TRASAL01 | EX00019524 | HOLD BACK KIT-STAINLESS STEEL,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | PART | | TRASAL01 | EX00019524 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | PART | | TRASAL01 | EX00019524 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | PART | | TRASAL01 | EX00019524 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | ENVLEV | | TRASAL01 | EX00019524 | ENVIRONMENTAL LEVY,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | CON | | TRASAL01 | EX00019524 | Consumables,RP25 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | | Consumables |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | CON | | TRASAL01 | | 679782 | ,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | ENVLEV | | TRASAL01 | | 679782 | ENVIRONMENTAL LEVY,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | PART | | TRASAL01 | | 679782 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | PART | | TRASAL01 | | 679782 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | PART | | TRASAL01 | | 679782 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | H00033 | | TRASAL01 | | 679782 | HOLD BACK KIT-STAINLESS STEEL,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | WI97965 | | TRASAL01 | | 679782 | SIKAFLEX 221 GREY 600G,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | W01661- | | TRASAL01 | | 679782 | 3/16 AVDEL RIVET,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | 50339 | | TRASAL01 | | 679782 | Hinge, Trailer door (Maxicube),RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | PART | | TRASAL01 | | 679782 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | WG1945 | | TRASAL01 | | 679782 | CHOPPEDSTRAND MATTING 450 CSM,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | WG0210 | | TRASAL01 | | 679782 | LAMINATING RESIN SUMMER/WINTER,RP25 |
| RPS25 | 989QWX | 38952 | 06/24/2021 | GEN | 39 | LAB | | TRASAL01 | | 679782 | Labour,RP25 |
| RPS25 | 989QWX | 39139 | 06/28/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00019580 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 39163 | 06/28/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00019581 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 39139 | 06/28/2021 | FRIVANA | SERVICE COMPLETED BY BVR 23.06.2021 | | | | | | |
| RPS25 | 989QWX | 39163 | 06/28/2021 | FRIVANA | SERVICE COMPLETED BY BVR 24.06.2021 | | | | | | |
| RPS25 | 989QWX | 39139 | 06/28/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 6429 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 39163 | 06/28/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 6430 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 39362 | 07/06/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00019667 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 39362 | 07/06/2021 | FRIVANA | SERVICE COMPLETED BY BVR 02/07/2021 | | | | | | |
| RPS25 | 989QWX | 39362 | 07/06/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 6558 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 39611 | 07/14/2021 | TRA | 0 | LABOUR | MECH1 | Labour | | | |
| RPS25 | 989QWX | 39611 | 07/14/2021 | TRA | SERVICE COMPLETED SEAN AND KEIRAN | | | | | | |
| RPS25 | 989QWX | 39611 | 07/14/2021 | TRA | 0 | LABOUR | APPREN | 1 | 85 | 85 | |
| RPS25 | 989QWX | 39611 | 07/14/2021 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 39975 | 07/18/2021 | GEN | 39 | LAB | | KIMMAR01 | | EX00019924 | Labour,989QWX |
| RPS25 | 989QWX | 39975 | 07/18/2021 | GEN | 39 | LAB | | KIMMAR01 | | 72975 | Labour,989QWX |
| RPS25 | 989QWX | 40032 | 07/23/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00019934 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40032 | 07/23/2021 | FRIVANA | SERVICE COMPLETED BY BVR 20/07/2021 | | | | | | |
| RPS25 | 989QWX | 40032 | 07/23/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 6749 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40341 | 07/30/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00020054 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40383 | 07/30/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00020055 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40419 | 07/30/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00020056 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40458 | 07/30/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00020057 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40488 | 07/30/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00020058 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40341 | 07/30/2021 | FRIVANA | SERVICE COMPLETED BY BVR 22.07.2021 | | | | | | |
| RPS25 | 989QWX | 40383 | 07/30/2021 | FRIVANA | SERVICE COMPLETED BY BVR 23/07/2021 | | | | | | |
| RPS25 | 989QWX | 40419 | 07/30/2021 | FRIVANA | SERVICE COMPLETED BY BVR 26/07/2021 | | | | | | |
| RPS25 | 989QWX | 40458 | 07/30/2021 | FRIVANA | SERVICE COMPLETED BY BVR 28/07/2021 | | | | | | |
| RPS25 | 989QWX | 40488 | 07/30/2021 | FRIVANA | SERVICE COMPLETED BY BVR 27/07/2021 | | | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 40341 | 07/30/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | 6820 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40383 | 07/30/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | 6821 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40419 | 07/30/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | 6854 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40458 | 07/30/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | 6879 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40488 | 07/30/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | 6883 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40176 | 07/30/2021 | FVGEN | 39 | 33-0230 | | BRIVAL01 | EX00020031 | SUCTION SERVICE VALVE ORING,RP25 |
| RPS25 | 989QWX | 40176 | 07/30/2021 | FVGEN | 39 | R404A | | BRIVAL01 | EX00020031 | GAS R404A,RP25 |
| RPS25 | 989QWX | 40176 | 07/30/2021 | FVGEN | 39 | CON | | BRIVAL01 | EX00020031 | Consumables,RP25 |
| RPS25 | 989QWX | 40176 | 07/30/2021 | FVGEN | 39 | LAB | | BRIVAL01 | EX00020031 | Labour,RP25 |
| RPS25 | 989QWX | 40176 | 07/30/2021 | FVGEN | SERVICE COMPLETED BY BVR 23.07.2021 | | | | | |
| RPS25 | 989QWX | 40176 | 07/30/2021 | FVGEN | 39 | LAB | | BRIVAL01 | 6808 | Labour,RP25 |
| RPS25 | 989QWX | 40176 | 07/30/2021 | FVGEN | 39 | CON | | BRIVAL01 | 6808 | Consumables,RP25 |
| RPS25 | 989QWX | 40176 | 07/30/2021 | FVGEN | 39 | R404A | | BRIVAL01 | 6808 | GAS R404A,RP25 |
| RPS25 | 989QWX | 40176 | 07/30/2021 | FVGEN | 39 | 33-0230 | | BRIVAL01 | 6808 | SUCTION SERVICE VALVE ORING,RP25 |
| RPS25 | 989QWX | 40264 | 08/03/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00020072 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40309 | 08/03/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00020074 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40264 | 08/03/2021 | FRIVANA | SERVICE COMPLETED BY BVR 29/07/2021 | | | | | |
| RPS25 | 989QWX | 40309 | 08/03/2021 | FRIVANA | SERVICE COMPLETED BY BVR 30/07/2021 | | | | | |
| RPS25 | 989QWX | 40264 | 08/03/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | 6916 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40309 | 08/03/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | 6924 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 41117 | 08/17/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | EX00020315 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 41117 | 08/17/2021 | FRIVANA | SERVICE COMPLETED BY BVR 17/08/2021 | | | | | |
| RPS25 | 989QWX | 41117 | 08/17/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | 6968 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 40882 | 08/17/2021 | GEN | 39 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 40882 | 08/17/2021 | GEN | REPAIR COMPLETED.<br><br>TRACKER INSTALLED: 86528404 1042593 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 41025 | 08/19/2021 | DEFECT | Defect :- Defect Code : 00005687 Defect Reference : WO33393 Date : 04/01/2021 Description of Defect : REAR AXEL LEFT AND RIGHT FRONT OF HANGER MEETS CHASSIS IS CRACKED AND SAME FOR MIDDLE LHS |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 41025 | 08/19/2021 | DEFECT | Reported Defect :- Defect Code : 00004885 Defect Reference : WO30088 Date : 02/09/2020 Description of Defect : CHASSIS RAIL CRACKED LHS FRONT AXLE. | | | | |
| RPS25 | 989QWX | 41025 | 08/19/2021 | TRA | | 0 | LABOUR | MECH | Labour |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 41025 | 08/19/2021 | TRA | SERVICE COMPLETED BY SEAN AND KEIRAN.<br><br>REPAIRED AND PATCH CHASSIS ON LH SIDE INBETWEEN FRONT AND MIDDLE GUARD. ALSO REPAIRED MULTIPLE CRACKS ON BODY/CHASSIS. | | | | | | |
| RPS25 | 989QWX | 41025 | 08/19/2021 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 41025 | 08/19/2021 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 41179 | 08/20/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00020320 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 41179 | 08/20/2021 | FRIVANA | SERVICE COMPLETED BY BVR 20/08/2021 | | | | | | |
| RPS25 | 989QWX | 41179 | 08/20/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 7192 | LABOUR & CONSUMABLES,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | AIR GAUGE:20250 ADJUSTED:21000 WEIGHBRIDGE:20900 | | | | | |
| RPS25 | 989QWX | 41664 | 09/01/2021 | WEICAL | AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | | |
| RPS25 | 989QWX | 41493 | 09/02/2021 | FRIVANA | | 1 | LABCON | BRIVAL01 | EX00020412 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 41607 | 09/02/2021 | FRIVANA | | 1 | LABCON | BRIVAL01 | EX00020473 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 41493 | 09/02/2021 | FRIVANA | SERVICE COMPLETED BY BVR 31/08/2021 | | | | | |
| RPS25 | 989QWX | 41607 | 09/02/2021 | FRIVANA | SERVICE COMPLETED BY BVR 01/09/2021 | | | | | |
| RPS25 | 989QWX | 41493 | 09/02/2021 | FRIVANA | | 1 | LABCON | BRIVAL01 | 7319 | LABOUR & CONSUMABLES,RP25 |
| RPS25 | 989QWX | 41607 | 09/02/2021 | FRIVANA | | 1 | LABCON | BRIVAL01 | 7332 | LABOUR & CONSUMABLES,RP25 |
| | | | | | AIR GAUGE: 16750 ADJUSTED:16500 WEIGHBRIDGE:16270 | | | | | |
| RPS25 | 989QWX | 41567 | 09/07/2021 | WEICAL | AIR GAUGE CALIBRATION COMPLETED INCORRECTLY. | | | | | |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 43567 | 09/08/2021 | FRIVANB | 39 | LABOUR | MECH | 1 | 85 | 85 | | |
| RPS25 | 989QWX | 41728 | 09/09/2021 | TYRES | 15 | 77000180 | | BRIAUS01 | | EX00020498 | CASE STOCK 11-22.5,RP25 | |
| RPS25 | 989QWX | 41728 | 09/09/2021 | TYRES | 15 | 33000096 | | BRIAUS01 | | EX00020498 | PUNCTURE REPAIR TBR,RP25 | |
| RPS25 | 989QWX | 41728 | 09/09/2021 | TYRES | 15 | 33000096 | | BRIAUS01 | | 86464704 | PUNCTURE REPAIR TBR,RP25 | |
| RPS25 | 989QWX | 41728 | 09/09/2021 | TYRES | 15 | 77000180 | | BRIAUS01 | | 86464704 | CASE STOCK 11-22.5,RP25 | |
| RPS25 | 989QWX | 42138 | 09/13/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00020647 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 42138 | 09/13/2021 | FRIVANA | SERVICE COMPLETED BY BVR 13/09/2021 | | | | | | | |
| RPS25 | 989QWX | 42138 | 09/13/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 7499 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 42118 | 09/14/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00020646 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 42118 | 09/14/2021 | FRIVANA | SERVICE COMPLETED BY BVR 14/09/2021 | | | | | | | |
| RPS25 | 989QWX | 42118 | 09/14/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 7502 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 42339 | 09/24/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00020702 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 42339 | 09/24/2021 | FRIVANA | SERVICE COMPLETED BY BVR 24/09/2021 | | | | | | | |
| RPS25 | 989QWX | 42339 | 09/24/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 7709 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 42713 | 10/06/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00020871 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 42713 | 10/06/2021 | FRIVANA | SERVICE COMPLETED BY BVR 06/10/2021 | | | | | | | |
| RPS25 | 989QWX | 42713 | 10/06/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 7853 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 43150 | 10/18/2021 | WEICAL | AIR GAUGE:17000 ADJUSTED:19000 WEIGHBRIDGE:18570<br><br>AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | | | | |
| RPS25 | 989QWX | 43518 | 11/01/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | EX00021213 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 43518 | 11/01/2021 | FRIVANA | SERVICE COMPLETED BY BVR 01/11/2021 | | | | | | | |
| RPS25 | 989QWX | 43518 | 11/01/2021 | FRIVANA | 1 | LABCON | | BRIVAL01 | | 8107 | LABOUR & CONSUMABLES,RP25 | |
| RPS25 | 989QWX | 43568 | 11/09/2021 | FRIVANB | 39 | 100417 | | BRIVAL01 | | EX00021254 | Filter Service Kit, Fridge Motor, SLX-400,RP25 | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 43568 | 11/09/2021 | FRIVANB | 39 | CON | | BRIVAL01 | EX00021254 | Consumables,RP25 |
| RPS25 | 989QWX | 43568 | 11/09/2021 | FRIVANB | 39 | LAB | | BRIVAL01 | EX00021254 | Labour,RP25 |
| RPS25 | 989QWX | 43568 | 11/09/2021 | FRIVANB | SERVICE COMPLETED BVR 09/11/2021 | | | | | |
| RPS25 | 989QWX | 43568 | 11/09/2021 | FRIVANB | 39 | | 100417 | BRIVAL01 | 8199 | Filter Service Kit, Fridge Motor, SLX-400,RP25 |
| RPS25 | 989QWX | 43568 | 11/09/2021 | FRIVANB | 39 | CON | | BRIVAL01 | 8199 | Consumables,RP25 |
| RPS25 | 989QWX | 43568 | 11/09/2021 | FRIVANB | 39 | LAB | | BRIVAL01 | 8199 | Labour,RP25 |
| RPS25 | 989QWX | 43699 | 11/18/2021 | DEFECT | Reported Defect :- Defect Code : 00007037 Defect Reference : INTERNAL Date : 14/10/2021 Description of Defect : TAILGATE BUTTONS CHECKED AND REMOTE CONTROLLER FITTED | | | | | |
| RPS25 | 989QWX | 43699 | 11/18/2021 | TRA | 0 | LABOUR | MECH1 | Labour | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | SERVICE COMPLETED BY IAN AND BEN | | | | | |
| RPS25 | 989QWX | 43699 | 11/18/2021 | TRA | REPLACE DOWN BUTTON ON TAILGATE LIFTER REPLACE LATCH ON FRIDGE DOORS REFIT PARK LIGHT L/H TOP FRONT | | | | | |
| RPS25 | 989QWX | 43699 | 11/18/2021 | TRA | | 0 | LABOUR | APPREN | Labour - Internal | |
| RPS25 | 989QWX | 43699 | 11/18/2021 | TRA | | 16 | CON | | YAT | Consumables |
| RPS25 | 989QWX | 44072 | 12/07/2021 | EXOINS | | 1 | LABOUR | MECH | Labour | |
| RPS25 | 989QWX | 44072 | 12/07/2021 | EXOINS | VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1 INSPECTION COMPLETED BY DIESEL SERVICES | | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 44072 | 12/07/2021 | GEN | 39 | PART | | DIESER01 | EX00021728 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | GEN | 39 | PART | | DIESER01 | EX00021728 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | GEN | 39 | LAB | | DIESER01 | EX00021728 | Labour,RP25 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | GEN | 39 | LAB | | DIESER01 | EX00021728 | Labour,RP25 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | GEN | 39 | LAB | | DIESER01 | EX00021728 | Labour,RP25 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | GEN | 39 | LAB | | DIESER01 | EX00021728 | Labour,RP25 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | GEN | 39 | CON | | DIESER01 | EX00021728 | Consumables,RP25 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | GEN | 39 | CON | | DIESER01 | 27081 | Consumables,RP25 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | GEN | 39 | LAB | | DIESER01 | 27081 | Labour,RP25 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | GEN | 39 | LAB | | DIESER01 | 27081 | Labour,RP25 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | GEN | 39 | LAB | | DIESER01 | 27081 | Labour,RP25 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | GEN | 39 | LAB | | DIESER01 | 27081 | Labour,RP25 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | GEN | 39 | PART | | DIESER01 | 27081 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | GEN | 39 | PART | | DIESER01 | 27081 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | TRA | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | TRA | SERVICE COMPLETED. | | | | | |
| RPS25 | 989QWX | 44072 | 12/07/2021 | TRB | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 44072 | 12/07/2021 | TRB | SERVICE COMPLETED. | | | | | |
| RPS25 | 989QWX | 44072 | 12/07/2021 | TRC | 1 | LABOUR | Labour | | | 0 |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 44072 | 12/07/2021 | TRC | COMPLETED BY DIESEL SERVICES INV# 00027081<br><br>C&D SERVICE WITH BEARINGS PACK ALL BEARINGS, SET ALL BEARINGS ADJUST ALL BRAKES REPLACE RH MIDDLE AIRBAG WELD CRACKS IN RAIL (LH FRONT) DEGREASE |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 44072 | 12/07/2021 | TRC | 11 | 0980107040TSSC | YAT | KIT W/BRG & SEAL 10T ECO | |
| RPS25 | 989QWX | 44072 | 12/07/2021 | TRC | 11 | 84012/50 | YAT | REFLECTOR-RED 60MM | |
| RPS25 | 989QWX | 44072 | 12/07/2021 | TRC | 11 | SP0062M | YAT | AIRBAG ASSEMBLY | |
| RPS25 | 989QWX | 44072 | 12/07/2021 | TRC | 11 | KZC1012/01BO | YAT | KING PIN 2" JOST WITH BOLTS | |
| RPS25 | 989QWX | 44087 | 12/08/2021 | TYRES | 15 | 33000188 | BRIAUS01 | EX00021570 | B FLEET PRESSURE CHECK,RP25 |
| RPS25 | 989QWX | 44091 | 12/08/2021 | TYRES | 15 | 77000180 | BRIAUS01 | EX00021574 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 44087 | 12/08/2021 | TYRES | 15 | 33000188 | BRIAUS01 | 86931412 | B FLEET PRESSURE CHECK,RP25 |
| RPS25 | 989QWX | 44091 | 12/08/2021 | TYRES | 15 | 33000084 | BRIAUS01 | EX00021574 | FIT TBR TYRE,RP25 |
| RPS25 | 989QWX | 44091 | 12/08/2021 | TYRES | 15 | 33000084 | BRIAUS01 | 86931411 | FIT TBR TYRE,RP25 |
| RPS25 | 989QWX | 44091 | 12/08/2021 | TYRES | 15 | 77000180 | BRIAUS01 | 86931411 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 44186 | 12/10/2021 | TYRES | 15 | 33000114 | BRIAUS01 | EX00021657 | RE-TORQUE TRUCK WHEEL EA WHEEL,RP25 |
| RPS25 | 989QWX | 44186 | 12/10/2021 | TYRES | 15 | 33000114 | BRIAUS01 | 86947682 | RE-TORQUE TRUCK WHEEL EA WHEEL,RP25 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 45162 | 02/08/2022 | TRA | 0 | LABOUR | APPRENB | Labour | | | |
| RPS25 | 989QWX | 45162 | 02/08/2022 | TRA | SERVICE COMPLETED BY BEN AND IAN | | | | | | |
| RPS25 | 989QWX | 45162 | 02/08/2022 | TRA | CHANGE FIRE EXTINGUISHER | | | | | | |
| RPS25 | 989QWX | 45162 | 02/08/2022 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 45162 | 02/08/2022 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 45219 | 02/10/2022 | TYRES | 15 | 77000180 | | BRIAUS01 | | EX00022418 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 45219 | 02/10/2022 | TYRES | 15 | 77000180 | | BRIAUS01 | | 87242983 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 45974 | 02/23/2022 | WEICAL | AIR GAUGE: 15.00 ADJUSTED: 15.00 WEIGHBRIDGE: 14.660 | | | | | | |
| RPS25 | 989QWX | 46561 | 03/30/2022 | TRA | AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | | | |
| RPS25 | 989QWX | 46561 | 03/30/2022 | TRA | 1 | LABOUR | Labour | | | | 0 |
| RPS25 | 989QWX | 46561 | 03/30/2022 | TRA | SERVICE COMPLETED BRENDAN, IAN AND KEIRAN | | | | | | |
| RPS25 | 989QWX | 46561 | 03/30/2022 | TRA | 0 | LABOUR | APPRENK | Labour - Internal | | | |
| RPS25 | 989QWX | 46561 | 03/30/2022 | TRA | 0 | LABOUR | MECH1 | Labour - Internal | | | |
| RPS25 | 989QWX | 46561 | 03/30/2022 | TRA | 0 | LABOUR | SUBMEC | Labour - Internal | | | |
| RPS25 | 989QWX | 46561 | 03/30/2022 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 46650 | 04/01/2022 | GEN | 0 | LABOUR | MECH1 | Labour | | | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 46650 | 04/01/2022 | GEN | REPAIR COMPLETED BY IAN<br><br>CHECK AND REFIT REAR SEAL TO LH DOOR | | | | | | |
| RPS25 | 989QWX | 46650 | 04/01/2022 | GEN | | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 47184 | 04/05/2022 | FVGEN | | 39 | CON | | BRIVAL01 | EX00023426 | Consumables,RP25 |
| RPS25 | 989QWX | 47184 | 04/05/2022 | FVGEN | | 39 | LAB | | BRIVAL01 | EX00023426 | Labour,RP25 |
| RPS25 | 989QWX | 47184 | 04/05/2022 | FVGEN | SERVICE COMPLETED BY BVR - 04.04.2022 | | | | | | |
| RPS25 | 989QWX | 47184 | 04/05/2022 | FVGEN | | 39 | LAB | | BRIVAL01 | 10027 | Labour,RP25 |
| RPS25 | 989QWX | 47184 | 04/05/2022 | FVGEN | | 39 | CON | | BRIVAL01 | 10027 | Consumables,RP25 |
| RPS25 | 989QWX | 47649 | 05/17/2022 | TRA | | 0 | LABOUR | APPRENB | Labour | | |
| RPS25 | 989QWX | 47649 | 05/17/2022 | TRA | SERVICE COMPLETEDBY BEN AND BRENDAN<br><br>NOT EQUIPPED WITH EBS - 17/05/2022 | | | | | | |
| RPS25 | 989QWX | 47649 | 05/17/2022 | TRA | | 0 | LABOUR | SUBMEC | Labour - Internal | | |
| RPS25 | 989QWX | 47649 | 05/17/2022 | TRA | | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 47861 | 05/25/2022 | GEN | | 0 | LABOUR | SUBMEC | Labour | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 47861 | 05/25/2022 | GEN | REPAIR COMPLETED BY BRENDAN AND TYLER<br><br>REFIT FALLEN OFF MUDGAURD AND REPAIR ALL BENT BRACKETS . NEW BOLTS NUTS AND WASHERS FITTED | | | | | |
| RPS25 | 989QWX | 47861 | 05/25/2022 | GEN | 0 | LABOUR | TRADEA | Labour - Internal | | |
| RPS25 | 989QWX | 47861 | 05/25/2022 | GEN | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 47993 | 05/27/2022 | GEN | 39 | PART | | BRIVAL01 | EX00023822 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 47993 | 05/27/2022 | GEN | 39 | 61-0600 | | BRIVAL01 | EX00023822 | RECIEVER DRIER, FRIDGE MOTOR,RP25 |
| RPS25 | 989QWX | 47993 | 05/27/2022 | GEN | 39 | PART | | BRIVAL01 | EX00023822 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 47993 | 05/27/2022 | GEN | 39 | R404A | | BRIVAL01 | EX00023822 | GAS R404A,RP25 |
| RPS25 | 989QWX | 47993 | 05/27/2022 | GEN | 39 | CON | | BRIVAL01 | EX00023822 | Consumables,RP25 |
| RPS25 | 989QWX | 47993 | 05/27/2022 | GEN | 39 | LAB | | BRIVAL01 | EX00023822 | Labour,RP25 |
| RPS25 | 989QWX | 47993 | 05/27/2022 | GEN | SERVICE COMPLETED BY BVR 27.05.2022 | | | | | |
| RPS25 | 989QWX | 47993 | 05/27/2022 | GEN | 39 | LAB | | BRIVAL01 | 10869 | Labour,RP25 |
| RPS25 | 989QWX | 47993 | 05/27/2022 | GEN | 39 | CON | | BRIVAL01 | 10869 | Consumables,RP25 |
| RPS25 | 989QWX | 47993 | 05/27/2022 | GEN | 39 | R404A | | BRIVAL01 | 10869 | GAS R404A,RP25 |
| RPS25 | 989QWX | 47993 | 05/27/2022 | GEN | 39 | PART | | BRIVAL01 | 10869 | GENERAL PART CODE,RP25 |
| RPS25 | 989QWX | 47993 | 05/27/2022 | GEN | 39 | 61-0600 | | BRIVAL01 | 10869 | RECIEVER DRIER, FRIDGE MOTOR,RP25 |
| RPS25 | 989QWX | 47993 | 05/27/2022 | GEN | 39 | PART | | BRIVAL01 | 10869 | GENERAL PART CODE,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 48168 | 06/06/2022 | FVGEN | | 39 | CON | BRIVAL01 | EX00023921 | Consumables,RP25 |
| RPS25 | 989QWX | 48168 | 06/06/2022 | FVGEN | | 39 | LAB | BRIVAL01 | EX00023921 | Labour,RP25 |
| RPS25 | 989QWX | 48168 | 06/06/2022 | FVGEN | | 39 | 41-7064 | BRIVAL01 | EX00023921 | OIL PRESSURE SWITCH FRIDGE,RP25 |
| RPS25 | 989QWX | 48168 | 06/06/2022 | FVGEN | SERVICE COMPLETED BY BVR - 03.06.2022 - REMOVED AND REPLACE OIL PRESSURE SWITCH - UNIT RUN ON TEST - PRETRIP PASSED | | | | | |
| RPS25 | 989QWX | 48168 | 06/06/2022 | FVGEN | | 39 | 41-7064 | BRIVAL01 | 11009 | OIL PRESSURE SWITCH FRIDGE,RP25 |
| RPS25 | 989QWX | 48168 | 06/06/2022 | FVGEN | | 39 | LAB | BRIVAL01 | 11009 | Labour,RP25 |
| RPS25 | 989QWX | 48168 | 06/06/2022 | FVGEN | | 39 | CON | BRIVAL01 | 11009 | Consumables,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | AIR GAUGE: 18000 ADJUSTED : 20750 WEIGHBRIDGE: 20500 | | | | | |
| RPS25 | 989QWX | 48639 | 06/26/2022 | WEICAL | AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | | |
| RPS25 | 989QWX | 48599 | 06/28/2022 | TRA | 1 | LABOUR | Labour | | | 0 |
| RPS25 | 989QWX | 48599 | 06/28/2022 | TRA | SERVICE COMPLETED. | | | | | |
| RPS25 | 989QWX | 48599 | 06/28/2022 | TRB | 0 | LABOUR | APPRENK | Labour | | |
| RPS25 | 989QWX | 48599 | 06/28/2022 | TRB | SERVICE COMPLETED BY KEIRAN AND TYLER REPLACED FLAT BATTERY IN TAILGATE LIFTER | | | | | |
| RPS25 | 989QWX | 48599 | 06/28/2022 | TRB | 0 | LABOUR | APPREN | Labour - Internal | | |
| RPS25 | 989QWX | 48599 | 06/28/2022 | TRB | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 48599 | 06/28/2022 | TRB | 14 | MF70ZZDT | | YAT | BATTERY DEEP CYCLE & TRUCK | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 48995 | 06/28/2022 | WEICAL | AIR GAUGE: 20500 ADJUSTED : 17000 WEIGHBRIDGE: 16620 | | | | |
| RPS25 | 989QWX | 48995 | 06/28/2022 | WEICAL | AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | |
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | 39 | 78-1360 | BRIVAL01 | EX00024198 | ALTERNATOR BELT FRIDGE,RP25 |
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | 39 | 45-2258 | BRIVAL01 | EX00024198 | 120 AMP ALTERNATOR,RP25 |
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | 39 | 820CCA | BRIVAL01 | EX00024198 | HEAVY DUTY BATTERY (FRIDGE MOTOR),RP25 |
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | 39 | PART | BRIVAL01 | EX00024198 | POSITIVE BATTERY TERMINAL,RP25 |
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | 39 | PART | BRIVAL01 | EX00024198 | HOT GAS VALVE COIL,RP25 |
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | 39 | CON | BRIVAL01 | EX00024198 | Consumables ,RP25 |
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | 39 | LAB | BRIVAL01 | EX00024198 | Labour Call out rate,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | COMPLETED BY BVR<br><br>Travel to site and inspect unit Waited for trailer to be unloaded Found unit showing code 45 Remove and replace u/s Z1 hot gas coil Remove and replace u/s battery and positive | | | | | |
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | | 39 | LAB | BRIVAL01 | 11344 | Labour Call out rate,RP25 |
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | | 39 | CON | BRIVAL01 | 11344 | Consumables,RP25 |
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | | 39 | PART | BRIVAL01 | 11344 | HOT GAS VALVE COIL,RP25 |
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | | 39 | PART | BRIVAL01 | 11344 | POSITIVE BATTERY TERMINAL,RP25 |
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | | 39 | 820CCA | BRIVAL01 | 11344 | HEAVY DUTY BATTERY (FRIDGE MOTOR),RP25 |
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | | 39 | 45-2258 | BRIVAL01 | 11344 | 120 AMP ALTERNATOR,RP25 |
| RPS25 | 989QWX | 48661 | 06/29/2022 | FVGEN | | 39 | 78-1360 | BRIVAL01 | 11344 | ALTERNATOR BELT FRIDGE,RP25 |

| | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 49327 | 07/21/2022 | GEN | | 39 | con | | BRIAUS01 | | EX00024474 | Consumables,rp25 |
| RPS25 | 989QWX | 49327 | 07/21/2022 | GEN | | 39 | LAB | | BRIAUS01 | | EX00024474 | Labour,RP25 |
| RPS25 | 989QWX | 49327 | 07/21/2022 | GEN | SERVICE COMPLETED BY BVR 21.07.2022<br><br>RESEALED LEAKING OIL FILTER HOUSING AS REQUIRED | | | | | | | |
| RPS25 | 989QWX | 49327 | 07/21/2022 | GEN | | 39 | LAB | | BRIVAL01 | | 11615 | Labour,RP25 |
| RPS25 | 989QWX | 49327 | 07/21/2022 | GEN | | 39 | con | | BRIVAL01 | | 11615 | Consumables,rp25 |
| RPS25 | 989QWX | 49827 | 08/10/2022 | FRIVANSE | | 39 | 100417 | | BRIVAL01 | | EX00024747 | Filter Service Kit, Fridge Motor, SLX-400,RP25 |
| RPS25 | 989QWX | 49827 | 08/10/2022 | FRIVANSE | | 39 | CON | | BRIVAL01 | | EX00024747 | Consumables,RP25 |
| RPS25 | 989QWX | 49827 | 08/10/2022 | FRIVANSE | | 39 | LAB | | BRIVAL01 | | EX00024747 | Labour,RP25 |
| RPS25 | 989QWX | 49827 | 08/10/2022 | FRIVANSE | SERVICE COMPLETED BY BVR 09.08.2022 | | | | | | | |
| RPS25 | 989QWX | 49827 | 08/10/2022 | FRIVANSE | | 39 | 100417 | | BRIVAL01 | | 11779 | Filter Service Kit, Fridge Motor, SLX-400,RP25 |
| RPS25 | 989QWX | 49827 | 08/10/2022 | FRIVANSE | | 39 | CON | | BRIVAL01 | | 11779 | Consumables,RP25 |
| RPS25 | 989QWX | 49827 | 08/10/2022 | FRIVANSE | | 39 | LAB | | BRIVAL01 | | 11779 | Labour,RP25 |
| RPS25 | 989QWX | 49928 | 08/16/2022 | TRA | | 0 | LABOUR | APPREN | 1 | 105 | 105 | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | SERVICE COMPLETED BY TYLER AND KEIRAN | | | | | |
| RPS25 | 989QWX | 49928 | 08/16/2022 | TRA | REPAIRED WIRING ON TAIL GATE | | | | | |
| RPS25 | 989QWX | 49928 | 08/16/2022 | TRA | | 0 | LABOUR | MECH1 | Labour - Internal | |
| RPS25 | 989QWX | 49928 | 08/16/2022 | TRA | | 16 | CON | | YAT | Consumables |
| | | | | | AIR GAUGE: 17750 ADJUSTED: 18000 WEIGHBRIDGE: 17740 | | | | | |
| RPS25 | 989QWX | 50927 | 09/28/2022 | WEICAL | AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | AIR GAUGE: 10500 ADJUSTED :10000 WEIGHBRIDGE: 9620 | | | | |
| RPS25 | 989QWX | 50945 | 09/29/2022 | WEICAL | | AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | |
| RPS25 | 989QWX | 51062 | 09/30/2022 | GEN | 39 | CON | BRIVAL01 | EX00025350 | | Consumables ,RP25 |
| RPS25 | 989QWX | 51062 | 09/30/2022 | GEN | 39 | LAB | BRIVAL01 | EX00025350 | | Labour,RP25 |
| RPS25 | 989QWX | 51062 | 09/30/2022 | GEN | 39 | CON | BRIVAL01 | 12445 | | Consumables ,RP25 |
| RPS25 | 989QWX | 51062 | 09/30/2022 | GEN | 39 | LAB | BRIVAL01 | 12445 | | Labour,RP25 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | AIR GAUGE: 20500 ADJUSTED: 21000 WEIGHBRIDGE: 20560 | | | | | | |
| RPS25 | 989QWX | 51249 | 10/05/2022 | WEICAL | AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | | | |
| RPS25 | 989QWX | 51572 | 10/21/2022 | TRA | 0 | LABOUR | APPREN | Labour | | | |
| RPS25 | 989QWX | 51572 | 10/21/2022 | TRA | SERVICE COMPLETED BY TYLER AND FLYNN | | | | | | |
| RPS25 | 989QWX | 51572 | 10/21/2022 | TRA | 0 | LABOUR | APPRENF | Labour - Internal | | | |
| RPS25 | 989QWX | 51572 | 10/21/2022 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 51628 | 10/24/2022 | TYRES | 15 | 77000180 | | BRIAUS01 | | EX00025625 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 51628 | 10/24/2022 | TYRES | 15 | 77000180 | | BRIAUS01 | | 88574102 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | 39 | 78-0603 | | BRIVAL01 | | EX00025838 | SB Series Fridge motor fanbelt,RP25 |
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | 39 | 78-0629 | | BRIVAL01 | | EX00025838 | SB series fridge motor fanbelt,RP25 |
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | 39 | 78-1360 | | BRIVAL01 | | EX00025838 | ALTERNATOR BELT FRIDGE,RP25 |
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | 39 | 66-7636 | | BRIVAL01 | | EX00025838 | PILOT SOLENOID,RP25 |
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | 39 | R404A | | BRIVAL01 | | EX00025838 | GAS R404A,RP25 |
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | 39 | CON | | BRIVAL01 | | EX00025838 | Consumables,RP25 |
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | 39 | LAB | | BRIVAL01 | | EX00025838 | Labour,RP25 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | 07/11/2022 - TRAVELLED TO SITE AND INSPECTED UNIT - CALIBRATED SENSORS - REMOVED AND REPLACED BELTS - REMOVED AND REPLACED SOLENOID - TOPPED AT GAS - UNIT RUN ON TEST<br><br>SERVICE COMPLETED BY BVR | | | | | | |
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | | 39 | LAB | | BRIVAL01 | 13001 | Labour,RP25 |
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | | 39 | CON | | BRIVAL01 | 13001 | Consumables,RP25 |
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | | 39 | R404A | | BRIVAL01 | 13001 | GAS R404A,RP25 |
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | | 39 | 66-7636 | | BRIVAL01 | 13001 | PILOT SOLENOID,RP25 |
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | | 39 | 78-1360 | | BRIVAL01 | 13001 | ALTERNATOR BELT FRIDGE,RP25 |
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | | 39 | 78-0629 | | BRIVAL01 | 13001 | SB series fridge motor fanbelt,RP25 |
| RPS25 | 989QWX | 51991 | 11/10/2022 | GEN | | 39 | 78-0603 | | BRIVAL01 | 13001 | SB Series Fridge motor fanbelt,RP25 |
| RPS25 | 989QWX | 53092 | 12/30/2022 | TYRES | | 15 | 33000096 | | BRIAUS01 | EX00026529 | PUNCTURE REPAIR TBR,RP25 |
| RPS25 | 989QWX | 53092 | 12/30/2022 | TYRES | | 15 | 33000096 | | BRIAUS01 | 4.72E+09 | PUNCTURE REPAIR TBR,RP25 |
| RPS25 | 989QWX | 53176 | 01/05/2023 | TRA | | 1 | LABOUR | APPREN | Labour | | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 53176 | 01/05/2023 | TRA | SERVICE COMPLETED. REPLACED LH MIDDLE SHOCK | | | | | | |
| RPS25 | 989QWX | 53176 | 01/05/2023 | TRA | 0 | LABOUR | APPRENF | Labour - Internal | | | |
| RPS25 | 989QWX | 53176 | 01/05/2023 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 53176 | 01/05/2023 | TRA | 1 | F5002 | | YAT | SHOCK ABSORBER, BPW LONG | | |
| RPS25 | 989QWX | 53344 | 01/13/2023 | GEN | 39 | CON | | MTTRAI01 | | EX00026694 | Consumables Electrical fault tailgate loaer blowing fuses Check over replace 10amp with 15amp run & test |
| RPS25 | 989QWX | 53344 | 01/13/2023 | GEN | 39 | LABEXT | | MTTRAI01 | | EX00026694 | Labour External, |
| RPS25 | 989QWX | 53344 | 01/13/2023 | GEN | 39 | LABEXT | | MTTRAI01 | | 27889 | Labour External, |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 53344 | 01/13/2023 | GEN | 39 | CON | MTTRAI01 | 27889 | Consumables Electrical fault tailgate loaer blowing fuses Check over replace 10amp with 15amp run & test |
| RPS25 | 989QWX | 54325 | 02/22/2023 | FVGEN | 39 | CON | BRIVAL01 | EX00027278 | Consumables ,RP25 |
| RPS25 | 989QWX | 54325 | 02/22/2023 | FVGEN | 39 | LAB | BRIVAL01 | EX00027278 | Labour - CALL OUT,RP25 |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 54325 | 02/22/2023 | FVGEN | 17/02/2023 - Service completed by BVR - CALL OUT. Travel to site and inspect unit. Unit coded up on the air sensors in the rear zone. unit loaded. Note - Unit needs return air sensors replaced in zone 2. | | | | |
| RPS25 | 989QWX | 54402 | 02/24/2023 | EXOINS | | 1 | LABOUR | MECH | Labour |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 54402 | 02/24/2023 | EXOINS | VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1<br><br>INSPECTION COMPLETED BY DIESEL SERVICES<br><br>INVOICE # 00028306 | | | | |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | 2.57E+08 | DIESER01 | EX00027343 | O-RING - EXODAS STOCK, |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | SUND | DIESER01 | EX00027343 | SUNDRIES - 840375 RED REAR REFLECTORS 70X28 RECTANGLE. EXODAS STOCK, |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | 91700BL | DIESER01 | EX00027343 | Clearance Light, LED Amber, Narva - EXODAS STOCK, |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | CRC-5073 | DIESER01 | EX00027343 | DEGREASER CAN, |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | LABEXT | DIESER01 | EX00027343 | Labour External - C&D NO GREASE, |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | LABEXT | DIESER01 | EX00027343 | Labour External - REPLACE SIDE AMBER LAMP AND REPLACE MISSING REAR REFL |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | DEL | DIESER01 | EX00027343 | DELIVERY, |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | MISCON | DIESER01 | EX00027343 | MISCELLANEOUS CONSUMABLES, |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | MISCON | DIESER01 | 28306 | MISCELLANEOUS CONSUMABLES, |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | DEL | DIESER01 | 28306 | DELIVERY, |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | LABEXT | DIESER01 | 28306 | Labour External - REPLACE SIDE AMBER LAMP AND REPLACE MISSING REAR REFL |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | LABEXT | DIESER01 | 28306 | Labour External - C&D NO GREASE, |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | CRC-5073 | DIESER01 | 28306 | DEGREASER CAN, |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | 91700BL | DIESER01 | 28306 | Clearance Light, LED Amber, Narva - EXODAS STOCK, |
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | 39 | SUND | DIESER01 | 28306 | SUNDRIES - 840375 RED REAR REFLECTORS 70X28 RECTANGLE. EXODAS STOCK, |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 54401 | 02/24/2023 | GEN | | 39 | 2.57E+08 | | DIESER01 | 28306 | O-RING - EXODAS STOCK, |
| RPS25 | 989QWX | 54401 | 02/24/2023 | TRA | | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 54401 | 02/24/2023 | TRA | SERVICE COMPLETED. | | | | | | |
| RPS25 | 989QWX | 54401 | 02/24/2023 | TRB | | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 54401 | 02/24/2023 | TRB | SERVICE COMPLETED. | | | | | | |
| RPS25 | 989QWX | 54401 | 02/24/2023 | TRC | | 1 | LABOUR | MECH | Labour | | |
| | | | | | COMPLETED. COMPLETED C&D SERVICE, NO GREASE, CHECK WHEEL BEARINGS, ADJUST 3RD AXLE RH, 2ND AXLE LH, 1ST AXLE LH WHEEL BEARINGS, ADJUST BRAKES, CHECK SUSPENSION POINTS. FIT REAR REFLECTORS, | | | | | | |
| RPS25 | 989QWX | 54401 | 02/24/2023 | TRC | REPLACE | | | | | | |
| RPS25 | 989QWX | 54391 | 02/28/2023 | DEFECT | | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 54391 | 02/28/2023 | DEFECT | | | | | | | |
| RPS25 | 989QWX | 54391 | 02/28/2023 | DEFECT | DEFECT CLEARED. | | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 54391 | 02/28/2023 | DEFECT | Reported Defect :- Defect Code : 00008745 Defect Reference : RP25 Date : 15/02/2023 Description of Defect : TAILGATE FLAP HINGES BROKEN |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 54391 | 02/28/2023 | DEFECT | Reported Defect :- Defect Code : 00008726 Defect Reference : 37112 Date : 08/02/2023 Description of Defect : HINGES ON METAL PLATE ON TAILGATE LOADER NEED FIXING | | | | |
| RPS25 | 989QWX | 54391 | 02/28/2023 | GEN | | 0 | LABOUR | MECH1 | Labour |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 54391 | 02/28/2023 | GEN | REPAIR COMPLETED. REMADE BROKEN HINGES ON TAIL GATE PLATFORM FITTED NEW HINGES, CLEANED /LUBED TROLLEY STOPPERS | | | | | |
| RPS25 | 989QWX | 54391 | 02/28/2023 | GEN | | 16 | CON | | YAT | Consumables |
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVANB | | 0 | LABOUR | MECH | Labour | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVANB | VAN "B" SERVICE COMPLETED.<br><br>FRIDGE VAN UNIT CALIBRATED @ SERVICE.<br><br>SERVICE COMPLETED BY BVR.<br><br>OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE<br>R+R ENGINE OIL<br>R+R |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | Consumab |
| | | | | | | | | | | les |
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVANB | 39 | CON | | BRIVAL01 | EX00027591 | ,RP25 |
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVANB | 39 | CC | | BRIVAL01 | EX00027591 | CALIBRATION CETIFICATE,RP25 |
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVANB | 39 | 100417 | | BRIVAL01 | EX00027591 | Filter Service Kit, Fridge Motor, SLX-400,RP25 |
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVANB | 39 | 55-2208 | | BRIVAL01 | EX00027591 | COPPER WASHER,RP25 |
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVANB | 39 | LAB | | BRIVAL01 | EX00027591 | Labour,RP25 |
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVANB | 40 | 3413005 | | YAT | OIL 15W-40, CK 4/E9 | |
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVANB | Service completed by BVR 10/03/2023 - Carry out Bservice as per BVR Specifications - Clean fuel screen and replace u/s copper washers | | | | | |
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVANB | 39 | LAB | | BRIVAL01 | 15031 | Labour,RP25 |
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVANB | 39 | 55-2208 | | BRIVAL01 | 15031 | COPPER WASHER,RP25 |
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVANB | 39 | 100417 | | BRIVAL01 | 15031 | Filter Service Kit, Fridge Motor, SLX-400,RP25 |
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVANB | 39 | CC | | BRIVAL01 | 15031 | CALIBRATION CETIFICATE,RP25 |
| | | | | | | | | | | Consumab |
| | | | | | | | | | | les |
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVANB | 39 | CON | | BRIVAL01 | 15031 | ,RP25 |
| RPS25 | 989QWX | 54819 | 03/15/2023 | FRIVCAL | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 55078 | 03/24/2023 | DEFECT | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 55078 | 03/24/2023 | DEFECT | | | | | | |
| RPS25 | 989QWX | 55078 | 03/24/2023 | DEFECT | DEFECT CLEARED. | | | | | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 55078 | 03/24/2023 | DEFECT | Reported Defect :- Defect Code : 00008963 Defect Reference : 37113 Date : 22/03/2023 Description of Defect : DOWN BUTTON NOT WORKING ON TAILGATE LOADER MIDDLE RUBBER STOPPER NEEDS FIXING | | | | |
| RPS25 | 989QWX | 55078 | 03/24/2023 | GEN | | 0 | LABOUR | MECH 2 | Labour |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 55078 | 03/24/2023 | GEN | REPAIR COMPLETED. REMOLDED TAILGATE SWITCH 3, CLEANED / REFIT REPLACED BULB IN POWER INDICATOR LIGHT, REMOVED COVER AND TIGHTED SWITCH, FITTED HAND CONTROLLER TO TOOLBOX | | | | | | |
| RPS25 | 989QWX | 55078 | 03/24/2023 | GEN | | 0 | LABOUR | APPRENB | Labour - Internal | | |
| RPS25 | 989QWX | 55078 | 03/24/2023 | GEN | | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 55172 | 03/28/2023 | TYRES | | 15 | 11004117 | | BRIAUS01 | EX00027808 | 11R22.5 148/145L FS FT469,RP25 |
| RPS25 | 989QWX | 55172 | 03/28/2023 | TYRES | | 15 | 77000180 | | BRIAUS01 | EX00027808 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 55172 | 03/28/2023 | TYRES | | 15 | 33000084 | | BRIAUS01 | EX00027808 | FIT TBR TYRE,RP25 |
| RPS25 | 989QWX | 55172 | 03/28/2023 | TYRES | | 15 | 33000517 | | BRIAUS01 | EX00027808 | REMOVAL: CUSTOMER PULL POINT,RP25 |
| RPS25 | 989QWX | 55172 | 03/28/2023 | TYRES | | 15 | 33000517 | | BRIAUS01 | 89403625 | REMOVAL: CUSTOMER PULL POINT,RP25 |
| RPS25 | 989QWX | 55172 | 03/28/2023 | TYRES | | 15 | 33000084 | | BRIAUS01 | 89403625 | FIT TBR TYRE,RP25 |
| RPS25 | 989QWX | 55172 | 03/28/2023 | TYRES | | 15 | 77000180 | | BRIAUS01 | 89403625 | CASE STOCK 11-22.5,RP25 |
| RPS25 | 989QWX | 55172 | 03/28/2023 | TYRES | | 15 | 11004117 | | BRIAUS01 | 89403625 | 11R22.5 148/145L FS FT469,RP25 |
| RPS25 | 989QWX | 55724 | 04/14/2023 | FVGEN | | 39 | CON | | BRIVAL01 | EX00028151 | Consumables ,RP25 |
| RPS25 | 989QWX | 55724 | 04/14/2023 | FVGEN | | 39 | 40-0974 | | BRIVAL01 | EX00028151 | GRADED SENSOR,RP25 |
| RPS25 | 989QWX | 55724 | 04/14/2023 | FVGEN | | 39 | LAB | | BRIVAL01 | EX00028151 | Labour,RP25 |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 55724 | 04/14/2023 | FVGEN | Service completed by BVR 06/04/2023 - Travel to site and inspect unit - Remove and replace u/s discharge air sensor - Unit run on test | | | | | | |
| RPS25 | 989QWX | 55724 | 04/14/2023 | FVGEN | | 39 | LAB | | BRIVAL01 | 15516 | Labour,RP25 |
| RPS25 | 989QWX | 55724 | 04/14/2023 | FVGEN | | 39 | 40-0974 | | BRIVAL01 | 15516 | GRADED SENSOR,RP25 |
| RPS25 | 989QWX | 55724 | 04/14/2023 | FVGEN | | 39 | CON | | BRIVAL01 | 15516 | Consumables,RP25 |
| RPS25 | 989QWX | 56366 | 05/22/2023 | DEFECT | | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 56366 | 05/22/2023 | DEFECT | | | | | | | |
| RPS25 | 989QWX | 56366 | 05/22/2023 | DEFECT | DEFECT CLEARED. | | | | | | |
| RPS25 | 989QWX | 56366 | 05/22/2023 | DEFECT | Reported Defect :- Defect Code : 00008979 Defect Reference : 17051 Date : 21/03/2023 Description of Defect : NUMBER PLATE SURROUND IS HEAVILY CORRODEN, AND NEEDS ATTENTION | | | | | | |
| RPS25 | 989QWX | 56366 | 05/22/2023 | TRA | | 0 | LABOUR | MECH 3 | Labour | | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 56366 | 05/22/2023 | TRA | SERVICE COMPLETED. WELDED UP BACK ALLOY PLATE HOLDING THE NUMBER PLATE TO FRAME, MAKING IT NOW SECURE. FIXED LOADING RAMP FLAPS, RERIVEDTED LOADING RAMP LIGHTS | | | | | | |
| RPS25 | 989QWX | 56366 | 05/22/2023 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 56366 | 05/22/2023 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 56495 | 05/22/2023 | TYRES | 15 | 33000085 | | BRIAUS01 | | EX00028676 | ROTATE TBR TYRE, |
| RPS25 | 989QWX | 56495 | 05/22/2023 | TYRES | 15 | 33000125 | | BRIAUS01 | | EX00028676 | ETA MIN FEE, |
| RPS25 | 989QWX | 56495 | 05/22/2023 | TYRES | 15 | 33000085 | | BRIAUS01 | | 4.72E+09 | ROTATE TBR TYRE, |
| RPS25 | 989QWX | 56495 | 05/22/2023 | TYRES | 15 | 33000125 | | BRIAUS01 | | 4.72E+09 | ETA MIN FEE, |
| RPS25 | 989QWX | 56656 | 05/26/2023 | TYRES | 15 | 11004117 | | BRIAUS01 | | EX00028764 | 11R22.5 148/145L FS FT469, |
| RPS25 | 989QWX | 56656 | 05/26/2023 | TYRES | 15 | 77000180 | | BRIAUS01 | | EX00028764 | CASE STOCK 11-22.5, |
| RPS25 | 989QWX | 56656 | 05/26/2023 | TYRES | 15 | 33000084 | | BRIAUS01 | | EX00028764 | FIT TBR TYRE, |
| RPS25 | 989QWX | 56656 | 05/26/2023 | TYRES | 15 | 33000517 | | BRIAUS01 | | EX00028764 | REMOVAL: CUSTOMER PULL POINT, |
| RPS25 | 989QWX | 56656 | 05/26/2023 | TYRES | 15 | 33000517 | | BRIAUS01 | | 89717921 | REMOVAL: CUSTOMER PULL POINT, |
| RPS25 | 989QWX | 56656 | 05/26/2023 | TYRES | 15 | 33000084 | | BRIAUS01 | | 89717921 | FIT TBR TYRE, |
| RPS25 | 989QWX | 56656 | 05/26/2023 | TYRES | 15 | 77000180 | | BRIAUS01 | | 89717921 | CASE STOCK 11-22.5, |
| RPS25 | 989QWX | 56656 | 05/26/2023 | TYRES | 15 | 11004117 | | BRIAUS01 | | 89717921 | 11R22.5 148/145L FS FT469, |
| RPS25 | 989QWX | 57266 | 06/15/2023 | TRA | 0 | LABOUR | APPRENB | Labour | | | |
| RPS25 | 989QWX | 57266 | 06/15/2023 | TRA | SERVICE COMPLETED. | | | | | | |
| RPS25 | 989QWX | 57266 | 06/15/2023 | TRA | 0 | LABOUR | MECH 1 | Labour - Internal | | | |
| RPS25 | 989QWX | 57266 | 06/15/2023 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 57777 | 07/06/2023 | TRA | 0 | LABOUR | MECH 3 | Labour | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 57777 | 07/06/2023 | TRA | SERVICE COMPLETED.<br><br>TAP BOLT HOLES - BOLTED REAR FLAP ON TAILGATE LIFTER DUE TO RIVETS KEPT POPPING OUT. | | | | | |
| RPS25 | 989QWX | 57777 | 07/06/2023 | TRA | | 0 | LABOUR | APPREN | Labour - Internal | |
| RPS25 | 989QWX | 57777 | 07/06/2023 | TRA | | 16 | CON | | YAT | Consumables |
| RPS25 | 989QWX | 58077 | 07/13/2023 | FVGEN | | 39 | CON | | BRIVAL01 | EX00029543 | Consumables,RP25 |
| RPS25 | 989QWX | 58077 | 07/13/2023 | FVGEN | | 39 | 40-0974 | | BRIVAL01 | EX00029543 | GRADED SENSOR,RP25 |
| RPS25 | 989QWX | 58077 | 07/13/2023 | FVGEN | | 39 | LAB | | BRIVAL01 | EX00029543 | Labour,RP25 |
| RPS25 | 989QWX | 58077 | 07/13/2023 | FVGEN | Service completed by BVR 13/07/2023 - Travel to site and inspect unit - Return air sensor zone 2 reported not working correctly - Check over and found faulty se | | | | | |
| RPS25 | 989QWX | 58077 | 07/13/2023 | FVGEN | | 39 | CON | | BRIVAL01 | 17051 | Consumables,RP25 |
| RPS25 | 989QWX | 58077 | 07/13/2023 | FVGEN | | 39 | 40-0974 | | BRIVAL01 | 17051 | GRADED SENSOR,RP25 |
| RPS25 | 989QWX | 58077 | 07/13/2023 | FVGEN | | 39 | LAB | | BRIVAL01 | 17051 | Labour,RP25 |
| RPS25 | 989QWX | 58367 | 07/20/2023 | FVGEN | | 39 | CON | | BRIVAL01 | EX00029680 | Consumables,RP25 |
| RPS25 | 989QWX | 58367 | 07/20/2023 | FVGEN | | 39 | 40-0974 | | BRIVAL01 | EX00029680 | GRADED SENSOR,RP25 |
| RPS25 | 989QWX | 58367 | 07/20/2023 | FVGEN | | 39 | LAB | | BRIVAL01 | EX00029680 | Labour,RP25 |
| RPS25 | 989QWX | 58367 | 07/20/2023 | FVGEN | Service completed by BVR 20/07/2023 - Travel to site and inspect unit - Wait for trailer to be taken off dock and brought to yard - Remove and replace faulty tem | | | | | |
| RPS25 | 989QWX | 58367 | 07/20/2023 | FVGEN | | 39 | CON | | BRIVAL01 | 17166 | Consumables,RP25 |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 58367 | 07/20/2023 | FVGEN | 39 | 40-0974 | BRIVAL01 | 17166 | GRADED SENSOR,RP25 |
| RPS25 | 989QWX | 58367 | 07/20/2023 | FVGEN | 39 | LAB | BRIVAL01 | 17166 | Labour,RP25 |
| RPS25 | 989QWX | 58488 | 07/31/2023 | TYRES | 15 | 11002821 | BRIAUS01 | EX00029738 | 11R22.5 148/145L BS R119 ECO, |
| RPS25 | 989QWX | 58488 | 07/31/2023 | TYRES | 15 | 77000232 | BRIAUS01 | EX00029738 | CASE STOCK 11R22.5 ECOPIA, |
| RPS25 | 989QWX | 58488 | 07/31/2023 | TYRES | 15 | 33000084 | BRIAUS01 | EX00029738 | FIT TBR TYRE, |
| RPS25 | 989QWX | 58488 | 07/31/2023 | TYRES | 15 | 33000517 | BRIAUS01 | EX00029738 | REMOVAL: CUSTOMER PULL POINT, |
| RPS25 | 989QWX | 58488 | 07/31/2023 | TYRES | 15 | 33000085 | BRIAUS01 | EX00029738 | ROTATE TBR TYRE, |
| RPS25 | 989QWX | 58488 | 07/31/2023 | TYRES | 15 | 33000118 | BRIAUS01 | EX00029738 | SCHEDULED DEPOT SERVICE 15MIN, |
| RPS25 | 989QWX | 58488 | 07/31/2023 | TYRES | 15 | 11002821 | BRIAUS01 | 1.87E+08 | 11R22.5 148/145L BS R119 ECO, |
| RPS25 | 989QWX | 58488 | 07/31/2023 | TYRES | 15 | 77000232 | BRIAUS01 | 1.87E+08 | CASE STOCK 11R22.5 ECOPIA, |
| RPS25 | 989QWX | 58488 | 07/31/2023 | TYRES | 15 | 33000084 | BRIAUS01 | 1.87E+08 | FIT TBR TYRE, |
| RPS25 | 989QWX | 58488 | 07/31/2023 | TYRES | 15 | 33000517 | BRIAUS01 | 1.87E+08 | REMOVAL: CUSTOMER PULL POINT, |
| RPS25 | 989QWX | 58488 | 07/31/2023 | TYRES | 15 | 33000085 | BRIAUS01 | 1.87E+08 | ROTATE TBR TYRE, |
| RPS25 | 989QWX | 58488 | 07/31/2023 | TYRES | 15 | 33000118 | BRIAUS01 | 1.87E+08 | SCHEDULED DEPOT SERVICE 15MIN, |
| RPS25 | 989QWX | 59158 | 08/04/2023 | FVGEN | 39 | CON | BRIVAL01 | EX00030109 | Consumables,RP25 |
| RPS25 | 989QWX | 59158 | 08/04/2023 | FVGEN | 39 | 42-0100 | BRIVAL01 | EX00030109 | STOP FUEL SOLENOID, FRIDGE MOTORS,RP25 |
| RPS25 | 989QWX | 59158 | 08/04/2023 | FVGEN | 39 | 33-2230 | BRIVAL01 | EX00030109 | SOLENOID O-RING  FRIDGE MOTORS,RP25 |
| RPS25 | 989QWX | 59158 | 08/04/2023 | FVGEN | 39 | 45-2753 | BRIVAL01 | EX00030109 | Yanmar Starter Motor,RP25 |
| RPS25 | 989QWX | 59158 | 08/04/2023 | FVGEN | 39 | LAB | BRIVAL01 | EX00030109 | Labour,RP25 |
| RPS25 | 989QWX | 59158 | 08/04/2023 | FVGEN | Service completed by BVR 04/08/2023 - Travel to site and inspect unit - Remove and replace worn starter motor and fuel solenoid as required - Tension alternat | | | | |
| RPS25 | 989QWX | 59158 | 08/04/2023 | FVGEN | 39 | CON | BRIVAL01 | INV-00017075 | Consumables,RP25 |
| RPS25 | 989QWX | 59158 | 08/04/2023 | FVGEN | 39 | 42-0100 | BRIVAL01 | INV-00017075 | STOP FUEL SOLENOID, FRIDGE MOTORS,RP25 |
| RPS25 | 989QWX | 59158 | 08/04/2023 | FVGEN | 39 | 33-2230 | BRIVAL01 | INV-00017075 | SOLENOID O-RING  FRIDGE MOTORS,RP25 |
| RPS25 | 989QWX | 59158 | 08/04/2023 | FVGEN | 39 | 45-2753 | BRIVAL01 | INV-00017075 | Yanmar Starter Motor,RP25 |
| RPS25 | 989QWX | 59158 | 08/04/2023 | FVGEN | 39 | LAB | BRIVAL01 | INV-00017075 | Labour,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | CON | BRIVAL01 | EX00030027 | Consumables,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | 41-3669 | BRIVAL01 | EX00030027 | SWITCH HPCO,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | 77-2856 | BRIVAL01 | EX00030027 | Bush Drive Coupling,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | 22-1160 | BRIVAL01 | EX00030027 | OIL PUMP ASSEMBLY FRIDGE,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | 33-0230 | BRIVAL01 | EX00030027 | SUCTION SERVICE VALVE ORING,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | 33-1221 | BRIVAL01 | EX00030027 | O-RING,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | 33-2805 | BRIVAL01 | EX00030027 | MANIFOLD GASKET FRIDGE,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | 61-0600 | BRIVAL01 | EX00030027 | RECIEVER DRIER, FRIDGE MOTOR,RP25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | LAB | | BRIVAL01 | EX00030027 | Labour,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | Service completed by BVR 10/08/2023 - Travel to site and inspect unit - Pump down and remove compressor - Remove and replace worn oil pump - Remove and | | | | | |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | CON | | BRIVAL01 | INV-00017198 | Consumables,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | 41-3669 | | BRIVAL01 | INV-00017198 | SWITCH HPCO,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | 77-2856 | | BRIVAL01 | INV-00017198 | Bush Drive Coupling,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | 22-1160 | | BRIVAL01 | INV-00017198 | OIL PUMP ASSEMBLY FRIDGE,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | 33-0230 | | BRIVAL01 | INV-00017198 | SUCTION SERVICE VALVE ORING,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | 33-1221 | | BRIVAL01 | INV-00017198 | O-RING,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | 33-2805 | | BRIVAL01 | INV-00017198 | MANIFOLD GASKET FRIDGE,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | 61-0600 | | BRIVAL01 | INV-00017198 | RECIEVER DRIER, FRIDGE MOTOR,RP25 |
| RPS25 | 989QWX | 59070 | 08/10/2023 | FVGEN | 39 | LAB | | BRIVAL01 | INV-00017198 | Labour,RP25 |
| RPS25 | 989QWX | 58867 | 08/14/2023 | TRA | 1 | LABOUR | MECH 3 | Labour | | |
| RPS25 | 989QWX | 58867 | 08/14/2023 | TRA | SERVICE COMPLETED BY MATT & TYLER ON 28/07/2023.<br><br>REPAIR SECTION OF BRAKE HOSE (CRACKED AND PERISHED) FIT HOSE AND CHECK LEAKS WHEN COMPLETE. REPLACED DOOR LATCH ON THE FRIDGE. | | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 58867 | 08/14/2023 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | |
| RPS25 | 989QWX | 58867 | 08/14/2023 | TRA | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 58867 | 08/14/2023 | TRA | 16 | HS010-20 | | YAT | CLAMP HOSE 14-27MM PERFORA CONVERSION | |
| RPS25 | 989QWX | 58867 | 08/14/2023 | TRA | 16 | CON | | YAT | 600MM BRAKE HOSE | |
| RPS25 | 989QWX | 59329 | 08/24/2023 | GEN | 39 | LABEXT | | RCCLOW01 | EX00030181 | LABOUR INSPECT TRAILER - REPLACE AIRBAG, |
| RPS25 | 989QWX | 59329 | 08/24/2023 | GEN | 39 | AIRBAG | | RCCLOW01 | EX00030181 | AIRBAG COMPLETE, |
| RPS25 | 989QWX | 59329 | 08/24/2023 | GEN | 16 | CON | | RCCLOW01 | EX00030181 | Consumables, |
| RPS25 | 989QWX | 59329 | 08/24/2023 | GEN | 16 | CON | | RCCLOW01 | 35376 | Consumables, |
| RPS25 | 989QWX | 59329 | 08/24/2023 | GEN | 39 | AIRBAG | | RCCLOW01 | 35376 | AIRBAG COMPLETE, |
| RPS25 | 989QWX | 59329 | 08/24/2023 | GEN | 39 | LABEXT | | RCCLOW01 | 35376 | LABOUR INSPECT TRAILER - REPLACE AIRBAG, |
| RPS25 | 989QWX | 59243 | 08/28/2023 | TRA | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 59243 | 08/28/2023 | TRA | SERVICE COMPLETED. | | | | | |
| RPS25 | 989QWX | 59243 | 08/28/2023 | TRB | 1 | LABOUR | MECH 3 | Labour | | |
| RPS25 | 989QWX | 59243 | 08/28/2023 | TRB | SERVICE COMPLETED BY MATT & JOSEPH ON 24/08/2023. | | | | | |
| RPS25 | 989QWX | 59243 | 08/28/2023 | TRB | 0 | LABOUR | APPRENJ | Labour - Internal | | |
| RPS25 | 989QWX | 59243 | 08/28/2023 | TRB | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 59667 | 09/07/2023 | GEN | 39 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 59667 | 09/07/2023 | GEN | REPAIR COMPLETED BY MICK & BEN ON 07/09/2023. | | | | | |
| RPS25 | 989QWX | 59667 | 09/07/2023 | GEN | FITTED TAIL GATE LIFTER STRAPS | | | | | |
| RPS25 | 989QWX | 59667 | 09/07/2023 | GEN | 0 | LABOUR | APPRENB | Labour - Internal | | |
| RPS25 | 989QWX | 59667 | 09/07/2023 | GEN | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 59934 | 09/15/2023 | TRA | 1 | LABOUR | MECH 3 | Labour | | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 59934 | 09/15/2023 | TRA | SERVICE COMPLETED BY MATT & FLYNN ON 14/09/2023.<br><br>REPAIRED MARKER LIGHT RIGHT HAND SIDE REPLACED RIGHT HAND REAR ALUMINIUM DOOR HINGE | | | | |
| RPS25 | 989QWX | 59934 | 09/15/2023 | TRA | | 0 | LABOUR | APPRENF | Labour - Internal |
| RPS25 | 989QWX | 59934 | 09/15/2023 | TRA | | 16 | CON | YAT | Consumables |
| RPS25 | 989QWX | 59934 | 09/15/2023 | TRA | | 14 | 91700BL | YAT | Clearance Light, LED Amber, Narva |
| RPS25 | 989QWX | 59934 | 09/15/2023 | TRA | | 16 | CON | YAT | DOOR HINGE (ALUMINIUM) |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | | AIR GAUGE: 21800 ADJUSTED: 21900 WEIGHBRIDGE: 21540 | | | | |
| RPS25 | 989QWX | 61272 | 10/09/2023 | WEICAL | AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | |
| RPS25 | 989QWX | 60891 | 10/18/2023 | TRA | | 1 | LABOUR | MECH 1 | Labour |
| RPS25 | 989QWX | 60891 | 10/18/2023 | TRA | SERVICE COMPLETED BY NICK, TYLER & JOSEPH ON 18/10/2023. REPLACED BATTERY TERMINAL ON TAILGATE BATTERY. LOAD TESTED BATTERY ON TAILGATE LIFTER | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 60891 | 10/18/2023 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | |
| RPS25 | 989QWX | 60891 | 10/18/2023 | TRA | 0 | LABOUR | APPRENJ | Labour - Internal | | |
| RPS25 | 989QWX | 60891 | 10/18/2023 | TRA | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVANB | 0 | LABOUR | MECH | Labour | | |
| | | | | | VAN "B" SERVICE COMPLETED.<br><br>FRIDGE VAN UNIT CALIBRATED @ SERVICE.<br><br>SERVICE COMPLETED BY BVR.<br><br>OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL | | | | | |
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVANB | R+R | | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVANB | 39 | CON | | BRIVAL01 | EX00031214 | Consumables,RP25 |
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVANB | 39 | CC | | BRIVAL01 | EX00031214 | CALIBRATION CETIFICATE,RP25 |
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVANB | 39 | 100417 | | BRIVAL01 | EX00031214 | Filter Service Kit, Fridge Motor, SLX-400,RP25 |
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVANB | 39 | 40-0985 | | BRIVAL01 | EX00031214 | LED Status Light KIt,RP25 |
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVANB | 39 | LAB | | BRIVAL01 | EX00031214 | Labour,RP25 |
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVANB | 40 | 3413005 | | YAT | OIL 15W-40, CK 4/E9 | |
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVANB | Service completed by BVR 30/10/023 - Carry out B Service as per BVR Specifications - Fit new status light | | | | | |
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVANB | 39 | CON | | BRIVAL01 | INV-00018405 | Consumables,RP25 |
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVANB | 39 | CC | | BRIVAL01 | INV-00018405 | CALIBRATION CETIFICATE,RP25 |
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVANB | 39 | 100417 | | BRIVAL01 | INV-00018405 | Filter Service Kit, Fridge Motor, SLX-400,RP25 |
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVANB | 39 | 40-0985 | | BRIVAL01 | INV-00018405 | LED Status Light KIt,RP25 |
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVANB | 39 | LAB | | BRIVAL01 | INV-00018405 | Labour,RP25 |
| RPS25 | 989QWX | 61528 | 11/03/2023 | FRIVCAL | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 62023 | 11/15/2023 | TRA | 1 | LABOUR | MECH | Labour | | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 62023 | 11/15/2023 | TRA | SERVICE COMPLETED BY NQFM ON 15/11/2023. INVOICE NO. 36132<br><br>CARRY OUT 'A' SERVICE AS REQUIRED. REMOVE FRONT RIGHT AIRBAG AND REFIT NEW ONE. | | | | |
| RPS25 | 989QWX | 62023 | 11/15/2023 | TRA | | 1 | LABEXT | RCCLOW01 | EX00031477 | CARRY OUT 'A' SERVICE, |
| RPS25 | 989QWX | 62023 | 11/15/2023 | TRA | | 39 | LABEXT | RCCLOW01 | EX00031477 | REMOVE FRONT RIGHT AIRBAG AND REFIT NEW ONE, |
| RPS25 | 989QWX | 62023 | 11/15/2023 | TRA | | 39 | AIRBAG | RCCLOW01 | EX00031477 | AIRBAG, |
| RPS25 | 989QWX | 62023 | 11/15/2023 | TRA | | 16 | CON | RCCLOW01 | EX00031477 | GREASE, |
| RPS25 | 989QWX | 62023 | 11/15/2023 | TRA | | 16 | CON | RCCLOW01 | EX00031477 | Consumables, |
| RPS25 | 989QWX | 62023 | 11/15/2023 | TRA | | 16 | ENVLEV | RCCLOW01 | EX00031477 | ENVIRONMENTAL LEVY, |
| RPS25 | 989QWX | 62023 | 11/15/2023 | TRA | | 16 | ENVLEV | RCCLOW01 | 36132 | ENVIRONMENTAL LEVY, |
| RPS25 | 989QWX | 62023 | 11/15/2023 | TRA | | 16 | CON | RCCLOW01 | 36132 | Consumables, |
| RPS25 | 989QWX | 62023 | 11/15/2023 | TRA | | 16 | CON | RCCLOW01 | 36132 | GREASE, |
| RPS25 | 989QWX | 62023 | 11/15/2023 | TRA | | 39 | AIRBAG | RCCLOW01 | 36132 | AIRBAG, |
| RPS25 | 989QWX | 62023 | 11/15/2023 | TRA | | 39 | LABEXT | RCCLOW01 | 36132 | REMOVE FRONT RIGHT AIRBAG AND REFIT NEW ONE, |
| RPS25 | 989QWX | 62023 | 11/15/2023 | TRA | | 1 | LABEXT | RCCLOW01 | 36132 | CARRY OUT 'A' SERVICE, |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | AIR GAUGE: 21000 ADJUSTED : 21500 WEIGHBRIDGE: 21000 | | | | | | |
| RPS25 | 989QWX | 63143 | 12/27/2023 | WEICAL | AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | | | |
| RPS25 | 989QWX | 63444 | 01/02/2024 | FVGEN | | 39 | CON | | BRIVAL01 | EX00032195 | Consumables ,RP25 |
| RPS25 | 989QWX | 63444 | 01/02/2024 | FVGEN | | 39 | 1000CCA | | BRIVAL01 | EX00032195 | Heavy Duty Battery - 1000CCA,RP25 |
| RPS25 | 989QWX | 63444 | 01/02/2024 | FVGEN | | 39 | LAB | | BRIVAL01 | EX00032195 | Labour,RP25 |
| RPS25 | 989QWX | 63444 | 01/02/2024 | FVGEN | Service completed by BVR 02/01/2024 - Travel to site and inspect unit for reported not starting - Remove and replace u/s battery (BVR supplied) - Tighten alt bel | | | | | | |
| RPS25 | 989QWX | 63444 | 01/02/2024 | FVGEN | | 39 | CON | | BRIVAL01 | INV-00019285 | Consumables ,RP25 |
| RPS25 | 989QWX | 63444 | 01/02/2024 | FVGEN | | 39 | 1000CCA | | BRIVAL01 | INV-00019285 | Heavy Duty Battery - 1000CCA,RP25 |
| RPS25 | 989QWX | 63444 | 01/02/2024 | FVGEN | | 39 | LAB | | BRIVAL01 | INV-00019285 | Labour,RP25 |
| RPS25 | 989QWX | 63669 | 01/18/2024 | DEFECT | | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 63670 | 01/18/2024 | DEFECT | | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 63669 | 01/18/2024 | DEFECT | | | | | | | |
| RPS25 | 989QWX | 63670 | 01/18/2024 | DEFECT | | | | | | | |
| RPS25 | 989QWX | 63669 | 01/18/2024 | DEFECT | DEFECT CLEARED. | | | | | | |
| RPS25 | 989QWX | 63670 | 01/18/2024 | DEFECT | DEFECT CLEARED. | | | | | | |
| RPS25 | 989QWX | 63670 | 01/18/2024 | EXOINS | | 1 | LABOUR | MECH | Labour | | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 63670 | 01/18/2024 | EXOINS | PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT #2<br><br>FIRST INSPECTION COMPLETED BY DIESEL SERVICES ON 18/01/2024 INVOICE NO. 00029194<br><br>NOTED: FIRE EXTINGUISHER |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 63670 | 01/18/2024 | EXOINS | 17 | MG650.R | YAT | MUDGUARD PLASTIC RED 650MM WIDE | |
| RPS25 | 989QWX | 63670 | 01/18/2024 | EXOINS | 31 | 84037/50 | YAT | REFLECTOR-RED, 70MM X 28MM | |
| RPS25 | 989QWX | 63670 | 01/18/2024 | EXOINS | 1 | LABEXT | DIESER01 | EX00032292 | CARRY OUT C & D SERVICE WITHOUT BEARINGS, |
| RPS25 | 989QWX | 63670 | 01/18/2024 | EXOINS | 39 | LABEXT | DIESER01 | EX00032292 | LABOUR - GUARD REPLACEMENT, |
| RPS25 | 989QWX | 63670 | 01/18/2024 | EXOINS | 39 | LABEXT | DIESER01 | EX00032292 | REPLACE MISSING / DAMAGED REFLECTORS, |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 63670 | 01/18/2024 | EXOINS | 16 | CON | | DIESER01 | EX00032292 | DEGREASER, |
| RPS25 | 989QWX | 63670 | 01/18/2024 | EXOINS | 16 | CON | | DIESER01 | EX00032292 | MATERIALS, |
| RPS25 | 989QWX | 63670 | 01/18/2024 | EXOINS | 1 | LABEXT | | DIESER01 | 29194 | CARRY OUT C & D SERVICE WITHOUT BEARINGS, |
| RPS25 | 989QWX | 63670 | 01/18/2024 | EXOINS | 39 | LABEXT | | DIESER01 | 29194 | LABOUR - GUARD REPLACEMENT, |
| RPS25 | 989QWX | 63670 | 01/18/2024 | EXOINS | 39 | LABEXT | | DIESER01 | 29194 | REPLACE MISSING / DAMAGED REFLECTORS, |
| RPS25 | 989QWX | 63670 | 01/18/2024 | EXOINS | 16 | CON | | DIESER01 | 29194 | DEGREASER, |
| RPS25 | 989QWX | 63670 | 01/18/2024 | EXOINS | 16 | CON | | DIESER01 | 29194 | MATERIALS, |
| RPS25 | 989QWX | 63669 | 01/18/2024 | TRA | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 63669 | 01/18/2024 | TRA | SERVICE COMPLETED. | | | | | |
| RPS25 | 989QWX | 63669 | 01/18/2024 | TRB | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 63669 | 01/18/2024 | TRB | SERVICE COMPLETED. | | | | | |
| RPS25 | 989QWX | 63669 | 01/18/2024 | TRC | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 63669 | 01/18/2024 | TRC | COMPLETED BY DIESEL SERVICES QLD ON 18/01/2024. INVOICE NO. 00029194<br><br>Service as per C and D service sheet without bearings. Retention all fasteners to factory torque settings and grease all points, adjust all | | | | | |
| RPS25 | 989QWX | 63949 | 01/19/2024 | GEN | 39 | MG650.R | | GIBBS01 | EX00032432 | MUDGUARD PLASTIC RED 650MM WIDE, |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 63949 | 01/19/2024 | GEN | 39 | MG650.R | | GIBBS01 | 9051085 | MUDGUARD PLASTIC RED 650MM WIDE, |
| RPS25 | 989QWX | 63718 | 01/22/2024 | DEFECT | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 63718 | 01/22/2024 | DEFECT | | | | | | |
| RPS25 | 989QWX | 63718 | 01/22/2024 | DEFECT | DEFECT CLEARED. Defect :- Defect Code : 00010727 Defect Reference : RP25 Date : 18/01/2024 Description of Defect : FIRE EXTINGUISHER EXPIRED<br><br>DEFECT CLEARED 22/01/2024 CHECKED/ REPLACED FIRE EXTINGUISHER. | | | | | |
| RPS25 | 989QWX | 63718 | 01/22/2024 | GEN | 39 | LABOUR | MECH | Labour | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 63718 | 01/22/2024 | GEN | REPAIR COMPLETED BY MICK/ETHAN ON 22/01/2024. FIRE EXTINGUISHER REPLACED | | | | | |
| RPS25 | 989QWX | 63718 | 01/22/2024 | GEN | 16 | CON | YAT | Consumables | | |
| RPS25 | 989QWX | 63718 | 01/22/2024 | GEN | 19 | FIREEXT4.5KG | YAT | 4.5KG FIRE EXTINGUISHER | | |
| RPS25 | 989QWX | 64354 | 01/28/2024 | FVGEN | 39 | 45-2256 | BRIVAL01 | | EX00032681 | ALTERNATOR 65 AMP, Consumables |
| RPS25 | 989QWX | 64354 | 01/28/2024 | FVGEN | 39 | CON | BRIVAL01 | | EX00032681 | , |
| RPS25 | 989QWX | 64354 | 01/28/2024 | FVGEN | 39 | LABEXT | BRIVAL01 | | EX00032681 | LABOUR 0 ICEMAN TRANSPORT REFRIGERATION, |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 64354 | 01/28/2024 | FVGEN | COMPLETED BY ICEMAN TRANSPORT REFRIGERATION 28/01/2024<br><br>ALARMS # 25 & #61 LOADED AT MT ST JOHN. AFTER HOURS CALLOUT TRAVELLED TO SITE CHECKED OVER UNIT REPORTED DISPLAYING ALARMS | | | | | |
| RPS25 | 989QWX | 64354 | 01/28/2024 | FVGEN | | 39 | LABEXT | BRIVAL01 | INV-00019709 | LABOUR 0 ICEMAN TRANSPORT REFRIGERATION, |
| RPS25 | 989QWX | 64354 | 01/28/2024 | FVGEN | | 39 | CON | BRIVAL01 | INV-00019709 | Consumables, |
| RPS25 | 989QWX | 64354 | 01/28/2024 | FVGEN | | 39 | 45-2256 | BRIVAL01 | INV-00019709 | ALTERNATOR 65 AMP, |
| RPS25 | 989QWX | 64078 | 01/30/2024 | TYRES | | 15 | 11002821 | BRIAUS01 | EX00032545 | 11R22.5 148/145L BS R119 ECO, |
| RPS25 | 989QWX | 64078 | 01/30/2024 | TYRES | | 15 | 77000232 | BRIAUS01 | EX00032545 | CASE STOCK 11R22.5 ECOPIA, |
| RPS25 | 989QWX | 64078 | 01/30/2024 | TYRES | | 15 | 33000084 | BRIAUS01 | EX00032545 | FIT TBR TYRE, |
| RPS25 | 989QWX | 64078 | 01/30/2024 | TYRES | | 15 | 33000517 | BRIAUS01 | EX00032545 | REMOVAL: CUSTOMER PULL POINT, |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 64078 | 01/30/2024 | TYRES | 15 | 33000085 | BRIAUS01 | EX00032545 | ROTATE TBR TYRE, |
| RPS25 | 989QWX | 64078 | 01/30/2024 | TYRES | 15 | 33000118 | BRIAUS01 | EX00032545 | SCHEDULED DEPOT SERVICE 15MIN, |
| RPS25 | 989QWX | 64078 | 01/30/2024 | TYRES | 15 | 11002821 | BRIAUS01 | 1.88E+08 | 11R22.5 148/145L BS R119 ECO, |
| RPS25 | 989QWX | 64078 | 01/30/2024 | TYRES | 15 | 77000232 | BRIAUS01 | 1.88E+08 | CASE STOCK 11R22.5 ECOPIA, |
| RPS25 | 989QWX | 64078 | 01/30/2024 | TYRES | 15 | 33000084 | BRIAUS01 | 1.88E+08 | FIT TBR TYRE, |
| RPS25 | 989QWX | 64078 | 01/30/2024 | TYRES | 15 | 33000517 | BRIAUS01 | 1.88E+08 | REMOVAL: CUSTOMER PULL POINT, |
| RPS25 | 989QWX | 64078 | 01/30/2024 | TYRES | 15 | 33000085 | BRIAUS01 | 1.88E+08 | ROTATE TBR TYRE, |
| RPS25 | 989QWX | 64078 | 01/30/2024 | TYRES | 15 | 33000118 | BRIAUS01 | 1.88E+08 | SCHEDULED DEPOT SERVICE 15MIN, |
| RPS25 | 989QWX | 64102 | 02/01/2024 | GEN | 39 | LABEXT | RCCLOW01 | EX00032567 | INSPECT. FOUND FRONT LH SIDE AIRBAG TO HAVE HOLE IN IT. REPLACED AIRBA( |
| RPS25 | 989QWX | 64102 | 02/01/2024 | GEN | 10 | AIRBAG | RCCLOW01 | EX00032567 | AIRBAG, |
| | | | | | | | | | Consumab |
| | | | | | | | | | les |
| RPS25 | 989QWX | 64102 | 02/01/2024 | GEN | 16 | CON | RCCLOW01 | EX00032567 | , |
| RPS25 | 989QWX | 64102 | 02/01/2024 | GEN | 39 | LABEXT | RCCLOW01 | 36719 | INSPECT. FOUND FRONT LH SIDE AIRBAG TO HAVE HOLE IN IT. REPLACED AIRBA( |
| RPS25 | 989QWX | 64102 | 02/01/2024 | GEN | 10 | AIRBAG | RCCLOW01 | 36719 | AIRBAG, |
| | | | | | | | | | Consumab |
| | | | | | | | | | les |
| RPS25 | 989QWX | 64102 | 02/01/2024 | GEN | 16 | CON | RCCLOW01 | 36719 | , |
| RPS25 | 989QWX | 64833 | 02/20/2024 | TRA | 1 | LABOUR MECH | Labour | | |
| | | | | | | SERVICE COMPLETED BY NQFM ON 20/02/2024. INVOICE NO. 36912 | | | |
| RPS25 | 989QWX | 64833 | 02/20/2024 | TRA | | CARRY OUT 'A' SERVICE ON TRAILER | | | |
| RPS25 | 989QWX | 64833 | 02/20/2024 | TRA | 1 | LABEXT | RCCLOW01 | EX00032929 | CARRY OUT 'A' SERVICE ON TRAILER, |
| RPS25 | 989QWX | 64833 | 02/20/2024 | TRA | 16 | 0210404900-20 | RCCLOW01 | EX00032929 | GREASE, |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | Consumab |
| | | | | | | | | | les |
| RPS25 | 989QWX | 64833 | 02/20/2024 | TRA | 16 | CON | RCCLOW01 | EX00032929 | , |
| RPS25 | 989QWX | 64833 | 02/20/2024 | TRA | 16 | ENVLEV | RCCLOW01 | EX00032929 | ENVIRONMENTAL LEVY, |
| RPS25 | 989QWX | 64833 | 02/20/2024 | TRA | 1 | LABEXT | RCCLOW01 | 36912 | CARRY OUT 'A' SERVICE ON TRAILER, |
| RPS25 | 989QWX | 64833 | 02/20/2024 | TRA | 16 | 0210404900-20 | RCCLOW01 | 36912 | GREASE, |
| | | | | | | | | | Consumab |
| | | | | | | | | | les |
| RPS25 | 989QWX | 64833 | 02/20/2024 | TRA | 16 | CON | RCCLOW01 | 36912 | , |
| RPS25 | 989QWX | 64833 | 02/20/2024 | TRA | 16 | ENVLEV | RCCLOW01 | 36912 | ENVIRONMENTAL LEVY, |
| RPS25 | 989QWX | 65048 | 02/27/2024 | GEN | 39 | LABEXT | REDTRU01 | EX00033041 | INSPECT FOR WATER DAMAGE. FOUND WATER IN BEARINGS. SERVICED HUBS. R |
| RPS25 | 989QWX | 65048 | 02/27/2024 | GEN | 16 | GREASE | REDTRU01 | EX00033041 | GREASE, |
| RPS25 | 989QWX | 65048 | 02/27/2024 | GEN | 16 | CON | REDTRU01 | EX00033041 | DEGREASER, |
| RPS25 | 989QWX | 65048 | 02/27/2024 | GEN | 39 | LABEXT | REDTRU01 | INV-0130 | INSPECT FOR WATER DAMAGE. FOUND WATER IN BEARINGS. SERVICED HUBS. R |
| RPS25 | 989QWX | 65048 | 02/27/2024 | GEN | 16 | GREASE | REDTRU01 | INV-0130 | GREASE, |
| RPS25 | 989QWX | 65048 | 02/27/2024 | GEN | 16 | CON | REDTRU01 | INV-0130 | DEGREASER, |
| | | | | | | | | | Consumab |
| | | | | | | | | | les |
| RPS25 | 989QWX | 65932 | 03/25/2024 | FVGEN | 39 | CON | BRIVAL01 | EX00033589 | ,RP25 |
| RPS25 | 989QWX | 65932 | 03/25/2024 | FVGEN | 39 | 45-2258 | BRIVAL01 | EX00033589 | 120 AMP ALTERNATOR,RP25 |
| RPS25 | 989QWX | 65932 | 03/25/2024 | FVGEN | 39 | 78-1360 | BRIVAL01 | EX00033589 | ALTERNATOR BELT FRIDGE,RP25 |
| RPS25 | 989QWX | 65932 | 03/25/2024 | FVGEN | 39 | LAB | BRIVAL01 | EX00033589 | Labour,RP25 |
| RPS25 | 989QWX | 65932 | 03/25/2024 | FVGEN | Service completed by BVR 25/03/2024 - Travel to site and inspect unit for reported not starting - Found belt loose and worn out - Remove and replace u/s belt - I | | | | |
| | | | | | | | | | Consumab |
| | | | | | | | | | les |
| RPS25 | 989QWX | 65932 | 03/25/2024 | FVGEN | 39 | CON | BRIVAL01 | INV-00020440 | ,RP25 |
| RPS25 | 989QWX | 65932 | 03/25/2024 | FVGEN | 39 | 45-2258 | BRIVAL01 | INV-00020440 | 120 AMP ALTERNATOR,RP25 |
| RPS25 | 989QWX | 65932 | 03/25/2024 | FVGEN | 39 | 78-1360 | BRIVAL01 | INV-00020440 | ALTERNATOR BELT FRIDGE,RP25 |
| RPS25 | 989QWX | 65932 | 03/25/2024 | FVGEN | 39 | LAB | BRIVAL01 | INV-00020440 | Labour,RP25 |
| RPS25 | 989QWX | 65837 | 03/26/2024 | TRA | 1 | LABOUR MECH 4 | Labour | | |
| RPS25 | 989QWX | 65837 | 03/26/2024 | TRA | SERVICE COMPLETED BY ETHAN & NICK ON 26/03/2024. | | | | |
| RPS25 | 989QWX | 65837 | 03/26/2024 | TRA | 0 | LABOUR MECH 1 | Labour - Internal | | |
| RPS25 | 989QWX | 65837 | 03/26/2024 | TRA | 16 | CON | YAT | Consumables | |
| | | | | | | | | | Consumab |
| | | | | | | | | | les |
| RPS25 | 989QWX | 66730 | 04/16/2024 | FVGEN | 39 | CON | BRIVAL01 | EX00033996 | ,RPS25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 66730 | 04/16/2024 | FVGEN | | 39 | 91-4159 | BRIVAL01 | EX00033996 | VIBRATION MOUNT,RPS25 |
| RPS25 | 989QWX | 66730 | 04/16/2024 | FVGEN | | 39 | LAB | BRIVAL01 | EX00033996 | Labour,RPS25 |
| RPS25 | 989QWX | 66730 | 04/16/2024 | FVGEN | Service completed by BVR 16/04/2024 - Travel to site and inspect unit for reported engine has movement - Located worn front mounts - Remove battery - Remo | | | | | |
| RPS25 | 989QWX | 66730 | 04/16/2024 | FVGEN | | 39 | CON | BRIVAL01 | INV-00020728 | Consumables,RPS25 |
| RPS25 | 989QWX | 66730 | 04/16/2024 | FVGEN | | 39 | 91-4159 | BRIVAL01 | INV-00020728 | VIBRATION MOUNT,RPS25 |
| RPS25 | 989QWX | 66730 | 04/16/2024 | FVGEN | | 39 | LAB | BRIVAL01 | INV-00020728 | Labour,RPS25 |
| RPS25 | 989QWX | 66475 | 04/16/2024 | WEICAL | AIR GAUGE: ADJUSTED: WEIGHBRIDGE: AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | | AIR GAUGE: 20250 ADJUSTED : 20000 WEIGHBRIDGE: 19680 | | | | |
| RPS25 | 989QWX | 67005 | 05/02/2024 | WEICAL | AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | |
| RPS25 | 989QWX | 66982 | 05/10/2024 | DEFECT | | 1 | LABOUR | MECH | Labour |
| RPS25 | 989QWX | 66982 | 05/10/2024 | DEFECT | | | | | |
| RPS25 | 989QWX | 66982 | 05/10/2024 | DEFECT | DEFECT CLEARED. | | | | |
| RPS25 | 989QWX | 66982 | 05/10/2024 | TRA | | 1 | LABOUR | MECH 4 | Labour |
| RPS25 | 989QWX | 66982 | 05/10/2024 | TRA | 'A' SERVICE COMPLETED BY ETHAN ON 10/05/2024. RE-TENSIONED FRIDGE MOTOR BELT AS IT IS LOOSE. NO ISSUE WITH TRACKING | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 66982 | 05/10/2024 | TRA | | 16 | CON | | YAT | Consumables |
| RPS25 | 989QWX | 68154 | 06/11/2024 | FRIVANB | VAN "B" SERVICE COMPLETED.<br><br>FRIDGE VAN UNIT CALIBRATED @ SERVICE.<br><br>SERVICE COMPLETED BY BVR 07/06/2024 | 0 | LABOUR | MECH | Labour | |
| RPS25 | 989QWX | 68154 | 06/11/2024 | FRIVANB | OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE | | | | | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 68154 | 06/11/2024 | FRIVANB | 40 | 3413005 | | YAT | OIL 15W-40, CK 4/E9 | | |
| RPS25 | 989QWX | 68154 | 06/11/2024 | FRIVANB | 39 | CON | | BRIVAL01 | | EX00034748 | Consumables, |
| RPS25 | 989QWX | 68154 | 06/11/2024 | FRIVANB | 39 | CC | | BRIVAL01 | | EX00034748 | CALIBRATION CETIFICATE, |
| RPS25 | 989QWX | 68154 | 06/11/2024 | FRIVANB | 39 | 10-417 | | BRIVAL01 | | EX00034748 | FILTER KIT (FRIDGE MOTOR), |
| RPS25 | 989QWX | 68154 | 06/11/2024 | FRIVANB | 39 | 55-2208 | | BRIVAL01 | | EX00034748 | COPPER WASHER, |
| RPS25 | 989QWX | 68154 | 06/11/2024 | FRIVANB | 39 | LAB | | BRIVAL01 | | EX00034748 | Labour, |
| RPS25 | 989QWX | 68154 | 06/11/2024 | FRIVANB | 39 | CON | | BRIVAL01 | | INV-00021452 | Consumables, |
| RPS25 | 989QWX | 68154 | 06/11/2024 | FRIVANB | 39 | CC | | BRIVAL01 | | INV-00021452 | CALIBRATION CETIFICATE, |
| RPS25 | 989QWX | 68154 | 06/11/2024 | FRIVANB | 39 | 10-417 | | BRIVAL01 | | INV-00021452 | FILTER KIT (FRIDGE MOTOR), |
| RPS25 | 989QWX | 68154 | 06/11/2024 | FRIVANB | 39 | 55-2208 | | BRIVAL01 | | INV-00021452 | COPPER WASHER, |
| RPS25 | 989QWX | 68154 | 06/11/2024 | FRIVANB | 39 | LAB | | BRIVAL01 | | INV-00021452 | Labour, |
| RPS25 | 989QWX | 68154 | 06/11/2024 | FRIVCAL | 1 | LABOUR | MECH | Labour | | | |
| RPS25 | 989QWX | 68632 | 06/26/2024 | GEN | 39 | LAB | | KENAUT01 | | EX00034954 | TAIL GATE NOT WORKING, |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | COMPLETED BY KENNY'S AUTO ELECTRICAL 26/06/2024 | | | | | | |
| RPS25 | 989QWX | 68632 | 06/26/2024 | GEN | PROCEED TO AND TESTED TAIL GATE NOT MOVING. DIAGNOSED WATER IN ELECTRIC MOTOR. HIT MOTOR TO GET TAIL GATE UP. ADVISE CUSTOME | | | | | | |
| RPS25 | 989QWX | 68632 | 06/26/2024 | GEN | | 39 | LAB | | KENAUT01 | 57722 | TAIL GATE NOT WORKING, |
| RPS25 | 989QWX | 68827 | 07/03/2024 | TRA | | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 68827 | 07/03/2024 | TRA | SERVICE COMPLETED. | | | | | | |
| RPS25 | 989QWX | 68827 | 07/03/2024 | TRB | | 1 | LABOUR | MECH 1 | Labour | | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 68827 | 07/03/2024 | TRB | SERVICE COMPLETED BY WORKSHOP 03/07/2024.<br><br>REPLACED BATTERIES X 2 FOR TAILGATE LIFTER REPLACED 1 NOS BATTERIES LEAD REPLACED O RING IN FILTER VALVE FIXED VARIOUS AIR LEAKS |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 68827 | 07/03/2024 | TRB | 0 | LABOUR | APPRENA | Labour - Internal | | |
| RPS25 | 989QWX | 68827 | 07/03/2024 | TRB | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 68827 | 07/03/2024 | TRB | 16 | N70 BATTERY | | YAT | N70 BATTERY | |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | CON | | BRIVAL01 | EX00035184 | Consumables,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | 22-1101 | | BRIVAL01 | EX00035184 | SEALED COMPRESSOR, LGE SHAFT, A/C,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | 33-0230 | | BRIVAL01 | EX00035184 | SUCTION SERVICE VALVE ORING,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | 33-2805 | | BRIVAL01 | EX00035184 | MANIFOLD GASKET FRIDGE,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | 33-2513 | | BRIVAL01 | EX00035184 | FRONT COVER GASKET,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | R404A | | BRIVAL01 | EX00035184 | GAS R404A,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | NITRO | | BRIVAL01 | EX00035184 | NITROGEN HIGH PURITY,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | LAB | | BRIVAL01 | EX00035184 | Labour,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | Service completed by BVR 04/07/2024 - Travel to site and inspect unit for reported low on gas - Pressure test unit with nirtogen - Located leaking shaft seal - Pun | | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | CON | | BRIVAL01 | INV-00021814 | Consumables ,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | 22-1101 | | BRIVAL01 | INV-00021814 | SEALED COMPRESSOR, LGE SHAFT, A/C,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | 33-0230 | | BRIVAL01 | INV-00021814 | SUCTION SERVICE VALVE ORING,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | 33-2805 | | BRIVAL01 | INV-00021814 | MANIFOLD GASKET FRIDGE,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | 33-2513 | | BRIVAL01 | INV-00021814 | FRONT COVER GASKET,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | R404A | | BRIVAL01 | INV-00021814 | GAS R404A,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | NITRO | | BRIVAL01 | INV-00021814 | NITROGEN HIGH PURITY,RPS25 |
| RPS25 | 989QWX | 68986 | 07/04/2024 | FVGEN | 39 | LAB | | BRIVAL01 | INV-00021814 | Labour,RPS25 |
| RPS25 | 989QWX | 69032 | 07/09/2024 | GEN | 39 | LABOUR | MECH 5 | Labour | | |
| RPS25 | 989QWX | 69032 | 07/09/2024 | GEN | | REPAIR COMPLETED BY WORKSHOP 09/07/2024<br><br>TAIL GATE ISSUE. REPLACED TAILGATE LIFT PUMP REPAIRED TAILGATE BUTTON WIRING REPLACED ALL TAILGATE BUTTONS | | | | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 69032 | 07/09/2024 | GEN | 0 | LABOUR | MECH 1 | Labour - Internal | | | |
| RPS25 | 989QWX | 69032 | 07/09/2024 | GEN | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 69032 | 07/09/2024 | GEN | 16 | A358.049 | | YAT | MOTOR & RELAY 12V F3 | | |
| RPS25 | 989QWX | 69198 | 07/11/2024 | FVGEN | 39 | CON | | BRIVAL01 | | EX00035298 | Consumables,RPS25 |
| RPS25 | 989QWX | 69198 | 07/11/2024 | FVGEN | 39 | LAB | | BRIVAL01 | | EX00035298 | Labour,RPS25 |
| RPS25 | 989QWX | 69198 | 07/11/2024 | FVGEN | 13 | 98-7302NG | | YAT | SB HONEYCOMB ROADSIDE GRILL | | |
| RPS25 | 989QWX | 69198 | 07/11/2024 | FVGEN | Service completed by BVR 11/07/2024 - Travel to site and inspect unit - Fit missing honeycomb panel on drivers side (customer supplied) - Fit missing bolts - Unit | | | | | | |
| RPS25 | 989QWX | 69198 | 07/11/2024 | FVGEN | 39 | CON | | BRIVAL01 | | INV-00021922 | Consumables,RPS25 |
| RPS25 | 989QWX | 69198 | 07/11/2024 | FVGEN | 39 | LAB | | BRIVAL01 | | INV-00021922 | Labour,RPS25 |
| RPS25 | 989QWX | 70063 | 08/14/2024 | SANI | TRAILER SANITISATION COMPLETED ON 14.08.2024.<br><br>AT LOCATION : YATALA | | | | | | |
| RPS25 | 989QWX | 70084 | 08/14/2024 | TRA | 1 | LABOUR | MECH 6 | Labour | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 70084 | 08/14/2024 | TRA | SERVICE COMPLETED BY COREY ON 14/08/2024. BOOSTER CHANGED AND NEW AIR HOSES FITTED.<br><br>NOTED: NEEDS TAILGATE GREASED AND WORKED * TWO RED REFLECTORS FITTED TO BACK OF TRAILER * RIGHT HAND | | | | | |
| RPS25 | 989QWX | 70084 | 08/14/2024 | TRA | | 16 | CON | YAT | Consumables | |
| RPS25 | 989QWX | 70578 | 08/26/2024 | FVGEN | | 39 | CON | BRIVAL01 | EX00035960 | Consumables,RPS25 |
| RPS25 | 989QWX | 70578 | 08/26/2024 | FVGEN | | 39 | 92-0374 | BRIVAL01 | EX00035960 | SLAM LATCH FRIDGE, |
| RPS25 | 989QWX | 70578 | 08/26/2024 | FVGEN | | 39 | LAB | BRIVAL01 | EX00035960 | Labour, |
| RPS25 | 989QWX | 70578 | 08/26/2024 | FVGEN | Service completed by BVR 26/08/2024 - Travel to site and inspect unit - Found doors are not closing properly - Remove and replace worn door slams as required | | | | | |
| RPS25 | 989QWX | 70578 | 08/26/2024 | FVGEN | | 39 | CON | BRIVAL01 | INV-00022591 | Consumables,RPS25 |
| RPS25 | 989QWX | 70578 | 08/26/2024 | FVGEN | | 39 | 92-0374 | BRIVAL01 | INV-00022591 | SLAM LATCH FRIDGE, |
| RPS25 | 989QWX | 70578 | 08/26/2024 | FVGEN | | 39 | LAB | BRIVAL01 | INV-00022591 | Labour, |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 71035 | 09/17/2024 | DEFECT | | 1 | LABOUR | MECH | Labour |
| RPS25 | 989QWX | 71035 | 09/17/2024 | DEFECT | | | | | |
| RPS25 | 989QWX | 71035 | 09/17/2024 | DEFECT | DEFECT CLEARED. | | | | |
| RPS25 | 989QWX | 71035 | 09/17/2024 | DEFECT | Reported Defect :- Defect Code : 00012167 Defect Reference : RPS25 Date : 14/08/2024 Description of Defect : RIGHT HAND REAR LIGHT NOT WORKING | | | | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 71035 | 09/17/2024 | DEFECT | Reported Defect :- Defect Code : 00012166 Defect Reference : RPS25 Date : 14/08/2024 Description of Defect : TWO RED REFLECTORS FITTED TO BACK OF TRAILER |
| RPS25 | 989QWX | 71035 | 09/17/2024 | DEFECT | Reported Defect :- Defect Code : 00012165 Defect Reference : RPS25 Date : 14/08/2024 Description of Defect : NEEDS TAILGATE GREASED AND WORKED |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 71035 | 09/17/2024 | TRA | SERVICE COMPLETED BY COREY, TYLER & JOSH (WORKSHOP) ON 17/09/2024. | 1 | LABOUR | MECH 6 | Labour |
| RPS25 | 989QWX | 71035 | 09/17/2024 | TRA | REPLACED 2 SPRING EYE BUSHES WELDED BRACKET FOR REAR LICENCE PLATE FITTED BATTERY HOLD DOWN CLAMP TO FRIDGE MOTOR | | | | |
| RPS25 | 989QWX | 71035 | 09/17/2024 | TRA | | 0 | LABOUR | APPREN | Labour - Internal |
| RPS25 | 989QWX | 71035 | 09/17/2024 | TRA | | 0 | LABOUR | APPRENJC | Labour - Internal |
| RPS25 | 989QWX | 71035 | 09/17/2024 | TRA | | 16 | CON | | YAT Consumables |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 72647 | 10/01/2024 | SANI | TRAILER SANITISATION COMPLETED ON 01.10.2024<br><br>AT LOCATION : YATALA |
| RPS25 | 989QWX | 72664 | 10/03/2024 | CONCLE | FRIDGE MOTOR CONDENSOR CLEAN COMPLETED ON 03.10.2024<br><br>AT LOCATION : YATALA |
| RPS25 | 989QWX | 72664 | 10/03/2024 | SANI | TRAILER SANITISATION COMPLETED ON 03.10.2024<br><br>AT LOCATION : YATALA |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 72872 | 10/23/2024 | TRA | 1 | LABOUR | MECH 1 | Labour | | | |
| RPS25 | 989QWX | 72872 | 10/23/2024 | TRA | SERVICE COMPLETED. | | | | | | |
| RPS25 | 989QWX | 72872 | 10/23/2024 | TRA | 0 | LABOUR | APPRENJ | Labour - Internal | | | |
| RPS25 | 989QWX | 72872 | 10/23/2024 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 73622 | 11/22/2024 | TRA | 1 | LABOUR | MECH 5 | Labour | | | |
| RPS25 | 989QWX | 73622 | 11/22/2024 | TRA | 'A'<br>SERVICE<br>COMPLET<br>ED BY BEN<br>& TYLER<br>(WORKSH<br>OP) ON<br>22.11.202<br>4<br><br>REPLACED<br>MARKER<br>LIGHT<br>LHS.<br><br>F/E EXP :<br>DEC 2024 | | | | | | |
| RPS25 | 989QWX | 73622 | 11/22/2024 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 73622 | 11/22/2024 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 73622 | 11/22/2024 | TRA | 14 | 91700BL | | YAT | Clearance Light, LED Amber, Narva | | |
| RPS25 | 989QWX | 73684 | 11/26/2024 | TYRES | 15 | 99015526 | | BRIAUS01 | | EX00037361 | RUNOUT TYRE, |
| RPS25 | 989QWX | 73684 | 11/26/2024 | TYRES | 15 | 77000180 | | BRIAUS01 | | EX00037361 | CASE STOCK 11-22.5, |
| RPS25 | 989QWX | 73684 | 11/26/2024 | TYRES | 15 | 33000084 | | BRIAUS01 | | EX00037361 | FIT TBR TYRE, |
| RPS25 | 989QWX | 73684 | 11/26/2024 | TYRES | 15 | 33000517 | | BRIAUS01 | | EX00037361 | REMOVAL: CUSTOMER PULL POINT, |
| RPS25 | 989QWX | 73684 | 11/26/2024 | TYRES | 15 | 33000118 | | BRIAUS01 | | EX00037361 | SCHEDULED DEPOT SERVICE 15MIN, |
| RPS25 | 989QWX | 73684 | 11/26/2024 | TYRES | 15 | 33000118 | | BRIAUS01 | | 1.9E+08 | SCHEDULED DEPOT SERVICE 15MIN, |
| RPS25 | 989QWX | 73684 | 11/26/2024 | TYRES | 15 | 33000517 | | BRIAUS01 | | 1.9E+08 | REMOVAL: CUSTOMER PULL POINT, |
| RPS25 | 989QWX | 73684 | 11/26/2024 | TYRES | 15 | 33000084 | | BRIAUS01 | | 1.9E+08 | FIT TBR TYRE, |
| RPS25 | 989QWX | 73684 | 11/26/2024 | TYRES | 15 | 77000180 | | BRIAUS01 | | 1.9E+08 | CASE STOCK 11-22.5, |
| RPS25 | 989QWX | 73684 | 11/26/2024 | TYRES | 15 | 99015526 | | BRIAUS01 | | 1.9E+08 | RUNOUT TYRE, |
| RPS25 | 989QWX | 74443 | 01/02/2025 | DEFECT | 1 | LABOUR | MECH | Labour | | | |
| RPS25 | 989QWX | 74443 | 01/02/2025 | DEFECT | | | | | | | |
| RPS25 | 989QWX | 74443 | 01/02/2025 | DEFECT | DEFECT CLEARED. | | | | | | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 74443 | 01/02/2025 | DEFECT | Defect :- Defect Code : 00013079 Defect Reference : 35719(A) Date : 04/12/2024 Description of Defect : DRIVER'S MUDGUARD. KANGAROO BENT PLASTIC INTO WHEEL - RUBBING.<br><br>DEFECT CLEARED ON 02/01/20 | | | | |
| RPS25 | 989QWX | 74443 | 01/02/2025 | TRA | | 1 | LABOUR | APPREN | Labour |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | | SERVICE COMPLETED BY TYLER, BEN & JOSH (WORKSHOP) ON 02/01/2025.<br><br>BENT GUARD BRACKET BACK OUT REPLACED 2 SIDE CLEARANCE LIGHTS REPLACED 2 FORWARD FACING LIGHTS AT THE TOP | | | | |
| RPS25 | 989QWX | 74443 | 01/02/2025 | TRA | F/E EXP : | | | | |
| RPS25 | 989QWX | 74443 | 01/02/2025 | TRA | | 0 | LABOUR | MECH 5 | Labour - Internal |
| RPS25 | 989QWX | 74443 | 01/02/2025 | TRA | | 0 | LABOUR | APPRENJC | Labour - Internal |
| RPS25 | 989QWX | 74443 | 01/02/2025 | TRA | | 16 | CON | YAT | Consumables |
| RPS25 | 989QWX | 74443 | 01/02/2025 | TRA | | 14 | 91622 | YAT | LED Marker light. Amber. Narva |
| RPS25 | 989QWX | 74443 | 01/02/2025 | TRA | | 14 | 91700BL | YAT | Clearance Light, LED Amber, Narva |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | | AIR GAUGE: 18380 ADJUSTED : 18880 WEIGHBRIDGE: 19250 | | | | |
| RPS25 | 989QWX | 74907 | 01/12/2025 | WEICAL | AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | |
| RPS25 | 989QWX | 74967 | 01/17/2025 | DEFECT | | 1 | LABOUR | MECH | Labour |
| RPS25 | 989QWX | 74969 | 01/17/2025 | DEFECT | | 1 | LABOUR | MECH | Labour |
| RPS25 | 989QWX | 74967 | 01/17/2025 | DEFECT | | | | | |
| RPS25 | 989QWX | 74969 | 01/17/2025 | DEFECT | | | | | |
| RPS25 | 989QWX | 74967 | 01/17/2025 | DEFECT | DEFECT CLEARED. | | | | |
| RPS25 | 989QWX | 74969 | 01/17/2025 | DEFECT | DEFECT CLEARED. | | | | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # |
| | | | | | | | | | INSPECTION COMPLETED BY DIESEL SERVICES QLD ON 17/01/2025 INVOICE NO. 00030036 |
| | | | | | | | | | NO APPARENT FAULTS FOUND |
| RPS25 | 989QWX | 74969 | 01/17/2025 | EXOINS | | | | | |
| RPS25 | 989QWX | 74969 | 01/17/2025 | EXOINS | 1 | LABEXT | DIESER01 | EX00038149 | C & D SERVICE WITH BEARINGS AND GREASE, |
| RPS25 | 989QWX | 74969 | 01/17/2025 | EXOINS | 16 | CON | DIESER01 | EX00038149 | Consumables, |
| RPS25 | 989QWX | 74969 | 01/17/2025 | EXOINS | 16 | DEGREASER | DIESER01 | EX00038149 | DEGREASER, |
| RPS25 | 989QWX | 74969 | 01/17/2025 | EXOINS | 1 | LABEXT | DIESER01 | 30036 | C & D SERVICE WITH BEARINGS AND GREASE, |
| RPS25 | 989QWX | 74969 | 01/17/2025 | EXOINS | 16 | CON | DIESER01 | 30036 | Consumables, |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 74969 | 01/17/2025 | EXOINS | 16 | DEGREASER | | DIESER01 | 30036 | DEGREASER, |
| RPS25 | 989QWX | 74967 | 01/17/2025 | TRA | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 74967 | 01/17/2025 | TRA | SERVICE COMPLETED. | | | | | |
| RPS25 | 989QWX | 74967 | 01/17/2025 | TRB | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 74967 | 01/17/2025 | TRB | SERVICE COMPLETED. | | | | | |
| RPS25 | 989QWX | 74967 | 01/17/2025 | TRC | SERVICE COMPLETED BY DIESEL SERVICES QLD ON 17/01/2025. INVOICE NO. 00030036<br><br>Check as per C& D no bearings - bearings unserviceable. Change to C & D with bearings C and D service with bearings and | | | | | |
| RPS25 | 989QWX | 74967 | 01/17/2025 | TRC | 11 | 0980107040TSSC | | YAT | KIT W/BRG & SEAL 10T ECO | |
| RPS25 | 989QWX | 74967 | 01/17/2025 | TRC | 16 | 2.57E+08 | | YAT | Hub Seal Grease, BPW, Eco Plus | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | AIR GAUGE: 17000 ADJUSTED: 17250 WEIGHBRIDGE: 17500 |
| RPS25 | 989QWX | 75538 | 01/26/2025 | WEICAL | | | | | | AIR GAUGE CALIBRATION COMPLETED CORRECTLY. |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | 39 | CON | ICEGRO01 | EX00038416 | | Consumables ,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | 39 | 555920 | ICEGRO01 | EX00038416 | | U BOLT EEC - FRIDGE MOTOR,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | 39 | 665784 | ICEGRO01 | EX00038416 | | VIBRASORBER (MOUNT),RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | 39 | 910372 | ICEGRO01 | EX00038416 | | CLAMP TUBE - FRIDGE MOTOR,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | 39 | R404A | ICEGRO01 | EX00038416 | | GAS R404A,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | 39 | 33-2805-10 | ICEGRO01 | EX00038416 | | DISCHARGE GASKET,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | 39 | PH-62NTA-6 | ICEGRO01 | EX00038416 | | 3/8" JOINER (PARKER HANNIFIN),RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | 39 | PH-62NTA-4 | ICEGRO01 | EX00038416 | | 1/4" JOINER (PARKER HANNIFIN),RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | 39 | NITRO | ICEGRO01 | EX00038416 | | NITROGEN HIGH PURITY,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | 39 | LAB | ICEGRO01 | EX00038416 | | Labour,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | 39 | CON | ICEGRO01 | EX00038416 | | WELDING & MATERIALS,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | 39 | 910373 | ICEGRO01 | EX00038416 | | CLAMP SET,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | Service completed by Iceman 03/02/2025 - Installed gauges - Checked refrigerant level pressures - Pressure tested system with nitrogen, found leaking vibrasorb | | | | | |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | 39 | CON | ICEGRO01 | 896265 | | Consumables ,RPS25 |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | | 39 | 555920 | | ICEGRO01 | 896265 | U BOLT EEC - FRIDGE MOTOR,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | | 39 | 665784 | | ICEGRO01 | 896265 | VIBRASORBER (MOUNT),RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | | 39 | 910372 | | ICEGRO01 | 896265 | CLAMP TUBE - FRIDGE MOTOR,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | | 39 | R404A | | ICEGRO01 | 896265 | GAS R404A,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | | 39 | 33-2805-10 | | ICEGRO01 | 896265 | DISCHARGE GASKET,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | | 39 | PH-62NTA-6 | | ICEGRO01 | 896265 | 3/8" JOINER (PARKER HANNIFIN),RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | | 39 | PH-62NTA-4 | | ICEGRO01 | 896265 | 1/4" JOINER (PARKER HANNIFIN),RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | | 39 | NITRO | | ICEGRO01 | 896265 | NITROGEN HIGH PURITY,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | | 39 | LAB | | ICEGRO01 | 896265 | Labour,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | | 39 | CON | | ICEGRO01 | 896265 | WELDING & MATERIALS,RPS25 |
| RPS25 | 989QWX | 75454 | 02/03/2025 | FVGEN | | 39 | 910373 | | ICEGRO01 | 896265 | CLAMP SET,RPS25 |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | | 0 | LABOUR | MECH | Labour | | |
| | | | | | VAN "B" SERVICE COMPLETED.<br><br>FRIDGE VAN UNIT CALIBRATED @ SERVICE.<br><br>SERVICE COMPLETED BY BVR.<br><br>OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL | | | | | | |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | R+R | | | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | Consumab les |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | 39 | CON | ICEGRO01 | EX00038554 | | ,RPS25 |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | 39 | CC | ICEGRO01 | EX00038554 | | CALIBRATION CETIFICATE,RPS25 |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | 39 | 100417 | ICEGRO01 | EX00038554 | | Filter Service Kit, Fridge Motor, SLX-400,RPS25 |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | 39 | 77-2359-10 | ICEGRO01 | EX00038554 | | ALTERNATOR PULEY SB,RPS25 |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | 39 | LAB | ICEGRO01 | EX00038554 | | Labour,RPS25 |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | 39 | 78-1360-10 | ICEGRO01 | EX00038554 | | ALTERNATOR TO WATER PUMP BELT SB200/SB,RPS25 |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | 40 | 3413005 | YAT | OIL 15W-40, CK 4/E9 | | |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | Service completed by Iceman 17/02/2025 - Carried out B Service as per Iceman Specifications - Loosened fan belts - Replaced worn alt belt and pulley - Refitted a | | | | | |
| | | | | | | | | | | Consumab les |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | 39 | CON | ICEGRO01 | 897253 | | ,RPS25 |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | 39 | CC | ICEGRO01 | 897253 | | CALIBRATION CETIFICATE,RPS25 |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | 39 | 100417 | ICEGRO01 | 897253 | | Filter Service Kit, Fridge Motor, SLX-400,RPS25 |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | 39 | 77-2359-10 | ICEGRO01 | 897253 | | ALTERNATOR PULEY SB,RPS25 |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | 39 | LAB | ICEGRO01 | 897253 | | Labour,RPS25 |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVANB | 39 | 78-1360-10 | ICEGRO01 | 897253 | | ALTERNATOR TO WATER PUMP BELT SB200/SB,RPS25 |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVCAL | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 75797 | 02/19/2025 | FRIVCAL | FRIDGE VAN CALIBRATION COMPLETED | | | | | |
| RPS25 | 989QWX | 75981 | 02/26/2025 | DEFECT | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 75981 | 02/26/2025 | DEFECT | DEFECT CLEARED. | | | | | |
| RPS25 | 989QWX | 75981 | 02/26/2025 | TRA | 1 | LABOUR | APPRENJ | Labour - Internal | | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | A SERVICE COMPLETED BY JOSEPH (WORKSHOP) ON 26/02/2025. | | | | | | |
| RPS25 | 989QWX | 75981 | 02/26/2025 | TRA | FIRE EXT EXP: JULY 2025 | | | | | | |
| RPS25 | 989QWX | 75981 | 02/26/2025 | TRA | | 16 | CON | YAT | Consumables | | |
| RPS25 | 989QWX | 77005 | 04/04/2025 | FVGEN | | 39 | CON | ICEGRO01 | | EX00039378 | Consumables,RPS25 |
| RPS25 | 989QWX | 77005 | 04/04/2025 | FVGEN | | 39 | LAB | ICEGRO01 | | EX00039378 | Labour,RPS25 |
| RPS25 | 989QWX | 77005 | 04/04/2025 | FVGEN | Service completed by Iceman 04/04/2025 - Inspected unit - Unit set to -22c and not reaching set point - Defrosted both zones - Ran unit down to -22c, all ok - Ch | | | | | | |
| RPS25 | 989QWX | 77005 | 04/04/2025 | FVGEN | | 39 | CON | ICEGRO01 | | 900545 | Consumables,RPS25 |
| RPS25 | 989QWX | 77005 | 04/04/2025 | FVGEN | | 39 | LAB | ICEGRO01 | | 900545 | Labour,RPS25 |
| RPS25 | 989QWX | 77038 | 04/11/2025 | DEFECT | | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 77038 | 04/11/2025 | DEFECT | DEFECT CLEARED. | | | | | | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 77038 | 04/11/2025 | DEFECT | Reported Defect :- Defect Code : 00013345 Defect Reference : RPS25 Date : 15/01/2025 Description of Defect : LEGS ARE VERY HARD TO WIND. PROBABLY TOO HARD FOR FEMALE AND OLDER DRIVERS | | | | |
| RPS25 | 989QWX | 77038 | 04/11/2025 | TRA | | 1 | LABOUR | APPREN | Labour - Internal |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 77038 | 04/11/2025 | TRA | A SERVICE COMPLETED BY WORKSHOP 11/04/2025<br><br>FIRE EXT EXP: MAY 25<br><br>CHECKED CHARGE RATE OF TAILGATE LIFTER CANT FAULT LEG - WIND UP AND DOWN PERFECT | | | | | |
| RPS25 | 989QWX | 77038 | 04/11/2025 | TRA | | 16 | CON | | YAT | Consumables |
| RPS25 | 989QWX | 77896 | 05/22/2025 | TRA | | 1 | LABOUR | MECH 1 | Labour - Internal | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 77896 | 05/22/2025 | TRA | COMPLETED BY WORKSHOP 22.05.2025<br><br>FIRE EXT EXP: JULY 2025<br><br>ADJUST SUSPENSION SIDE HEIGHT STRAIGHTEN AND TIGHTEN R/H FRONT MUDGUARD MOUNT REVEIVET AND SECURE L/H |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 77896 | 05/22/2025 | TRA | 16 | CON | | YAT | Consumables | |
| RPS25 | 989QWX | 77896 | 05/22/2025 | TRA | 0 | LABOUR | APPRENJC | Labour - Internal | | |
| RPS25 | 989QWX | 78191 | 05/27/2025 | TYRES | 15 | 11002821 | | BRIAUS01 | EX00040164 | 11R22.5 148/145L BS R119 ECO, |
| RPS25 | 989QWX | 78191 | 05/27/2025 | TYRES | 15 | 99015526 | | BRIAUS01 | EX00040164 | RUNOUT TYRE, |
| RPS25 | 989QWX | 78191 | 05/27/2025 | TYRES | 15 | 77000232 | | BRIAUS01 | EX00040164 | CASE STOCK 11R22.5 ECOPIA, |
| RPS25 | 989QWX | 78191 | 05/27/2025 | TYRES | 15 | 33000084 | | BRIAUS01 | EX00040164 | FIT TBR TYRE, |
| RPS25 | 989QWX | 78191 | 05/27/2025 | TYRES | 15 | 33000517 | | BRIAUS01 | EX00040164 | REMOVAL: CUSTOMER PULL POINT, |
| RPS25 | 989QWX | 78191 | 05/27/2025 | TYRES | 15 | 33000096 | | BRIAUS01 | EX00040164 | PUNCTURE REPAIR TBR, |
| RPS25 | 989QWX | 78191 | 05/27/2025 | TYRES | 15 | 33000118 | | BRIAUS01 | EX00040164 | SCHEDULED DEPOT SERVICE 15MIN, |
| RPS25 | 989QWX | 78191 | 05/27/2025 | TYRES | 15 | 11002821 | | BRIAUS01 | 1.91E+08 | 11R22.5 148/145L BS R119 ECO, |
| RPS25 | 989QWX | 78191 | 05/27/2025 | TYRES | 15 | 99015526 | | BRIAUS01 | 1.91E+08 | RUNOUT TYRE, |
| RPS25 | 989QWX | 78191 | 05/27/2025 | TYRES | 15 | 77000232 | | BRIAUS01 | 1.91E+08 | CASE STOCK 11R22.5 ECOPIA, |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 78191 | 05/27/2025 | TYRES | 15 | 33000084 | | BRIAUS01 | 1.91E+08 | FIT TBR TYRE, |
| RPS25 | 989QWX | 78191 | 05/27/2025 | TYRES | 15 | 33000517 | | BRIAUS01 | 1.91E+08 | REMOVAL: CUSTOMER PULL POINT, |
| RPS25 | 989QWX | 78191 | 05/27/2025 | TYRES | 15 | 33000096 | | BRIAUS01 | 1.91E+08 | PUNCTURE REPAIR TBR, |
| RPS25 | 989QWX | 78191 | 05/27/2025 | TYRES | 15 | 33000118 | | BRIAUS01 | 1.91E+08 | SCHEDULED DEPOT SERVICE 15MIN, |
| RPS25 | 989QWX | 81711 | 06/27/2025 | WEICAL | WEIGHBRIDGE:18480 AIR GAUGE:18500 ADJUSTED: 18750<br><br>AIR GAUGE CALIBRATION COMPLETED CORRECTLY. | | | | | |
| RPS25 | 989QWX | 79045 | 07/03/2025 | DEFECT | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 79045 | 07/03/2025 | DEFECT | DEFECT CLEARED. | | | | | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 79045 | 07/03/2025 | DEFECT | Defect :- Defect Code : 00014555 Defect Reference : RPS25 Date : 18/06/2025 Description of Defect : LEGS ARE VERY HARD TO WIND UP AND DOWN, NEEDS FEW NEW FEMALE LIGHT SOCKET AND DUMMY EBS PLUG | | | | | | |
| RPS25 | 989QWX | 79144 | 07/03/2025 | FVGEN | | 39 | CON | | ICEGRO01 | EX00040824 | Consumables ,RPS25 |
| RPS25 | 989QWX | 79144 | 07/03/2025 | FVGEN | | 39 | 400974 | | ICEGRO01 | EX00040824 | Sensor, Return Air, QTK Fridge,RPS25 |
| RPS25 | 989QWX | 79144 | 07/03/2025 | FVGEN | | 39 | LAB | | ICEGRO01 | EX00040824 | Labour,RPS25 |
| RPS25 | 989QWX | 79144 | 07/03/2025 | FVGEN | Service completed by Iceman 03/07/2025 - Inspected unit - Removed covers - Replaced u/s evap coil sensor as required - Refitted covers - Topped up engine oil - | | | | | | |
| RPS25 | 989QWX | 79144 | 07/03/2025 | FVGEN | | 39 | CON | | ICEGRO01 | 906486 | Consumables ,RPS25 |
| RPS25 | 989QWX | 79144 | 07/03/2025 | FVGEN | | 39 | 400974 | | ICEGRO01 | 906486 | Sensor, Return Air, QTK Fridge,RPS25 |
| RPS25 | 989QWX | 79144 | 07/03/2025 | FVGEN | | 39 | LAB | | ICEGRO01 | 906486 | Labour,RPS25 |
| RPS25 | 989QWX | 79045 | 07/03/2025 | TRA | | 1 | LABOUR | MECH | Labour - Internal | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | A SERVICE COMPLETED. | | | | | |
| RPS25 | 989QWX | 79045 | 07/03/2025 | TRA | FIRE EXT EXP: | | | | | |
| RPS25 | 989QWX | 79045 | 07/03/2025 | TRA | | 16 | CON | | YAT | Consumables |
| RPS25 | 989QWX | 79045 | 07/03/2025 | TRB | | 1 | LABOUR | MECH 1 | Labour - Internal | |
| RPS25 | 989QWX | 79045 | 07/03/2025 | TRB | COMPLETED BY WORKSHOP 03.07.2025 FIRE EXT EXP: JANUARY 2026 REPAIR BAD CONNECTION TO INTERNAL LIGHTS REPLACED LANDING LEGS FITTED DUMMY EBS PLUG DEFECT N # 14555 - REPLACE | | | | | |
| RPS25 | 989QWX | 79045 | 07/03/2025 | TRB | | 16 | CON | | YAT | Consumables |
| RPS25 | 989QWX | 79045 | 07/03/2025 | TRB | | 0 | LABOUR | APPRENJC | Labour - Internal | |
| RPS25 | 989QWX | 79045 | 07/03/2025 | TRB | | 0 | LABOUR | MECH 5 | Labour - Internal | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 79045 | 07/03/2025 | TRB | 16 | B0201 | | YAT | 19" LANDING LEG C/W COMPENSATOR FEET P/N 2463 520 011 | |
| RPS25 | 989QWX | 79045 | 07/03/2025 | TRB | 16 | 82196 | | YAT | EBS Plug, 7 pin 12/24v | |
| RPS25 | 989QWX | 79207 | 07/08/2025 | FVGEN | 39 | CON | | ICEGRO01 | EX00040856 | Consumables,RPS25 |
| RPS25 | 989QWX | 79207 | 07/08/2025 | FVGEN | 39 | 400974 | | ICEGRO01 | EX00040856 | Sensor, Return Air, QTK Fridge,RPS25 |
| RPS25 | 989QWX | 79207 | 07/08/2025 | FVGEN | 39 | LAB | | ICEGRO01 | EX00040856 | Labour,RPS25 |
| RPS25 | 989QWX | 79207 | 07/08/2025 | FVGEN | Service completed by Iceman 08/07/2025 - Inspected unit - Removed covers - Replaced u/s discharge sensor - Recalibrated unit - Checked operation - Unit ran o | | | | | |
| RPS25 | 989QWX | 79207 | 07/08/2025 | FVGEN | 39 | CON | | ICEGRO01 | 906794 | Consumables,RPS25 |
| RPS25 | 989QWX | 79207 | 07/08/2025 | FVGEN | 39 | 400974 | | ICEGRO01 | 906794 | Sensor, Return Air, QTK Fridge,RPS25 |
| RPS25 | 989QWX | 79207 | 07/08/2025 | FVGEN | 39 | LAB | | ICEGRO01 | 906794 | Labour,RPS25 |
| RPS25 | 989QWX | 79338 | 07/16/2025 | FVGEN | 39 | CON | | ICEGRO01 | EX00040949 | Consumables,RPS25 |
| RPS25 | 989QWX | 79338 | 07/16/2025 | FVGEN | 39 | LAB | | ICEGRO01 | EX00040949 | Labour,RPS25 |
| RPS25 | 989QWX | 79338 | 07/16/2025 | FVGEN | 35 | SS66TI | | YAT | BATTERY, STOP/START AGM | |
| RPS25 | 989QWX | 79338 | 07/16/2025 | FVGEN | Service completed by Iceman 16/07/2025 - Inspected unit for reported not starting - Replaced u/s battery (customer supplied) - Checked operation - Unit ran on | | | | | |
| RPS25 | 989QWX | 79338 | 07/16/2025 | FVGEN | 39 | CON | | ICEGRO01 | 907227 | Consumables,RPS25 |
| RPS25 | 989QWX | 79338 | 07/16/2025 | FVGEN | 39 | LAB | | ICEGRO01 | 907227 | Labour,RPS25 |
| RPS25 | 989QWX | 80661 | 08/07/2025 | TYRES | 15 | 11002821 | | BRIAUS01 | EX00041879 | 11R22.5 148/145L BS R119 ECO, |
| RPS25 | 989QWX | 80661 | 08/07/2025 | TYRES | 15 | 77000232 | | BRIAUS01 | EX00041879 | CASE STOCK 11R22.5 ECOPIA, |
| RPS25 | 989QWX | 80661 | 08/07/2025 | TYRES | 15 | 33000084 | | BRIAUS01 | EX00041879 | FIT TBR TYRE, |
| RPS25 | 989QWX | 80661 | 08/07/2025 | TYRES | 15 | 33001507 | | BRIAUS01 | EX00041879 | CUSTOMER SCRAPPED OWN TYRE, |
| RPS25 | 989QWX | 80661 | 08/07/2025 | TYRES | 15 | 33000517 | | BRIAUS01 | EX00041879 | REMOVAL: CUSTOMER PULL POINT, |
| RPS25 | 989QWX | 80661 | 08/07/2025 | TYRES | 15 | 33000531 | | BRIAUS01 | EX00041879 | REMOVAL: FLAT OR UNDER INFLATED, |
| RPS25 | 989QWX | 80661 | 08/07/2025 | TYRES | 15 | 33000118 | | BRIAUS01 | EX00041879 | SCHEDULED DEPOT SERVICE 15MIN, |
| RPS25 | 989QWX | 80661 | 08/07/2025 | TYRES | 15 | 11002821 | | BRIAUS01 | 1.91E+08 | 11R22.5 148/145L BS R119 ECO, |
| RPS25 | 989QWX | 80661 | 08/07/2025 | TYRES | 15 | 77000232 | | BRIAUS01 | 1.91E+08 | CASE STOCK 11R22.5 ECOPIA, |
| RPS25 | 989QWX | 80661 | 08/07/2025 | TYRES | 15 | 33000084 | | BRIAUS01 | 1.91E+08 | FIT TBR TYRE, |
| RPS25 | 989QWX | 80661 | 08/07/2025 | TYRES | 15 | 33001507 | | BRIAUS01 | 1.91E+08 | CUSTOMER SCRAPPED OWN TYRE, |
| RPS25 | 989QWX | 80661 | 08/07/2025 | TYRES | 15 | 33000517 | | BRIAUS01 | 1.91E+08 | REMOVAL: CUSTOMER PULL POINT, |
| RPS25 | 989QWX | 80661 | 08/07/2025 | TYRES | 15 | 33000531 | | BRIAUS01 | 1.91E+08 | REMOVAL: FLAT OR UNDER INFLATED, |
| RPS25 | 989QWX | 80661 | 08/07/2025 | TYRES | 15 | 33000118 | | BRIAUS01 | 1.91E+08 | SCHEDULED DEPOT SERVICE 15MIN, |
| RPS25 | 989QWX | 79884 | 08/11/2025 | GEN | 39 | LABOUR | MECH | Labour | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | REPAIR COMPLETED. | | | | | |
| RPS25 | 989QWX | 79884 | 08/11/2025 | GEN | FIRE EXT EXP: | | | | | |
| RPS25 | 989QWX | 79884 | 08/11/2025 | GEN | | 16 | CON | | YAT | Consumables |
| RPS25 | 989QWX | 79884 | 08/11/2025 | TRA | COMPLETED BY WORKSHOP 11/8/2025 | 1 | LABOUR | MECH 5 | Labour - Internal | |
| RPS25 | 989QWX | 79884 | 08/11/2025 | TRA | FIRE EXT EXP: JANUARY 2026 REPLACE HEIGHT CONTROL VALVE AND ADJUSTED TO 375MM REPLACE 2 X SHOCK ABSORBERS 3RD AXEL REPAIRED CRACKS | | | | | |
| RPS25 | 989QWX | 79884 | 08/11/2025 | TRA | | 16 | CON | | YAT | Consumables |
| RPS25 | 989QWX | 79884 | 08/11/2025 | TRA | | 0 | LABOUR | MECH 1 | Labour - Internal | |
| RPS25 | 989QWX | 79884 | 08/11/2025 | TRA | | 0 | LABOUR | APPRENJ | Labour - Internal | |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 79884 | 08/11/2025 | TRA | 0 | LABOUR | APPRENJC | Labour - Internal | | | |
| RPS25 | 989QWX | 79884 | 08/11/2025 | TRA | 16 | 4.64E+09 | | YAT | Levelling Valve, M12x1.5mm | | |
| RPS25 | 989QWX | 79884 | 08/11/2025 | TRA | 16 | F5002 | | YAT | SHOCK ABSORBER, BPW LONG | | |
| RPS25 | 989QWX | 79884 | 08/11/2025 | TRA | 16 | ZS-32 | | YAT | AZOLLA ZS-32 HYDRAULIC OIL | | |
| RPS25 | 989QWX | 79884 | 08/11/2025 | TRA | 6 | 215063 | | YAT | OIL FILTER | | |
| RPS25 | 989QWX | 79935 | 08/11/2025 | TYRES | 15 | 33000096 | | BRIAUS01 | | EX00041364 | PUNCTURE REPAIR TBR, |
| RPS25 | 989QWX | 79935 | 08/11/2025 | TYRES | 15 | 33000118 | | BRIAUS01 | | EX00041364 | SCHEDULED DEPOT SERVICE 15MIN, |
| RPS25 | 989QWX | 79935 | 08/11/2025 | TYRES | 15 | 33000096 | | BRIAUS01 | | 1.91E+08 | PUNCTURE REPAIR TBR, |
| RPS25 | 989QWX | 79935 | 08/11/2025 | TYRES | 15 | 33000118 | | BRIAUS01 | | 1.91E+08 | SCHEDULED DEPOT SERVICE 15MIN, |
| RPS25 | 989QWX | 80881 | 09/10/2025 | FRIVANB | 0 | LABOUR | MECH | Labour | | | |
| | | | | | | VAN "B" SERVICE COMPLETED.<br><br>FRIDGE VAN UNIT CALIBRATED @ SERVICE.<br><br>SERVICE COMPLETED BY ICEMAN<br><br>OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL | | | | | | |
| RPS25 | 989QWX | 80881 | 09/10/2025 | FRIVANB | | R+R | | | | | |

| | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | Consumab les |
| RPS25 | 989QWX | 80881 | 09/10/2025 | FRIVANB | 39 | CON | | ICEGRO01 | EX00042039 | ,RPS25 |
| RPS25 | 989QWX | 80881 | 09/10/2025 | FRIVANB | 39 | CC | | ICEGRO01 | EX00042039 | CALIBRATION CETIFICATE,RPS25 |
| RPS25 | 989QWX | 80881 | 09/10/2025 | FRIVANB | 39 | | 100417 | ICEGRO01 | EX00042039 | Filter Service Kit, Fridge Motor, SLX-400,RPS25 |
| RPS25 | 989QWX | 80881 | 09/10/2025 | FRIVANB | 39 | LAB | | ICEGRO01 | EX00042039 | Labour,RPS25 |
| RPS25 | 989QWX | 80881 | 09/10/2025 | FRIVANB | 40 | | 3413005 | YAT | OIL 15W-40, CK 4/E9 | |
| RPS25 | 989QWX | 80881 | 09/10/2025 | FRIVANB | SERVICE COMPLETED BY ICEMAN 10/09/2025 - CARRIED OUT B SERVICE AS PER ICEMAN SPECIFICATIONS | | | | | |
| | | | | | | | | | | Consumab les |
| RPS25 | 989QWX | 80881 | 09/10/2025 | FRIVANB | 39 | CON | | ICEGRO01 | 910765 | ,RPS25 |
| RPS25 | 989QWX | 80881 | 09/10/2025 | FRIVANB | 39 | CC | | ICEGRO01 | 910765 | CALIBRATION CETIFICATE,RPS25 |
| RPS25 | 989QWX | 80881 | 09/10/2025 | FRIVANB | 39 | | 100417 | ICEGRO01 | 910765 | Filter Service Kit, Fridge Motor, SLX-400,RPS25 |
| RPS25 | 989QWX | 80881 | 09/10/2025 | FRIVANB | 39 | LAB | | ICEGRO01 | 910765 | Labour,RPS25 |
| RPS25 | 989QWX | 80881 | 09/10/2025 | FRIVCAL | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 80881 | 09/10/2025 | FRIVCAL | FRIDGE VAN CALIBRATION COMPLETED | | | | | |
| RPS25 | 989QWX | 81340 | 10/09/2025 | DEFECT | 1 | LABOUR | MECH | Labour | | |
| RPS25 | 989QWX | 81340 | 10/09/2025 | DEFECT | DEFECT CLEARED. | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| RPS25 | 989QWX | 81340 | 10/09/2025 | DEFECT | Reported Defect :- Defect Code : 00014824 Defect Reference : RPS25 Date : 11/08/2025 Description of Defect : NEED NEW NHUR LABEL - MADI TO ORDER |
| RPS25 | 989QWX | 81340 | 10/09/2025 | DEFECT | Reported Defect :- Defect Code : 00014978 Defect Reference : RPS25 Date : 26/08/2025 Description of Defect : NO TELEMETRY DATA FOR TEMPS |

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 81340 | 10/09/2025 | TRA | 1 | LABOUR | MECH 1 | Labour - Internal | | | |
| | | | | | | COMPLETED BY WORKSHOP 09/10/2025<br><br>FIRE EXT EXP: JANUARY 2026<br><br>REPLACE 7 PIN LIGHT PLUG STRAIGHTEN LH FRONT MUDGUARD MOUNT BRACKET<br><br>DEFECT 14824 - FIT NEW | | | | | | |
| RPS25 | 989QWX | 81340 | 10/09/2025 | TRA | | NHVR | | | | | |
| RPS25 | 989QWX | 81340 | 10/09/2025 | TRA | 16 | CON | | YAT | Consumables | | |
| RPS25 | 989QWX | 81340 | 10/09/2025 | TRA | 0 | LABOUR | APPREN | Labour - Internal | | | |
| RPS25 | 989QWX | 81340 | 10/09/2025 | TRA | 0 | LABOUR | APPREND | Labour - Internal | | | |
| RPS25 | 989QWX | 81853 | 10/22/2025 | TYRES | 15 | 11004117 | | BRIAUS01 | EX00042662 | 11R22.5 148/145L FS FT469, | |
| RPS25 | 989QWX | 81853 | 10/22/2025 | TYRES | 15 | 77000180 | | BRIAUS01 | EX00042662 | CASE STOCK 11-22.5, | |
| RPS25 | 989QWX | 81853 | 10/22/2025 | TYRES | 15 | 33000084 | | BRIAUS01 | EX00042662 | FIT TBR TYRE, | |
| RPS25 | 989QWX | 81853 | 10/22/2025 | TYRES | 15 | 33001507 | | BRIAUS01 | EX00042662 | CUSTOMER SCRAPPED OWN TYRE, | |
| RPS25 | 989QWX | 81853 | 10/22/2025 | TYRES | 15 | 33000518 | | BRIAUS01 | EX00042662 | REMOVAL: CUSTOMER REQUEST, | |
| RPS25 | 989QWX | 81853 | 10/22/2025 | TYRES | 15 | 33000535 | | BRIAUS01 | EX00042662 | REMOVAL: WORN TOO FAR, | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| RPS25 | 989QWX | 81853 | 10/22/2025 | TYRES | 15 | 11004117 | BRIAUS01 | 1.92E+08 | 11R22.5 148/145L FS FT469, |
| RPS25 | 989QWX | 81853 | 10/22/2025 | TYRES | 15 | 77000180 | BRIAUS01 | 1.92E+08 | CASE STOCK 11-22.5, |
| RPS25 | 989QWX | 81853 | 10/22/2025 | TYRES | 15 | 33000084 | BRIAUS01 | 1.92E+08 | FIT TBR TYRE, |
| RPS25 | 989QWX | 81853 | 10/22/2025 | TYRES | 15 | 33001507 | BRIAUS01 | 1.92E+08 | CUSTOMER SCRAPPED OWN TYRE, |
| RPS25 | 989QWX | 81853 | 10/22/2025 | TYRES | 15 | 33000518 | BRIAUS01 | 1.92E+08 | REMOVAL: CUSTOMER REQUEST, |
| RPS25 | 989QWX | 81853 | 10/22/2025 | TYRES | 15 | 33000535 | BRIAUS01 | 1.92E+08 | REMOVAL: WORN TOO FAR, |

Total for Asset ########

Total for Report ########

Options:
Sort By
-
AssetCode
Starting
Asset
Code -
RPS25
To
- RPS25
Starting
Registrati
on -
To
-
Starting
Operation
s No -
To
-
From:
Work
Order
Location -
To
-
From:

JT ALARM 15, GLOW PLUG CIRCUIT DIR TY, CLEAN GLOW PLUG TERMINALS, ALL OK - WORK COMPLETED BY JC & SL TOTAL TRANSPORT AT YATALA YA

,RF

,RF

ARGE AIR SENS

EFLECTO

EFLECTO

/ sensor - Remove and replace u/s sensor - Unit run on t

temp sensor - Calibrated sensors - Ran both zones to 0c - Unit run on test - Pretrip pass

nator and fan belts as required - Unit run on t

and replace worn drive bushes and cracked HP switches - Fit new suction o-rings - Vac out unit - Unit run on t

belt - Unitr un on t

BA

BA

5. REMOVED AND REPLACED BEARIN

5. REMOVED AND REPLACED BEARIN

t - Found alternator not charging - Remove and replace u/s alt - Unit run on t

move and replace worn front engine mounts - Tighten belts - Refit battery - Ran unit down to 14c - Unit run on t

Pump down compressor and remove - Remove drive plate and bell housing - Remove and replace u/s shaft seal - Clean down dirty bell housing on compressor - Vac out unit and regas system - Tighten alt belt - Top up gas - Run to 0c and check gas level -

Jnit run on t

red - Check operation - Unit run on t

:orber - Replaced u/s discharge vibrasorber - Replaced worn discharge clamps - Reinstalled service valve with new gasket - Pressure tested with nitrogen and checked for leaks, ok - Vac out unit and regassed system - Found 3/8" and 1/4" fuel lines have ru

ed and tensioned fan be

Checked operations - Unit ran on t

oil - Checked operation - Unit ran on t

n on t

on t

Unit run on t

ubber through - Repaired fuel lines and resecured - Ran both zones down to 0c - Checked operation - Unit ran on te