Vehicle History Detail

Fleet #	
Registration	
Make	SCANIA
Model	R560
VIN / Chassis #	YS2R6X40009187404

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
29/07/2026	1,259,107 kms	**A - 10K/90Days** S-31830 A SERVICE			$369.37
27/06/2026		**ENGINE DERATED, GEARBOX MALFUNCTION, HIGH EMISSIONS WARNING** R-65958			$0.00
15/06/2026	1,255,513 kms	**COOLANT LEAK** R-63348	SCANIA AUSTRALIA 10 - 52157		$858.00
12/06/2026	1,255,513 kms	**TAILLIGHT** R-63323			$309.55
09/06/2026	1,255,221 kms	**FUEL LEAK** R-62865			$503.83
28/05/2026	1,255,221 kms	**ADBLUE PUMP** R-62548 replace adblue pump and test operation	SCANIA AUSTRALIA 10 - 52157		$7,741.69
27/05/2026	1,253,714 kms	**B - 20K/180Days** S-30411 B SERVICE			$333.50
27/05/2026		**DIFF OIL LEAK** R-62433	SCANIA AUSTRALIA 10 - 52157		$296.76
22/05/2026	1,249,504 kms	**NO NHVR STICKER** R-62138			$77.00
04/05/2026	1,253,097 kms	**DERATED** R-61001			$612.92
29/04/2026	1,253,097 kms	**DRIVERS SEAT** R-60852 Using three air way valve for the air supply for the seat .			$231.00
06/03/2026	1,246,271 kms	**DRIVERS SEAT WORN** R-58290	SCANIA AUSTRALIA 10 - 52157		$1,286.34
06/03/2026	1,246,271 kms	**MIRROR** R-58095			$77.00
02/03/2026	1,246,271 kms	**A - 10K/90Days** S-28394 A SERVICE			$231.00
02/03/2026	1,246,271 kms	**WORN TYRES** T-16070 Replace TYRES 2ND AXLE DRIVE			$1,548.01

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
02/03/2026	1,246,271 kms	**CHECKOVER** R-57804 A service completed ☑ adjusted turntable . Done Replace worn tyres with new haulster. Second drive axle. Done replace blow fuse for reverse light . Done need to replace real and front engine mountain need to replace a blue doser	SCANIA AUSTRALIA 10 - 52157		$2,395.89
14/02/2026	1,243,371 kms	**WORN TYRE** T-15654 Replaced with good runout tyre.			$154.00
11/02/2026	1,242,864 kms	**B - 20K/180Days** S-27978 B SERVICE			$646.17
27/01/2026	1,241,261 kms	**BROKEN LHF MUDGUARD** R-55908			$187.73
07/01/2026	1,235,800 kms	**AIR LEAK** R-54881	SCANIA AUSTRALIA 10 - 52157		$3,094.63
17/12/2025	1,234,636 kms	**ENGINE WARNING LIGHT** R-53461			$154.00
15/12/2025	1,234,636 kms	**BRAKES** R-53616 Replace hub seal second axle both sides. Done Replace brake pads second axle both side. Done Replace brake disc second axle both side. Done Replace brakes first axle both sides. Done Replace brake caliper LS . Done MQT026 KM(1234636)	SCANIA AUSTRALIA 10 - 52157		$3,047.44
09/12/2025	1,234,550 kms	**A - 10K/90Days** S-26643 A SERVICe Sump gasket leaking P/S middle hub seal leaking Rear main seal leaking Need new washers jets Need brakes 1st and 2nd axles Heater stay on Need grab handle to go inside truck			$1,076.46
07/11/2025	1,322,539 kms	**FLAT BATTERIES** R-51924 Replace flat battery			$558.12
06/10/2025	1,228,082 kms	**TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS** I-2465 Annual inspection done			$0.00
01/10/2025	1,228,082 kms	**CHECK ENGINE LIGHT** R-49919			$154.00
24/09/2025	1,228,082 kms	**C - 100K/365Days** S-25062 C SERVICE			$1,846.77
17/09/2025	1,226,876 kms	**SUZI COILS** R-49178			$37.40
14/07/2025	1,214,367 kms	**B - 20K/180Days** S-23289 Replaced candy strips on rear Replaced front passenger cab air bag Installed new wheel nut indicators on steer wheels both sides			$1,244.26
08/07/2025	1,214,094 kms	**FAULT REPORT, HIGH EMISSIONS** R-46287			-$729.47
23/05/2025		**FLAT BATTERIES** R-44245			$1,734.72
15/05/2025	1,206,864 kms	**CLUTCH** R-43599			$4,079.45
08/05/2025	1,206,411 kms	**FAULT REPORT, HEADLAMP** R-43457			$1,386.33
06/05/2025	1,205,941 kms	**ELECTRICAL PLUG, FAULT REPORT** R-43295			$231.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
29/04/2025	120,406 kms	**FAULT REPORT, HEADLAMP** R-42773 Replace rhs headlight bulb			$154.00
26/04/2025	1,204,560 kms	**GEARBOX** R-42887			$385.00
15/04/2025	1,202,776 kms	**EBS CABLE DAMAGED, FAULT REPORT** R-42418 Travel to seven hills fit new ebs cable			$231.00
08/04/2025	1,201,684 kms	**PUMP, WINDSCREEN WIPERS** R-41752 Replaced front wind screen wipers Replaced cab tilt pump, filled up oil Tested, functioning as per normal repair lights not working and check all - Replaced blown indicator globe - Replaced faulty cruise control switch			$2,938.38
31/03/2025	1,199,875 kms	**A - 10K/90Days** S-21407 No handbrake alarm fitted Cab tilt pump leaking from seal Topped up and got it operating Seal needs to be repaired to hold pressure and oil Wipers streaking badly on windscreen (8mm) Candy strip drivers side is peeling on the edges possible defect			$231.00
26/03/2025	1,199,650 kms	**FAULT REPORT** R-41438	SCANIA AUSTRALIA - 16		$3,891.18
13/03/2025	1,197,208 kms	**BROKEN SEAT SUSPENSION, FAULT REPORT** R-40709 Inspected and found leaking and worn shock absorber within drivers seat Parts request sent through to get part fit new shock and test operation			$2,440.39
27/02/2025	1,194,875 kms	**ENGINE MALFUNCTION** R-39160 Replaced Knox sensor Replaced both engine speed sensors on bellhousing. Found seat suspension on weakest adjustment, adjusted to max and seat did not bottom out again. Air leak in cab is from steering column switch, need to order a new one.			$3,038.15
27/02/2025	1,194,875 kms	**B - 20K/180Days** S-20881 Front engine mounts starting to crack, still serviceable, need to monitor. Adjusted turntable.			$802.20
17/02/2025		**CAB AIRBAG** R-39760 Need LHS front cebine airbag.			$583.70
30/01/2025	1,188,762 kms	**FAULT REPORT** R-38813 Repair was done at seven Hills			$154.00
30/01/2025	1,188,762 kms	**FAULT REPORT** R-38898 Replaced blown p/s front indicator bulb with new one, all good. Tightened loose top mirror mounting bolts on both d/s and p/s mirrors. Tested all good.			$77.00
21/01/2025	118,091 kms	**BATTERY FLAT** R-38497 Checked and jumped start the machine.			$0.00
10/01/2025	1,188,091 kms	**DRAG LINK ARM, EMMISIONS FAULT** R-38052 Found Draglink to have excessive movement, - Jack up vehicle, remove POS 2 Wheel, removed Booster to gain access to Drag link, Replace Drag link, Refit Booster & Wheel Tensioned wheel nuts & Fitted wheel nut indicators. Drag Link Removed R/S mudguard and air filter housing to gain more access to remove the link.	TRUCKSMART PTY LTD - 10		$1,291.97
23/12/2024	1,183,313 kms	**AIRLEAK** R-37486 Adjusted drain plug washer. Leak tested good.			$77.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
10/12/2024		**BROKEN MIRROR** R-36790 Replace with new mirror	TRUCKSMART PTY LTD - 10		$0.00
28/11/2024	1,182,267 kms	**BLOWN HEADLIGHTS** R-36413 Remove and replace headlight with new one Tested okay			$77.00
07/11/2024	1,176,938 kms	**PARK BRAKE** R-35288 Removed leaking valve and sent for part. Waiting for part.	TRUCKSMART PTY LTD - 10		$462.00
06/11/2024		**BREAKDOWN** R-35237 find out air leaking from LHS 2nd axle park break valve, swap truck for driver and adjusted bring truck back to work shop.			$616.00
25/10/2024	1,175,146 kms	**B - 20K/180Days** S-18508 A service completed ☑			$609.07
24/10/2024	1,175,146 kms	**NEW** T-9985 Replace steer tyres with new Bridgestone. Done			$231.00
09/10/2024	1,165 kms	**FLAT** T-9772 First axle left outer punctured drive tyre replaced with a new Roadone 11R 22.5 as seen.			$454.00
03/10/2024	678,334 kms	**FAULT REPORT** R-34102 top up fluid level			$77.00
29/09/2024	1,165 kms	**FLAT** T-9771 Left-hand side leaking punctured drive outer rear axle tyre replaced with a new Roadone 11R 22.5 respectively as seen.			$154.00
16/09/2024	9,773,862 kms	**Fault** T-9646 Replace flat tires with new roadone . Ls rear inner . Done			$454.00
12/09/2024	1,161,099 kms	**FLAT** T-9596 Found both LH third axle tyres flat. Replaced all third axle tyres with new ROADONE 11R 22.5			$308.00
07/09/2024	9,773,862 kms	**FAULT REPORT, MUDGUARD STRAPS** R-32643 Install mad card strap			$50.56
19/08/2024	1,151,622 kms	**TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS** I-1743 Accomplished annual inspection			$0.00
19/08/2024	1,151,622 kms	**B - 20K/180Days** S-17184 1.. B service done			$749.23
19/08/2024	1,142,228 kms	**ENGINE DERATED, FLAT BATTERIES** R-31677 replace flat battery's change blown head light globe and clear fault code for nox sensor			$385.00
01/08/2024		**TURBO DRAIN LEAK** R-30877 cleaned engine bay and take for a test drive spotted oil leak halfway through test drive remove and replace oil return line and replace gaskets and o-rings Allan & Josh replace Turbo drain hose, tested with no leaks. Found turbo inlet hose Brittle, various broken lock tabs on exhaust telephone pipe.	SCANIA AUSTRALIA 10 - 52157		$1,414.52

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
02/07/2024	1,134,903 kms	**FAULT REPORT** R-29389 Replaced P/S headlight globe			$38.50
01/07/2024	1,134,253 kms	**AIR LEAK** R-29231 Checked over vehicle for air leaks and found none Switched off towing unit button All good			$154.00
21/06/2024	1,130,808 kms	**C - 100K/365Days** S-15193 C" services curried out per servic sheet requires Also changed out all defects difflock plus two air valve l			$2,232.93
15/06/2024	1,129,379 kms	**AIR LEAK** R-28465 Air leak was caused from exhaust brake button being activated Switch off exhaust brake (okay) Front diff lock leaking when activated (will need to be scheduled in at a later stage)			$231.00
06/06/2024	1,128,149 kms	**HIGH EMISSIONS** R-28185			$4,800.78
18/05/2024		**FAULT REPORT** R-26977 Handles for back and head adjusters missing (they are on order) Replace leavers for back adjustment and upper back adjustment Tested operation Okay No air leak in seat found			$471.69
07/03/2024	1,111,385 kms	**B - 20K/180Days** S-13220 B service completed. Replace first axle R/S air bag Replace rear axle R/S air bag			$903.23
28/02/2024	1,109,146 kms	**FAULT REPORT** R-24064 R&R driver side head light globe			$38.50
21/02/2024		**FAULT REPORT** R-23798 Replaced top P/S visor Parker light			$38.50
21/02/2024	1,107,058 kms	**A - 10K/90Days** S-13011 Carry out A service as per job card Adjust turntable Multiple chips in windscreen			$506.44
25/01/2024	1,100,661 kms	**B - 20K/180Days** S-12510 Completed B service			$749.24
25/01/2024		**FAULT REPORT, tablet** R-22741 Replaced Tablet Cradle and Hardwired tablet to permanent 12V. Tablet charged to 100% and tested Ok			$77.00
22/12/2023	1,089,531 kms	**A - 10K/90Days** S-11939 A service done			$231.00
20/12/2023	1,088,185 kms	**FAULT REPORT** R-21345 Replace LHS headlight bulb			$0.00
01/12/2023	1,083,890 kms	**FAULT REPORT** R-20288 Replaced windows washer bottle			$1,200.10
13/11/2023	1,077,593 kms	**B - 20K/180Days** S-11220 B SERVICE COMPLETE DONE Replace first axle drive tyre both side new haulstar done Repair LHS front bottom cover damage done Repair LHS front guards damage done Replace tail shaft front greasing points done			$1,065.70

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
13/11/2023	1,077,593 kms	**NEW** T-5807 Replace first axle drive tyre both side new haulstar done			$1,228.00
10/11/2023	1,063,619 kms	**FAULT REPORT** R-19951 fit new trailer Suzi lead , check lights , wiggle cable to ensure good connection. all lights operating			$154.00
26/09/2023	1,063,181 kms	**B - 20K/180Days** S-10392 B SERVICE COMPLETE DONE Replace RHS head lights glob done Replace rear RHS shackles pin greasing points done			$648.40
25/09/2023	1,061,737 kms	**RUNOUT** T-5290			$231.00
09/09/2023	1,056,491 kms	**Puncture** T-5128 Replaced first axle rhs inner drive with runout			$77.00
01/09/2023		**FAULT REPORT** R-16965			$154.00
31/08/2023	1,053,948 kms	**A - 10K/90Days** S-9928 Front shackle pins and bush's worn O/s/2/3 air bags cracking requires replacement			$308.00
31/08/2023	1,053,948 kms	**TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS** I-1046 Front shackle pins and bush's worn			$0.00
30/08/2023	1,053,530 kms	**FAULT REPORT** R-17183 Replaced blown LHS headlight bulb with new one.			$46.20
04/08/2023	1,047,682 kms	**CAB** R-14255 Replaced cab stabiliser bar and bump stops			$4,419.86
19/07/2023	1,046,277 kms	**B - 20K/180Days** S-9200 B SERVICE COMPLETE DONE Repair wiring for LHS step indicators in glowed blinkers in step done Replace front LHS indicators glob done Retention all bolt for turntable loss done Repair LHS front off rear madguard cracked done Note front LHS steps blinker need replace Missing half blinkers Turntable need to be replaced worn out			$2,635.44
08/05/2023	1,022,019 kms	**C - 100K/365Days** S-7906 C SERVICE COMPLETE DONE Replace rear wing LHS piston plus repair mounting brackets done Repair cooling leack from bottom radiator hose cleam done Retention driver side cleam handle bolt done LHS passengers guard blinkers broken need replacement			$710.93
19/04/2023	1,007,524 kms	**New** T-4010 Replaced new steer tyres			$880.00
29/03/2023		**PARK BRAKE ALARM** R-12728 INSTALLED REDARC PARK BRAKE ALARM SYSTEM INTO VEHICLE. INSTALLATION INCLUDED REDARC UNIT, WIRING HARNESS, SEPARATE HORN (INSTALLED IN DASH), DOOR SWITCH AND ACTIVATION SWITCH ATTACHED TO PARK BRAKE AIR LINES INSIDE DASH. TESTED OK.			$135.30
02/03/2023		**HEADLIGHT** R-11827 re secure front lhs light in bull bar, drill and fix to back of bracket			$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
15/02/2023		**INDICATOR** R-11329 replace suzi lead			$0.00
25/01/2023	986,225 kms	**ENGINE** R-10745 replace nox sensor and clear fault codes			$1,265.05
20/01/2023	855,173 kms	**ABS, MARKER PLATES** R-10596 no abs faults logged in system ,maker plate on the rhs has small part of reflector missing but still road worthy			$0.00
19/01/2023	985,173 kms	**A - 10K/90Days** S-6236 carry out service as per check sheet. need to wash and diagnose oil leak at rear of engine correctly so repair can be carried out			$0.00
04/01/2023	978,363 kms	**FAULT REPORT** R-10184 Check operation of trailer walk button and it is working as it should			$0.00
29/12/2022	975,104 kms	**FAULT REPORT** R-9993 Replaced DS inner bull bar light as required Test operation Okay			$0.00
22/12/2022		**NEW** T-3040 replace first drive axle tyres			$2,560.01
09/12/2022	972,000 kms	**B - 20K/180Days** S-5564 Carry out B service as per job card Coolant leaking from radiator cap (replaced cap) Air leak from under truck (repaired) Air leak from air tank (replaced drain cock) DS inner bullbar light damaged (needs new light)			$419.69
09/12/2022	917,615 kms	**AIR CONDITIONING** R-8251 Remove and replace condenser , dryer and o rings . Regas and tested operation okay. Parts on order Replace DS step assembly Replace missing step indicator Test operation okay Warning light on dash (plug laptop in and clear codes)			$3,086.43
05/12/2022	971,561 kms	**BATTERIES** R-9268 Replaced new batteries.Done. Positive cable touching bracket. Secured DONE. Need to replace cable for between both batteries.			$154.00
30/11/2022	971,557 kms	**BATTERIES** R-9057			$0.00
07/11/2022	964,270 kms	**HEADLIGHTS** R-8485 Replace head lights glob LHS DONE			$0.00
05/11/2022	963,223 kms	**BATTERY** R-8463 Replaced 1 new battery (D/S)			$0.00
27/10/2022	960,654 kms	**TURNTABLE JAWS** R-8183 R &R turn table jaws Straighten handle Check operation all good			$391.96
26/10/2022	960,654 kms	**A - 10K/90Days** S-4914 A service complete done Replace driver side wipers blades done Turntable not locking handle and bottom plate bent Right step blinker missing Bottom corner cover RHS and LHS broken			$0.00
21/10/2022		**BREAK DOWN** R-16475	SCANIA AUSTRALIA 10 - 52157		$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
19/10/2022	958,615 kms	**CLUTCH** R-10461	SCANIA AUSTRALIA 10 - 52157		$9,203.77
27/09/2022	948,327 kms	**REPAIR** R-7462 Replace jack shaft unit both side new one done Note out side cups not same fit old cups one			$254.32
26/09/2022	947,836 kms	**PUNCTURED TYRE** T-2297 Repair puncture 2nd axle RHS inner done			$0.00
26/09/2022	947,836 kms	**STEERING** R-7445 Rebalance both side steering wheel done			$0.00
26/09/2022	947,836 kms	**B - 20K/180Days** S-4412 B SERVICE COMPLETE DONE Repair puncture 2nd axle RHS inner tyre done Jack shaft unit both side excess movement badly need to replace tomorrow King pin both side movement after greasing Cabin bottom cover both side missing Driver side middle step missing			$266.57
16/09/2022	945,101 kms	**BROKEN TAIL LIGHT** R-7208 Replace rear taillight LHS new one done ✔			$345.95
08/09/2022	942,010 kms	**VARIOUS** R-7006 Replace front LHS shock absorber done Replace air tank Drain plugs done Replace damage cooling pipe bushes done Replace 2nd axle LHS shock absorber done Check all brakes booster for possible internal leaks all good done			$2,550.69
29/08/2022	939,137 kms	**TIE ROD** R-6710 Checked operation okay It's doesn't have up and down movement			$0.00
28/08/2022	939,137 kms	**TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS** I-440 Front right bottom shock bushes worn Left side air tank drain cock leaking Gearbox coolant hose bushes broken on left side ABS module leaking air Upon releasing park brake (possible 1 of brake boosters bypassing) Drivers step indicator light out(done) Middle axle left shocks leaking			$0.00
25/08/2022	937,929 kms	**BREAKDOWN** R-6650 Travel to Lidcombe Had to Wait for truck outside Chaps Fitted new cuzi coils Tested okay Return to workshop			$0.00
19/08/2022	936,691 kms	**A - 10K/90Days** S-3848 A service complete done Replace RHS blinkers from side steps done Repair bulbar park lights 4x done			$0.00
19/08/2022	936,691 kms	**WHEEL NUT INDICATORS** R-6470 Fit new wheels indicators for steer tyre both side done			$0.00
12/08/2022	927,188 kms	**MUDGUARD** R-6258 Replace damaged mudguards			$0.00
16/07/2022	927,185 kms	**FAULT REPORT** R-5518 re-secure 12v trailer light plug, removed from bracket as this plug does not get used			$0.00
14/07/2022	926,878 kms	**B - 20K/180Days** S-3404 B SERVICE COMPLETE DONE Repair front RHS blinkers not working done Replace missing nut off cabin rubber stopped front LHS DONE Tie rod bar excess movement			$258.91

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
20/06/2022	925,443 kms	**EXHAUST** R-5215 Exhaust leaks from manifold casket LHS damage replace LHS manifold casket replace 2x bolts start check all good done			$0.00
06/06/2022	917,919 kms	**VARIOUS** R-4814 headlight replaced Replace fan belt both new one done Replace 2nd axle air back LHS new one done			$1,413.74
06/06/2022	917,423 kms	**A - 10K/90Days** S-2902 A service complete done Fan belt worn need to replace 2nd axle LHS air back small cut			$0.00
10/05/2022	910,911 kms	**FAULT REPORT** R-4162 Check tyre both side steer all new in balance done Check all steering joint good			$0.00
27/04/2022	908,099 kms	**C - 100K/365Days** S-2522 C SERVICE COMPLETE DONE Drive shaft excess movement before greasing Cabin stopped rubber missing LHS			$722.15
11/04/2022	904,949 kms	**HEADLIGHTS** R-3678 Replace head lights glob RHS done			$0.00
17/03/2022	898,349 kms	**VARIOUS** R-3193 Repair air leack from front air back RHS missing oring done Adjust toll box warning light on dash done			$537.90
25/02/2022	894,269 kms	**FAULT REPORT** R-2697 Replace front LHS cabin air back new one done			$380.77
18/02/2022	892,069 kms	**VARIOUS** R-1764 Done by night shift Remove and replace light Checked okay Done by night shift Checked bolt holds nothing so left it as is Done by night shift Remove and replace rear axle brakes Stitched with cable ties Checked okay Fitted runout tyre on rear axle left side			$507.22
11/02/2022	891,427 kms	**A - 10K/90Days** S-1717 1.Completed A service. 2.Rear axle brake getting low 27% LH and 37% RH. 3.LH rear exhaust pipe leaking. 4.FLH mudguard cracked. 5.Missing front RH /LH corner cover. 6.hand brake alarm not working.			$0.00
07/02/2022	889,968 kms	**FAULT REPORT** R-2295 Replaced clutch fluid reservoir assembly.new one fill up brakes fluid done			$225.28
11/01/2022	863,064 kms	**AIR FILTER** R-1060			$0.00
06/01/2022	882,745 kms	**B - 20K/180Days** S-1373 B SERVICE COMPLETE DONE			$241.71
04/01/2022	848,556 kms	**DRIVELINE, OIL LEAK** R-135 Replaced tailshaft uni. Engineering cut the uni COMPRESSOR SEAL REPALCED ADJUST FRONT BONNET CATCHES AND LOCK STRAIGHTEN BRACKET NOW CAN CLOSE BETTER THAN BEFORE			$950.33
22/12/2021	876,099 kms	**New** T-659 change steer tyres and balance as required			$880.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
19/12/2021	874,642 kms	**A - 10K/90Days** S-1234 Diiff lock leaking Faulty LHR taillight, no number plate light No first aid kit D/S washer block Bolts broken and bracket missing on exhaust manifold Compressor oring leaking Need steer tyres and alignment. D/ S on indicator			$0.00
10/12/2021	871,407 kms 1 hrs	**SUZI COILS** R-1440 Replace damage souzi coil both side new done			$0.00
15/11/2021	865,542 kms	**B - 20K/180Days** S-819 Compressor mounting o ring leaking Coolant pipe that runs under Compressor leaking Coolants needs new o ring Remove and blown step bulbs Fitted missing grease nipples on driveshaft			
08/11/2021	863,064 kms	**TURNTABLE** R-811 TIGHTEN TURNTABLE BOLTS,REPLACE LHS HEADLIGHT GLOBE, ADJUST BONNET LATCH,TIGHTEN LOOSE SHACKLE PIN BOLTS			$0.00
01/11/2021	860,734 kms	**A - 10K/90Days** S-695 A service complete done Replace drive shaft greas nippel done Compressor oil leak from oring covers for under air dryer and air cleaner missing Exhaust manifold gasket ring leaking			
01/11/2021	860,712 kms	**SPEEDO** R-714 REPAIRS CARRIED OUT BY SCANIA SPEED LIMITER SET TO 98KLM	SCANIA AUSTRALIA 10 - 52157		$175.00
21/10/2021	857,625 kms	**Puncture** T-306 Truck broken down in cordina Flat tyre replace drive tyre LHS other first axle done			$0.00
01/10/2021	852,165 kms	**BATTERY** R-249 REPLACE NEW BATTERY (DUE TO OLD BATTERY			
29/09/2021	846,250 kms	**New** T-169 Replace all rear drive tyres.			$115.63
20/09/2021	846,233 kms	**B - 20K/180Days** S-198 Travel to cordina pick up truck and come back, carry out B service. Find there is a play in shaft both universal crosses, oil leaking from air compressor seal and bonnet doesn't closed properly. Moreover rear axle first RH inner tyre was puncture and LHR inner low tread. Put all wheel nuts indicators as well.Replace all rear tyres with new. Then drop back truck at girrawreen yard.			$216.15
152 Records				**Total:**	**$109,601.19**