E10-15

DIESELR Corp
3975 1 Avenue South
Lethbridge, AB T1J 4P8, CA
sales@dieselrcorp.com
403-795-4399

Invoice: DSLR-9122
Date: 24/2/2026

Bill To
[redacted]

Remit Payment To
DIESELR Corp
3975 1 Avenue South
Lethbridge, AB T1J 4P8, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
DSLR-9555	COD	24/2/2026	Jay Reeder		Kendall, Brett	7

Item	Description	Quantity	Rate	Amount
Complaint: Diagnose ABS light				
Cause: Customer request				
Labor	**Correction:** Brakes / ABS System / Monitored wheel speed sensor while rotating wheels and noted right front speed signal dropping out and giving erratic readings. Noted also the right front wheel bearing is noisy. Replace right front bearing and hub assembly.	1.40000	$140.00	$196.00
Parts	SKF Wheel Bearing and Hub Assembly - BR930858	1.00000	$395.226	$395.23
			Subtotal	$591.23

Unit: 7 **VIN:** 1C6RR7PM5GS280504
2016 RAM 1500
Chassis: 222,541 Miles

Labor	$196.00
Parts	$395.23
Shop Supplies	$4.90
Pre-Charge Subtotal	$596.13
GST (5% of $596.13)	$29.81
Total	$625.94
Payments & Credits	$0.00
Balance Due	$625.94

GST#: 789063476RT0001

Still owing

2% Interest per Month will be added on Accounts over 30 days.

Payment Options:

- **NEW** Pay Online at **portal.dieselrcorp.com**

E10-15

[redacted]

[redacted]

DIESELR Corp
3975 1 Avenue South
Lethbridge, AB T1J 4P8, CA
sales@dieselrcorp.com
403-795-4399

Invoice: DSLR-8978
Date: 6/2/2026

Bill To
[redacted]

Remit Payment To
DIESELR Corp
3975 1 Avenue South
Lethbridge, AB T1J 4P8, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
DSLR-9453	COD	6/2/2026	Jay Reeder		Kendall, Brett	7

Item	Description	Quantity	Rate	Amount
Complaint: Perform Mechanical Fitness Assessment				
Cause: Customer request				
Labor	**Correction:** Engine / Assembly / Perform Mechanical Fitness Assessment. Several non-compliant points noted: Emergency brake, and front side windows tinted. Noted also coolant level low, right front fog light inoperable, left hood strut failed, and engine code for coolant bypass valve stuck.	1.00000	$140.00	$140.00
			Subtotal	$140.00
Complaint: Diagnose exhaust/whistle noise				
Cause: Customer request				
Labor	**Correction:** Engine / Turbo / Test drove and was able to verify a whistle/squeal that did not sound normal. Inspected exhaust system for leaks but could not pinpoint concern. Removed engine cover to inspect for boost leaks and noted EGR feed pipe at intake manifold is loose. The bolts are missing and the gasket is blown out.	0.25000	$140.00	$35.00
			Subtotal	$35.00
Complaint: Fix EGR leak				
Cause: Customer request				
(Inspection)				
Labor	**Correction:** Exhaust / EGR / Remove EGR feed tube from intake manifold and clean off the accumulation of oil and soot. Re-install EGR feed tube, ensuring sealing ring is securely in place. Install bolts and ensure they are tight. Test drove the truck and the squealing noise is no longer evident.	1.00000	$140.00	$140.00
			Subtotal	$140.00
Complaint: Install Fender flares				
Cause: Customer request				

(Inspection)

Labor	**Correction:** Chassis / Fenders / installed husky fender flares. Had to remove EcoDiesel badges on both sides and move them as they were in the way for flare installation.	2.00000	$140.00	$280.00
Parts	POCKET STYLE FLARES (4) 09-18 RAM 1500/ 19-24 CLASSIC - 2805915	1.00000	$567.827	$567.83
			Subtotal	$847.83

Unit: 7 VIN: 1C6RR7PM5GS280504
2016 RAM 1500
Chassis: 222,435 Miles

Labor	$595.00
Parts	$567.83
Shop Supplies	$14.88
Pre-Charge Subtotal	$1,177.71
GST (5% of $1,177.71)	$58.89
Total	$1,236.60
Payments & Credits	$0.00
Balance Due	$1,236.60

GST#: 789063476RT0001

2% Interest per Month will be added on Accounts over 30 days.

Payment Options:

- **NEW** Pay Online at **portal.dieselrcorp.com**

- E-Transfer - Send to sales@dieselrcorp.com (Please put your Invoice# in E-Transfer comments)

- Credit Card - Call us to pay your Invoice over the phone

Visit our Websites! www.dieselrcorp.com and www.dieselrcorp.ca

Review us on Google!

** WARNING! PLEASE ENSURE THAT YOUR WHEEL NUTS ARE CHECKED FOR TIGHTNESS WITHIN FIRST 100 KM **

By proceeding with the outlined work, you agree to the following terms:

Any warranties on the parts and accessories sold are provided by the manufacturer. You understand and agree that DIESELR Corp. makes no warranties unless expressly stated in writing. You acknowledge that DIESELR Corp. is not responsible for loss or damage to the vehicle or its contents due to fire, theft, or any other 'act of God.' You understand that DIESELR Corp. is not liable for any outcomes resulting from performance modifications made to your vehicle, and you are aware that aftermarket modifications may impact or void the vehicle's warranty.

DIESELR Corp
3975 1 Avenue South
Lethbridge, AB T1J 4P8, CA
sales@dieselrcorp.com
403-795-4399

Estimate DSLR-9432
Date: 2/2/2026
Description:

[redacted]

Remit Payment To
DIESELR Corp
3975 1 Avenue South
Lethbridge, AB T1J 4P8, CA

Service Order	Purchase Order	Service Writer	Authorizer
DSLR-9432		Shaw, Chris	

Item	Description	Quantity	Rate	Amount
Labor	Install Pocket style Fender flares	2.00000	$140.00	$280.00
Parts	HUSKY POCKET STYLE FLARES (4) ; 09-18 DODGE RAM 1500/ 19-24 1500 CLASSIC - 1	1	$567.827	$567.83
			Subtotal	$847.83
	Shop Supplies			$7.00

Unit: 7 **VIN:** 1C6RR7PM5GS280504
2016RAM1500
Chassis: 222,283 Miles

Labor	$280.00
Parts	$567.83
Subtotal	$854.83
GST (5% of $854.83)	$42.74
Total	$897.57

***: Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a separate invoice.**
By proceeding with the outlined work, you agree to the following terms:

Any warranties on the parts and accessories sold are provided by the manufacturer. You understand and agree that DIESELR Corp. makes no warranties unless expressly stated in writing. You acknowledge that DIESELR Corp. is not responsible for loss or damage to the vehicle or its contents due to fire, theft, or any other 'act of God.' You understand that DIESELR Corp. is not liable for any outcomes resulting from performance modifications made to your vehicle, and you are aware that aftermarket modifications may impact or void the vehicle's warranty.

You grant DIESELR Corp. and its employees permission to operate the vehicle on streets, highways, or other locations as necessary for testing or inspection purposes.

[redacted]

DIESELR Corp
3975 1 Avenue South
Lethbridge, AB T1J 4P8, CA
sales@dieselrcorp.com
403-795-4399

Invoice: DSLR-8866
Date: 27/1/2026

Bill To
[redacted]

Remit Payment To
DIESELR Corp
3975 1 Avenue South
Lethbridge, AB T1J 4P8, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
DSLR-9268	COD	27/1/2026	Jay Reeder		Kendall, Brett	7

Item	Description	Quantity	Rate	Amount
Complaint: Perform inspection				
Cause: Customer request				
Labor	**Correction:** Engine / Assembly / Performed inspection and found that both lower ball joints and both cv axles need to be replaced The third brake light, one cargo light and the driver side fog light are not working The truck has codes for the right front wheel speed sensor, front axle disconnect actuator and for the air suspension	1.50000	$140.00	$210.00
Parts	ABS Sensor - ALS2587	1.00000	$109.98	$109.98
Parts	4WD Actuator - 600-399	1.00000	$345.605	$345.61
Parts	Halogen Bulb - 9006 - 9006	2.00000	$8.92	$17.84
			Subtotal	$683.43
Complaint: diagnose the trucks codes				
Cause: Customer request				
(Inspection)				
Labor	Electrical System / Wiring / diagnose the trucks codes	3.00000	$140.00	$420.00
			Subtotal	$420.00
Complaint: Remove and replace both cv axles				
Cause: Customer request				
(Inspection)				
Labor	**Correction:** Front Axle & Steering / Wheel Seals / Removed and replaced both cv axles	3.00000	$140.00	$420.00
Parts	CV Axle - 139256C	2.00000	$259.675	$519.35
Parts	Intermediate Shaft - 139511	1.00000	$89.25	$89.25
			Subtotal	$1,028.60

Complaint: Remove and replace both lower ball joints

Cause: Customer request

(Inspection)

Labor	**Correction:** Front Axle & Steering / Ball Joints / Removed and replaced both lower ball joints	1.00000	$140.00	$140.00
Parts	Ball Joint - K500286	2.00000	$111.99	$223.98
			Subtotal	$363.98

Complaint: Install new fog light bulbs

Cause: Customer request

(Inspection)

Labor	Electrical System / Headlights/Bulbs / Install new fog light bulbs	0.30000	$140.00	$42.00
			Subtotal	$42.00

Unit: 7 VIN: 1C6RR7PM5GS280504
2016 RAM 1500
Chassis: 222,283 Miles

Labor	$1,232.00
Parts	$1,306.01
Shop Supplies	$30.80
Pre-Charge Subtotal	$2,568.81
GST (5% of $2,568.81)	$128.44
Total	$2,697.25
Payments & Credits	$2,697.25
Balance Due	$0.00

Payment Information

Date Created	Date Applied	Payment #	Method	Reference #	Amount
27/1/2026	27/1/2026	103498931	E-Transfer	C1AJRYmYh8ZN	$2,697.25

GST#: 789063476RT0001

2% Interest per Month will be added on Accounts over 30 days.

Payment Options:

- ****NEW**** Pay Online at **portal.dieselrcorp.com**

- E-Transfer - Send to sales@dieselrcorp.com (Please put your Invoice# in E-Transfer comments)

- Credit Card - Call us to pay your Invoice over the phone

Visit our Websites! www.dieselrcorp.com and www.dieselrcorp.ca

Review us on Google!

CSN Kustom
PO BOX 1281 1623 20th Ave
Coaldale, Alberta T1M 1N1
Phone # (403) 345-3079 Fax:

Invoice # 31766

Date: 01/28/2026
Time: 14:21:21
Tax # 121518666RT

[redacted] [redacted] Home: [redacted] PO:	Make: 2016 Ram Model: 1500 Pickup Style: 4 Door Crew Cab 140" License: Color: VIN: 1C6RR7PM5GS280504 Mileage In: Unit No.:	Customer Pay Alberta Coaldale Canada Adjuster: , Ins. Phone: Claim #: Date of Loss:

Line #	Description	Type	Price	Lbr Hrs	Ref Hrs
1	WINDSHIELD	New Parts	$153.00	1.3	
2	SHOP SUPPLIES	Shop Materials	$25.00		
3	tweak head light			0.3	

Totals

New Parts		$153.00
	Parts Total	**$153.00**
Body Labour	0.3 @ 110	$33.00
Glass Labor	1.3 @ 100	$130.00
	Labor Total	**$163.00**
Shop Materials		$25.00
		$0.00
	Other Total	**$25.00**
	Sub Total	**$341.00**
GST	Rate = 5 %	**$17.05**
Customer Total		**$323.40**
Payment Amount		**$0.00**
Balance Due		**$358.05**

Thank you for choosing CSN Kustom for your repairs.

[redacted]

RITCHIE BROS.
Auctioneers®

Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is "sold as is" no warranties made or implied

---

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture