Vehicle History Summary

[redacted]

Fleet #	PM14
Registration	[redacted]
Make	Kenworth
Model	2023 Prime Mover T610
VIN / Chassis #	6F5000000NA483292
Build Date	2023

Date	Reading / Units	Type / Repairer Notes	Repairer
31/08/2026		**Electrical** R-3386 se attached invoice	KENNYS AUTO ELECTRICAL TSV
30/08/2026	858,801 kms	**Chassis** R-3369 carried out work as requested	[redacted]
21/08/2026	858,806 kms	**Battery** R-3352 JUMP STARTED TRUCK	[redacted]
19/08/2026		**Truck Wash** R-3338 WASHED TRUCK AS REQUESTED	[redacted]
30/07/2026		**Fault** R-3163 NO ACTIUVE FAULTS AT TIME OF INSPECTION	
23/06/2026		**Electrical** R-3176 see attached invoice for details of repair	Warrego Transport Repairs
01/06/2026		**NEW** T-1360 sarina tyres to repair	TYREPOWER SARINA
22/05/2026	802,706 kms	**C - 100k/Annual** S-1426 carried out service as per jobcard replaced oils and filters greased and adjusted brakes front diff output seal leaking moved turn tabke forwards to bring within length requirements lateral torque rod bushes need replacing airbags have signs of cracking and beginning to leak (monitor) replaced light plug king pins need replacing slack adjusters barely click adjusted fine this service	24 Hour Hose, [redacted]
24/04/2026		**PUNCTURE** T-1341 REPAIR AS PER INVOICE	OTR TYRES
07/04/2026		**PUNCTURE** T-1333 SEE ATTACHED INVOICE	Carroll Tyres Pty Ltd
31/03/2026		**Engine** R-2941 hifs plugged computer in not active faults found.	HEAVY INDUSTRIAL FLEET SERVICES
24/03/2026		**PUNCTURE** T-1337 REPAIRED OTR TYRES	OTR HENDRA
18/03/2026		**Cab** R-2924 FIXED BY DRIVER	
02/03/2026	751,331 kms	**Brakes** R-2848 As attached	Brown & Hurley
25/02/2026	748,849 kms	**Main/inspect** T-1209 Replaced 2 Steer Tyres	OTR YATALA

Date	Reading / Units	Type / Repairer Notes	Repairer
24/02/2026	748,849 kms	**Steering** R-2834	OTR YATALA
		SEE TYRE JOB T1209 AND ATTACHED INVOICE	
23/02/2026		**Cab** R-2760	Brown & Hurley
		29/01/26-EMAIL SENT TO TERESA AT ARMESTO WITH PICTURES AND B&H QUOTE. SEE ATTACHED QUOTE - BROWN & HURLEY FOR REPAIRS TO VEHICLE DRIVER SIDE MIRROR. GAVE B&H PO NUMBER, JONO COLLECTING HOUSING MIRROR FROM B&H CABOOLTURE. **UNDER NO CIRCUMSTANCES ARE WE PAYING FOR ANY ITEMS**ARMESTO TRANSPORT TO PAY*****	
23/02/2026		**Electrical** R-2630	[redacted]
10/02/2026	736,924 kms 10,320 hrs	**Chassis** R-2777	Brown & Hurley, Cummins
		SEE ATTACHED BROWN & HURLEY PARTS INVOICE 3782642 FOR CUMMINS. AWAITING CUMMINS INVOICE FOR REPAIR.	
13/01/2026	723,050 kms	**A - 10k** S-1212	[redacted]
		SEE ATTACHED SERVICE JOBCARD - BRAKES: STEER - 17MM. AXLE 1 - 14MM. AXLE 2 - 14MM. REPLACED TURNTABLE & LOCKING JAW KIT. MECHANIC BREAKDOWN HOURS: NATHAN 2HRS MIKAYLA 2HRS	
13/01/2026	723,050 kms	**Rotate** T-1131	[redacted]
		SEE ATTACHED TYRE JOBCARD - SIDE 2 SIDE STEER ROTATION. 10 PRESSURE CHECKS.	
31/12/2025		**Cab** R-2481	Andrew's Mobile Windscreens
		ATTACHED SERVICE JOBCARD #1164 STATES: WINDSCREEN REPLACED. ANDREWS DID NOT ATTEND TO VEHICLE.	
31/12/2025		**Chassis** R-2189	[redacted]
		-23/9-INSPECTED BY PRIMARY MECHANICAL- REQUIRES NEW RUBBER SEAL FOR FUEL CAP. SERVICE JOBCARD 1164 STATES: FAULT FIXED.	
31/12/2025		**Cab** R-2196	
		SERVICE JOBCARD #1164 STATES: DEFER TO NEXT SERVICE.	
31/12/2025		**Cab** R-2197	[redacted]
		SERVICE JOBCARD #1164 STATES: FAULT FIXED.	
18/12/2025		**Chassis, Electrical** R-2589	[redacted]
		SERVICE JOBCARD #1164 STATES: FAULT FIXED. 18/12-ADVISED REPAIRED.	
17/12/2025	705,018 kms	**Battery** R-2600	[redacted]
		SEE ATTACHED INVOICE FROM A1 BATTERYPRO #710868. SEE ATTACHED REPAIR JOBCARD #2600.-INSPECT BATTERIES. ADJUST CLUTCH 3. RE-WIRE AD-BLUE LIGHT & TEST.	
16/12/2025	704,198 kms	**C - 100k/Annual** S-1164	[redacted]
		SEE ATTACHED SERVICE JOBCARD - REPLACED ENGINE AIR FILTERS. REPLACED CABIN FILTER & INSIDE FILTER HAS BEEN CLEANED. TOPPED UP COOLANT. REPLACED WIPER BLADES. SERVICE ICEPACK.	
16/12/2025		**CLUTCH** R-2511	HEAVY INDUSTRIAL FLEET SERVICES
		SERVICE JOBCARD #1164 STATES FAULT FIXED. I FOLLOWED UP WITH HIFS SEEKING INVOICE FOR REPAIR. REPAIR JOBCARD NOW CLOSED...REFER TO REPAIR R2523. (WAITING ON INVOICE FROM HIFS, PO ISSED 1966 FOR THEIR REPAIR.) SEE ATTACHED INVOICE FROM HIFS FOR REPAIR TO CLUTCH #52235, ORIGINAL REPAIR JOBCARD HAS DETAILS: R2523.	
11/12/2025		**Lights** R-2463	
04/12/2025		**Brakes** R-2542	CUBS TRUCKS & TRAILER REPAIRS
		SEE ATTACHED INVOICE 1374 - PAID BY CREDIT CARD 8/12/25.	
28/11/2025	689,435 kms	**CLUTCH** R-2523	HEAVY INDUSTRIAL FLEET SERVICES
		SEE ATTACHED INVOICE 52235	
24/11/2025	676,733 kms	**Fault** T-1008	Carroll Tyres Pty Ltd

Date	Reading / Units	Type / Repairer Notes	Repairer
		SEE ATTACHED JOB CARD 34364 SEE ATTACHED INVOICE 302898	
17/11/2025		**Chassis** R-2401	[redacted] NOVUS WINDSCREENS BNE STH
		NOVUS SUPPLIED & FIT FRONT WINDSCREEN. SEE ATTACHED INVOICE 44645, paid by credit card. SEE ATTACHED EMAIL DEFECT CLEARANCE BY NHVR. 17/11/25-DEFECT/REPAIR CLOSED.	
04/11/2025	668,918 kms	**A - 10k** S-1016	[redacted] Primary Mechanical Repairs
		SEE ATTACHED SERVICE JOBCARD - LAST PAGE MISSING WITH NO RECORD OF KLMS NOR HOURS HOWEVER KLMS RECORDED ON TOP OF SERVICE SHEET, THIS IS WHAT I RECORDED TO CLOSE OFF. SEE ATTACHED PROFORMA FOR PRIMARY MECHANICAL #1612. RECORDED KLMS CHANGED TO WHAT IS REFLECTED ON PMR INVOICE.#668918. SEE ATTACHED PMR INVOICE #1612.	
27/10/2025	650,348 kms	**Chassis** R-2368	BROWN & HURLEY YATALA
		SEE ATTACHED INVOICE 3675431 WITH PO 1765.	
22/10/2025	649,900 kms	**Chassis** R-2357	BROWN & HURLEY YATALA
		SEE ATTACHED INVOICE 3682887 WITH NO PO. SEE ATTACHED INVOICE 3682887 WITH PO.	
22/10/2025	638,787 kms	**Chassis** R-2356	BROWN & HURLEY BUNDABERG
		*SEE ATTACHED SERVICE INVOICE PROFORMA (repair order #944431 ON 22/9/25) FOR SAME TRUCK BY BROWN & HURLEY FOR AFTER HOURS CALLOUT TO VEHICLE LOCATED AT SOUTH TINANA BP AS AIR FAILING TO BUILD. *WAITING PO ON INVOICE. SEE ATTACHED INVOICE 3688653.	
21/10/2025	658,309 kms	**Chassis** R-2433	BROWN & HURLEY YATALA
		BROWN & HURLEY YATALA CALLED OUT TO BREAKDOWN. SEE ATTACHED TAX INVOICE 3686905 WITH NO PO. new valve governor needed. SEE ATTACHED RECTIFIED INVOICE 3689605.	
07/10/2025	647,862 kms	**Chassis** R-2315	Brown & Hurley
		*SEE ATTACHED INVOICE 3673626, ATTENDED BREAKDOWN, CONFIRMED STARTER NOT ENGAGING. NEW STARTER INSTALLED.	
23/09/2025	640,596 kms	**B - 40k** S-1047	
		SEE ATTACHED SERVICE JOBCARD BY PRIMARY MECHANICAL (HARRY O.) 4.5HRS.	
23/09/2025	640,596 kms	**Glass** R-2159	
		23/9-PRIMARY MECHNICAL ADV FUSES TESTED. ALL OKAY. WATER LEVEL TOPPED UP FURTHER DIAG REQUIRED.(SEE ATTACHED PAGE 5 OF S1047.	
26/08/2025	620,184 kms	**Driveline** R-2101	[redacted]
		SEE ATTACHED REPAIR JOBCARD. (FRONT DIFF)	
21/08/2025	613,925 kms	**Driveline** R-1975	Penske
		As per attached Penske invoice/Notes	
23/07/2025		**AdBlue** R-1911	
		AdBlue flushed, all ok	
03/07/2025	597,581 kms	**Rotate** T-899	[redacted]
		8x rotation Pressure check	
02/07/2025	597,581 kms	**B - 40k** S-923	[redacted]
		Replace fan bel and accessories belt. Replace P-clamps on heater pipe. Replace wiper blades. Grease bonnet mounts to stop squeak. Topped up water in batteries. Replaced passenger side Indicator Light (tail light). Inspect fuel leak. FOund driver front fuel tank has rotated and if over full leaks out breather hose.	
01/07/2025		**Brakes** R-1630	
01/07/2025	596,797 kms	**New** T-891	[redacted]
		2x New Aeolus Steer Tyres Pressure Check	
30/06/2025	596,797 kms	**Chassis** R-1862	
		Grease all points on vehicle Adjust clutch solo and bring back to spec.	

Date	Reading / Units	Type / Repairer Notes	Repairer
26/06/2025	592,052 kms	**Reverse Alarm** R-1831 Topped up coolant. Inspect reverse light not working. Found circuit breaker popped. Reset and lights work	
11/06/2025		**Brakes** R-1763	
11/06/2025		**Lights** R-1762	
09/06/2025	576,459 kms	**Cab** R-1769 Too much movement found in front bonnet bushes. Unplug all wiring. Unbolt bonnet struts and lay bonnet onto pallet with blanket. Unbolt front mounts and remove bonnet. Unbolt and remove bumper bar. Hammer out old bonnet bushes. Noticed movement and tightened bonnet bush mounts. Fit new eye bushes and refit bonnet. Refit all struts and wiring. Straighten mud flap mounts on bumper bar and remove all bolts further straighten mounts and brackets an fit new bolts. Drill out broken bolt for R/H top bumper mount. Refit bumper bar and replaced missing bolt. Found rubbed through 3/8 air hose near rear of trans. Cut out rubbed section. Move hose away from where it can rub through and refit with joiner. Ziptie hoses in place. Replaced trailer lights plug.	[redacted]
02/06/2025	569,682 kms	**Pressure Check** T-831 Pressure checks	[redacted]
19/05/2025	557,894 kms	**C - 100k/Annual** S-869 Unbolt and flip l/h spotlight bracket to move away from radiator. Replace broken spotter mirror on passenger side. Bend trailer connections bracket back straight. Fit new EBS socket. Fit new bolts to bulbar where missing.	
30/04/2025		**Electrical** R-1455	
30/04/2025		**Fault** T-771	
30/04/2025		**Electrical, Lights** R-1354	
30/04/2025		**Air Conditioner Cabin Truck dash** R-1361	
30/04/2025		**Engine** R-1476	
30/04/2025		**Chassis** R-1593	
15/04/2025	533,896 kms	**Engine** R-1482 Flushed adblue system twice, lights on dash went out during first flush	[redacted]
04/04/2025	523,314 kms	**New** T-712 1x Runout left rear inner Pressure Checks	
19/03/2025		**Lights** R-1219 Fault fixed with Service 813	KENNYS AUTO ELECTRICAL TSV
19/03/2025		**Chassis** R-1260 Fault fixed with service #813	
19/03/2025		**Electrical** R-1273 Fault fixed with service #813	[redacted]
19/03/2025		**Electrical** R-1320 Fault fixed with service #813	[redacted]
19/03/2025		**Lights** R-1180 Fault fixed with service #813	[redacted]
19/03/2025		**Cab** R-1207 Fault fixed with service #813	Primary Mechanical Repairs
19/03/2025	510,511 kms	**A - 10k** S-813	[redacted]

Date	Reading / Units	Type / Repairer Notes	Repairer
		Refit driver Hi/Low beam lights after hitting a roo - and adjusted. Rewire passenger side lights on rear step. Cut back and refit 1/4 hose to ride height for suspension dump. Topped up batteries with water, removed and cleaned all terminals. Inspect movement in front end then greased vehicle. Connect to trailer and adjust turntable.	
10/03/2025	463,078 kms	**B - 40k** S-781	Primary Mechanical Repairs
03/03/2025		**Fault Report** I-34	
28/02/2025	491,846 kms	**Lights** R-1205	KENNYS AUTO ELECTRICAL TSV
		Find 2 x Faults spotlights, pick up new lights, rewire bottom of harness	
14/02/2025		**Pressure Check** T-624	[redacted]
21/01/2025	459,897 kms	**New, Puncture** T-590	[redacted]
13/01/2025	454,177 kms	**Suspension** R-889	[redacted]
13/01/2025	454,177 kms	**Bullbar** R-913	[redacted]
		Replace Shock Pins	
13/01/2025	454,177 kms	**Engine** R-889	[redacted]
13/01/2025	454,177 kms	**A - 10k** S-716	[redacted]
		Repaired spare light force LED Spotlight and fit to passenger side. Replaced worn shocky bushes	
09/01/2025		**Glass** R-55	
03/12/2024	423,078 kms	**Rotate** T-470	[redacted]
		2 x Side 2 Side Steer rotation	
03/12/2024	423,078 kms	**C - 100k/Annual** S-663	[redacted]
		ICEPACK HOURS: 1380hrs -Rear left top shockie bush worn out, nil stock, bushes to be ordered in. (Tightened nut) - Needs a tune up (valve clearance) can hear it missing on a cylinder.	
25/09/2024	372,533 kms	**A - 10k** S-584	[redacted]
21/08/2024		**Cab** R-745	[redacted]
		20.8.2024 350902km -removed passenger mirror clearance light and bracket, gave bracket to Francis for new part to be sorced/ordered. Replaced plastic clearance light bracket and refit light.	
20/08/2024	350,902 kms	**Electrical** R-745	[redacted]
		16.08.2024 350901km -Inspect all fuses and relays, remove dash and stereo unit and check fuse and power to unit, all is has power and ground, believe head unit to be faulty as was having issues earlier with sound and turning on and off intermittently. 20.08.2024 350902km -Fit and setup new Stereo/Radio to truck, run usb cable though dash to passenger side and out near cupholders, run microphone cable through dash and out near steering column. Steering controls, reverse and park brake sensor cables and other acc to be wired in at a later date.	
19/08/2024	350,902 kms	**Exhaust** R-414	
		Unbolt step up clamp on flex pipe on rear of turbo, push flex pipe down further and retighten step up clamp.	
16/08/2024	350,901 kms	**B - 40k** S-537	[redacted]
		-Alternator squeals, tried to pull apart to replace bearings but after penitrant and heat didn't unsieze the bearing from the housing the main shaft cracked from the puller trying to remove it. -Water in air tanks, drier cartridge to be replaced. - windscreen cracked through middle and across bottom of driver side.	
15/08/2024	350,901 kms 1 hrs	**Rotate** T-361	[redacted]
		2 new continental HSR-2, 8 x Drive Rotation P/C	
25/07/2024		**Glass** R-533	
25/07/2024		**Glass** R-695	[redacted]

Date	Reading / Units	Type / Repairer Notes	Repairer
19/07/2024	331,666 kms	**Electrical** R-663	[redacted]
		Inspect trailer indicators not working all the time, found relays in trailer fuse/relay box dont sound the best and were skipping every now and then, pick up new relays from Napa and fit to truck, indicators now work consistently.	
13/07/2024	329,404 kms	**A - 10k** S-478	[redacted]
06/07/2024	325,448 kms	**Driveline** R-626	[redacted]
		Inspect leak on front diff, leak appears to be formed more around filter then the input shaft seal, remove front walkplate cover, spray complete diff down with degreaser and hose off, remove diff filter, tighten filter housing center bolt and fit new filter, tighten pipe on front of diff, degrease and hose down diff again as first attempt wasnt cleaned to satisfactory (Diff oil has gone tacky and was hard to clean off completely).	
05/07/2024	325,448 kms	**Pressure Check, Rim** T-486	[redacted]
		1 x Flip on Rim Right front 9 x Pressure Check	
12/06/2024	310,239 kms	**Brakes** R-533	[redacted]
		Remove heat shield from driver firewall, remove all airlines from TP5 valve, unbolt TP5 valve from firewall and remove remaining two airlines that go inside cab, picked up new TP5 valve but store produced the wrong part, return and pick up the correct part, swap all air fittings to new valve and install in truck, check operation is good and refit heat shield.	
12/06/2024	310,239 kms	**C - 100k/Annual** S-408	[redacted]
		Engine oils and filters not due. TP5 valve failed, Lets brake air through suzi lines. Windscreen cracked horizontally through driver side connecting to vertical crack passenger side.	
12/06/2024	310,239 kms	**A - 10k** S-402	[redacted]
		Completed under C service #408	
28/05/2024	298,092 kms	**Glass, Lights** R-388	
24/05/2024	297,952 kms	**B - 40k** S-361	[redacted]
24/05/2024	297,986 kms 1 hrs	**Main/inspect** T-240	
07/05/2024	282,109 kms	**Coolant** R-331	[redacted]
		Topped up coolant till full	
03/05/2024	267,442 kms	**Rim** T-182	[redacted]
		2 X FLIP ON RIM	
03/05/2024	274,052 kms 2 hrs	**New** T-151	[redacted]
03/05/2024		**New** T-163	ADVANTAGE TYRES
		8 X NEW TRYES BLACKLION BT165 295/80R22.5	
24/04/2024	274,688 kms	**Electrical** R-307	[redacted]
		Remove driver kick panels, disconnect trailer hi/low sensor as not needed in system and refit panels	
22/03/2024	251,564 kms	**B - 40k** S-229	[redacted]
12/03/2024	242,693 kms	**Cab** R-127	
		Inspect wiper speed and found speeds inconsistent with stalk positions. Wiper stalk to be booked in and replaced under warranty.	
03/03/2024	201,507 kms	**Battery** R-168	Brown & Hurley
		WARRANTY	
16/02/2024		**Warranty** R-37	Brown & Hurley
		WARRANTY COMPETED	
03/02/2024	231,758 kms	**New** T-19	

Date	Reading / Units	Type / Repairer Notes	Repairer
		x2 new steer tyres Sourced from stock Goodyear fuelmax 295-80x22-5 Checked x8 Pressure check	
29/01/2024	228,614 kms	**Driveline** R-3	Penske
		Taken to Penske Cairns. Removed and replaced RHF hub cap and gasket. Topped up oil.	
21/12/2023	209,005 kms	**C - 100k/Annual** S-21	NQ Fuel & Maintenance (RCC Lowth Pty Ltd)
		C SERVICE	
14/10/2023	158,094 kms	**B - 40k** S-22	NQ Fuel & Maintenance (RCC Lowth Pty Ltd)
		B SERVICE	

Signed: _____

Name: _____

Date: _____