Complaint: carry out turbo replacement

Cause: service intervel

Correction:

brought truck into workshop and removed turbo cleaned the base fitted new turbo with new gasket tightned all bolts and replaced the studs with bolts fitted new gasket on oil return lines checked all work all ok started truck and recheck all ok

	LABOUR CARRY OUT TURBO REPLACEMENT		500.00
622	(S) EXCH, TURBOCHARGER	1	3,140.01
1	FLANGE SCREW	4	77.72
2783	CLAMP	1	76.79
4537	GASKET	1	26.52
06133	GASKET	1	7.26
07685	GASKET	1	20.48
601	SEAL RING	1	24.28

****

Sub Total: 3,873.06

RY OUT COOLANT PUMP REPLACEMENT

26202-2 Coolant pump replacement

Complaint: carry out coolant pump replacement

Cause: service intervel

Correction: drain coolant removed the belt removed the coolant pump cleaned the surface fitted new coolant pump with new gasket and torqued all bolts folowing impact filled back the coolant fitted back the belt started truck and rechecked all work all ok

	LABOUR CARRY OUT COOLANT PUMP REPLACEMENT		500.00
T85023583	(S) EXCH, WATER PUMP UNIT	1	1,050.74
T21103569	SEALING RING	1	41.77
VT21103569	SEALING RING	1	41.77

****

Sub Total: 1,634.28

WIPER BLADES ARE WORN OUT REPLACE

CORRECTION: Remove and fit new wiper blades.

1L	LABOUR WIPER BLADES ARE WORN OUT REPLACE		100.00
VT82485683	WIPER BLADE KIT	2	120.64
VT994786	SIX POINT SOCKET S	3	4.74

****

Sub Total: 225.38

SEAT BELT NOT WORKING PROPERLY REPAIR

No repair done at this time, vehilce required. Customer are aware of faults.

****

Sub Total: 0.00

WARNING ON DASH FRONT BRAKE CALLIPER BUSHES EXCESS PLAY

No repair done at this time, vehilce required. Customer are aware of faults.

****

Sub Total: 0.00

Continued ...

VOLVO UD TRUCKS MACK

TAX INVOICE 728433

ONE EXHAUST CLAMP NEAR CAT IS LEAKING

No repair done at this time, vehilce required. Customer

faults.

****

Sub Total: 0.00

REAR DIFF INPUT SHAFT HAS TWO U CAPS SPLIT

No repair done at this time, vehilce required. Customer are aware of

faults.

****

Sub Total: 0.00

FRONT DIFF OUTPUT SHAFT HAS THREE U CAPS SPLIT

No repair done at this time, vehilce required. Customer are aware of

faults.

****

Sub Total: 0.00

GEARBOX OUTPUT SHAFT SEAL IS WEEPING HEAVY

No repair done at this time, vehilce required. Customer are aware of

faults.

****

Sub Total:

Parts: $13,145.63 Labour: $5,100.00 Others: $1,040.20

Sub Total: $ 19,285.83

Total GST: $ 1,928.59

** 24 MONTHS/500,000km WARRANTY ON FITTED PARTS**
When our workshop installs genuine parts to your
Mack UD or Volvo Truck. You recieve
24 months / 500,000km warranty
This includes parts & labour How's that for uptime value
**Please check terms & conditions

INVOICE TOTAL 21,214.42

Payment by EFT: BSB: 065 000
Account #: 1208 0520
Reference: 728433
Please email deposit details to
accounts@southcentraltrucks.com.au

For terms and conditions see last page

Ver.2.2

VOLVO UD TRUCKS MACK