Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00042528	24/09/2021	GEN	39			PART	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			PART	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			PART	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			PART	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			PART	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			PART	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			LAB	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			PART	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			PART	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			LAB	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			PART	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			PART	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			PART	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			PART	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			PART	
PM166	XQ33UH	00042528	24/09/2021	GEN	39			PART	
PM166	XQ33UH	00042498	1/10/2021	GEN	00	LABOUR MECH1			
PM166	XQ33UH	00042498	1/10/2021	GEN		REPAIR COMPLETED BY SEAN			
						FITTED DRIVING LIGHTS AND WIRED IN FITTED TRA(FITTED LIGHT AND EBS LEAD (SUPPLIED)			
PM166	XQ33UH	00042498	1/10/2021	GEN	16			TRACKER INSTALLED - 864431048068714 CON	YAT
PM166	XQ33UH	00043148	18/10/2021	WEICAL		AIR GAUGE:16000 ADJUSTED:15500 WEIGHBRIDGE:1			
PM166	XQ33UH	00043042	22/10/2021	CUMAE5	00	AIR GAUGE CALIBRATION COMPLETED CORRECTLY APPREN			
PM166	XQ33UH	00043042	22/10/2021	CUMAE5		SERVICE COMPLETED BY KEIRAN, MICK AND BEN			
						COMPLETED FIRST SERVICE FILTER CHANGE			
						NEEDS TO GO TO RTE AND HAVE DODGY WIRING RI DRIVER DEFECT ABOUT DOOR TO BE DONE BY B&H			
PM166	XQ33UH	00043042	22/10/2021	CUMAE5	00				
PM166	XQ33UH	00043042	22/10/2021	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00043042	22/10/2021	CUMAE5	16			CON	YAT
PM166	XQ33UH	00043042	22/10/2021	CUMAE5	06			LF14000NN	YAT
PM166	XQ33UH	00043042	22/10/2021	CUMAE5	06			WF2126	YAT
PM166	XQ33UH	00043042	22/10/2021	CUMAE5	06			FF5776	YA
PM166	XQ33UH	00043042	22/10/2021	CUMAE5	06			17237	YAT
PM166	XQ33UH	00043042	22/10/2021	CUMAE5	06			A-3380W1687	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00043042	22/10/2021	CUMAE5	40			3413005	YAT
PM166	XQ33UH	00043468	5/11/2021	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00043468	5/11/2021	CUMAE5		SERVICE COMPLETED BY BEN, MICK AND KEIRAN			
PM166	XQ33UH	00043468	5/11/2021	CUMAE5	00	FITTED DG BAG LABOUR APPREN			
PM166	XQ33UH	00043468	5/11/2021	CUMAE5	00	LABOUR MECH			
PM166	XQ33UH	00043468	5/11/2021	CUMAE5	16			CON	YAT
PM166	XQ33UH	00043602	15/11/2021	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00043602	15/11/2021	CUMAE5		SERVICE COMPLETED BY BEN			
PM166	XQ33UH	00043602	15/11/2021	CUMAE5	16			CON	YAT
PM166	XQ33UH	00043898	29/11/2021	CUMAE5	01	LABOUR			
PM166	XQ33UH	00043898	29/11/2021	CUMAE5		SERVICE COMPLETED.			
PM166	XQ33UH	00043898	29/11/2021	CUMBE5	00	LABOUR MECH1			
PM166	XQ33UH	00043898	29/11/2021	CUMBE5		SERVICE COMPLETED BY IAN AND BEN			
PM166	XQ33UH	00043898	29/11/2021	CUMBE5	00	FITTED SPARE OIL BOTTLE REPLACED WIPER BLADES LABOUR APPREN			
PM166	XQ33UH	00043898	29/11/2021	CUMBE5	16			CON	YAT
PM166	XQ33UH	00043898	29/11/2021	CUMBE5	06			MK13584	YAT

PM166	XQ33UH	00043898	29/11/2021	CUMBE5	40			3413005	YAT
PM166	XQ33UH	00044205	13/12/2021	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00044205	13/12/2021	CUMAE5		SERVICE COMPLETED BY BEN			
PM166	XQ33UH	00044205	13/12/2021	CUMAE5	16			CON	YAT
PM166	XQ33UH	00044715	18/01/2022	CUMAE5	00	LABOUR MECH1			
PM166	XQ33UH	00044715	18/01/2022	CUMAE5		SERVICE COMPLETED BY IAN			
PM166	XQ33UH	00044715	18/01/2022	CUMAE5	16	ADJUST CLUTCH CON			YAT
PM166	XQ33UH	00045028	2/02/2022	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00045028	2/02/2022	CUMAE5		SERVICE COMPLETED BY KEIRAN AND MICK			
PM166	XQ33UH	00045028	2/02/2022	CUMAE5	00	NEEDS TO HAVE BOLTS IN FRONT OF IDLER PULLEY			
PM166	XQ33UH	00045028	2/02/2022	CUMAE5	16			CON	YAT
PM166	XQ33UH	00045028	2/02/2022	DEFECT		Reported Defect :-Defect Code : 00007131 Defect Reference : 42401 Date : 17/10/2021 Description c DRIVERS DOOR NOT SEALING PROPERLY			
PM166	XQ33UH	00045253	11/02/2022	CUMAE5	01	NEEDS TO GO TO BROWN & HURLEY (WARRANTY) DEFECT CLEARED BY KEIRAN LABOUR			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00045253	11/02/2022	CUMAE5		SERVICE COMPLETED.			
PM166	XQ33UH	00045253	11/02/2022	CUMBE5	00	LABOUR MECH1			
PM166	XQ33UH	00045253	11/02/2022	CUMBE5		SERVICE COMPLETED BY IAN AND BRENDON			
PM166	XQ33UH	00045253	11/02/2022	CUMBE5	00	CHECKED FRONT HUBS AND NO OIL LEAKING LABOI			
PM166	XQ33UH	00045253	11/02/2022	CUMBE5	16			CON	YAT
PM166	XQ33UH	00045253	11/02/2022	CUMBE5	06			MK13584	YAT
PM166	XQ33UH	00045253	11/02/2022	CUMBE5	06			FS19764	YAT
PM166	XQ33UH	00045253	11/02/2022	CUMBE5	40			3413005	YAT
PM166	XQ33UH	00045784	26/02/2022	CUMAE5	00	LABOUR MECH1			
PM166	XQ33UH	00045784	26/02/2022	CUMAE5		SERVICE COMPLETED.			
PM166	XQ33UH	00045784	26/02/2022	CUMAE5	00	LABOUR APPRENB			
PM166	XQ33UH	00045784	26/02/2022	CUMAE5	00	LABOUR TRADEA			
PM166	XQ33UH	00045784	26/02/2022	CUMAE5	16			CON	YAT
PM166	XQ33UH	00045822	2/03/2022	TYRES	15			33000051	BRIAUS
PM166	XQ33UH	00045925	2/03/2022	TYRES	15			33000051	BRIAUS
PM166	XQ33UH	00045822	2/03/2022	TYRES	15			33000051	BRIAUS
PM166	XQ33UH	00045925	2/03/2022	TYRES	15			33000051	BRIAUS
PM166	XQ33UH	00046410	4/03/2022	WEICAL		AIR GAUGE: 15 ADJUSTED: 15 WEIGHBRIDGE: 14.6			
PM166	XQ33UH	00046158	16/03/2022	CUMAE5	00	AIR GAUGE CALIBRATION COMPLETED CORRECTLY SUBMEC			
PM166	XQ33UH	00046158	16/03/2022	CUMAE5		SERVICE COMPLETED BY BRENDAN AND TYLER			
PM166	XQ33UH	00046158	16/03/2022	CUMAE5	00	DEFECT 42407 (WORK ORDER 7417) COMPLETED LA APPREN			
PM166	XQ33UH	00046158	16/03/2022	CUMAE5	16			CON	YAT
PM166	XQ33UH	00046158	16/03/2022	CUMAE5	40			3413005	YAT
PM166	XQ33UH	00046158	16/03/2022	DEFECT	00	LABOUR SUBMEC			
PM166	XQ33UH	00046158	16/03/2022	DEFECT					
PM166	XQ33UH	00046158	16/03/2022	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00046158	16/03/2022	DEFECT		Reported Defect :- Defect Code : 00007417 Defect Reference : 42407 Date : 16/03/2 DUE FOR A SERVICE			
PM166	XQ33UH	00046158	16/03/2022	ECO	00	LABOUR SUBMEC			
PM166	XQ33UH	00046158	16/03/2022	ECO		SERVICE COMPLETED BY BRENDAN			
PM166	XQ33UH	00046158	16/03/2022	ECO	16			CON	YAT

PM166	XQ33UH	00046158	16/03/2022	ECO	40			10W50	YAT
PM166	XQ33UH	00046227	21/03/2022	GEN	00	LABOUR MECH1			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00046227	21/03/2022	GEN		REPAIR COMPLETED BY IAN			
				GEN	16	CHECK SPOT LIGHTS FOUND AND REPLACED BLOW NONE FOUND - NOW WIRING OK ADJUSTED L/H MIRROR UPWARDS AS REQUESTED CON YAT			
PM166	XQ33UH	00046227	21/03/2022						
PM166	XQ33UH	00046568	30/03/2022	DEFECT	00	LABOUR MECH			
PM166	XQ33UH	00046568	30/03/2022	DEFECT		DEFECT CLEARED BY MICK			
PM166	XQ33UH	00046568	30/03/2022	DEFECT		Reported Defect :-Defect Code : 00007457 Defect Reference : 42410 Date : 30/03/2022 Description c			
PM166	XQ33UH	00046568	30/03/2022	TRA	00	MICK CORRECTED THIS TO SAY A SERVICE LABOUR			
PM166	XQ33UH	00046568	30/03/2022	TRA		SERVICE COMPLETED COMPLETED BY MICK AND BF			
						*DOORS NEED ADJUSTING WARRENTY *CHECK 2ND FRIDGE OPERATION WARRENTY LABO			
PM166	XQ33UH	00046568	30/03/2022	TRA	00				
PM166	XQ33UH	00046568	30/03/2022	TRA	16			CON	YAT
PM166	XQ33UH	00046878	4/04/2022	WEICAL		AIR GAUGE: 15 ADJUSTED: 15 WEIGHBRIDGE 14.620:			
PM166	XQ33UH	00046944	8/04/2022	GEN	00	AIR GAUGE CALIBRATION COMPLETED CORRECTLY			
PM166	XQ33UH	00046944	8/04/2022	GEN		REPAIR COMPLETED BY BEN			
PM166	XQ33UH	00046944	8/04/2022	GEN	16			CON	YAT
PM166	XQ33UH	00046944	8/04/2022	GEN	14			200.203	YAT
PM166	XQ33UH	00046944	8/04/2022	GEN	14			2619 705 001	YAT
PM166	XQ33UH	00046944	8/04/2022	GEN	14			82529	YAT
PM166	XQ33UH	00046850	12/04/2022	CUMAE5	00	LABOUR MECH1			
PM166	XQ33UH	00046850	12/04/2022	CUMAE5		SERVICE COMPLETED IAN AND TYLER			
PM166	XQ33UH	00046850	12/04/2022	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00046850	12/04/2022	CUMAE5	16			CON	YAT
PM166	XQ33UH	00046850	12/04/2022	CUMAE5	06			MK13584	YAT
PM166	XQ33UH	00046850	12/04/2022	CUMAE5	06			FS19764	YAT
PM166	XQ33UH	00047253	30/04/2022	CUMAE5	00	LABOUR MECH1			
PM166	XQ33UH	00047253	30/04/2022	CUMAE5		SERVICE COMPLETED BY IAN AND TYLER			
						CARRY OUT A SERVICE SERVICE SLEEPER AIR			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00047253	30/04/2022	CUMAE5	00	LABOUR	TRADEA		
PM166	XQ33UH	00047253	30/04/2022	CUMAE5	16			CON	YAT
PM166	XQ33UH	00047253	30/04/2022	ECO	00	LABOUR MECH1			
PM166	XQ33UH	00047253	30/04/2022	ECO		SERVICE COMPLETED BY IAN			
PM166	XQ33UH	00047253	30/04/2022	ECO	16			CON	YAT
PM166	XQ33UH	00047253	30/04/2022	ECO	40			10W50	YAT
PM166	XQ33UH	00047786	23/05/2022	CUMAE5	00	LABOUR SUBMEC			
PM166	XQ33UH	00047786	23/05/2022	CUMAE5		SERVICE COMPLETED BRENDAN KEIRAN AND MICK DEFECT 42416 - ECM REPROGRAMMED - PLEASE CL DEFECT 7343 - FRIDGE TURN FROM OF TO ON - PLE DEFECT 42415 - PLEASE MONITOR AFTER REPAIR O LABOUR APPRENK			
PM166	XQ33UH	00047786	23/05/2022	CUMAE5	00				
PM166	XQ33UH	00047786	23/05/2022	CUMAE5	00	LABOUR MECH1			
PM166	XQ33UH	00047786	23/05/2022	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00047786	23/05/2022	DEFECT					

PM166	XQ33UH	00047786	23/05/2022	DEFECT		DEFECT CLEARED.					
PM166	XQ33UH	00047786	23/05/2022	DEFECT		Reported Defect :-Defect Code : 00007344					
PM166	XQ33UH	00047786	23/05/2022	DEFECT		Defect Reference : 42405 Date : 27/01/2022 Description c					
						Reported Defect :-					
						Defect Code : 00007343 Defect Reference : 42406 Date :					
						LH FRIDGE NOT WORKING NOT GETTING COLD					
						LABOUR					
PM166	XQ33UH	00048478	22/06/2022	CUMAE5	01						
PM166	XQ33UH	00048478	22/06/2022	CUMAE5		SERVICE COMPLETED.					
PM166	XQ33UH	00048478	22/06/2022	CUMBE5	00	LABOUR MECH					
PM166	XQ33UH	00048478	22/06/2022	CUMBE5		SERVICE COMPLETED BY MICK AND BRENDAN					
PM166	XQ33UH	00048478	22/06/2022	CUMBE5	00	ADBLUE AIR FLUSH COMPLETED LABOUR SUBMEC					
PM166	XQ33UH	00048478	22/06/2022	CUMBE5	16			CON		YAT	
PM166	XQ33UH	00048478	22/06/2022	CUMBE5	06				LF14000NN	YAT	
PM166	XQ33UH	00048478	22/06/2022	CUMBE5	06				FF5776	YA	
PM166	XQ33UH	00048478	22/06/2022	CUMBE5	06				AS2474	YAT	
PM166	XQ33UH	00048478	22/06/2022	CUMBE5	40				3413005	YAT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	Su Co
PM166	XQ33UH	00048478	22/06/2022	DEFECT		Reported Defect :-				
						Defect Code : 00007626 Defect Reference : 42415 Date : 23/05/2				
						JAKE BRAKE NOT ENGAGING SOMETIMES - PLEASE MONIT				
PM166	XQ33UH	00048849	7/07/2022	CUMAE5	00	NEW DRIVER SAYS ITS ALL OK - NO LABOUR APPRENB			PROBLEM	
PM166	XQ33UH	00048849	7/07/2022	CUMAE5		SERVICE COMPLETED BY BEN				
PM166	XQ33UH	00048849	7/07/2022	CUMAE5	16			CON	YAT	
PM166	XQ33UH	00049685	4/08/2022	CUMAE5	00	LABOUR APPRENB				
PM166	XQ33UH	00049685	4/08/2022	CUMAE5		SERVICE COMPLETED BY BEN				
PM166	XQ33UH	00049685	4/08/2022	CUMAE5	16			CON	YAT	
PM166	XQ33UH	00049685	4/08/2022	DEFECT		Reported Defect :-Defect Code : 00007774				
						Defect Reference : 42417 Date : 22/06/2022				
						Description of Defect :				
						ENGINE RETARDER LIGHT NOT WORKING, AXEL OIL RR, MA				
PM166	XQ33UH	00049685	4/08/2022	ECO	00	LABOUR APPRENB				
PM166	XQ33UH	00049685	4/08/2022	ECO		SERVICE COMPLETED BY BEN				
PM166	XQ33UH	00049685	4/08/2022	ECO	16			CON	YAT	
PM166	XQ33UH	00049685	4/08/2022	ECO	06			ED2175254-S	YAT	
PM166	XQ33UH	00049685	4/08/2022	ECO	40			10W50	YAT	
PM166	XQ33UH	00049858	11/08/2022	CUMAE5	01	LABOUR				
PM166	XQ33UH	00049858	11/08/2022	CUMAE5		SERVICE COMPLETED BY KEIRAN AND TYLER				
PM166	XQ33UH	00049858	11/08/2022	CUMAE5	00	- TOPPED UP ENGINE OIL - 2L LABOUR MECH1				
PM166	XQ33UH	00049858	11/08/2022	CUMAE5	00	LABOUR APPREN				
PM166	XQ33UH	00049858	11/08/2022	CUMAE5	16			CON	YAT	
PM166	XQ33UH	00049858	11/08/2022	CUMAE5	40			3413005	YAT	
PM166	XQ33UH	00049901	15/08/2022	TYRES	15			33000096		
PM166	XQ33UH	00049901	15/08/2022	TYRES	15			33000096		
PM166	XQ33UH	00050191	25/08/2022	CUMAE5	01	LABOUR				
PM166	XQ33UH	00050191	25/08/2022	CUMAE5		SERVICE COMPLETED.				
PM166	XQ33UH	00050191	25/08/2022	CUMBE5	00	LABOUR APPRENB				
PM166	XQ33UH	00050191	25/08/2022	CUMBE5		SERVICE COMPLETED BY BEN AND MICK				

						CLEANED ADBLUE LINES AND BREATHER RE-SHAPED ADBLUE TANK MOVE ADBLUE TANK LABOUR MECH				
PM166	XQ33UH	00050191	25/08/2022	CUMBE5	00					
PM166	XQ33UH	00050191	25/08/2022	CUMBE5	16			CON	YAT	
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code		W/H Code
PM166	XQ33UH	00050191	25/08/2022	CUMBE5	06			LF14000NN		YAT
PM166	XQ33UH	00050191	25/08/2022	CUMBE5	06			FF5776		YAT
PM166	XQ33UH	00050191	25/08/2022	CUMBE5	06			AS2474		YAT
PM166	XQ33UH	00050191	25/08/2022	CUMBE5	40			3413005		YAT
PM166	XQ33UH	00050368	25/08/2022	WEICAL		AIR GAUGE: 17000 ADJUSTED: 17000 WEIGHBRIDGE: 16700				
PM166	XQ33UH	00050564	13/09/2022	CUMAE5	00	AIR GAUGE CALIBRATION COMPLETED CORRECTLY MECH1				
PM166	XQ33UH	00050564	13/09/2022	CUMAE5		SERVICE COMPLETE BY KEIRAN				
PM166	XQ33UH	00050564	13/09/2022	CUMAE5	16			CON		YAT
PM166	XQ33UH	00050598	15/09/2022	TYRES	15			33000051		
PM166	XQ33UH	00050598	15/09/2022	TYRES	15			33000051		
PM166	XQ33UH	00050664	16/09/2022	TYRES	15			11006520		
PM166	XQ33UH	00050664	16/09/2022	TYRES	39			33000241		
PM166	XQ33UH	00050664	16/09/2022	TYRES	39			33000125		
PM166	XQ33UH	00050664	16/09/2022	TYRES	15			11006520		
PM166	XQ33UH	00050664	16/09/2022	TYRES	39			33000241		
PM166	XQ33UH	00050664	16/09/2022	TYRES	39			33000125		
PM166	XQ33UH	00050990	29/09/2022	CUMAE5	01	LABOUR MECH				
PM166	XQ33UH	00050990	29/09/2022	CUMAE5		SERVICE COMPLETED BY BENNY AND TYLER				
PM166	XQ33UH	00050990	29/09/2022	CUMAE5	00	- TIGHTENED GRILL BOLTS LABOUR APPRENB				
PM166	XQ33UH	00050990	29/09/2022	CUMAE5	00	LABOUR APPREN				
PM166	XQ33UH	00050990	29/09/2022	CUMAE5	16			CON	YAT	
PM166	XQ33UH	00051101	6/10/2022	TYRES	15			33000051		BRIAU
PM166	XQ33UH	00051101	6/10/2022	TYRES	15			33000051		BRIAU
PM166	XQ33UH	00051369	14/10/2022	CUMAE5	01	LABOUR MECH				
PM166	XQ33UH	00051369	14/10/2022	CUMAE5		SERVICE COMPLETED BY KEIREN				
PM166	XQ33UH	00051369	14/10/2022	CUMAE5	00	- REPLACED WIPER BLADES LABOUR MECH1				
PM166	XQ33UH	00051369	14/10/2022	CUMAE5	16			CON	YAT	
PM166	XQ33UH	00051370	14/10/2022	ECO	01	LABOUR				
PM166	XQ33UH	00051370	14/10/2022	ECO		SERVICE COMPLETED BY KEIRAN				
PM166	XQ33UH	00051370	14/10/2022	ECO	00	LABOUR MECH1				
PM166	XQ33UH	00051370	14/10/2022	ECO	16			CON	YAT	
PM166	XQ33UH	00051370	14/10/2022	ECO	06			ED2175254-S	YAT	
PM166	XQ33UH	00051370	14/10/2022	ECO	40			10W50	YAT	
PM166	XQ33UH	00051428	17/10/2022	TYRES	15			PART		BRIAU
PM166	XQ33UH	00051428	17/10/2022	TYRES	15			PART		BRIAU
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code		W/H Code
PM166	XQ33UH	00051713	28/10/2022	CUMAE5	01	LABOUR MECH				
PM166	XQ33UH	00051713	28/10/2022	CUMAE5		SERVICE COMPLETED.				
PM166	XQ33UH	00051713	28/10/2022	CUMBE5	00	LABOUR MECH1				
PM166	XQ33UH	00051713	28/10/2022	CUMBE5		SERVICE COMPLETED BY KEIRAN AND TYLER				
						HAD TO BLEED THE POWER STEERING DUE TO ONE OF TH REPLACED MALE LIGHT PLUG				
PM166	XQ33UH	00051713	28/10/2022	CUMBE5	00	LABOUR APPREN				
PM166	XQ33UH	00051713	28/10/2022	CUMBE5	16			CON		YAT
PM166	XQ33UH	00051713	28/10/2022	CUMBE5	06			MK13584		YAT
PM166	XQ33UH	00051713	28/10/2022	CUMBE5	06			FS19764		YAT
PM166	XQ33UH	00051742	31/10/2022	CUMAE5	00	LABOUR APPREN				
PM166	XQ33UH	00051742	31/10/2022	CUMAE5		SERVICE COMPLETED BY TYLER				

PM166	XQ33UH	00051742	31/10/2022	CUMAE5	16	REPLACED BOTH WIPER BLADES CON			YAT
PM166	XQ33UH	00051742	31/10/2022	CUMAE5	11			WW710R8-10	YAT
PM166	XQ33UH	00052181	10/11/2022	CUMCE5	00	LABOUR MECH1			
PM166	XQ33UH	00052181	10/11/2022	CUMCE5		SERVICE COMPLETED.			
PM166	XQ33UH	00052181	10/11/2022	CUMCE5	00	LABOUR APPREN			
PM166	XQ33UH	00052181	10/11/2022	CUMCE5	00	LABOUR APPRENF			
PM166	XQ33UH	00052181	10/11/2022	CUMCE5	06			A-3380W1687	YAT
PM166	XQ33UH	00052181	10/11/2022	CUMCE5	06			17237	YAT
PM166	XQ33UH	00052181	10/11/2022	CUMCE5	06			LF637	YAT
PM166	XQ33UH	00052181	10/11/2022	CUMCE5	03			27H-780HD	YAT
PM166	XQ33UH	00052181	10/11/2022	CUMCE5	06			25189011	YAT
PM166	XQ33UH	00052181	10/11/2022	CUMCE5	06			TT224P	YAT
PM166	XQ33UH	00052181	10/11/2022	CUMCE5	40			3334800	YAT
PM166	XQ33UH	00052362	10/11/2022	EXOINS	00	LABOUR MECH1			
PM166	XQ33UH	00052362	10/11/2022	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECT			
PM166	XQ33UH	00052362	10/11/2022	EXOINS	00	INSPECTION COMPLETED BY KEIRAN AND TYLER LA			
PM166	XQ33UH	00052411	2/12/2022	CUMAE5	00	LABOUR APPRENB			
PM166	XQ33UH	00052411	2/12/2022	CUMAE5		REPLACED WIPER BLADES TOPPED UP ENGINE OIL SERVICE COMPLETED BY BEN AND MICK LABOUR M			
PM166	XQ33UH	00052411	2/12/2022	CUMAE5	40			15W40	YAT
PM166	XQ33UH	00052411	2/12/2022	CUMAE5	16			CON	YAT
PM166	XQ33UH	00052701	13/12/2022	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00052701	13/12/2022	CUMAE5		SERVICE COMPLETED BY TYLER			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00052701	13/12/2022	CUMAE5	16			CON	YAT
PM166	XQ33UH	00052695	13/12/2022	ECO	00	LABOUR APPRENF			
PM166	XQ33UH	00052695	13/12/2022	ECO		SERVICE COMPLETED BY FLYNN			
PM166	XQ33UH	00052695	13/12/2022	ECO	06			ED2175254-S	YAT
PM166	XQ33UH	00052695	13/12/2022	ECO	40			10W50	YAT
PM166	XQ33UH	00052695	13/12/2022	ECO	16			CON	YAT
PM166	XQ33UH	00053142	3/01/2023	CUMAE5	01	LABOUR APPREN			
PM166	XQ33UH	00053142	3/01/2023	CUMAE5		SERVICE COMPLETED.			
PM166	XQ33UH	00053142	3/01/2023	CUMAE5	16			MK13584	YAT
PM166	XQ33UH	00053142	3/01/2023	CUMAE5	16			3413005	YAT
PM166	XQ33UH	00053142	3/01/2023	CUMAE5	16			12PK2380	YAT
PM166	XQ33UH	00053142	3/01/2023	CUMAE5	16			6PK1625	YAT
PM166	XQ33UH	00053142	3/01/2023	CUMAE5	16			CON	YAT
PM166	XQ33UH	00053585	24/01/2023	CUMAE5	01	LABOUR APPRENK			
PM166	XQ33UH	00053585	24/01/2023	CUMAE5		SERVICE COMPLETED. DEFECT 8299 STILL NEEDS TO GO TO BROWN AND HURLEY FOR \			
PM166	XQ33UH	00053585	24/01/2023	CUMAE5	00	REPLACED 4 BATTERIES LABOUR APPRENF			
PM166	XQ33UH	00053585	24/01/2023	CUMAE5	16			MF70ZZDT	YAT
PM166	XQ33UH	00053585	24/01/2023	CUMAE5	16			CON	YAT
PM166	XQ33UH	00053585	24/01/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00053585	24/01/2023	DEFECT					
PM166	XQ33UH	00053585	24/01/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00053587	24/01/2023	ECO	01	LABOUR APPRENK			
PM166	XQ33UH	00053587	24/01/2023	ECO		SERVICE COMPLETED. REPLACE LIFT PUMP/FUEL PUMP AS			REQU
PM166	XQ33UH	00053587	24/01/2023	ECO	16			ED2175254-S	YAT
PM166	XQ33UH	00053587	24/01/2023	ECO	16			10W50	YAT
PM166	XQ33UH	00053587	24/01/2023	ECO	16			ED0065851390S	YAT
PM166	XQ33UH	00053587	24/01/2023	ECO	16			CON	YAT
PM166	XQ33UH	00053771	31/01/2023	CUMAE5	00	LABOUR APPRENB			
PM166	XQ33UH	00053771	31/01/2023	CUMAE5		SERVICE COMPLETED. REPLACED WIPER			
PM166	XQ33UH	00053771	31/01/2023	CUMAE5	00	BLADES LABOUR APPRENF			

PM166	XQ33UH	00053771	31/01/2023	CUMAE5	16			WIPRBLAD	YAT
PM166	XQ33UH	00053771	31/01/2023	CUMAE5	16			CON	YAT
PM166	XQ33UH	00053771	31/01/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00053771	31/01/2023	DEFECT					
PM166	XQ33UH	00053771	31/01/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00053761	1/02/2023	TYRES	15			11004493	
PM166	XQ33UH	00053761	1/02/2023	TYRES	15			77000180	
PM166	XQ33UH	00053761	1/02/2023	TYRES	15			33000084	
PM166	XQ33UH	00053761	1/02/2023	TYRES	15			33000517	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00053761	1/02/2023	TYRES	15			33000517	
PM166	XQ33UH	00053761	1/02/2023	TYRES	15			33000084	
PM166	XQ33UH	00053761	1/02/2023	TYRES	15			77000180	
PM166	XQ33UH	00053761	1/02/2023	TYRES	15			11004493	
PM166	XQ33UH	00054243	21/02/2023	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00054243	21/02/2023	CUMAE5		SERVICE COMPLETED.			
PM166	XQ33UH	00054243	21/02/2023	CUMAE5	16			CON	YAT
PM166	XQ33UH	00054243	21/02/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00054243	21/02/2023	DEFECT					
PM166	XQ33UH	00054243	21/02/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00054521	7/03/2023	CUMAE5	01	LABOUR MECH			
PM166	XQ33UH	00054521	7/03/2023	CUMAE5		SERVICE COMPLETED.			
PM166	XQ33UH	00054521	7/03/2023	CUMBE5	00	LABOUR APPREN			
PM166	XQ33UH	00054521	7/03/2023	CUMBE5		SERVICE COMPLETED.			
PM166	XQ33UH	00054521	7/03/2023	CUMBE5	00	LABOUR APPRENF			
PM166	XQ33UH	00054521	7/03/2023	CUMBE5	06			PART	YAT
PM166	XQ33UH	00054521	7/03/2023	CUMBE5	40			PART	YAT
PM166	XQ33UH	00054521	7/03/2023	CUMBE5	16			CON	YAT
PM166	XQ33UH	00054521	7/03/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00054521	7/03/2023	DEFECT					
PM166	XQ33UH	00054521	7/03/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00054660	9/03/2023	TYRES	15			99015526	
PM166	XQ33UH	00054660	9/03/2023	TYRES	15			77000194	
PM166	XQ33UH	00054660	9/03/2023	TYRES	15			33000084	
PM166	XQ33UH	00054660	9/03/2023	TYRES	15			33000517	
PM166	XQ33UH	00054660	9/03/2023	TYRES	15			33000051	
PM166	XQ33UH	00054660	9/03/2023	TYRES	15			99015526	
PM166	XQ33UH	00054660	9/03/2023	TYRES	15			77000194	
PM166	XQ33UH	00054660	9/03/2023	TYRES	15			33000084	
PM166	XQ33UH	00054660	9/03/2023	TYRES	15			33000517	
PM166	XQ33UH	00054660	9/03/2023	TYRES	15			33000051	
PM166	XQ33UH	00054769	10/03/2023	TYRES	15			11006520	
PM166	XQ33UH	00054769	10/03/2023	TYRES	15			33000084	
PM166	XQ33UH	00054769	10/03/2023	TYRES	15			33000051	
PM166	XQ33UH	00054769	10/03/2023	TYRES	15			33000237	
PM166	XQ33UH	00054769	10/03/2023	TYRES	15			33000237	
PM166	XQ33UH	00054769	10/03/2023	TYRES	15			33000237	
PM166	XQ33UH	00054769	10/03/2023	TYRES	15			33000237	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00054769	10/03/2023	TYRES	15			33000051	
PM166	XQ33UH	00054769	10/03/2023	TYRES	15			33000084	
PM166	XQ33UH	00054769	10/03/2023	TYRES	15			11006520	
PM166	XQ33UH	00055183	28/03/2023	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00055183	28/03/2023	DEFECT					
PM166	XQ33UH	00055183	28/03/2023	DEFECT		DEFECT	CLEARED.		
PM166	XQ33UH	00055183	28/03/2023	ECO	00	LABOUR MECH 3			
PM166	XQ33UH	00055183	28/03/2023	ECO		SERVICE COMPLETED.			
PM166	XQ33UH	00055183	28/03/2023	ECO	00	LABOUR MECH 2			
PM166	XQ33UH	00055183	28/03/2023	ECO	06			ED2175254-S	YAT

PM166	XQ33UH	00055183	28/03/2023	ECO	40			10W50	YAT
PM166	XQ33UH	00055182	29/03/2023	CUMAE5	00	LABOUR MECH 2			
PM166	XQ33UH	00055182	29/03/2023	CUMAE5		SERVICE COMPLETED.			
PM166	XQ33UH	00055182	29/03/2023	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00055182	29/03/2023	CUMAE5	16			CON	YAT
PM166	XQ33UH	00055182	29/03/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00055182	29/03/2023	DEFECT					
PM166	XQ33UH	00055182	29/03/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00055421	6/04/2023	CUMAE5	00	LABOUR MECH 3			
PM166	XQ33UH	00055421	6/04/2023	CUMAE5		SERVICE COMPLETED. TIGHTENED LOOSE			
PM166	XQ33UH	00055421	6/04/2023	CUMAE5	00	GRILL LABOUR APPRENF			
PM166	XQ33UH	00055421	6/04/2023	CUMAE5	16			CON	YAT
PM166	XQ33UH	00055421	6/04/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00055421	6/04/2023	DEFECT					
PM166	XQ33UH	00055421	6/04/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00055421	6/04/2023	DEFECT		Reported Defect :-Defect Code : 00008299			
PM166	XQ33UH	00055735	20/04/2023	CUMAE5		Defect Reference : WO 52181 Date : 10/11/2022 Description of Defect : TACHO ONLY WORKS SOMETIMES PASSENGER DOOR FRIDGE U/S LABOUR APPRENF			
PM166	XQ33UH	00055735	20/04/2023	CUMAE5	00	SERVICE COMPLETED.			
PM166	XQ33UH	00055735	20/04/2023	CUMAE5	00	ADJUST TURNTABLE TOPPED OIL UP LABOUR MECH 3			
PM166	XQ33UH	00055735	20/04/2023	CUMAE5	16			CON	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00055756	21/04/2023	GE		Inspected under bunk fridge operation. Found the fridge power supply, earth circuits and found to be in working c mattress from truck. Removed bunk plate to gain access have correct plug in stock for fridge so had to fit deutsch Let cool down whilst completing other jobs. Tested temp refit mattress.			
PM166	XQ33UH	00055756	21/04/2023	GEN	39	VANGO ON W434446 FRIDGE IN OP VANGO TESTED OVER 4 DAYS AND REACHED AND MAINTA		LABEXT	
PM166	XQ33UH	00055756	21/04/2023	GEN	39			ENVLEV	
PM166	XQ33UH	00055756	21/04/2023	GEN	39			MISCON	
PM166	XQ33UH	00055756	21/04/2023	GEN	39			MISCON	
PM166	XQ33UH	00055756	21/04/2023	GEN	39			ENVLEV	
PM166	XQ33UH	00055756	21/04/2023	GEN	39			LABEXT	
PM166	XQ33UH	00056047	4/05/2023	ECO	00	LABOUR APPRENF			
PM166	XQ33UH	00056047	4/05/2023	ECO		SERVICE COMPLETED.			
PM166	XQ33UH	00056047	4/05/2023	ECO	40			10W50	YAT
PM166	XQ33UH	00056047	4/05/2023	ECO	16			CON	YAT
PM166	XQ33UH	00056046	5/05/2023	CUMA	01	LABOUR MECH			
PM166	XQ33UH	00056046	5/05/2023	CUMA		SERVICE COMPLETED.			
PM166	XQ33UH	00056046	5/05/2023	CUMB	00	LABOUR MECH 1			
PM166	XQ33UH	00056046	5/05/2023	CUMBE5		SERVICE COMPLETED. ADJUSTED CLUTCH			
PM166	XQ33UH	00056046	5/05/2023	CUMBE5	00	CARRIED JOUT AD BLUE FLUSH LABOUR APPREN			
PM166	XQ33UH	00056046	5/05/2023	CUMB	06			MK13584	YAT
PM166	XQ33UH	00056046	5/05/2023	CUMB	40			15W40	YAT
PM166	XQ33UH	00056046	5/05/2023	CUMB	16			CON	YAT
PM166	XQ33UH	00056046	5/05/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00056046	5/05/2023	DEFECT					
PM166	XQ33UH	00056046	5/05/2023	DEFECT		DEFECT CLEARED.			

PM166	XQ33UH	00056046	5/05/2023	DEFECT	Reported Defect :-Defect Code : 00009169
PM166	XQ33UH	00056572	25/05/2023	CUMAE5 00	Defect Reference : 42418 Date : 03/05/2023 Description of Defect : AFTERTEAT LIGHT ON TRAILER ABS LIGHT ON CLUSTER BLOWN LABOUR MECH 3

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00056572	25/05/2023	CUMAE5		SERVICE COMPLETED. REAFFIXED DRIVERS SIDE G DRIVERS SIDE SCREEN HAS A CRACK THAT NEEDS			
PM166	XQ33UH	00056572	25/05/2023	CUMAE5	00	LABOUR APPRENF			
PM166	XQ33UH	00056572	25/05/2023	CUMAE5	16			CON	YAT
PM166	XQ33UH	00057593	1/06/2023	GEN	39			PART	
PM166	XQ33UH	00057593	1/06/2023	GEN	39			CON	
PM166	XQ33UH	00057593	1/06/2023	GEN	39			CON	
PM166	XQ33UH	00057593	1/06/2023	GEN	39			PART	
PM166	XQ33UH	00057074	9/06/2023	CUMAE5	00	LABOUR APPRENF			
PM166	XQ33UH	00057074	9/06/2023	CUMAE5		SERVICE COMPLETED.			
PM166	XQ33UH	00057074	9/06/2023	CUMAE5	00	REPLACED 1KG FIRE EXTINGUSHER REPLACED COOLING FAN FOR AIR EVAPARATOR LA			
PM166	XQ33UH	00057074	9/06/2023	CUMAE5	19			FIREEXT1KG	YAT
PM166	XQ33UH	00057074	9/06/2023	CUMAE5	16			FA0023	YAT
PM166	XQ33UH	00057074	9/06/2023	CUMAE5	16			CON	YAT
PM166	XQ33UH	00057074	9/06/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00057074	9/06/2023	DEFECT					
PM166	XQ33UH	00057074	9/06/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00057134	9/06/2023	GEN	39			WHEALI	
PM166	XQ33UH	00057134	9/06/2023	GEN	39			TYRREP	
PM166	XQ33UH	00057134	9/06/2023	GEN	39			WHEALI	
PM166	XQ33UH	00057134	9/06/2023	GEN	39			TYRREP	
PM166	XQ33UH	00057165	12/06/2023	TYRES	15			11004496	
PM166	XQ33UH	00057165	12/06/2023	TYRES	15			33000084	
PM166	XQ33UH	00057165	12/06/2023	TYRES	15			33000370	
PM166	XQ33UH	00057165	12/06/2023	TYRES	15			33000525	
PM166	XQ33UH	00057165	12/06/2023	TYRES	15			33000518	
PM166	XQ33UH	00057165	12/06/2023	TYRES	15			33000051	
PM166	XQ33UH	00057165	12/06/2023	TYRES	15			33000084	
PM166	XQ33UH	00057165	12/06/2023	TYRES	15			11004496	
PM166	XQ33UH	00057165	12/06/2023	TYRES	15			33000370	
PM166	XQ33UH	00057165	12/06/2023	TYRES	15			33000525	
PM166	XQ33UH	00057165	12/06/2023	TYRES	15			33000518	
PM166	XQ33UH	00057165	12/06/2023	TYRES	15			33000051	
PM166	XQ33UH	00057182	13/06/2023	TYRES	15			33000188	
PM166	XQ33UH	00057182	13/06/2023	TYRES	15			33000188	
PM166	XQ33UH	00057637	29/06/2023	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00057637	29/06/2023	CUMAE5		SERVICE COMPLETED.			
PM166	XQ33UH	00057637	29/06/2023	CUMAE5	16			CON	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00057637	29/06/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00057638	29/06/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00057637	29/06/2023	DEFECT					
PM166	XQ33UH	00057638	29/06/2023	DEFECT					
PM166	XQ33UH	00057637	29/06/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00057638	29/06/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00057638	29/06/2023	ECO	00	LABOUR APPREN			
PM166	XQ33UH	00057638	29/06/2023	ECO		SERVICE COMPLETED.			
PM166	XQ33UH	00057638	29/06/2023	ECO	40			10W50	YAT
PM166	XQ33UH	00057638	29/06/2023	ECO	06			ED2175254-S	YAT
PM166	XQ33UH	00057638	29/06/2023	ECO	16			CON	YAT
PM166	XQ33UH	00057791	6/07/2023	GEN	15			99015526	
PM166	XQ33UH	00057791	6/07/2023	GEN	15			33000084	

PM166	XQ33UH	00057791	6/07/2023	GEN	15			33000370	
PM166	XQ33UH	00057791	6/07/2023	GEN	15			33000518	
PM166	XQ33UH	00057791	6/07/2023	GEN	15			33000518	
PM166	XQ33UH	00057791	6/07/2023	GEN	15			33000370	
PM166	XQ33UH	00057791	6/07/2023	GEN	15			33000084	
PM166	XQ33UH	00057791	6/07/2023	GEN	15			99015526	
PM166	XQ33UH	00058202	24/07/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00058202	24/07/2023	DEFECT					
PM166	XQ33UH	00058202	24/07/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00058202	24/07/2023	DEFECT		Reported Defect :-Defect Code : 00009557			
PM166	XQ33UH	00058202	24/07/2023	GEN		Defect Reference : 17172 Date : 24/07/2023 Description c			
						PLEASE CLEAN/REPLACE INTERIOR CAB FILTER			
						LABOUR APPRENF			
					00				
PM166	XQ33UH	00058202	24/07/2023	GEN		REPAIR COMPLETED. REPLACED CABIN FILTER.			
PM166	XQ33UH	00058202	24/07/2023	GEN	16			CON	YAT
PM166	XQ33UH	00058202	24/07/2023	GEN	06			TRPCAF0001	YAT
PM166	XQ33UH	00058301	25/07/2023	CUMAE5	01	LABOUR MECH			
PM166	XQ33UH	00058301	25/07/2023	CUMAE5		SERVICE COMPLETED.			
PM166	XQ33UH	00058301	25/07/2023	CUMBE5	00	LABOUR MECH 3			
PM166	XQ33UH	00058301	25/07/2023	CUMBE5		SERVICE COMPLETED.			
PM166	XQ33UH	00058301	25/07/2023	CUMBE5	00	LABOUR APPREN			
PM166	XQ33UH	00058301	25/07/2023	CUMBE5	16			CON	YAT
PM166	XQ33UH	00058301	25/07/2023	CUMBE5	06			MK13584	YAT
PM166	XQ33UH	00058301	25/07/2023	CUMBE5	06			FS19764	YAT
PM166	XQ33UH	00058301	25/07/2023	CUMBE5	06			AF1969M	YAT
PM166	XQ33UH	00058301	25/07/2023	CUMBE5	40			3413005	YAT
PM166	XQ33UH	00058301	25/07/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00058301	25/07/2023	DEFECT					

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00058301	25/07/2023	DEFECT		DEFECT	CLEARED.		
PM166	XQ33UH	00058603	25/07/2023	GEN	13			WINSCR	
PM166	XQ33UH	00058603	25/07/2023	GEN	13			WINSCR	
PM166	XQ33UH	00058764	10/08/2023	CUMAE5	01	LABOUR MECH 3			
PM166	XQ33UH	00058764	10/08/2023	CUMAE5		SERVICE COMPLETED BY MATT & FLYNN ON 09/08/2			
						ADBLUE FLUSH CARRIED OUT - DASH WARNING LAMP EXTI			
PM166	XQ33UH	00058764	10/08/2023	CUMAE5	00	LABOUR APPRENF			
PM166	XQ33UH	00058764	10/08/2023	CUMAE5	16			CON	YAT
PM166	XQ33UH	00058764	10/08/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00058764	10/08/2023	DEFECT					
PM166	XQ33UH	00058764	10/08/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00059104	21/08/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00059104	21/08/2023	DEFECT					
PM166	XQ33UH	00059104	21/08/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00059104	21/08/2023	DEFECT		Reported Defect :-			
						Defect Code : 00009737 Defect Reference : XQ33UH Date : 20/08			
						DRIVERS SEAT BROKEN. MAIN AIR SUPPLY LINE SNAPPED			
						REPAIR COMPLETED BY NICK ON 21/08/2023.			
PM166	XQ33UH	00059104	21/08/2023	GEN	39	REPLAIRED SEAT AIR LINE, REPLACED BROKEN AIR 1			
PM166	XQ33UH	00059104	21/08/2023	GEN		REPAIR COMPLETED BY NICK ON 21/08/2023.			
PM166	XQ33UH	00059104	21/08/2023	GEN	16	REPLAIRED SEAT AIR LINE, REPLACED BROKEN AIR CON YAT			
PM166	XQ33UH	00059104	21/08/2023	GEN	16			CON	YAT
PM166	XQ33UH	00059394	28/08/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00059394	28/08/2023	DEFECT					
PM166	XQ33UH	00059394	28/08/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00059394	28/08/2023	GEN	39	LABOUR MECH 3			

PM166	XQ33UH	00059394	28/08/2023	GEN		REPAIR COMPLETED BY MATT ON 28/08/2023.			
						REMOVE WHEEL, BRAKES & HUB. CLEAN, INSPECT, REASS			
PM166	XQ33UH	00059394	28/08/2023	GEN	16			CON	YAT
PM166	XQ33UH	00059394	28/08/2023	GEN	12			43764	YAT
PM166	XQ33UH	00059394	28/08/2023	GEN	12			453795	YAT
PM166	XQ33UH	00059352	30/08/2023	CUMAE5	01	LABOUR MECH 3			
PM166	XQ33UH	00059352	30/08/2023	CUMAE5		SERVICE COMPLETED BY MATT, TYLER & JOE ON 28			
						TOPPED UP ENGINE OIL			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00059352	30/08/2023	CUMAE5	00	LABOUR	APPREN		
PM166	XQ33UH	00059352	30/08/2023	CUMAE5	00	LABOUR	APPRENJ		
PM166	XQ33UH	00059352	30/08/2023	CUMAE5	40			3413005	YAT
PM166	XQ33UH	00059352	30/08/2023	CUMAE5	16			CON	YAT
PM166	XQ33UH	00059352	30/08/2023	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00059352	30/08/2023	DEFECT					
PM166	XQ33UH	00059352	30/08/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00059352	30/08/2023	DEFECT		Reported Defect :-Defect Code : 00009795			
PM166	XQ33UH	00059599	31/08/2023	WEICAL		Defect Reference : 07110 Date : 28/08/2023 Description c A SERVICE REQUIRED. AIR GAUGE:15580			
						ADJUSTED:15580 WEIGHBRIDGE:15880			
PM166	XQ33UH	00059509	4/09/2023	DEFECT	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY MECH			
PM166	XQ33UH	00059509	4/09/2023	DEFECT					
PM166	XQ33UH	00059509	4/09/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00059509	4/09/2023	DEFECT		Reported Defect :-Defect Code : 00009841 Defect Reference : 07103 Date : 03/09/2023 Description c AIR SCOOP REQUIRES REPLACING			
PM166	XQ33UH	00059509	4/09/2023	DEFECT		DEFECT CLEARED 04/09/2023 REPLACED AIR SCOOI Reported Defect :-			
						Defect Code : 00009842 Defect Reference : 07105 Date : Description of Defect : ICEPAK LEAKING OIL WHILST RUNNING.			
PM166	XQ33UH	00059509	4/09/2023	GEN	39	DEFECT CLEARED 04/09/2023 FITTED NEW PRESSURE SWITCH ON SLEEPER AIR L 1			
PM166	XQ33UH	00059509	4/09/2023	GEN		REPAIR COMPLETED BY NICK ON 04/09/2023.			
PM166	XQ33UH	00059509	4/09/2023	GEN	16	REPLACED AIR SCOOP. FITTED NEW PRESSURE SWITCH ON SLEEPER AIR CON YAT			
PM166	XQ33UH	00059509	4/09/2023	GEN	16			CON	YAT
PM166	XQ33UH	00059509	4/09/2023	GEN	16			CON	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00059762	5/09/2023	WEICAL		AIR GAUGE: 15300 ADJUSTED: 15000 WEIGHBRIDGE: 15300			
PM166	XQ33UH	00059765	6/09/2023	WEICAL		AIR GAUGE CALIBRATION COMPLETED CORRECTLY 16230			
						ADJUSTED: 16530 WEIGHBRIDGE: 16230			
PM166	XQ33UH	00060088	11/09/2023	DEFECT	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY LABOUR MECH			

PM166	XQ33UH	00060088	11/09/2023	DEFECT					
PM166	XQ33UH	00060088	11/09/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00060088	11/09/2023	DEFECT		Reported Defect :-			
						Defect Code : 00009959 Defect Reference : 07104 Date : 31/08/2 REFERENCE TO RP75A/B CHECK FRONT LIGHT PLUG. BRAKE LIGHTS STAY ON WHEI			
PM166	XQ33UH	00060088	11/09/2023	DEFECT		DEFECT CLEARED BY MICK ON 11/09/2023 FAULT WITH PM166 ELECTRICAL LEAD FIXED Reported Defect :-Defect Code : 00009960 Defect Reference : 07112 Date : 10/09/2023 Description c RP137A/B BRAKE LIGHTS STAY ON WHEN LIGHTS ON.			
PM166	XQ33UH	00060088	11/09/2023	GEN	39	DEFECT CLEARED BY MICK ON 11/09/2023 FAULT WI FIXED LABOUR MECH			
PM166	XQ33UH	00060088	11/09/2023	GEN		REPAIR COMPLETED BY MICK & JOE ON 11/09/2023. (			
PM166	XQ33UH	00060088	11/09/2023	GEN	00	ELECTRICAL LEAD LABOUR APPRENJ			
PM166	XQ33UH	00060088	11/09/2023	GEN	31			82506	YAT
PM166	XQ33UH	00059785	13/09/2023	CUMAE5	01	LABOUR MECH 1			
PM166	XQ33UH	00059785	13/09/2023	CUMAE5		SERVICE COMPLETED BY NICK & FLYNN ON 11/09/20			
PM166	XQ33UH	00059785	13/09/2023	CUMAE5	00	ADJUSTED CLUTCH LABOUR APPRENF			
PM166	XQ33UH	00059785	13/09/2023	CUMAE5	16			CON	YAT
PM166	XQ33UH	00059785	13/09/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00059808	13/09/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00059785	13/09/2023	DEFECT					

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00059808	13/09/2023	DEFECT					
PM166	XQ33UH	00059785	13/09/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00059808	13/09/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00059785	13/09/2023	DEFECT		Reported Defect :-Defect Code : 00009889 Defect Refer Description of Defect : 'A' SERVICE DUE CHECK CLUTCH ADJUSTMENT			
						DEFECT CLEARED 11/09/2023 BY NICK - WORKSHOP ADJUSTED CLUTCH LABOUR MECH 1			
PM166	XQ33UH	00059808	13/09/2023	ECO	01				
PM166	XQ33UH	00059808	13/09/2023	ECO		SERVICE COMPLETED BY NICK ON 11/09/2023.			
PM166	XQ33UH	00059808	13/09/2023	ECO	16			CON	YAT
PM166	XQ33UH	00059808	13/09/2023	ECO	40			3413005	YAT
PM166	XQ33UH	00059808	13/09/2023	ECO	06			ED2175254-S	YAT
PM166	XQ33UH	00060090	20/09/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00060090	20/09/2023	DEFECT					
PM166	XQ33UH	00060090	20/09/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00060090	20/09/2023	GEN	39	LABOUR MECH 3			
PM166	XQ33UH	00060090	20/09/2023	GEN		REPAIR COMPLETED BY MATT & JOE ON 20/09/2023.			
						FLUSHED AD BLUE SYSTEM AND REMOVED WARNING LAM			
PM166	XQ33UH	00060090	20/09/2023	GEN	00	LABOUR APPRENJ			
PM166	XQ33UH	00060090	20/09/2023	GEN	16			CON	YAT
PM166	XQ33UH	00060090	20/09/2023	GEN	16			COOLANT	YAT
PM166	XQ33UH	00060437	20/09/2023	WEICAL		AIR GAUGE: 14700 ADJUSTED: 14480 WEIGHBRIDGE: 14780			
PM166	XQ33UH	00060153	25/09/2023	CUMAE5	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY			

PM166	XQ33UH	00060153	25/09/2023	CUMAE5		SERVICE COMPLETED.			
PM166	XQ33UH	00060153	25/09/2023	CUMBE5	01	LABOUR APPRENB			
PM166	XQ33UH	00060153	25/09/2023	CUMBE5		SERVICE COMPLETED BY BEN, JOE & TYLER ON 25/(			
PM166	XQ33UH	00060153	25/09/2023	CUMBE5	00	WINDSCREEN HAS BEEN REPAIRED. LABOUR APPR			
PM166	XQ33UH	00060153	25/09/2023	CUMBE5	00	LABOUR APPREN			
PM166	XQ33UH	00060153	25/09/2023	CUMBE5	16			CON	YAT
PM166	XQ33UH	00060153	25/09/2023	CUMBE5	06			MK13584	YAT
PM166	XQ33UH	00060153	25/09/2023	CUMBE5	40			3413005	YAT
PM166	XQ33UH	00060153	25/09/2023	DEFECT	01	LABOUR MECH			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00060153	25/09/2023	DEFECT					
PM166	XQ33UH	00060153	25/09/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00060153	25/09/2023	DEFECT		Reported Defect :-			
						Defect Code : 00009266 Defect Reference : PM166 Date : 25/05/2			
						DRIVERS SIDE SCREEN HAS A CRACK THAT NEEDS REPAIF			
						DEFECT CLEARED 25/09/2023			
						WINDSCREEN HAS BEEN REPAIRED			
PM166	XQ33UH	00060209	26/09/2023	GEN	15			33000085	
PM166	XQ33UH	00060209	26/09/2023	GEN	15			33000118	
PM166	XQ33UH	00060209	26/09/2023	GEN	15			33000540	
PM166	XQ33UH	00060209	26/09/2023	GEN	15			33000540	
PM166	XQ33UH	00060209	26/09/2023	GEN	15			33000118	
PM166	XQ33UH	00060209	26/09/2023	GEN	15			33000085	
PM166	XQ33UH	00060487	26/09/2023	WEICAL		AIR GAUGE: 16000			
						ADJUSTED: 16000			
						WEIGHBRIDGE: 15640			
						AIR GAUGE CALIBRATION COMPLETED CORRECTLY			
PM166	XQ33UH	00060903	18/10/2023	CUMAE5	01	LABOUR MECH 3			
PM166	XQ33UH	00060903	18/10/2023	CUMAE5		SERVICE COMPLETED BY MATT, TYLER AND JOSEPI			
						CHECKED ALL BUSHES, SPRINGS AND SHOCKS FOR WEAR			
						FAULT			
						CLUTCH ADJUST			
						CHECKED OIL NESTING AT DIRVERS HUB CAP			
PM166	XQ33UH	00060903	18/10/2023	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00060903	18/10/2023	CUMAE5	00	LABOUR APPRENJ			
PM166	XQ33UH	00060903	18/10/2023	CUMAE5	16			CON	YAT
PM166	XQ33UH	00060903	18/10/2023	CUMAE5	40			3413005	YAT
PM166	XQ33UH	00060903	18/10/2023	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00060903	18/10/2023	DEFECT					
PM166	XQ33UH	00060903	18/10/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00060903	18/10/2023	DEFECT		Reported Defect :-			
						Defect Code : 00010138 Defect Reference : 42419 Date :			
						LHS THUD WHEN HIT BUMPS. BUSHES ON SHOCKEI			
						DEFECT CLEARED 18/10/2023			
						CHECKED ITEMS THAT COULD INDUCE NOISE, NOTH			
						APPRENF			
PM166	XQ33UH	00061232	27/10/2023	CUMAE5	01				
PM166	XQ33UH	00061232	27/10/2023	CUMAE5		SERVICE COMPLETED BY FLYNN ON 27/10/2023.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00061232	27/10/2023	CUMAE5	16			CON	YAT
PM166	XQ33UH	00061770	10/11/2023	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00061770	10/11/2023	DEFECT					
PM166	XQ33UH	00061770	10/11/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00061770	10/11/2023	DEFECT		Reported Defect :-			

						Defect Code : 00010250 Defect Reference : 07116 Date : AD BLUE TANK NOT BREATHING (SUCKING IN). PLAC				
						DEFECT CLEARED ON 10/11/2023.				
PM166	XQ33UH	00061770	10/11/2023	GEN	39	REMOVED AD BLUE STEM AND UNBLOCKED BREATI LABOUR MECH				
PM166	XQ33UH	00061770	10/11/2023	GEN		REPAIR COMPLETED BY MICK ON 10/11/2023.				
PM166	XQ33UH	00061770	10/11/2023	GEN	16	REMOVED AD BLUE STEM AND UNBLOCKED BREATI				
						CON	YAT			(
PM166	XQ33UH	00070555	13/11/2023	WEICAL		CALIBRATED BY NATHAN BENNETT 13/11/2023				
						AIR GAUGE:				
						ADJUSTED:				
						WEIGHBRIDGE:				
						AIR GAUGE CALIBRATION COMPLETED CORRECTLY				
PM166	XQ33UH	00062013	15/11/2023	GEN	39	0A5801F1F1A0A	EMAX01	EX00031466	58(	
PM166	XQ33UH	00062013	15/11/2023	GEN	39			AW-IVU-TRANS		
PM166	XQ33UH	00062013	15/11/2023	GEN	39			AW-BYPASS-12		
PM166	XQ33UH	00062013	15/11/2023	GEN	39		AW-AIR-KW		EMAX(	
PM166	XQ33UH	00062013	15/11/2023	GEN	39		AWIMM TRUCK		EMAX0	
PM166	XQ33UH	00062013	15/11/2023	GEN	39		AWIMM TRUCK		EMAX0	
PM166	XQ33UH	00062013	15/11/2023	GEN	39		AW-AIR-KW		EMAX(	
PM166	XQ33UH	00062013	15/11/2023	GEN	39			AW-BYPASS-12		
PM166	XQ33UH	00062013	15/11/2023	GEN	39			AW-IVU-TRANS		
PM166	XQ33UH	00062013	15/11/2023	GEN	39	0A5801F1F1A0A	EMAX01	7130344	58(	
PM166	XQ33UH	00062165	24/11/2023	CUMAE5	01	CONTROL, LABOUR APPRENB				
PM166	XQ33UH	00062165	24/11/2023	CUMAE5		SERVICE COMPLETED BY MATT, BEN & TYLER ON 2				
PM166	XQ33UH	00062165	24/11/2023	CUMAE5	00	LABOUR APPREN				
PM166	XQ33UH	00062165	24/11/2023	CUMAE5	00	LABOUR MECH 3				
PM166	XQ33UH	00062165	24/11/2023	CUMAE5	16		CON	YAT		
PM166	XQ33UH	00062167	24/11/2023	CUMCE5	01	LABOUR APPRENB				
PM166	XQ33UH	00062167	24/11/2023	CUMCE5		SERVICE COMPLETED BY BEN & TYLER ON 24/11/20				
PM166	XQ33UH	00062167	24/11/2023	CUMCE5	00	LABOUR APPREN				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00062167	24/11/2023	CUMCE5	16			CON	YAT
PM166	XQ33UH	00062167	24/11/2023	CUMCE5	06			T224P	YAT
PM166	XQ33UH	00062167	24/11/2023	CUMCE5	06			WF2126	YAT
PM166	XQ33UH	00062167	24/11/2023	CUMCE5	06			LF637	YAT
PM166	XQ33UH	00062167	24/11/2023	CUMCE5	06			TRPCAF0001	YAT
PM166	XQ33UH	00062167	24/11/2023	CUMCE5	06			17237	YAT
PM166	XQ33UH	00062167	24/11/2023	CUMCE5	06			A-3380W1687	YAT
PM166	XQ33UH	00062167	24/11/2023	CUMCE5	40			3372765	YAT
PM166	XQ33UH	00062167	24/11/2023	CUMCE5	40			3334800	YAT
PM166	XQ33UH	00062167	24/11/2023	CUMCE5	06			UF110	YAT
PM166	XQ33UH	00062165	24/11/2023	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00062166	24/11/2023	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00062167	24/11/2023	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00062165	24/11/2023	DEFECT					
PM166	XQ33UH	00062166	24/11/2023	DEFECT					
PM166	XQ33UH	00062167	24/11/2023	DEFECT					
PM166	XQ33UH	00062165	24/11/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00062166	24/11/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00062167	24/11/2023	DEFECT		DEFECT CLEARED 24/11/2023.			
PM166	XQ33UH	00062167	24/11/2023	DEFECT		Reported Defect :-			
						Defect Code : 00010344			
						Defect Reference : 07117 Date : 23/11/2023 Description of Defect			
						RIGHT STEER WHEEL SEAL WEEPING			

PM166	XQ33UH	00062166	24/11/2023	ECO	01	DEFECT CLEARED 24/11/2023 LABOUR APPRENJ			
PM166	XQ33UH	00062166	24/11/2023	ECO		SERVICE COMPLETED BY JOE ON			24/11/202
PM166	XQ33UH	00062166	24/11/2023	ECO	16			CON	YAT
PM166	XQ33UH	00062166	24/11/2023	ECO	06			0037301210	YAT
PM166	XQ33UH	00062166	24/11/2023	ECO	06			FS1251	YAT
PM166	XQ33UH	00062166	24/11/2023	ECO	06			0021751550	YAT
PM166	XQ33UH	00062166	24/11/2023	ECO	06			ED2175254-S	YAT
PM166	XQ33UH	00062166	24/11/2023	ECO	40			10W50	YAT
PM166	XQ33UH	00062166	24/11/2023	ECO	16			BS358N70	YAT
PM166	XQ33UH	00062168	24/11/2023	EXOINS	01	LABOUR APPRENB			
PM166	XQ33UH	00062168	24/11/2023	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECT			
PM166	XQ33UH	00062168	24/11/2023	EXOINS	00	INSPECTION COMPLETED BY BEN & TYLER ON 24/11 LABOUR APPREN			
PM166	XQ33UH	00062276	27/11/2023	GEN	15			99015526	I

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00062276	27/11/2023	GEN	15			33000084	
PM166	XQ33UH	00062276	27/11/2023	GEN	15			33000524	
PM166	XQ33UH	00062276	27/11/2023	GEN	15			33000524	
PM166	XQ33UH	00062276	27/11/2023	GEN	15			33000084	
PM166	XQ33UH	00062276	27/11/2023	GEN	15			99015526	
PM166	XQ33UH	00062420	29/11/2023	GEN	39			LAB	
PM166	XQ33UH	00062532	29/11/2023	GEN	39			LABEXT	
PM166	XQ33UH	00062540	29/11/2023	GEN	39			LABEXT	
PM166	XQ33UH	00062420	29/11/2023	GEN	39			CON	
PM166	XQ33UH	00062532	29/11/2023	GEN	16			CON	
PM166	XQ33UH	00062540	29/11/2023	GEN	39			CON	
PM166	XQ33UH	00062420	29/11/2023	GEN	39			LAB	
PM166	XQ33UH	00062532	29/11/2023	GEN	16			CON	
PM166	XQ33UH	00062540	29/11/2023	GEN	39			CON	
PM166	XQ33UH	00062420	29/11/2023	GEN	39			CON	
PM166	XQ33UH	00062532	29/11/2023	GEN	39			LABEXT	
PM166	XQ33UH	00062540	29/11/2023	GEN	39			LABEXT	
PM166	XQ33UH	00062525	6/12/2023	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00062525	6/12/2023	DEFECT					
PM166	XQ33UH	00062525	6/12/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00062525	6/12/2023	DEFECT		Reported Defect :- Defect Code : 00010429 Defect Reference : 50915 Date : 05/12/2023 Description of Defect RED AIR LINE FOR TRAILERS HAS A LEAK. SPLIT IN HOSE N			
PM166	XQ33UH	00062525	6/12/2023	GEN	39	DEFECT CLEARED 06/12/2023 REPLACED SUZI COIL LABOUR APPRENJ			
PM166	XQ33UH	00062525	6/12/2023	GEN		REPAIR COMPLETED BY JOE ON 06/12/2023. REPLAC			
PM166	XQ33UH	00062525	6/12/2023	GEN	16	CON	YAT		
PM166	XQ33UH	00062525	6/12/2023	GEN	31			61-SC3MTLTSE	YAT
PM166	XQ33UH	00063053	20/12/2023	CUMAE5	01	LABOUR MECH			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00063053	20/12/2023	CUMAE5		SERVICE COMPLETED.			
PM166	XQ33UH	00063053	20/12/2023	CUMBE5	01	LABOUR MECH 3			

PM166	XQ33UH	00063053	20/12/2023	CUMBE5		SERVICE COMPLETED BY MATT, AARON, TYLER & JC			
PM166	XQ33UH	00063053	20/12/2023	CUMBE5	00	REMOVE & FIT NEW LOAD LAMP AT DRIVERS SIDE W SERVICE LABOUR MECH 4			
PM166	XQ33UH	00063053	20/12/2023	CUMBE5	00	LABOUR APPREN			
PM166	XQ33UH	00063053	20/12/2023	CUMBE5	00	LABOUR APPRENJ			
PM166	XQ33UH	00063053	20/12/2023	CUMBE5	16			CON	YAT
PM166	XQ33UH	00063053	20/12/2023	CUMBE5	06			MK13584	YAT
PM166	XQ33UH	00063053	20/12/2023	CUMBE5	14			PART	YAT
PM166	XQ33UH	00063053	20/12/2023	CUMBE5	40			3413005	YAT
PM166	XQ33UH	00063053	20/12/2023	CUMBE5	13			MX1-7S	YAT
PM166	XQ33UH	00063108	21/12/2023	GEN	39			LABEXT	
PM166	XQ33UH	00063108	21/12/2023	GEN	39			PART	
PM166	XQ33UH	00063108	21/12/2023	GEN	39			PART	
PM166	XQ33UH	00063108	21/12/2023	GEN	39			LABEXT	
PM166	XQ33UH	00063154	27/12/2023	DEFECT	01				
PM166	XQ33UH	00063154	27/12/2023	DEFECT		LABOUR MECH			
PM166	XQ33UH	00063154	27/12/2023	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00063154	27/12/2023	DEFECT		Reported Defect :- Defect Code : 00010560 Defect Reference : 07118 Date : WEATHER SHIELD DRIVER'S SIDE NEEDS REPLACEI RP30A, RP22 NO SIDE MARKER LIGHTS, HAS TAIL LIC			
PM166	XQ33UH	00063154	27/12/2023	GEN	39	DEFECT CLEARED 27/12/2023 REPLACED WEATHERSHIELD DRIVERS SIDE LABOUR MECH 4			
PM166	XQ33UH	00063154	27/12/2023	GEN		REPAIR COMPLETED BY AARON ON 27/12/2023. REP			
PM166	XQ33UH	00063154	27/12/2023	GEN	16	DEFECT NO. 00010560 CLEARED CON YAT			(
PM166	XQ33UH	00063154	27/12/2023	GEN	13			D104R	YAT
PM166	XQ33UH	00063110	28/12/2023	GEN	39			D104R	
PM166	XQ33UH	00063110	28/12/2023	GEN	39			D104R	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00063455	11/01/2024	CUMAE5	01	LABOUR APPRENB			
PM166	XQ33UH	00063455	11/01/2024	CUMAE5		SERVICE COMPLETED BY BEN & JOE ON 11/01/2024.			
PM166	XQ33UH	00063455	11/01/2024	CUMAE5	00	LABOUR APPRENJ			
PM166	XQ33UH	00063455	11/01/2024	CUMAE5	16			CON	YAT
PM166	XQ33UH	00064165	31/01/2024	CUMAE5	01	LABOUR APPRENJ			
PM166	XQ33UH	00064165	31/01/2024	CUMAE5		SERVICE COMPLETED BY JOE & BEN ON 31/01/2024. WIPER BLADES			
PM166	XQ33UH	00064165	31/01/2024	CUMAE5	00	NOTED: * ALL REAR BRACKS ALMOST READY FOR RELINE. DEFECT LABOUR APPRENB			
PM166	XQ33UH	00064165	31/01/2024	CUMAE5	16			CON	YAT
PM166	XQ33UH	00064539	13/02/2024	GEN	14			NGP95D31R	
PM166	XQ33UH	00064813	13/02/2024	GEN	39			LABEXT	
PM166	XQ33UH	00064816	13/02/2024	GEN	39			LABEXT	
PM166	XQ33UH	00064539	13/02/2024	GEN	39			LABEXT	
PM166	XQ33UH	00064813	13/02/2024	GEN	14			BATTERY	
PM166	XQ33UH	00064816	13/02/2024	GEN	14			BATTERY	
PM166	XQ33UH	00064539	13/02/2024	GEN	39			LABEXT	

PM166	XQ33UH	00064813	13/02/2024	GEN	39			LABEXT	
PM166	XQ33UH	00064816	13/02/2024	GEN	39			LABEXT	
PM166	XQ33UH	00064539	13/02/2024	GEN	14			NGP95D31R	
PM166	XQ33UH	00064813	13/02/2024	GEN	14			BATTERY	
PM166	XQ33UH	00064816	13/02/2024	GEN	14			BATTERY	
PM166	XQ33UH	00064668	15/02/2024	CUMAE5	01	LABOUR APPRENB			
PM166	XQ33UH	00064668	15/02/2024	CUMAE5		SERVICE COMPLETED BY BEN ON 15/02/2024.			
						NOTED: * WILL NEED BRAKE RELINE WHEN 'B' SERVICE DONE. DEFI * NHVR STICKER NEEDS REPLACING, PLEASE ORDER ONE. * WRITE DATE ON BATTERIES WHEN 'B' SERVICE IS DONE.			
PM166	XQ33UH	00064668	15/02/2024	CUMAE5	16			CON	YAT
PM166	XQ33UH	00064668	15/02/2024	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00064668	15/02/2024	DEFECT					
PM166	XQ33UH	00064668	15/02/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00065071	29/02/2024	CUMAE5	01	LABOUR MECH			
PM166	XQ33UH	00065071	29/02/2024	CUMAE5		SERVICE COMPLETED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00065071	29/02/2024	CUMBE5	01	LABOUR MECH 1			
PM166	XQ33UH	00065071	29/02/2024	CUMBE5		'B' SERVICE COMPLETED BY NICK & ETHAN ON 29/02 BATTERIES			
PM166	XQ33UH	00065071	29/02/2024	CUMBE5	00	NOTED: * BRAKES NEED RELINE ASAP. DEFECT NO. 0001099			
PM166	XQ33UH	00065071	29/02/2024	CUMBE5	16			CON	YAT
PM166	XQ33UH	00065071	29/02/2024	CUMBE5	06			MK13584	YAT
PM166	XQ33UH	00065071	29/02/2024	CUMBE5	40			3413005	YAT
PM166	XQ33UH	00065071	29/02/2024	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00065071	29/02/2024	DEFECT					
PM166	XQ33UH	00065071	29/02/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00065071	29/02/2024	DEFECT		Reported Defect :- Defect Code : 00010938 Defect Reference : PM166 Date Defect : WRITE DATE ON BATTERIES WHEN 'B' SERVICE IS D			
						DEFECT CLEARED27/02/2024			
PM166	XQ33UH	00065563	20/03/2024	GEN	15			99015526	
PM166	XQ33UH	00065563	20/03/2024	GEN	15			33000084	
PM166	XQ33UH	00065563	20/03/2024	GEN	15			33000517	
PM166	XQ33UH	00065563	20/03/2024	GEN	15			99015526	
PM166	XQ33UH	00065563	20/03/2024	GEN	15			33000084	
PM166	XQ33UH	00065563	20/03/2024	GEN	15			33000517	
PM166	XQ33UH	00065926	27/03/2024	CUMAE5	01	LABOUR MECH			
PM166	XQ33UH	00065926	27/03/2024	CUMAE5		'A' SERVICE COMPLETED BY RED'S TRUCK & TRAILEI			
						CARRIED OUT 'A' SERVICE. * BRAKES NEED REPLACING *. DEFECTS ALREADY CI * FIRE EXTINGUISHER EXPIRY DATE - NOV 2023. DEFI			
PM166	XQ33UH	00065926	27/03/2024	CUMAE5	01			LABEXT	
PM166	XQ33UH	00065926	27/03/2024	CUMAE5	40			3413005	
PM166	XQ33UH	00065926	27/03/2024	CUMAE5	01			LABEXT	
PM166	XQ33UH	00065926	27/03/2024	CUMAE5	40			3413005	
PM166	XQ33UH	00065926	27/03/2024	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00065926	27/03/2024	DEFECT					
PM166	XQ33UH	00065926	27/03/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00066038	2/04/2024	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00066038	2/04/2024	DEFECT					
PM166	XQ33UH	00066038	2/04/2024	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code

PM166	XQ33UH	00066038	2/04/2024	DEFECT		Reported Defect :-Defect Code : 00010936 Defect Reference : PM166 Date : 15/02/2024 Description WILL NEED BRAKE RELINE WHEN 'B' SERVICE DONE				
PM166	XQ33UH	00066038	2/04/2024	DEFECT		DEFECT CLEARED ON 02/04/2024 ALL DRIVE BRAKES REPLACED AND READJUSTED Reported Defect :- Defect Code : 00010997 Defect Reference : PM166 Date Description of Defect : BRAKES NEED RELINE ASAP				
PM166	XQ33UH	00066038	2/04/2024	DEFECT		DEFECT CLEARED ON 02/04/2024 ALL DRIVE BRAKES REPLACED AND READJUSTED Reported Defect :- Defect Code : 00010803 Defect Reference : PM166 Date Description of Defect : ALL REAR BRACKS ALMOST READY FOR RELINE.				
PM166	XQ33UH	00066038	2/04/2024	GEN	39	DEFECT CLEARED ON 02/04/2024 ALL DRIVE BRAKES REPLACED AND READJUSTED L 1				
PM166	XQ33UH	00066038	2/04/2024	GEN		REPAIR COMPLETED BY NICK & JOSEPH ON 02/04/2(				
PM166	XQ33UH	00066038	2/04/2024	GEN		ALL DRIVE BRAKES AND READJUSTED THEM LOCK- GRILL BOLTS LABOUR APPRENJ				
					00					
PM166	XQ33UH	00066038	2/04/2024	GEN	16			CON	YAT	
PM166	XQ33UH	00066038	2/04/2024	GEN	02			KSMA2124707Q	YAT	
PM166	XQ33UH	00066123	9/04/2024	GEN	15			11003134		
PM166	XQ33UH	00066123	9/04/2024	GEN	15			77000232		
PM166	XQ33UH	00066123	9/04/2024	GEN	15			33000084		
PM166	XQ33UH	00066123	9/04/2024	GEN	15			33000370		
PM166	XQ33UH	00066123	9/04/2024	GEN	15			33000517		
PM166	XQ33UH	00066123	9/04/2024	GEN	15			33000518		
PM166	XQ33UH	00066123	9/04/2024	GEN	15			33000118		
PM166	XQ33UH	00066123	9/04/2024	GEN	15			11003134		
PM166	XQ33UH	00066123	9/04/2024	GEN	15			77000232		
PM166	XQ33UH	00066123	9/04/2024	GEN	15			33000084		
PM166	XQ33UH	00066123	9/04/2024	GEN	15			33000370		
PM166	XQ33UH	00066123	9/04/2024	GEN	15			33000517		
PM166	XQ33UH	00066123	9/04/2024	GEN	15			33000518		

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00066123	9/04/2024	GEN	15			33000118	
PM166	XQ33UH	00066328	10/04/2024	CUMAE5	01	LABOUR MECH 1			
PM166	XQ33UH	00066328	10/04/2024	CUMAE5		'A' SERVICE COMPLETED BY NICK, JOSEPH & TYLER			
PM166	XQ33UH	00066328	10/04/2024	CUMAE5	00	BOLTS IN FRONT GRILL REPLACED OIL FILTER REPLACED LOCKING CORD ON TURN TABLE FIRE/E LABOUR APPRENJ			
PM166	XQ33UH	00066328	10/04/2024	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00066328	10/04/2024	CUMAE5	16			CON	YAT
PM166	XQ33UH	00066328	10/04/2024	CUMAE5	06			LF14000NN	YAT
PM166	XQ33UH	00066328	10/04/2024	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00066328	10/04/2024	DEFECT					
PM166	XQ33UH	00066328	10/04/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00066328	10/04/2024	DEFECT		Reported Defect :- Defect Code : 00011178 Defect Reference : PM166 Date : : Description of Defect : REPLACE FIRE EXTINGUISHER. FIRE EXTINGUISHER EXPIRY DATE NOVEMBER 2023			
						DEFECT CLEARED ON 10/04/2024			

PM166	XQ33UH	00066519	19/04/2024	GEN	15			11006520	
PM166	XQ33UH	00066519	19/04/2024	GEN	15			77000194	
PM166	XQ33UH	00066519	19/04/2024	GEN	15			33000084	
PM166	XQ33UH	00066519	19/04/2024	GEN	15			33000517	
PM166	XQ33UH	00066519	19/04/2024	GEN	15			33000118	
PM166	XQ33UH	00066519	19/04/2024	GEN	15			11006520	
PM166	XQ33UH	00066519	19/04/2024	GEN	15			77000194	
PM166	XQ33UH	00066519	19/04/2024	GEN	15			33000084	
PM166	XQ33UH	00066519	19/04/2024	GEN	15			33000517	
PM166	XQ33UH	00066519	19/04/2024	GEN	15			33000118	
PM166	XQ33UH	00066640	24/04/2024	GEN	15			99015526	
PM166	XQ33UH	00066640	24/04/2024	GEN	15			33000084	
PM166	XQ33UH	00066640	24/04/2024	GEN	15			33000370	
PM166	XQ33UH	00066640	24/04/2024	GEN	15			33000518	
PM166	XQ33UH	00066640	24/04/2024	GEN	15			33000115	
PM166	XQ33UH	00066640	24/04/2024	GEN	15			99015526	
PM166	XQ33UH	00066640	24/04/2024	GEN	15			33000084	
PM166	XQ33UH	00066640	24/04/2024	GEN	15			33000370	
PM166	XQ33UH	00066640	24/04/2024	GEN	15			33000518	
PM166	XQ33UH	00066640	24/04/2024	GEN	15			33000115	
PM166	XQ33UH	00066716	29/04/2024	GEN	15			99015526	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00066716	29/04/2024	GEN	15			33000084	
PM166	XQ33UH	00066716	29/04/2024	GEN	15			33000370	
PM166	XQ33UH	00066716	29/04/2024	GEN	15			33000518	
PM166	XQ33UH	00066716	29/04/2024	GEN	15			33000118	
PM166	XQ33UH	00066716	29/04/2024	GEN	15			99015526	
PM166	XQ33UH	00066716	29/04/2024	GEN	15			33000084	
PM166	XQ33UH	00066716	29/04/2024	GEN	15			33000370	
PM166	XQ33UH	00066716	29/04/2024	GEN	15			33000518	
PM166	XQ33UH	00066716	29/04/2024	GEN	15			33000118	
PM166	XQ33UH	00066896	4/05/2024	CUMAE5	01	LABOUR MECH 1			
PM166	XQ33UH	00066896	4/05/2024	CUMAE5		'A' SERVICE COMPLETED BY NICK & JOSEPH ON 04/(			
PM166	XQ33UH	00066896	4/05/2024	CUMAE5	00	LOOSE PIN IN PLUG LABOUR APPRENJ			
PM166	XQ33UH	00066896	4/05/2024	CUMAE5	16			CON	YAT
PM166	XQ33UH	00066896	4/05/2024	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00066896	4/05/2024	DEFECT					
PM166	XQ33UH	00066896	4/05/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00067122	16/05/2024	CUMAE5	01	LABOUR MECH			
PM166	XQ33UH	00067122	16/05/2024	CUMAE5		SERVICE COMPLETED.			
PM166	XQ33UH	00067122	16/05/2024	CUMBE5	01	LABOUR MECH 5			
PM166	XQ33UH	00067122	16/05/2024	CUMBE5		'B' SERVICE COMPLETED BY BEN & ETHAN ON 16/05/			
						NOTED: * ELECTRICAL HORNS NEED REPLACING. DEFECT NO. 0001			
PM166	XQ33UH	00067122	16/05/2024	CUMBE5	00	LABOUR MECH 4			
PM166	XQ33UH	00067122	16/05/2024	CUMBE5	16			CON	YAT
PM166	XQ33UH	00067122	16/05/2024	CUMBE5	06			MK13584	YAT
PM166	XQ33UH	00067122	16/05/2024	CUMBE5	40			3413005	YAT
PM166	XQ33UH	00067122	16/05/2024	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00067122	16/05/2024	DEFECT					
PM166	XQ33UH	00067122	16/05/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00068017	10/06/2024	CUMAE5		'A' SERVICE COMPLETED BY RED'S TRUCK & TRAILE			
						CARRIED OUT 'A' SERVICE MECHANIC RECOMMENDATIONS: * REAR AXLE SHOCKIE BUSHES NEED REPLACING.			
PM166	XQ33UH	00068017	10/06/2024	CUMAE5	01			LABEXT	
PM166	XQ33UH	00068017	10/06/2024	CUMAE5	01			LABEXT	
PM166	XQ33UH	00068017	10/06/2024	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00068017	10/06/2024	DEFECT					
PM166	XQ33UH	00068017	10/06/2024	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code

PM166	XQ33UH	00068196	12/06/2024	WEICAL		AIR GAUGE: 12180 ADJUSTED: 12750 WEIGHBRIDGE: 12260
PM166	XQ33UH	00068492	19/06/2024	WEICAL		AIR GAUGE CALIBRATION COMPLETED CORRECTLY ADJUSTED: 14820 WEIGHBRIDGE: 14520
PM166	XQ33UH	00068746	1/07/2024	CUMAE5	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY
PM166	XQ33UH	00068746	1/07/2024	CUMAE5		'A' SERVICE COMPLETED BY TYLER & COREY ON 01/
PM166	XQ33UH	00068746	1/07/2024	CUMAE5	00	REPLACED IN PRIOR SERVICE REPLACED HORN LABOUR MECH 6
PM166	XQ33UH	00068746	1/07/2024	CUMAE5	16	CON YAT
PM166	XQ33UH	00068746	1/07/2024	DEFECT	01	LABOUR MECH
PM166	XQ33UH	00068746	1/07/2024	DEFECT		
PM166	XQ33UH	00068746	1/07/2024	DEFECT		DEFECT CLEARED.
PM166	XQ33UH	00068746	1/07/2024	DEFECT		Reported Defect :-Defect Code : 00010937 Defect Reference : PM166 Date : 15/02/2024 Description NHVR STICKER NEEDS REPLACING, PLEASE ORDEF
PM166	XQ33UH	00068746	1/07/2024	DEFECT		DEFECT CLEARED ON 01/07/2024 NHVR STICKER HAS BEEN REPLACED IN PRIOR SER Reported Defect :- Defect Code : 00011482 Defect Reference : PM166 Date Defect : ELECTRICAL HORNS NEED REPLACING
PM166	XQ33UH	00069095	2/07/2024	WEICAL		DEFECT CLEARED ON 01/07/2024 REPLACED HORN AIR GAUGE: 15000 ADJUSTED: 15620 WEIGHBRIDGE: 15320
PM166	XQ33UH	00069204	16/07/2024	CUMAE5	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY
PM166	XQ33UH	00069204	16/07/2024	CUMAE5		'A' SERVICE COMPLETED BY TYLER, JOSEPH, ETHAN, ALEX &
PM166	XQ33UH	00069204	16/07/2024	CUMAE5	00	LABOUR APPRENJ
PM166	XQ33UH	00069204	16/07/2024	CUMAE5	00	LABOUR MECH 4
PM166	XQ33UH	00069204	16/07/2024	CUMAE5	00	LABOUR APPRENA

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00069204	16/07/2024	CUMAE5	00	LABOUR	MECH 5		
PM166	XQ33UH	00069204	16/07/2024	CUMAE5	16			CON	YAT
PM166	XQ33UH	00069204	16/07/2024	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00069204	16/07/2024	DEFECT					
PM166	XQ33UH	00069204	16/07/2024	DEFECT		DEFECT	CLEARED.		
PM166	XQ33UH	00069807	5/08/2024	TYRES	15			33000096	
PM166	XQ33UH	00069807	5/08/2024	TYRES	15			33000237	
PM166	XQ33UH	00069807	5/08/2024	TYRES	15			33000237	
PM166	XQ33UH	00069807	5/08/2024	TYRES	15			33000096	
PM166	XQ33UH	00069807	5/08/2024	TYRES	15			33000237	
PM166	XQ33UH	00069807	5/08/2024	TYRES	15			33000237	
PM166	XQ33UH	00069793	7/08/2024	CUMAE5	01	LABOUR	MECH		
PM166	XQ33UH	00069793	7/08/2024	CUMAE5		SERVICE	COMPLETED.		
PM166	XQ33UH	00069793	7/08/2024	CUMBE5	01	LABOUR	MECH 5		
PM166	XQ33UH	00069793	7/08/2024	CUMBE5		'B' SERVICE COMPLETED BY BEN, ALEX & JOSEPH (WORKSHC			
PM166	XQ33UH	00069793	7/08/2024	CUMBE5	00	LABOUR APPRENA			
PM166	XQ33UH	00069793	7/08/2024	CUMBE5	00	LABOUR APPRENJ			
PM166	XQ33UH	00069793	7/08/2024	CUMBE5	16			CON	YAT

PM166	XQ33UH	00069793	7/08/2024	CUMBE5	06			MK13584	YAT
PM166	XQ33UH	00069793	7/08/2024	CUMBE5	40			3413005	YAT
PM166	XQ33UH	00069793	7/08/2024	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00069794	7/08/2024	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00069793	7/08/2024	DEFECT					
PM166	XQ33UH	00069794	7/08/2024	DEFECT					
PM166	XQ33UH	00069793	7/08/2024	DEFECT		DEFECT	CLEARED.		
PM166	XQ33UH	00069794	7/08/2024	DEFECT		DEFECT	CLEARED.		
PM166	XQ33UH	00069794	7/08/2024	ECO	01	LABOUR	APPRENA		
PM166	XQ33UH	00069794	7/08/2024	ECO		SLEEPER AIR SERVICE COMPLETED BY ALEX & JOSH (WORKS			
PM166	XQ33UH	00069794	7/08/2024	ECO	00	LABOUR	APPRENJC		
PM166	XQ33UH	00069794	7/08/2024	ECO	16			CON	YAT
PM166	XQ33UH	00069794	7/08/2024	ECO	40			10W50	YAT
PM166	XQ33UH	00069794	7/08/2024	ECO	06			ED2175254-S	YAT
PM166	XQ33UH	00070911	11/09/2024	CUMAE5	01	LABOUR	MECH 6		
PM166	XQ33UH	00070911	11/09/2024	CUMAE5		'A' SERVICE COMPLETED BY COREY (WORKSHOP) C			
						PASSENGER SIDE WHEEL SEAL ON STEER WAS LEAKING A			
						PASSENGER SIDE FUEL TANK STRAPS REPLACED AND BO			
PM166	XQ33UH	00070911	11/09/2024	CUMAE5	16			CON	YAT
PM166	XQ33UH	00070911	11/09/2024	CUMAE5	10			090-2209SP3B	YAT
PM166	XQ33UH	00070911	11/09/2024	CUMAE5	08			43764	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00070911	11/09/2024	CUMAE5	08			1613CR	YAT
PM166	XQ33UH	00070911	11/09/2024	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00070911	11/09/2024	DEFECT					
PM166	XQ33UH	00070911	11/09/2024	DEFECT		DEFECT	CLEARED.		
PM166	XQ33UH	00071897	11/09/2024	GEN	10			090-2209SP3B	
PM166	XQ33UH	00071897	11/09/2024	GEN	16			TS50	
PM166	XQ33UH	00071897	11/09/2024	GEN	16			TS50	
PM166	XQ33UH	00071897	11/09/2024	GEN	10			090-2209SP3B	
PM166	XQ33UH	00072078	28/09/2024	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00072078	28/09/2024	DEFECT					
PM166	XQ33UH	00072078	28/09/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00072078	28/09/2024	GEN		REPAIR COMPLETED BY BROWN & HURLEY BUND/			
						Troubleshoot Hard to Build Air Complaint Receive afterhours callout request from PACCAR reporting vehicl workshop to complete repair; travel out to vehicle roadside; arrive build air; found D2 Governor Valve constantly unloading ; remove in compressor head; fit new D2 Governor Valve to vehicle; run enc return vehicle to service; pack up gear & return to workshop.			
						Technician noted compressor output is average ; recommend repl			
PM166	XQ33UH	00072078	28/09/2024	GEN	39			CALL OUT FEE	
PM166	XQ33UH	00072078	28/09/2024	GEN	39			CALL OUT FEE	
PM166	XQ33UH	00072078	28/09/2024	GEN	03			PART	
PM166	XQ33UH	00072078	28/09/2024	GEN	39			LABEXT	
PM166	XQ33UH	00072078	28/09/2024	GEN	16			CON	
PM166	XQ33UH	00072078	28/09/2024	GEN	16			ENVLEV	
PM166	XQ33UH	00072078	28/09/2024	GEN	39			CALL OUT FEE	
PM166	XQ33UH	00072078	28/09/2024	GEN	39			CALL OUT FEE	
PM166	XQ33UH	00072078	28/09/2024	GEN	03			PART	
PM166	XQ33UH	00072078	28/09/2024	GEN	39			LABEXT	
PM166	XQ33UH	00072078	28/09/2024	GEN	16			CON	
PM166	XQ33UH	00072078	28/09/2024	GEN	16			ENVLEV	
PM166	XQ33UH	00072156	9/10/2024	CUMA	01	LABOUR	MECH		
PM166	XQ33UH	00072156	9/10/2024	CUMA		SERVICE COMPLETED.			
PM166	XQ33UH	00072156	9/10/2024	CUMB	01	LABOUR	MECH 6		

PM166	XQ33UH	00072156	9/10/2024	CUMBE5	'B' SERVICE COMPLETED BY COREY, JOSEPH & MICI
PM166	XQ33UH	00072156	9/10/2024	CUMBE5 00	LABOUR APPRENJ

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00072156	9/10/2024	CUMBE5	00	LABOUR	MECH		
PM166	XQ33UH	00072156	9/10/2024	CUMBE5	16			CON	YAT
PM166	XQ33UH	00072156	9/10/2024	CUMBE5	06			MK13584	YAT
PM166	XQ33UH	00072156	9/10/2024	CUMBE5	40			3413005	YAT
PM166	XQ33UH	00072156	9/10/2024	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00072156	9/10/2024	DEFECT					
PM166	XQ33UH	00072156	9/10/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00072156	9/10/2024	DEFECT		Reported Defect :-Defect Code : 00012617 Defect Reference : PM166 Date : 06/10/2024 Description B SERVICE DUE			
PM166	XQ33UH	00072911	24/10/2024	DEFECT	01	DEFECT CLEARED ON 09/10/2024 SERVICE CARRIED LABOUR MECH			
PM166	XQ33UH	00072911	24/10/2024	DEFECT					
PM166	XQ33UH	00072911	24/10/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00072911	24/10/2024	GEN	39	LABOUR APPRENJ			
PM166	XQ33UH	00072911	24/10/2024	GEN		REPAIR COMPLETED BY WORKSHOP 24/10/2024.			
						REPLACED TURBO AND GASKET ON THE EXHAUST REPLACED O-RINGS ON THE OIL PICK UP AND SUPP RING ON INTERCOOLER LINE FROM TURBO REPLAC REPLACED GOVENOR VALVE REPLACED DOZER PU			
PM166	XQ33UH	00072911	24/10/2024	GEN	00				
PM166	XQ33UH	00072911	24/10/2024	GEN	16			CON	YAT
PM166	XQ33UH	00072911	24/10/2024	GEN	11			2866337	YAT
PM166	XQ33UH	00072911	24/10/2024	GEN	39			5607734RX	YAT
PM166	XQ33UH	00072911	24/10/2024	GEN	11			5440813	YAT
PM166	XQ33UH	00072911	24/10/2024	GEN	13			3690864RX	YAT
PM166	XQ33UH	00072911	24/10/2024	GEN	13			4931694D	YAT
PM166	XQ33UH	00072911	24/10/2024	GEN	11			4026884	YAT
PM166	XQ33UH	00073883	5/11/2024	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00073883	5/11/2024	DEFECT					
PM166	XQ33UH	00073883	5/11/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00073883	5/11/2024	DEFECT		Reported Defect :-Defect Code : 00012907 Defect Reference : 07121 Date : 08/11/2024 Description c AIR CON BLOWING HOT AIR ON COLD TEMP			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00073883	5/11/2024	GEN		REPAIR COMPLETED BY BDS MECHANICAL ON 05/11			
						TRUCK A/C BLOWING HOT Aircon License #: AU61491 Drive to site - diagnose A/C blowing hot air. Gauges were recovered getting 510g. System was then pressure checked with 250g nitrogen. No leaks were found. System then vacuumed down and cl ring/ System has no leaks so was charged with 1400g of r pulling down and high side not moving at all. Suggesting compressor failure. Compressor was replaced Area cleaned and drove back to workshop LABEXT BDSMEC01 EX00037504 TF			
PM166	XQ33UH	00073883	5/11/2024	GEN	39				

								INVESTIGATE, DIAGNOSE AND	
PM166	XQ33UH	00073883	5/11/2024	GEN	39			TRAVEL FEE	BDSME
PM166	XQ33UH	00073883	5/11/2024	GEN	16			R134A	
PM166	XQ33UH	00073883	5/11/2024	GEN	16			LABEXT	BDSME
PM166	XQ33UH	00073883	5/11/2024	GEN	16			CON	BDSME
PM166	XQ33UH	00073883	5/11/2024	GEN	16			, CON	BDSME
PM166	XQ33UH	00073883	5/11/2024	GEN	16			, LABEXT	BDSME
PM166	XQ33UH	00073883	5/11/2024	GEN	16			R134A	
PM166	XQ33UH	00073883	5/11/2024	GEN	39			TRAVEL FEE	BDSME
PM166	XQ33UH	00073883	5/11/2024	GEN	39	LABEXT	BDSMEC01	GC-RIN08127 TR	
PM166	XQ33UH	00073281	9/11/2024	CUMAE5	01	INVESTIGATE, DIAGNOSE AND REPAIR, LABOUR APPRENJ			
PM166	XQ33UH	00073281	9/11/2024	CUMAE5		'A' SERVICE COMPLETED BY JOSEPH & TYLER (WORI			
						TIGHTENED UP BELLY BAR BOLTS HAD MIDLIFE IN PRIOR SERVICE TRUCK IS GROUNDED UNTIL A/C GETS REGASSED AND NE'			
PM166	XQ33UH	00073281	9/11/2024	CUMAE5	00	NOTED: * NEEDS AIR DRYER LABOUR APPREN			
PM166	XQ33UH	00073281	9/11/2024	CUMAE5	16			CON	YAT
PM166	XQ33UH	00073281	9/11/2024	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00073281	9/11/2024	DEFECT					
PM166	XQ33UH	00073281	9/11/2024	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00073281	9/11/2024	DEFECT		Reported Defect :-Defect Code : 00012876			
PM166	XQ33UH	00073281	9/11/2024	DEFECT		Defect Reference : 07121 Date : 08/11/2024 Description c AIR CON BLOWING HOT AIR ON COLD TEMP Reported Defect :-			
						Defect Code : 00012565 Defect Reference : 07119 Date : BROKE DONW 4 HOURS. MECHANIC REPLACED AIR AND DRYER.			
PM166	XQ33UH	00073395	12/11/2024	DEFECT	01	NEEDS COMPRESSOR AND DRYER LABOUR MECH			
PM166	XQ33UH	00073395	12/11/2024	DEFECT					
PM166	XQ33UH	00073395	12/11/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00073395	12/11/2024	GEN	39	LABOUR MECH 5			
PM166	XQ33UH	00073395	12/11/2024	GEN		REPAIR COMPLETED BY WORKSHOP 12/11/2024 HORTON WORK NO BRAKE PLATE LEFT			
PM166	XQ33UH	00073395	12/11/2024	GEN	16	REPLACED HORTON KIT CON	YAT		(
PM166	XQ33UH	00073395	12/11/2024	GEN	02			F35008SD	YAT
PM166	XQ33UH	00073918	5/12/2024	CUMAE5	01	LABOUR MECH 5			
PM166	XQ33UH	00073918	5/12/2024	CUMAE5		'A' SERVICE COMPLETED BY BEN & JOSH (WORKSHC			
						REPLACED 1.5KG FIRE EXTINGUISHER F/E EXP : JUNE 2024			
PM166	XQ33UH	00073918	5/12/2024	CUMAE5	00	LABOUR APPRENJC			
PM166	XQ33UH	00073918	5/12/2024	CUMAE5	16			CON	YAT
PM166	XQ33UH	00073918	5/12/2024	CUMAE5	19			FIREEXT1.5KG	YAT
PM166	XQ33UH	00073920	5/12/2024	CUMCE5	01	LABOUR APPRENJC			
PM166	XQ33UH	00073920	5/12/2024	CUMCE5		'C' SERVICE COMPLETED BY JOSH & BEN (WORKSHOP) ON 05			
PM166	XQ33UH	00073920	5/12/2024	CUMCE5	00	F/E EXP : JUNE 2025 LABOUR MECH 5			
PM166	XQ33UH	00073920	5/12/2024	CUMCE5	16			CON	YAT
PM166	XQ33UH	00073920	5/12/2024	CUMCE5	06			T224P	YAT
PM166	XQ33UH	00073920	5/12/2024	CUMCE5	06			WF2127	YAT
PM166	XQ33UH	00073920	5/12/2024	CUMCE5	06			LF637	YAT

PM166	XQ33UH	00073920	5/12/2024	CUMCE5	06			A-3380W1687	YAT
PM166	XQ33UH	00073920	5/12/2024	CUMCE5	40			3430284	YAT
PM166	XQ33UH	00073920	5/12/2024	CUMCE5	06			FF17237	YAT
PM166	XQ33UH	00073920	5/12/2024	CUMCE5	40			3430336	YAT
PM166	XQ33UH	00073920	5/12/2024	CUMCE5	06			TRPCAF0001	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00073920	5/12/2024	CUMCE5	06			UF110	YAT
PM166	XQ33UH	00073917	5/12/2024	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00073918	5/12/2024	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00073920	5/12/2024	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00073921	5/12/2024	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00073917	5/12/2024	DEFECT					
PM166	XQ33UH	00073918	5/12/2024	DEFECT					
PM166	XQ33UH	00073920	5/12/2024	DEFECT					
PM166	XQ33UH	00073921	5/12/2024	DEFECT					
PM166	XQ33UH	00073917	5/12/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00073918	5/12/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00073920	5/12/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00073921	5/12/2024	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00073920	5/12/2024	DEFECT		Reported Defect :- Defect Code : 00012879 Defect Reference : PM166 Date : 09/11/2024 Description of Defect : NEEDS AIR DRYER LABOUR MECH 6			
PM166	XQ33UH	00073917	5/12/2024	ECO	01				
PM166	XQ33UH	00073917	5/12/2024	ECO		SLEEPER AIR SERVICE COMPLETED BY COREY (WOR			
PM166	XQ33UH	00073917	5/12/2024	ECO	16			CON	YAT
PM166	XQ33UH	00073917	5/12/2024	ECO	06			ED002175254-S	YAT
PM166	XQ33UH	00073917	5/12/2024	ECO	06			ED0021751550	YAT
PM166	XQ33UH	00073917	5/12/2024	ECO	06			ED0037300960	YAT
PM166	XQ33UH	00073917	5/12/2024	ECO	06			FS1251	YAT
PM166	XQ33UH	00073917	5/12/2024	ECO	40			10W50	YAT
PM166	XQ33UH	00073917	5/12/2024	ECO	16			BS358N70	YAT
PM166	XQ33UH	00073921	5/12/2024	EXOINS	01	LABOUR MECH 5			
PM166	XQ33UH	00073921	5/12/2024	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECT			
						INSPECTION COMPLETED BY BEN & JOSH (WORKSHOP) ON			
						NO DEFECTS IDENTIFIED			
						F/E EXP: JUNE 2025 LABOUR APPRENJC			
PM166	XQ33UH	00073921	5/12/2024	EXOINS	00				
PM166	XQ33UH	00074149	13/12/2024	GEN	39			K015-FLY	
PM166	XQ33UH	00074149	13/12/2024	GEN	16			CON	
PM166	XQ33UH	00074149	13/12/2024	GEN	16			ENVLEV	
PM166	XQ33UH	00074149	13/12/2024	GEN	39			K015-FLY	
PM166	XQ33UH	00074149	13/12/2024	GEN	16			CON	
PM166	XQ33UH	00074149	13/12/2024	GEN	16			ENVLEV	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00074235	18/12/2024	TYRES	15			11006520	
PM166	XQ33UH	00074235	18/12/2024	TYRES	15			77000194	
PM166	XQ33UH	00074235	18/12/2024	TYRES	15			33000084	
PM166	XQ33UH	00074235	18/12/2024	TYRES	15			33000517	
PM166	XQ33UH	00074235	18/12/2024	TYRES	15			33000118	
PM166	XQ33UH	00074235	18/12/2024	TYRES	15			11006520	
PM166	XQ33UH	00074235	18/12/2024	TYRES	15			77000194	
PM166	XQ33UH	00074235	18/12/2024	TYRES	15			33000084	
PM166	XQ33UH	00074235	18/12/2024	TYRES	15			33000517	
PM166	XQ33UH	00074235	18/12/2024	TYRES	15			33000118	
PM166	XQ33UH	00074301	21/12/2024	CUMAE5	01	LABOUR	APPRENJC		
PM166	XQ33UH	00074301	21/12/2024	CUMAE5		'A' SERVICE COMPLETED BY JOSH & MICK (WORKSHOP) ON 2			
						TIGHTENED HEATER TAP DUE TO SMALL LE			

						NOTED:				
PM166	XQ33UH	00074301	21/12/2024	CUMAE5	00	* MONITOR HEATER TAP LEAK LABOUR MECH				
PM166	XQ33UH	00074301	21/12/2024	CUMAE5	16			CON		YAT
PM166	XQ33UH	00074301	21/12/2024	CUMAE5	40			3413005		YAT
PM166	XQ33UH	00074301	21/12/2024	DEFECT	01	LABOUR MECH				
PM166	XQ33UH	00074301	21/12/2024	DEFECT						
PM166	XQ33UH	00074301	21/12/2024	DEFECT		DEFECT CLEARED.				
PM166	XQ33UH	00075176	24/01/2025	CUMAE5	01	LABOUR MECH				
PM166	XQ33UH	00075176	24/01/2025	CUMAE5		SERVICE COMPLETED.				
PM166	XQ33UH	00075176	24/01/2025	CUMBE5	01	LABOUR APPRENJ				
PM166	XQ33UH	00075176	24/01/2025	CUMBE5		'B' SERVICE COMPLETED BY JOSEPH, BEN, TYLER & J				
						REPLACED BOTTOM BUSH ON RADIATOR SUPPORT E				
						F/E EXP :				
						NOTED: * CHECK FOR WATER IN AIR TANKS NEW SERV. MAY				
PM166	XQ33UH	00075176	24/01/2025	CUMBE5	00	LABOUR MECH 5				
PM166	XQ33UH	00075176	24/01/2025	CUMBE5	00	LABOUR APPREN				
PM166	XQ33UH	00075176	24/01/2025	CUMBE5	00	LABOUR APPRENJC				
PM166	XQ33UH	00075176	24/01/2025	CUMBE5	16			CON		YAT
PM166	XQ33UH	00075176	24/01/2025	CUMBE5	06			MK13584		YAT
PM166	XQ33UH	00075176	24/01/2025	CUMBE5	40			3413005		YAT
PM166	XQ33UH	00075176	24/01/2025	DEFECT	01	LABOUR MECH				
PM166	XQ33UH	00075176	24/01/2025	DEFECT						
PM166	XQ33UH	00075176	24/01/2025	DEFECT		DEFECT CLEARED.				
PM166	XQ33UH	00075477	8/02/2025	DEFECT	01	LABOUR MECH				
PM166	XQ33UH	00075477	8/02/2025	DEFECT		DEFECT CLEARED.				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00075477	8/02/2025	DEFECT		Reported Defect :-Defect Code : 00013603 Defect Reference : 07123 Date : 06/02/2025 Description c BATTERIES VERY WEAK UPON START UP. WEAK CR			
PM166	XQ33UH	00075489	8/02/2025	GEN	14	DEFECT CLEARED ON 08/02/2025 REPLACED 4 BATT N70 BATTERY		MCKMEC01	EX00038436 N7
PM166	XQ33UH	00075477	8/02/2025	GEN	39	MAINTENANCE FREE CALCIUM BATTERY - LHP, LABOUR APPRENJ			
PM166	XQ33UH	00075489	8/02/2025	GEN	14	N70 BATTERY		MCKMEC01	INV-0144 N7
PM166	XQ33UH	00075477	8/02/2025	GEN		MAINTENANCE FREE CALCIUM BATTERY - LHP, REPAIR COMPLETED BY JOSEPH (WORKSHOP) ON (			
PM166	XQ33UH	00075477	8/02/2025	GEN	16	REPLACED 4 BATTERIES CON		YAT	(
PM166	XQ33UH	00075477	8/02/2025	GEN	14			MF70ZZDT	YAT
PM166	XQ33UH	00075605	10/02/2025	GEN	39			LABEXT	GRA+F
PM166	XQ33UH	00075605	10/02/2025	GEN	39			REPLACE (2) BOTTOM BATTEI LABEXT	GRA+F
						REPLACE (2) BOTTOM BATTERIES. BATTERIES SUPF LABOUR APPREN			
PM166	XQ33UH	00075874	22/02/2025	CUMAE5	00				
PM166	XQ33UH	00075874	22/02/2025	CUMAE5		A SERVICE COMPLETED BY TYLER & JOSH (WORKSI			
						FIRE EXT EXP: JULY 2025			
						BOTH HEATER TAPS AREN'T LEAKING NOT REPLACING AIR DRYER FILTER, WILL NEED WH			
PM166	XQ33UH	00075874	22/02/2025	CUMAE5	16	NOTED: * REPLACE AIR DRYER KIT WHEN TIME APPLIES. CON		YAT	(

PM166	XQ33UH	00075874	22/02/2025	CUMAE5	00	LABOUR APPRENJC			
PM166	XQ33UH	00075874	22/02/2025	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00075874	22/02/2025	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00075874	22/02/2025	DEFECT		Reported Defect :-Defect Code : 00013467 Defect Reference : PM166 Date : 24/01/2025 Description CHECK FOR WATER IN AIR TANKS NEW SERV. MAY			
PM166	XQ33UH	00075874	22/02/2025	DEFECT		DEFECT CLEARED ON 22/02/2025 Reported Defect :- Defect Code : 00013201 Defect Reference : PM166 Date MONITOR HEATER TAP LEAK			
PM166	XQ33UH	00076702	31/03/2025	CUMAE5	00	DEFECT CLEARED ON 22/02/2025 BOTH HEATER TAPS ARE NOT LEAKING LABOUR APPREN			
PM166	XQ33UH	00076702	31/03/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 29/03/2025			
PM166	XQ33UH	00076702	31/03/2025	CUMAE5	16	FIRE EXT EXP: JUNE 2025 CON YAT			(
PM166	XQ33UH	00076702	31/03/2025	CUMAE5	00	LABOUR MECH 1			
PM166	XQ33UH	00076702	31/03/2025	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00076702	31/03/2025	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00077258	23/04/2025	CUMAE5	00	LABOUR MECH			
PM166	XQ33UH	00077258	23/04/2025	CUMAE5		A SERVICE COMPLETED.			
PM166	XQ33UH	00077258	23/04/2025	CUMAE5	16	FIRE EXT EXP: CON YAT			(
PM166	XQ33UH	00077258	23/04/2025	CUMBE5	01	LABOUR APPRENJ			
PM166	XQ33UH	00077258	23/04/2025	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 23/04/2025			
						FIRE EXT EXP: JUNE 25			
						REFITTED AIR DRYER AND REPLACED THE FILTER REPLACED TURN TABLE JACK AND ADJUSTED TO J ONLY TINT ON WINDOW IS SCRATCHED REPAIR WIF CON YAT			(
PM166	XQ33UH	00077258	23/04/2025	CUMBE5	16				
PM166	XQ33UH	00077258	23/04/2025	CUMBE5	00	LABOUR APPREN			
PM166	XQ33UH	00077258	23/04/2025	CUMBE5	16			RSK154 YAT	
PM166	XQ33UH	00077258	23/04/2025	CUMBE5	16			3413005	YAT
PM166	XQ33UH	00077258	23/04/2025	CUMBE5	16			Z1006 YAT	
PM166	XQ33UH	00077258	23/04/2025	CUMBE5	16			T224P	YAT
PM166	XQ33UH	00077258	23/04/2025	CUMBE5	16			SK3221/52Z	YAT
PM166	XQ33UH	00077258	23/04/2025	CUMBE5	16			FS19764	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00077258	23/04/2025	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00077258	23/04/2025	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00077258	23/04/2025	DEFECT		Reported Defect :-Defect Code : 00013208			
PM166	XQ33UH	00077258	23/04/2025	DEFECT		Defect Reference : PM166 Date : 22/12/2024 Description DRIVER'S WINDOW VERY SCRATCHED Reported Defect :-			
						Defect Code : 00013741 Defect Reference : PM166 Date Description of Defect : REPLACE AIR DRYER KIT WHEN TIME APPLIES. LABOUR MECH 1			
PM166	XQ33UH	00077779	17/05/2025	CUMAE5	00				
PM166	XQ33UH	00077779	17/05/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 17.05.2025			
						FIRE EXT EXP: JUNE 2025			

PM166	XQ33UH	00077779	17/05/2025	CUMAE5	16	SUPPLY ANDERSON LEAD CON		YAT		
PM166	XQ33UH	00077779	17/05/2025	CUMAE5	00	LABOUR APPRENJC				
PM166	XQ33UH	00077779	17/05/2025	CUMAE5	00	LABOUR MECH 5				
PM166	XQ33UH	00077779	17/05/2025	DEFECT	01	LABOUR MECH				
PM166	XQ33UH	00077780	17/05/2025	DEFECT	01	LABOUR MECH				
PM166	XQ33UH	00077779	17/05/2025	DEFECT		DEFECT CLEARED.				
PM166	XQ33UH	00077780	17/05/2025	DEFECT		DEFECT CLEARED.				
PM166	XQ33UH	00077780	17/05/2025	GEN	39	LABOUR MECH 1				
PM166	XQ33UH	00077780	17/05/2025	GEN		REPAIR COMPLETED BY WORKSHOP 17.05.2025 FIRE EXT EXP: N/A				
PM166	XQ33UH	00077780	17/05/2025	GEN	16	ADJUST BELTS CON		YAT		
PM166	XQ33UH	00077780	17/05/2025	GEN	00	LABOUR APPRENJC				
PM166	XQ33UH	00077780	17/05/2025	GEN	40			10W50	YAT	
PM166	XQ33UH	00077780	17/05/2025	GEN	06			ED002175254-S	YAT	
PM166	XQ33UH	00078152	30/05/2025	DEFECT	01	LABOUR MECH				
PM166	XQ33UH	00078152	30/05/2025	DEFECT		DEFECT CLEARED.				
PM166	XQ33UH	00078152	30/05/2025	DEFECT		Reported Defect :-Defect Code : 00014317 Defect Reference : 07124 Date : 29/05/2025 Description of Defect : AD BLUE TANK PRESSURING - CAP HARD TO REMOVE AND M				
PM166	XQ33UH	00078152	30/05/2025	GEN	39	LABOUR APPRENJC				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00078152	30/05/2025	GEN		REPAIR COMPLETED BY WORKSHOP 30.05.2025			
PM166	XQ33UH	00078152	30/05/2025	GEN	16	REMOVED ADBLUE PUMP AND FLUSHED OUT TO RE CON		YAT	
PM166	XQ33UH	00078150	31/05/2025	CUMAE5	00	LABOUR MECH 1			
PM166	XQ33UH	00078150	31/05/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 31.05.2025 FIRE EXT EXP: JUNE 2025			
PM166	XQ33UH	00078150	31/05/2025	CUMAE5	16	REPLACE MISSING LH STEER HUB CAP REPLACED A CON		YAT	
PM166	XQ33UH	00078150	31/05/2025	CUMAE5	00	LABOUR APPRENJC			
PM166	XQ33UH	00078150	31/05/2025	CUMAE5	00	LABOUR APPRENJ			
PM166	XQ33UH	00078150	31/05/2025	CUMAE5	16			RT1209A6	YAT
PM166	XQ33UH	00078150	31/05/2025	CUMAE5	16			SA003TRP	YAT
PM166	XQ33UH	00078150	31/05/2025	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00078150	31/05/2025	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00081464	6/06/2025	WEICAL		AIR GAUGE:16180 ADJUSTED: 16300 WEIGHBRIDGE: 16600 AIR GAUGE CALIBRATION COMPLETED CORRECTLY			
PM166	XQ33UH	00078438	10/06/2025	TYRES	15			33000096	
PM166	XQ33UH	00078438	10/06/2025	TYRES	15			33000118	
PM166	XQ33UH	00078438	10/06/2025	TYRES	15			33000096	
PM166	XQ33UH	00078438	10/06/2025	TYRES	15			33000118	
PM166	XQ33UH	00078653	21/06/2025	CUMAE5	00	LABOUR MECH 5			
PM166	XQ33UH	00078653	21/06/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 21.06.2025 FIRE EXT EXP: JANUARY 2026			
PM166	XQ33UH	00078653	21/06/2025	CUMAE5	16	REPLACED FIRE EXT CON		YAT	
PM166	XQ33UH	00078653	21/06/2025	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00078653	21/06/2025	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00078653	21/06/2025	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00084642	1/07/2025	WEICAL		EMPTY WEIGHBRIDGE: LOADED WEIGHBRIDGE: 156 AIR GAUGE CALIBRATION COMPLETED CORRECTLY			

PM166	XQ33UH	00079090	4/07/2025	CUMAE5	00	LABOUR MECH			
PM166	XQ33UH	00079090	4/07/2025	CUMAE5		A SERVICE COMPLETED.			

FIRE EXT EXP:

PM166	XQ33UH	00079090	4/07/2025	CUMAE5	16			CO	Y
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00079090	4/07/2025	CUMBE5	01	LABOUR MECH 5			
PM166	XQ33UH	00079090	4/07/2025	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 04.07.2025			
						FIRE EXT EXP: JANUARY 2026			
PM166	XQ33UH	00079090	4/07/2025	CUMBE5	16	RELINE ALL DRIVE BRAKES REPLACE WHEEL SEAL 1ST DRIVE RHS CON		YAT	
PM166	XQ33UH	00079090	4/07/2025	CUMBE5	00	LABOUR APPRENJC			
PM166	XQ33UH	00079090	4/07/2025	CUMBE5	00	LABOUR MECH 1			
PM166	XQ33UH	00079090	4/07/2025	CUMBE5	16			RSK154	YAT
PM166	XQ33UH	00079090	4/07/2025	CUMBE5	06			Z1006	YAT
PM166	XQ33UH	00079090	4/07/2025	CUMBE5	40			3413005	YAT
PM166	XQ33UH	00079090	4/07/2025	CUMBE5	06			HDA5979	YAT
PM166	XQ33UH	00079090	4/07/2025	CUMBE5	16			47697S	YAT
PM166	XQ33UH	00079090	4/07/2025	CUMBE5	16			KSMA2124707Q	YAT
PM166	XQ33UH	00079090	4/07/2025	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00079090	4/07/2025	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00079091	5/07/2025	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00079091	5/07/2025	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00079091	5/07/2025	GEN	39	LABOUR APPRENJC			
PM166	XQ33UH	00079091	5/07/2025	GEN		REPAIR COMPLETED BY WORKSHOP 05.07.2025			
PM166	XQ33UH	00079091	5/07/2025	GEN	16			CON	YAT
PM166	XQ33UH	00079091	5/07/2025	GEN	06			ED2175254-S	YAT
PM166	XQ33UH	00079091	5/07/2025	GEN	40			10W50	YAT
PM166	XQ33UH	00079684	31/07/2025	TYRES	15			11006520	
PM166	XQ33UH	00079685	31/07/2025	TYRES	15			11006520	
PM166	XQ33UH	00079696	31/07/2025	TYRES	15			11006520	
PM166	XQ33UH	00079684	31/07/2025	TYRES	15			33000084	
PM166	XQ33UH	00079685	31/07/2025	TYRES	15			33000084	
PM166	XQ33UH	00079696	31/07/2025	TYRES	15			33000084	
PM166	XQ33UH	00079684	31/07/2025	TYRES	15			33001507	
PM166	XQ33UH	00079685	31/07/2025	TYRES	15			33001507	
PM166	XQ33UH	00079696	31/07/2025	TYRES	15			33001507	
PM166	XQ33UH	00079684	31/07/2025	TYRES	15			33000520	
PM166	XQ33UH	00079685	31/07/2025	TYRES	15			33000520	
PM166	XQ33UH	00079696	31/07/2025	TYRES	15			33000520	
PM166	XQ33UH	00079684	31/07/2025	TYRES	15			33000125	
PM166	XQ33UH	00079685	31/07/2025	TYRES	15			33000125	
PM166	XQ33UH	00079696	31/07/2025	TYRES	15			22001381	
PM166	XQ33UH	00079684	31/07/2025	TYRES	15			33000237	
PM166	XQ33UH	00079685	31/07/2025	TYRES	15			33000237	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00079696	31/07/2025	TYRES	15			33000237	
PM166	XQ33UH	00079684	31/07/2025	TYRES	15			11006520	
PM166	XQ33UH	00079685	31/07/2025	TYRES	15			11006520	
PM166	XQ33UH	00079696	31/07/2025	TYRES	15			33000125	
PM166	XQ33UH	00079684	31/07/2025	TYRES	15			33000084	
PM166	XQ33UH	00079685	31/07/2025	TYRES	15			33000084	
PM166	XQ33UH	00079696	31/07/2025	TYRES	15			11006520	
PM166	XQ33UH	00079684	31/07/2025	TYRES	15			33001507	
PM166	XQ33UH	00079685	31/07/2025	TYRES	15			33001507	
PM166	XQ33UH	00079696	31/07/2025	TYRES	15			33000084	
PM166	XQ33UH	00079684	31/07/2025	TYRES	15			33000520	
PM166	XQ33UH	00079685	31/07/2025	TYRES	15			33000520	
PM166	XQ33UH	00079696	31/07/2025	TYRES	15			33001507	
PM166	XQ33UH	00079684	31/07/2025	TYRES	15			33000125	
PM166	XQ33UH	00079685	31/07/2025	TYRES	15			33000125	

PM166	XQ33UH	00079696	31/07/2025	TYRES	15			33000520	
PM166	XQ33UH	00079684	31/07/2025	TYRES	15			33000237	
PM166	XQ33UH	00079685	31/07/2025	TYRES	15			33000237	
PM166	XQ33UH	00079696	31/07/2025	TYRES	15			22001381	
PM166	XQ33UH	00079696	31/07/2025	TYRES	15			33000237	
PM166	XQ33UH	00079696	31/07/2025	TYRES	15			33000125	
PM166	XQ33UH	00079959	13/08/2025	CUMAE5	00	LABOUR MECH 1			
PM166	XQ33UH	00079959	13/08/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 13/8/2025			
						FIRE EXT EXP: JANUARY 2026			
						DRAIN WATER FROM AIR TANKS AND FIT TAP TO AIR DRYE REPLACE SWITCH FOR AIR HORNS CHECK FOR ALTERNATOR LIGHT ON AND REPAIR			
PM166	XQ33UH	00079959	13/08/2025	CUMAE5	16			CON	YAT
PM166	XQ33UH	00079959	13/08/2025	CUMAE5	00	LABOUR APPRENJ			
PM166	XQ33UH	00079959	13/08/2025	CUMAE5	16			G90-1107-002R	YAT
PM166	XQ33UH	00079960	13/08/2025	ECO	01	LABOUR APPREND			
PM166	XQ33UH	00079960	13/08/2025	ECO		ECO WIND SERVICE COMPLETED BY WORKSHOP 13			
PM166	XQ33UH	00079960	13/08/2025	ECO	16			3413005	YAT
PM166	XQ33UH	00079960	13/08/2025	ECO	06			SA17117	YAT
PM166	XQ33UH	00079960	13/08/2025	ECO	16			CON	YAT
PM166	XQ33UH	00080079	14/08/2025	TYRES	15			11004493	
PM166	XQ33UH	00080079	14/08/2025	TYRES	15			77000180	
PM166	XQ33UH	00080079	14/08/2025	TYRES	15			33000084	
PM166	XQ33UH	00080079	14/08/2025	TYRES	15			33000517	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00080079	14/08/2025	TYRES	15			33000118	
PM166	XQ33UH	00080079	14/08/2025	TYRES	15			11004493	
PM166	XQ33UH	00080079	14/08/2025	TYRES	15			77000180	
PM166	XQ33UH	00080079	14/08/2025	TYRES	15			33000084	
PM166	XQ33UH	00080079	14/08/2025	TYRES	15			33000517	
PM166	XQ33UH	00080079	14/08/2025	TYRES	15			33000118	
PM166	XQ33UH	00080246	23/08/2025	CUMAE5	00	LABOUR APPRENJC			
PM166	XQ33UH	00080246	23/08/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 23/8/2025			
						FIRE EXT EXP: JANUARY 2026			
PM166	XQ33UH	00080246	23/08/2025	CUMAE5	16	REPLACED FAN FOR CONDENSOR (SLEEPER AIR) H MINOR LEAK, DO ON B SERVICE CON YAT			
PM166	XQ33UH	00080246	23/08/2025	CUMAE5	00	LABOUR APPREND			
PM166	XQ33UH	00080246	23/08/2025	CUMAE5	16	FA0023 YAT			
PM166	XQ33UH	00080701	10/09/2025	CUMAE5	00	LABOUR MECH			
PM166	XQ33UH	00080701	10/09/2025	CUMAE5		A SERVICE COMPLETED.			
PM166	XQ33UH	00080701	10/09/2025	CUMAE5	16	FIRE EXT EXP: CON YAT			
PM166	XQ33UH	00080701	10/09/2025	CUMBE5	01	LABOUR MECH 1			
PM166	XQ33UH	00080701	10/09/2025	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 10/09/2025			
PM166	XQ33UH	00080701	10/09/2025	CUMBE5	16	FIRE EXT EXP: JANUARY 2026 CON YAT			
PM166	XQ33UH	00080701	10/09/2025	CUMBE5	00	LABOUR MECH 5			
PM166	XQ33UH	00080701	10/09/2025	CUMBE5	00	LABOUR APPRENJ			
PM166	XQ33UH	00080701	10/09/2025	CUMBE5	16			3413005	YAT
PM166	XQ33UH	00080701	10/09/2025	CUMBE5	06			RSK154	YAT
PM166	XQ33UH	00080701	10/09/2025	CUMBE5	06			Z1006	YAT
PM166	XQ33UH	00081427	13/10/2025	CUMAE5	00	LABOUR MECH			
PM166	XQ33UH	00081427	13/10/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 13/10/2025			
						FIRE EXT EXP: JANUARY 2026			
PM166	XQ33UH	00081427	13/10/2025	CUMAE5	16	REPLACED INDICATOR STALK TIGHTENED PYRO CON YAT			

PM166	XQ33UH	00081427	13/10/2025	CUMAE5	00	LABOUR APPRENJC			
PM166	XQ33UH	00081427	13/10/2025	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00081427	13/10/2025	CUMAE5	16			202-841	YAT
PM166	XQ33UH	00081427	13/10/2025	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00081427	13/10/2025	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00081427	13/10/2025	DEFECT		Reported Defect :-Defect Code : 00015329			
PM166	XQ33UH	00081427	13/10/2025	DEFECT		Defect Reference : XQ33UH Date : 12/10/2025 Descriptio INDICATOR - WIPER STALK FALLEN APART, NEEDS T Reported Defect :- Defect Code : 00015330 Defect Reference : 07127 Date : : PYRO GUAGE IN DASH NEED TIGHTENING LABOUR MECH			
PM166	XQ33UH	00081463	14/10/2025	DEFECT	01				
PM166	XQ33UH	00081463	14/10/2025	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00081463	14/10/2025	DEFECT		Reported Defect :-Defect Code : 00015355			
PM166	XQ33UH	00081463	14/10/2025	GEN	39	Defect Reference : 07128 Date : 12/10/2025 Description c AFTER TREAT FAULT - CODE 277 ADBLUE TANK ALWAYS FULL AND NOT USING CHECK ENGINE LIGHT ILLIMINATED FROM AFTER TR			
PM166	XQ33UH	00081463	14/10/2025	GEN		REPAIR COMPLETED BY WORKSHOP 14/10/2025 RAN NEW LOOM FOR NOX SENSOR POWER SUPPLY			
PM166	XQ33UH	00081463	14/10/2025	GEN	16			CON	YAT
PM166	XQ33UH	00081463	14/10/2025	GEN	00	LABOUR APPRENJC			
PM166	XQ33UH	00081631	17/10/2025	GEN	39			CALL OUT FEE	
PM166	XQ33UH	00081631	17/10/2025	GEN	39			LABEXT	
PM166	XQ33UH	00081631	17/10/2025	GEN	39			WRKSCONS	
PM166	XQ33UH	00081631	17/10/2025	GEN	39			ENVLEV	
PM166	XQ33UH	00081631	17/10/2025	GEN	39			22	
PM166	XQ33UH	00081631	17/10/2025	GEN		REPAIR COMPLETED BY BDS MECHANICAL 17/10/20 INVOICE #MK-RIN18246 PICK UP PARTS AND TRAVELEED TO CARMILA. REMOVE AIRLINE, REMOVE DRYER ASSEMBLY AND TO WORKSHOP CALL OUT FEE BDSMEC01 MK-RIN18246 Cal			
PM166	XQ33UH	00081631	17/10/2025	GEN	39				
PM166	XQ33UH	00081631	17/10/2025	GEN	39			LABEXT	BDSMI
PM166	XQ33UH	00081631	17/10/2025	GEN	39			INSPECT AIR LEAK AND REPA CONSUMABLES,	
PM166	XQ33UH	00081631	17/10/2025	GEN	39			ENVLEV	
PM166	XQ33UH	00081631	17/10/2025	GEN	39			22	BDSMI
PM166	XQ33UH	00081887	29/10/2025	DEFECT	01	LABOUR MECH			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00081887	29/10/2025	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00081887	29/10/2025	DEFECT		Reported Defect :-Defect Code : 00015491			
PM166	XQ33UH	00081887	29/10/2025	ECO		Defect Reference : 07130 Date : 28/10/2025 Description c SLEEPER AIR NEEDS SERVICE - BELT SQUEALS AND THEN FAULT CAME ON BELT BROKEN, NOW COOLS LABOUR APPRENJC			
PM166	XQ33UH	00081887	29/10/2025	ECO	01	ECO WIND SERVICE COMPLETED BY WORKSHOP 29			
PM166	XQ33UH	00081887	29/10/2025	ECO	16			CON	YAT
PM166	XQ33UH	00081887	29/10/2025	ECO	16			3413005	YAT
PM166	XQ33UH	00081887	29/10/2025	ECO	06			SA17117	YAT
PM166	XQ33UH	00081887	29/10/2025	ECO	11			13A0990	YAT
PM166	XQ33UH	00081961	30/10/2025	CUMAE5	00	LABOUR APPRENJC			

PM166	XQ33UH	00081961	30/10/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 30/10/2025
PM166	XQ33UH	00081961	30/10/2025	CUMAE5	16	FIRE EXT EXP: JANUARY 2026 CON YAT
PM166	XQ33UH	00081961	30/10/2025	CUMAE5	00	LABOUR APPREN
PM166	XQ33UH	00081961	30/10/2025	CUMAE5	00	LABOUR APPREND
PM166	XQ33UH	00082567	21/11/2025	CUMAE5	00	LABOUR MECH
PM166	XQ33UH	00082567	21/11/2025	CUMAE5		A SERVICE COMPLETED.
PM166	XQ33UH	00082567	21/11/2025	CUMAE5	16	FIRE EXT EXP: CON YAT
PM166	XQ33UH	00082567	21/11/2025	CUMBE5	01	LABOUR MECH 1
PM166	XQ33UH	00082567	21/11/2025	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 21/11/2025
						FIRE EXT EXP: JANUARY 2026 EYEWASH EXP - FEBR
						ADJUST CLUTCH REMOVE INSPECTION PLATE AND GREASE CLUTCH RACE \
PM166	XQ33UH	00082567	21/11/2025	CUMBE5	16	CON YAT
PM166	XQ33UH	00082567	21/11/2025	CUMBE5	00	LABOUR APPREND
PM166	XQ33UH	00082567	21/11/2025	CUMBE5	00	LABOUR APPRENJ
PM166	XQ33UH	00082567	21/11/2025	CUMBE5	06	RSK154 YAT
PM166	XQ33UH	00082567	21/11/2025	CUMBE5	06	Z1006 YAT
PM166	XQ33UH	00082567	21/11/2025	CUMBE5	06	F37-TP-1000 YAT
PM166	XQ33UH	00082567	21/11/2025	CUMBE5	40	3413005 YAT
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	01	LABOUR MECH 1
PM166	XQ33UH	00082568	21/11/2025	CUMCE5		C SERVICE COMPLETED BY WORKSHOP 21/11/2025
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	16	FIRE EXT EXP: JANUARY 2026 CON YAT
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	00	LABOUR APPREND

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	00	LABOUR	APPRENJ		
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	06			A3380W1687	YAT
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	06			17237	YAT
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	06			UF110	YAT
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	06			WF2127	YAT
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	16			170.T224	YAT
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	06			LF637	YAT
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	11			12PK2380	YAT
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	11			6PK1590	YAT
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	11			89440	YAT
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	11			89448	YAT
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	40			3430336	YAT
PM166	XQ33UH	00082568	21/11/2025	CUMCE5	40			3430284	YAT
PM166	XQ33UH	00082569	21/11/2025	EXOINS	01	LABOUR MECH 1			
PM166	XQ33UH	00082569	21/11/2025	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECT #1			
						INSPECTION COMPLETED BY WORKSHOP 21/11/202			
						FIRE EXT EXP - JANUARY 2026 EYEWASH EXP - FEBI			
PM166	XQ33UH	00082570	22/11/2025	GEN	39	DEFECTS IDENTIFIED - NONE LABOUR APPRENJ			
PM166	XQ33UH	00082570	22/11/2025	GEN		REPAIR COMPLETED BY WORKSHOP 22/11/2025			
						FIRE EXT EXP:			
						2 ROOF LIGHTS WERE OUT, COULD NOT GET TO THE WIRE			
						LHS SPOTTER WINDOW WIRING HAD FALLEN DOWN, FIXEI			
						REPLACED CUBERB DOOR HINGE			
PM166	XQ33UH	00082570	22/11/2025	GEN	16			CON	YAT
PM166	XQ33UH	00082570	22/11/2025	GEN	00	LABOUR MECH			
PM166	XQ33UH	00082570	22/11/2025	GEN	16			5000KLED	YAT

PM166	XQ33UH	00082780	24/11/2025	TYRES	15			99015526	
PM166	XQ33UH	00082780	24/11/2025	TYRES	15			33000084	
PM166	XQ33UH	00082780	24/11/2025	TYRES	15			33001507	
PM166	XQ33UH	00082780	24/11/2025	TYRES	15			33000527	
PM166	XQ33UH	00082780	24/11/2025	TYRES	15			33000118	
PM166	XQ33UH	00082780	24/11/2025	TYRES	15			99015526	
PM166	XQ33UH	00082780	24/11/2025	TYRES	15			33000084	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00082780	24/11/2025	TYRES	15			33001507	
PM166	XQ33UH	00082780	24/11/2025	TYRES	15			33000527	
PM166	XQ33UH	00082780	24/11/2025	TYRES	15			33000118	
PM166	XQ33UH	00083361	18/12/2025	CUMAE5	00	LABOUR APPREN			
PM166	XQ33UH	00083361	18/12/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 18/12/2025 FIRE EXT EXP: JANUARY 2026 REPLACED HEATER TAP REPLACED D2 GOVERNOR FULL SLEEPER AIR AERVICE CARRIED OUT KEY FOE CON YAT			
PM166	XQ33UH	00083361	18/12/2025	CUMAE5	16				
PM166	XQ33UH	00083361	18/12/2025	CUMAE5	00	LABOUR APPREND			
PM166	XQ33UH	00083361	18/12/2025	CUMAE5	00	LABOUR APPRENJC			
PM166	XQ33UH	00083361	18/12/2025	CUMAE5	00	LABOUR MECH 5			
PM166	XQ33UH	00083361	18/12/2025	CUMAE5	16			277486 YAT	
PM166	XQ33UH	00083361	18/12/2025	CUMAE5	16			SK3221/50Z YAT	
PM166	XQ33UH	00083361	18/12/2025	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00083362	18/12/2025	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00083361	18/12/2025	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00083362	18/12/2025	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00083361	18/12/2025	DEFECT		Reported Defect :-Defect Code : 00014825			
PM166	XQ33UH	00083362	18/12/2025	DEFECT		Defect Reference : PM166 Date : 11/08/2025 Description KEY FOB AND CHECK WHEEL ALIGNMENT Reported Defect :-			
						Defect Code : 00015681 Defect Reference : PM166 Date Defect : FULL ECOWIND SERVICE TO BE COMPLETED AT NE Reported Defect :-			
PM166	XQ33UH	00083361	18/12/2025	DEFECT ECO	01	Defect Code : 00011704 Defect Reference : PM166 Date Defect : REAR AXLE SHOCKIE BUSHES NEED REPLACING LA			
PM166	XQ33UH	00083362	18/12/2025						
PM166	XQ33UH	00083362	18/12/2025	ECO		ECO WIND SERVICE COMPLETED BY WORKSHOP 18			
PM166	XQ33UH	00083362	18/12/2025	ECO	06			SA17117 YAT	
PM166	XQ33UH	00083362	18/12/2025	ECO	40			10W50 YAT	
PM166	XQ33UH	00083362	18/12/2025	ECO	06			SO 8010 YAT	
PM166	XQ33UH	00083362	18/12/2025	ECO	06			SN 80008 YAT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00083362	18/12/2025	ECO	06			FS1251	YAT
PM166	XQ33UH	00083362	18/12/2025	ECO	16			CON	YAT
PM166	XQ33UH	00083578	3/01/2026	CUMAE5	00	LABOUR APPRENJ			
PM166	XQ33UH	00083578	3/01/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 03/01/2026 FIRE EXT EXP: MAY 2026 REPLACED MIDDLE ROOF LIGHT CON YAT			
PM166	XQ33UH	00083578	3/01/2026	CUMAE5	16				
PM166	XQ33UH	00083578	3/01/2026	CUMAE5	00	LABOUR APPRENJC			
PM166	XQ33UH	00083578	3/01/2026	CUMAE5	00	LABOUR APPREND			
PM166	XQ33UH	00083578	3/01/2026	CUMAE5	16			5000KLED YAT	
PM166	XQ33UH	00083792	12/01/2026	GEN	39	LABOUR APPRENJC			

PM166	XQ33UH	00083792	12/01/2026	GEN		REPAIR COMPLETED BY WORKSHOP 12/01/2026			
PM166	XQ33UH	00083792	12/01/2026	GEN	16	DIAGNOSED AIR LEAK COMING (CRACKED) FROM UI PURGE TANK AND TESTED FOR AIR LEAKS CON YAT			
PM166	XQ33UH	00083792	12/01/2026	GEN	00	LABOUR APPREN			
PM166	XQ33UH	00083792	12/01/2026	GEN	06			620300	YAT
PM166	XQ33UH	00083890	14/01/2026	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00083890	14/01/2026	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00083890	14/01/2026	DEFECT		Reported Defect :-Defect Code : 00016103			
PM166	XQ33UH	00083890	14/01/2026	GEN	39	Defect Reference : 07133 Date : 13/01/2026 Description c NO EBC PLUG, TRAILER REVERSE BUZZER STAYS C LABOUR APPREN			
PM166	XQ33UH	00083890	14/01/2026	GEN		REPAIR COMPLETED BY WORKSHOP 14/01/2026			
						REPLACED EBS PLUG REPLACED 10AMP & 30AMP FUSES CHECKED LIGHTS AND PLUG TO MAKE SURE NO WIRES WI			
PM166	XQ33UH	00083890	14/01/2026	GEN	16			CON	YAT
PM166	XQ33UH	00083890	14/01/2026	GEN	16			EBS1002	YAT
PM166	XQ33UH	00084316	30/01/2026	CUMAE5	00	LABOUR MECH 1			
PM166	XQ33UH	00084316	30/01/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 30/01/2026			
						FIRE EXT EXP: MAY 2026			
						ADJUST CLUTCH CHANGE ALL DASH GAUGE GLOVES TO STANDARD 1 COLC			
PM166	XQ33UH	00084316	30/01/2026	CUMAE5	16			CON	YAT
PM166	XQ33UH	00084316	30/01/2026	CUMAE5	00	LABOUR APPRENJC			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00084352	30/01/2026	TYRES	15			11006520	
PM166	XQ33UH	00084352	30/01/2026	TYRES	15			77000194	
PM166	XQ33UH	00084352	30/01/2026	TYRES	15			33000084	
PM166	XQ33UH	00084352	30/01/2026	TYRES	15			33000370	
PM166	XQ33UH	00084352	30/01/2026	TYRES	15			33000517	
PM166	XQ33UH	00084352	30/01/2026	TYRES	15			33000536	
PM166	XQ33UH	00084352	30/01/2026	TYRES	15			33000118	
PM166	XQ33UH	00084352	30/01/2026	TYRES	15			11006520	
PM166	XQ33UH	00084352	30/01/2026	TYRES	15			77000194	
PM166	XQ33UH	00084352	30/01/2026	TYRES	15			33000084	
PM166	XQ33UH	00084352	30/01/2026	TYRES	15			33000370	
PM166	XQ33UH	00084352	30/01/2026	TYRES	15			33000517	
PM166	XQ33UH	00084352	30/01/2026	TYRES	15			33000536	
PM166	XQ33UH	00084352	30/01/2026	TYRES	15			33000118	
PM166	XQ33UH	00085232	6/02/2026	GEN	39			LABEXT	
PM166	XQ33UH	00085232	6/02/2026	GEN	39			GENERAL PART	
PM166	XQ33UH	00085232	6/02/2026	GEN	39			Q21-6004	
PM166	XQ33UH	00085232	6/02/2026	GEN	39			MISCON	
PM166	XQ33UH	00085232	6/02/2026	GEN	39			ENVLEV	
PM166	XQ33UH	00085232	6/02/2026	GEN		REPAIR COMPLETED BY BROWN N HURLEY 06/02/202			
						INVOICE #3811206			
						k046 DRIVER THINKS FAULTY SPEED SENSOR - SHUT Drove truck into workshop and jacked over cab. Sourced wi back of the gearbox. Wires tested okay. load tested circuit a sensors. Road tested vehicle and still wouldn?t rev over 15(Road tested vehicle again and results remained the same. I Road tested vehicle again and now revving over 1500rpm. A Driver requested spare speed sensor, provided.			
PM166	XQ33UH	00085232	6/02/2026	GEN	39			LABEXT	
PM166	XQ33UH	00085232	6/02/2026	GEN	39			GENERAL PART	

PM166	XQ33UH	00085232	6/02/2026	GEN	39			Q21-6004	
PM166	XQ33UH	00085232	6/02/2026	GEN	39			MISCON	
PM166	XQ33UH	00085232	6/02/2026	GEN	39			ENVLEV	
PM166	XQ33UH	00085066	27/02/2026	CUMAE5	00	LABOUR MECH			
PM166	XQ33UH	00085066	27/02/2026	CUMAE5		A SERVICE COMPLETED.			
PM166	XQ33UH	00085066	27/02/2026	CUMAE5	16	FIRE EXT EXP: CON			YAT
PM166	XQ33UH	00085066	27/02/2026	CUMBE5	01	LABOUR MECH 1			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00085066	27/02/2026	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 27/02/2026			
PM166	XQ33UH	00085066	27/02/2026	CUMBE5	16	FIRE EXT EXP: MAY 2026 EYEWASH EXP - FEBRUAR CON YAT			
PM166	XQ33UH	00085066	27/02/2026	CUMBE5	00	LABOUR APPRENJC			
PM166	XQ33UH	00085066	27/02/2026	CUMBE5	40			3413005	YAT
PM166	XQ33UH	00085066	27/02/2026	CUMBE5	06			RSK154	YAT
PM166	XQ33UH	00085066	27/02/2026	CUMBE5	06			Z1006	YAT
PM166	XQ33UH	00085067	27/02/2026	ECO	01	LABOUR APPRENJC			
PM166	XQ33UH	00085067	27/02/2026	ECO		ECO WIND SERVICE COMPLETED BY WORKSHOP 27			
PM166	XQ33UH	00085067	27/02/2026	ECO	00	REMOVE U/S SUMP PLUG AND REPLACE WITH USEI			
PM166	XQ33UH	00085067	27/02/2026	ECO	16			CON	YAT
PM166	XQ33UH	00085067	27/02/2026	ECO	06			SA17117	YAT
PM166	XQ33UH	00085067	27/02/2026	ECO	40			10W50	YAT
PM166	XQ33UH	00085476	16/03/2026	GEN	39	LABOUR APPRENJC			
PM166	XQ33UH	00085476	16/03/2026	GEN		REPAIR COMPLETED BY WORKSHOP 16/03/2026			
						JOB COMPLAINT - WIPERS NEED CHANGING - SLEEPER AIR NOT BLOWING AIR			
						REPLACED WINDSCREEN WIPERS SLEEPER AIR BLOWER MOTOR WAS JAMMED, NOW BLOWI			
PM166	XQ33UH	00085476	16/03/2026	GEN	16			CON	YAT
PM166	XQ33UH	00085476	16/03/2026	GEN	16			084871080	YAT
PM166	XQ33UH	00085951	27/03/2026	GEN	39			LABEXT	
PM166	XQ33UH	00085951	27/03/2026	GEN	39			275707	
PM166	XQ33UH	00085951	27/03/2026	GEN	39			ENVLEV	
PM166	XQ33UH	00085951	27/03/2026	GEN	39			CON	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00085951	27/03/2026	GEN		REPAIR COMPLETED BY CUMMINS SOUTH PACIFIC 2			
						INVOICE #1935328			
						COMPLAINT - WONT BUILD AIR CAUSE - GOVERNOR CORRECTION - GUIDANZ SO NUMBER 01781546			

Hrs/Klms: 103,407 hrs / 1,039,535 km ECM KLM: 1,039,5
ECM HRS: 14,392 hrs ECM Fuel Burn: 561,407 L AG78D
Travelled from workshop to Target South Rockhampton . .
download .
Jacked cab, inspected. Compressor pumping good air. Fo
Replaced.
Air built up, all good. Travelled back to workshop. XG595 ·
Drove to JBS abattoir, just East of Rockhampton.
Spoke with security to gain entry to their property and the t
Manually jacked the cab.
Found the air compressor governor was continuously exha
Removed the signal line to the Air Dryer & found that it ha
line.
Capped off the signal port on the air compressor governor
pressor back up to 800kPa.
We left the abattoir and moved down to the truck parking l
I removed the signal line from the air dryer, removed the fi
installed a bung into the
air dryer to stop the air leaking from the air dryer. Collecte
Drove back to the workshop completed documentation.
LABEXT CUMMIN01 1935328

PM166	XQ33UH	00085951	27/03/2026	GEN	39				
PM166	XQ33UH	00085951	27/03/2026	GEN	39			275707	CUMM
PM166	XQ33UH	00085951	27/03/2026	GEN	39			ENVLEV	CUMM
PM166	XQ33UH	00085951	27/03/2026	GEN	39			CON	CUMM
PM166	XQ33UH	00086137	9/04/2026	GEN	39			LABEXT	BROH
PM166	XQ33UH	00086137	9/04/2026	GEN	39			MISCON	BROH
PM166	XQ33UH	00086137	9/04/2026	GEN	39			ENVLEV	BROH

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00086137	9/04/2026	GEN		REPAIR BY BROWN N HURLEY YATALA 09/04/2026			
						INVOICE #3847114			
						RESURFACE FLYWHEEL			
						WARRANTY REPAIR REPAIRS/SERVICE AT NO CHARC LOADED UP THE UTE AND HEADED TO EXODAS YARI NEW CRANK SEAL. TOOK PHOTOS AND THE DOWNLC			
PM166	XQ33UH	00086137	9/04/2026	GEN	39			LABEXT	
PM166	XQ33UH	00086137	9/04/2026	GEN	39			MISCON	
PM166	XQ33UH	00086137	9/04/2026	GEN	39			ENVLEV	
PM166	XQ33UH	00086050	10/04/2026	CUMAE5	00	LABOUR APPRENJ			
PM166	XQ33UH	00086050	10/04/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 10/04/2026			
PM166	XQ33UH	00086050	10/04/2026	CUMAE5	16	FIRE EXT EXP: MAY 2026 CON YAT			
PM166	XQ33UH	00086050	10/04/2026	CUMAE5	00	LABOUR MECH			
PM166	XQ33UH	00086051	10/04/2026	GEN	39	LABOUR APPRENJ			
PM166	XQ33UH	00086051	10/04/2026	GEN		REPAIR COMPLETED BY WORKSHOP 10/04/2026			
						JOB COMPLAINT -BROKEN CLUTCH -AIR DRYER NOT WORKING -SLEEPER AIR VOLT FAULT			

						REMOVED GEAR BOX FROM TRUCK, TOOK BROKEN PUT NEW FLYWHEEL ON AND TORQUE TO SPEC , R RE FITTED GEAR BOX, ADJUSTED CLUTCH TO SPEC DRYER SLEEPER AIR VOLTS NOT CHARGING TO 13V, REPLA CON YAT			
PM166	XQ33UH	00086051	10/04/2026	GEN	16				
PM166	XQ33UH	00086051	10/04/2026	GEN	00	LABOUR APPREN			
PM166	XQ33UH	00086051	10/04/2026	GEN	16			308935-531-PAC	YAT
PM166	XQ33UH	00086051	10/04/2026	GEN	16			K-4450-PAC	YAT
PM166	XQ33UH	00086051	10/04/2026	GEN	16			620300	YA
PM166	XQ33UH	00086051	10/04/2026	GEN	16			LV1690	YAT
PM166	XQ33UH	00086916	20/05/2026	CUMAE5	00	LABOUR MECH 6			
PM166	XQ33UH	00086916	20/05/2026	CUMAE5		A SERVICE COMPLETED.BY WORKSHOP 15/05/26			
						FIRE EXT EXP:DEC 2026			
						REPLACED LHS LOWER SHOCK BUSHES REPLACED FIXED POOR CONTACT FOR REVERSE LIGHTS BEEF			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00086916	20/05/2026	CUMAE5	16			CON	YAT
PM166	XQ33UH	00086916	20/05/2026	CUMAE5	00	LABOUR	APPRENL		
PM166	XQ33UH	00086916	20/05/2026	CUMAE5	16			FIREEXT2.0KG	YAT
PM166	XQ33UH	00086916	20/05/2026	DEFECT	01	LABOUR	MECH		
PM166	XQ33UH	00086916	20/05/2026	DEFECT		DEFECT	CLEARED.		
PM166	XQ33UH	00087368	2/06/2026	GEN	39	LABOUR MECH 7			
PM166	XQ33UH	00087368	2/06/2026	GEN		REPAIR COMPLETED BY WORKSHOP 02/06/2026			
						JOB COMPLAINT -TURNTABLE WONT LOCK			
						REMOVE AND FIT SECOND HAND TURNTABLE, FIT NEW BU FIT STEERING WHEEL COVER REPLACE MULTIPLE DASH LI FIT NEW POGO STICK TO SUZI COILS			
PM166	XQ33UH	00087368	2/06/2026	GEN	16			CON	YAT
PM166	XQ33UH	00087368	2/06/2026	GEN	16			MX1-7S	YAT
PM166	XQ33UH	00087368	2/06/2026	GEN	16			SK4000	YAT
PM166	XQ33UH	00087368	2/06/2026	GEN	16			SK212169Z	YAT
PM166	XQ33UH	00087469	6/06/2026	GEN	39	LABOUR MECH 7			
PM166	XQ33UH	00087469	6/06/2026	GEN		REPAIR COMPLETED BY WORKSHOP 06/06/2026			
						JOB COMPLAINT -U/S AIR LINES			
PM166	XQ33UH	00087469	6/06/2026	GEN	16	REPLACE BOTH SUZI LINES AS THEY WERE KINKED TRUCK SIDE CON YAT			
PM166	XQ33UH	00087555	10/06/2026	CUMAE5	00	LABOUR MECH			
PM166	XQ33UH	00087555	10/06/2026	CUMAE5		A SERVICE COMPLETED.			
PM166	XQ33UH	00087555	10/06/2026	CUMAE5	16	FIRE EXT EXP: CON YAT			
PM166	XQ33UH	00087555	10/06/2026	CUMBE5	01	LABOUR MECH 7			
PM166	XQ33UH	00087555	10/06/2026	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 10/06/2026			
						FIRE EXT EXP: DECEMBER 2026 EYEWASH EXP - FEI			
						REPLACED D2 GOVERNOR VALVE AS NEEDED REPL REPLACED TOP RH ROOF LIGHT REPAIR WIRING TO CABLE TO AIR HORNS CON YAT			
PM166	XQ33UH	00087555	10/06/2026	CUMBE5	16				
PM166	XQ33UH	00087555	10/06/2026	CUMBE5	00	LABOUR APPRENL			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00087555	10/06/2026	CUMBE5	06			MK13555	YAT

PM166	XQ33UH	00087555	10/06/2026	CUMBE5	06		FS19764	YAT
PM166	XQ33UH	00087555	10/06/2026	CUMBE5	06		AS2474	YAT
PM166	XQ33UH	00087555	10/06/2026	CUMBE5	06		HDA5979	YAT
PM166	XQ33UH	00087555	10/06/2026	CUMBE5	40		3413005	YAT
PM166	XQ33UH	00087555	10/06/2026	CUMBE5	16		KW275707	YAT
PM166	XQ33UH	00087555	10/06/2026	CUMBE5	16		5000KLED	YAT
PM166	XQ33UH	00087555	10/06/2026	DEFECT	01	LABOUR MECH		
PM166	XQ33UH	00087555	10/06/2026	DEFECT		DEFECT CLEARED.		
PM166	XQ33UH	00087555	10/06/2026	DEFECT		Reported Defect :-Defect Code : 00017439 Defect Reference : PM166 Date : 31/05/2026 Description of Defect : DRIVER TROY S HAD MAJOR ISSUES WITH PM TURN UP TO RP29A. HE ADVISES HE WILL NOT BE ABLE TO OPS PLEASE CONTACT HIM IN AM TO DISCUSS THIS		
PM166	XQ33UH	00087555	10/06/2026	DEFECT		Reported Defect :- Defect Code : 00017461 Defect Reference : PM166 Date DRIVER TROY S HAS ISSUES WITH PM TURNTABLE. HE IS SLATED TO DEPART AGAIN AT 1200HRS		
PM166	XQ33UH	00087555	10/06/2026	DEFECT		Defect Code : 00017217 Defect Reference : PM166 Date DRIVERS WINDOW NEEDS TO BE LOOKED AT AND A		

PM166	XQ33UH	00087915	10/06/2026	GEN	39		1675741		
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00087915	10/06/2026	GEN		REPAIR COMPLETED BY BROWN N HURLEY YATALA INVOICE #3918956 Warranty Repairs/Service At No Charge inspect and found coolant transfer tube leaking. Removed Checked level after road test and all good. Checked for le Warranty Repairs/Service At No Charge inspected and found exhaust manifold gaskets to be leaki return, turbo, exhaust manifold. Cleaned up surfaces, got Inspect turbo wastegate actuator travel, found to be out of spec at 0.086 spec at 0.040?. After doing coolant transfer tube, Fit turbo gasket. Fit exhaust flex pipe with new gaskets. Fit cac pipe 1675741 BROHUR01 3918956 HC			
PM166	XQ33UH	00087915	10/06/2026	GEN	39				
PM166	XQ33UH	00089441	19/06/2026	TYRES	15			YFPSI	YOKTY
PM166	XQ33UH	00089441	19/06/2026	TYRES		SERVICE COMPLETED BY YOKOHAMA 19/06/2026 - P			
PM166	XQ33UH	00089441	19/06/2026	TYRES	15			YFPSI	YOKTY
PM166	XQ33UH	00088269	11/07/2026	CUMAE5	00	LABOUR APPRENJC			
PM166	XQ33UH	00088269	11/07/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 10/07/2026 FIRE EXT EXP: DECEMBER 2026			
PM166	XQ33UH	00088269	11/07/2026	CUMAE5	16	REPLACED LHS CAB LOCK CON YAT			
PM166	XQ33UH	00088269	11/07/2026	CUMAE5	00	LABOUR MECH 7			
PM166	XQ33UH	00088269	11/07/2026	CUMAE5	16			K156-27 YAT	
PM166	XQ33UH	00089216	18/08/2026	CUMAE5	00	LABOUR MECH 7			
PM166	XQ33UH	00089216	18/08/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 18/08/2026 FIRE EXT EXP: DECEMBER 2026			

						REPLACED FRONT RHS AND LHS WHEEL BEARING A TENSIONED WHEEL NUTS READJUSTED BRAKES CON YAT				
PM166	XQ33UH	00089216	18/08/2026	CUMAE5	16					
PM166	XQ33UH	00089216	18/08/2026	CUMAE5	00	LABOUR BILLY				
PM166	XQ33UH	00089216	18/08/2026	CUMAE5	00	LABOUR APPRENJC				
PM166	XQ33UH	00089216	18/08/2026	CUMAE5	40			3413005		YAT
PM166	XQ33UH	00089216	18/08/2026	CUMAE5	16			WBK4SCHB	YAT	
PM166	XQ33UH	00089216	18/08/2026	CUMAE5	16			MSKMG1A4515	YAT	
PM166	XQ33UH	00089216	18/08/2026	CUMAE5	16			FQ6612	YAT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00089216	18/08/2026	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00089216	18/08/2026	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00089216	18/08/2026	DEFECT		Reported Defect :-Defect Code : 00018345			
PM166	XQ33UH	00089649	19/08/2026	TYRES	15	Defect Reference : 15760 Date : 18/08/2026 Description of Defect : ADJUST CLUTCH NO CLUTCH BRAKE YFROTTBX			
PM166	XQ33UH	00089649	19/08/2026	TYRES	15			YFPSI	
PM166	XQ33UH	00089649	19/08/2026	TYRES		SERVICE COMPLETED BY YOKOHAMA 19/08/2026 - TYRE ROTA 7,8,9,10			
PM166	XQ33UH	00089649	19/08/2026	TYRES	15			YFPSI	
PM166	XQ33UH	00089649	19/08/2026	TYRES	15			YFROTTBX	
PM166	XQ33UH	00089824	27/08/2026	TYRES	15			YFPSI	
PM166	XQ33UH	00089824	27/08/2026	TYRES		SERVICE COMPLETED BY YOKOHAMA 27/08/2026 - PRESSURE			
PM166	XQ33UH	00089824	27/08/2026	TYRES	15			YFPSI	
PM166	XQ33UH	00089596	3/09/2026	GEN	39	LABOUR RAM			
PM166	XQ33UH	00089596	3/09/2026	GEN		REPAIR COMPLETED BY WORKSHOP 03/09/2026 JOB COMPLAINT -SPEEDOMETER JUMPING UP AND DOWN SPEEDOMETER JUMPING UP AND DOWN AND GIVIN FURTHER INSPECTION FOUND A DAMAGE LOOSE W WIRING TEST DROVE CONFIRMED SPEEDO OPERATING COR CON YAT			
PM166	XQ33UH	00089596	3/09/2026	GEN	16				
PM166	XQ33UH	00090223	8/09/2026	TYRES	15			YFPUNTBX	YOKTY
PM166	XQ33UH	00090223	8/09/2026	TYRES		SERVICE COMPLETED BY YOKOHAMA 08/09/2026 - P			
PM166	XQ33UH	00090223	8/09/2026	TYRES	15	Pos:10 RSD 026058 YFPUNTBX YOKTYR01 IN-131979-202TR			
PM166	XQ33UH	00090098	24/09/2026	CUMAE5	00	LABOUR MECH			
PM166	XQ33UH	00090098	24/09/2026	CUMAE5		A SERVICE COMPLETED.			
PM166	XQ33UH	00090098	24/09/2026	CUMAE5	16	FIRE EXT EXP: CON YAT			
PM166	XQ33UH	00090098	24/09/2026	CUMBE5	01	LABOUR BILLY			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM166	XQ33UH	00090098	24/09/2026	CUMBE5		B SERVICE COMPLETED BY WORKSHOP ON 24/09/20 FIRE EXT EXP: DEC 2026 REPPLACE RADIATOR CAP REPLACED A HAND CLAM REMOVED AND LOCKTIGHT 3 BOLTS THAT HOLD TH COVER REPLACED THE BUNG IN THE FRONT COVER DEGREASED AND SENT TO GET WASHED TO TRY SI REPLACE P CLAMP CON YAT			
PM166	XQ33UH	00090098	24/09/2026	CUMBE5	16				
PM166	XQ33UH	00090098	24/09/2026	CUMBE5	00	LABOUR 4THYEARA			
PM166	XQ33UH	00090098	24/09/2026	CUMBE5	16			IHCWS08-16	YAT
PM166	XQ33UH	00090098	24/09/2026	CUMBE5	16			AE9976132	YAT
PM166	XQ33UH	00090098	24/09/2026	CUMBE5	16			MK13584	YAT

PM166	XQ33UH	00090098	24/09/2026	CUMBE5	16			AS2474	YAT
PM166	XQ33UH	00090098	24/09/2026	CUMBE5	16			3413005	YAT
PM166	XQ33UH	00090098	24/09/2026	DEFECT	01	LABOUR MECH			
PM166	XQ33UH	00090098	24/09/2026	DEFECT		DEFECT CLEARED.			
PM166	XQ33UH	00090098	24/09/2026	DEFECT		Reported Defect :-Defect Code : 00018346			
PM166	XQ33UH	00090098	24/09/2026	DEFECT		Defect Reference : PM166 Date : 18/08/2026 Description CHECK WHEEL BEARING ADJUSTMENT NEXT SERVI Reported Defect :-			
				GEN	16			Defect Code : 00017601 Defec RE PART	
PM166	XQ33UH	00090922	27/10/2026						
PM166	XQ33UH	00091071	27/10/2026	GEN	39			LABEXT	
PM166	XQ33UH	00090922	27/10/2026	GEN	16	CON	KENAUT01	EX00048993	Cc
PM166	XQ33UH	00091071	27/10/2026	GEN		, REPAIR COMPLETED BY NQFM 27/10/2026 INVOICE #44491			
				GEN	16	CALL OUT TO JUMP START VEHICLE - TILT CAB TO G			
PM166	XQ33UH	00090922	27/10/2026			LAB	KENAUT01	EX00048993	La

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code

Report Options:

Sort By	- AssetCode
Starting Asset Code	- PM166
To	- PM166
Starting Registration	-
To	-
Starting Operations No	-
To	-
From: Work Order Location	-
To	-
From: Work Order Date	- 01/01/1901
To	- 31/12/9999
From: Completion Date	-
To	-
From: RM Category Code	-
To	-
Starting Category Code	-
To	-
Starting Owned By	-
To	-
Starting Based By	-
To	-
Starting Location	-
To	-
Assets For	- All Assets
Include Disposed Assets	- no
Warranty Items Only	- no
Include Non Active Assets	- no
Exclude Estimates	- no
Fleet Assets Only	- no
Service Code	-
Task Code	-
Mechanic Code	-
Product Code	-
Warehouse	-
WO Supplier Code	-
Include All	- yes
Labour	- yes
Parts	- yes
Supplies	- yes
Tyres	- yes
Comments	- yes

Supplier Code	Invoice	Details	Purchase Order	
ROCTRU01	EX00020767	GENERAL PART CODE,PM166	EX0002076	
ROCTRU01	EX00020767	GENERAL PART CODE,PM166	EX0002076	
ROCTRU01	EX00020767	GENERAL PART CODE,PM166	EX0002076	
ROCTRU01	EX00020767	GENERAL PART CODE,PM166	EX0002076	
ROCTRU01	EX00020767	GENERAL PART CODE,PM166	EX0002076	
ROCTRU01	EX00020767	GENERAL PART CODE,PM166	EX0002076	
ROCTRU01	EX00020767	Labour,PM166	EX0002076	
ROCTRU01	EX00020767	GENERAL PART CODE,PM166	EX0002076	
ROCTRU01	131776	GENERAL PART CODE,PM166	EX0002076	
ROCTRU01	131776	Labour,PM166	EX0002076	
ROCTRU01	131776	GENERAL PART CODE,PM166	EX0002076	
ROCTRU01	131776	GENERAL PART CODE,PM166	EX0002076	
ROCTRU01	131776	GENERAL PART CODE,PM166	EX0002076	
ROCTRU01	131776	GENERAL PART CODE,PM166	EX0002076	
ROCTRU01	131776	GENERAL PART CODE,PM166	EX0002076	
ROCTRU01	131776	GENERAL PART CODE,PM166	EX0002076	
		Labour		2.00

CKER

		Consumables	5.00

L5060

. LABOUR

		Labour	1.00

EPAIRED
NEXT TIME IT GOES THERE FOR SOMETHING LABOUR MECH

			1.00
			1.00
		Consumables	5.00
		Oil Filter (was LF9080)	1.00
		Coolent Filter Kenworth	1.00
T		FF5776 Fuel Filter	1.00
		Filter Element Gearbox Eaton	1.00
		DIFF FILTER	1.00

Supplier Code	Invoice	Details	Purchase Order	
		OIL 15W-40, CK 4/E9		
		Labour		1.00
				1.00
				1.00
		Consumables		4.00
		Labour		1.00
		Consumables		3.00
		Labour		0.00
		Labour		1.50
				1.50
		Consumables		2.00
		MAINTENANCE KIT		1.00

		OIL 15W-40, CK 4/E9	55.00
		Labour	1.00
		Consumables	3.00
		Labour	1.00
		Consumables	4.00
		Labour	0.75
' LOCTITE LABOUR MECH			
		Labour - Internal	0.75
		Consumables	3.00

ıf Defect :

		Labour	0.00

Supplier Code	Invoice	Details	Purchase Order
		Labour	
UR SUBMEC			
		Labour - Internal	
		Consumables	
		MAINTENANCE KIT	
		Element 10 Micron	
		OIL 15W-40, CK 4/E9	
		Labour	
		Labour - Internal	
		Labour - Internal	
		Consumables	
S01	EX00022737	BALANCE TBR,PM166	EX0002273
S01	EX00022794	BALANCE TBR,PM166	EX0002279
S01	87349731	BALANCE TBR,PM166	EX0002273
S01	87349731A	BALANCE TBR,PM166	EX0002279
. LABOUR			
		Labour	
ıBOUR			
		Labour - Internal	
		Consumables	
		OIL 15W-40, CK 4/E9	
		Labour	

022 Description of Defect :

		Labour	1.50
		Consumables	3.00

		HITECH SYNPLUS 10W50	1.00
		Labour	1.00

Supplier Code	Invoice	Details	Purchase Order
'N FUSE CHECK FENDERS		FOR RUBS, CHAFES ON	
		Consumables	
			2.00
		Labour	0.75
f Defect : DUE 4 B SERVICE			
MECH			
		Labour	0.75
RENDAN			
UR SUBMEC			
		Labour - Internal	0.75
		Consumables	3.00
. LABOUR APPRENB			
		Labour	0.75
		Consumables	3.00
		LONG TAIL SUZI COIL	1.00
		WIRE 7 CORE EBS	1.00
		ELECTRIC SUZI COIL. 4.6M W/LONG TAIL	1.00
		Labour	1.50
		Labour - Internal	1.50
		Consumables	4.00
		MAINTENANCE KIT	1.00
		Element 10 Micron	1.00
		Labour	1.00

Supplier Code	Invoice	Details	Purchase Order
		Labour - Internal	
		Consumables	
		Labour	1.00
		Consumables	2.00
		HITECH SYNPLUS 10W50	1.00
		Labour	1.00
EAR DEFECT 42414 - SERVICE COMPLETED - PLS CLEAR			
ASE CELAR DEFECT 4344 - DOORS ADJUSTED - PLEASE CLEAR			
F DEFECT (ADJUSTMENT MADE BY MICK)			
		Labour - Internal	
			0.50
		Labour - Internal	0.50
		Labour	0.00

ıf Defect : DOORS NEED ADJUSTING

27/01/2022 Description of Defect :

		Labour		
				0.00
		Labour		1.00
				1.00
		Consumables		5.00
		Oil Filter (was LF9080)		1.00
T		FF5776 Fuel Filter		1.00
		Ad Blue filter Kenworth		1.00
		OIL 15W-40, CK 4/E9		48.00
pplier de	Invoice	Details	Purchase Order	

022 Description of Defect :
OR GOING FORWARD - ORIGINALLY ADJUSTED BY MICK 23/05/2022

ı		Labour		1.00
		Consumables		3.00
		Labour		1.00
		Consumables		3.00

ıIN TRANS TEMP, ENG OIL TEMP LIGHTS NOT WORKING

		Labour		0.50
		Consumables		2.00
		AIR FILTER SLEEPER AIR		1.00
		HITECH SYNPLUS 10W50		1.00
		Labour		0.00
		Labour - Internal		1.00
		Labour - Internal		1.00
		Consumables		
		OIL 15W-40, CK 4/E9		
BRIAUS01	EX00024776	PUNCTURE REPAIR TBR,PM166	EX0002477	
BRIAUS01	88209323	PUNCTURE REPAIR TBR,PM166	EX0002477	
		Labour		0.00
		Labour		2.25

		Labour - Internal	2.25
		Consumables	4.00

Supplier Code	Invoice	Details	Purchase Order
		Oil Filter (was LF9080)	
		FF5776 Fuel Filter	
		Ad Blue filter Kenworth	
		OIL 15W-40, CK 4/E9	

. LABOUR

		Labour	1.00
		Consumables	
BRIAUS01	EX00025152	BALANCE TBR,PM166	EX0002515
BRIAUS01	88377826	BALANCE TBR,PM166	EX0002515
BRIAUS01	EX00025174	295/80R22.5 152/148M BS R154 ECO,PM166	EX0002517
BRIAUS01	EX00025174	SCRAP TYRES TBR,PM166	EX0002517
BRIAUS01	EX00025174	ETA MIN FEE,PM166	EX0002517
BRIAUS01	4420435519	295/80R22.5 152/148M BS R154 ECO,PM166	EX0002517
BRIAUS01	4420435519	SCRAP TYRES TBR,PM166	EX0002517
BRIAUS01	4420435519	ETA MIN FEE,PM166	EX0002517
		Labour	
		Labour - Internal	
		Labour - Internal	
		Consumables	
S01	EX00025381	BALANCE TBR,PM166	EX0002538
S01	88484202	BALANCE TBR,PM166	EX0002538
		Labour	
		Labour - Internal	
		Consumables	
		Labour	
		Labour - Internal	
		Consumables	
		AIR FILTER SLEEPER AIR	
		HITECH SYNPLUS 10W50	
IS01	EX00025535	GENERAL PART CODE,XQ33UH	EX0002553
IS01	88537292	GENERAL PART CODE,XQ33UH	EX0002553

Supplier Code	Invoice	Details	Purchase Order
		Labour	0.00
		Labour	1.00

E FITTINGS HAD COME LOOSE AND DROPPED ALL THE POWER STEERING FLUID

	Labour - Internal	2.50
	Consumables	5.00
	MAINTENANCE KIT	1.00
	Element 10 Micron	1.00
	Labour	1.00

		Consumables	3.00
		WIPER REFILL 8MM RUBBER BACKED	2.00
		Labour	4.00
		Labour - Internal	4.00
		Labour - Internal	4.00
		DIFF FILTER	1.00
		Filter Element Gearbox Eaton	1.00
		Power Steer Filter LF637	1.00
		BATT-12V DELKOR	1.00
		Air Filter-Cabin	1.00
		Air Dryer Filter	1.00
		Diff/Gear Oil 80W90 Castrol	34.00
		Labour	1.00

ION. ATTEMPT # 1

ABOUR APPREN

		Labour - Internal	1.00
		Labour	0.50

ECH

		Labour - Internal	0.50
		ENGINE OIL	5.00
		Consumables	4.00
		Labour	1.00

Supplier Code	Invoice	Details	Purchase Order
		Consumables	3.00
		Labour	5.00
		AIR FILTER SLEEPER AIR	1.00
		HITECH SYNPLUS 10W50	1.00
		Consumables	3.00
		Labour	2.00
		MAINTENANCE KIT	1.00
		OIL 15W-40, CK 4/E9	49.00
		Drive Belt, K200	1.00
		M/Ribbed belt (A/C)	1.00
		Consumables	3.00
		Labour	1.25

WARRANTY - TACHO AND FRIDGE

		Labour - Internal	
		BATTERY DEEP CYCLE & TRUCK	
		Consumables	
		Labour	
		Labour	

IRED

		AIR FILTER SLEEPER AIR	
		HITECH SYNPLUS 10W50	
		Fuel Pump	
		Consumables	
		Labour	
		Labour - Internal	

		WIPER BLADE	
		Consumables	
		Labour	
BRIAUS01	EX00026927	11R22.5 148/145L BS M866,	EX0002692
BRIAUS01	EX00026927	CASE STOCK 11-22.5,	EX0002692
BRIAUS01	EX00026927	FIT TBR TYRE,	EX0002692
BRIAUS01	EX00026927	REMOVAL: CUSTOMER PULL POINT,	EX0002692

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	89097960	REMOVAL: CUSTOMER PULL POINT,	EX0002692
BRIAUS01	89097960	FIT TBR TYRE,	EX0002692
BRIAUS01	89097960	CASE STOCK 11-22.5,	EX0002692
BRIAUS01	89097960	11R22.5 148/145L BS M866,	EX0002692
		Labour	
		Consumables	
		Labour	
		Labour	
		Labour	
		Labour - Internal	
		GENERAL PART CODE - FILTER KIT FS13584	
		GENERAL PART CODE - 15W40	
		Consumables	
		Labour	
BRIAUS01	EX00027490	RUNOUT TYRE,PM1466	EX0002749
BRIAUS01	EX00027490	case stock 295/80-22.5,PM166	EX0002749
BRIAUS01	EX00027490	FIT TBR TYRE,PM166	EX0002749
BRIAUS01	EX00027490	REMOVAL: CUSTOMER PULL POINT,PM166	EX0002749
BRIAUS01	EX00027490	BALANCE TBR,PM166	EX0002749
BRIAUS01	89301820	RUNOUT TYRE,PM1466	EX0002749
BRIAUS01	89301820	case stock 295/80-22.5,PM166	EX0002749
BRIAUS01	89301820	FIT TBR TYRE,PM166	EX0002749
BRIAUS01	89301820	REMOVAL: CUSTOMER PULL POINT,PM166	EX0002749
BRIAUS01	89301820	BALANCE TBR,PM166	EX0002749
BRIAUS01	EX00027549	295/80R22.5 152/148M BS R154 ECO,PM166	EX0002754
BRIAUS01	EX00027549	FIT TBR TYRE,PM166	EX0002754
BRIAUS01	EX00027549	BALANCE TBR,PM166	EX0002754
BRIAUS01	EX00027549	JOB DONE BRUCE HWY BP BURPENGARY POS3	EX0002754
BRIAUS01	EX00027549	FS,PM166 JOB DONE BRUCE HWY BP	EX0002754
BRIAUS01	89311073	BURPENGARY POS3 FS,PM166 JOB DONE BRUCE HWY BP	EX0002754
BRIAUS01	89311073	BURPENGARY POS3 FS,PM166 JOB DONE BRUCE HWY BP	EX0002754

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	89311073	BALANCE TBR,PM166	EX0002754
BRIAUS01	89311073	FIT TBR TYRE,PM166	EX0002754
BRIAUS01	89311073	295/80R22.5 152/148M BS R154 ECO,PM166	EX0002754
		Labour	

Labour	0.75
Labour - Internal	0.25
AIR FILTER SLEEPER AIR	1.00

HITECH SYNPLUS 10W50	1.00
Labour	1.00
Labour - Internal	1.00
Consumables	3.00
Labour	0.00
Labour	1.00
Labour - Internal	1.00
Consumables	3.00
Labour	0.00
Labour	1.00
Labour - Internal	1.00
Consumables	3.00

Supplier Code	Invoice	Details	Purchase Order

to be staying at room temperature. Removed bed and bed base. Checked
rder. Removed fridge and sent to authorised repair agent.Removed
s to where fridge goes. Fit hardware as required. Fit fridge to truck. Did not
plug instead. Fit plug and connected up. Secured wiring as necessary.
perature inside fridge ? 2 degrees. Put bunk back together as necessary and

INED SET TEMP.

BROHUR01	EX00028189	Labour External,	EX0002818
BROHUR01	EX00028189	ENVIRONMENTAL LEVY,	EX0002818
BROHUR01	EX00028189	MISCELLANEOUS CONSUMABLES - SUBLET,	EX0002818
BROHUR01	2852570	MISCELLANEOUS CONSUMABLES -	EX0002818
BROHUR01	2852570	SUBLET, ENVIRONMENTAL LEVY,	EX0002818
BROHUR01	2852570	Labour External,	EX0002818
		Labour	
		HITECH SYNPLUS 10W50	
		Consumables	
		Labour	
		Labour	
		Labour - Internal	
		MAINTENANCE KIT	
		ENGINE OIL	
		Consumables	
		Labour	0.00

		Labour	1.00

Supplier Code	Invoice	Details	Purchase Order
RILL R&R WIPERS REPAIR / REPLACEMENT			
		Labour - Internal	
		Consumables	
BROHUR01	EX00029274	GENERAL PART CODE,	EX0002927
BROHUR01	EX00029274	Consumables	EX0002927
BROHUR01	2870596	,	EX0002927
		Consumables	
BROHUR01	2870596	,	EX0002927
		GENERAL PART CODE,	
		Labour	1.00
BOUR MECH 1			
		Labour - Internal	1.00
		1KG FIRE EXTINGUISHER	
		12" 24V 85W REVERSIBLE FAN - CONDENSOR	
		Consumables	
		Labour	
DLLAS01	EX00029023	Wheel Alignment,	EX0002902
DLLAS01	EX00029023	Tyre Repair,	EX0002902
DLLAS01	Q620222	Wheel Alignment,	EX0002902
DLLAS01	Q620222	Tyre Repair,	EX0002902
BRIAUS01	EX00029031	295/80R22.5 152M BS R154,	EX0002903
BRIAUS01	EX00029031	FIT TBR TYRE,	EX0002903
BRIAUS01	EX00029031	TYRE HELD FOR RUNOUT,	EX0002903
BRIAUS01	EX00029031	REMOVAL: WARRANTY CLAIM,	EX0002903
BRIAUS01	EX00029031	REMOVAL: CUSTOMER REQUEST,	EX0002903
BRIAUS01	EX00029031	BALANCE TBR,	EX0002903
BRIAUS01	89799612	FIT TBR TYRE,	EX0002903
BRIAUS01	89799612	295/80R22.5 152M BS R154,	EX0002903
BRIAUS01	89799612	TYRE HELD FOR RUNOUT,	EX0002903
BRIAUS01	89799612	REMOVAL: WARRANTY CLAIM,	EX0002903
BRIAUS01	89799612	REMOVAL: CUSTOMER REQUEST,	EX0002903
BRIAUS01	89799612	BALANCE TBR,	EX0002903
BRIAUS01	EX00029050	B FLEET PRESSURE CHECK,	EX0002905
BRIAUS01	89804586	B FLEET PRESSURE CHECK,	EX0002905
		Labour	1.00

		Consumables	3.00

Supplier Code	Invoice	Details	Purchase Order
		Labour	
		Labour	
		Labour	
		HITECH SYNPLUS 10W50	
		AIR FILTER SLEEPER AIR	
		Consumables	
BRIAUS01	EX00029387	RUNOUT TYRE,	EX0002938
BRIAUS01	EX00029387	FIT TBR TYRE,	EX0002938

BRIAUS01	EX00029387	TYRE HELD FOR RUNOUT,	EX0002938
BRIAUS01	EX00029387	REMOVAL: CUSTOMER REQUEST,	EX0002938
BRIAUS01	89937729	REMOVAL: CUSTOMER REQUEST,	EX0002938
BRIAUS01	89937729	TYRE HELD FOR RUNOUT,	EX0002938
BRIAUS01	89937729	FIT TBR TYRE,	EX0002938
BRIAUS01	89937729	RUNOUT TYRE,	EX0002938
		Labour	0.00

f Defect :

Labour	1.20
Consumables	3.00
TRP KW CAB AIR FILTER	1.00
Labour	0.00
Labour	2.00
Labour - Internal	2.00
Consumables	4.00
MAINTENANCE KIT	1.00
Element 10 Micron	1.00
Air Filter	1.00
OIL 15W-40, CK 4/E9	48.00
Labour	0.00

Supplier Code	Invoice	Details	Purchase Order
QUAWIND01	EX00029794	SUPPLY AND FIT FRONT WINDSCREEN RHS	EX0002979
QUAWIND01	6833	KENWORTH K200, SUPPLY AND FIT FRONT	EX0002979
		WINDSCREEN RHS KENWORTH K200,	
		Labour	1.00

023.

INGUISHED.

Labour - Internal	1.00
Consumables	3.00
Labour	0.00
Labour	0.00

3/2023 Description of Defect :
OFF

LINE FITTING. LABOUR MECH

Labour	1.00

LINE FITTING.

Consumables	3.00
AIRLINE FITTING	1.00
Labour	0.00
Labour	2.00

EMBLE AND ADJUST

	Consumables	4.00
	CR SEAL - HUB SEAL	1.00
	GASKET SUIT HUB CAP SEAL 1613 (Exodas Stock)	1.00
	Labour	1.00

/08/2023.

Supplier Code	Invoice	Details	Purchase Order
		Labour - Internal	
		Labour - Internal	
		OIL 15W-40, CK 4/E9	
		Consumables	
		Labour	

f Defect :

. LABOUR

	Labour	0.00

f Defect :

03/09/2023

ABOUR MECH	Labour	1.50
	Consumables	6.00
	AIR SCOOP	1.00
	VDO SWITCH / PRESSURE SWITCH	1.00

Supplier Code	Invoice	Details	Purchase Order

. AIR GAUGE:

Labour		0.00

023 Description of Defect :

N LIGHTS ARE ON.

f Defect : REFERENCE TO

TH PM166 ELECTRICAL LEAD

	Labour	1.00

CHECKED AND REPLACED

	Labour - Internal	1.00
	Eurocoil-7 Core Suzi Coil Long Tail	1.00
	Labour	1.00

023. CARRIED OUT 'A' SERVICE.

	Labour - Internal	1.00
	Consumables	3.00
	Labour	0.00
	Labour	0.00

Supplier Code	Invoice	Details	Purchase Rate	Units Extension

ence : 07111 Date : 10/09/2023

CARRIED OUT 'A' SERVICE.

	Labour	1.00
	Consumables	3.00
	OIL 15W-40, CK 4/E9	1.00
	AIR FILTER SLEEPER AIR	1.00
	Labour	0.00
	Labour	0.75

ADDED COOLANT

P ON DASH

	Labour - Internal	0.75
	Consumables	3.00
	COOLANT	1.50

. LABOUR MECH

	Labour	0.00

	Labour	1.50

09/2023.

ENJ

	Labour - Internal	1.50
	Labour - Internal	1.50
	Consumables	4.00
	MAINTENANCE KIT	1.00
	OIL 15W-40, CK 4/E9	50.00
	Labour	0.00

Supplier Code	Invoice	Details	Purchase Units	Rate

2023 Description of Defect :
R / REPLACEMENT

BRIAUS01	EX00030636	ROTATE TBR TYRE,	EX0003063
BRIAUS01	EX00030636	SCHEDULED DEPOT SERVICE 15MIN,	EX0003063
BRIAUS01	EX00030636	FLIP TRUCK TYRE OR RETREAD,	EX0003063
BRIAUS01	187382302	FLIP TRUCK TYRE OR RETREAD,	EX0003063
BRIAUS01	187382302	SCHEDULED DEPOT SERVICE 15MIN,	EX0003063
BRIAUS01	187382302	ROTATE TBR TYRE,	EX0003063

.

	Labour	0.75

H ON 18/10/2023.

ING OR BEING LOOSE. COULDN'T FAULT SHAKED CAB TO TRY SIMULATE A THUD BUT COULDN'T

	Labour - Internal	0.75
	Labour - Internal	0.75
	Consumables	4.00
	OIL 15W-40, CK 4/E9	4.00
	Labour	0.00

03/05/2023 Description of Defect :
O OR SPRING MAYBE.

HING FOUND LABOUR

	Labour	1.00

Supplier Code	Invoice	Details	Purchase Order
		Consumables	
		Labour	

09/11/2023 Description of Defect :
CED RAG OVER FOR A FILTER. CAP IS IN TOOLBOX ON PRIME MOVER.

HER TUBES
Labour

HER TUBES
Consumables

.
00 SERIES TRUCK KIT DUAL HEIGHT EX0003146

CONTROL,
EMAX01 EX00031466 Transtech lead for IVU, EX0003146
EMAX01 EX00031466 12V BYPASS KIT, EX0003146
01 EX00031466 Airweigh Airline Fitting for Kenworth, EX0003146
1 EX00031466 Airweigh Truck Installation, EX0003146
1 7130344 Airweigh Truck Installation, EX0003146
01 7130344 Airweigh Airline Fitting for Kenworth, EX0003146
EMAX01 7130344 12V BYPASS KIT, EX0003146
EMAX01 7130344 Transtech lead for IVU, EX0003146
00 SERIES TRUCK KIT DUAL HEIGHT EX0003146

Labour

4/11/2023.

Labour - Internal
Labour - Internal
Consumables
Labour

23.

Labour - Internal

Supplier Code	Invoice	Details	Purchase Order
		Consumables	
		Turbo 2000 Air dryer	
		Coolent Filter Kenworth	
		Power Steer Filter LF637	
		TRP KW CAB AIR FILTER	
		Filter Element Gearbox Eaton	
		DIFF FILTER	
		Syntrans Gear Oil 75w-90	
		Diff/Gear Oil 80W90 Castrol	
		REPLACEMENT ELEMENT INLINE FILTER	
		Labour	
		Labour	
		Labour	

: : SERVICE DUE

	Labour	1.00

3.

Consumables	3.00
Fuel Filter Eco Wind	1.00
Fuel/Water seperator filter	1.00
Eco Oil Filter Cartridge	1.00
AIR FILTER SLEEPER AIR	1.00
HITECH SYNPLUS 10W50	1.00
BS358N 70 O-RING 142.24 X 5.3	1.00
Labour	3.50

ION. ATTEMPT # 1

./2023 NO FAULTS APPARENT

Labour - Internal	3.50

3RIAUS01	EX00031617	RUNOUT TYRE,	EX0003161

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	EX00031617	FIT TBR TYRE,	EX0003161
BRIAUS01	EX00031617	REMOVAL: TREAD CUT OR CHUNKING,	EX0003161
BRIAUS01	187711939	REMOVAL: TREAD CUT OR CHUNKING,	EX0003161
BRIAUS01	187711939	FIT TBR TYRE,	EX0003161
BRIAUS01	187711939	RUNOUT TYRE,	EX0003161
REDTRU01	EX00031725	Labour,	EX0003172
REDTRU01	EX00031745	FABRICATE BRACKET TO HOLD MIRROR	EX0003174
REDTRU01	EX00031752	BRACKET TO DOOR,STRAIGHTEN MIRROR BRACKET, MIRROR AND TOP REVERSE LIGHT MIRROR BRACKET FABRICATION,	EX0003175
REDTRU01	EX00031725	Consumables	EX0003172
REDTRU01	EX00031745	, Consumables	EX0003174
REDTRU01	EX00031752	, Consumables	EX0003175
REDTRU01	29769	, Labour,	EX0003172
REDTRU01	29769A	Consumables	EX0003174
REDTRU01	29769R	, Consumables	EX0003175
REDTRU01	29769	, Consumables	EX0003172
REDTRU01	29769A	, FABRICATE BRACKET TO HOLD MIRROR BRACKET TO DOOR,STRAIGHTEN MIRROR BRACKET, MIRROR AND TOP REVERSE LIGHT MIRROR BRACKET FABRICATION,	EX0003174
REDTRU01	29769R	Labour	EX0003175

: :
EAR COUPLING

Labour	1.50

:ED SUZI COIL

Consumables	4.00
Suzi Coil Long	1.00
Labour	0.00

Supplier Code	Invoice	Details	Purchase Order
		Labour	1.50

)E ON 20/12/2023.

/INDOW. CARRY OUT 'B'

		Labour - Internal	1.50
		Labour - Internal	0.75
		Labour - Internal	0.75
		Consumables	
		MAINTENANCE KIT	
		WELDEX LED LIGHT	
		OIL 15W-40, CK 4/E9	
		Spotter mirror 7" inch	
ARRTRA01	EX00032045	REMOVE & REFIT GRAB HANDLES, MIRROR	EX0003204
ARRTRA01	EX00032045	FRAME AND ACCESSORIES. REPAIR DENT TO RH CAB SIDE PANEL,& REPAIR RH TOP DOOR FRAME RH TOP MIRROR BRACKET TO DOOR,	EX0003204
ARRTRA01	11777	RH TOP MIRROR BRACKET TO DOOR,	EX0003204
ARRTRA01	11777	REMOVE & REFIT GRAB HANDLES, MIRROR FRAME AND ACCESSORIES. REPAIR DENT TO RH CAB SIDE PANEL,& REPAIR RH TOP DOOR FRAME	EX0003204
		Labour	

27/12/2023 Description of Defect :
D.
GHTS, BRAKES & INDICATORS

Labour

LACED WEATHERSHIELD DRIVERS SIDE

Consumables

		Weathershield RHS K200	
BROHUR01	EX00032052	Weathershield RHS K200,	EX0003205
BROHUR01	3083701	Weathershield RHS K200,	EX0003205

Supplier Code	Invoice	Details	Purchase Order	
		Labour		0.50
		Labour - Internal		0.50
		Consumables		3.00
		Labour		1.00

REPLACED

' NO. 00010803 CREATED

		Labour - Internal	
		Consumables	
CBRDIE01	EX00032759	NEXT GENERATION PREM - BATTERY N70ZZ,	EX0003275
CBRDIE01	EX00032919	TEST & REPLACE BATTERIES,	EX0003291
REDTRU01	EX00032922	TEST & REPLACE BATTERIES,	EX0003292
CBRDIE01	EX00032759	TESTED BATTERIES & FOUND THEY NEEDED	EX0003275
CBRDIE01	EX00032919	REPLACING. REPLACED 4 BATTERIES. TESTED. BATTERIES CHARGING AT 14 VOLTS, BATTERY,	EX0003291
REDTRU01	EX00032922	NGP95D31R NEXT GENERATION PREM	EX0003292
CBRDIE01	INV-0090	- BATTERY N70ZZ, TESTED BATTERIES & FOUND THEY	EX0003275

		NEEDED REPLACING. REPLACED 4 BATTERIES. TESTED. BATTERIES CHARGING AT 14 VOLTS, TEST & REPLACE BATTERIES,	
CBRDIE01	INV-0090R		EX0003291
REDTRU01	INV-0090	TEST & REPLACE BATTERIES,	EX0003292
CBRDIE01	INV-0090	NEXT GENERATION PREM - BATTERY N70ZZ,	EX0003275
CBRDIE01	INV-0090R	BATTERY,	EX0003291
REDTRU01	INV-0090	NGP95D31R NEXT GENERATION PREM - BATTERY N70ZZ,	EX0003292
		Labour	1.00

ECT NO. 00010936 CREATED
. DEFECT NO. 00010937 CREATED
(13/02/2024). DEFECT NO. 00010938 CREATED

	Consumables	4.00
	Labour	0.00
	Labour	0.00

Supplier Code	Invoice	Details	Purchase Order
		Labour	2.00

2/2024. WROTE DATE ON

7 CREATED LABOUR MECH 4

	Labour - Internal	2.00
	Consumables	3.00
	MAINTENANCE KIT	2.00
	OIL 15W-40, CK 4/E9	52.00
	Labour	0.00

: 15/02/2024 Description of

ONE. (13/02/2024)

BRIAUS01	EX00033328	RUNOUT TYRE,	EX0003332
BRIAUS01	EX00033328	FIT TBR TYRE,	EX0003332
BRIAUS01	EX00033328	REMOVAL: CUSTOMER PULL POINT,	EX0003332
BRIAUS01	188316226	RUNOUT TYRE,	EX0003332
BRIAUS01	188316226	FIT TBR TYRE,	EX0003332
BRIAUS01	188316226	REMOVAL: CUSTOMER PULL POINT,	EX0003332
		Labour	

R REPAIRS ON 27/03/2024. INVOICE NO. INV-0196

REATED FOR BRAKES

ECT NO. 00011178 CREATED

REDTRU01	EX00033587	CARRY OUT 'A' SERVICE,	EX0003358
REDTRU01	EX00033587	OIL 15W-40, CK 4/E9,	EX0003358
REDTRU01	INV-0196	CARRY OUT 'A' SERVICE,	EX0003358
REDTRU01	INV-0196	OIL 15W-40, CK 4/E9,	EX0003358
		Labour	
		Labour	

Supplier Code	Invoice	Details	Purchase Order

of Defect :
:

: 29/02/2024

: 31/01/2024

ABOUR MECH		Labour	2.00
)24. REPLACED .			
TIGHTED	Labour - Internal		
			2.00
		Consumables	4.00
		Kit Q-Plus Brake Shoe	
BRIAUS01	EX00033701	11R22.5 148/145L BS M749II ECO,CUSTOMERS	EX0003370
BRIAUS01	EX00033701	OWN STOCK CASE STOCK 11R22.5 ECOPIA,	EX0003370
BRIAUS01	EX00033701	FIT TBR TYRE,	EX0003370
BRIAUS01	EX00033701	TYRE HELD FOR RUNOUT,	EX0003370
BRIAUS01	EX00033701	REMOVAL: CUSTOMER PULL POINT,	EX0003370
BRIAUS01	EX00033701	REMOVAL: CUSTOMER REQUEST,	EX0003370
BRIAUS01	EX00033701	SCHEDULED DEPOT SERVICE 15MIN,	EX0003370
BRIAUS01	188411855	11R22.5 148/145L BS M749II ECO,CUSTOMERS	EX0003370
BRIAUS01	188411855	OWN STOCK CASE STOCK 11R22.5 ECOPIA,	EX0003370
BRIAUS01	188411855	FIT TBR TYRE,	EX0003370
BRIAUS01	188411855	TYRE HELD FOR RUNOUT,	EX0003370
BRIAUS01	188411855	REMOVAL: CUSTOMER PULL POINT,	EX0003370
BRIAUS01	188411855	REMOVAL: CUSTOMER REQUEST,	EX0003370

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	188411855	SCHEDULED DEPOT SERVICE 15MIN,	EX0003370
		Labour	1.00

: ON 10/04/2024. REPLACED

XT CHECKED - IN DATE

	Labour - Internal	1.00
	Labour - Internal	1.00
	Consumables	4.00
	Oil Filter (was LF9080)	1.00
	Labour	0.00

27/03/2024

BRIAUS01	EX00033879	295/80R22.5 152/148M BS R154 ECO,	EX0003387
BRIAUS01	EX00033879	case stock 295/80-22.5,	EX0003387
BRIAUS01	EX00033879	FIT TBR TYRE,	EX0003387
BRIAUS01	EX00033879	REMOVAL: CUSTOMER PULL POINT,	EX0003387
BRIAUS01	EX00033879	SCHEDULED DEPOT SERVICE 15MIN,	EX0003387
BRIAUS01	188472897	295/80R22.5 152/148M BS R154 ECO,	EX0003387
BRIAUS01	188472897	case stock 295/80-22.5,	EX0003387
BRIAUS01	188472897	FIT TBR TYRE,	EX0003387
BRIAUS01	188472897	REMOVAL: CUSTOMER PULL POINT,	EX0003387
BRIAUS01	188472897	SCHEDULED DEPOT SERVICE 15MIN,	EX0003387
BRIAUS01	EX00033943	RUNOUT TYRE,	EX0003394
BRIAUS01	EX00033943	FIT TBR TYRE,	EX0003394
BRIAUS01	EX00033943	TYRE HELD FOR RUNOUT,	EX0003394
BRIAUS01	EX00033943	REMOVAL: CUSTOMER REQUEST,	EX0003394
BRIAUS01	EX00033943	SVC CALL OUT NORMAL HOURS/15MINS,	EX0003394
BRIAUS01	188502252	RUNOUT TYRE,	EX0003394
BRIAUS01	188502252	FIT TBR TYRE,	EX0003394
BRIAUS01	188502252	TYRE HELD FOR RUNOUT,	EX0003394
BRIAUS01	188502252	REMOVAL: CUSTOMER REQUEST,	EX0003394
BRIAUS01	188502252	SVC CALL OUT NORMAL HOURS/15MINS,	EX0003394
BRIAUS01	EX00033972	RUNOUT TYRE,	EX0003397

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	EX00033972	FIT TBR TYRE,	EX0003397
BRIAUS01	EX00033972	TYRE HELD FOR RUNOUT,	EX0003397
BRIAUS01	EX00033972	REMOVAL: CUSTOMER REQUEST,	EX0003397
BRIAUS01	EX00033972	SCHEDULED DEPOT SERVICE 15MIN,	EX0003397
BRIAUS01	188515469	RUNOUT TYRE,	EX0003397
BRIAUS01	188515469	FIT TBR TYRE,	EX0003397
BRIAUS01	188515469	TYRE HELD FOR RUNOUT,	EX0003397
BRIAUS01	188515469	REMOVAL: CUSTOMER REQUEST,	EX0003397
BRIAUS01	188515469	SCHEDULED DEPOT SERVICE 15MIN,	EX0003397
		Labour	1.00

)5/2024. REPAIR LIGHT PLUS

	Labour - Internal	1.00
	Consumables	4.00
	Labour	0.00
	Labour	0.00
	Labour	3.00

/2024.

.1482 CREATED

Labour - Internal	3.00
Consumables	5.00
MAINTENANCE KIT	1.00
OIL 15W-40, CK 4/E9	51.00
Labour	0.00

:R REPAIRS ON 10/06/2024. INVOICE NO. INV-0390

DEFECT NO. 00011704 CREATED.

REDTRU01	EX00034678	CARRIED OUT 'A' SERVICE,	EX0003467
REDTRU01	INV-0390	CARRIED OUT 'A' SERVICE,	EX0003467
		Labour	

Supplier Code	Invoice	Details	Purchase Order

'. AIR GAUGE: 14500

'. LABOUR APPREN

	Labour	1.00

'07/2024. NHVR STICKER BEEN

	Labour - Internal	1.00
	Consumables	6.00
	Labour	0.00

of Defect :
ξ ONE

:VICE

: 16/05/2024 Description of

'. LABOUR APPREN

	Labour	0.50

BEN ON 16/07/2024.

	Labour - Internal	0.50
	Labour - Internal	0.50
	Labour - Internal	0.50

Supplier Code	Invoice	Details	Purchase Order
		Labour - Internal	
		Consumables	
		Labour	
BRIAUS01	EX00035627	PUNCTURE REPAIR TBR,	EX0003562
BRIAUS01	EX00035627	JOB DONE BRUCE HWY BP BURPENGARY POS3	EX0003562
BRIAUS01	EX00035627	FS, JOB DONE BRUCE HWY BP	EX0003562
BRIAUS01	189052143	BURPENGARY POS3 FS, PUNCTURE REPAIR TBR,	EX0003562
BRIAUS01	189052143	JOB DONE BRUCE HWY BP BURPENGARY POS3	EX0003562
BRIAUS01	189052143	FS, JOB DONE BRUCE HWY BP	EX0003562
		BURPENGARY POS3 FS,	
		Labour	0.00
		Labour	1.00

)P) ON 07/08/2024.

	Labour - Internal	1.00
	Labour - Internal	1.00
	Consumables	3.00

MAINTENANCE KIT		1.00
OIL 15W-40, CK 4/E9		51.00
Labour		0.00
Labour		0.00

Labour	1.00

SHOP) ON 07/08/2024.

Labour - Internal	1.00
Consumables	3.00
HITECH SYNPLUS 10W50	1.00
AIR FILTER SLEEPER AIR	1.00
Labour	5.00

ON 11/09/2024.

AND NEW OIL CAP FITTED NEW RUBBERS FITTED TO PASSENGER SIDE REAR DRIVE SHOCKIE

TTOM SKIRT STRAIGHTENED.

Consumables	3.00
Shock Absorber -Koni,Front	2.00
CR SEAL - HUB SEAL	1.00

Supplier Code	Invoice	Details	Purchase Order
		CAP FRONT HUB	
		Labour	
BROHUR01	EX00036518	Shock Absorber -Koni,Front,	EX0003651
BROHUR01	EX00036518	TANK STRAP RUBBER 50MM,	EX0003651
BROHUR01	3317802	TANK STRAP RUBBER 50MM,	EX0003651
BROHUR01	3317802	Shock Absorber -Koni,Front,	EX0003651
		Labour	

ABERG ON 28/09/2024. INVOICE NO. 3344108

e breakdown near Miriam Vale ; collect parts & equipment from
on site; inspect air system; confirm vehicle losing & failing to
failed valve; confirm piston unserviceable; free up unloader valve
gine; confirm vehicle successfully building air & retaining levels;

lacing at the nearest convenience

BROHUR01	EX00036570	Call Out After Hours/Off Site,	EX0003657
BROHUR01	EX00036570	PARTS CALLOUT FEE,	EX0003657
BROHUR01	EX00036570	GOVERNOR D2 TRP,	EX0003657
BROHUR01	EX00036570	TROUBLESHOOT HARD TO BUILD AIR	EX0003657
BROHUR01	EX00036570	COMPLAINT, Consumables	EX0003657
BROHUR01	EX00036570	, ENVIRONMENTAL LEVY,	EX0003657
BROHUR01	3344108	Call Out After Hours/Off Site,	EX0003657
BROHUR01	3344108	PARTS CALLOUT FEE,	EX0003657
BROHUR01	3344108	GOVERNOR D2 TRP,	EX0003657
BROHUR01	3344108	TROUBLESHOOT HARD TO BUILD AIR	EX0003657
BROHUR01	3344108	COMPLAINT, Consumables	EX0003657
BROHUR01	3344108	, ENVIRONMENTAL LEVY,	EX0003657
		Labour	
		Labour	

K (WORKSHOP) ON 09/10/2024.

		Labour - Internal	1.50

Supplier Code	Invoice	Details	Purchase Order
		LABOUR - INTERNAL	
		Consumables	
		MAINTENANCE KIT	
		OIL 15W-40, CK 4/E9	
		Labour	

of Defect :

OUT

		Labour	0.00
		Labour	5.50

LY FOR TURBO REPLACED O-
ED AIR COMPRESSOR
MP LABOUR MECH 5

		Labour - Internal	5.50
		Consumables	8.00
		Gasket, Exhaust Flex, K200	1.00
		RECON TURBOCHARGER KIT	1.00
		GASKET ACC DRIVE SUPPORT	1.00
		AIR COMPRESSOR SX, RECONDITIONED CORE	1.00
		PUMP DOSER	1.00
		Turbo Mount Gasket	1.00
		Labour	0.00

f Defect :

Supplier Code	Invoice	Details	Purchase Order

/2024. INVOICE NO. GC-RIN08127

connected low side pressure cutting in and out suggesting low gas. System was then

hecked for leaks. Service valves checked and replaced as one had a slightly damaged O-
efrigerant. Vehicle run up and operation checked. Gauges checked and noticed low side

l along with dryer/ Operation of vehicle was checked. Vent temp getting down to 8deg.

RUCK A/C BLOWING HOT.

) REPAIR,
EC01 EX00037504 Travel Fee to Breakdowns, EX0003750

BDSMEC01 EX00037504 R134A, A/C GAS, EX0003750
EC01 EX00037504 NITROGEN PRESSURE TEST, EX0003750
EC01 EX00037504 Consumables EX0003750
EX0003750
EC01 GC-RIN08127 Consumables

EC01 GC-RIN08127 NITROGEN PRESSURE TEST, EX0003750
BDSMEC01 GC-RIN08127 R134A, A/C GAS, EX0003750
EC01 GC-RIN08127 Travel Fee to Breakdowns, EX0003750
UCK A/C BLOWING HOT. EX0003750

Labour

KSHOP) ON 09/11/2024.

W HORTON FAN IS PUT ON

Labour - Internal	0.50
Consumables	3.00
Labour	0.00

Supplier Code	Invoice	Details	Purchase Order

f Defect :

28/09/2024 Description of Defect :
REGULATOR ON COMRESSOR AND HE SAID THAT IT'S DUE FOR COMPRESSOR

Labour 0.00

Labour 3.50

Consumables 4.00

HT/S SUPER DUTY OEM KIT 1.00
Labour 0.50
P) ON 05/12/2024.

Labour - Internal 0.50

Consumables 3.00
1.5KG FIRE EXTINGUISHER 1.00
Labour 2.00
/12/2024.

Labour - Internal 2.00

Consumables 5.00
Turbo 2000 Air dryer 1.00
ES Water Filter 1.00
Power Steer Filter LF637 1.00

		DIFF FILTER	1.00
		TRANS DYNADRIVE LL 80W90	34.00
		17237 Gearbox Filter	1.00
		TRANS MAN HVY DUTY 75W90 205L	12.00
		TRP KW CAB AIR FILTER	1.00

Supplier Code	Invoice	Details	Purchase Order
		REPLACEMENT ELEMENT INLINE FILTER	
		Labour	
		Labour	
		Labour	
		Labour	

		Labour	
KSHOP) ON 05/12/2024.			
		Consumables	3.00
		Air Filter Sleeper Air	1.00
		Oil Filter Eco/Sleeper	1.00
		Fuel Filter (Sleeper Air)	1.00
		Fuel/Water seperator filter	1.00
		HITECH SYNPLUS 10W50	1.00
		BS358N 70 O-RING 142.24 X 5.3	1.00
		Labour	2.50

ION. ATTEMPT # 1

J 05/12/2024

		Labour - Internal	
BROHUR01	EX00037671	FLYWHEEL MACHINED - B&H,	EX0003767
BROHUR01	EX00037671	Consumables	EX0003767
BROHUR01	EX00037671	, ENVIRONMENTAL LEVY,	EX0003767
BROHUR01	3409210	FLYWHEEL MACHINED - B&H,	EX0003767
BROHUR01	3409210	Consumables	EX0003767
BROHUR01	3409210	, ENVIRONMENTAL LEVY,	EX0003767

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	EX00037751	295/80R22.5 152/148M BS R154 ECO,	EX0003775
BRIAUS01	EX00037751	case stock 295/80-22.5,	EX0003775
BRIAUS01	EX00037751	FIT TBR TYRE,	EX0003775
BRIAUS01	EX00037751	REMOVAL: CUSTOMER PULL POINT,	EX0003775
BRIAUS01	EX00037751	SCHEDULED DEPOT SERVICE 15MIN,	EX0003775
BRIAUS01	189842273	295/80R22.5 152/148M BS R154 ECO,	EX0003775
BRIAUS01	189842273	case stock 295/80-22.5,	EX0003775
BRIAUS01	189842273	FIT TBR TYRE,	EX0003775
BRIAUS01	189842273	REMOVAL: CUSTOMER PULL POINT,	EX0003775
BRIAUS01	189842273	SCHEDULED DEPOT SERVICE 15MIN,	EX0003775
		Labour	

1/12/2024.

EAK

Labour - Internal	0.17
Consumables	5.00
OIL 15W-40, CK 4/E9	5.00
Labour	0.00
Labour	0.00
Labour	1.00

)OSH (WORKSHOP) ON 24/01/2025.

3RACKET.

NEED AIR DRYER FILTER

Labour - Internal	1.00
Labour - Internal	1.00
Labour - Internal	1.00
Consumables	4.00
MAINTENANCE KIT	1.00
OIL 15W-40, CK 4/E9	50.00
Labour	0.00
Labour	0.00

Supplier Code	Invoice	Details	Purchase Order

of Defect :
:ANKING - NOT CHARGING

ERIES
'0ZZ - 12 VOLT 750CCA PREDATOR EX0003843

Labour

'0ZZ - 12 VOLT 750CCA PREDATOR EX0003843

)8/02/2025.

Consumables

BATTERY DEEP CYCLE & TRUCK

PMPA0 EX00038483 CHECK OUT BATTERY FAILURE. EX0003848
RIES. BATTERIES SUPPLIED BY LEE MACKAY, EX0003848
PMPA0 2260 CHECK OUT BATTERY FAILURE.

PLIED BY LEE MACKAY,

Labour - Internal

HOP) ON 22/02/2025.

IOLE AIR KIT. REPLACED LHS NUT COVERS AND HUBCAPS

Consumables

Labour - Internal

Labour

Supplier Code	Invoice	Details	Purchase Order

of Defect :

NEED AIR DRYER FILTER

: 21/12/2024 Description of Defect :

	Labour - Internal	1.00
Consumables		3.00
	Labour - Internal	1.00
	Labour	0.00
	Labour - Internal	0.00
Consumables		0.00
	Labour - Internal	4.00

OSX SPECS REPLACED FUEL PRO

RING IN LHS DOOR PEEP WINDOW

Consumables

		5.00
		4.00
	SERVICE KIT	1.00
	OIL 15W-40, CK 4/E9	51.00
	AIR OIL FILTER	1.00
	Turbo 2000 Air dryer	1.00
	Jaw Repair Kit JSK37/42	1.00
	Element 10 Micron	1.00

Supplier Code	Invoice	Details	Purchase Order
		Labour	0.00

of Defect :

: 22/02/2025

	Labour - Internal	1.00

		Consumables	6.00
		Labour - Internal	1.00
		Labour - Internal	1.00
		Labour	0.00
		Labour	0.00
		Labour	0.50
		Consumables	3.00
		Labour - Internal	0.50
		HITECH SYNPLUS 10W50	1.00
		Air Filter Sleeper Air	1.00
		Labour	0.00

MABYE BLOCKING BREATHER

		Labour	0.50

Supplier Code	Invoice	Details	Purchase Order
EMOVE BUILD UP		OF CRYSTALS	
		Consumables	3.00
		Labour - Internal	1.00

ALL DRIVE SHOCKS

		Consumables	5.00
		Labour - Internal	2.00
		Labour - Internal	2.50
		Hub Cap, Steers	1.00
		SHOCK AB KW AIRGLIDE	4.00
		Labour	0.00

BRIAUS01	EX00040329	PUNCTURE REPAIR TBR,	EX0004032
BRIAUS01	EX00040329	SCHEDULED DEPOT SERVICE 15MIN,	EX0004032
BRIAUS01	190785454	PUNCTURE REPAIR TBR,	EX0004032
BRIAUS01	190785454	SCHEDULED DEPOT SERVICE 15MIN,	EX0004032
		Labour - Internal	1.00
		Consumables	4.00
		Labour - Internal	1.00
		Labour	0.00

		Labour - Internal	0.00

		Consumables	
Supplier Code	Invoice	Details	Purchase Order
		Labour - Internal	4.00
		Consumables	8.00
		Labour - Internal	4.00
		Labour - Internal	2.00
		SERVICE KIT	1.00
		AIR OIL FILTER	1.00
		OIL 15W-40, CK 4/E9	51.00
		AIR FILTER	1.00
		Seal - Drive	1.00
		Kit Q-Plus Brake Shoe	4.00
		Labour	0.00
		Labour	0.00
		Labour	1.00
		Consumables	
		AIR FILTER SLEEPER AIR	
		HITECH SYNPLUS 10W50	
BRIAUS01	EX00041212	295/80R22.5 152/148M BS R154 ECO,	EX0004121
BRIAUS01	EX00041213	295/80R22.5 152/148M BS R154 ECO,	EX0004121
BRIAUS01	EX00041220	295/80R22.5 152/148M BS R154 ECO,	EX0004122
BRIAUS01	EX00041212	FIT TBR TYRE,	EX0004121
BRIAUS01	EX00041213	FIT TBR TYRE,	EX0004121
BRIAUS01	EX00041220	FIT TBR TYRE,	EX0004122
BRIAUS01	EX00041212	CUSTOMER SCRAPPED OWN TYRE,	EX0004121
BRIAUS01	EX00041213	CUSTOMER SCRAPPED OWN TYRE,	EX0004121
BRIAUS01	EX00041220	CUSTOMER SCRAPPED OWN TYRE,	EX0004122
BRIAUS01	EX00041212	REMOVAL: IRR WEAR OR ALIGNMENT,	EX0004121
BRIAUS01	EX00041213	REMOVAL: IRR WEAR OR ALIGNMENT,	EX0004121
BRIAUS01	EX00041220	REMOVAL: IRR WEAR OR ALIGNMENT,	EX0004122
BRIAUS01	EX00041212	ETA MIN FEE,	EX0004121
BRIAUS01	EX00041213	ETA MIN FEE,	EX0004121
BRIAUS01	EX00041220	EQUAL POWDER - DROP IN,	EX0004122
BRIAUS01	EX00041212	POS 1,2 WORK COMPLETE 30.07.2025,	EX0004121
BRIAUS01	EX00041213	POS 1,2 WORK COMPLETE	EX0004121

		30.07.2025,	
Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	EX00041220	POS 1,2 WORK COMPLETE	EX0004122
BRIAUS01	191078539	30.07.2025, 295/80R22.5 152/148M BS R154 ECO,	EX0004121
BRIAUS01	191078976	295/80R22.5 152/148M BS R154 ECO,	EX0004121
BRIAUS01	EX00041220	ETA MIN FEE,	EX0004122
BRIAUS01	191078539	FIT TBR TYRE,	EX0004121
BRIAUS01	191078976	FIT TBR TYRE,	EX0004121
BRIAUS01	191079006	295/80R22.5 152/148M BS R154 ECO,	EX0004122
BRIAUS01	191078539	CUSTOMER SCRAPPED OWN TYRE,	EX0004121
BRIAUS01	191078976	CUSTOMER SCRAPPED OWN TYRE,	EX0004121
BRIAUS01	191079006	FIT TBR TYRE,	EX0004122
BRIAUS01	191078539	REMOVAL: IRR WEAR OR ALIGNMENT,	EX0004121
BRIAUS01	191078976	REMOVAL: IRR WEAR OR ALIGNMENT,	EX0004121
BRIAUS01	191079006	CUSTOMER SCRAPPED OWN TYRE,	EX0004122
BRIAUS01	191078539	ETA MIN FEE,	EX0004121
BRIAUS01	191078976	ETA MIN FEE,	EX0004121

BRIAUS01	191079006	REMOVAL: IRR WEAR OR ALIGNMENT,	EX0004122
BRIAUS01	191078539	POS 1,2 WORK COMPLETE 30.07.2025,	EX0004121
BRIAUS01	191078976	POS 1,2 WORK COMPLETE	EX0004121
BRIAUS01	191079006	30.07.2025, EQUAL POWDER - DROP IN,	EX0004122
BRIAUS01	191079006	POS 1,2 WORK COMPLETE 30.07.2025,	EX0004122
BRIAUS01	191079006	ETA MIN FEE,	EX0004122
		Labour - Internal	3.00

R EXHAUST PART ADJUST CLUTCH

		Consumables	4.00
		Labour - Internal	3.00
		VALVE-AIR HORN	1.00
		Labour	1.00

3/8/2025

		OIL 15W-40, CK 4/E9	
		KOHLER AIR FILTER	
		Consumables	
BRIAUS01	EX00041482	11R22.5 148/145L BS M866,	EX0004148
BRIAUS01	EX00041482	CASE STOCK 11-22.5,	EX0004148
BRIAUS01	EX00041482	FIT TBR TYRE,	EX0004148
BRIAUS01	EX00041482	REMOVAL: CUSTOMER PULL POINT,	EX0004148

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	EX00041482	SCHEDULED DEPOT SERVICE 15MIN,	EX0004148
BRIAUS01	191165733	11R22.5 148/145L BS M866,	EX0004148
BRIAUS01	191165733	CASE STOCK 11-22.5,	EX0004148
BRIAUS01	191165733	FIT TBR TYRE,	EX0004148
BRIAUS01	191165733	REMOVAL: CUSTOMER PULL POINT,	EX0004148
BRIAUS01	191165733	SCHEDULED DEPOT SERVICE 15MIN,	EX0004148
		Labour - Internal	1.00

EATER TAP

	Consumables	5.00
	Labour - Internal	1.00
	12" 24V 85W REVERSIBLE FAN - CONDENSOR	1.00
	Labour - Internal	0.00
	Consumables	0.00
	Labour - Internal	2.00
	Consumables	4.00
	Labour - Internal	2.00
	Labour - Internal	2.00
	OIL 15W-40, CK 4/E9	51.00
	SERVICE KIT	1.00
	AIR OIL FILTER	1.00
	Labour - Internal	0.00
	Consumables	3.00

Labour - Internal	2.50
Labour - Internal	2.75
Wiper Control Stalk	1.00
Labour	0.00

Supplier Code	Invoice	Details	Purchase Order

n of Defect :
ΓO BE FIXED

12/10/2025 Description of Defect

Labour	0.00

ıf Defect :

ɛEAT FAULT LABOUR MECH 5

Labour	3.00

ʻ

		Consumables	
		Labour - Internal	
BDSMEC01	EX00042543	Call Out After Hours/Off Site,	EX0004254
BDSMEC01	EX00042543	Labour External,TRAVEL TO SITE INSPECT AIR	EX0004254
BDSMEC01	EX00042543	LEAK AND REPAIR WORKSHOP CONSUMABLES,	EX0004254
BDSMEC01	EX00042543	ENVIRONMENTAL LEVY,	EX0004254
BDSMEC01	EX00042543	TRAVEL,	EX0004254

ƨ5

REBUILD. FIT BACK TO TRUCK, BUILD UP AIR AND CHECK FOR LEAKS. RETURN

ll Out After Hours/Off Site,

			EX0004254
ΞC01	MK-RIN18246	Labour External,TRAVEL TO SITE	EX0004254
.IR WRKSCONS	BDSMEC01	MK-RIN18246 WORKSHOP	EX0004254
BDSMEC01	MK-RIN18246	ENVIRONMENTAL LEVY,	EX0004254
EC01	MK-RIN18246	TRAVEL,	EX0004254

Labour

Supplier Code	Invoice	Details	Purchase Order

ıf Defect :
ɔ GOES OFF AND ON INTERMITENT PROBLEM - GOT HOT AND WOULDNT COOL
AGAIN

Labour

	1.00

ɣ/10/2025

Consumables	4.00
OIL 15W-40, CK 4/E9	1.00
KOHLER AIR FILTER	1.00
DAYCO BLUE LABEL BELT	2.00
Labour - Internal	1.00

Consumables			5.00
		Labour - Internal	1.00
		Labour - Internal	1.00
		Labour - Internal	0.00
Consumables			0.00
		Labour - Internal	1.50

:UARY 2028

WITH ENGINE RUNNING AS WAS DRY

		Consumables	4.00
		Labour - Internal	1.50
		Labour - Internal	1.50
		SERVICE KIT	1.00
		AIR OIL FILTER	1.00
		FILTER CABIN K200	1.00
		OIL 15W-40, CK 4/E9	51.00
		Labour - Internal	2.50
		Consumables	6.00
		Labour - Internal	2.50

Supplier Code	Invoice	Details	Purchase Order
		Labour - Internal	
		Filter Diff	
		Filter Element Gearbox Eaton	
		REPLACEMENT ELEMENT INLINE FILTER	
		ES Water Filter	
		DESICANT CARTRIDGE T2000	
		Power Steer Filter LF637	
		Drive Belt, K200	
		Fan Belt	
		BELT TENSIONER	
		BELT TENSIONER	
		TRANS MAN HVY DUTY 75W90 205L	
		TRANS DYNADRIVE LL 80W90	
		Labour	1.00

ION. ATTEMPT

5

RUARY 2028

		Labour	2.00

S, HAD TO DROP THE ROOF LINING AND CUBERBS REPLACED 1 ROOF LIGHT AND FIXED WIRING

) UP WIRING

		Consumables	
		Labour - Internal	
		Amber Roof Clearance Light	

BRIAUS01	EX00043245	RUNOUT TYRE,	EX0004324
BRIAUS01	EX00043245	FIT TBR TYRE,	EX0004324
BRIAUS01	EX00043245	CUSTOMER SCRAPPED OWN TYRE,	EX0004324
BRIAUS01	EX00043245	REMOVAL: SIDEWALL CUT OR STAKED,	EX0004324
BRIAUS01	EX00043245	SCHEDULED DEPOT SERVICE 15MIN,	EX0004324
BRIAUS01	191746007	RUNOUT TYRE,	EX0004324
BRIAUS01	191746007	FIT TBR TYRE,	EX0004324

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	191746007	CUSTOMER SCRAPPED OWN TYRE,	EX0004324
BRIAUS01	191746007	REMOVAL: SIDEWALL CUT OR STAKED,	EX0004324
BRIAUS01	191746007	SCHEDULED DEPOT SERVICE 15MIN,	EX0004324

Labour - Internal	1.00

VALVE REPLACED JAW KIT
3 FIXED PRIOR TO SERVICE

Consumables	5.00
Labour - Internal	1.00
Labour - Internal	1.00
Labour - Internal	1.00
D2 GOVERNOR - 1.8"	1.00
Turn Table Repair Kit	1.00
Labour	0.00
Labour	0.00

of Defect :

: 21/11/2025 Description of

XT SERVICE

: 10/06/2024 Description of

BOUR APPREND

Labour	0.50

3/12/2025

KOHLER AIR FILTER	1.00
HITECH SYNPLUS 10W50	1.00
KOHLER OIL FILTER CARTRIDGE	1.00
KOHLER FUEL FILTER	1.00

Supplier Code	Invoice	Details	Purchase Order
		Fuel/Water seperator filter	
		Consumables	
		Labour - Internal	1.00

Consumables	4.00
Labour - Internal	1.00
Labour - Internal	1.00
Amber Roof Clearance Light	1.00
Labour	1.50

RGE TANK REPFLACED

Consumables	4.00
Labour - Internal	1.50
AIR DRYER KIT	1.00
Labour	0.00

f Defect :
N

Labour	1.00

ERE TOUCHING REVERSE, BELIEVE DRIVER IS TALKING ABOUT THE SWITCH ON TRAILERS

Consumables	3.00
EBS TRAILER PLUG 12/24V WITH 2 GROMMETS FOR BIG/SMALL CABLES	1.00
Labour - Internal	1.50

UR GLOBES REPLACE 7 PIN PLUG

Consumables	4.00
Labour - Internal	1.50

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	EX00044359	295/80R22.5 152/148M BS R154 ECO,	EX0004435
BRIAUS01	EX00044359	case stock 295/80-22.5,	EX0004435
BRIAUS01	EX00044359	FIT TBR TYRE,	EX0004435
BRIAUS01	EX00044359	TYRE HELD FOR RUNOUT,	EX0004435
BRIAUS01	EX00044359	REMOVAL: CUSTOMER PULL POINT,	EX0004435
BRIAUS01	EX00044359	REMOVAL: MATCH OTD OR PATTERN,	EX0004435
BRIAUS01	EX00044359	SCHEDULED DEPOT SERVICE 15MIN,	EX0004435
BRIAUS01	192134191	295/80R22.5 152/148M BS R154 ECO,	EX0004435
BRIAUS01	192134191	case stock 295/80-22.5,	EX0004435
BRIAUS01	192134191	FIT TBR TYRE,	EX0004435
BRIAUS01	192134191	TYRE HELD FOR RUNOUT,	EX0004435
BRIAUS01	192134191	REMOVAL: CUSTOMER PULL POINT,	EX0004435
BRIAUS01	192134191	REMOVAL: MATCH OTD OR PATTERN,	EX0004435
BRIAUS01	192134191	SCHEDULED DEPOT SERVICE 15MIN,	EX0004435
BROHUR01	EX00044926	Labour External,	EX0004492
BROHUR01	EX00044926	Parts Supplied,CAP-FILLER TUBE	EX0004492
BROHUR01	EX00044926	Speedo/Tacho Sensor (K200),	EX0004492
BROHUR01	EX00044926	MISCELLANEOUS CONSUMABLES,	EX0004492
BROHUR01	EX00044926	ENVIRONMENTAL LEVY,	EX0004492

6

ITSELF DOWN BETWEEN 600-1500RPM
iring diagram and tested wires from ecu plug to the speed sensors at the
and one of the wires failed. Rewired both wires from ecu to speed
00 rpm. Swapped around both speed sensors to see if one was at fault.
Removed and replaced both speed sensors at the back of the gearbox.
All okay.

BROHUR01	3811206	Labour External,	EX0004492
BROHUR01	3811206	Parts Supplied,CAP-FILLER TUBE	EX0004492

BROHUR01	3811206	Speedo/Tacho Sensor (K200),	EX0004492
BROHUR01	3811206	MISCELLANEOUS CONSUMABLES,	EX0004492
BROHUR01	3811206	ENVIRONMENTAL LEVY,	EX0004492

Labour - Internal

Consumables

Labour - Internal

Supplier Code	Invoice	Details	Purchase Order

Y 2028

	Consumables	4.00
	Labour - Internal	1.50
	OIL 15W-40, CK 4/E9	51.00
	SERVICE KIT	1.00
	AIR OIL FILTER	1.00
	Labour	0.50

'/02/2026

) PLUG LABOUR APPRENJ

	Labour - Internal	0.50
	Consumables	3.00
	KOHLER AIR FILTER	1.00
	HITECH SYNPLUS 10W50	1.00
	Labour	1.00

NG COLD AIR

Consumables
WIPER BLADE

CUMMIN01	EX00045378	Labour External,	EX0004537
CUMMIN01	EX00045378	Valve Governor,	EX0004537
CUMMIN01	EX00045378	ENVIRONMENTAL LEVY,	EX0004537
CUMMIN01	EX00045378	Consumables	EX0004537

,

Supplier Code	Invoice	Details	Purchase Order

27/03/2026

VALVE LEAKING

35 km
- 27/03/2026
Arrived carried out JSA and took

ound governor valve leaking air.

- 27/03/2026

truck.

austing.
d air pressure coming out of the

. The compressor built the air

pay down the road.
tting, gave it to the driver,

d an ECM download and photos

		Labour External,	EX0004537
IN01	1935328	Valve Governor,	EX0004537
IN01	1935328	ENVIRONMENTAL LEVY,	EX0004537
IN01	1935328	Consumables	EX0004537
JR01	EX00045536	,	EX0004553
		Labour External,	
JR01	EX00045536	MISCELLANEOUS CONSUMABLES,	EX0004553
JR01	EX00045536	ENVIRONMENTAL LEVY,	EX0004553

Supplier Code	Invoice	Details	Purchase Order

GE
. TOOK PHOTOS OF LEAKING SEAL. REMOVED SEAL. CLEANED SEALING SURFACES. FITTED THE
OAD ON KW2 CAME BACK TO THE WORKSHOP AND FINALISED PAPERWORK AND WARRANTY

BROHUR01	3847114	Labour External,	EX0004553
BROHUR01	3847114	MISCELLANEOUS CONSUMABLES,	EX0004553
BROHUR01	3847114	ENVIRONMENTAL LEVY,	EX0004553
		Labour - Internal	1.00
		Consumables	4.00
		Labour - Internal	0.50
	Labour		10.00

CLUTCH OFF FLYWHEEL, SENT FLYWHEEL AWAY FOR MACHING
EPLACED CLUTCH AND PUT TORQUE BOLTS TO SPEC
: AND ROAD TESTED, ALL OK AIR DRYER HAD BEEN BY PASSED, REPLACED AIR

ACED VOLTAGE BOOSTER
Consumables

		20.00
	Labour - Internal	8.00
	PACGEN EP ADV CLUTCH	1.00
	CLUTCH KIT INC KW X SHAFTS	1.00
AT	AIR DRYER KIT	1.00
	VOLTAGE INVERTER	1.00
	Labour - Internal	2.00

) PULL CORD ON TURNTABLE
'ER

Supplier Code	Invoice	Details	Purchase Order
		Consumables	
		Labour - Internal	
		FIRE EXTINGUISHER 2.0KG	
		Labour	
		Labour	4.00

SH KIT AND PADS TO TOP, TENSION ALL BOLTS AND ADJUST SU
GHTS FIT NEW SPOT MIRROR TO RHS

	Consumables	9.00
	Spotter mirror 7" inch	1.00
	STEEL INSERT KIT JSK 37	1.00
	BUSH KIT TO SUIT 37 CZ & CW	1.00
	Labour	1.00

NEW FITTINGS FITTED TO

	Consumables	5.00
	Labour - Internal	0.00
	Consumables	0.00
	Labour - Internal	3.00

BRUARY 2028

ACED AIR FILTER
RH BULLBAR LIGHT REFIT

	Consumables	6.00
	Labour - Internal	3.00

Supplier Code	Invoice	Details	Purchase Order
		FILTER KIT, OIL & FUEL FILTER, (E5)	1.00

Element 10 Micron	1.00
Ad Blue filter Kenworth	1.00
AIR FILTER	1.00
OIL 15W-40, CK 4/E9	47.00
VALVE GOVERNOR D2	1.00
Amber Roof Clearance Light	1.00
Labour	0.00

ITABLE LAST NIGHT. ASSISTED BY JOEY J AT FMUS LAST NIGHT. HAS MANAGED TO HOOK UP BACK
O UNHOOK HIS A TRAILER UNTIL HE ARRIVES BACK AT YATALA DEPOT. CAN FLEET MECH AND STH
PLEASE. THANK YOU

: 01/06/2026 Description of Defect :
REMAINS HOOKED UP TO RP29A AND RP29 PER STH OPS INSTRUCTIONS FOR LOCAL DELIVERY AM.

: 01/05/2026 Description of Defect :
ALSO DASH LIGHS, THEY DONT ALL WORK AND FUEL GAUGE DONT WORK

BROHUR01	EX00046706	HOSE CLIP,	EX0004670
Supplier Code	Invoice	Details	Purchase Order

10/06/2026

and cleaned up tubes, replaced the o-rings and refit. Filled up coolant.
aks and all good.

ng. Removed intake pipe, cac pipe, exhaust flex pipe, turbo oil feed and
new gaskets. Fit exhaust manifold with new gaskets.

s?. Adjusted turbo waste gate actuator travel and re measured, now within
to manifold with new gasket. Fit turbo oil feed and drain pipe with new
e with new clamp as one snapped upon removal and intake pipe.
OSE CLIP,

			EX0004670
YR01	EX00047902	PRESSURE CHECK PER TYRE,	EX0004790
RESSURE CHECKS - CAB LOCKED			
YR01	IN-117430-202	PRESSURE CHECK PER TYRE,	EX0004790
		Labour - Internal	

Consumables

Labour - Internal
KEY-BLANK CAB DOOR LOCK
Labour - Internal

ND RACES REPLACED FRONT BRAKE SHOES AND DRUMS

Consumables

Labour - Internal
Labour - Internal
OIL 15W-40, CK 4/E9
W/Bearing Kit,Steer,K'worth
BRAKE SHOES & HARDWARE KIT
Brake Drums, 8 & 5/8" Wide, 10 Stud, 285 PCW

Supplier Code	Invoice	Details	Purchase Order
		Labour	

YOKTYR01	EX00048066	TRUCK TYRE ROTATION,	EX0004806
YOKTYR01	EX00048066	PRESSURE CHECK PER TYRE,	EX0004806

ATION + PRESSURE CHECKS - POS

YOKTYR01	IN-119854-202	PRESSURE CHECK PER TYRE,	EX0004806
YOKTYR01	IN-119854-202	TRUCK TYRE ROTATION,	EX0004806
YOKTYR01	EX00048185	PRESSURE CHECK PER TYRE,	EX0004818

E CHECKS

YOKTYR01	IN-123973-202	PRESSURE CHECK PER TYRE,	EX0004818

Labour

G INCORRECT READINGS SCANNED FOR FAULT CODES, NO FAULTS FOUND
IRING AFFECTING THE SPEEDOMETER SIGNAL REPAIRED AND SECURED

RRECTLY
Consumables

R01	EX00048509	TRUCK TYRE PUNCTURE (INC FIT),	EX0004850

O:PM166 - YFS:1802 - REGO:XQ33UH - ODO:1109556KM - FN:PM166 - RN:8-9-2026

EX0004850

UCK TYRE PUNCTURE (INC FIT),
Labour - Internal

Consumables

Labour - Internal

Supplier Code	Invoice	Details	Purchase Order
026			

MP
E IDLER PULLY ON CHECKED OTHER BOLTS FOR TENSION AROUND FRONT
R
EE WHERE ITS COMING FROM - BILLY REPAIR WIRING NEAR FUEL FILTERS -

Consumables

(W4) SS304 WORM DRIVE CLAMP SOLID BAND
CAP RADIATOR 15PSI

MAINTENANCE KIT

Ad Blue filter Kenworth

OIL 15W-40, CK 4/E9

Labour

of Defect :
CE

:t Reference : PM166 Date : 10/06/2026 Description of Defect :
EQUIRES CAB LOCK KIT FOR LH
KENAUT01 EX00048993 GENERAL PART CODE,

EX0004899

RCCLOW01 EX00049111 Labour External, EX0004911

onsumables EX0004899

SAIN ACCESS TO BATTERIES. JUMP STARTED, ALL OK
abour, EX0004899

Total for Asset 123,108.73

Total for Report 123,108.73

Supplier Code	Invoice	Details	Purchase Order