Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00043006	15/10/2021	GEN	39			PART	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			PART	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			PART	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			PART	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			PART	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			PART	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			LAB	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			PART	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			PART	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			LAB	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			PART	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			PART	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			PART	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			PART	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			PART	
PM168	XQ43UH	00043006	15/10/2021	GEN	39			PART	
PM168	XQ43UH	00043210	26/10/2021	GEN	00	LABOUR APPREN			
PM168	XQ43UH	00043210	26/10/2021	GEN		REPAIR COMPLETED BY KEIRAN FITTED SPOT LIGHTS TO LOWER BULLBAR FITTED ALL WIRING NECCESARY TO BOTH SIDES OF TRUCK			
PM168	XQ43UH	00043210	26/10/2021	GEN	16			CON	YAT
PM168	XQ43UH	00043210	26/10/2021	GEN	14			KINGS-9	YAT
PM168	XQ43UH	00043282	28/10/2021	CUMAE5	01	LABOUR			
PM168	XQ43UH	00043282	28/10/2021	CUMAE5		SERVICE COMPLETED BY MICK AND KEIRAN - COMPLETED FULL FIRST SERVICE - ADJUSTED TURN TABLE - FITTED TRACKER LABOUR MECH			
PM168	XQ43UH	00043282	28/10/2021	CUMAE5	00				
PM168	XQ43UH	00043282	28/10/2021	CUMAE5	00	LABOUR APPREN			
PM168	XQ43UH	00043282	28/10/2021	CUMAE5	16			CON	YAT
PM168	XQ43UH	00043282	28/10/2021	CUMAE5	06			LF14000NN	YAT
PM168	XQ43UH	00043282	28/10/2021	CUMAE5	40			3413005	YAT
PM168	XQ43UH	00043282	28/10/2021	CUMAE5	06			FF5776	YAT
PM168	XQ43UH	00043282	28/10/2021	CUMAE5	06			17237	YAT
PM168	XQ43UH	00043282	28/10/2021	CUMAE5	06			A-3380W1687	YAT
PM168	XQ43UH	00043282	28/10/2021	CUMAE5	40			3334800	YAT
PM168	XQ43UH	00043282	28/10/2021	CUMAE5	06			DFDBC4085	YAT
PM168	XQ43UH	00043281	29/10/2021	CUMAE5	01	LABOUR			
PM168	XQ43UH	00043281	29/10/2021	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00043533	8/11/2021	TYRES	15			33000051	
PM168	XQ43UH	00043533	8/11/2021	TYRES	15			33000051	
PM168	XQ43UH	00043722	20/11/2021	CUMAE5	00	LABOUR APPREN			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00043722	20/11/2021	CUMAE5		SERVICE COMPLETED BY BENAND MICK			
PM168	XQ43UH	00043722	20/11/2021	CUMAE5	00	LABOUR MECH			
PM168	XQ43UH	00043722	20/11/2021	CUMAE5	16			CON YAT	
PM168	XQ43UH	00043748	20/11/2021	GEN	39			LAB	QUAWI
PM168	XQ43UH	00043748	20/11/2021	GEN	39			LAB	QUAWI
PM168	XQ43UH	00043945	30/11/2021	CUMAE5	01	LABOUR			
PM168	XQ43UH	00043945	30/11/2021	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00043945	30/11/2021	CUMBE5	00	LABOUR APPREN			
PM168	XQ43UH	00043945	30/11/2021	CUMBE5		SERVICE COMPLETED BY KEIRAN AND MICK REPLACED PULL DRAIN LABOUR MECH			
PM168	XQ43UH	00043945	30/11/2021	CUMBE5	00				
PM168	XQ43UH	00043945	30/11/2021	CUMBE5	16			CON YAT	
PM168	XQ43UH	00043945	30/11/2021	CUMBE5	06			MK13584 YAT	
PM168	XQ43UH	00043945	30/11/2021	CUMBE5	40			3413005 YAT	
PM168	XQ43UH	00044079	8/12/2021	TYRES	15			33000051	BRIAUS
PM168	XQ43UH	00044096	8/12/2021	TYRES	15			33000188	BRIAUS
PM168	XQ43UH	00044079	8/12/2021	TYRES	15			33000085	BRIAUS
PM168	XQ43UH	00044096	8/12/2021	TYRES	15			33000188	BRIAUS
PM168	XQ43UH	00044079	8/12/2021	TYRES	15			33000085	BRIAUS

PM168	XQ43UH	00044079	8/12/2021	TYRES	15			33000051		BRIAUS
PM168	XQ43UH	00044212	11/12/2021	CUMAE5	00	LABOUR MECH1				
PM168	XQ43UH	00044212	11/12/2021	CUMAE5		SERVICE COMPLETED BY IAN AND BEN				
PM168	XQ43UH	00044212	11/12/2021	CUMAE5	00	LABOUR APPREN				
PM168	XQ43UH	00044212	11/12/2021	CUMAE5	16			CON	YAT	
PM168	XQ43UH	00044497	4/01/2022	CUMAE5	00	LABOUR APPREN				
PM168	XQ43UH	00044497	4/01/2022	CUMAE5		SERVICE COMPLETED BY BEN AND KEIRAN				
PM168	XQ43UH	00044497	4/01/2022	CUMAE5	00	LABOUR APPREN				
PM168	XQ43UH	00044497	4/01/2022	CUMAE5	16			CON	YAT	
PM168	XQ43UH	00044607	12/01/2022	CUMAE5	01	LABOUR				
PM168	XQ43UH	00044607	12/01/2022	CUMAE5		SERVICE COMPLETED BY IAN				
PM168	XQ43UH	00044607	12/01/2022	CUMAE5	00	SERVIC4E SLEEPER AIR UNIT FIT MASS MANAGAMEN LABOUR MECH1				
PM168	XQ43UH	00044607	12/01/2022	CUMAE5	16			CON	YAT	
PM168	XQ43UH	00044607	12/01/2022	CUMAE5	06			ED2175254-S	YAT	
PM168	XQ43UH	00044607	12/01/2022	CUMAE5	40			3413005	YAT	
PM168	XQ43UH	00044607	12/01/2022	ECO	00	LABOUR MECH1				
PM168	XQ43UH	00044607	12/01/2022	ECO		SERVICE COMPLETED.				
PM168	XQ43UH	00044607	12/01/2022	ECO	16			CON	YAT	
PM168	XQ43UH	00044806	21/01/2022	CUMAE5	01	LABOUR				
PM168	XQ43UH	00044806	21/01/2022	CUMAE5		SERVICE COMPLETED.				
PM168	XQ43UH	00044806	21/01/2022	CUMBE5	00	LABOUR MECH1				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code		W/H Code
PM168	XQ43UH	00044806	21/01/2022	CUMBE5		SERVICE COMPLETED BY IAN AND KEIRAN				
PM168	XQ43UH	00044806	21/01/2022	CUMBE5	00	ADJUST CLUTCH LABOUR APPREN				
PM168	XQ43UH	00044806	21/01/2022	CUMBE5	16			CON		YAT
PM168	XQ43UH	00045018	2/02/2022	CUMAE5	01	LABOUR				
PM168	XQ43UH	00045018	2/02/2022	CUMAE5		SERVICE COMPLETED KEIRAN				
PM168	XQ43UH	00045018	2/02/2022	CUMAE5	00	- TOPPED UP WITH 150ML COOLANT LABOUR APPRE				
PM168	XQ43UH	00045018	2/02/2022	CUMAE5	16			CON	YAT	
PM168	XQ43UH	00045018	2/02/2022	CUMAE5	06			COOLANT	YAT	
PM168	XQ43UH	00045782	26/02/2022	CUMAE5	00	LABOUR APPRENK				
PM168	XQ43UH	00045782	26/02/2022	CUMAE5		SERVICE COMPLETED BY KEIRAN, BEN AND IAN				
PM168	XQ43UH	00045782	26/02/2022	CUMAE5	00	LABOUR APPRENB				
PM168	XQ43UH	00045782	26/02/2022	CUMAE5	00	LABOUR MECH1				
PM168	XQ43UH	00045782	26/02/2022	CUMAE5	16			CON	YAT	
PM168	XQ43UH	00046078	11/03/2022	CUMAE5	01	LABOUR				
PM168	XQ43UH	00046078	11/03/2022	CUMAE5		SERVICE COMPLETED.				
PM168	XQ43UH	00046078	11/03/2022	CUMBE5	00	LABOUR APPRENK				
PM168	XQ43UH	00046078	11/03/2022	CUMBE5		SERVICE COMPLETED BY KEIRAN, BRENDAN AND TY				
						FITTED TEST OIL FILTER FITTED HUBCAP TO RH STEER CLEANED OUT DRIVERS SIDE OF TRUCK AS TRUCK WASH E				
PM168	XQ43UH	00046078	11/03/2022	CUMBE5	00	LABOUR SUBMEC				
PM168	XQ43UH	00046078	11/03/2022	CUMBE5	00	LABOUR TRADEA				
PM168	XQ43UH	00046078	11/03/2022	CUMBE5	16			CON		YAT
PM168	XQ43UH	00046078	11/03/2022	CUMBE5	06			FF5776		YAT
PM168	XQ43UH	00046078	11/03/2022	CUMBE5	06			AS2474		YAT
PM168	XQ43UH	00046078	11/03/2022	CUMBE5	06			LF14000NN		YAT
PM168	XQ43UH	00046078	11/03/2022	CUMBE5	40			3413005		YAT
PM168	XQ43UH	00046078	11/03/2022	CUMBE5	11			RT1209A6		YAT
PM168	XQ43UH	00046078	11/03/2022	ECO	00	LABOUR APPRENK				
PM168	XQ43UH	00046078	11/03/2022	ECO		SERVICE COMPLETED BY KERIAN AND BRENDAN				
PM168	XQ43UH	00046078	11/03/2022	ECO	00	NO AIR FILTERS IN STOCK LABOUR SUBMEC				
PM168	XQ43UH	00046078	11/03/2022	ECO	16			CON	YAT	
PM168	XQ43UH	00046078	11/03/2022	ECO	40			10W50	YAT	
PM168	XQ43UH	00046323	24/03/2022	CUMAE5	00	LABOUR MECH1				
PM168	XQ43UH	00046323	24/03/2022	CUMAE5		SERVICE COMPLETED BY IAN AND MICK				
PM168	XQ43UH	00046323	24/03/2022	CUMAE5	00	LABOUR MECH				
PM168	XQ43UH	00046323	24/03/2022	CUMAE5	16			CON	YAT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM168	XQ43UH	00047028	25/03/2022	WEICAL		AIR GAUGE: 10.250 ADJUSTED: 15.00 WEIGHBRIDGE: 14.62 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
PM168	XQ43UH	00046582	31/03/2022	TYRES	15			33000051		
PM168	XQ43UH	00046582	31/03/2022	TYRES	15			33000051		
PM168	XQ43UH	00046934	16/04/2022	CUMAE5	00	LABOUR APPRENK				
PM168	XQ43UH	00046934	16/04/2022	CUMAE5		SERVICE COMPLETED BY KEIRAN				
PM168	XQ43UH	00046934	16/04/2022	CUMAE5	16	*OIL FILTER WAS 1/4 TURN LOOSE CON			YAT	
PM168	XQ43UH	00047457	5/05/2022	TYRES	15			33000096		
PM168	XQ43UH	00047457	5/05/2022	TYRES	15			33000096		
PM168	XQ43UH	00047386	6/05/2022	CUMAE5	01	LABOUR				
PM168	XQ43UH	00047386	6/05/2022	CUMAE5		SERVICE COMPLETED.				
PM168	XQ43UH	00047386	6/05/2022	CUMBE5	00	LABOUR SUBMEC				
PM168	XQ43UH	00047386	6/05/2022	CUMBE5		SERVICE COMPLETED BRENDAN AND BEN				
						AD BLUE CLEANED LINES REPLACED BREATHER FILT ADBLUE SENDER MOVED TANK ADBLUE TIGHTENED TANK STRAPS ADBLUE				
PM168	XQ43UH	00047386	6/05/2022	CUMBE5	00	LABOUR APPRENB				
PM168	XQ43UH	00047386	6/05/2022	CUMBE5	16			CON	YAT	
PM168	XQ43UH	00047386	6/05/2022	CUMBE5	06			LF14000NN	YAT	
PM168	XQ43UH	00047386	6/05/2022	CUMBE5	06			FF5776	YAT	
PM168	XQ43UH	00047386	6/05/2022	CUMBE5	06			FS19764	YAT	
PM168	XQ43UH	00047386	6/05/2022	CUMBE5	06			AS2474	YAT	
PM168	XQ43UH	00047386	6/05/2022	CUMBE5	40			3413005	YAT	
PM168	XQ43UH	00047386	6/05/2022	ECO	00	LABOUR APPRENB				
PM168	XQ43UH	00047386	6/05/2022	ECO		SERVICE COMPLETED AT 1225 HOURS BY BEN AND E				
PM168	XQ43UH	00047386	6/05/2022	ECO	00	LABOUR SUBMEC				
PM168	XQ43UH	00047386	6/05/2022	ECO	16			CON	YAT	
PM168	XQ43UH	00047386	6/05/2022	ECO	06			ED2175254-S	YAT	
PM168	XQ43UH	00047386	6/05/2022	ECO	40			10W50	YAT	
PM168	XQ43UH	00047643	18/05/2022	CUMAE5	01	LABOUR				
PM168	XQ43UH	00047644	18/05/2022	CUMAE5	00	LABOUR MECH1				
PM168	XQ43UH	00047643	18/05/2022	CUMAE5		SERVICE COMPLETED.				
PM168	XQ43UH	00047644	18/05/2022	CUMAE5		SERVICE COMPLETED BY IAN AND			TYLER	
PM168	XQ43UH	00047644	18/05/2022	CUMAE5	00	LABOUR TRADEA				
PM168	XQ43UH	00047644	18/05/2022	CUMAE5	16			CON	YAT	
PM168	XQ43UH	00047940	30/05/2022	TYRES	15			33000051		
PM168	XQ43UH	00047940	30/05/2022	TYRES	15			33000051		
PM168	XQ43UH	00048052	2/06/2022	CUMAE5	00	LABOUR APPRENK				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00048052	2/06/2022	CUMAE5		SERVICE COMPLETED BY KEIRAN AND TYLER REPAIRED WIRING TO LH TANK LIGHT			
PM168	XQ43UH	00048052	2/06/2022	CUMAE5	00	REPLACED FE LABOUR APPREN			
PM168	XQ43UH	00048052	2/06/2022	CUMAE5	16			CON	YAT
PM168	XQ43UH	00048149	7/06/2022	GEN	00	LABOUR APPRENK			
PM168	XQ43UH	00048149	7/06/2022	GEN		REPAIR COMPLETED BY KEIRAN AND BRENDAN			
						CODE 3738 ACTIVE, COMPLETED FULL FLUSH OF DOSER UNIT			
PM168	XQ43UH	00048149	7/06/2022	GEN	00	LABOUR SUBMEC			
PM168	XQ43UH	00048149	7/06/2022	GEN	16			CON	YAT
PM168	XQ43UH	00048149	7/06/2022	GEN	06			AS2474	YAT
PM168	XQ43UH	00048352	16/06/2022	CUMAE5	00	LABOUR MECH			
PM168	XQ43UH	00048352	16/06/2022	CUMAE5		SERVICE COMPLETED BY MICK AND BEN			
PM168	XQ43UH	00048352	16/06/2022	CUMAE5	00	LABOUR APPRENB			
PM168	XQ43UH	00048352	16/06/2022	CUMAE5	16			CON	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00048606	22/06/2022	WEICAL		AIR GAUGE: 16500 ADJUSTED: 16500 WEIGHBRIDGE: 16200			
PM168	XQ43UH	00048636	26/06/2022	WEICAL		AIR GAUGE CALIBRATION COMPLETED CORRECTLY. 16000 ADJUSTED: 16000 WEIGHBRIDGE: 15740			
PM168	XQ43UH	00048755	1/07/2022	CUMAE5	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			
PM168	XQ43UH	00048755	1/07/2022	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00048755	1/07/2022	CUMBE5	00	LABOUR APPRENK			
PM168	XQ43UH	00048755	1/07/2022	CUMBE5		SERVICE COMPLETED BY KEIRAN AND BEN			
PM168	XQ43UH	00048755	1/07/2022	CUMBE5	00	FOUND ADBLUE ON AIR SOLENOID FOR DOSER FLUS COMPLETED 6 DAYS AGO SENT TO B&H FOR FURTHE LABOUR APPRENB			
PM168	XQ43UH	00048755	1/07/2022	CUMBE5	16			CON	YAT
PM168	XQ43UH	00048755	1/07/2022	CUMBE5	06			LF14000NN	YAT
PM168	XQ43UH	00048755	1/07/2022	CUMBE5	06			FF5776	YAT
PM168	XQ43UH	00048755	1/07/2022	CUMBE5	06			AS2474	YAT
PM168	XQ43UH	00048755	1/07/2022	CUMBE5	40			3413005	YAT
PM168	XQ43UH	00049019	12/07/2022	CUMAE5	00	LABOUR APPREN			
PM168	XQ43UH	00049019	12/07/2022	CUMAE5		SERVICE COMPLETED BY TYLER AND BRENDAN			
PM168	XQ43UH	00049019	12/07/2022	CUMAE5	00	LABOUR SUBMEC			
PM168	XQ43UH	00049019	12/07/2022	CUMAE5	16			CON	YAT
PM168	XQ43UH	00049477	24/07/2022	WEICAL		AIR GAUGE: 16.250 ADJUSTED: 15.750 WEIGHBRIDGE: 15.500			
PM168	XQ43UH	00049405	27/07/2022	GEN	39	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. LAB		BROHUR01	
PM168	XQ43UH	00049405	27/07/2022	GEN	39			LAB	BROHU
PM168	XQ43UH	00049390	28/07/2022	CUMAE5	00	LABOUR APPRENB			
PM168	XQ43UH	00049390	28/07/2022	CUMAE5		SERVICE COMPLETED BY BEN			
PM168	XQ43UH	00049390	28/07/2022	CUMAE5	16	TOPPED ENGINE OIL FLUSHED DOSA SYSTEM CON YAT			
PM168	XQ43UH	00049390	28/07/2022	CUMAE5	40			3413005	YAT
PM168	XQ43UH	00049947	13/08/2022	WEICAL		AIR GAUGE: 16.50 ADJUSTED: 16.75 WEIGHBRIDGE: 16.32			
PM168	XQ43UH	00050030	20/08/2022	CUMAE5	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			
PM168	XQ43UH	00050030	20/08/2022	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00050030	20/08/2022	CUMBE5	00	LABOUR MECH1			
PM168	XQ43UH	00050030	20/08/2022	CUMBE5		SERVICE COMPLETED BY KEIRAN AND MICK			
PM168	XQ43UH	00050030	20/08/2022	CUMBE5	00	LABOUR MECH			
PM168	XQ43UH	00050030	20/08/2022	CUMBE5	16			CON	YAT
PM168	XQ43UH	00050030	20/08/2022	CUMBE5	06			MK13584	YAT
PM168	XQ43UH	00050030	20/08/2022	CUMBE5	40			3413005	YAT
PM168	XQ43UH	00050327	1/09/2022	TYRES	15			33000051	
PM168	XQ43UH	00050327	1/09/2022	TYRES	15			33000051	
PM168	XQ43UH	00050570	7/09/2022	WARRAN	39	LABOUR			
PM168	XQ43UH	00050570	7/09/2022	WARRAN		WENT TO ROCKLEA TRUCK ELECTRICAL INV# 135470			
PM168	XQ43UH	00050803	21/09/2022	CUMAE5	00	UPDATED SLEEPER AIR PROGRAM FITTED STACK CHARGED ON 131761 15/10/21 LABOUF			
PM168	XQ43UH	00050803	21/09/2022	CUMAE5		SERVICE COMPLETED BY BEN			

							TOPPED UP ENG OIL (8l)			
PM168	XQ43UH	00050803	21/09/2022	CUMAE5	16		REPLACED BUNK ACCESSORIES FUSE			
							CON	YAT		
PM168	XQ43UH	00050803	21/09/2022	CUMAE5	40				3413005	YAT
PM168	XQ43UH	00050783	21/09/2022	GEN	39				PART	KENAU
PM168	XQ43UH	00050783	21/09/2022	GEN	39				PART	KENAU

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00050783	21/09/2022	GEN	39			PART	
PM168	XQ43UH	00050783	21/09/2022	GEN	39			CON	
PM168	XQ43UH	00050783	21/09/2022	GEN	39			LAB	
PM168	XQ43UH	00050783	21/09/2022	GEN			REPAIR COMPLETED BY KENNY'S AUTO ELECTRICAL I		
							INSPECT SPOT LIGHT FAULT, FOUND BLOWN FUSE, CI		
							VOLTAGE IS DROPPING AND CURRENT IS INCREASING		
							TILT CAB UP AND INSTALL SECONDARY EARTH FOR C.		
PM168	XQ43UH	00050783	21/09/2022	GEN	39			PART	
PM168	XQ43UH	00050783	21/09/2022	GEN	39			PART	
PM168	XQ43UH	00050783	21/09/2022	GEN	39			PART	
PM168	XQ43UH	00050783	21/09/2022	GEN	39			CON	
PM168	XQ43UH	00050783	21/09/2022	GEN	39			LAB	
PM168	XQ43UH	00051054	4/10/2022	CUMAE5	00		LABOUR MECH1		
PM168	XQ43UH	00051054	4/10/2022	CUMAE5			SERVICE COMPLETED BY KEIRAN AND TYLER		
							COMPLETED FULL AFTER TREAT FLUSH, REMOVED AND FLU		
							TOPPED UP ENGINE OIL 2L		
PM168	XQ43UH	00051054	4/10/2022	CUMAE5	00		LABOUR APPREN		
PM168	XQ43UH	00051054	4/10/2022	CUMAE5	16			CON	YAT
PM168	XQ43UH	00051054	4/10/2022	CUMAE5	40			3413005	YAT
PM168	XQ43UH	00051277	6/10/2022	WEICAL			AIR GAUGE: 16500 ADJUSTED: 16500 WEIGHBRIDGE: 16160		
							AIR GAUGE CALIBRATION COMPLETED CORRECTLY.		
PM168	XQ43UH	00051381	15/10/2022	CUMAE5	01				
PM168	XQ43UH	00051381	15/10/2022	CUMAE5			SERVICE COMPLETED.		
PM168	XQ43UH	00051381	15/10/2022	CUMBE5	00		LABOUR APPRENB		
PM168	XQ43UH	00051381	15/10/2022	CUMBE5			SERVICE COMPLETED BY BEN AND TYLER		
							CHECK LH STEERT HUB NEXT A SERVICE, FOUND GOOD AM		
PM168	XQ43UH	00051381	15/10/2022	CUMBE5	00		LABOUR APPREN		
PM168	XQ43UH	00051381	15/10/2022	CUMBE5	16			CON	YAT
PM168	XQ43UH	00051381	15/10/2022	CUMBE5	40			3413005	YAT
PM168	XQ43UH	00051381	15/10/2022	CUMBE5	06			FS19764	YAT
PM168	XQ43UH	00051381	15/10/2022	CUMBE5	06			LF14000NN	YAT
PM168	XQ43UH	00051381	15/10/2022	CUMBE5	06			FF5776	YAT
PM168	XQ43UH	00051381	15/10/2022	CUMBE5	06			AS2474	YAT
PM168	XQ43UH	00051485	18/10/2022	GEN	39			LAB	
PM168	XQ43UH	00051485	18/10/2022	GEN	39			LAB	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00051485	18/10/2022	GEN	39			CON	
PM168	XQ43UH	00051485	18/10/2022	GEN	39			PART	
PM168	XQ43UH	00051485	18/10/2022	GEN	39			PART	
PM168	XQ43UH	00051485	18/10/2022	GEN	39			CON	
PM168	XQ43UH	00051485	18/10/2022	GEN	39			LAB	
PM168	XQ43UH	00051485	18/10/2022	GEN	39			LAB	

PM168	XQ43UH	00051765	2/11/2022	DEFECT		Reported Defect :-Defect Code : 00008092			
PM168	XQ43UH	00051765	2/11/2022	GEN		Defect Reference : WO51381 Date : 15/10/2022 Descriptic CHECK LH STEER HUB NEXT A SERVICE, FOUND GOC LABOUR APPREN			
PM168	XQ43UH	00051765	2/11/2022	GEN	00	LABOUR APPRENF			
PM168	XQ43UH	00051765	2/11/2022	GEN		LH HUB LOOKS OK, NO EXCESSIVE OIL FOUND, INSPE			
PM168	XQ43UH	00051765	2/11/2022	GEN	16	DEFECT CLEARED BY TYLER AND MICK 02.11.22 CON YAT C			
PM168	XQ43UH	00051843	2/11/2022	WEICAL		AIR GAUGE: 135600 ADJUSTED: 13000 WEIGHBRIDGE: 12460			
PM168	XQ43UH	00051960	9/11/2022	ECO	00	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. LABOUR MECH			
PM168	XQ43UH	00051960	9/11/2022	ECO		SERVICE COMPLETED BY MICK			
PM168	XQ43UH	00051960	9/11/2022	ECO	06			ED2175254-S	YAT
PM168	XQ43UH	00051960	9/11/2022	ECO	40			10W50	YAT
PM168	XQ43UH	00051960	9/11/2022	ECO	16			CON	YAT
PM168	XQ43UH	00052101	16/11/2022	CUMAE5	00	LABOUR APPREN			
PM168	XQ43UH	00052101	16/11/2022	CUMAE5		SERVICE COMPLETED BY TYLER AND FLYNN			
PM168	XQ43UH	00052101	16/11/2022	CUMAE5	00	LABOUR APPRENF			
PM168	XQ43UH	00052101	16/11/2022	CUMAE5	16			CON	YAT
PM168	XQ43UH	00052305	29/11/2022	CUMAE5	00	LABOUR APPREN			
PM168	XQ43UH	00052305	29/11/2022	CUMAE5		COMPLETED FULL ADBLU FLUSH, AFTERTREAT LIGH COULD NOT FAULT 12V PLUGS. TESTED WITH MULTIMETRE			
PM168	XQ43UH	00052305	29/11/2022	CUMAE5	00	SERVICE COMPLETED BY TYLER AND FLYNN LABOUR APPRENF			
PM168	XQ43UH	00052305	29/11/2022	CUMAE5	16			CON	YAT
PM168	XQ43UH	00052305	29/11/2022	CUMAE5	06			UF110	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00052305	29/11/2022	DEFECT		Reported Defect :-Defect Code : 00008262			
PM168	XQ43UH	00052404	29/11/2022	GEN		Defect Reference : 11806 Date : 02/11/2022 Description of 12V PLUG NOT WORKING/ DASH AND UNDER DRIVER DEFECT CLEARED BY MICK LABOUR APPRENF			
PM168	XQ43UH	00052404	29/11/2022	GEN	00	REPLACED MALE ELECTRICAL PLUG LEADS			
PM168	XQ43UH	00052404	29/11/2022	GEN	00	REPAIR COMPLETED BY FLYNN AND MICK LABOUR M			
PM168	XQ43UH	00052404	29/11/2022	GEN	16			CON	YAT
PM168	XQ43UH	00052367	30/11/2022	GEN	39			PART	
PM168	XQ43UH	00052367	30/11/2022	GEN	39			LAB	
PM168	XQ43UH	00052367	30/11/2022	GEN	39			CON	
PM168	XQ43UH	00052367	30/11/2022	GEN	39			ENVLEV	
PM168	XQ43UH	00052367	30/11/2022	GEN	39			ENVLEV	
PM168	XQ43UH	00052367	30/11/2022	GEN	39			CON	
PM168	XQ43UH	00052367	30/11/2022	GEN	39			LAB	
PM168	XQ43UH	00052367	30/11/2022	GEN	39			PART	
PM168	XQ43UH	00052548	1/12/2022	CUMAE5	01	LABOUR MECH			
PM168	XQ43UH	00052548	1/12/2022	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00052548	1/12/2022	CUMBE5	01	LABOUR APPRENB			
PM168	XQ43UH	00052548	1/12/2022	CUMBE5		SERVICE COMPLETED BY BEN, TYLER AND FLYNN 01			
PM168	XQ43UH	00052548	1/12/2022	CUMBE5	00	**SLEEPER FULL SERVICE STILL DUE** LABOUR APPI			

PM168	XQ43UH	00052548	1/12/2022	CUMBE5	00	LABOUR APPREN			
PM168	XQ43UH	00052548	1/12/2022	CUMBE5	16		CON	YAT	
PM168	XQ43UH	00052548	1/12/2022	CUMBE5	40		3413005	YAT	
PM168	XQ43UH	00052548	1/12/2022	CUMBE5	06		MK13584	YAT	
PM168	XQ43UH	00052562	1/12/2022	CUMCE5	01	LABOUR APPRENB			
PM168	XQ43UH	00052562	1/12/2022	CUMCE5		SERVICE COMPLETED BY BEN, TYLER AND KEIRAN 0			
PM168	XQ43UH	00052562	1/12/2022	CUMCE5	00	**FIT CABIN FILTER @ NEXT SERVICE** - D: 8375 LABC			
PM168	XQ43UH	00052562	1/12/2022	CUMCE5	00	LABOUR APPRENF			
PM168	XQ43UH	00052562	1/12/2022	CUMCE5	16		CON	YAT	
PM168	XQ43UH	00052562	1/12/2022	CUMCE5	06		PACWF001	YAT	
PM168	XQ43UH	00052562	1/12/2022	CUMCE5	06		UF110	YAT	
PM168	XQ43UH	00052562	1/12/2022	CUMCE5	06		17237	YAT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00052562	1/12/2022	CUMCE5	06			LF637	YAT
PM168	XQ43UH	00052562	1/12/2022	CUMCE5	06			AF1969M	YAT
PM168	XQ43UH	00052562	1/12/2022	CUMCE5	06			PACWF001	YAT
PM168	XQ43UH	00052562	1/12/2022	CUMCE5	06			T224P	YAT
PM168	XQ43UH	00052562	1/12/2022	CUMCE5	40			3334800	YAT
PM168	XQ43UH	00052563	1/12/2022	EXOINS	01	LABOUR APPRENB			
PM168	XQ43UH	00052563	1/12/2022	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECTIC #1			
PM168	XQ43UH	00052563	1/12/2022	EXOINS	00	INSPECTION COMPLETED BY BEN AND TYLER 01.12.2 LABOUR APPREN			
PM168	XQ43UH	00052670	13/12/2022	CUMAE5	00	LABOUR MECH1			
PM168	XQ43UH	00052670	13/12/2022	CUMAE5		SERVICE COMPLETED BE KEIRAN AND FLYNN			
PM168	XQ43UH	00052670	13/12/2022	CUMAE5	00	LABOUR APPRENF			
PM168	XQ43UH	00052670	13/12/2022	CUMAE5	16			CON	YAT
PM168	XQ43UH	00052778	14/12/2022	TYRES	15			11004493	
PM168	XQ43UH	00052778	14/12/2022	TYRES	15			77000180	
PM168	XQ43UH	00052778	14/12/2022	TYRES	15			33000084	
PM168	XQ43UH	00052778	14/12/2022	TYRES	15			33000517	
PM168	XQ43UH	00052778	14/12/2022	TYRES	15			11004493	YAT
PM168	XQ43UH	00052778	14/12/2022	TYRES		CARRIED OUT BY BRIDGESTONE			
PM168	XQ43UH	00052778	14/12/2022	TYRES	15	REFER INVOICE: 88863961 33000517			
PM168	XQ43UH	00052778	14/12/2022	TYRES	15			33000084	
PM168	XQ43UH	00052778	14/12/2022	TYRES	15			77000180	
PM168	XQ43UH	00052778	14/12/2022	TYRES	15			11004493	
PM168	XQ43UH	00053141	4/01/2023	CUMAE5	01	LABOUR APPREN			
PM168	XQ43UH	00053141	4/01/2023	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00053141	4/01/2023	CUMAE5	00	REPLACED CABIN AIR FILTER LABOUR APPRENF			
PM168	XQ43UH	00053141	4/01/2023	CUMAE5	16			TRPCAF0001	YAT
PM168	XQ43UH	00053136	4/01/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00053136	4/01/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00053136	4/01/2023	DEFECT		Reported Defect :-Defect Code : 00008374 Defect Reference : WO52548 Date : 01/12/2022 Description of Defect : **SLEEPER FULL SERVICE STILL DUE**			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00053136	4/01/2023	DEFECT		Reported Defect :-Defect Code : 00008375			
PM168	XQ43UH	00053136	4/01/2023	ECO		Defect Reference : WO52562 Date : 01/12/2022 Descriptic **FIT CABIN FILTER @ NEXT SERVICE** LABOUR APPRENF			
PM168	XQ43UH	00053136	4/01/2023	ECO	01	SERVICE COMPLETED.			
PM168	XQ43UH	00053136	4/01/2023	ECO	16			CON	YAT

PM168	XQ43UH	00053136	4/01/2023	ECO	06			ED0037300960	YAT
PM168	XQ43UH	00053136	4/01/2023	ECO	06			ED2175254-S	YAT
PM168	XQ43UH	00053136	4/01/2023	ECO	06			0021751550	YAT
PM168	XQ43UH	00053269	10/01/2023	CUMAE5	01	LABOUR APPRENB			
PM168	XQ43UH	00053269	10/01/2023	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00053269	10/01/2023	CUMAE5	16			CON	YAT
PM168	XQ43UH	00053364	14/01/2023	DEFECT	01	LABOUR APPRENK			
PM168	XQ43UH	00053364	14/01/2023	DEFECT		Replaced all 4 battery's, as 2 were u/s Replaced suzi coils, female plug housing and male plug on REMIND MICK FUSE FOR CABIN BLOWING - WARREN			
PM168	XQ43UH	00053364	14/01/2023	DEFECT		Reported Defect :-Defect Code : 00008526			
PM168	XQ43UH	00053364	14/01/2023	DEFECT		Defect Reference : 11823 Date : 05/01/2023 Description of Roof light not working check Odo 371282 LABOUR APPRENF			
PM168	XQ43UH	00053364	14/01/2023	DEFECT	00 16			MF70ZZDT	YAT
PM168	XQ43UH	00053364	14/01/2023	DEFECT	16			61-SC3MTLTSE	YAT
PM168	XQ43UH	00053364	14/01/2023	DEFECT	16			CON	YAT
PM168	XQ43UH	00053364	14/01/2023	GEN	39	LABOUR			
PM168	XQ43UH	00053364	14/01/2023	GEN		REPAIR COMPLETED.			
PM168	XQ43UH	00053441	18/01/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00053441	18/01/2023	DEFECT					
PM168	XQ43UH	00053441	18/01/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00053441	18/01/2023	DEFECT		Reported Defect :-Defect Code : 00008567			
PM168	XQ43UH	00053441	18/01/2023	GEN		Defect Reference : 11805 Date : 13/01/2023 Description of BATTERY DIEING IN ONE DAY ROOF LIGHT IN CAB NC PLUG BROKEN LABOUR MECH			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00053441	18/01/2023	GEN	00	REPAIR COMPLETED.			
PM168	XQ43UH	00053441	18/01/2023	GEN		PANNEL BEAT REAR CHECKER PLATE, COMPLETED I APPRENB			
PM168	XQ43UH	00053441	18/01/2023	GEN	00	LABOUR APPRENF			
PM168	XQ43UH	00053441	18/01/2023	GEN	06			AS2474	YAT
PM168	XQ43UH	00053441	18/01/2023	GEN	16			CON	YAT
PM168	XQ43UH	00054219	21/02/2023	CUMAE5	01	LABOUR MECH			
PM168	XQ43UH	00054219	21/02/2023	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00054219	21/02/2023	CUMBE5	00	LABOUR APPRENB			
PM168	XQ43UH	00054219	21/02/2023	CUMBE5		SERVICE COMPLETED.			
PM168	XQ43UH	00054219	21/02/2023	CUMBE5	00	LABOUR APPRENF			
PM168	XQ43UH	00054219	21/02/2023	CUMBE5	16			MK13584	YAT
PM168	XQ43UH	00054219	21/02/2023	CUMBE5	40			3413004	YAT
PM168	XQ43UH	00054219	21/02/2023	CUMBE5	16			CON	YAT
PM168	XQ43UH	00054219	21/02/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00054219	21/02/2023	DEFECT					
PM168	XQ43UH	00054219	21/02/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00054219	21/02/2023	DEFECT		Reported Defect :-Defect Code : 00008577			
PM168	XQ43UH	00054841	15/03/2023	CUMAE5		Defect Reference : 11805A Date : 13/01/2023 Description INTERIOR LIGHT BACK OF CAB LABOUR MECH 1			
PM168	XQ43UH	00054841	15/03/2023	CUMAE5	00	SERVICE COMPLETED. ADJUSTED CLUTCH LABOUR			
PM168	XQ43UH	00054841	15/03/2023	CUMAE5	00				
PM168	XQ43UH	00054841	15/03/2023	CUMAE5	16			CON	YAT
PM168	XQ43UH	00054989	22/03/2023	CUMAE5	00	LABOUR APPREN			
PM168	XQ43UH	00054989	22/03/2023	CUMAE5		SERVICE COMPLETED.			

PM168	XQ43UH	00054989	22/03/2023	CUMAE5	00	LABOUR APPRENB			
PM168	XQ43UH	00054989	22/03/2023	CUMAE5	16			CON	YAT
PM168	XQ43UH	00055460	5/04/2023	TYRES	15			11006520	BRIAUS
PM168	XQ43UH	00055460	5/04/2023	TYRES	15			77000194	BRIAUS
PM168	XQ43UH	00055460	5/04/2023	TYRES	15			33000084	BRIAUS
PM168	XQ43UH	00055460	5/04/2023	TYRES	15			33000517	BRIAUS
PM168	XQ43UH	00055460	5/04/2023	TYRES	15			33000051	BRIAUS
PM168	XQ43UH	00055460	5/04/2023	TYRES	15			33000051	BRIAUS
PM168	XQ43UH	00055460	5/04/2023	TYRES	15			33000517	BRIAUS
PM168	XQ43UH	00055460	5/04/2023	TYRES	15			33000084	BRIAUS
PM168	XQ43UH	00055460	5/04/2023	TYRES	15			77000194	BRIAUS
PM168	XQ43UH	00055460	5/04/2023	TYRES	15			11006520	BRIAUS
PM168	XQ43UH	00055439	6/04/2023	CUMAE5	00	LABOUR APPREN			
PM168	XQ43UH	00055439	6/04/2023	CUMAE5		SERVICE COMPLETED. REPLACED RH SPOTTER MIRI			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00055439	6/04/2023	CUMAE5	16			PART	YAT
PM168	XQ43UH	00055439	6/04/2023	CUMAE5	16			CON	YAT
PM168	XQ43UH	00055439	6/04/2023	DEFECT	01	LABOUR	MECH		
PM168	XQ43UH	00055439	6/04/2023	DEFECT					
PM168	XQ43UH	00055439	6/04/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00055439	6/04/2023	DEFECT		Reported Defect :-Defect Code : 00009039			
PM168	XQ43UH	00055601	15/04/2023	DEFECT	01	Defect Reference : 11814 Date : 06/04/2023 Description of RIGHT HAND MIRROR SMASHED REAR RIGHT SIDE MUD GUARD REPLACE LABOUR ME			
PM168	XQ43UH	00055601	15/04/2023	DEFECT					
PM168	XQ43UH	00055601	15/04/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00055601	15/04/2023	DEFECT		Reported Defect :-Defect Code : 00009062 Defect Refere			
PM168	XQ43UH	00055601	15/04/2023	GEN	00	Date : 13/04/2023 Description of Defect : AFTERTEAT NOT USING ANY ADBLUE ICE PACK FULT LABOUR MECH 1			
PM168	XQ43UH	00055601	15/04/2023	GEN		REPAIR COMPLETED. REPAIRED AFTERTREAT LIGHT			
PM168	XQ43UH	00055601	15/04/2023	GEN	16	CON	YAT		
PM168	XQ43UH	00055752	21/04/2023	GEN		SLEEPER AIR			
PM168	XQ43UH	00055752	21/04/2023	GEN	39	Travel to site. Diagnose A/C faults, identify faulty pressure switch. Remov dryer (Supplied by customer). Recover gas, pressure test, a charge with gas. Test, all ok. Diagnose charging fault. Replace voltage booster (Supplied by customer). Replace Supplied by customer) LABEXT		BDSMEC01	
PM168	XQ43UH	00055752	21/04/2023	GEN	39			TRAVEL FEE	BDSME
PM168	XQ43UH	00055752	21/04/2023	GEN	39			R134A	BDSME
PM168	XQ43UH	00055752	21/04/2023	GEN	39			NITRO	BDSME
PM168	XQ43UH	00055752	21/04/2023	GEN	39			PART	BDSME
PM168	XQ43UH	00055752	21/04/2023	GEN	39			CON	BDSME
PM168	XQ43UH	00055752	21/04/2023	GEN	39			CON	BDSME
PM168	XQ43UH	00055752	21/04/2023	GEN	39			PART	BDSME
PM168	XQ43UH	00055752	21/04/2023	GEN	39			NITRO	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00055752	21/04/2023	GEN	39			R134A	
PM168	XQ43UH	00055752	21/04/2023	GEN	39			TRAVEL FEE	
PM168	XQ43UH	00055752	21/04/2023	GEN	39			LABEXT	
PM168	XQ43UH	00055770	24/04/2023	CUMAE5	01	LABOUR MECH			

PM168	XQ43UH	00055770	24/04/2023	CUMAE5		SERVICE COMPLETED.				
PM168	XQ43UH	00055770	24/04/2023	CUMBE5	00	LABOUR MECH 3				
PM168	XQ43UH	00055770	24/04/2023	CUMBE5		SERVICE COMPLETED. MONITOR STEERBOX, UNI BOLT WAS LOOSE ON SERVICE &				
PM168	XQ43UH	00055770	24/04/2023	CUMBE5	00	LABOUR APPREN				
PM168	XQ43UH	00055770	24/04/2023	CUMBE5	16			MK13584		YAT
PM168	XQ43UH	00055770	24/04/2023	CUMBE5	16			CON		YAT
PM168	XQ43UH	00055935	2/05/2023	CUMAE5	00	LABOUR MECH				
PM168	XQ43UH	00055935	2/05/2023	CUMAE5		SERVICE COMPLETED.				
PM168	XQ43UH	00055935	2/05/2023	CUMAE5	00	LABOUR APPRENF				
PM168	XQ43UH	00055935	2/05/2023	CUMAE5	16			CON		YAT
PM168	XQ43UH	00056297	16/05/2023	DEFECT	01	LABOUR MECH				
PM168	XQ43UH	00056297	16/05/2023	DEFECT						
PM168	XQ43UH	00056297	16/05/2023	DEFECT		DEFECT CLEARED.				
PM168	XQ43UH	00056297	16/05/2023	GEN	00	LABOUR MECH 1				
PM168	XQ43UH	00056297	16/05/2023	GEN		REPAIR COMPLETED. REFITTED NEW MUDGAURD RHR REPLACED LIGHT PLUG ON REAR OFF TRUCK				
PM168	XQ43UH	00056297	16/05/2023	GEN	16			CON		YAT
PM168	XQ43UH	00056369	22/05/2023	CUMAE5	00	LABOUR APPRENB				
PM168	XQ43UH	00056369	22/05/2023	CUMAE5		SERVICE COMPLETED.				
PM168	XQ43UH	00056369	22/05/2023	CUMAE5	00	LABOUR APPREN				
PM168	XQ43UH	00056369	22/05/2023	CUMAE5	16			CON		YAT
PM168	XQ43UH	00056369	22/05/2023	DEFECT	01	LABOUR MECH				
PM168	XQ43UH	00056369	22/05/2023	DEFECT						
PM168	XQ43UH	00056369	22/05/2023	DEFECT		DEFECT CLEARED.				
PM168	XQ43UH	00056576	24/05/2023	GEN	39			LABEXT		
PM168	XQ43UH	00056576	24/05/2023	GEN	39			ENVLEV		
PM168	XQ43UH	00056576	24/05/2023	GEN	39			MISCON		
PM168	XQ43UH	00056576	24/05/2023	GEN	39			SUND		
PM168	XQ43UH	00056576	24/05/2023	GEN	39			TRAVEL FEE		
PM168	XQ43UH	00056576	24/05/2023	GEN	39			LABEXT		
PM168	XQ43UH	00056576	24/05/2023	GEN	39			LABEXT		
PM168	XQ43UH	00056576	24/05/2023	GEN	39			ENVLEV		
PM168	XQ43UH	00056576	24/05/2023	GEN	39			MISCON		
PM168	XQ43UH	00056576	24/05/2023	GEN	39			SUND		
PM168	XQ43UH	00056576	24/05/2023	GEN	39			TRAVEL FEE		
PM168	XQ43UH	00056576	24/05/2023	GEN	39			LABEXT		

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00056941	26/05/2023	WEICAL		AIR GAUGE: 15250 ADJUSTED: 15500 WEIGHBRIDGE: 15250			
PM168	XQ43UH	00056852	2/06/2023	CUMAE5	00	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. APPREN			
PM168	XQ43UH	00056852	2/06/2023	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00056852	2/06/2023	CUMAE5	16			CON	YAT
PM168	XQ43UH	00056852	2/06/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00056852	2/06/2023	DEFECT					
PM168	XQ43UH	00056852	2/06/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00057054	4/06/2023	WEICAL		AIR GAUGE: 12.50 ADJUSTED: 12.25 WEIGHBRIDGE: 11.90			
PM168	XQ43UH	00057397	15/06/2023	WEICAL		AIR GAUGE CALIBRATION COMPLETED CORRECTLY. 16250 ADJUSTED: 16900 WEIGHBRIDGE:16580			
PM168	XQ43UH	00057416	15/06/2023	WEICAL		AIR GAUGE CALIBRATION COMPLETED CORRECTLY. 15180 ADJUSTED: 15180 WEIGHBRIDGE: 15500			
PM168	XQ43UH	00057303	17/06/2023	DEFECT	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. MECH			

PM168	XQ43UH	00057303	17/06/2023	DEFECT						
PM168	XQ43UH	00057303	17/06/2023	DEFECT		DEFECT CLEARED.				
PM168	XQ43UH	00057303	17/06/2023	ECO	00	LABOUR APPRENB				
PM168	XQ43UH	00057303	17/06/2023	ECO		SERVICE COMPLETED.				
PM168	XQ43UH	00057303	17/06/2023	ECO	00	LABOUR APPRENF				
PM168	XQ43UH	00057303	17/06/2023	ECO	00	LABOUR MECH 1				
PM168	XQ43UH	00057303	17/06/2023	ECO	00	LABOUR MECH				
PM168	XQ43UH	00057303	17/06/2023	ECO	06			ED2175254-S	YAT	
PM168	XQ43UH	00057303	17/06/2023	ECO	40			10W50	YAT	
PM168	XQ43UH	00057303	17/06/2023	ECO	16			CON	YAT	
PM168	XQ43UH	00057302	19/06/2023	CUMAE5	01	LABOUR MECH				
PM168	XQ43UH	00057302	19/06/2023	CUMAE5		SERVICE COMPLETED.				
PM168	XQ43UH	00057302	19/06/2023	CUMBE5	00	LABOUR MECH				
PM168	XQ43UH	00057302	19/06/2023	CUMBE5		SERVICE COMPLETED.				
PM168	XQ43UH	00057302	19/06/2023	CUMBE5	00	LABOUR APPRENB				
PM168	XQ43UH	00057302	19/06/2023	CUMBE5	00	LABOUR MECH 1				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00057302	19/06/2023	CUMBE5	06			MK13584	YAT
PM168	XQ43UH	00057302	19/06/2023	CUMBE5	40			3413005	YAT
PM168	XQ43UH	00057302	19/06/2023	CUMBE5	16			PART	YAT
PM168	XQ43UH	00057302	19/06/2023	CUMBE5	16			PART	YAT
PM168	XQ43UH	00057302	19/06/2023	CUMBE5	16			FS19764	YAT
PM168	XQ43UH	00057302	19/06/2023	CUMBE5	16			CON	YAT
PM168	XQ43UH	00057302	19/06/2023	DEFECT	01	LABOUR	MECH		
PM168	XQ43UH	00057302	19/06/2023	DEFECT					
PM168	XQ43UH	00057302	19/06/2023	DEFECT		DEFECT	CLEARED.		
PM168	XQ43UH	00057337	20/06/2023	DEFECT	01	LABOUR	MECH		
PM168	XQ43UH	00057337	20/06/2023	DEFECT					
PM168	XQ43UH	00057337	20/06/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00057337	20/06/2023	DEFECT		Reported Defect :-			
						Defect Code : 00009375 Defect Reference : 11815 Date : 20/06/20			
						AIRLINE SNAPPED.			
PM168	XQ43UH	00057337	20/06/2023	GEN	00	LABOUR APPREN			
PM168	XQ43UH	00057337	20/06/2023	GEN		REPAIR COMPLETED. REPLACED AIR LINES			
PM168	XQ43UH	00057337	20/06/2023	GEN	16	CON			YAT
PM168	XQ43UH	00057337	20/06/2023	GEN	16			61-SC3MTLTSE	YAT
PM168	XQ43UH	00057573	26/06/2023	WEICAL		AIR GAUGE: 18500			
						ADJUSTED: 18900			
						WEIGHBRIDGE: 18480			
						AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			
PM168	XQ43UH	00057813	28/06/2023	WEICAL					
						ADJUSTED: 16000 WEIGHBRIDGE:15600			
						AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			
PM168	XQ43UH	00057720	4/07/2023	CUMAE5	01				
PM168	XQ43UH	00057720	4/07/2023	CUMAE5		SERVICE COMPLETED. TOPPED UP ENGINE OIL			
PM168	XQ43UH	00057720	4/07/2023	CUMAE5	40	3413005	YAT		
PM168	XQ43UH	00057720	4/07/2023	CUMAE5	16			CON	YAT
PM168	XQ43UH	00058054	19/07/2023	CUMAE5	00	LABOUR MECH 3			
PM168	XQ43UH	00058054	19/07/2023	CUMAE5		SERVICE COMPLETED. 2 X DEFECTS RECORDED.			
PM168	XQ43UH	00058054	19/07/2023	CUMAE5	00	LABOUR APPRENF			
PM168	XQ43UH	00058054	19/07/2023	CUMAE5	16			CON	YAT
PM168	XQ43UH	00058054	19/07/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00058054	19/07/2023	DEFECT					
PM168	XQ43UH	00058054	19/07/2023	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00058275	20/07/2023	WEICAL		AIR GAUGE: 16000			
						ADJUSTED: 16060			
						WEIGHBRIDGE: 15780			

						AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			
PM168	XQ43UH	00058846	24/07/2023	GEN	39			LABEXT	
PM168	XQ43UH	00058859	24/07/2023	gen	39			LABEXT	
PM168	XQ43UH	00058846	24/07/2023	GEN	39			LABEXT	
PM168	XQ43UH	00058859	24/07/2023	gen	39			LABEXT	
PM168	XQ43UH	00058846	24/07/2023	GEN	39			LABEXT	
PM168	XQ43UH	00058846	24/07/2023	GEN	39			LABEXT	
PM168	XQ43UH	00058324	26/07/2023	GEN	39			LABEXT	
PM168	XQ43UH	00058368	26/07/2023	GEN	39			LABEXT	
PM168	XQ43UH	00058324	26/07/2023	GEN	39			LABEXT	
PM168	XQ43UH	00058368	26/07/2023	GEN	39			LABEXT	
PM168	XQ43UH	00058540	1/08/2023	DEFECT	00	LABOUR MECH			
PM168	XQ43UH	00058540	1/08/2023	DEFECT		DEFECT CLEARED - 01/08/2023			
						DIAGNOSED AND REPAIRED SLEEPER AIR ISSUE, TH			
						REPLACED LIFT PUMP ON SLEEPER AND FUEL FILTE			
PM168	XQ43UH	00058540	1/08/2023	DEFECT		REPLACED DIFF BREATHER ON REAR DIFF AS IT WA Reported Defect :-			
						Defect Code : 00009608 Defect Reference : PM168 Date : SLEEPER NOT STARTING. DIFF LEAK LABOUR MECH 1			
PM168	XQ43UH	00058540	1/08/2023	DEFECT	00				
PM168	XQ43UH	00058540	1/08/2023	DEFECT	00	LABOUR APPRENB			
PM168	XQ43UH	00058540	1/08/2023	DEFECT	16			CON	YAT
PM168	XQ43UH	00058540	1/08/2023	DEFECT	06			FS1251	YAT
PM168	XQ43UH	00058540	1/08/2023	DEFECT	06			ED0037300960	YAT
PM168	XQ43UH	00058540	1/08/2023	DEFECT	16			CON	YAT
PM168	XQ43UH	00058540	1/08/2023	DEFECT	16			CON	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00058613	2/08/2023	GEN		REPAIR CARRIED OUT BY BDS MECHANICAL ON 02/08			
						S Arrived onsite and inspected vehicle. Fo 10PSI in the system. Recovered the las			
						a leak on the suction hose near the front put in place and crimped. Pressure tested system, vacu tested. Sleep ai			
						S LABEXT			
PM168	XQ43UH	00058613	2/08/2023	GEN	39				
PM168	XQ43UH	00058613	2/08/2023	GEN	39			TRAVEL FEE	BDSME
PM168	XQ43UH	00058613	2/08/2023	GEN	39			CON	BDSME
PM168	XQ43UH	00058613	2/08/2023	GEN	39			, LABEXT	BDSME
PM168	XQ43UH	00058613	2/08/2023	GEN	39			TRAVEL FEE	BDSME
PM168	XQ43UH	00058613	2/08/2023	GEN	39			CON	BDSME
PM168	XQ43UH	00058687	4/08/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00058687	4/08/2023	DEFECT					
PM168	XQ43UH	00058687	4/08/2023	DEFECT		DEFECTS CLEARED 04/08/2023.			
						BUNK A/C REPAIRED BY B.D.S			

PM168	XQ43UH	00058687	4/08/2023	DEFECT						REPLACED SEATBELT AS REQUIRED. Reported Defect :-
										Defect Code : 00009641 Defect Reference : 11816 Date : 2 Description of Defect : BUNK A/C NOT WORKING Reported Defect :-
PM168	XQ43UH	00058687	4/08/2023	DEFECT						
										Defect Code : 00009640 Defect Reference : 11817 Date : 2 Description of Defect : SEAT BELT NEEDS TO BE REPLACED. LABOUR MECH 1
PM168	XQ43UH	00058687	4/08/2023	GEN	39					
PM168	XQ43UH	00058687	4/08/2023	GEN						REPAIR COMPLETED BY NICK ON 04/08/2023.
										FITTED NEW BUG SCREEN AND NEW NUT FITTED NEW SPO REMOVED GLASS IN PASSENGER DOOR, RE-SECURED WIR
PM168	XQ43UH	00058687	4/08/2023	GEN	16			CON		YAT
PM168	XQ43UH	00058687	4/08/2023	GEN	13			SNS-00S-0007		YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00058880	10/08/2023	GEN	39			PART	
PM168	XQ43UH	00058880	10/08/2023	GEN	39			LABEXT	
PM168	XQ43UH	00058880	10/08/2023	GEN	39			PART	
PM168	XQ43UH	00058880	10/08/2023	GEN	39			LABEXT	
PM168	XQ43UH	00059134	18/08/2023	GEN	39			LABEXT	
PM168	XQ43UH	00059134	18/08/2023	GEN	39			LABEXT	
PM168	XQ43UH	00059134	18/08/2023	GEN	39			PART	
PM168	XQ43UH	00059134	18/08/2023	GEN	39			CON	
PM168	XQ43UH	00059134	18/08/2023	GEN	39			ENVLEV	
PM168	XQ43UH	00059134	18/08/2023	GEN	39			LABEXT	
PM168	XQ43UH	00059134	18/08/2023	GEN	39			LABEXT	
PM168	XQ43UH	00059134	18/08/2023	GEN	39			PART	
PM168	XQ43UH	00059134	18/08/2023	GEN	39			CON	
PM168	XQ43UH	00059134	18/08/2023	GEN	39			ENVLEV	
PM168	XQ43UH	00059233	28/08/2023	CUMAE5	01	LABOUR	MECH 3		
PM168	XQ43UH	00059233	28/08/2023	CUMAE5		SERVICE COMPLETED BY MATT, NICK, FLYNN & JOSE			
PM168	XQ43UH	00059233	28/08/2023	CUMAE5	00	REAR AXLE BRAKE RELINE LABOUR APPRENJ			
PM168	XQ43UH	00059233	28/08/2023	CUMAE5	00	LABOUR MECH 1			
PM168	XQ43UH	00059233	28/08/2023	CUMAE5	00	LABOUR APPRENF			
PM168	XQ43UH	00059233	28/08/2023	CUMAE5	16			CON	YAT
PM168	XQ43UH	00059233	28/08/2023	CUMAE5	02			KSMA2124707Q	YAT
PM168	XQ43UH	00059233	28/08/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00059233	28/08/2023	DEFECT					
PM168	XQ43UH	00059233	28/08/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00059532	4/09/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00059532	4/09/2023	DEFECT					
PM168	XQ43UH	00059532	4/09/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00059532	4/09/2023	DEFECT		Reported Defect :-Defect Code : 00009848 Defect Reference : 11819 Date : 29/08/2023 Description of ALPINE STEREO CDE-173EBT UNIT WORKS PROPERL FAULT BUT CAN'T FIND "PWR IC" SETTING, SO GAVE			
						DEFECT CLEARED 04/09/2023 FIXED WIRING FOR STE			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code

PM168	XQ43UH	00059532	4/09/2023	DEFECT		Reported Defect :-Defect Code : 00009847 Defect Reference : 11829 Date : 03/09/2023 Description of D COULD I PLEASE HAVE AN ASSORTMENT OF BULBS FO			
PM168	XQ43UH	00059532	4/09/2023	DEFECT		DEFECT CLEARED 04/09/2023 CHANGED DASH GLOBES Reported Defect :- Defect Code : 00009846 Defect Reference : 11830 Date : 03 CAB NOT SITTING RIGHT, TILTED TOWARDS REAR (HIT			
PM168	XQ43UH	00059527	4/09/2023	GEN	39	DEFECT CLEARED 04/09/2023 FITTED SPACER PLATE UNDER LEFT HAND SIDE OF CA	K221-5032		
PM168	XQ43UH	00059533	4/09/2023	GEN	39		K221-5032		
PM168	XQ43UH	00059527	4/09/2023	GEN	39		K221-5032		
PM168	XQ43UH	00059532	4/09/2023	GEN	39	LABOUR MECH 1			
PM168	XQ43UH	00059533	4/09/2023	GEN	39		K221-5032		
PM168	XQ43UH	00059532	4/09/2023	GEN		REPAIR COMPLETED BY NICK ON 04/09/2023. FIXED WIRING FOR STEREO CHANGED DASH GLOBES FITTED SPACER PLATE UNDER LEFT HAND SIDE OF CON YAT			
PM168	XQ43UH	00059532	4/09/2023	GEN	16				
PM168	XQ43UH	00059532	4/09/2023	GEN	13		K221-5032	YAT	
PM168	XQ43UH	00059532	4/09/2023	GEN	16		CON	YAT	
PM168	XQ43UH	00059944	18/09/2023	CUMAE5	01	LABOUR MECH			
PM168	XQ43UH	00059944	18/09/2023	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00059944	18/09/2023	CUMBE5	01	LABOUR MECH			
PM168	XQ43UH	00059944	18/09/2023	CUMBE5		SERVICE COMPLETED BY BEN & MICK ON 16/09/2023.			
PM168	XQ43UH	00059944	18/09/2023	CUMBE5		LHS HAS BEEN REPAIRED. REPLACED 1.5KG FIRE EX EMAIL IS OUT FOR INVERTER TO BE INSTALLED. LABOUR APPRENB			
PM168	XQ43UH	00059944	18/09/2023	CUMBE5	00 16		CON	YAT	
PM168	XQ43UH	00059944	18/09/2023	CUMBE5	06		MK13584	YAT	
PM168	XQ43UH	00059944	18/09/2023	CUMBE5	40		3413005	YAT	
PM168	XQ43UH	00059944	18/09/2023	CUMBE5	06		FS19764	YAT	
PM168	XQ43UH	00059944	18/09/2023	CUMBE5	19		FIREEXT1.5KG	YAT	
PM168	XQ43UH	00059944	18/09/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00059944	18/09/2023	DEFECT					
PM168	XQ43UH	00059944	18/09/2023	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00059944	18/09/2023	DEFECT		Reported Defect :-Defect Code : 00009518 Defect Reference : PM168 Date : 15/07/2023 Description of LHS DOOR WIRING HANGING DOWN IN SPOTTER WIND			
PM168	XQ43UH	00059944	18/09/2023	DEFECT		DEFECT CLEARED 16/09/2023 SPOTTER WINDOW WIRING LHS HAS BEEN REPAIRED Reported Defect :- Defect Code : 00009911 Defect Reference : 11821 Date : 02 WAS JUST WONDERING IF TRUCK COULD BE CABLED MICROWAVE. STEVE WALKER SAID IT'S OKAY.			
PM168	XQ43UH	00060053	19/09/2023	GEN	15	DEFECT CLEARED 16/09/2023 EMAIL IS OUT FOR INVERTER TO BE INSTALLED	33000096		
PM168	XQ43UH	00060053	19/09/2023	GEN	15		33000096		
PM168	XQ43UH	00060137	20/09/2023	GEN	39		LABEXT		
PM168	XQ43UH	00060137	20/09/2023	GEN	39		450205F		

PM168	XQ43UH	00060137	20/09/2023	GEN	16			CON	
PM168	XQ43UH	00060137	20/09/2023	GEN	16			ENVLEV	
PM168	XQ43UH	00060137	20/09/2023	GEN	16			ENVLEV	
PM168	XQ43UH	00060137	20/09/2023	GEN	16			CON	
PM168	XQ43UH	00060137	20/09/2023	GEN	39			450205F	
PM168	XQ43UH	00060137	20/09/2023	GEN	39			LABEXT	
PM168	XQ43UH	00060156	25/09/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00060156	25/09/2023	DEFECT					
PM168	XQ43UH	00060156	25/09/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00060156	25/09/2023	DEFECT		Reported Defect :-Defect Code : 00009996 Defect Reference : 11831 Date : 25/09/2023 Description of SUSPECT COOLANT LEAK. CAN SMELL COOLANT			
PM168	XQ43UH	00060156	25/09/2023	DEFECT		DEFECT CLEARED 25/09/2023 COULDN'T FAULT COOL			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00060156	25/09/2023	DEFECT		Reported Defect :-Defect Code : 00009997 Defect Reference : 11812 Date : 25/09/2023 Description of SLEEPER AIR LOW/HIGH GASS PRESSURE FAULT SY AIR			
PM168	XQ43UH	00060156	25/09/2023	GEN	39	DEFECT CLEARED 25/09/2023 REPLACED FAN ON CO UNIT LABOUR MECH 3			
PM168	XQ43UH	00060156	25/09/2023	GEN		REPAIR COMPLETED BY NICK ON 25/09/2023.			
PM168	XQ43UH	00060156	25/09/2023	GEN	16	REPLACED FAN ON CONDENSER UNIT COULDN'T FAU LEAK CON YAT			
PM168	XQ43UH	00060156	25/09/2023	GEN	13			FA0023 YAT	
PM168	XQ43UH	00060592	26/09/2023	GEN	39			450205F	BROHUI
PM168	XQ43UH	00060592	26/09/2023	GEN	39			LABEXT	BROHU
PM168	XQ43UH	00060592	26/09/2023	GEN	39			CON	BROHU
PM168	XQ43UH	00060592	26/09/2023	GEN	39			CON	BROHU
PM168	XQ43UH	00060592	26/09/2023	GEN	39			LABEXT	BROHU
PM168	XQ43UH	00060592	26/09/2023	GEN	39			450205F	BROHUI
PM168	XQ43UH	00060496	26/09/2023	WEICAL		AIR GAUGE: 16000 ADJUSTED: 16200 WEIGHBRIDGE: 15900			
PM168	XQ43UH	00060585	9/10/2023	CUMAE5	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. APPREN			
PM168	XQ43UH	00060585	9/10/2023	CUMAE5		SERVICE COMPLETED BY TYLER & NICK ON 09/10/202			
PM168	XQ43UH	00060585	9/10/2023	CUMAE5	00	FITTED SEAT COVERS LABOUR MECH 1			
PM168	XQ43UH	00060585	9/10/2023	CUMAE5	16			CON YAT	
PM168	XQ43UH	00060585	9/10/2023	CUMAE5	13	SK554BHRSB YAT			
PM168	XQ43UH	00060585	9/10/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00060585	9/10/2023	DEFECT					
PM168	XQ43UH	00060585	9/10/2023	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00060585	9/10/2023	DEFECT		Reported Defect :-Defect Code : 00010059 Defect Reference : 11832 Date : 25/09/2023 Description of D ARRANGED WITH STEVE WALKER TO FIT BLACK KW L			

						DEFECT CLEARED 09/10/2023 FITTED NEW SEAT COVE			
PM168	XQ43UH	00061213	24/10/2023	GEN	39		0A5801F1F1A0A		
PM168	XQ43UH	00061213	24/10/2023	GEN	39		AW-IVU-TRANS		
PM168	XQ43UH	00061213	24/10/2023	GEN	39		AW-BYPASS-12		
PM168	XQ43UH	00061213	24/10/2023	GEN	39		AW-AIR-KW		
PM168	XQ43UH	00061213	24/10/2023	GEN	39		AWIMM TRUCK		
PM168	XQ43UH	00061213	24/10/2023	GEN	39		0A5801F1F1A0A		
PM168	XQ43UH	00061213	24/10/2023	GEN	39		AW-IVU-TRANS		
PM168	XQ43UH	00061213	24/10/2023	GEN	39		AW-BYPASS-12		
PM168	XQ43UH	00061213	24/10/2023	GEN	39		AW-AIR-KW		
PM168	XQ43UH	00061213	24/10/2023	GEN	39		AWIMM TRUCK		
PM168	XQ43UH	00061252	30/10/2023	CUMAE5	01	LABOUR MECH 1			
PM168	XQ43UH	00061252	30/10/2023	CUMAE5		SERVICE COMPLETED BY NICK & BEN ON 30/10/2023.			
PM168	XQ43UH	00061252	30/10/2023	CUMAE5	00	REPLACED BOTTOM HEATER TAP LABOUR APPRENE			
PM168	XQ43UH	00061252	30/10/2023	CUMAE5	16		CON	YAT	
PM168	XQ43UH	00061252	30/10/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00061252	30/10/2023	DEFECT					
PM168	XQ43UH	00061252	30/10/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00070563	30/10/2023	WEICAL		CALIBRATED BY NATHAN BENNETT 30/10/2023			
						AIR GAUGE: ADJUSTED: WEIGHBRIDGE:			
PM168	XQ43UH	00061502	31/10/2023	GEN	39	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. LAB	QUAWIND01 EX00031198		
PM168	XQ43UH	00061502	31/10/2023	GEN	39		LAB	QUAWI	
PM168	XQ43UH	00061898	14/11/2023	CUMAE5	01	LABOUR APPRENB			
PM168	XQ43UH	00061898	14/11/2023	CUMAE5		SERVICE COMPLETED BY BEN & TYLER ON 14/11/202			
PM168	XQ43UH	00061898	14/11/2023	CUMAE5	00	LABOUR APPREN			
PM168	XQ43UH	00061898	14/11/2023	CUMAE5	16		CON	YAT	
PM168	XQ43UH	00061898	14/11/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00061898	14/11/2023	DEFECT					

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00061898	14/11/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00062058	21/11/2023	CUMCE5	01	LABOUR MECH 3			
PM168	XQ43UH	00062058	21/11/2023	CUMCE5		SERVICE COMPLETED BY MATT, TYLER, BEN & JOE C			
PM168	XQ43UH	00062058	21/11/2023	CUMCE5	00	LABOUR APPREN			
PM168	XQ43UH	00062058	21/11/2023	CUMCE5	00	LABOUR APPRENB			
PM168	XQ43UH	00062058	21/11/2023	CUMCE5	00	LABOUR APPRENJ			
PM168	XQ43UH	00062058	21/11/2023	CUMCE5	06			T224P	YAT
PM168	XQ43UH	00062058	21/11/2023	CUMCE5	06			TRPCAF0001	YAT
PM168	XQ43UH	00062058	21/11/2023	CUMCE5	06			LF637	YAT
PM168	XQ43UH	00062058	21/11/2023	CUMCE5	06			A-3380W1687	YAT
PM168	XQ43UH	00062058	21/11/2023	CUMCE5	06			17237	YAT
PM168	XQ43UH	00062058	21/11/2023	CUMCE5	06			WF2127	YAT
PM168	XQ43UH	00062058	21/11/2023	CUMCE5	16			CON	YAT
PM168	XQ43UH	00062056	21/11/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00062058	21/11/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00062059	21/11/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00062056	21/11/2023	DEFECT					
PM168	XQ43UH	00062058	21/11/2023	DEFECT					
PM168	XQ43UH	00062059	21/11/2023	DEFECT					
PM168	XQ43UH	00062056	21/11/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00062058	21/11/2023	DEFECT		DEFECT CLEARED ON 21/11/2023.			
PM168	XQ43UH	00062059	21/11/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00062058	21/11/2023	DEFECT		Reported Defect :-			

Defect Code : 00009519 Defect Reference : PM168 Date : 15/07/2
FRONT DIFF OUTPUT SHAFT STARTING TO LEAK

DEFECT CLEARED 21/11/2023
NOT DONE AT SERVICE - MINOR

PM168	XQ43UH	00062056	21/11/2023	ECO	01	LABOUR APPRENJ		
PM168	XQ43UH	00062056	21/11/2023	ECO		SERVICE COMPLETED BY JOE & BEN ON 21/11/2023.		
PM168	XQ43UH	00062056	21/11/2023	ECO	00	LABOUR APPRENB		
PM168	XQ43UH	00062056	21/11/2023	ECO	16		CON	YAT
PM168	XQ43UH	00062056	21/11/2023	ECO	40		10W50	YAT
PM168	XQ43UH	00062056	21/11/2023	ECO	06		ED2175254-S	YAT
PM168	XQ43UH	00062056	21/11/2023	ECO	06		FS1251	YAT
PM168	XQ43UH	00062056	21/11/2023	ECO	06		0021751550	YAT
PM168	XQ43UH	00062056	21/11/2023	ECO	06		ED0037301210	YAT
PM168	XQ43UH	00062059	21/11/2023	EXOINS	01	LABOUR MECH 3		
PM168	XQ43UH	00062059	21/11/2023	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECTIC		

INSPECTION COMPLETED BY MATT & TYLER ON 21/11

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00062059	21/11/2023	EXOINS	00	LABOUR	APPREN		
PM168	XQ43UH	00062269	27/11/2023	GEN	15			11006520	
PM168	XQ43UH	00062269	27/11/2023	GEN	15			33000084	
PM168	XQ43UH	00062269	27/11/2023	GEN	15			33000370	
PM168	XQ43UH	00062269	27/11/2023	GEN	15			33000518	
PM168	XQ43UH	00062269	27/11/2023	GEN	15			33000118	
PM168	XQ43UH	00062269	27/11/2023	GEN	15			33000118	
PM168	XQ43UH	00062269	27/11/2023	GEN	15			33000518	
PM168	XQ43UH	00062269	27/11/2023	GEN	15			33000370	
PM168	XQ43UH	00062269	27/11/2023	GEN	15			33000084	
PM168	XQ43UH	00062269	27/11/2023	GEN	15			11006520	
PM168	XQ43UH	00062591	4/12/2023	GEN	39			LABEXT	
PM168	XQ43UH	00063244	4/12/2023	GEN	39			LABEXT	
PM168	XQ43UH	00062591	4/12/2023	GEN	39			TRAVEL FEE	
PM168	XQ43UH	00063244	4/12/2023	GEN	39			TRAVEL FEE	
PM168	XQ43UH	00062591	4/12/2023	GEN	39			LABEXT	
PM168	XQ43UH	00063244	4/12/2023	GEN	39			TRAVEL FEE	
PM168	XQ43UH	00062591	4/12/2023	GEN	39			TRAVEL FEE	
PM168	XQ43UH	00063244	4/12/2023	GEN	39			LABEXT	
PM168	XQ43UH	00063083	27/12/2023	CUMAE5	01	LABOUR MECH			
PM168	XQ43UH	00063083	27/12/2023	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00063083	27/12/2023	CUMBE5	01	LABOUR APPRENJ			
PM168	XQ43UH	00063083	27/12/2023	CUMBE5		SERVICE COMPLETED BY JOE, AARON & MICK ON 27/			
PM168	XQ43UH	00063083	27/12/2023	CUMBE5	00	LABOUR MECH 4			
PM168	XQ43UH	00063083	27/12/2023	CUMBE5	00	LABOUR MECH			
PM168	XQ43UH	00063083	27/12/2023	CUMBE5	16			CON	YAT
PM168	XQ43UH	00063083	27/12/2023	CUMBE5	06			MK13584	YAT
PM168	XQ43UH	00063083	27/12/2023	CUMBE5	40			3413005	YAT
PM168	XQ43UH	00063083	27/12/2023	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00063083	27/12/2023	DEFECT					
PM168	XQ43UH	00063083	27/12/2023	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00063270	6/01/2024	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00063270	6/01/2024	DEFECT					
PM168	XQ43UH	00063270	6/01/2024	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00063270	6/01/2024	GEN	39	LABOUR APPRENB			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code

PM168	XQ43UH	00063270	6/01/2024	GEN		REPAIR COMPLETED BY BEN ON 06/01/2024. REPLACI			
PM168	XQ43UH	00063270	6/01/2024	GEN	03	GOVERNOR VALVE KW275707 YAT			
PM168	XQ43UH	00063270	6/01/2024	GEN	16		CON	YAT	
PM168	XQ43UH	00063409	7/01/2024	WEICAL		AIR GAUGE: 17000 ADJUSTED: 16600 WEIGHBRIDGE: 16300			
PM168	XQ43UH	00063521	7/01/2024	WEICAL		AIR GAUGE CALIBRATION COMPLETED CORRECTLY. 17000 ADJUSTED: 16600 WEIGHBRIDGE: 16300			
PM168	XQ43UH	00063924	22/01/2024	DEFECT	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. MECH			
PM168	XQ43UH	00063924	22/01/2024	DEFECT					
PM168	XQ43UH	00063924	22/01/2024	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00063924	22/01/2024	DEFECT		Reported Defect :-Defect Code : 00010771			
PM168	XQ43UH	00063924	22/01/2024	GEN		Defect Reference : 11820 Date : 18/01/2024 Description of SUZI COIL SOCK. CAN I HAVE OFFSET RIMS FROM XQ68QI RP91B CHEC AND BATTERY LABOUR MECH			
PM168	XQ43UH	00063924	22/01/2024	GEN	39				
PM168	XQ43UH	00063924	22/01/2024	GEN		REPAIR COMPLETED BY MICK ON 22/01/2024. FITTED			
PM168	XQ43UH	00063924	22/01/2024	GEN		SUZI COILS RP91 BATTERY ON FRIDGE HAS BEEN CHANGED. " N SWAPPINGS WHEELS N TYRES			
					16	CON YAT			
PM168	XQ43UH	00063855	23/01/2024	CUMAE5	01	LABOUR APPRENJ			
PM168	XQ43UH	00063855	23/01/2024	CUMAE5		SERVICE COMPLETED BY JOE & MATT ON 23/01/2024.			
PM168	XQ43UH	00063855	23/01/2024	CUMAE5	00	CARRY OUT A-SERVICE LABOUR MECH 3			
PM168	XQ43UH	00063855	23/01/2024	CUMAE5	16		CON	YAT	
PM168	XQ43UH	00063855	23/01/2024	CUMAE5	40		3413005	YAT	
PM168	XQ43UH	00063855	23/01/2024	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00063855	23/01/2024	DEFECT					
PM168	XQ43UH	00063855	23/01/2024	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00063958	23/01/2024	GEN	31		LABEXT		CALDIE
PM168	XQ43UH	00063958	23/01/2024	GEN	31		PART		CALDIE
PM168	XQ43UH	00063958	23/01/2024	GEN	31		LABEXT		CALDIE
PM168	XQ43UH	00063958	23/01/2024	GEN	31		PART		CALDIE

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00064341	29/01/2024	WEICAL		AIR GAUGE: 16240 ADJUSTED: 15620 WEIGHBRIDGE: 15320			
PM168	XQ43UH	00064434	10/02/2024	CUMAE5	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. MECH 1			
PM168	XQ43UH	00064434	10/02/2024	CUMAE5		SERVICE COMPLETED BY NICK & TYLER ON 10/02/202			
PM168	XQ43UH	00064434	10/02/2024	CUMAE5	00	STRAIGHTENED LHT TANK STEP LABOUR APPREN			
PM168	XQ43UH	00064434	10/02/2024	CUMAE5	16			CON YAT	
PM168	XQ43UH	00064434	10/02/2024	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00064434	10/02/2024	DEFECT					
PM168	XQ43UH	00064434	10/02/2024	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00065154	2/03/2024	CUMAE5	01	LABOUR MECH 1			
PM168	XQ43UH	00065154	2/03/2024	CUMAE5		SERVICE COMPLETED BY NICK & JOSEPH ON 02.03.2(			
PM168	XQ43UH	00065154	2/03/2024	CUMAE5	00	MUDGUARD BEING REPLACED. LABOUR APPRENJ			
PM168	XQ43UH	00065154	2/03/2024	CUMAE5	16			CON YAT	
PM168	XQ43UH	00065154	2/03/2024	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00065154	2/03/2024	DEFECT					

PM168	XQ43UH	00065154	2/03/2024	DEFECT	DEFECT CLEARED.
PM168	XQ43UH	00065154	2/03/2024	DEFECT	Reported Defect :-Defect Code : 00009138 Defect Reference : 11810 Date : 23/03/2023 Description of NO POWER TO BACK CAN I GET THE RIGHT REAR GUARD REPLACE
PM168	XQ43UH	00065154	2/03/2024	DEFECT	DEFECT CLEARED 02/03/2024 Reported Defect :- Defect Code : 00010071 Defect Reference : 11833 Date : 2 PURCHASED A SET OF KINGS 9" DRIVING LIGHTS. CA

DEFECT CLEARED 02/03/2024

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00065154	2/03/2024	DEFECT		Reported Defect :-Defect Code : 00010919 Defect Reference : 11814 Date : 06/04/2023 Description of D RIGHT HAND MIRROR SMASHED REAR RIGHT SIDE MUD GUARD - REPLACE PLEASE			
PM168	XQ43UH	00065169	4/03/2024	GEN	15	DEFECT CLEARED 02/03/2024 11004493			
PM168	XQ43UH	00065169	4/03/2024	GEN	15			33000084	
PM168	XQ43UH	00065169	4/03/2024	GEN	15			33001507	
PM168	XQ43UH	00065169	4/03/2024	GEN	15			33000533	
PM168	XQ43UH	00065169	4/03/2024	GEN	15			33000116	
PM168	XQ43UH	00065169	4/03/2024	GEN	15			33000125	
PM168	XQ43UH	00065169	4/03/2024	GEN	15			11004493	
PM168	XQ43UH	00065169	4/03/2024	GEN	15			33000084	
PM168	XQ43UH	00065169	4/03/2024	GEN	15			33001507	
PM168	XQ43UH	00065169	4/03/2024	GEN	15			33000533	
PM168	XQ43UH	00065169	4/03/2024	GEN	15			33000116	
PM168	XQ43UH	00065169	4/03/2024	GEN	15			33000125	
PM168	XQ43UH	00065267	6/03/2024	GEN	39			LABEXT	
PM168	XQ43UH	00066077	6/03/2024	GEN	39			LABEXT	
PM168	XQ43UH	00065267	6/03/2024	GEN	16			TRAVEL FEE	
PM168	XQ43UH	00066077	6/03/2024	GEN	39			TRAVEL FEE	
PM168	XQ43UH	00065267	6/03/2024	GEN	16			CON	
PM168	XQ43UH	00066077	6/03/2024	GEN	16			CON	
PM168	XQ43UH	00065267	6/03/2024	GEN	16			CALL OUT FEE	
PM168	XQ43UH	00066077	6/03/2024	GEN	39			CALL OUT FEE	
PM168	XQ43UH	00065267	6/03/2024	GEN	39			LABEXT	
PM168	XQ43UH	00066077	6/03/2024	GEN	39			LABEXT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00065267	6/03/2024	GEN	16			TRAVEL FEE	
PM168	XQ43UH	00066077	6/03/2024	GEN	39			TRAVEL FEE	

PM168	XQ43UH	00065267	6/03/2024	GEN	16			CON	
PM168	XQ43UH	00066077	6/03/2024	GEN	16			CON	
PM168	XQ43UH	00065267	6/03/2024	GEN	16			CALL OUT FEE	
PM168	XQ43UH	00066077	6/03/2024	GEN	39			CALL OUT FEE	
PM168	XQ43UH	00065243	7/03/2024	DEFECT	01	LABOUR	MECH		
PM168	XQ43UH	00065243	7/03/2024	DEFECT					
PM168	XQ43UH	00065243	7/03/2024	DEFECT		DEFECT	CLEARED.		
PM168	XQ43UH	00065243	7/03/2024	GEN	39	LABOUR APPREN			
PM168	XQ43UH	00065243	7/03/2024	GEN		REPAIR COMPLETED BY TYLER & BEN ON 07/03/2024.			
PM168	XQ43UH	00065243	7/03/2024	GEN		& AIR BAG FITTED 2 NEW KENWORTH MUDFLAPS			
					00	LABOUR APPRENB			
PM168	XQ43UH	00065243	7/03/2024	GEN	17			K127-1116-10A	YAT
PM168	XQ43UH	00065243	7/03/2024	GEN	14			P54-1281-006	YAT
PM168	XQ43UH	00065243	7/03/2024	GEN	10			C81-1005	YAT
PM168	XQ43UH	00065243	7/03/2024	GEN	17			KWB6B	YAT
PM168	XQ43UH	00065520	18/03/2024	CUMAE5	01	LABOUR MECH			
PM168	XQ43UH	00065520	18/03/2024	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00065520	18/03/2024	CUMBE5	01	LABOUR MECH 4			
PM168	XQ43UH	00065520	18/03/2024	CUMBE5		SERVICE COMPLETED BY ETHAN & JOSEPH ON 18/03			
PM168	XQ43UH	00065520	18/03/2024	CUMBE5	00	WIPERS LABOUR APPRENJ			
PM168	XQ43UH	00065520	18/03/2024	CUMBE5	16			CON	YAT
PM168	XQ43UH	00065520	18/03/2024	CUMBE5	06			MK13584	YAT
PM168	XQ43UH	00065520	18/03/2024	CUMBE5	40			3413005	YAT
PM168	XQ43UH	00065520	18/03/2024	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00065520	18/03/2024	DEFECT					
PM168	XQ43UH	00065520	18/03/2024	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00065520	18/03/2024	DEFECT		Reported Defect :- Defect Code : 00011031 Defect Reference : 11822 Date : 09 PASSENGER SIDE TANK TOP FOOT PLATE REPAIR OR DRIVE TYRES AS HAD SLIDE OTHER DAY			
PM168	XQ43UH	00065520	18/03/2024	DEFECT		DEFECT CLEARED 18/03/2024			
PM168	XQ43UH	00065520	18/03/2024	DEFECT		Reported Defect :-Defect Code : 00011052 Defect Reference : 11824(A) Date : 06/03/2024 Description WIPER BLADES REPLACE & WATER HOSES			
PM168	XQ43UH	00065520	18/03/2024	DEFECT		DEFECT CLEARED 18/03/2024 Reported Defect :- Defect Code : 00011054 Defect Reference : 11824(C) Date : 06/03/2024 Description of Defect : INDICATOR REVERSE BEEPER			
PM168	XQ43UH	00065652	20/03/2024	GEN	15	DEFECT CLEARED 18/03/2024 11004493			
PM168	XQ43UH	00065652	20/03/2024	GEN	15			33000084	
PM168	XQ43UH	00065652	20/03/2024	GEN	15			33000371	
PM168	XQ43UH	00065652	20/03/2024	GEN	15			33000517	
PM168	XQ43UH	00065652	20/03/2024	GEN	15			33000118	
PM168	XQ43UH	00065652	20/03/2024	GEN	15			11004493	
PM168	XQ43UH	00065652	20/03/2024	GEN	15			33000084	
PM168	XQ43UH	00065652	20/03/2024	GEN	15			33000371	
PM168	XQ43UH	00065652	20/03/2024	GEN	15			33000517	
PM168	XQ43UH	00065652	20/03/2024	GEN	15			33000118	
PM168	XQ43UH	00066335	12/04/2024	CUMAE5	01	LABOUR MECH 4			
PM168	XQ43UH	00066335	12/04/2024	CUMAE5		'A' SERVICE COMPLETED BY ETHAN & TYSON ON 12/0			
PM168	XQ43UH	00066335	12/04/2024	CUMAE5	00	LABOUR APPRENT2			
PM168	XQ43UH	00066335	12/04/2024	CUMAE5	16			CON	YAT
PM168	XQ43UH	00066335	12/04/2024	DEFECT	01	LABOUR MECH			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code

PM168	XQ43UH	00066335	12/04/2024	DEFECT					
PM168	XQ43UH	00066335	12/04/2024	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00066371	15/04/2024	WEICAL		AIR GAUGE: 15780 ADJUSTED: 16500 WEIGHBRIDGE: 16240			
PM168	XQ43UH	00066504	20/04/2024	CUMAE5	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			
PM168	XQ43UH	00066504	20/04/2024	CUMAE5		'A' SERVICE COMPLETED BY TYLER ON 20/04/2024. RE CAMERA READJUSTED INSIDE CAMERA			
						NOTED: * MONITOR FRONT DRIVE BRAKE WEAR. DEFECT NO. 00011			
PM168	XQ43UH	00066504	20/04/2024	CUMAE5	16			CON	YAT
PM168	XQ43UH	00066504	20/04/2024	CUMAE5	40			3413005	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00066504	20/04/2024	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00066504	20/04/2024	DEFECT					
PM168	XQ43UH	00066504	20/04/2024	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00066504	20/04/2024	DEFECT		Reported Defect :-Defect Code : 00011302 Defect Reference : 17401 Date : 11/04/2024 Description of RESET DRIVER FACING CAMERA. REPOSITION - CALL			
PM168	XQ43UH	00067421	24/05/2024	CUMAE5	01	DEFECT CLEARED ON 20/04/2024 REPLACED DRIVER' 4			
PM168	XQ43UH	00067421	24/05/2024	CUMAE5		'A' SERVICE COMPLETED BY ETHAN & JOSEPH ON 24			
PM168	XQ43UH	00067421	24/05/2024	CUMAE5	00	LABOUR APPRENJ			
PM168	XQ43UH	00067421	24/05/2024	CUMAE5	16			CON	YAT
PM168	XQ43UH	00067421	24/05/2024	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00067483	24/05/2024	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00067421	24/05/2024	DEFECT					
PM168	XQ43UH	00067483	24/05/2024	DEFECT					
PM168	XQ43UH	00067421	24/05/2024	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00067483	24/05/2024	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00067483	24/05/2024	ECO	01	LABOUR APPRENJ			
PM168	XQ43UH	00067483	24/05/2024	ECO		SLEEPER AIR SERVICE COMPLETED BY JOSEPH & BE			
PM168	XQ43UH	00067483	24/05/2024	ECO	16	NOTED: * REPLACE FUEL PRIMER PUMP ON NEXT FULL SERV CON YAT C			
PM168	XQ43UH	00067483	24/05/2024	ECO	00	LABOUR MECH 5			
PM168	XQ43UH	00067483	24/05/2024	ECO	40			10W50	YAT
PM168	XQ43UH	00067483	24/05/2024	ECO	06			ED002175254-S	YAT
PM168	XQ43UH	00068594	19/06/2024	CUMAE5	01	LABOUR MECH			
PM168	XQ43UH	00068594	19/06/2024	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00068594	19/06/2024	CUMBE5	01	LABOUR MECH 4			
PM168	XQ43UH	00068594	19/06/2024	CUMBE5		'B' SERVICE COMPLETED BY ETHAN, JOSEPH & CORE			
						BODY BOLTS ON CROSSBAR LOOSE - RETORQUED R REPLACED AIR FILTER AS WAS PERISHED ADJUSTED HEAD LIGHT AND REPAIRED RHS HEAD LI LABOUR APPRENJ			
PM168	XQ43UH	00068594	19/06/2024	CUMBE5	00				
PM168	XQ43UH	00068594	19/06/2024	CUMBE5	00	LABOUR MECH 6			
PM168	XQ43UH	00068594	19/06/2024	CUMBE5	40			3413005	YAT
PM168	XQ43UH	00068594	19/06/2024	CUMBE5	06			MK13584	YAT
PM168	XQ43UH	00068594	19/06/2024	CUMBE5	06			AF1969M	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00068594	19/06/2024	CUMBE5	03			5607734RX	YAT
PM168	XQ43UH	00068594	19/06/2024	CUMBE5	03			3690864RX	YAT
PM168	XQ43UH	00068594	19/06/2024	CUMBE5	06			COOLANT	YAT

PM168	XQ43UH	00068594	19/06/2024	CUMBE5	03			275707	YAT
PM168	XQ43UH	00068594	19/06/2024	CUMBE5	03			PART	YAT
PM168	XQ43UH	00068594	19/06/2024	CUMBE5	02			KSMA2124707Q	YAT
PM168	XQ43UH	00068594	19/06/2024	CUMBE5	16			CON	YAT
PM168	XQ43UH	00068594	19/06/2024	DEFECT	01	LABOUR	MECH		
PM168	XQ43UH	00068594	19/06/2024	DEFECT					
PM168	XQ43UH	00068594	19/06/2024	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00068594	19/06/2024	DEFECT		Reported Defect :-Defect Code : 00011303 Defect Reference : PM168 Date : 20/04/2024 Description o MONITOR FRONT DRIVE BRAKE WEAR			
PM168	XQ43UH	00068594	19/06/2024	DEFECT		DEFECT CLEARED ON 19/06/2024 Reported Defect :- Defect Code : 00011053 Defect Reference : 11824(B) Date Description of Defect : STEERING ALIGNMENT			
PM168	XQ43UH	00068594	19/06/2024	DEFECT		DEFECT CLEARED ON 19/06/2024 ALIGNMENT LOOKS Reported Defect :- Defect Code : 00011269 Defect Reference : 36871 Date : 1 Description of Defect : AIR DRYER NOT WORKING AIR GAUGE: 16300			
PM168	XQ43UH	00068473	19/06/2024	WEICAL		ADJUSTED: 16600 WEIGHBRIDGE: 16300			
PM168	XQ43UH	00068477	19/06/2024	WEICAL		AIR GAUGE CALIBRATION COMPLETED CORRECTLY. 16700 ADJUSTED: 16400 WEIGHBRIDGE: 16700 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00068481	19/06/2024	WEICAL		AIR GAUGE: 14720 ADJUSTED: 14420 WEIGHBRIDGE: 14720 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			
PM168	XQ43UH	00068485	19/06/2024	WEICAL		ADJUSTED: 15000 WEIGHBRIDGE: 15280 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			
PM168	XQ43UH	00068940	28/06/2024	WEICAL		ADJUSTED: 15680 WEIGHBRIDGE: 15380 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			
PM168	XQ43UH	00068943	28/06/2024	WEICAL		ADJUSTED: 14640 WEIGHBRIDGE: 14240 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			
PM168	XQ43UH	00069022	28/06/2024	WEICAL		ADJUSTED: 16620 WEIGHBRIDGE: 16220 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.			
PM168	XQ43UH	00069763	7/08/2024	CUMAE5	01				
PM168	XQ43UH	00069763	7/08/2024	CUMAE5		'A' SERVICE COMPLETED BY NICK & JOSEPH ON 07/0			

						NOTED: * REAR DIFF SEEPING * LHS CAB MOUNT SHOCK LEAKING LABOUR APPREN				
PM168	XQ43UH	00069763	7/08/2024	CUMAE5	00					
PM168	XQ43UH	00069763	7/08/2024	CUMAE5	16			CON	YAT	
PM168	XQ43UH	00069763	7/08/2024	DEFECT	01	LABOUR MECH				
PM168	XQ43UH	00069763	7/08/2024	DEFECT						
PM168	XQ43UH	00069763	7/08/2024	DEFECT		DEFECT CLEARED.				
PM168	XQ43UH	00070784	6/09/2024	CUMAE5	01	LABOUR MECH 1				
PM168	XQ43UH	00070784	6/09/2024	CUMAE5		'A' SERVICE COMPLETED BY NICK & BEN (WORKSHOI				
PM168	XQ43UH	00070784	6/09/2024	CUMAE5	00	REPLACED ADJUSTABLE STEERING WHEEL TILT CAE CAP LABOUR MECH 5				
PM168	XQ43UH	00070784	6/09/2024	CUMAE5	16			CON	YAT	
PM168	XQ43UH	00070784	6/09/2024	DEFECT	01	LABOUR MECH				
PM168	XQ43UH	00070784	6/09/2024	DEFECT						

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00070784	6/09/2024	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00071452	25/09/2024	CUMAE5	01	LABOUR MECH			
PM168	XQ43UH	00071452	25/09/2024	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00071452	25/09/2024	CUMBE5	01	LABOUR APPRENJ			
PM168	XQ43UH	00071452	25/09/2024	CUMBE5		'B' SERVICE COMPLETED BY JOSEPH, TYLER, NICK &			
						REPLACED AIR INTAKE RUBBERS. REPLACED BOLT F REPLACED TURNTABLE JAW REPLACED INDICATOR LABOUR APPREN			
PM168	XQ43UH	00071452	25/09/2024	CUMBE5	00				
PM168	XQ43UH	00071452	25/09/2024	CUMBE5	00	LABOUR MECH 1			
PM168	XQ43UH	00071452	25/09/2024	CUMBE5	00	LABOUR APPRENJC			
PM168	XQ43UH	00071452	25/09/2024	CUMBE5	16			CON	YAT	
PM168	XQ43UH	00071452	25/09/2024	CUMBE5	06			AS2474	YAT	
PM168	XQ43UH	00071452	25/09/2024	CUMBE5	11			89440	YAT	
PM168	XQ43UH	00071452	25/09/2024	CUMBE5	11			6PK1590	YAT	
PM168	XQ43UH	00071452	25/09/2024	CUMBE5	11			12PK2380	YA	
PM168	XQ43UH	00071452	25/09/2024	CUMBE5	11			89448	YAT	
PM168	XQ43UH	00071452	25/09/2024	CUMBE5	40			3413005	YAT	
PM168	XQ43UH	00071452	25/09/2024	CUMBE5	06			MK13555	YAT	
PM168	XQ43UH	00071452	25/09/2024	CUMBE5	13			SK3221/52Z	YAT	
PM168	XQ43UH	00071452	25/09/2024	CUMBE5	13			202-841	YAT	
PM168	XQ43UH	00071452	25/09/2024	DEFECT	01	LABOUR MECH				
PM168	XQ43UH	00071452	25/09/2024	DEFECT						
PM168	XQ43UH	00071452	25/09/2024	DEFECT		DEFECT CLEARED.				
PM168	XQ43UH	00072865	23/10/2024	CUMAE5	01	LABOUR MECH 5				
PM168	XQ43UH	00072865	23/10/2024	CUMAE5		SERVICE COMPLETED.				
						REPAIRED TRAILER LIGHTS HARNESS AS IT WAS FUL REPLACED RED AIRLINE AND EBS LEAD REPLACED F 43764 YAT CI			
PM168	XQ43UH	00072865	23/10/2024	CUMAE5	16					
PM168	XQ43UH	00072865	23/10/2024	CUMAE5	16			CON	YAT	
PM168	XQ43UH	00072865	23/10/2024	CUMAE5	00	LABOUR APPRENJ				
PM168	XQ43UH	00072865	23/10/2024	DEFECT	01	LABOUR MECH				
PM168	XQ43UH	00072865	23/10/2024	DEFECT						
PM168	XQ43UH	00072865	23/10/2024	DEFECT		DEFECT CLEARED.				
PM168	XQ43UH	00072865	23/10/2024	DEFECT		Reported Defect :-Defect Code : 00012597 Defect Reference : PM168 Date : 08/10/2024 Description o DRIVER FACING CAMERA NEEDS TO BE RE-MOUNTEI DRIVER DISMOUNTED IT AND LEFT IT ON THE DASH.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code

PM168	XQ43UH	00072865	23/10/2024	DEFECT		Reported Defect :-Defect Code : 00012511
PM168	XQ43UH	00075032	2/11/2024	WEICAL		Defect Reference : 36251 Date : 22/09/2024 Description of DRIVER FACING CAMERA MOVED. POSSIBLY DAMAGI AIR GAUGE: 16.36
						ADJUSTED: 16.66 WEIGHBRIDGE: 16.10
PM168	XQ43UH	00073220	5/11/2024	DEFECT	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. MECH
PM168	XQ43UH	00073220	5/11/2024	DEFECT		
PM168	XQ43UH	00073220	5/11/2024	DEFECT		DEFECT CLEARED.
PM168	XQ43UH	00073220	5/11/2024	DEFECT		Reported Defect :-Defect Code : 00012771
PM168	XQ43UH	00073220	5/11/2024	DEFECT		Defect Reference : PM168 Date : 23/10/2024 Description o NO AIRCON Reported Defect :-
				GEN	13	Defect Code : 00012721 Defect Reference : PM168 Date : Description of Defect : AIR CON NOT WORKING K251-571 BROHUR01
PM168	XQ43UH	00073156	5/11/2024			
PM168	XQ43UH	00073156	5/11/2024	GEN	16	K207-965-6 BROHUI
PM168	XQ43UH	00073156	5/11/2024	GEN	13	F69-1019 BROHUI
PM168	XQ43UH	00073220	5/11/2024	GEN		REPAIR COMPLETED BY BDS MECHANICAL ON 05/11/
						A/C NOT COLD Drive to site. Diagnose A/C not getting cold. Gauges conne gauges not moving - meaning compressor not engaging. P compressor all good - meaning clutch has failed. New parts removed. New compressor mounted & secured. Belt was p with new. Vehicle pressure tested with 200psi nitrogen. No vacuumed & checked for leaks & all good. System was cha Operation checked & vent temp getting below 9deg. Vehicl cleaned up. Drive back to workshop. K251-571 BROHUR01 3370345

PM168	XQ43UH	00073156	5/11/2024	GEN	13				
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00073220	5/11/2024	GEN	39			LABEXT	
PM168	XQ43UH	00073156	5/11/2024	GEN	16			K207-965-6	
PM168	XQ43UH	00073220	5/11/2024	GEN	16			TRAVEL FEE	
PM168	XQ43UH	00073156	5/11/2024	GEN	13			F69-1019	
PM168	XQ43UH	00073220	5/11/2024	GEN	16			CON	
PM168	XQ43UH	00073220	5/11/2024	GEN	39			LABEXT	
PM168	XQ43UH	00073220	5/11/2024	GEN	39			LABEXT	
PM168	XQ43UH	00073220	5/11/2024	GEN	16			TRAVEL FEE	
PM168	XQ43UH	00073220	5/11/2024	GEN	16			CON	
PM168	XQ43UH	00073220	5/11/2024	GEN	39			LABEXT	
PM168	XQ43UH	00073361	7/11/2024	TYRES	15			11006520	
PM168	XQ43UH	00073361	7/11/2024	TYRES	15			77000194	
PM168	XQ43UH	00073361	7/11/2024	TYRES	15			33000084	
PM168	XQ43UH	00073361	7/11/2024	TYRES	15			33000517	
PM168	XQ43UH	00073361	7/11/2024	TYRES	15			33000118	
PM168	XQ43UH	00073361	7/11/2024	TYRES	15			11006520	
PM168	XQ43UH	00073361	7/11/2024	TYRES	15			77000194	
PM168	XQ43UH	00073361	7/11/2024	TYRES	15			33000084	
PM168	XQ43UH	00073361	7/11/2024	TYRES	15			33000517	

PM168	XQ43UH	00073361	7/11/2024	TYRES	15			33000118	
PM168	XQ43UH	00073591	21/11/2024	CUMAE5	01	LABOUR APPREN			
PM168	XQ43UH	00073591	21/11/2024	CUMAE5		'A' SERVICE COMPLETED BY TYLER & JOSEPH (WORKSHOP) O			
TOPPED UP ENGINE OIL									
PM168	XQ43UH	00073591	21/11/2024	CUMAE5	00	LABOUR APPRENJ			
PM168	XQ43UH	00073591	21/11/2024	CUMAE5	16			CON	YAT
PM168	XQ43UH	00073591	21/11/2024	CUMAE5	40			3413005	YAT
PM168	XQ43UH	00073591	21/11/2024	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00073591	21/11/2024	DEFECT					
PM168	XQ43UH	00073591	21/11/2024	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00074351	24/12/2024	CUMAE5	01	LABOUR MECH			
PM168	XQ43UH	00074351	24/12/2024	CUMAE5		SERVICE COMPLETED.			
PM168	XQ43UH	00074351	24/12/2024	CUMBE5	01	LABOUR MECH 6			
PM168	XQ43UH	00074351	24/12/2024	CUMBE5		'B' SERVICE COMPLETED BY COREY & JOSEPH (WORK			
						REPLACED RADIATOR STAY BAR BUSHES TERMINALS FOR SLEEPER AIR WERE LOOSE (TIGHTENED U			
						F/E EXP : JULY 2025			
PM168	XQ43UH	00074351	24/12/2024	CUMBE5	00	LABOUR APPRENJ			
PM168	XQ43UH	00074351	24/12/2024	CUMBE5	16			CON	YAT
PM168	XQ43UH	00074351	24/12/2024	CUMBE5	40			3413005	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00074351	24/12/2024	CUMBE5	06			MK13584	YAT
PM168	XQ43UH	00074351	24/12/2024	DEFECT	01	LABOUR	MECH		
PM168	XQ43UH	00074351	24/12/2024	DEFECT					
PM168	XQ43UH	00074351	24/12/2024	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00074351	24/12/2024	DEFECT		Reported Defect :- Defect Code : 00013219 Defect Reference : 58651 Date : 2 Description of Defect : SLEEPER AIR COOLER LOW BATTERY VOLTAGE. RIG SPOTLIGHT NOT WORKING GOT NO FLOOR K200 MATS.			
PM168	XQ43UH	00074351	24/12/2024	DEFECT		DEFECT CLEARED ON 24/12/2024 Reported Defect :- Defect Code : 00013149 Defect Reference : PM168 Date : Description of Defect : RIGHT HAND SPOTLIGHT NO WORKING			
PM168	XQ43UH	00074719	9/01/2025	GEN	39	DEFECT CLEARED ON 24/12/2024 LABEXT	NABQAN01		
PM168	XQ43UH	00074719	9/01/2025	GEN	06			PART	NABQA
PM168	XQ43UH	00074719	9/01/2025	GEN	39			LABEXT	NABQA
PM168	XQ43UH	00074719	9/01/2025	GEN	06			PART	NABQA
PM168	XQ43UH	00074773	16/01/2025	CUMAE5	01	LABOUR APPREN			
PM168	XQ43UH	00074773	16/01/2025	CUMAE5		'A' SERVICE COMPLETED BY TYLER & JOSH (WORKSHOP) ON 1			
PM168	XQ43UH	00074773	16/01/2025	CUMAE5	00	F/E EXP : JULY 2025 LABOUR APPRENJC			
PM168	XQ43UH	00074773	16/01/2025	CUMAE5	16			CON	YAT
PM168	XQ43UH	00074774	16/01/2025	CUMCE5	01	LABOUR MECH 6			
PM168	XQ43UH	00074774	16/01/2025	CUMCE5		'C' SERVICE COMPLETED BY COREY, TYLER & JOSH (			
						ADJUSTED TURNTABLE. ADJUSTED RHS STEER WHEEL BEARING (SMALL MO'			
						NOTED: * THRU SHAFT SEAL LEAKING * CHECK OIL LEAK AROUND POWER STEERING PUMF LABOUR APPREN			
PM168	XQ43UH	00074774	16/01/2025	CUMCE5	00				
PM168	XQ43UH	00074774	16/01/2025	CUMCE5	00	LABOUR APPRENJC			
PM168	XQ43UH	00074774	16/01/2025	CUMCE5	16			CON	YAT
PM168	XQ43UH	00074774	16/01/2025	CUMCE5	06			17237	YAT
PM168	XQ43UH	00074774	16/01/2025	CUMCE5	06			WF2127	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00074774	16/01/2025	CUMCE5	06			A-3380W1687	YAT
PM168	XQ43UH	00074774	16/01/2025	CUMCE5	06			UF110	YAT
PM168	XQ43UH	00074774	16/01/2025	CUMCE5	06			LF637	YAT
PM168	XQ43UH	00074774	16/01/2025	CUMCE5	06			FS19764	YAT
PM168	XQ43UH	00074774	16/01/2025	CUMCE5	06			T224P	YAT
PM168	XQ43UH	00074774	16/01/2025	CUMCE5	06			TRPCAF0001	YAT
PM168	XQ43UH	00074774	16/01/2025	CUMCE5	11			6PK1590	YAT
PM168	XQ43UH	00074774	16/01/2025	CUMCE5	11			12PK2380	YAT
PM168	XQ43UH	00074773	16/01/2025	DEFECT	01	LABOUR	MECH		
PM168	XQ43UH	00074774	16/01/2025	DEFECT	01	LABOUR	MECH		
PM168	XQ43UH	00074775	16/01/2025	DEFECT	01	LABOUR	MECH		
PM168	XQ43UH	00074776	16/01/2025	DEFECT	01	LABOUR	MECH		
PM168	XQ43UH	00074773	16/01/2025	DEFECT					
PM168	XQ43UH	00074774	16/01/2025	DEFECT					
PM168	XQ43UH	00074775	16/01/2025	DEFECT					
PM168	XQ43UH	00074776	16/01/2025	DEFECT					
PM168	XQ43UH	00074773	16/01/2025	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00074774	16/01/2025	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00074775	16/01/2025	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00074776	16/01/2025	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00074773	16/01/2025	DEFECT		Reported Defect :-			
						Defect Code : 00011582			
						Defect Reference : PM168 Date : 24/05/2024 Description of Defect			
						REPLACE FUEL PRIMER PUMP ON NEXT SERVICE - SLEEPER			
PM168	XQ43UH	00074776	16/01/2025	ECO	01	DEFECT CLEARED ON 16/01/2025 FUEL PUMP WAS ALL GOOD LABOUR MECH 6			
PM168	XQ43UH	00074776	16/01/2025	ECO		SLEEPER AIR SERVICE COMPLETED BY COREY & JOS			
PM168	XQ43UH	00074776	16/01/2025	ECO	00	FUEL PUMP WAS ALL GOOD LABOUR APPRENJC			
PM168	XQ43UH	00074776	16/01/2025	ECO	16			CON	YAT
PM168	XQ43UH	00074776	16/01/2025	ECO	40			10W50	YAT
PM168	XQ43UH	00074776	16/01/2025	ECO	06			ED0021751550	YAT
PM168	XQ43UH	00074776	16/01/2025	ECO	06			ED0037300960	YAT
PM168	XQ43UH	00074776	16/01/2025	ECO	06			FS1251	YAT
PM168	XQ43UH	00074776	16/01/2025	ECO	06			ED002175254-S	YAT
PM168	XQ43UH	00074776	16/01/2025	ECO	16			BS358N70	YAT
PM168	XQ43UH	00074775	16/01/2025	EXOINS	01	LABOUR MECH 6			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00074775	16/01/2025	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECTIC			
PM168	XQ43UH	00075747	17/02/2025	CUMAE5	00	INSPECTION COMPLETED BY COREY (WORKSHOP) C NO DEFECTS IDENTIFIED LABOUR APPRENJ			
PM168	XQ43UH	00075747	17/02/2025	CUMAE5		A SERVICE COMPLETED BY JOSEPH, BEN & JOSH (W FIRE EXT EXP: JULY 2025 NOTED: * LEAK FRONT LHS IN THE FRONT. NEED TO GET IT B.			
PM168	XQ43UH	00075747	17/02/2025	CUMAE5	16			CON	YAT
PM168	XQ43UH	00075747	17/02/2025	CUMAE5	00	LABOUR MECH 5			
PM168	XQ43UH	00075747	17/02/2025	CUMAE5	00	LABOUR APPRENJC			
PM168	XQ43UH	00075747	17/02/2025	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00075747	17/02/2025	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00076206	13/03/2025	CUMAE5	00	LABOUR MECH			
PM168	XQ43UH	00076206	13/03/2025	CUMAE5		A SERVICE COMPLETED.			
PM168	XQ43UH	00076206	13/03/2025	CUMAE5	16	FIRE EXT EXP: CON			YAT
PM168	XQ43UH	00076206	13/03/2025	CUMBE5	01	LABOUR APPREN			

PM168	XQ43UH	00076206	13/03/2025	CUMBE5			B SERVICE COMPLETED BY WORKSHOP 10/03/2025		
							FIRE EXT EXP: JULY 2025		
							CPOMPLETED FULL DRIVE BRAKE RELINE		
							DEFECT - *MONITOR OIL FROM OIL FILTER (OLD OIL FILTER S		
PM168	XQ43UH	00076206	13/03/2025	CUMBE5	16			CON	YAT
PM168	XQ43UH	00076206	13/03/2025	CUMBE5	00		LABOUR APPRENJC		
PM168	XQ43UH	00076206	13/03/2025	CUMBE5	00		LABOUR MECH 5		
PM168	XQ43UH	00076206	13/03/2025	CUMBE5	16			R4707QP	YAT
PM168	XQ43UH	00076206	13/03/2025	CUMBE5	16			RSK154	YAT
PM168	XQ43UH	00076206	13/03/2025	CUMBE5	06			Z1006	YAT
PM168	XQ43UH	00076206	13/03/2025	DEFECT	01		LABOUR MECH		
PM168	XQ43UH	00076206	13/03/2025	DEFECT			DEFECT CLEARED.		
PM168	XQ43UH	00076261	13/03/2025	GEN	15			PART	
PM168	XQ43UH	00076261	13/03/2025	GEN	39			LAB	
PM168	XQ43UH	00076261	13/03/2025	GEN	15			LAB	
PM168	XQ43UH	00076261	13/03/2025	GEN	15			PART	
PM168	XQ43UH	00076261	13/03/2025	GEN	39			LAB	
PM168	XQ43UH	00076261	13/03/2025	GEN	15			LAB	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			99015526	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			33000084	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			33000370	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			33000536	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			33000118	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			11006520	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			33000084	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			33000370	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			33000518	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			99015526	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			33000084	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			33000370	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			33000536	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			33000118	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			11006520	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			33000084	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			33000370	
PM168	XQ43UH	00076636	26/03/2025	TYRES	15			33000518	
PM168	XQ43UH	00076954	8/04/2025	DEFECT	01		LABOUR MECH		
PM168	XQ43UH	00076954	8/04/2025	DEFECT			DEFECT CLEARED.		
PM168	XQ43UH	00076954	8/04/2025	GEN	39		LABOUR MECH 1		
PM168	XQ43UH	00076954	8/04/2025	GEN			REPAIR COMPLETED BY WORKSHOP 08/04/2025		
PM168	XQ43UH	00076954	8/04/2025	GEN	16		REPAIR AND REPLACE MALE 7 PIN PLUG AND TEST R REPLACE SUZI COILS CON YAT		
PM168	XQ43UH	00076954	8/04/2025	GEN	16			82161/1	YAT
PM168	XQ43UH	00076954	8/04/2025	GEN	16			61-SC3MTLTSE	YAT
PM168	XQ43UH	00077115	15/04/2025	CUMAE5	00		LABOUR MECH 1		
PM168	XQ43UH	00077115	15/04/2025	CUMAE5			A SERVICE COMPLETED BY WORKSHOP 14/04/2025		
							FIRE EXT EXP: JULY 25		
							DEFECTS CHECKED - ALL OK #12088 #12089 #13688 #13369 #13838 #13368 #13480 #13895 #12088 #12089		
							DEFECT #13952 - TYRE SENT TO TYRE BAY EXHAUST LEAK A FIT POGO STIICK AND SECURE SUZI COILS ECT.		
PM168	XQ43UH	00077115	15/04/2025	CUMAE5	16			CON	YAT

PM168	XQ43UH	00077115	15/04/2025	CUMAE5	00	LABOUR APPRENJC			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00077115	15/04/2025	CUMAE5	16			BGCA3559	YAT
PM168	XQ43UH	00077115	15/04/2025	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00077115	15/04/2025	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00077115	15/04/2025	DEFECT		Reported Defect :-Defect Code : 00013952			
PM168	XQ43UH	00077115	15/04/2025	DEFECT		Defect Reference : 58655B Date : 04/04/2025 Description o BATTERIES ARE ON WAY OUT Reported Defect :-			
						Defect Code : 00013688 Defect Reference : PM168 Date : LEAK FRONT LHS IN THE FRONT. NEED TO GET IT BA Reported Defect :-			
PM168	XQ43UH	00077115	15/04/2025	DEFECT		Defect Code : 00013369 Defect Reference : PM168 Date : CHECK OIL LEAK AROUND POWER STEERING PUMP Reported Defect :-			
PM168	XQ43UH	00077115	15/04/2025	DEFECT		Defect Code : 00013838 Defect Reference : PM168 Date : MONITOR OIL FROM OIL FILTER (OIL FILTER SEAL LEA Reported Defect :-			
PM168	XQ43UH	00077115	15/04/2025	DEFECT		Defect Code : 00013950 Defect Reference : 58655 Date : 0 NEW STEER TYRE ON RIGHT OLD ONE ON LEFT Reported Defect :-			
PM168	XQ43UH	00077115	15/04/2025	DEFECT		Defect Code : 00013895 Defect Reference : 58654 Date : 2 STEERING HAS A LOT OF PLAY IN IT. Reported Defect :-			
PM168	XQ43UH	00077115	15/04/2025	DEFECT		Defect Code : 00013368 Defect Reference : PM168 Date : THRU SHAFT SEAL LEAKING			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00077115	15/04/2025	DEFECT		Reported Defect :-Defect Code : 00012089			
PM168	XQ43UH	00077115	15/04/2025	DEFECT		Defect Reference : PM168 Date : 07/08/2024 Description o LHS CAB MOUNT SHOCK LEAKING Reported Defect :-			
						Defect Code : 00013480 Defect Reference : PM168 Date : FRIDGE UNDERNEATH THE BUNK ON PASSENGER SI PASSENGER SIDE. Reported Defect :-			
PM168	XQ43UH	00077115	15/04/2025	DEFECT		Defect Code : 00012088 Defect Reference : PM168 Date : REAR DIFF SEEPING LABOUR APPREN			
PM168	XQ43UH	00077312	28/04/2025	CUMAE5	00				
PM168	XQ43UH	00077312	28/04/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 26/04/2025 FIRE EXT EXP: JULY 25			

PM168	XQ43UH	00077312	28/04/2025	CUMAE5	16				STEER TYRES ARE GOOD CLEANED UP TANK LIGHT \ CON YAT C
PM168	XQ43UH	00077312	28/04/2025	DEFECT	01				LABOUR MECH
PM168	XQ43UH	00077312	28/04/2025	DEFECT					DEFECT CLEARED.
PM168	XQ43UH	00077312	28/04/2025	DEFECT					Reported Defect :-Defect Code : 00013951 Defect Reference : 58655A Date : 04/04/2025 Description EXHAUST GOT HOLE IN IT
PM168	XQ43UH	00077620	8/05/2025	TYRES	15			33000096	
PM168	XQ43UH	00077620	8/05/2025	TYRES	15			33000118	
PM168	XQ43UH	00077620	8/05/2025	TYRES	15			33000096	
PM168	XQ43UH	00077620	8/05/2025	TYRES	15			33000118	
PM168	XQ43UH	00078079	26/05/2025	TYRES	15			11003134	
PM168	XQ43UH	00078079	26/05/2025	TYRES	15			77000232	
PM168	XQ43UH	00078079	26/05/2025	TYRES	15			33000084	
PM168	XQ43UH	00078079	26/05/2025	TYRES	15			33000517	
PM168	XQ43UH	00078079	26/05/2025	TYRES	15			33000118	
PM168	XQ43UH	00078079	26/05/2025	TYRES	15			11003134	
PM168	XQ43UH	00078079	26/05/2025	TYRES	15			77000232	
PM168	XQ43UH	00078079	26/05/2025	TYRES	15			33000084	
PM168	XQ43UH	00078079	26/05/2025	TYRES	15			33000517	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00078079	26/05/2025	TYRES	15			33000118	
PM168	XQ43UH	00078151	31/05/2025	CUMAE5	00	LABOUR MECH			
PM168	XQ43UH	00078151	31/05/2025	CUMAE5		A SERVICE COMPLETED.			
PM168	XQ43UH	00078151	31/05/2025	CUMAE5	16	FIRE EXT EXP: CON			YAT
PM168	XQ43UH	00078151	31/05/2025	CUMBE5	01	LABOUR MECH 1			
PM168	XQ43UH	00078151	31/05/2025	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 31.05.2025			
						FIRE EXT EXP: JULY 2025			
						SHOCKY LEKAKING 2ND AXLE R/H D# 14327 THROUG LEAKING D# 14328 GEAR BOX SEAL LEAKING D# 14329 GEAR BOX PRESSURE SWITCH LEAKING D# 14330			
PM168	XQ43UH	00078151	31/05/2025	CUMBE5	16	TIGHTENED BELLY FOR BOLT S REPLACED 1X TOP RADIATOR STAY RUBBER CON YAT			
PM168	XQ43UH	00078151	31/05/2025	CUMBE5	00	LABOUR APPREN			
PM168	XQ43UH	00078151	31/05/2025	CUMBE5	00	LABOUR APPRENJ			
PM168	XQ43UH	00078151	31/05/2025	CUMBE5	16			RSK154	YAT
PM168	XQ43UH	00078151	31/05/2025	CUMBE5	16			Z1006	YAT
PM168	XQ43UH	00078151	31/05/2025	CUMBE5	40			3413005	YAT
PM168	XQ43UH	00078151	31/05/2025	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00078151	31/05/2025	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00078777	24/06/2025	CUMAE5	00	LABOUR APPREN			
PM168	XQ43UH	00078777	24/06/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 24.06.2025			
						FIRE EXT EXP: JULY 2025			
						ADJUSTED DRIVER FACING CAMERA REPLACED LHF DRIVE REPLACED RHR SHOCK IS ONLY MISTING ORDERED GEARBOX PRESSURE SWTCH REPLACING NEXT STEER TYRES ARE GOOD REPLACE COMPRESSURE TO POWER STEERING PUMP GAS			
PM168	XQ43UH	00078777	24/06/2025	CUMAE5	16			CON	YAT
PM168	XQ43UH	00078777	24/06/2025	CUMAE5	00	LABOUR APPRENJC			
PM168	XQ43UH	00078742	24/06/2025	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00078777	24/06/2025	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00078742	24/06/2025	DEFECT		DEFECT CLEARED.			

PM168	XQ43UH	00078777	24/06/2025	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00078777	24/06/2025	DEFECT		Reported Defect :-Defect Code : 00013892			
PM168	XQ43UH	00078742	24/06/2025	GEN		Defect Reference : 17451 Date : 24/03/2025 Description of DRIVE FACING CAMERA NEEDS TO BE MOUNTED HIG LABOUR APPRENJC			
					39				
PM168	XQ43UH	00078742	24/06/2025	GEN		REPAIR COMPLETED BY WORKSHOP 24.06.2025			
PM168	XQ43UH	00078742	24/06/2025	GEN	16			CON	YAT
PM168	XQ43UH	00078742	24/06/2025	GEN	40			10W50	YAT
PM168	XQ43UH	00078742	24/06/2025	GEN	06			ED2175254-S	YAT
PM168	XQ43UH	00079317	16/07/2025	CUMAE5	00	LABOUR APPRENJC			
PM168	XQ43UH	00079317	16/07/2025	CUMAE5		A SERVICE COMPLETED. BY WORKSHOP 16/7/2025 FIRE EXT EXP: FEB 2026 REPLACED GEARBOX PRESSURE SWITCH REPLACEI REPLACED SUZI COILS REPLACED LIGHT PLUG ON LIGHT LEAD REPAIRED AIR LEAK COMING FROM HORTEN FAN SO			
PM168	XQ43UH	00079317	16/07/2025	CUMAE5	16				
PM168	XQ43UH	00079317	16/07/2025	CUMAE5	16			FD20-31112-5PS	YAT
PM168	XQ43UH	00079317	16/07/2025	CUMAE5	16			61-SC3MTLTSE	YAT
PM168	XQ43UH	00079317	16/07/2025	CUMAE5	19			FIREEXT1KG	YAT
PM168	XQ43UH	00079317	16/07/2025	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00079317	16/07/2025	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00079317	16/07/2025	DEFECT		Reported Defect :-Defect Code : 00014330			
PM168	XQ43UH	00079693	1/08/2025	CUMAE5		Defect Reference : PM168 Date : 31/05/2025 Description o GEAR BOX PRESSURE SWITCH LEAKING LABOUR ME			
					00				
PM168	XQ43UH	00079693	1/08/2025	CUMAE5		A SERVICE COMPLETED.			
PM168	XQ43UH	00079693	1/08/2025	CUMAE5	16	FIRE EXT EXP: CON YAT			
PM168	XQ43UH	00079693	1/08/2025	CUMBE5	01	LABOUR APPREN			
PM168	XQ43UH	00079693	1/08/2025	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 01/08/2025 FIRE EXT EXP: NOVEMBER 2025 TIGHTENED DIFF HOUSING BOLTS TIGHTENED GRILL DRIVE SHOCK REPLACED RHS BULLBAR LIGHT CON YAT			
PM168	XQ43UH	00079693	1/08/2025	CUMBE5	16				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00079693	1/08/2025	CUMBE5	00	LABOUR	MECH 5		
PM168	XQ43UH	00079693	1/08/2025	CUMBE5	00	LABOUR	APPREND		
PM168	XQ43UH	00079693	1/08/2025	CUMBE5	16			3413005	YAT
PM168	XQ43UH	00079693	1/08/2025	CUMBE5	16			RSK154	YAT
PM168	XQ43UH	00079693	1/08/2025	CUMBE5	06			Z1006	YAT
PM168	XQ43UH	00079693	1/08/2025	CUMBE5	14			2110-12V	YAT
PM168	XQ43UH	00079693	1/08/2025	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00079693	1/08/2025	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00079693	1/08/2025	DEFECT		Reported Defect :-Defect Code : 00014327			
PM168	XQ43UH	00079763	5/08/2025	CUMAE5	00	Defect Reference : PM168 Date : 31/05/2025 Description o SHOCKY LEKAKING 2ND AXLE R/H LABOUR MECH 1			
PM168	XQ43UH	00079763	5/08/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 05/08/2025 FIRE EXT EXP: FEBRUARY 2026			

						TIDY UP AND ZIP TIE SUZI AND EBS LEADS ADJUST C			
PM168	XQ43UH	00079763	5/08/2025	CUMAE5	16	CON		YAT	
PM168	XQ43UH	00079763	5/08/2025	CUMAE5	00	LABOUR APPRENJC			
PM168	XQ43UH	00079763	5/08/2025	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00079763	5/08/2025	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00080429	29/08/2025	GEN	39	LABOUR APPREN			
PM168	XQ43UH	00080429	29/08/2025	GEN		REPAIR COMPLETED BY WORKSHOP 29/8/2025			
						FIRE EXT EXP:			
						FOUND FAILED BATTERY, REPLACED ALL			
PM168	XQ43UH	00080429	29/08/2025	GEN	16		CON	YAT	
PM168	XQ43UH	00080429	29/08/2025	GEN	16		MF70ZZDT	YAT	
PM168	XQ43UH	00081148	1/09/2025	TYRES	15		11006520		
PM168	XQ43UH	00081148	1/09/2025	TYRES	15		33000084		
PM168	XQ43UH	00081148	1/09/2025	TYRES	15		33000370		
PM168	XQ43UH	00081148	1/09/2025	TYRES	15		33000518		
PM168	XQ43UH	00081148	1/09/2025	TYRES	15		33000118		
PM168	XQ43UH	00081148	1/09/2025	TYRES	15		11006520		
PM168	XQ43UH	00081148	1/09/2025	TYRES	15		33000084		
PM168	XQ43UH	00081148	1/09/2025	TYRES	15		33000370		
PM168	XQ43UH	00081148	1/09/2025	TYRES	15		33000518		
PM168	XQ43UH	00081148	1/09/2025	TYRES	15		33000118		
PM168	XQ43UH	00080733	11/09/2025	CUMAE5	00	LABOUR MECH			
PM168	XQ43UH	00080733	11/09/2025	CUMAE5		A SERVICE COMPLETED.			
						FIRE EXT EXP:			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00080733	11/09/2025	CUMAE5	16			CON	YAT
PM168	XQ43UH	00080733	11/09/2025	CUMBE5	01	LABOUR MECH 1			
PM168	XQ43UH	00080733	11/09/2025	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 11/09/2025			
						FIRE EXT EXP: FEBRUARY 2026			
						EYE WASH EXP - FEBRUARY 2028			
						REPLACE HEATER TAP AT RH SIDE OF ENGINE REPA			
						DRAIN AXLE FIT TAP TO AIR DRYER EXHAUST PART F			
						DEFECT 14328 - REPLACE THRU SHAFT SEAL			
						DEFECT 14522 - REPLACE POWER STEERING GASKE			
						DEFECT 14523/14518 - REPLACE LH FUEL TANK STRA			
PM168	XQ43UH	00080733	11/09/2025	CUMBE5	16	CON		YAT	
PM168	XQ43UH	00080733	11/09/2025	CUMBE5	00	LABOUR APPRENJ			
PM168	XQ43UH	00080733	11/09/2025	CUMBE5	00	LABOUR APPREND			
PM168	XQ43UH	00080733	11/09/2025	CUMBE5	00	LABOUR APPRENJC			
PM168	XQ43UH	00080733	11/09/2025	CUMBE5	16			R945008	YAT
PM168	XQ43UH	00080733	11/09/2025	CUMBE5	06			RSK154	YAT
PM168	XQ43UH	00080733	11/09/2025	CUMBE5	06			Z1006	YAT
PM168	XQ43UH	00080733	11/09/2025	CUMBE5	16			3413005	YAT
PM168	XQ43UH	00080733	11/09/2025	CUMBE5	16			FS19764	YAT
PM168	XQ43UH	00080733	11/09/2025	CUMBE5	16			SP1244	YAT
PM168	XQ43UH	00080733	11/09/2025	CUMBE5	16			MSKMG1A4515F	YAT
PM168	XQ43UH	00080733	11/09/2025	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00080733	11/09/2025	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00080733	11/09/2025	DEFECT		Reported Defect :-Defect Code : 00014208			
						Defect Reference : 58656 Date : 04/05/2025 Description of			
						RUBBER STRAP ON FUEL TANK ON LEFT HAND SIDE.			
						DRIVE TYRE ON RIGHT HAND SIDE FIRST AXLE GOT S			
PM168	XQ43UH	00080733	11/09/2025	DEFECT		Reported Defect :-			

Defect Code : 00014523 Defect Reference : PM168 Date :
REPLACE TANK STRAP RUBBERS ON B SERVICE
Reported Defect :-

PM168 XQ43UH 00080733 11/09/2025 DEFECT

Defect Code : 00014328 Defect Reference : PM168 Date :

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00080733	11/09/2025	DEFECT		Reported Defect :-Defect Code : 00014522 Defect Reference : PM168 Date : 26/06/2025 Description of REPLACE COMPRESSURE TO POWER STEERING PUM			
PM168	XQ43UH	00081200	1/10/2025	GEN	39			LABEXT	
PM168	XQ43UH	00081200	1/10/2025	GEN	39			F35008SD	
PM168	XQ43UH	00081200	1/10/2025	GEN	39			FF5776	
PM168	XQ43UH	00081200	1/10/2025	GEN	39			AF1969M	
PM168	XQ43UH	00081200	1/10/2025	GEN	39			MATERIALS	
PM168	XQ43UH	00081200	1/10/2025	GEN	39			WRKSCONS	
PM168	XQ43UH	00081200	1/10/2025	GEN	39			CON	
PM168	XQ43UH	00081200	1/10/2025	GEN		REPAIR COMPLETED BY CUMMINS SOUTH PACIFIC 01/			
						INVOICE #1753421			
						COMPLAINT - PARTS NOT COVERED BY WARRANTY C/ CORRECTION - PARTS THAT WERE NOT COVERED BY TO HORTON FAN			
PM168	XQ43UH	00081200	1/10/2025	GEN	39			LABEXT	
PM168	XQ43UH	00081200	1/10/2025	GEN	39			F35008SD	
PM168	XQ43UH	00081200	1/10/2025	GEN	39			FF5776	
PM168	XQ43UH	00081200	1/10/2025	GEN	39			AF1969M	
PM168	XQ43UH	00081200	1/10/2025	GEN	39			MATERIALS	
PM168	XQ43UH	00081200	1/10/2025	GEN	39			WRKSCONS	
PM168	XQ43UH	00081200	1/10/2025	GEN	39			CON	
PM168	XQ43UH	00081246	3/10/2025	GEN	39	LABOUR MECH			
PM168	XQ43UH	00081246	3/10/2025	GEN		REPAIR COMPLETED BY WORKSHOP 03/10/2025			
						FIRE EXT EXP: N/A			
PM168	XQ43UH	00081246	3/10/2025	GEN	16	REPLACED FAN BELT REPLACED TENSIONER CON YAT			
PM168	XQ43UH	00081246	3/10/2025	GEN	11			89440	YAT
PM168	XQ43UH	00081246	3/10/2025	GEN	11			12pk2380	YAT
PM168	XQ43UH	00081426	13/10/2025	GEN	39	LABOUR APPREN			
PM168	XQ43UH	00081426	13/10/2025	GEN		REPAIR COMPLETED BY WORKSHOP 13/10/2025			
						FIRE EXT EXP:			
						REPLACED LHS WINDOW MODULATER FOUND BURNT RELAY TO AC BLOWER (REPLACED)			
PM168	XQ43UH	00081426	13/10/2025	GEN	16			CON	YAT
PM168	XQ43UH	00081426	13/10/2025	GEN	16			LV4502	YAT
PM168	XQ43UH	00081426	13/10/2025	GEN	16			Q21-1051-002	YAT
PM168	XQ43UH	00081756	23/10/2025	CUMAE5 00		LABOUR APPREN			
PM168	XQ43UH	00081756	23/10/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 23/10/2025			
						FIRE EXT EXP: FEBRUARY 2026			

							GEARBOX GASKET BEEN REPLACED COULDNT FAUL AC BEEN FIXED PRIOR TO SERVICE REPLACED ROOF FIXED LH INDICATOR IN TRAILER LIGHT PLUG ALTERI GOOD CON YAT			
PM168	XQ43UH	00081756	23/10/2025	CUMAE5	16					
PM168	XQ43UH	00081756	23/10/2025	CUMAE5	00	LABOUR APPRENJC				
PM168	XQ43UH	00081756	23/10/2025	DEFECT	01	LABOUR MECH				
PM168	XQ43UH	00081756	23/10/2025	DEFECT		DEFECT CLEARED.				
PM168	XQ43UH	00081756	23/10/2025	DEFECT		Reported Defect :-Defect Code : 00015304				
PM168	XQ43UH	00081756	23/10/2025	DEFECT		Defect Reference : PM168 Date : 09/10/2025 Description o TRUCK AIR CONDITIONER Reported Defect :-				
						Defect Code : 00014329 Defect Reference : PM168 Date : Description of Defect : GEAR BOX SEAL LEAKING Reported Defect :-				
PM168	XQ43UH	00081756	23/10/2025	DEFECT GEN	39	Defect Code : 00015222 Defect Reference : XQ43UH Date Description of Defect : REPLACE ALTERNATOR AT NEXT SERVICE LABOUR MECH 1				
PM168	XQ43UH	00081823	27/10/2025							
PM168	XQ43UH	00081823	27/10/2025	GEN		REPAIR COMPLETED BY WORKSHOP 27/10/2025				
						CARRY OUT PRESSURE CHECK OF INTERCOOLER AND BOC SEND TO BROWN N HURLEY FOR FURTHER DIAGNOSIS			
PM168	XQ43UH	00081823	27/10/2025	GEN	16			CON		YAT
PM168	XQ43UH	00081823	27/10/2025	GEN	00	LABOUR APPRENJC				
PM168	XQ43UH	00081823	27/10/2025	GEN	11			HE 8071		YAT
PM168	XQ43UH	00081990	1/11/2025	GEN	39	LABOUR APPRENJC				
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code		W/H Code
PM168	XQ43UH	00081990	1/11/2025	GEN		REPAIR COMPLETED BY WORKSHOP 01/11/2025				
						DID AN ADBLUE FLUSH TO SEE IF BLOCKED NO LEAK FLUSHES STEM CHECK OERATION OF ADBLUE SYSTEM - ALL OK NO I CON YAT				
PM168	XQ43UH	00081990	1/11/2025	GEN	16					
PM168	XQ43UH	00081990	1/11/2025	GEN	00	LABOUR MECH 1				
PM168	XQ43UH	00081990	1/11/2025	GEN	06			AS2474		YAT
PM168	XQ43UH	00082655	25/11/2025	CUMAE5	00	LABOUR MECH 1				
PM168	XQ43UH	00082655	25/11/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 25/11/2025				
						FIRE EXT EXP: FEBRUARY 2026				
						REPAIR ISSUE WITH LIGHT PLUG				
PM168	XQ43UH	00082655	25/11/2025	CUMAE5	16	ADJUST CLUTCH MANUALLY MREASED THRUST CON YAT				
PM168	XQ43UH	00082655	25/11/2025	CUMAE5	00	LABOUR APPRENJ				
PM168	XQ43UH	00082656	25/11/2025	ECO	01	LABOUR APPREND				
PM168	XQ43UH	00082656	25/11/2025	ECO		ECO WIND SERVICE COMPLETED BY WORKSHOP 25/				
PM168	XQ43UH	00082656	25/11/2025	ECO	16			CON		YAT
PM168	XQ43UH	00082656	25/11/2025	ECO	06			SA17117		YAT
PM168	XQ43UH	00082656	25/11/2025	ECO	40			10W50		YAT
PM168	XQ43UH	00083371	19/12/2025	CUMAE5	00	LABOUR MECH				
PM168	XQ43UH	00083371	19/12/2025	CUMAE5		A SERVICE COMPLETED.				
PM168	XQ43UH	00083371	19/12/2025	CUMAE5	16	FIRE EXT EXP: CON YAT				
PM168	XQ43UH	00083371	19/12/2025	CUMBE5	01	LABOUR MECH 1				
PM168	XQ43UH	00083371	19/12/2025	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 19/12/2025				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00083371	19/12/2025	CUMBE5	16	FIRE EXT EXP: FEBRUARY 2026 EYEWASH - FEBRUAF CON	YAT		
PM168	XQ43UH	00083371	19/12/2025	CUMBE5	00	LABOUR APPRENJC			
PM168	XQ43UH	00083371	19/12/2025	CUMBE5	00	LABOUR APPREND			
PM168	XQ43UH	00083371	19/12/2025	CUMBE5	40			3413005	YAT
PM168	XQ43UH	00083371	19/12/2025	CUMBE5	06			RSK154	YAT
PM168	XQ43UH	00083371	19/12/2025	CUMBE5	06			Z1006	YAT
PM168	XQ43UH	00083919	15/01/2026	CUMAE5	00	LABOUR APPRENJC			
PM168	XQ43UH	00083919	15/01/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 15/01/2026 FIRE EXT EXP: FEBRUARY 2026 CLEANED UP WIRING AROUND G-BOX REPLACED ALI REPLACED FRONT DRIVE TORQUE ROD BUSHES REF TIGHTENED GRILL BOLTS FIXED CENTRE PIN FOR BULLBAR (WELDED HANDLE CON	YAT		
PM168	XQ43UH	00083919	15/01/2026	CUMAE5	16				
PM168	XQ43UH	00083919	15/01/2026	CUMAE5	00	LABOUR APPREN			
PM168	XQ43UH	00083919	15/01/2026	CUMAE5	16			GENERAL PART	YAT
PM168	XQ43UH	00083919	15/01/2026	CUMAE5	16			839310	YAT
PM168	XQ43UH	00083919	15/01/2026	CUMAE5	16			43764	YAT
PM168	XQ43UH	00083920	15/01/2026	CUMCE5	01	LABOUR APPREN			
PM168	XQ43UH	00083920	15/01/2026	CUMCE5		C SERVICE COMPLETED BY WORKSHOP 15/01/2026 FIRE EXT EXP: FEBRUARY 2026 *WROTE EVERYTHING ON 'A' SERVICE SHEET			
PM168	XQ43UH	00083920	15/01/2026	CUMCE5	16	CON	YAT		
PM168	XQ43UH	00083920	15/01/2026	CUMCE5	00	LABOUR APPRENJC			
PM168	XQ43UH	00083920	15/01/2026	CUMCE5	06			F37-TP-1000	YAT
PM168	XQ43UH	00083920	15/01/2026	CUMCE5	06			HDA5979	YAT
PM168	XQ43UH	00083920	15/01/2026	CUMCE5	06			A3380W1687	YAT
PM168	XQ43UH	00083920	15/01/2026	CUMCE5	06			T224P	YAT
PM168	XQ43UH	00083920	15/01/2026	CUMCE5	16			17237	YAT
PM168	XQ43UH	00083920	15/01/2026	CUMCE5	06			LF637	YAT
PM168	XQ43UH	00083920	15/01/2026	CUMCE5	06			WF2127	YAT
PM168	XQ43UH	00083920	15/01/2026	CUMCE5	40			3430336	YAT
PM168	XQ43UH	00083920	15/01/2026	CUMCE5	40			3430284	YAT
PM168	XQ43UH	00083920	15/01/2026	CUMCE5	06	UF110	YAT		
PM168	XQ43UH	00083921	15/01/2026	EXOINS	01	LABOUR APPREN			
PM168	XQ43UH	00083921	15/01/2026	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECTIC #1 INSPECTION COMPLETED BY WORKSHOP 15/01/2026 FIRE EXT EXP - FEBRUARY 2026 EYEWASH EXP - FEB			
PM168	XQ43UH	00083921	15/01/2026	EXOINS	00	DEFECTS IDENITIFED -NONE LABOUR APPRENJC			
PM168	XQ43UH	00084024	16/01/2026	TYRES	15			11006520	
PM168	XQ43UH	00084024	16/01/2026	TYRES	15			33000084	
PM168	XQ43UH	00084024	16/01/2026	TYRES	15			33000370	
PM168	XQ43UH	00084024	16/01/2026	TYRES	15			33000518	
PM168	XQ43UH	00084024	16/01/2026	TYRES	15			33000118	
PM168	XQ43UH	00084024	16/01/2026	TYRES	15			11006520	
PM168	XQ43UH	00084024	16/01/2026	TYRES	15			33000084	
PM168	XQ43UH	00084024	16/01/2026	TYRES	15			33000370	
PM168	XQ43UH	00084024	16/01/2026	TYRES	15			33000518	
PM168	XQ43UH	00084024	16/01/2026	TYRES	15			33000118	
PM168	XQ43UH	00084376	3/02/2026	CUMAE5	00	LABOUR MECH 1			
PM168	XQ43UH	00084376	3/02/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 03/02/2026			

						FIRE EXT EXP: N/A			
						REPLACE FIRE EXT AND REMOUNT BRACKET REPLA			
						REPLACE WIPER BLADE			
						CHECK FOR AFTER BURN FAULT-FLUSH AND RUN DI			
PM168	XQ43UH	00084376	3/02/2026	CUMAE5	16				
PM168	XQ43UH	00084376	3/02/2026	CUMAE5	00	LABOUR MECH 5			
PM168	XQ43UH	00084376	3/02/2026	CUMAE5	19			FIREEXT1KG	YAT
PM168	XQ43UH	00085467	2/03/2026	GEN	39			LABEXT	BROHU
PM168	XQ43UH	00085467	2/03/2026	GEN	39			F35008SD	BROHU
PM168	XQ43UH	00085467	2/03/2026	GEN	39			MISCON	BROHU
PM168	XQ43UH	00085467	2/03/2026	GEN	39			ENVLEV	BROHU

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00085467	2/03/2026	GEN		REPAIR COMPLETED BY BROWN N HURLEY YATALA			
						INVOICE #3818796			
						K039 HORTON FAN CLUTCH LEAKING AIT			
						Brought the truck into the workshop and carried out an inspection. I			
						leaking air internally. Removed the fan belt and fan assembly, then			
						inspection.			
						Applied air pressure and found the grub screw at the front of the un			
						occur if the unit overheats, causing loss of air pressure and prevent			
						appearing to have been pinched. This would allow air			
						to leak internally and could have caused the fan to slip during enga			
						and the grub screw blowing. The friction material and plate also sh			
						Found some damaged threads on the end of the shaft; the supervis			
						findings to the foreman and was advised to proceed with the repair.			
						and rebuilt the Horton fan using a new rebuild kit. Bench tested the			
						carried out operational checks ? all OK.			
						When lowering the			
						cab, it would not go down. Topped up the cab tilt pump oil and succ			
PM168	XQ43UH	00085467	2/03/2026	GEN	39			LABEXT	
PM168	XQ43UH	00085467	2/03/2026	GEN	39			F35008SD	
PM168	XQ43UH	00085467	2/03/2026	GEN	39			MISCON	
PM168	XQ43UH	00085467	2/03/2026	GEN	39			ENVLEV	
PM168	XQ43UH	00085255	6/03/2026	CUMAE5	00	LABOUR MECH 1			
PM168	XQ43UH	00085255	6/03/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 06/03/2026			
						FIRE EXT EXP: AUGUST 2026			
						DEFECT 16526 - ALTERNATOR REPLACED			
						REMOVE UNUSED U/S ELECTRIC SUZI COIL AND TIDY			
PM168	XQ43UH	00085255	6/03/2026	CUMAE5	16	CON		YAT	
PM168	XQ43UH	00085255	6/03/2026	CUMAE5	00	LABOUR APPRENJC			
PM168	XQ43UH	00085255	6/03/2026	CUMAE5	40			3413005	YAT
PM168	XQ43UH	00085255	6/03/2026	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00085255	6/03/2026	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00085255	6/03/2026	DEFECT		Reported Defect :-Defect Code : 00016526			
PM168	XQ43UH	00085256	6/03/2026	ECO		Defect Reference : PM168 Date : 28/02/2026 Description o			
						DRIVER STEVE W ADVISED HIS ELECTRICS BEGAN P			
						AND HIS VOLTAGE DROPPED AND HIS PM WAS OVER			
						LABOUR APPRENJC			
					01				
PM168	XQ43UH	00085256	6/03/2026	ECO		ECO WIND SERVICE COMPLETED BY WORKSHOP 06/			
PM168	XQ43UH	00085256	6/03/2026	ECO	16			CON	YAT
PM168	XQ43UH	00085256	6/03/2026	ECO	06			SA17117	YAT

PM168	XQ43UH	00085256	6/03/2026	ECO	40			10W50	YAT
PM168	XQ43UH	00085254	6/03/2026	GEN	39	LABOUR APPRENJC			
PM168	XQ43UH	00085254	6/03/2026	GEN		REPAIR COMPLETED BY WORKSHOP 06/03/2026			
						JOB COMPLAINT - NEEDS NEW ALTERNATOR			
PM168	XQ43UH	00085254	6/03/2026	GEN	16	REPLACED ALTERNATOR AS NOT CHARGING AT COF CON YAT C			
PM168	XQ43UH	00085254	6/03/2026	GEN	16			LBP2189GH	YAT
PM168	XQ43UH	00085791	28/03/2026	CUMAE5	00	LABOUR MECH			
PM168	XQ43UH	00085791	28/03/2026	CUMAE5		A SERVICE COMPLETED.			
PM168	XQ43UH	00085791	28/03/2026	CUMAE5	16	FIRE EXT EXP: CON YAT C			
PM168	XQ43UH	00085791	28/03/2026	CUMBE5	01	LABOUR MECH 1			
PM168	XQ43UH	00085791	28/03/2026	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 28/03/2026			
						FIRE EXT EXP: AUGUST 2026 EYEWASH EXP - FEBRU			
PM168	XQ43UH	00085791	28/03/2026	CUMBE5	16			CON	YAT
PM168	XQ43UH	00085791	28/03/2026	CUMBE5	00	LABOUR APPREND			
PM168	XQ43UH	00085791	28/03/2026	CUMBE5	00	LABOUR MECH 5			
PM168	XQ43UH	00085791	28/03/2026	CUMBE5	40			3413005	YAT
PM168	XQ43UH	00085791	28/03/2026	CUMBE5	06			RSK154	YAT
PM168	XQ43UH	00085791	28/03/2026	CUMBE5	06			Z1006	YAT
PM168	XQ43UH	00085971	2/04/2026	TYRES	15			33000188	
PM168	XQ43UH	00085971	2/04/2026	TYRES	15			33000237	
PM168	XQ43UH	00085971	2/04/2026	TYRES	15			33000237	

PM168	XQ43UH	00085971	2/04/2026	TYRES	15			33000188	
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00085971	2/04/2026	TYRES	15			33000237	
PM168	XQ43UH	00085971	2/04/2026	TYRES	15			33000237	

PM168	XQ43UH	00086713	13/04/2026	GEN	39			61-SC3MTLTSE	
PM168	XQ43UH	00086713	13/04/2026	GEN	39			ASA93-35	
PM168	XQ43UH	00086713	13/04/2026	GEN	39			GENERAL PART	
PM168	XQ43UH	00086713	13/04/2026	GEN	39			ASA93-20	
PM168	XQ43UH	00086713	13/04/2026	GEN	39			GENERAL PART	
PM168	XQ43UH	00086713	13/04/2026	GEN	39			WORKSHOP	
PM168	XQ43UH	00086713	13/04/2026	GEN	39			LABEXT	
PM168	XQ43UH	00086713	13/04/2026	GEN	39			ROUNDING	
PM168	XQ43UH	00086713	13/04/2026	GEN		REPAIR COMPLETED BY GILBERT N ROACH 13/04/202			
						INVOICE #KWCSN71785			
						REPLACE SUZI COILS INSPECTED AND FOUND KINK IN SUZI COILS REMOVE REPLACED SUZI COILS AS REQUIRED 61-SC3MTLTSE GILROA01			
PM168	XQ43UH	00086713	13/04/2026	GEN	39				
PM168	XQ43UH	00086713	13/04/2026	GEN	39			ASA93-35	GILROA
PM168	XQ43UH	00086713	13/04/2026	GEN	39			GENERAL PART	GILROA
PM168	XQ43UH	00086713	13/04/2026	GEN	39			ASA93-20	GILROA
PM168	XQ43UH	00086713	13/04/2026	GEN	39			GENERAL PART	GILROA
PM168	XQ43UH	00086713	13/04/2026	GEN	39			WORKSHOP	GILROA
PM168	XQ43UH	00086713	13/04/2026	GEN	39			LABEXT	GILROA
PM168	XQ43UH	00086713	13/04/2026	GEN	39			ROUNDING	GILROA
PM168	XQ43UH	00086230	18/04/2026	CUMAE5	00	LABOUR APPRENJ			
PM168	XQ43UH	00086230	18/04/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 18/04/2026			
						ADJUSTED CLUTCH			

PM168	XQ43UH	00086230	18/04/2026	CUMAE5	16	FIRE EXT EXP: JULY 26 CON		YAT	
PM168	XQ43UH	00086230	18/04/2026	CUMAE5	00	LABOUR APPRENJC			
PM168	XQ43UH	00086230	18/04/2026	CUMAE5	00	LABOUR APPREND			
PM168	XQ43UH	00086230	18/04/2026	CUMAE5	00	LABOUR MECH 6			
PM168	XQ43UH	00086230	18/04/2026	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00086230	18/04/2026	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00086230	18/04/2026	DEFECT				Reported Defect :-Defect C	
PM168	XQ43UH	00086362	23/04/2026	GEN		Defect Reference : PM168 Date : 02/04/2026 Descr CLUTCH VERY HIGH ON PEDDLE, NEEDS LABEXT			
PM168	XQ43UH	00086362	23/04/2026	GEN	39			MISCON	BROHUI
PM168	XQ43UH	00086362	23/04/2026	GEN	39			ENVLEV	BROHUI
PM168	XQ43UH	00086362	23/04/2026	GEN		REPAIR COMPLETED BY BROWN N HURLEY 23/04/202 INVOICE #3856302 RESURFACE FLYWHEEL AS REQUESTED			
PM168	XQ43UH	00086362	23/04/2026	GEN	39	LABEXT		BROHUR01	
PM168	XQ43UH	00086362	23/04/2026	GEN	39			MISCON	BROHUI
PM168	XQ43UH	00086362	23/04/2026	GEN	39			ENVLEV	BROHUI
PM168	XQ43UH	00086449	28/04/2026	GEN	39	LABOUR APPRENJ			
PM168	XQ43UH	00086449	28/04/2026	GEN		REPAIR COMPLETED BY WORKSHOP 28/04/2026 JOB COMPLAINT -SLEEPER AIR SHUT DOWN ALTERNATOR NOT CHARGING PROPERLEY, REPLACE RUNNS GOOD NOW, SWAPPED ALTERNATOR, BUT PUT OLD ONE BACK ON OK			
PM168	XQ43UH	00086449	28/04/2026	GEN	16			CON	YAT
PM168	XQ43UH	00086449	28/04/2026	GEN	00	LABOUR MECH 5			
PM168	XQ43UH	00086449	28/04/2026	GEN	06			LV1690	YAT
PM168	XQ43UH	00086952	18/05/2026	GEN	16			LAB	
PM168	XQ43UH	00086952	18/05/2026	GEN	16			KSMA2124707Q	
PM168	XQ43UH	00086952	18/05/2026	GEN	16			47693S	
PM168	XQ43UH	00086952	18/05/2026	GEN	16			03-01568	
PM168	XQ43UH	00086952	18/05/2026	GEN	16			CON	
PM168	XQ43UH	00086952	18/05/2026	GEN	16			ksma2124707qp	
PM168	XQ43UH	00086952	18/05/2026	GEN	16			ENVLEV	
PM168	XQ43UH	00086952	18/05/2026	GEN	16			LAB	
PM168	XQ43UH	00086952	18/05/2026	GEN	16			KSMA2124707Q	
PM168	XQ43UH	00086952	18/05/2026	GEN	16			47693S	
PM168	XQ43UH	00086952	18/05/2026	GEN	16			03-01568	
PM168	XQ43UH	00086952	18/05/2026	GEN	16			CON	
PM168	XQ43UH	00086952	18/05/2026	GEN	16			ksma2124707qp	
PM168	XQ43UH	00086952	18/05/2026	GEN	16			ENVLEV	
PM168	XQ43UH	00087094	19/05/2026	GEN	39			LABEXT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Category	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00087094	19/05/2026	GEN	39			GENERAL PART	
PM168	XQ43UH	00087094	19/05/2026	GEN	39			GENERAL PART	
PM168	XQ43UH	00087094	19/05/2026	GEN	39			GENERAL PART	
PM168	XQ43UH	00087094	19/05/2026	GEN	39			DEGREASER	
PM168	XQ43UH	00087094	19/05/2026	GEN	39			GREASE	
PM168	XQ43UH	00087094	19/05/2026	GEN	39			CON	
PM168	XQ43UH	00087094	19/05/2026	GEN	39			ENVLEV	
PM168	XQ43UH	00087094	19/05/2026	GEN		REPAIR COMPLETED BY NQFM 19/05/2026 INVOICE #43370			

Jack up rear axle - Removed chrome hub caps, removed tyres, $49
bearings and refit bearings to hub. Replaced hub seal, removed bra
tension to spec - all ok

PM168	XQ43UH	00087094	19/05/2026	GEN	39			LABEXT	
PM168	XQ43UH	00087094	19/05/2026	GEN	39			GENERAL PART	
PM168	XQ43UH	00087094	19/05/2026	GEN	39			GENERAL PART	
PM168	XQ43UH	00087094	19/05/2026	GEN	39			GENERAL PART	
PM168	XQ43UH	00087094	19/05/2026	GEN	39			DEGREASER	
PM168	XQ43UH	00087094	19/05/2026	GEN	39			GREASE	
PM168	XQ43UH	00087094	19/05/2026	GEN	39			CON	
PM168	XQ43UH	00087094	19/05/2026	GEN	39			ENVLEV	
PM168	XQ43UH	00087148	26/05/2026	CUMAE5	00	LABOUR MECH 7			
PM168	XQ43UH	00087148	26/05/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 26/05/2026			
						FIRE EXT EXP: AUGUST 2026			
						ADJUSTED TURNTABLE - REPLACE MULTIPLE DASH C SECOND HAND STEERING WHEEL CONTROLS FIT ST REPLACE MALE LIGHT PLUG REPLACE POGO STICK AND RESEAL BRASS ENDS FI SLEEPER REPLACE 2 X VISOR CLIPS INSPECT FOR NOISE/KNOCK IN FRONT, ALL OK, MON STEERING COUUM CNF REMOVE EYEWASH BRACKET FROM CAB (IS IN DG KI CLEAN OUT ADBLUE TANK BREATHER PLUG IN WARI CON YAT			
PM168	XQ43UH	00087148	26/05/2026	CUMAE5	16				
PM168	XQ43UH	00087148	26/05/2026	CUMAE5	00	LABOUR APPREND			
PM168	XQ43UH	00087148	26/05/2026	CUMAE5	00	LABOUR APPRENL			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00087148	26/05/2026	CUMAE5	16			FQ0300F	YAT
PM168	XQ43UH	00087147	27/05/2026	GEN	39	LABOUR MECH 7			
PM168	XQ43UH	00087147	27/05/2026	GEN		REPAIR COMPLETED BY WORKSHOP 27/05/2026			
						JOB COMPLAINT -REPAIRS			
						INSPECT A/C BLOWER ISSUE, REPLACE RELAY HOLDER ANI			
PM168	XQ43UH	00087147	27/05/2026	GEN	16			CON	YAT
PM168	XQ43UH	00087147	27/05/2026	GEN	00	LABOUR APPRENJ			
PM168	XQ43UH	00087147	27/05/2026	GEN	16			LV4502	YAT
PM168	XQ43UH	00087147	27/05/2026	GEN	16			47697S	YAT
PM168	XQ43UH	00087701	18/06/2026	CUMAE5	00	LABOUR MECH 7			
PM168	XQ43UH	00087701	18/06/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 18/06/2026			
						FIRE EXT EXP: JULY 2026			
PM168	XQ43UH	00087701	18/06/2026	CUMAE5	16	REPLACED LIGHT PLUG FITTED NHVR STICKER CON YAT			
PM168	XQ43UH	00087701	18/06/2026	CUMAE5	00	LABOUR APPRENL			
PM168	XQ43UH	00087701	18/06/2026	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00087701	18/06/2026	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00087701	18/06/2026	DEFECT		Reported Defect :-Defect Code : 00017561			
PM168	XQ43UH	00087701	18/06/2026	DEFECT		Defect Reference : pm168 Date : 08/06/2026 Description o PASSENGER SIDE MIRROR BROKEN Reported Defect :-			

				ECO	01	Defect Code : 00017414 Defect Reference : PM168 Date : REQUIRES NEW NHVR STICKER LABOUR APPREND			
PM168	XQ43UH	00087778	22/06/2026						
PM168	XQ43UH	00087778	22/06/2026	ECO		ECO WIND SERVICE COMPLETED BY WORKSHOP 22/			
PM168	XQ43UH	00087778	22/06/2026	ECO	16	REPLACED FAN MOTOR AS NEEDED CON YAT			
PM168	XQ43UH	00087778	22/06/2026	ECO	06			SA17117	YAT
PM168	XQ43UH	00087778	22/06/2026	ECO	40			10W50	YAT
PM168	XQ43UH	00087778	22/06/2026	ECO	16			EMX520	YAT
PM168	XQ43UH	00087904	29/06/2026	CUMAE5	00	LABOUR MECH			
PM168	XQ43UH	00087904	29/06/2026	CUMAE5		A SERVICE COMPLETED.			
						FIRE EXT EXP:			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00087904	29/06/2026	CUMAE5	16			CON	YAT
PM168	XQ43UH	00087904	29/06/2026	CUMBE5	01	LABOUR MECH 1			
PM168	XQ43UH	00087904	29/06/2026	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 29/06/2026			
						FIRE EXT EXP: AUGUST 2026 EYEWASH EXP - FEBRU/			
PM168	XQ43UH	00087904	29/06/2026	CUMBE5	16	RELINE ALL 4 X DRIVE BRAKES CON YAT			
PM168	XQ43UH	00087904	29/06/2026	CUMBE5	00	LABOUR APPREND			
PM168	XQ43UH	00087904	29/06/2026	CUMBE5	00	LABOUR MECH 5			
PM168	XQ43UH	00087904	29/06/2026	CUMBE5	40			3413005	YAT
PM168	XQ43UH	00087904	29/06/2026	CUMBE5	06			MK13555	YAT
PM168	XQ43UH	00087904	29/06/2026	CUMBE5	06			AS2474	YAT
PM168	XQ43UH	00087904	29/06/2026	CUMBE5	16			KSMA2124715Q	YAT
PM168	XQ43UH	00087904	29/06/2026	CUMBE5	06			FS19764	YAT
PM168	XQ43UH	00087904	29/06/2026	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00087904	29/06/2026	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00087904	29/06/2026	DEFECT		Reported Defect :-Defect Code : 00014515			
PM168	XQ43UH	00088215	7/07/2026	GEN	39	Defect Reference : 58656 Date : 04/05/2025 Description of RUBBER STRAP ON FUEL TANK ON LEFT HAND SIDE. LABEXT BROHUR01			
PM168	XQ43UH	00088215	7/07/2026	GEN	39			MISCON	BROHUI
PM168	XQ43UH	00088215	7/07/2026	GEN	39			ENVLEV	BROHUI
PM168	XQ43UH	00088215	7/07/2026	GEN		REPAIR COMPLETED BY BROWN N HURLEY 07/07/202			
						INVOICE #3928178			
PM168	XQ43UH	00088215	7/07/2026	GEN	39	RESURFACED FLYWHEEL AS REQUESTED LABEXT BROHUR01			
PM168	XQ43UH	00088215	7/07/2026	GEN	39			MISCON	BROHUI
PM168	XQ43UH	00088215	7/07/2026	GEN	39			ENVLEV	BROHUI
PM168	XQ43UH	00088570	23/07/2026	GEN	39	LABOUR MECH 1			
PM168	XQ43UH	00088570	23/07/2026	GEN		REPAIR COMPLETED BY WORKSHOP 23/07/2026			
						JOB COMPLAINT -VEHICLE NOT STARTING DUE TO FAULTY STARTER I			
						GOT TO TOP YARD AND BUILD UP AIR AND TOW STAI WORKSHOP R + R STARTER MOTOR LOAD TEST AND REPLACE BATTERIES CHECK CHAR CON YAT			
PM168	XQ43UH	00088570	23/07/2026	GEN	16				
PM168	XQ43UH	00088570	23/07/2026	GEN	00	LABOUR APPRENJC			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00088570	23/07/2026	GEN	00	LABOUR	RAM		
PM168	XQ43UH	00088570	23/07/2026	GEN	16			MF70ZZDT	YAT
PM168	XQ43UH	00088570	23/07/2026	GEN	16			D61-1004-004	YAT

PM168	XQ43UH	00088834	31/07/2026	CUMAE5	00	LABOUR MECH 1				
PM168	XQ43UH	00088834	31/07/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 31/07/2026				
						FIRE EXT EXP: AUGUST 2026				
						REPLACED CLEARANCE LIGHT IN LEFT SIDE FUEL TANK LIG REPLACED GASKET ON POWER STEERING PUMP, PRESSUF REQUIRED REPLACED CRACKED PLASTIC MUDGUARD BRA(				
PM168	XQ43UH	00088834	31/07/2026	CUMAE5	16			CON		YAT
PM168	XQ43UH	00088834	31/07/2026	CUMAE5	00	LABOUR BILLY				
PM168	XQ43UH	00088834	31/07/2026	CUMAE5	00	LABOUR APPRENJC				
PM168	XQ43UH	00088834	31/07/2026	CUMAE5	00	LABOUR APPREND				
PM168	XQ43UH	00088834	31/07/2026	CUMAE5	00	LABOUR RAM				
PM168	XQ43UH	00088834	31/07/2026	CUMAE5	06			FF5776		YAT
PM168	XQ43UH	00088834	31/07/2026	CUMAE5	16			26260AK		YAT
PM168	XQ43UH	00088834	31/07/2026	CUMAE5	16			SSBK-1		YAT
PM168	XQ43UH	00089008	7/08/2026	CUMAE5	00	LABOUR MECH 1				
PM168	XQ43UH	00089008	7/08/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 07/08/2026				
						FIRE EXT EXP: MARCH 2027				
PM168	XQ43UH	00089008	7/08/2026	CUMAE5	16	REPLACE FIRE EXT CON	YAT			
PM168	XQ43UH	00089008	7/08/2026	CUMAE5	00	LABOUR APPREND				
PM168	XQ43UH	00089008	7/08/2026	CUMAE5	19			FIREEXT1KG	YAT	
PM168	XQ43UH	00090272	4/09/2026	TYRES	15			1122516TY517T		YOKTYR
PM168	XQ43UH	00090272	4/09/2026	TYRES	39			YFSFTBX		YOKTYF
PM168	XQ43UH	00090272	4/09/2026	TYRES		SERVICE COMPLETED BY YOKOHAMA 04/09/2026 - PC				
PM168	XQ43UH	00090272	4/09/2026	TYRES	15	Pos:2-3-4-5-6-7-8(pull point 4) 4 kept for run out RSD 0382 1122516TY517T		YOKTYR01		IN-131952-20211R:
PM168	XQ43UH	00090272	4/09/2026	TYRES	39			YFSFTBX		YOKTYF
PM168	XQ43UH	00089816	11/09/2026	CUMAE5	00	LABOUR MECH				
PM168	XQ43UH	00089816	11/09/2026	CUMAE5		A SERVICE COMPLETED.				
PM168	XQ43UH	00089816	11/09/2026	CUMAE5	16	FIRE EXT EXP: CON	YAT			C
PM168	XQ43UH	00089816	11/09/2026	CUMBE5	01	LABOUR BILLY				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00089816	11/09/2026	CUMBE5		B SERVICE COMPLETED BY WROKSHOP 11/09/2026			
						FIRE EXT EXP: MARCH 2027			
PM168	XQ43UH	00089816	11/09/2026	CUMBE5	16	REPLACED HOB SWITCH (ABS/ESC LIGHT) CON	YAT		
PM168	XQ43UH	00089816	11/09/2026	CUMBE5	00	LABOUR MECH 7			
PM168	XQ43UH	00089816	11/09/2026	CUMBE5	16			MK13555	YAT
PM168	XQ43UH	00089816	11/09/2026	CUMBE5	16			AS2474	YAT
PM168	XQ43UH	00089816	11/09/2026	CUMBE5	16			FS19764	YAT
PM168	XQ43UH	00089816	11/09/2026	CUMBE5	16			41-7064-10	YAT
PM168	XQ43UH	00089816	11/09/2026	CUMBE5	16			3413005	YAT
PM168	XQ43UH	00089816	11/09/2026	CUMBE5	16			COOLANT	YAT
PM168	XQ43UH	00089816	11/09/2026	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00089816	11/09/2026	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00089816	11/09/2026	DEFECT		Reported Defect :-Defect Code : 00018552			
PM168	XQ43UH	00089838	11/09/2026	GEN	39	Defect Reference : PM168 Date : 08/09/2026 Description o LABOUR APPREND			
PM168	XQ43UH	00089838	11/09/2026	GEN		REPAIR COMPLETED BY WORKSHOP ON 11/09/2026			
						REPLACED STEER DRUMS REPLACED STEER BRAKE STEER HUB SEAL ADJUSTED BRAKES FITTED NEW HUBCAP TO LH STEER AND RH REAR DF CON	YAT		
PM168	XQ43UH	00089838	11/09/2026	GEN	16				

PM168	XQ43UH	00089838	11/09/2026	GEN	16			DB003TRP	YAT
PM168	XQ43UH	00089838	11/09/2026	GEN	16			0509146320BH9	YAT
PM168	XQ43UH	00089838	11/09/2026	GEN	16			43764	YAT
PM168	XQ43UH	00089838	11/09/2026	GEN	16			MK 9711-9208C	YAT
PM168	XQ43UH	00089838	11/09/2026	GEN	16			7001151	YAT
PM168	XQ43UH	00089831	14/09/2026	GEN	39	LABOUR MECH 7			
PM168	XQ43UH	00089831	14/09/2026	GEN		REPAIR COMPLETED BY WORKSHOP 14/09/2026			
						INSPECT SLEEPER BLOWER FAN, FOUND BUSHES U/S, REMOVE			
						CHECK AND ADJUST CLUTCH FOR WEAR			
PM168	XQ43UH	00089831	14/09/2026	GEN	16			CON	YAT
PM168	XQ43UH	00089831	14/09/2026	GEN	00	LABOUR MECH 1			
PM168	XQ43UH	00089831	14/09/2026	GEN	16			EM0922	YAT
PM168	XQ43UH	00090892	23/10/2026	DEFECT	01	LABOUR MECH			
PM168	XQ43UH	00090892	23/10/2026	DEFECT		DEFECT CLEARED.			
PM168	XQ43UH	00090892	23/10/2026	GEN	39	LABOUR MECH 1			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM168	XQ43UH	00090892	23/10/2026	GEN		REPAIR COMPLETED.BY WROKSHOP ON 23/10/2026			
						REPLACE TORQUE ROD BUSHES AT REAR DRIVE BOT			
						GET DIAGNOSTIC CHECKED			
						HAVE FAULT FOR L/H REAR WHEEL SENSOR - REPLAC			
						PASS JOB ONTO RAM TO DIAGNOSE WIRING FAULT			
PM168	XQ43UH	00090892	23/10/2026	GEN	16			CON	YAT
PM168	XQ43UH	00090892	23/10/2026	GEN	00	LABOUR APPRENJC			
PM168	XQ43UH	00090892	23/10/2026	GEN	16			VO23637090	YAT
PM168	XQ43UH	00090892	23/10/2026	GEN	16			839310	YAT
PM168	XQ43UH	00090921	26/10/2026	GEN	16			K14128K50	
PM168	XQ43UH	00090966	28/10/2026	GEN	16			LAB	
PM168	XQ43UH	00090966	28/10/2026	GEN	16			CON	
PM168	XQ43UH	00090966	28/10/2026	GEN	16			ENVLEV	
PM168	XQ43UH	00091027	30/10/2026	GEN	39	LABOUR MECH 1			
PM168	XQ43UH	00091027	30/10/2026	GEN		REPAIR COMPLETED BY WORKSHOP 30/10/2026			
						JOB COMPLAINT			
						-WALK PLATES REMOVED			
						-CLUTCH NEEDS ADJUSTING			
						REFIT WALKPLATES ADJUST CLUTCH GREASE TURN			
						CON YAT			
PM168	XQ43UH	00091027	30/10/2026	GEN	16				
PM168	XQ43UH	00091027	30/10/2026	GEN	00	LABOUR APPRENJC			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code

Report Options:

Sort By - AssetCode
Starting Asset Code - PM168
To - PM168
Starting Registration -
To -
Starting Operations No -
To -
From: Work Order Location -
To -
From: Work Order Date - 01/01/1901
To - 31/12/9999
From: Completion Date -
To -
From: RM Category Code -
To -
Starting Category Code -
To -
Starting Owned By -
To -
Starting Based By -

To	-
Starting Location	-
To	-
Assets For	- All Assets
Include Disposed Assets	- no
Warranty Items Only	- no
Include Non Active Assets	- no
Exclude Estimates	- no
Fleet Assets Only	- no
Service Code	-
Task Code	-
Mechanic Code	-
Product Code	-
Warehouse	-
WO Supplier Code	-
Include All	- yes
Labour	- yes
Parts	- yes
Supplies	- yes
Tyres	- yes
Comments	- yes

Supplier Code	Invoice	Details	Purchase Order
ROCTRU01	EX00020944	GENERAL PART CODE,PM168	EX0002094
ROCTRU01	EX00020944	GENERAL PART CODE,PM168	EX0002094
ROCTRU01	EX00020944	GENERAL PART CODE,PM168	EX0002094
ROCTRU01	EX00020944	GENERAL PART CODE,PM168	EX0002094
ROCTRU01	EX00020944	GENERAL PART CODE,PM168	EX0002094
ROCTRU01	EX00020944	GENERAL PART CODE,PM168	EX0002094
ROCTRU01	EX00020944	Labour,PM168	EX0002094
ROCTRU01	EX00020944	GENERAL PART CODE,PM168	EX0002094
ROCTRU01	131761	GENERAL PART CODE,PM168	EX0002094
ROCTRU01	131761	Labour,PM168	EX0002094
ROCTRU01	131761	GENERAL PART CODE,PM168	EX0002094
ROCTRU01	131761	GENERAL PART CODE,PM168	EX0002094
ROCTRU01	131761	GENERAL PART CODE,PM168	EX0002094
ROCTRU01	131761	GENERAL PART CODE,PM168	EX0002094
ROCTRU01	131761	GENERAL PART CODE,PM168	EX0002094
ROCTRU01	131761	GENERAL PART CODE,PM168	EX0002094
		Labour	2.00

: (ABOUT 10M OF WIRE AND SPLIT TUBE, NO PLUGS)

		Consumables	7.00
		KINGS DRIVING LIGHTS 9"	1.00
		Labour	0.00
		Labour - Internal	1.50
		Labour - Internal	2.00
		Consumables	
		Oil Filter (was LF9080)	
		OIL 15W-40, CK 4/E9	
		FF5776 Fuel Filter	
		Filter Element Gearbox Eaton	
		DIFF FILTER	
		Diff/Gear Oil 80W90 Castrol	
		COOLANT FILTER BLUE DONALDSON	
		Labour	
BRIAUS01	EX00021227	BALANCE TBR,PM168	EX0002122
BRIAUS01	86764881	BALANCE TBR,PM168	EX0002122
		Labour	

Supplier Code	Invoice	Details	Purchase Order
		Labour - Internal	
		Consumables	
ND01	EX00021352	Labour,XQ43UH	EX0002135
ND01	5664	Labour,XQ43UH	EX0002135
		Labour	
		Labour	
		Labour - Internal	
		Consumables	
		MAINTENANCE KIT	
		OIL 15W-40, CK 4/E9	
01	EX00021562	BALANCE TBR,PM168	EX0002156
01	EX00021579	B FLEET PRESSURE CHECK,PM168	EX0002157
01	EX00021562	ROTATE TBR TYRE,PM168	EX0002156
01	86931401	B FLEET PRESSURE CHECK,PM168	EX0002157
01	86931402	ROTATE TBR TYRE,PM168	EX0002156

01	86931402	BALANCE TBR,PM168	EX0002156
		Labour	
		Labour - Internal	
		Consumables	
		Labour	
		Consumables	
		Labour	
IT LABEL			
		Labour - Internal	
		Consumables	
		AIR FILTER SLEEPER AIR	
		OIL 15W-40, CK 4/E9	
		Labour	
		Consumables	
		Labour	
		Labour	

Supplier Code	Invoice	Details	Purchase Order
		Labour - Internal	2.50
		Consumables	4.00
		Labour	0.00
N			
		Labour - Internal	1.00
		Consumables	4.00
		COOLANT	0.15
		Labour	0.50
			0.50
			0.50
		Consumables	4.00
		Labour	0.00
		Labour	1.50
LER			
BOTTLE BROKE AND LEAKED			
		Labour - Internal	1.50
		Labour - Internal	0.50
		Consumables	5.00
		FF5776 Fuel Filter	1.00
		Ad Blue filter Kenworth	1.00
		Oil Filter (was LF9080)	1.00
		OIL 15W-40, CK 4/E9	47.00
		Hub Cap, Steers	1.00
		Labour	0.50
		Labour - Internal	0.50
		Consumables	3.00
		HITECH SYNPLUS 10W50	1.00
		Labour	1.00
		Labour - Internal	1.00
		Consumables	4.00

Supplier Code	Invoice	Details		Purchase Order	
BRIAUS01	EX00023173	BALANCE TBR,PM168		EX0002317	
BRIAUS01	87505570	BALANCE TBR,PM168		EX0002317	
		Labour			
		Consumables			
BRIAUS01	EX00023575	PUNCTURE REPAIR TBR,PM168		EX0002357	
BRIAUS01	87678627	PUNCTURE REPAIR TBR,PM168		EX0002357	
		Labour			0.00
		Labour			1.50
TER CLEANED					
		Labour - Internal		1.50	85.00
		Consumables			5.00
		Oil Filter (was LF9080)			1.00
		FF5776 Fuel Filter			1.00
		Element 10 Micron			1.00
		Ad Blue filter Kenworth			1.00
		OIL 15W-40, CK 4/E9			50.00
		Labour			0.50
BRENDAN					
		Labour - Internal			0.50
		Consumables			
		AIR FILTER SLEEPER AIR			
		HITECH SYNPLUS 10W50			
		Labour			
		Labour			
		Labour - Internal			
		Consumables			
BRIAUS01	EX00023792	BALANCE TBR,PM168		EX0002379	
BRIAUS01	87806169	BALANCE TBR,PM168		EX0002379	
		Labour			

Supplier Code	Invoice	Details		Purchase Order	
		Labour - Internal			1.00
		Consumables			5.00
		Labour			0.75
AND LINES, REPLACED AS2474					
		Labour - Internal			0.75
		Consumables			2.00
		Ad Blue filter Kenworth			1.00
		Labour			0.50
		Labour - Internal			0.50
		Consumables			3.00

AIR GAUGE:

LABOUR

		Labour	0.00
		Labour	1.50

;H WAS ON;Y
ER DIAGNOSIS

		Labour - Internal	1.50
		Consumables	5.00
		Oil Filter (was LF9080)	1.00
		FF5776 Fuel Filter	1.00
		Ad Blue filter Kenworth	1.00
		OIL 15W-40, CK 4/E9	50.00
			1.00
		Labour - Internal	1.00

Supplier Code	Invoice	Details	Purchase Order
		Consumables	
	EX00024537	Labour,XQ43UH	EX0002453
IR01	2538938	Labour,XQ43UH	EX0002453
		Labour	
		Consumables	
		OIL 15W-40, CK 4/E9	

LABOUR

		Labour	
		Labour	
		Labour - Internal	
		Consumables	
		MAINTENANCE KIT	
		OIL 15W-40, CK 4/E9	
BRIAUS01	EX00024960	BALANCE TBR,PM168	EX0002496
BRIAUS01	88306648	BALANCE TBR,PM168	EX0002496
		Labour - Internal	

)

R APPRENB

		Labour	

		Consumables	
		OIL 15W-40, CK 4/E9	
T01	EX00025232	GENERAL PART CODE,XQ43UH	EX0002523
T01	EX00025232	GENERAL PART CODE,XQ43UH	EX0002523

Supplier Code	Invoice	Details	Purchase Order
KENAUT01	EX00025232	GENERAL PART CODE,XQ43UH	EX0002523
KENAUT01	EX00025232	Consumables	EX0002523
KENAUT01	EX00025232	,XQ43UH	EX0002523
		Labour,XQ43UH	

NV# 51576

HECK CURRENT DRAW AND VOLTAGE AT LIGHTS
S SLOWLY, WIRE IN SECONDARY CIRCUIT TO SPLIT SPOT LIGHTS
AB

KENAUT01	51576	GENERAL PART CODE,XQ43UH	EX0002523
KENAUT01	51576	GENERAL PART CODE,XQ43UH	EX0002523
KENAUT01	51576	GENERAL PART CODE,XQ43UH	EX0002523
KENAUT01	51576	Consumables	EX0002523
KENAUT01	51576	,XQ43UH	EX0002523
		Labour,XQ43UH	
		Labour	1.50

JSHED TANK STALK TENSIONED BOLTS ON SUNVISOR

	Labour - Internal	1.50
	Consumables	4.00
	OIL 15W-40, CK 4/E9	2.00

LABOUR MECH

	Labour	0.00
	Labour	2.00

IOUNT OF OIL

		Labour - Internal	
		Consumables	
		OIL 15W-40, CK 4/E9	
		Element 10 Micron	
		Oil Filter (was LF9080)	
		FF5776 Fuel Filter	
		Ad Blue filter Kenworth	
VIEWTR01	EX00025559	Labour,PM168	EX0002555
VIEWTR01	EX00025559	Labour - 10% DISCOUNT,PM168	EX0002555

Supplier Code	Invoice	Details	Purchase Order
VIEWTR01	EX00025559	Consumables	EX0002555
VIEWTR01	EX00025559	,PM168	EX0002555
		STAINLESS STEEL CAMERA	
VIEWTR01	INV-0200	BRACKETS,PM168	EX0002555
		STAINLESS STEEL CAMERA	
VIEWTR01	INV-0200	BRACKETS,PM168	EX0002555
		Consumables	
VIEWTR01	INV-0200	,PM168	EX0002555
		Labour - 10% DISCOUNT,PM168	
VIEWTR01	INV-0200	Labour,PM168	EX0002555

on of Defect :
OD AMOUNT OF OIL

	Labour	
		1.00
	Labour	1.00

ECTED RH AND NO EXCESSIVE OIL FOUND AS WELL

onsumables		3.00
	Labour	1.00
	AIR FILTER SLEEPER AIR	1.00
	HITECH SYNPLUS 10W50	1.00
	Consumables	2.00
	Labour	1.00
	Labour - Internal	1.00
	Consumables	3.00
	Labour	1.50

T IS GONE

AL READ 12.60V

	Labour - Internal	1.00
	Consumables	3.00
	REPLACEMENT ELEMENT INLINE FILTER	1.00

Supplier Code	Invoice	Details	Purchase Order

Defect :
S SEAT COULD NOT FAULT

		Labour	2.50
ECH			
		Labour - Internal	2.50
		Consumables	
BROHUR01	EX00026105	PARTS,XQ43UH	EX0002610
BROHUR01	EX00026105	Labour BREAKDOWN REPAIRS,XQ43UH	EX0002610
BROHUR01	EX00026105	Consumables	EX0002610
BROHUR01	EX00026105	,XQ43UH ENVIRONMENTAL LEVY,XQ43UH	EX0002610
BROHUR01	2698448	ENVIRONMENTAL LEVY,XQ43UH	EX0002610
BROHUR01	2698448	Consumables	EX0002610
BROHUR01	2698448	,XQ43UH	EX0002610
BROHUR01	2698448	Labour BREAKDOWN REPAIRS,XQ43UH PARTS,XQ43UH	EX0002610
		Labour	0.00
		Labour	2.00

.12.2022

RENF

		Labour - Internal	2.00

		Labour - Internal	2.00
		Consumables	0.00
		OIL 15W-40, CK 4/E9	51.00
		MAINTENANCE KIT	1.00
		Labour	2.00

1.12.2022

)UR APPREN

		Labour - Internal	2.00
		Labour - Internal	1.00
		Consumables	5.00
		COOLANT FILTER	1.00
		REPLACEMENT ELEMENT INLINE FILTER	
		Filter Element Gearbox Eaton	

Supplier Code	Invoice	Details	Purchase Order
		Power Steer Filter LF637	
		Air Filter	
		COOLANT FILTER	
		Turbo 2000 Air dryer	
		Diff/Gear Oil 80W90 Castrol	
		Labour	2.00

)N. ATTEMPT

:022

		Labour - Internal	2.00
		Labour	1.00
		Labour - Internal	1.00
		Consumables	
BRIAUS01	EX00026323	11R22.5 148/145L BS M866,PM168	EX0002632
BRIAUS01	EX00026323	CASE STOCK 11-22.5,PM168	EX0002632
BRIAUS01	EX00026323	FIT TBR TYRE,PM168	EX0002632
BRIAUS01	EX00026323	REMOVAL: CUSTOMER PULL POINT,PM168	EX0002632
		11R22.5 148/145L BS M866	
BRIAUS01	88863961	REMOVAL: CUSTOMER PULL	EX0002632
BRIAUS01	88863961	POINT,PM168	EX0002632
		FIT TBR TYRE,PM168	
BRIAUS01	88863961	CASE STOCK 11-22.5,PM168	EX0002632
BRIAUS01	88863961	11R22.5 148/145L BS M866,PM168	EX0002632
		Labour	
		Labour - Internal	
		TRP KW CAB AIR FILTER	
		Labour	

Supplier Code	Invoice	Details	Purchase Order

)n of Defect :

		Labour	2.00
		Consumables	3.00

Fuel Filter (Sleeper Air)		1.00
AIR FILTER SLEEPER AIR		1.00
Eco Oil Filter Cartridge		1.00
Labour		1.00
Consumables		4.00
Labour		1.75

trailer end.

TY DEFECT CLEARED.

Defect : Battery dying within a day.

Labour - Internal		1.75
BATTERY DEEP CYCLE & TRUCK		4.00
Suzi Coil Long		1.00
Consumables		5.00
Labour		0.00
Labour		0.00

Defect :
)T WORKING TRAILER LIGHT

		Labour	1.00
Supplier Code	Invoice	Details	Purchase Order
DOSER FLUSH LABOUR		Labour - Internal	
		Labour - Internal	
		Ad Blue filter Kenworth	
		Consumables	
		Labour	
		Labour	
		Labour - Internal	
		MAINTENANCE KIT	
		VECTRON 15W-40 CK-4/E9	
		Consumables	
		Labour	

of Defect :

		Labour	
APPREN			
		Labour - Internal	
		Consumables	
		Labour	

		Labour - Internal	
		Consumables	
;01	EX00027955	295/80R22.5 152/148M BS R154 ECO,	EX0002795
01	EX00027955	case stock 295/80-22.5,	EX0002795
01	EX00027955	FIT TBR TYRE,	EX0002795
01	EX00027955	REMOVAL: CUSTOMER PULL POINT,	EX0002795
01	EX00027955	BALANCE TBR,	EX0002795
01	89453530	BALANCE TBR,	EX0002795
01	89453530	REMOVAL: CUSTOMER PULL POINT,	EX0002795
01	89453530	FIT TBR TYRE,	EX0002795
01	89453530	case stock 295/80-22.5,	EX0002795
;01	89453530	295/80R22.5 152/148M BS R154 ECO,	EX0002795
		Labour	

RROR

Supplier Code	Invoice	Details	Purchase Order
		GENERAL PART CODE - SPOTTER MIRROR	
		Consumables	
		Labour	

Defect :

ECH

		Labour	

nce : 11811

.

		Labour	
.		Consumables	

e and replace
all ok. Vac and

alternator (

	EX00028183	Labour External,	EX0002818
C01	EX00028183	Travel Fee to Breakdowns,	EX0002818
C01	EX00028183	R134A, A/C GAS,	EX0002818
C01	EX00028183	NITROGEN HIGH PURITY,	EX0002818
:C01	EX00028183	GENERAL PART CODE - PRESSURE SWITHC,	EX0002818
C01	EX00028183	Consumables	EX0002818
C01	GC-RIN03556	, Consumables	EX0002818
:C01	GC-RIN03556	, GENERAL PART CODE - PRESSURE	EX0002818
BDSMEC01	SWITHC, GC-RIN03556	NITROGEN HIGH PURITY,	EX0002818

Supplier Code	Invoice	Details	Purchase Order
BDSMEC01	GC-RIN03556	R134A, A/C GAS,	EX0002818
BDSMEC01	GC-RIN03556	Travel Fee to Breakdowns,	EX0002818
BDSMEC01	GC-RIN03556	Labour External,	EX0002818
		Labour	0.00

Labour	2.00

& TIGHTENED

Labour - Internal	2.00
MAINTENANCE KIT	1.00
Consumables	3.00
Labour	1.00
Labour - Internal	1.00
Consumables	3.00
Labour	0.00
Labour	2.00
Consumables	
Labour	
Labour - Internal	
Consumables	
Labour	

Supplier Code	Invoice	Details	Purchase Order
CUMMIN01	EX00028718	Labour External,	EX0002871
CUMMIN01	EX00028718	ENVIRONMENTAL LEVY,	EX0002871
CUMMIN01	EX00028718	ROAD TOLLS,	EX0002871
CUMMIN01	EX00028718	OVERTIME,	EX0002871
CUMMIN01	EX00028718	Travel Fee to Breakdowns,	EX0002871
CUMMIN01	EX00028718	TRAVEL LABOUR,	EX0002871
CUMMIN01	9779915	Labour External,	EX0002871
CUMMIN01	9779915	ENVIRONMENTAL LEVY,	EX0002871
CUMMIN01	9779915	ROAD TOLLS,	EX0002871
CUMMIN01	9779915	OVERTIME,	EX0002871
CUMMIN01	9779915	Travel Fee to Breakdowns,	EX0002871
CUMMIN01	9779915	TRAVEL LABOUR,	EX0002871

LABOUR

Labour	1.00
Consumables	3.00
Labour	0.00

AIR GAUGE:

AIR GAUGE:

LABOUR

Labour	0.00

		Labour		0.25
		Labour - Internal		0.25
		Labour - Internal		0.25
		Labour - Internal		0.25
		AIR FILTER SLEEPER AIR		1.00
		HITECH SYNPLUS 10W50		1.00
		Consumables		3.00
		Labour		0.00
		Labour		2.00
		Labour - Internal		2.00
		Labour - Internal		2.00

Supplier Code	Invoice	Details	Purchase Order
		MAINTENANCE KIT	
		OIL 15W-40, CK 4/E9	
		AC BELT, GPK1590	
		FAN BELT	
		Element 10 Micron	
		Consumables	
		Labour	
		Labour	

)23 Description of Defect :

		Labour		0.50
		Consumables		3.00
		Suzi Coil Long		1.00

AIR GAUGE: 16600

LABOUR APPRENB

		Labour - Internal		3.00
		OIL 15W-40, CK 4/E9		5.00
		Consumables		3.00
		Labour		1.00
		Labour - Internal		1.00
		Consumables		3.00
		Labour		0.00

Supplier Code	Invoice	Details	Purchase Order

HEAHAU01	EX00029900	TOW TO HHTA YARD CAMPBELLFIELD., TOWED	EX0002990
HEAHAU01	EX00029902	TO HHTA YARD	EX0002990
HEAHAU01	EX00029901	CAMPBELLFIELD, TOWED TO HHTA YARD,	EX0002990
HEAHAU01	INV-8655	TOWED TO HHTA YARD CAMPBELLFIELD,	EX0002990
HEAHAU01	INV-8655A	TOW TO HHTA YARD	EX0002990
HEAHAU01	INV-8655R	CAMPBELLFIELD., TOWED TO HHTA YARD,	EX0002990
WINBOS01	EX00029654	Labour External,REPLACE LH & RH FRONT	EX0002965
NICPOR01	EX00029681	WINDSCREEN SUPPLIED AND FITTED	EX0002968
		Labour External,TRUCK CABIN GLASS	
		REMOVAL AND DETAIL CLEAN. (GLASS SMASHED BY TREE)	
WINBOS01	QNV0406	Labour External,REPLACE LH & RH	EX0002965
		FRONT WINDSCREEN SUPPLIED AND FITTED	
NICPOR01	014	Labour External,TRUCK CABIN GLASS	EX0002968
		REMOVAL AND DETAIL CLEAN. (GLASS SMASHED BY TREE)	
		Labour	

E ELEMENT WAS BLOWN.

RS.

S BROKEN OFF.

01/08/2023 Description of Defect :

Labour - Internal	3.50
Labour - Internal	3.50
Consumables	5.00
Fuel/Water seperator filter	1.00
Fuel Filter (Sleeper Air)	1.00
HW DIFF BREATHER	1.00
RTE LIFT PUMP	1.00

Supplier Code	Invoice	Details	Purchase Order

3/2023 INVOICE NO. GC-RIN04192

SLEEPER AIR NOT WORKING
und sleep air not working. Put air conditioner gauges on and found only
st of the refrigerant, carried out a pressure test and checked for leaks.
Found
axle caused by rubbing on the U-Bolt. Cut the hose and an adaptor was
umed down to check it would hold in a vacuum. Recharged system with refrigerant and
r vent was down to 6.8 degrees whilst running.
Confirmed
sleep air was working correctly.
BDSMEC01 EX00029810 REPAIR SLEEPER AIR.,

			EX0002981
C01	EX00029810	Travel Fee to Breakdowns,	EX0002981
C01	EX00029810	Consumables	EX0002981
			EX0002981
C01	GC-RIN04192	REPAIR SLEEPER AIR.,	
C01	GC-RIN04192	Travel Fee to Breakdowns,	EX0002981
C01	GC-RIN04192	Consumables	EX0002981

,
Labour 0.00

:8/02/2023

:8/02/2023

Labour 3.00

TTER MIRROR
ING TO DOOR. REPLACED SEAT BELT AS REQUIRED.

Consumables 6.00
MIRROR-SPOTTER 7" 1.00

Supplier Code	Invoice	Details	Purchase Order
VIEWTR01	EX00029904	PREMIUM FORWARD FACING CAMERA	EX0002990
VIEWTR01	EX00029904	- 180 DEGREE, ON-SITE INSTALLATION AT EXODAS,	EX0002990
VIEWTR01	INV-0436	PREMIUM FORWARD FACING CAMERA	EX0002990
VIEWTR01	INV-0436	- 180 DEGREE, ON-SITE INSTALLATION AT EXODAS,	EX0002990
BROHUR01	EX00030075	LABOUR - FIND CAUSE OF SCRATCHED	EX0003007
BROHUR01	EX00030075	WINDOW TINT, LABOUR - REPAIR SCRATCHED	EX0003007
BROHUR01	EX00030075	WINDOW TINTING, SEAL - DOOR GLASS,	EX0003007
BROHUR01	EX00030075	Consumables	EX0003007
BROHUR01	EX00030075	, ENVIRONMENTAL LEVY,	EX0003007
BROHUR01	2964234	LABOUR - FIND CAUSE OF SCRATCHED	EX0003007
BROHUR01	2964234	WINDOW TINT, LABOUR - REPAIR SCRATCHED	EX0003007
BROHUR01	2964234	WINDOW TINTING, SEAL - DOOR GLASS,	EX0003007
BROHUR01	2964234	Consumables	EX0003007
BROHUR01	2964234	, ENVIRONMENTAL LEVY,	EX0003007
		Labour	

:PH ON 24/08/2023.

Labour - Internal 1.00
Labour - Internal 1.00
Labour - Internal 1.00
Consumables 3.00
Kit Q-Plus Brake Shoe 2.00
Labour 0.00

Labour 0.00

Defect :
.Y EXCEPT IT HAS NO SOUND AT ALL THROUGH SPEAKERS. RESEARCHED
UP. MAYBE NEW HEAD UNIT REQUIRED.

:REO

Supplier Code	Invoice	Details	Purchase Order

)efect :
)R CAB & DASH AS SOME GAUGES ARE NOT LIT AT NIGHT

S X 3

)/09/2023 Description of Defect :
TTING CHECKERPLATE ON TANK WITH WING)

AB

BRIAUS01	EX00030303	SPACER REAR CAB SUPPORT,	EX0003030
BROHUR01	EX00030307	SPACER REAR CAB SUPPORT,	EX0003030
BRIAUS01	EX00030306	SPACER REAR CAB SUPPORT,	EX0003030
		Labour	
BROHUR01	2979924	SPACER REAR CAB SUPPORT,	EX0003030

S X 3
CAB

Consumables	6.00
SPACER REAR CAB SUPPORT	1.00
DASH GLOBES X 3	1.00
Labour	0.00
Labour	2.00

SPOTTER WINDOW WIRING
TINGUISHER

Labour - Internal	1.00
Consumables	4.00
MAINTENANCE KIT	1.00
OIL 15W-40, CK 4/E9	50.00
Element 10 Micron	1.00
1.5KG FIRE EXTINGUISHER	1.00
Labour	0.00

Supplier Code	Invoice	Details	Purchase Order

Defect :
)OW

)/09/2023 Description of Defect :
FOR AN INVERTOR (AS I HAVE 1 + A MICROWAVE) CURRENTLY TRUCK HAS NO INVERTOR OR

BRIAUS01	EX00030527	PUNCTURE REPAIR TBR,	EX0003052
BRIAUS01	187347824	PUNCTURE REPAIR TBR,	EX0003052
BROHUR01	EX00030570	REPLACE STEERING COLUMN CABLE,	EX0003057
BROHUR01	EX00030570	CABLE -GEN 2.5STR COLUMN KW,	EX0003057

BROHUR01	EX00030570	Consumables	EX0003057
BROHUR01	EX00030570	,	EX0003057
		ENVIRONMENTAL LEVY,	
BROHUR01	2995172	ENVIRONMENTAL LEVY,	EX0003057
BROHUR01	2995172	Consumables	EX0003057
BROHUR01	2995172	,	EX0003057
		CABLE -GEN 2.5STR COLUMN KW,	
BROHUR01	2995172	REPLACE STEERING COLUMN CABLE,	EX0003057
		Labour	0.00

Defect :

ANT LEAK

Supplier Code	Invoice	Details	Purchase Order

Defect :
STEM U/S HOT

NDENSER

Labour

JLT COOLANT

Consumables

		12" 24V 85W REVERSIBLE FAN - CONDENSOR	
R01	EX00030781	CABLE -GEN 2.5STR COLUMN KW,	EX0003078
R01	EX00030781	Labour External,	EX0003078
R01	EX00030781	Consumables	EX0003078
R01	3000597	,	EX0003078
		Consumables	
R01	3000597	,	EX0003078
		Labour External,	
R01	3000597	CABLE -GEN 2.5STR COLUMN KW,	EX0003078

LABOUR

Labour

23.

Labour - Internal

Consumables

LAMBSWOOL DRIVERS SEAT COVER - KENWORTH - BLACK

Labour

Supplier Code	Invoice	Details	Purchase Order

Defect :
AMBSWOOL SEAT COVERS. CAN THESE BE FITTED PLEASE?

ERS

EMAX01	EX00031092	5800 SERIES TRUCK KIT DUAL HEIGHT	EX0003109
EMAX01	EX00031092	CONTROL,	EX0003109
		Transtech lead for IVU,	
EMAX01	EX00031092	12V BYPASS KIT,	EX0003109
EMAX01	EX00031092	QAirweigh Airline Fitting for Kenworth,	EX0003109
EMAX01	EX00031092	Airweigh Truck Installation,	EX0003109
EMAX01	7130129	5800 SERIES TRUCK KIT DUAL HEIGHT	EX0003109
EMAX01	7130129	CONTROL,	EX0003109
		Transtech lead for IVU,	
EMAX01	7130129	12V BYPASS KIT,	EX0003109
EMAX01	7130129	QAirweigh Airline Fitting for Kenworth,	EX0003109
EMAX01	7130129	Airweigh Truck Installation,	EX0003109
		Labour	

ł

		Labour - Internal	
		Consumables	
		Labour	

		Labour,	EX0003119
ND01 6999		Labour,	EX0003119
		LABOUR	

3.

		Labour - Internal	
		Consumables	
		Labour	

Supplier Code	Invoice	Details	Purchase Order
		Labour	1.00

)N 21/11/2023.

		Labour - Internal	1.00
		Labour - Internal	1.00
		Labour - Internal	1.00
		Turbo 2000 Air dryer	1.00
		TRP KW CAB AIR FILTER	1.00
		Power Steer Filter LF637	1.00
		DIFF FILTER	1.00
		Filter Element Gearbox Eaton	1.00
		ES Water Filter	1.00
		Consumables	3.00
		Labour	0.00
		Labour	0.00
		Labour	0.00

023 Description of Defect :

		Labour	1.00
		Labour - Internal	1.00
		Consumables	3.00
		HITECH SYNPLUS 10W50	1.00
		AIR FILTER SLEEPER AIR	1.00
		Fuel/Water seperator filter	1.00
		Eco Oil Filter Cartridge	1.00
		Fuel Filter Ecowind	1.00
		Labour	3.00

ON. ATTEMPT # 1

L/2023 NO FAULTS APPARENT

Supplier Code	Invoice	Details	Purchase Order
		Labour - Internal	
BRIAUS01	EX00031610	295/80R22.5 152/148M BS R154 ECO,FITTED	EX0003161
BRIAUS01	EX00031610	FROM CUSTOMER'S OWN STOCK	EX0003161
		FIT TBR TYRE,	
BRIAUS01	EX00031610	TYRE HELD FOR RUNOUT,	EX0003161
BRIAUS01	EX00031610	REMOVAL: CUSTOMER REQUEST,	EX0003161
BRIAUS01	EX00031610	SCHEDULED DEPOT SERVICE 15MIN,	EX0003161
BRIAUS01	187711937	SCHEDULED DEPOT SERVICE 15MIN,	EX0003161
BRIAUS01	187711937	REMOVAL: CUSTOMER REQUEST,	EX0003161
BRIAUS01	187711937	TYRE HELD FOR RUNOUT,	EX0003161
BRIAUS01	187711937	FIT TBR TYRE,	EX0003161
BRIAUS01	187711937	295/80R22.5 152/148M BS R154 ECO,FITTED	EX0003161
NABQAN01	EX00031774	FROM CUSTOMER'S OWN STOCK	EX0003177
		TRAVEL TO BURSTALL BREEZE AND	
		JUMP START KENWORTH PRIME MOVER,	
NABQAN01	EX00032119	JUMP START KENWORTH PRIME	EX0003211
		MOVER,	
NABQAN01	EX00031774	Travel Fee to Breakdowns,	EX0003177
NABQAN01	EX00032119	Travel Fee to Breakdowns,	EX0003211
NABQAN01	53991	TRAVEL TO BURSTALL BREEZE AND JUMP	EX0003177
NABQAN01	53991A	START KENWORTH PRIME MOVER,	EX0003211
		Travel Fee to Breakdowns,	
NABQAN01	53991	Travel Fee to Breakdowns,	EX0003177
NABQAN01	53991A	JUMP START KENWORTH PRIME MOVER,	EX0003211
		Labour	0.00
		Labour	2.00

'12/2023.

		Labour - Internal	2.00
		Labour - Internal	2.00
		Consumables	4.00
		MAINTENANCE KIT	1.00
		OIL 15W-40, CK 4/E9	50.00
		Labour	0.00
		Labour	0.00
		Labour	0.50

Supplier Code	Invoice	Details	Purchase Order

ED D2

VALVE GOVERNOR D2

Consumables

AIR GAUGE:

LABOUR

Labour

Defect :

:K STARTER

Labour

SOCK FOR

OT "

Consumables
Labour

Labour - Internal

Consumables
OIL 15W-40, CK 4/E9
Labour

01	EX00032447	REMOVE & REPLACE RED & BLUE LONG TAIL	EX0003244
:01	EX00032447	SUZI COILS, SET LONG TAIL SUZI COILS,	EX0003244
01	00001827	REMOVE & REPLACE RED & BLUE LONG TAIL	EX0003244
:01	00001827	SUZI COILS, SET LONG TAIL SUZI COILS,	EX0003244

Supplier Code	Invoice	Details	Purchase Order

LABOUR

Labour 1.00

:4.

Labour - Internal 1.00

Consumables 3.00
Labour 0.00

Labour 1.00

024

Labour - Internal 1.00

Consumables 3.00
Labour 0.00

Defect :

25/09/2023 Description of Defect :
.N THESE BE FITTED IN ADDITION TO ONES ALREADY FITTED. ON TOP RAIL WOULD BE EXCELLENT.

Supplier Code	Invoice	Details	Purchase Order
)efect :			
BRIAUS01	EX00033123	11R22.5 148/145L BS M866,	EX0003312
BRIAUS01	EX00033123	FIT TBR TYRE,	EX0003312
BRIAUS01	EX00033123	CUSTOMER SCRAPPED OWN TYRE,	EX0003312
BRIAUS01	EX00033123	REMOVAL: SEPARATION,	EX0003312
BRIAUS01	EX00033123	SVC CALL OUT AFTER HOURS/15MINS,	EX0003312
BRIAUS01	EX00033123	ETA MIN FEE,	EX0003312
BRIAUS01	188225894	11R22.5 148/145L BS M866,	EX0003312
BRIAUS01	188225894	FIT TBR TYRE,	EX0003312
BRIAUS01	188225894	CUSTOMER SCRAPPED OWN TYRE,	EX0003312
BRIAUS01	188225894	REMOVAL: SEPARATION,	EX0003312
BRIAUS01	188225894	SVC CALL OUT AFTER HOURS/15MINS,	EX0003312
BRIAUS01	188225894	ETA MIN FEE,	EX0003312
NABQAN01	EX00033169	CALL OUT AFTER HOURS. TRUCK HAD BLOWN	EX0003316
DUNDIE01	EX00033678	TYRE & AIR BAG. ISOLATE DAMAGED BAG. REMOVE & REPLACE TYRE. TIGHTENED MUDGUARDS, TRUCK HAD BLOWN TYRE & BLOWN AIRBAG ON AXLE 3 R/H. ISOLATED DAMAGED BAG SUPPLY LINE. REMOVED & REPLACED BLOWN OUT TYRE. TIGHTENED MUDGUARD AND CUT AWAY DAMAGED SECTIONS,	EX0003367
NABQAN01	EX00033169	Travel Fee to Breakdowns,	EX0003316
DUNDIE01	EX00033678	Travel Fee to Breakdowns,	EX0003367
NABQAN01	EX00033169	Consumables	EX0003316
DUNDIE01	EX00033678	, Consumables	EX0003367
NABQAN01	EX00033169	, Call Out After Hours/Off Site,	EX0003316
DUNDIE01	EX00033678	Call Out After Hours/Off Site,	EX0003367
NABQAN01	INV-0465	CALL OUT AFTER HOURS. TRUCK HAD BLOWN	EX0003316
DUNDIE01	INV-0465	TYRE & AIR BAG. ISOLATE DAMAGED BAG. REMOVE & REPLACE TYRE. TIGHTENED MUDGUARDS, TRUCK HAD BLOWN TYRE & BLOWN AIRBAG ON AXLE 3 R/H. ISOLATED DAMAGED BAG SUPPLY LINE. REMOVED & REPLACED BLOWN OUT TYRE. TIGHTENED MUDGUARD AND CUT AWAY DAMAGED SECTIONS,	EX0003367

Supplier Code	Invoice	Details	Purchase Order
NABQAN01	INV-0465	Travel Fee to Breakdowns,	EX0003316
DUNDIE01	INV-0465	Travel Fee to Breakdowns,	EX0003367

NABQAN01	INV-0465	Consumables	EX0003316
DUNDIE01	INV-0465	, Consumables	EX0003367
NABQAN01	INV-0465	, Call Out After Hours/Off Site,	EX0003316
DUNDIE01	INV-0465	Call Out After Hours/Off Site, Labour	EX0003367

Labour	2.50

REPLACED GUARD, TAIL LIGHT

Labour - Internal	1.00
FENDER L/BLUE SPRAYSAFE	1.00
LAMP-TAIL LIGHT (RH WITH REF)	1.00
Air Bag, Drive K200	1.00
Mudflap, Kenworth	2.00
Labour	0.00

Labour	1.50

/2024. FIXED WATER JET FOR

Labour - Internal	1.50

Consumables	4.00
MAINTENANCE KIT	1.00
OIL 15W-40, CK 4/E9	52.00
Labour	0.00

/02/2024 Description of Defect :
REPLACE. CHECK ALL DRIVE

Supplier Code	Invoice	Details	Purchase Order

of Defect :

BRIAUS01	EX00033390	11R22.5 148/145L BS M866,	EX0003339
BRIAUS01	EX00033390	FIT TBR TYRE,	EX0003339
BRIAUS01	EX00033390	TYRE SENT FIR CAPPING,	EX0003339
BRIAUS01	EX00033390	REMOVAL: CUSTOMER PULL POINT,	EX0003339
BRIAUS01	EX00033390	SCHEDULED DEPOT SERVICE 15MIN,	EX0003339
BRIAUS01	188316439	11R22.5 148/145L BS M866,	EX0003339
BRIAUS01	188316439	FIT TBR TYRE,	EX0003339
BRIAUS01	188316439	TYRE SENT FIR CAPPING,	EX0003339
BRIAUS01	188316439	REMOVAL: CUSTOMER PULL POINT,	EX0003339
BRIAUS01	188316439	SCHEDULED DEPOT SERVICE 15MIN,	EX0003339

Labour	0.50

)4/2024.

Labour - Internal	0.50
Consumables	3.00
Labour	0.00

LABOUR APPREN

Labour		1.00

EPLACED DRIVER'S SIDE

303 CREATED

Consumables		3.00
OIL 15W-40, CK 4/E9		3.00

Supplier Code	Invoice	Details	Purchase Order	
		Labour		0.00

Defect :
. MADI

'S SIDE CAMERA LABOUR MECH

Labour		0.50

/05/2024.

Labour - Internal		0.50
Consumables		3.00
Labour		0.00
Labour		0.00

Labour		0.50

EN ON 24/05/2024.

ICE. DEFECT NO. 00011582 CREATED 1.00
onsumables

Labour - Internal		0.50
HITECH SYNPLUS 10W50		1.00
Air Filter Sleeper Air		1.00
Labour		0.00

Labour		12.00

EY ON 19/06/2024.

RE-WIRED LHS PARK LIGHTS

GHT STEERING IS OKAY.

Labour - Internal

1.00

Labour - Internal		1.00
OIL 15W-40, CK 4/E9		50.00
MAINTENANCE KIT		1.00
Air Filter		1.00

Supplier Code	Invoice	Details	Purchase Order	
		RECON TURBOCHARGER KIT		
		AIR COMPRESSOR SX, RECONDITIONED		
		COOLANT		

Valve Governor
DOSER UNIT - AAA9138439999
Kit Q-Plus Brake Shoe
Consumables
Labour

f Defect :

: 06/03/2024

OKAY

.2/04/2024

AIR GAUGE:

Supplier Code	Invoice	Details	Purchase Order

AIR GAUGE: 15280

AIR GAUGE: 16000

AIR GAUGE: 14240

AIR GAUGE: 16220

LABOUR MECH 1

Labour 1.00

3/2024.

JJ

Labour - Internal		1.00
Consumables		3.00
Labour		0.00
Labour		1.00

P) ON 06/09/2024.

3LE REPLACED LH SIDE OIL HUB

Labour - Internal		1.00
Consumables		5.00
Labour		0.00

Supplier Code	Invoice	Details	Purchase Order
		Labour	0.00
		Labour	3.50

JOSH ON 25/09/2024.

FOR CHC PIPE REPLACED BELTS AND TENSIONERS
STALK

	Labour - Internal		
			1.50
	Labour - Internal		2.00
	Labour - Internal		1.50
	Consumables		3.00
		Ad Blue filter Kenworth	1.00
		BELT TENSIONER	1.00
	Fan Belt		1.00
T		Drive Belt, K200	1.00
		BELT TENSIONER	1.00
		OIL 15W-40, CK 4/E9	50.00
		FILTER KIT, OIL & FUEL FILTER, (E5)	1.00
		Jaw Repair Kit JSK37/42	1.00
		Wiper Control Stalk	1.00
	Labour		0.00
	Labour - Internal		2.00

L OF WATER REATTACHED FRONT FACE CAMERA
RHS STEER HUB SEAL
R SEAL - HUB SEAL

		1.00
Consumables		6.00
Labour - Internal		1.00
Labour		0.00

f Defect :
D. IT SLIPPED TO FACE THE FLOOR THEN A

Supplier Code	Invoice	Details	Purchase Order

Defect :
ED

LABOUR

Labour

f Defect :

21/10/2024

	EX00037003	Receiver Drier, K200,	EX0003700
R01	EX00037003	O-RING,	EX0003700
R01	EX00037003	COMPRESSOR - REFRIGERANT,	EX0003700

2024. INVOICE NO. GC-RIN08079

cted & vehicle started. Noticed
ower supply checked at
; ordered. Old compressor
ut back on. Dryer was replaced
leaks found. System then
rged with 1400g of refrigerant.
e was put back together & area

Receiver Drier, K200, EX0003700

Supplier Code	Invoice	Details	Purchase Order
BDSMEC01	EX00037064	A/C NOT COLD. REMOVED AND REPLACED	EX0003706
BROHUR01	3370345	NEW COMPRESSOR & DRYER, O-RING,	EX0003700
BDSMEC01	EX00037064	Travel Fee to Breakdowns,	EX0003706
BROHUR01	3370345	COMPRESSOR - REFRIGERANT,	EX0003700
BDSMEC01	EX00037064	AIRCON REFRIGERANT,	EX0003706
BDSMEC01	EX00037064	NITROGEN PRESSURE TEST,	EX0003706
BDSMEC01	GC-RIN08079	A/C NOT COLD. REMOVED AND REPLACED NEW COMPRESSOR & DRYER,	EX0003706
BDSMEC01	GC-RIN08079	Travel Fee to Breakdowns,	EX0003706
BDSMEC01	GC-RIN08079	AIRCON REFRIGERANT,	EX0003706
BDSMEC01	GC-RIN08079	NITROGEN PRESSURE TEST,	EX0003706
BRIAUS01	EX00037158	295/80R22.5 152/148M BS R154 ECO,	EX0003715
BRIAUS01	EX00037158	case stock 295/80-22.5,	EX0003715
BRIAUS01	EX00037158	FIT TBR TYRE,	EX0003715
BRIAUS01	EX00037158	REMOVAL: CUSTOMER PULL POINT,	EX0003715
BRIAUS01	EX00037158	SCHEDULED DEPOT SERVICE 15MIN,	EX0003715
BRIAUS01	189589469	295/80R22.5 152/148M BS R154 ECO,	EX0003715
BRIAUS01	189589469	case stock 295/80-22.5,	EX0003715
BRIAUS01	189589469	FIT TBR TYRE,	EX0003715
BRIAUS01	189589469	REMOVAL: CUSTOMER PULL POINT,	EX0003715

BRIAUS01	189589469	SCHEDULED DEPOT SERVICE 15MIN,	EX0003715
		Labour	

N 21/11/2024.

Labour - Internal	1.00
Consumables	3.00
OIL 15W-40, CK 4/E9	6.00
Labour	0.00
Labour	0.00
Labour	4.00

(SHOP) ON 24/12/2024.

IP) FIXED SPOT LIGHT WIRING.

Labour - Internal	2.00
Consumables	6.00
OIL 15W-40, CK 4/E9	50.00

Supplier Code	Invoice	Details	Purchase Order
		MAINTENANCE KIT	
		Labour	

2/12/2024

HT

14/12/2024

	EX00038028	CHANGED OUT OIL FILTER THAT HAD	EX0003802
N01	EX00038028	LET GO ON SEAL, NEW FILTER,	EX0003802
N01	1051	CHANGED OUT OIL FILTER THAT HAD LET GO	EX0003802
N01	1051	ON SEAL, NEW FILTER,	EX0003802
		Labour	

6/01/2025.

LABOUR	1.00
Consumables	3.00
Labour	1.00

WORKSHOP) ON 16/01/2025.

VEMENT) AND FITTED A NEW OUTER CAP

(TIGHTENED BOLTS AND CLEANED DOWN AREA)

Labour - Internal	2.00
Labour - Internal	2.00
Consumables	7.00
Filter Element Gearbox Eaton	1.00
ES Water Filter	1.00

Supplier Code	Invoice	Details	Purchase Order
		DIFF FILTER	
		REPLACEMENT ELEMENT INLINE FILTER	
		Power Steer Filter LF637	
		Element 10 Micron	
		Turbo 2000 Air dryer	
		TRP KW CAB AIR FILTER	
		Fan Belt	
		Drive Belt, K200	
		Labour	
		Labour	
		Labour	
		Labour	

: :
R AIR

		Labour	1.00
SH (WORKSHOP)		ON 16/01/2025.	
		Labour - Internal	1.00
		Consumables	4.00
		HITECH SYNPLUS 10W50	1.00
		Oil Filter Eco/Sleeper	1.00
		Fuel Filter (Sleeper Air)	1.00
		Fuel/Water seperator filter	1.00
		Air Filter Sleeper Air	1.00
		BS358N 70 O-RING 142.24 X 5.3	1.00
		Labour	1.00

Supplier Code	Invoice	Details	Purchase Order
ON. ATTEMPT # 1			
N 16/01/2025			
		Labour - Internal	0.50
ORKSHOP) ON 17/02/2025.			
ACK TO THE WORKSHOP ASAP			
		Consumables	3.00
		Labour - Internal	0.50
		Labour - Internal	0.50
		Labour	0.00
		Labour - Internal	0.00
		Consumables	0.00
		Labour - Internal	4.00

SEAL LEAKING*

		Consumables	
		Labour - Internal	
		BRAKE SHOE SET DRIVES	
		SERVICE KIT	
		AIR OIL FILTER	
		Labour	
NABQAN01	EX00038860	KUMHO 11R22.5 148/145L,	EX0003886
NABQAN01	EX00038860	Labour,	EX0003886
NABQAN01	EX00038860	Labour,	EX0003886
NABQAN01	228307	KUMHO 11R22.5 148/145L,	EX0003886
NABQAN01	228307	Labour,	EX0003886
NABQAN01	228307	Labour,	EX0003886
BRIAUS01	EX00039107	RUNOUT TYRE,	EX0003910
BRIAUS01	EX00039107	FIT TBR TYRE,	EX0003910

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	EX00039107	TYRE HELD FOR RUNOUT,	EX0003910
BRIAUS01	EX00039107	REMOVAL: MATCH OTD OR PATTERN,	EX0003910
BRIAUS01	EX00039107	SCHEDULED DEPOT SERVICE 15MIN,	EX0003910
BRIAUS01	EX00039107	295/80R22.5 152/148M BS R154 ECO,	EX0003910
BRIAUS01	EX00039107	FIT TBR TYRE,	EX0003910
BRIAUS01	EX00039107	TYRE HELD FOR RUNOUT,	EX0003910
BRIAUS01	EX00039107	REMOVAL: CUSTOMER REQUEST,	EX0003910
BRIAUS01	190370806	RUNOUT TYRE,	EX0003910
BRIAUS01	190370806	FIT TBR TYRE,	EX0003910
BRIAUS01	190370806	TYRE HELD FOR RUNOUT,	EX0003910
BRIAUS01	190370806	REMOVAL: MATCH OTD OR PATTERN,	EX0003910
BRIAUS01	190370806	SCHEDULED DEPOT SERVICE 15MIN,	EX0003910
BRIAUS01	190370806	295/80R22.5 152/148M BS R154 ECO,	EX0003910
BRIAUS01	190370806	FIT TBR TYRE,	EX0003910
BRIAUS01	190370806	TYRE HELD FOR RUNOUT,	EX0003910
BRIAUS01	190370806	REMOVAL: CUSTOMER REQUEST,	EX0003910
		Labour	

	Labour	1.00

EPAIR AND

	Consumables	3.00
	7 PIN LG RND METAL PLUG	1.00
	Suzi Coil Long	1.00
	Labour - Internal	3.00

AND BATTERY LEADS OKAY NOTE RECHECK BATTERIES AND LOAD TEST NEXT SERVICE

	Consumables	6.00

3.00

Supplier Code	Invoice	Details	Purchase Order	
		Pogo Stick (2190mm-2900mm)		1.00
		Labour		0.00

of Defect :

17/02/2025 Description of Defect :
CK TO THE WORKSHOP ASAP

16/01/2025 Description of Defect :
(TIGHTENED BOLTS AND CLEANED DOWN AREA)

10/03/2025 Description of Defect :
AKING)

04/04/2025 Description of Defect :

25/03/2025 Description of Defect :

16/01/2025 Description of Defect :

Supplier Code	Invoice	Details	Purchase Order

f Defect :

27/01/2025 Description of Defect :
DE IS WORKING BUT NOT GETTING COLD. THERE IS AN OIL LEAK ON THE

07/08/2024 Description of Defect :

Labour - Internal

1.00

WIRING
onsumables 3.00

Labour 0.00

of Defect :

BRIAUS01	EX00039803	PUNCTURE REPAIR TBR,	EX0003980
BRIAUS01	EX00039803	SCHEDULED DEPOT SERVICE 15MIN,	EX0003980
BRIAUS01	190606512	PUNCTURE REPAIR TBR,	EX0003980
BRIAUS01	190606512	SCHEDULED DEPOT SERVICE 15MIN,	EX0003980
BRIAUS01	EX00040105	11R22.5 148/145L BS M749II ECO,	EX0004010
BRIAUS01	EX00040105	CASE STOCK 11R22.5 ECOPIA,	EX0004010
BRIAUS01	EX00040105	FIT TBR TYRE,	EX0004010
BRIAUS01	EX00040105	REMOVAL: CUSTOMER PULL POINT,	EX0004010
BRIAUS01	EX00040105	SCHEDULED DEPOT SERVICE 15MIN,	EX0004010
BRIAUS01	190701577	11R22.5 148/145L BS M749II ECO,	EX0004010
BRIAUS01	190701577	CASE STOCK 11R22.5 ECOPIA,	EX0004010
BRIAUS01	190701577	FIT TBR TYRE,	EX0004010
BRIAUS01	190701577	REMOVAL: CUSTOMER PULL POINT,	EX0004010

Supplier Code	Invoice	Details	Purchase Order	
BRIAUS01	190701577	SCHEDULED DEPOT SERVICE 15MIN,	EX0004010	
		Labour - Internal		0.00
		Consumables		0.00
		Labour - Internal		1.50

SH SHAFT

Consumables	3.00
Labour - Internal	1.50
Labour - Internal	0.50
SERVICE KIT	1.00
AIR OIL FILTER	1.00
OIL 15W-40, CK 4/E9	51.00
Labour	0.00
Labour - Internal	2.50

SHOCK BUSHES REPLACED 2 FAULTY BATTERIES (2ND HAND) ALL DRIVE TYRES HAVE BEEN

SERVICE COULDNT FIND HOLE IN EXHAUST

SKET ON "B" D# 14522 REPLACE TANK STRAP RUBBERS ON B SERVICE D# 14523

Consumables	6.00
Labour - Internal	2.50
Labour	0.00
Labour	0.00

Supplier Code	Invoice	Details	Purchase Order
Defect :			
HER			
		Labour	0.50
		Consumables	3.00
		HITECH SYNPLUS 10W50	1.00
		AIR FILTER SLEEPER AIR	1.00
		Labour - Internal	2.50
D 1KG FE			
LINOIED CON	YAT		
		Consumables	8.00
		SWITCH-PRESSURE 5PSI NC	1.00
		Suzi Coil Long	1.00
		1KG FIRE EXTINGUISHER	1.00
		Labour	0.00
f Defect :			
CH			
		Labour - Internal	0.00
		Consumables	0.00
		Labour - Internal	2.00
. BOLTS COULDN'T FAULT			
		Consumables	3.00

Supplier Code	Invoice	Details	Purchase Order
		Labour - Internal	
		Labour - Internal	
		OIL 15W-40, CK 4/E9	
		SERVICE KIT	
		AIR OIL FILTER	
		LED FRONT DIRECTION LAMP	
		Labour	0.00
f Defect :			
		Labour - Internal	1.00

LUTCH

Consumables		3.00
Labour - Internal		1.00
Labour		0.00
Labour		1.00

		Consumables	
		BATTERY DEEP CYCLE & TRUCK	
BRIAUS01	EX00041984	295/80R22.5 152/148M BS R154 ECO,	EX0004198
BRIAUS01	EX00041984	FIT TBR TYRE,	EX0004198
BRIAUS01	EX00041984	TYRE HELD FOR RUNOUT,	EX0004198
BRIAUS01	EX00041984	REMOVAL: CUSTOMER REQUEST,	EX0004198
BRIAUS01	EX00041984	SCHEDULED DEPOT SERVICE 15MIN,	EX0004198
BRIAUS01	191326439	295/80R22.5 152/148M BS R154 ECO,	EX0004198
BRIAUS01	191326439	FIT TBR TYRE,	EX0004198
BRIAUS01	191326439	TYRE HELD FOR RUNOUT,	EX0004198
BRIAUS01	191326439	REMOVAL: CUSTOMER REQUEST,	EX0004198
BRIAUS01	191326439	SCHEDULED DEPOT SERVICE 15MIN,	EX0004198
		Labour - Internal	

Supplier Code	Invoice	Details	Purchase Order
		Consumables	
		Labour - Internal	3.50

IR FULL CORD FOR AIR TANK
REPLACE FUEL PRO CANNISTER

T
AP RUBBERY

Consumables	8.00
Labour - Internal	3.50
Labour - Internal	3.50
Labour - Internal	3.50
Seal - Thru RP23160	1.00
SERVICE KIT	1.00
AIR OIL FILTER	1.00
OIL 15W-40, CK 4/E9	51.00
Element 10 Micron	1.00
Filter Housing Top (Fuel Pro)	1.00
BRAKE SHOE & HARDWARE KIT	1.00
Labour	0.00

Defect :

SPARE ON AT THE MOMENT. LEFT TYRE AT ROLLER DOOR

26/06/2025 Description of Defect :

31/05/2025 Description of Defect : THROUGH SHAFT LEAKING

Supplier Code	Invoice	Details	Purchase Order

Defect :
P GASKET ON "B"

CUMMIN01	EX00042255	Labour External,	EX0004225
CUMMIN01	EX00042255	HT/S SUPER DUTY OEM KIT,	EX0004225
CUMMIN01	EX00042255	FF5776 Fuel Filter,	EX0004225
CUMMIN01	EX00042255	Air Filter,	EX0004225
CUMMIN01	EX00042255	MATERIALS,HOSE DAYCO SILICONE	EX0004225
CUMMIN01	EX00042255	WORKSHOP CONSUMABLES,HEATER TAPS	EX0004225
CUMMIN01	EX00042255	Consumables	EX0004225

,

10/2025

AUSE - WARRANTY REPAIR
WARRANTY DURING REPAIR, FIT MAJOR KIT

CUMMIN01	1753421	Labour External,	EX0004225
CUMMIN01	1753421	HT/S SUPER DUTY OEM KIT,	EX0004225
CUMMIN01	1753421	FF5776 Fuel Filter,	EX0004225
CUMMIN01	1753421	Air Filter,	EX0004225
CUMMIN01	1753421	MATERIALS,HOSE DAYCO SILICONE	EX0004225
CUMMIN01	1753421	WORKSHOP CONSUMABLES,HEATER TAPS	EX0004225
CUMMIN01	1753421	Consumables	EX0004225

,

Labour	1.00
Consumables	3.00
BELT TENSIONER	1.00
Drive Belt, K200	1.00
Labour	1.50

Supplier Code	Invoice	Details	Purchase Order
		Consumables	
		12 V 5 PIN WATERPROOF RELAY	
		MIRROR CONTROL SWITCH K200	
		Labour - Internal	1.50

:T SHOCKIE
F LIGHT
NATOR IS

Consumables	6.00
Labour - Internal	1.50
Labour	0.00

f Defect :

31/05/2025

: 25/09/2025

Labour	1.50

OST SYSTEM PIPING, REPLACE 1 X INTERCOOLER HOSE AT TURBO - ALL OK

Consumables	3.00
Labour - Internal	1.50
INTERCOOLER HOSE	1.00
Labour	1.00

Supplier Code	Invoice	Details	Purchase Order

S ON OUTSIDE OF TANK

FAULT CODES

Consumables	0.00
Labour - Internal	0.50
Ad Blue filter Kenworth	1.00
Labour - Internal	1.00

Consumables	3.00
Labour - Internal	1.00
Labour	1.00

11/2025

Consumables	3.00
KOHLER AIR FILTER	1.00
HITECH SYNPLUS 10W50	1.00
Labour - Internal	0.00

Consumables	0.00
Labour - Internal	1.50

RY 2028

		Consumables	3.00
		Labour - Internal	1.50
		Labour - Internal	0.50
		OIL 15W-40, CK 4/E9	51.00
		SERVICE KIT	1.00
		AIR OIL FILTER	1.00
		Labour - Internal	10.00

Supplier Code	Invoice	Details	Purchase Order

L DRIVE SHOCKS
PLACED LHF DRIVE HUB SEAL

ON)

		Consumables	7.00
		Labour - Internal	10.00
		Parts Supplied	4.00
		Torque Rod Bush	4.00
		CR SEAL - HUB SEAL	1.00
		Labour - Internal	10.00

		Consumables	7.00
		Labour - Internal	10.00
		FILTER CABIN K200	1.00
		AIR FILTER	1.00
		Filter Diff	1.00
		Turbo 2000 Air Drier	1.00
		Filter Element Gearbox Eaton	1.00
		Power Steer Filter LF637	1.00
		ES Water Filter	1.00
		TRANS MAN HVY DUTY 75W90 205L	13.00
		TRANS DYNADRIVE LL 80W90	36.00
		REPLACEMENT ELEMENT INLINE FILTER	1.00
		Labour	5.00

ON. ATTEMPT

RUARY 2028

		Labour - Internal	5.00
BRIAUS01	EX00044154	295/80R22.5 152/148M BS R154 ECO,	EX0004415
BRIAUS01	EX00044154	FIT TBR TYRE,	EX0004415

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	EX00044154	TYRE HELD FOR RUNOUT,	EX0004415
BRIAUS01	EX00044154	REMOVAL: CUSTOMER REQUEST,	EX0004415
BRIAUS01	EX00044154	SCHEDULED DEPOT SERVICE 15MIN,	EX0004415
BRIAUS01	192055383	295/80R22.5 152/148M BS R154 ECO,	EX0004415
BRIAUS01	192055383	FIT TBR TYRE,	EX0004415
BRIAUS01	192055383	TYRE HELD FOR RUNOUT,	EX0004415
BRIAUS01	192055383	REMOVAL: CUSTOMER REQUEST,	EX0004415
BRIAUS01	192055383	SCHEDULED DEPOT SERVICE 15MIN,	EX0004415
		Labour - Internal	

CE D2 GOVERNOR VALVE

AGNOSIS CON YAT

			Consumables	
			Labour - Internal	
			1KG FIRE EXTINGUISHER	
R01	EX00045072		Labour External,	EX0004507
R01	EX00045072		HT/S SUPER DUTY OEM KIT,	EX0004507
R01	EX00045072		MISCELLANEOUS CONSUMABLES,	EX0004507
R01	EX00045072		ENVIRONMENTAL LEVY,	EX0004507

Supplier Code	Invoice	Details	Purchase Order

A 02/03/2026

Found the Horton fan was not locking in and appeared to be
removed the Horton fan and secured it in a vice for further

it had blown a hole in it. Supervisors advised this is designed to
ting the fan from locking in. Stripped the Horton fan down and found one of the internal O-rings damaged,

gement and disengagement, potentially leading to overheating
owed signs of overheating due to discolouration.
sor inspected and advised they were acceptable. Reported
. Removed and replaced bearings, friction material, and O-rings,
unit and confirmed correct operation. Reinstalled the Horton fan on the truck, refitted the fan and belt, and

essfully lowered the cab .

BROHUR01	3818796		Labour External,	EX0004507
BROHUR01	3818796		HT/S SUPER DUTY OEM KIT,	EX0004507
BROHUR01	3818796		MISCELLANEOUS CONSUMABLES,	EX0004507
BROHUR01	3818796		ENVIRONMENTAL LEVY,	EX0004507
			Labour - Internal	1.50

' UP COILS ADJUST CLUTCH

	Consumables	3.00
	Labour - Internal	1.50
	OIL 15W-40, CK 4/E9	5.00
	Labour	0.00

Supplier Code	Invoice	Details	Purchase Order

f Defect :
LAYING UP WITH MULTIPLE WARNINGS, HE RECEIVE ALTERNATOR WARNINGS
EHEATING SIGNIFICANTLY. HE HAS DROPPED HIS PM AT WORKSHOP
Labour

1.00

03/2026

Consumables		3.00
	KOHLER AIR FILTER	1.00

	HITECH SYNPLUS 10W50	1.00
	Labour	1.00

RRECT VOLTS

onsumables		3.00
	ALTERNATOR-L/N 160A PAD MT	1.00
	Labour - Internal	0.00

onsumables		0.00
	Labour - Internal	1.50

ARY 2028

		Consumables	
		Labour - Internal	
		Labour - Internal	
		OIL 15W-40, CK 4/E9	
		SERVICE KIT	
		AIR OIL FILTER	
BRIAUS01	EX00045402	B FLEET PRESSURE CHECK,	EX0004540
BRIAUS01	EX00045402	CHECK POS 4 DRIVE FOR PUNCTURE	EX0004540
BRIAUS01	EX00045402	- UNABLE TO FIND ANYTHING PRESSURE CHECK TYRES ON TRUCK 1/4/26, JOB CARD #112694 JEREMY - 0458033913 MICK - 0413966195 - APPROVED JOB 1/4/26,	EX0004540
BRIAUS01	192485681	B FLEET PRESSURE CHECK,	EX0004540

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	192485681	CHECK POS 4 DRIVE FOR PUNCTURE	EX0004540
BRIAUS01	192485681	- UNABLE TO FIND ANYTHING PRESSURE CHECK TYRES ON TRUCK 1/4/26, JOB CARD #112694 JEREMY - 0458033913 MICK - 0413966195 - APPROVED JOB 1/4/26,	EX0004540
GILROA01	EX00045952	Suzi Coil Long,	EX0004595
GILROA01	EX00045952	SELF SEALING 1/2" KIT,	EX0004595
GILROA01	EX00045952	Parts Supplied,HIGH PERF THREAD	EX0004595
GILROA01	EX00045952	Male Coupler Fitting,	EX0004595
GILROA01	EX00045952	Parts Supplied,TIE-CABLE BLK	EX0004595
GILROA01	EX00045952	WORKSHOP SUPPLIES,	EX0004595
GILROA01	EX00045952	Labour External,	EX0004595
GILROA01	EX00045952	ROUNDING,	EX0004595

6

ED AND

	KWCSN71785	Suzi Coil Long,	EX0004595
01	KWCSN71785	SELF SEALING 1/2" KIT,	EX0004595
01	KWCSN71785	Parts Supplied,HIGH PERF THREAD	EX0004595
01	KWCSN71785	Male Coupler Fitting,	EX0004595
01	KWCSN71785	Parts Supplied,TIE-CABLE BLK	EX0004595
01	KWCSN71785	WORKSHOP SUPPLIES,	EX0004595
01	KWCSN71785	Labour External,	EX0004595
01	KWCSN71785	ROUNDING,	EX0004595
		Labour - Internal	

Consumables

Labour - Internal
Labour - Internal
Labour - Internal
Labour

Supplier Code	Invoice	Details	Purchase Order
Code : 00016921			
ription of Defect :			
S ADJUSTMENT			
BROHUR01			
	EX00045733	Labour External,	EX0004573
R01	EX00045733	MISCELLANEOUS CONSUMABLES,	EX0004573
R01	EX00045733	ENVIRONMENTAL LEVY,	EX0004573
6			
	3856302	Labour External,	EX0004573
R01	3856302	MISCELLANEOUS CONSUMABLES,	EX0004573
R01	3856302	ENVIRONMENTAL LEVY,	EX0004573
		Labour	

D VOLTAGE BOOSTER AND CLEANED BATTERY TERMINALS, REPLACED LUG ON ALTERNATOR,

BECAUSE

Consumables
Labour - Internal
VOLTAGE INVERTER

BROHUR01	EX00046145	Labour,	EX0004614
BROHUR01	EX00046145	Kit Q-Plus Brake Shoe,	EX0004614
BROHUR01	EX00046145	Seal - Drive,	EX0004614
BROHUR01	EX00046145	Axle Shaft Gasket,	EX0004614
BROHUR01	EX00046145	Consumables	EX0004614
BROHUR01	EX00046145	, Kit Q-Plus Brake Shoe,	EX0004614
BROHUR01	EX00046145	ENVIRONMENTAL LEVY,	EX0004614
BROHUR01	3876466	Labour,	EX0004614
BROHUR01	3876466	Kit Q-Plus Brake Shoe,	EX0004614
BROHUR01	3876466	Seal - Drive,	EX0004614
BROHUR01	3876466	Axle Shaft Gasket,	EX0004614
BROHUR01	3876466	Consumables	EX0004614
BROHUR01	3876466	, Kit Q-Plus Brake Shoe,	EX0004614
BROHUR01	3876466	ENVIRONMENTAL LEVY,	EX0004614
RCCLOW01	EX00046232	Labour External,	EX0004623

Supplier Code	Invoice	Details	Purchase Order
RCCLOW01	EX00046232	Parts Supplied,HUB SEAL	EX0004623
RCCLOW01	EX00046232	Parts Supplied,AXLE GASKET	EX0004623
RCCLOW01	EX00046232	Parts Supplied,GEAR OIL	EX0004623
RCCLOW01	EX00046232	DEGREASER,	EX0004623
RCCLOW01	EX00046232	GREASE,	EX0004623
RCCLOW01	EX00046232	Consumables	EX0004623
RCCLOW01	EX00046232	, ENVIRONMENTAL LEVY,	EX0004623

)0.00 removed axle and hub. Removed seal from hub, cleaned all
ake shoes and cleaned all brakes. Refit brakes, refit hub to axle and tension to spec - Refit axle and tyres,

RCCLOW01	43370	Labour External,	EX0004623
RCCLOW01	43370	Parts Supplied,HUB SEAL	EX0004623
RCCLOW01	43370	Parts Supplied,AXLE GASKET	EX0004623
RCCLOW01	43370	Parts Supplied,GEAR OIL	EX0004623
RCCLOW01	43370	DEGREASER,	EX0004623
RCCLOW01	43370	GREASE,	EX0004623
RCCLOW01	43370	Consumables	EX0004623
RCCLOW01	43370	,	EX0004623
		ENVIRONMENTAL LEVY,	
		Labour - Internal	2.00

GLOBES REMOVE AND FIT
EERING WHEEL COVER

T 3 X DASH VENTS FOR

ITOR DRAGLINK INSPECT

H EXP FEB 2028)
NING BUZZER

		Consumables	5.00
		Labour - Internal	2.00
		Labour - Internal	1.00

Supplier Code	Invoice	Details	Purchase Order	
		Pogo Stick		
		Labour		2.00

D REWIRE ALL PINS REPLACED RHS REAR HUB SEAL

Consumables		5.00
Labour - Internal		1.00
12 V 5 PIN WATERPROOF RELAY		1.00
Seal - Drive		1.00
Labour - Internal		1.00

Consumables	3.00
Labour - Internal	1.00
Labour	0.00

f Defect :

26/05/2026 Description of Defect :

		Labour	0.50

06/2026

		Consumables	3.00
		KOHLER AIR FILTER	1.00
		HITECH SYNPLUS 10W50	1.00
		Fan Motor, Sleeper Air Evapourator	1.00
		Labour - Internal	0.00

Supplier Code	Invoice	Details	Purchase Order
		Consumables	
		Labour - Internal	

ARY 2028

		Consumables	
		Labour - Internal	
		Labour - Internal	
		OIL 15W-40, CK 4/E9	
		FILTER KIT, OIL & FUEL FILTER, (E5)	
		Ad Blue filter Kenworth	
		Kit Brake Shoe Steer MFS73	
		Element 10 Micron	
		Labour	

Defect :

	EX00046951	Labour External,	EX0004695
R01	EX00046951	MISCELLANEOUS CONSUMABLES,	EX0004695
R01	EX00046951	ENVIRONMENTAL LEVY,	EX0004695

:6

	3928178	Labour External,	EX0004695
R01	3928178	MISCELLANEOUS CONSUMABLES,	EX0004695
R01	3928178	ENVIRONMENTAL LEVY,	EX0004695
		Labour	4.50

MOTOR

RT BRING VEHICLE TO

GE RATE, ALL OK

		Consumables	5.00
		Labour - Internal	4.50

Supplier Code	Invoice	Details	Purchase Order
		Labour - Internal	
		BATTERY DEEP CYCLE & TRUCK	
		12V STARTER MOTOR	

Labour - Internal	1.50

HTS AS REQUIRED - RAM ADJUST CLUTCH AS REQUIRED
RE CLEAN AS REQUIRED REPLACED 2 X TANK STRAP RUBBERS ON DRIVERS SIDE FUEL TANK AS
CKET AS REQUIRED - BILLY

Consumables	5.00
Labour - Internal	1.50
Labour - Internal	1.50
Labour - Internal	1.00
Labour - Internal	1.00
FF5776 Fuel Filter	1.00
Marker llght LED, Amber, Lucidity	1.00
Spraysafe Fender-Bracket	1.00

Labour - Internal

Consumables

Labour - Internal

1KG FIRE EXTINGUISHER

R01	EX00048546	11R22.5 148/145M TY517T - B3620,	EX0004854
R01	EX00048546	TRUCK TYRES STRIP AND FIT,	EX0004854

):PM168 - YFS:1752 - REGO:XQ43UH - ODO:1136053KM - FN:PM168 - RN:04-09-2026
230 - POS 9-10
22.5 148/145M TY517T - B3620, EX0004854

R01	IN-131952-202	TRUCK TYRES STRIP AND FIT,	EX0004854

Labour - Internal

onsumables

Labour - Internal

Supplier Code	Invoice	Details	Purchase Order

Consumables	3.00
Labour - Internal	2.00
FILTER KIT, OIL & FUEL FILTER, (E5)	1.00
Ad Blue filter Kenworth	1.00
Element 10 Micron	1.00
OIL PRESSURE SWITCH	1.00
OIL 15W-40, CK 4/E9	5.00
COOLANT	5.00
Labour	0.00

f Defect : LIGHTS ON DASH

Labour	4.00

: SHOES REPLACED LEFT

RIVE

Consumables	7.00

TRP BRAKE DRUM 16-1/2 X 6"	2.00
BPW BRAKE SHOE & HARDWARE	2.00
CR SEAL - HUB SEAL	1.00
CHROME HUBCAP	1.00
Hub Cap Chrome, 8"	1.00
Labour	1.25

E AND REPLACE FAN, CHECK OK

Consumables	3.00
Labour - Internal	0.25
BLOWER MOTOR	1.00
Labour	0.00
Labour	3.00

Supplier Code	Invoice	Details	Purchase Order

H SIDES PLUG IN COMPUTER AND DOOR FAULT AND TEST DRIVE - ALL OK TAKE TO B+ HURLEY AMD

CE WHEEL SENSOR AND DOOR RELEASE RING AND ASSEMBLE

		Consumables	
		Labour - Internal	
		WHEEL SPEED SENSOR	
		Torque Rod Bush	
BROHUR01	EX00048992	KIT - WHEEL SPEED SENSOR,	EX0004899
BROHUR01	EX00049041	Labour,	EX0004904
BROHUR01	EX00049041	Consumables	EX0004904
BROHUR01	EX00049041	,	EX0004904
		ENVIRONMENTAL LEVY,	
		Labour	0.50

ITABLE

Consumables	3.00
Labour - Internal	0.50
Total for Asset	**137,011.36**
Total for Report	**137,011.36**

Supplier Code	Invoice	Details	Purchase Order