Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00030022	29/08/2020	GEN	39	LABOUR MECH1			
PM133	XQ86MI	00030022	29/08/2020	GEN		REPAIR COMPLETED BY SEAN & KEIRAN			
PM133	XQ86MI	00030022	29/08/2020	GEN	00	FITTED SPOTLIGHTS TO BULLBAR FITTED WINGLIGHTS FROM XQ23AV LABOUR APPREN			
PM133	XQ86MI	00030022	29/08/2020	GEN	14			KINGS-9	YAT
PM133	XQ86MI	00030022	29/08/2020	GEN	16			CON	YAT
PM133	XQ86MI	00030366	14/09/2020	GEN	39			3413005	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			3334800	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			LF637	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			17237	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			FS19764	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			AS2474	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			A3380W1687	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			LF14000NN	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			WF2127	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			FF5776	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			PART	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			ENVLEV	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			ROUNDING	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			3413005	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			3334800	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			LF637	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			17237	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			FS19764	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			AS2474	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			A3380W1687	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			LF14000NN	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			WF2127	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			FF5776	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			PART	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			ENVLEV	
PM133	XQ86MI	00030366	14/09/2020	GEN	39			ROUNDING	
PM133	XQ86MI	00030423	15/09/2020	GEN		NHVAS STICKER FITTED BY MICK BURTON 15.09.2020			
PM133	XQ86MI	00030570	22/09/2020	GEN		FUTURE FLEET TRACKER FITTED 22.09.2020			
PM133	XQ86MI	00031686	22/10/2020	CUMAE5	01	ESN: 5650 KMS: 20239 LABOUR MECH			
PM133	XQ86MI	00031686	22/10/2020	CUMAE5		SERVICE COMPLETED BY MICK AND BEN 22.10.2020			
PM133	XQ86MI	00031686	22/10/2020	CUMAE5	00	NEEDS ANDERSEN LEAD SYSTEM LABOUR APPREN			
PM133	XQ86MI	00031686	22/10/2020	CUMAE5	16			CON	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00032641	24/11/2020	CUMAE5	01	LABOUR			
PM133	XQ86MI	00032641	24/11/2020	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00032641	24/11/2020	CUMBE5	00	LABOUR MECH1			
PM133	XQ86MI	00032641	24/11/2020	CUMBE5		SERVICE COMPLETED BY SEAN			
PM133	XQ86MI	00032641	24/11/2020	CUMBE5	00	REPLACED MISSING EBS PLUG EXTENDED AIRLINES DANGEROUS GOODS CHECKLIST COMPLETED LABO			
PM133	XQ86MI	00032641	24/11/2020	CUMBE5	16			CON	YAT
PM133	XQ86MI	00032641	24/11/2020	CUMBE5	06			MK13555	YAT
PM133	XQ86MI	00032641	24/11/2020	CUMBE5	06			AS2474	YAT
PM133	XQ86MI	00032641	24/11/2020	CUMBE5	40			3413005	YAT
PM133	XQ86MI	00032641	24/11/2020	CUMBE5	14			82196	YAT
PM133	XQ86MI	00032641	24/11/2020	CUMBE5	06			FS19764	YAT
PM133	XQ86MI	00032641	24/11/2020	DEFECT		Reported Defect :-			
						Defect Code : 00005170 Defect Reference : 08505 Date : 0 EBS PLUS DOESNT FIT ALL TRAILERS THE GROOVE I			

PM133	XQ86MI	00032641	24/11/2020	DEFECT		DEFECT CLEARED BY SEAN Reported Defect :- Defect Code : 00005171 Defect Reference : 08506 Date : (Description of Defect : SUZIE LEADS /ELEC LEAD NEED EXTENDING				
PM133	XQ86MI	00033105	3/12/2020	WEICAL		DEFECT CLEARED BY SEAN AIR GAUGE: 15.25 ADJUSTED: WEIGHBRIDGE: 14.92				
PM133	XQ86MI	00032928	7/12/2020	ECO	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. MECH				
PM133	XQ86MI	00032928	7/12/2020	ECO		SERVICE COMPLETED BY MICK AND BEN 07.12.2020				
PM133	XQ86MI	00032928	7/12/2020	ECO	00	LABOUR APPREN				
PM133	XQ86MI	00032928	7/12/2020	ECO	16			CON	YAT	
PM133	XQ86MI	00032928	7/12/2020	ECO	06			ED002175254-S	YAT	
PM133	XQ86MI	00032928	7/12/2020	ECO	40			10W50	YAT	
PM133	XQ86MI	00032929	8/12/2020	CUMAE5	01	LABOUR MECH				
PM133	XQ86MI	00032929	8/12/2020	CUMAE5		SERVICE COMPLETED BY MICK AND BEN 08.12.2020				
PM133	XQ86MI	00032929	8/12/2020	CUMAE5	00	LABOUR APPREN				
PM133	XQ86MI	00032929	8/12/2020	CUMAE5	16			CON	YAT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00032929	8/12/2020	DEFECT		DEFECT CLEARED BY MICK 08.12.2020 Defect: 08501			
PM133	XQ86MI	00032946	8/12/2020	STEROT	00	Please refer to defect 00004874 + 00004875. LABOUR ME			
PM133	XQ86MI	00032946	8/12/2020	STEROT		STEER TYRE ROTATION COMPLETED 08.12.20 COMPLETED BY BRIDGESTONE - DAVE			
PM133	XQ86MI	00032984	8/12/2020	TYRSTE	15			33000085	BI
PM133	XQ86MI	00032984	8/12/2020	TYRSTE	15			33000051	BI
PM133	XQ86MI	00032984	8/12/2020	TYRSTE	15			33000051	BI
PM133	XQ86MI	00032984	8/12/2020	TYRSTE	15			33000085	BI
PM133	XQ86MI	00033569	9/01/2021	CUMAE5	01	LABOUR			
PM133	XQ86MI	00033569	9/01/2021	CUMAE5		SERVICE COMPLETED BY SEAN AND KEIRAN			
PM133	XQ86MI	00033569	9/01/2021	CUMAE5	00	ADJUSTED CLUTCH CHECKED ELECTRICAL PLUGS LABOUR MECH1			
PM133	XQ86MI	00033569	9/01/2021	CUMAE5	00	LABOUR APPREN			
PM133	XQ86MI	00033569	9/01/2021	CUMAE5	16			CON	YAT
PM133	XQ86MI	00033569	9/01/2021	DEFECT		Reported Defect :-Defect Code : 00005729 Defect Reference : 08514 Date : 09/01/2021 Description of FOR AN A SERVICE			
PM133	XQ86MI	00033569	9/01/2021	DEFECT		DEFECT CLEARED BY SEAN Reported Defect :- Defect Code : 00005728 Defect Reference : 08515 Date : (Description of Defect : LIGHT PLUG AND EBS LEAD HAVE BEEN STRETCHED			
PM133	XQ86MI	00033569	9/01/2021	DEFECT		DEFECT CLEARED BY SEAN Reported Defect :- Defect Code : 00005169 Defect Reference : 08507 Date : (Description of Defect : STILL HAS A KNOCK IN THE FRONT END DEFECT CLEARED BY SEAN			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00033569	9/01/2021	DEFECT		Reported Defect :-Defect Code : 00005551 Defect Reference : 08510 Date : 24/11/2020 Description of BANGING IN FRONT END				
PM133	XQ86MI	00033569	9/01/2021	DEFECT		DEFECT CLEARED BY SEAN Reported Defect :- Defect Code : 00005552 Defect Reference : 08511 Date : 2 Description of Defect : FRONT HUB SEALS ARE LEAKING				
PM133	XQ86MI	00034377	5/02/2021	CUMAE5	01	DEFECT CLEARED BY SEAN LABOUR				
PM133	XQ86MI	00034377	5/02/2021	CUMAE5		SERVICE COMPLETED.				
PM133	XQ86MI	00034377	5/02/2021	CUMBE5	00	LABOUR MECH1				
PM133	XQ86MI	00034377	5/02/2021	CUMBE5		SERVICE COMPLETED BY SEAN AND KERIAN				
						WIRED IN ANDERSON LEAD AND FITTED ANDERSON ELECTF				
PM133	XQ86MI	00034377	5/02/2021	CUMBE5	00	LABOUR APPREN				
PM133	XQ86MI	00034377	5/02/2021	CUMBE5	06			MK13584	YAT	
PM133	XQ86MI	00034377	5/02/2021	CUMBE5	40			3413005	YAT	
PM133	XQ86MI	00034425	8/02/2021	TYRES	15			77000194		
PM133	XQ86MI	00034425	8/02/2021	TYRES	15			33000051		
PM133	XQ86MI	00034425	8/02/2021	TYRES	15			77000194		
PM133	XQ86MI	00034425	8/02/2021	TYRES	15			33000051		
PM133	XQ86MI	00035082	25/02/2021	CUMAE5	01	LABOUR				
PM133	XQ86MI	00035082	25/02/2021	CUMAE5		SERVICE COMPLETED.				
PM133	XQ86MI	00035082	25/02/2021	DEFECT	00	LABOUR APPREN				
PM133	XQ86MI	00035082	25/02/2021	DEFECT		DEFECT CLEARED BY KEIRAN AND BEN25/02/2021.				
PM133	XQ86MI	00035082	25/02/2021	DEFECT	00	SERVICE COMPLETED BY KEIRAN AND BEN 25/02/202 APPREN				
PM133	XQ86MI	00035082	25/02/2021	DEFECT	16			CON	YAT	
PM133	XQ86MI	00036048	20/03/2021	CUMAE5	00	LABOUR APPREN				
PM133	XQ86MI	00036048	20/03/2021	CUMAE5		SERVICE COMPLETED BY BEN AND KEIRAN				
PM133	XQ86MI	00036048	20/03/2021	CUMAE5	00	REPLACED 1.5KG FIRE EXTINGUISHER LABOUR APPF				
PM133	XQ86MI	00036048	20/03/2021	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00036655	1/04/2021	WEICAL		AIR GAUGE: 14-70 ADJUSTED: 14-30 WEIGHBRIDGE: 13-20				
PM133	XQ86MI	00037000	15/04/2021	WEICAl		AIR GAUGE CALIBRATION COMPLETED CORRECTLY. 14500 ADJUSTED: 15000 WEIGHBRIDGE: 14550				
PM133	XQ86MI	00036780	17/04/2021	CUMAE5	01	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
PM133	XQ86MI	00036780	17/04/2021	CUMAE5		SERVICE COMPLETED.				
PM133	XQ86MI	00036780	17/04/2021	CUMBE5	00	LABOUR MECH1				
PM133	XQ86MI	00036780	17/04/2021	CUMBE5		SERVICE COMPLETED BY RYAN				
PM133	XQ86MI	00036780	17/04/2021	CUMBE5	16			CON	YAT	
PM133	XQ86MI	00036780	17/04/2021	CUMBE5	06			MK13584	YAT	
PM133	XQ86MI	00036780	17/04/2021	CUMBE5	06			FS19764	YAT	
PM133	XQ86MI	00036780	17/04/2021	DEFECT		Reported Defect :-Defect Code : 00006238 Defect Reference : 08520 Date : 15/04/2021 Description of FOR A 'B' SERVICE				

PM133	XQ86MI	00036780	17/04/2021	DEFECT		DEFECT CLEARED BY MICK 17.04.21 Reported Defect :- Defect Code : 00006239 Defect Reference : 08521 Date : 1 Description of Defect : TRAILER LIGHT PLUG IS BROKEN
PM133	XQ86MI	00037345	3/05/2021	WEICAL		DEFECT CLEARED BY MICK 17.04.21 AIR GAUGE: 15-0 ADJUSTED: WEIGHBRIDGE: 14-50
PM133	XQ86MI	00037391	3/05/2021	WEICAL		AIR GAUGE CALIBRATION COMPLETED CORRECTLY. 00 ADJUSTED: WEIGHBRIDGE: 14-50

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00038398	3/05/2021	WEICAL		AIR GAUGE: 15-00 ADJUSTED: WEIGHBRIDGE: 14-50				
PM133	XQ86MI	00037381	5/05/2021	CUMAE5	00	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
PM133	XQ86MI	00037381	5/05/2021	CUMAE5		SERVICE COMPLETED BY RYAN AND BEN				
PM133	XQ86MI	00037381	5/05/2021	CUMAE5	00	LABOUR APPREN				
PM133	XQ86MI	00037381	5/05/2021	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00037381	5/05/2021	ECO	00	LABOUR MECH1				
PM133	XQ86MI	00037381	5/05/2021	ECO		SERVICE COMPLETED BY RYAN AND BEN				
PM133	XQ86MI	00037381	5/05/2021	ECO	00	LABOUR APPREN				
PM133	XQ86MI	00037381	5/05/2021	ECO	16			CON	YAT	
PM133	XQ86MI	00037381	5/05/2021	ECO	06			ED2175254-S	YAT	
PM133	XQ86MI	00037381	5/05/2021	ECO	40			10W50	YAT	
PM133	XQ86MI	00037807	20/05/2021	CUMAE5	00	LABOUR MECH1				
PM133	XQ86MI	00037807	20/05/2021	CUMAE5		SERVICE COMPLETED BY SEAN AND BEN				
PM133	XQ86MI	00037807	20/05/2021	CUMAE5	00	LABOUR APPREN				
PM133	XQ86MI	00037807	20/05/2021	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00038332	9/06/2021	CUMAE5	00	LABOUR APPREN				
PM133	XQ86MI	00038332	9/06/2021	CUMAE5		SERVICE COMPLETED BY BEN AND MICK				
PM133	XQ86MI	00038332	9/06/2021	CUMAE5	00	LABOUR MECH				
PM133	XQ86MI	00038332	9/06/2021	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00038383	9/06/2021	GEN	00	LABOUR MECH1				
PM133	XQ86MI	00038383	9/06/2021	GEN		REPAIR COMPLETED SEAN AND BEN REMOVED OCTAHOSE SYSTEM FITTED NEW MOUNT RELOCATED AIR LINES, 7 PIN LIGHT PLUG AND EBS F AND LO0NG TAIL AIR LINES SHORTENED WALK PLATI LABOUR APPREN				
PM133	XQ86MI	00038383	9/06/2021	GEN	00					
PM133	XQ86MI	00038383	9/06/2021	GEN	16			CON	YAT	
PM133	XQ86MI	00038383	9/06/2021	GEN	14			82506	YAT	
PM133	XQ86MI	00038383	9/06/2021	GEN	14			61-SC3MTLTSE	YAT	
PM133	XQ86MI	00038383	9/06/2021	GEN	14			200.203		YAT
PM133	XQ86MI	00038383	9/06/2021	GEN	14			82196		YAT
PM133	XQ86MI	00038539	15/06/2021	TYRES	15			33000051		
PM133	XQ86MI	00038539	15/06/2021	TYRES	15			33000051		
PM133	XQ86MI	00038806	22/06/2021	CUMAE5	01	LABOUR				
PM133	XQ86MI	00038806	22/06/2021	CUMAE5		SERVICE COMPLETED.				
PM133	XQ86MI	00038806	22/06/2021	CUMBE5	00	LABOUR APPREN				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00038806	22/06/2021	CUMBE5		SERVICE COMPLETED BEN AND SEAN			
PM133	XQ86MI	00038806	22/06/2021	CUMBE5	00	COMPLETED SLEEPER SERVICE ADJUSTED CLUTCH LABOUR MECH1			

PM133	XQ86MI	00038806	22/06/2021	CUMBE5	16			CON	YAT
PM133	XQ86MI	00038806	22/06/2021	CUMBE5	06			MK13584	YAT
PM133	XQ86MI	00038806	22/06/2021	CUMBE5	40			3413005	YAT
PM133	XQ86MI	00038806	22/06/2021	ECO	00	LABOUR APPREN			
PM133	XQ86MI	00038806	22/06/2021	ECO		SERVICE COMPLETED BEN			
PM133	XQ86MI	00038806	22/06/2021	ECO	16			CON	YAT
PM133	XQ86MI	00038806	22/06/2021	ECO	06			ED2175254-S	YAT
PM133	XQ86MI	00038806	22/06/2021	ECO	40			10W50	YAT
PM133	XQ86MI	00039591	13/07/2021	GEN	39			LAB	
PM133	XQ86MI	00040107	13/07/2021	GEN	39			LAB	
PM133	XQ86MI	00040248	13/07/2021	GEN	39			LAB	
PM133	XQ86MI	00039591	13/07/2021	GEN	39			CON	
PM133	XQ86MI	00040107	13/07/2021	GEN	39			CON	
PM133	XQ86MI	00040248	13/07/2021	GEN	39			PART	
PM133	XQ86MI	00039591	13/07/2021	GEN	39			ENVLEV	
PM133	XQ86MI	00040107	13/07/2021	GEN	39			ENVLEV	
PM133	XQ86MI	00039591	13/07/2021	GEN	39			LAB	
PM133	XQ86MI	00039591	13/07/2021	GEN	39			CON	
PM133	XQ86MI	00039591	13/07/2021	GEN	39			ENVLEV	
PM133	XQ86MI	00039615	15/07/2021	CUMAE5	00	LABOUR APPREN			
PM133	XQ86MI	00039615	15/07/2021	CUMAE5		SERVICE COMPLETED MICK AND KEIRAN			
PM133	XQ86MI	00039615	15/07/2021	CUMAE5	00	- TOPPED UP ENGINE WITH OIL LABOUR MECH			
PM133	XQ86MI	00039615	15/07/2021	CUMAE5	16			CON	YAT
PM133	XQ86MI	00039615	15/07/2021	CUMAE5	40			3413005	YAT
PM133	XQ86MI	00039615	15/07/2021	DEFECT		Reported Defect :-Defect Code : 00006255			
PM133	XQ86MI	00039702	17/07/2021	GEN		Defect Reference : 08519 Date : 15/04/2021 Description of Defect : FRIDGE ISNT WORKING			
					39	PART			
PM133	XQ86MI	00039702	17/07/2021	GEN	39			PART	
PM133	XQ86MI	00040347	5/08/2021	CUMAE5	00	LABOUR APPREN			
PM133	XQ86MI	00040347	5/08/2021	CUMAE5		SERVICE COMPLETED BY BEN			
PM133	XQ86MI	00040347	5/08/2021	CUMAE5	16	WARRANTY FUEL PUMP WEEPING CON YAT			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00041474	3/09/2021	CUMAE5	01	LABOUR			
PM133	XQ86MI	00041474	3/09/2021	CUMAE5		SERVICE COMPLETED BY BEN AND			KEIRAN.
PM133	XQ86MI	00041474	3/09/2021	CUMBE5	00	LABOUR MECH1			
PM133	XQ86MI	00041474	3/09/2021	CUMBE5		SERVICE COMPLETED.			
PM133	XQ86MI	00041474	3/09/2021	CUMBE5	00	LABOUR APPREN			
PM133	XQ86MI	00041474	3/09/2021	CUMBE5	16			CON	YAT
PM133	XQ86MI	00041474	3/09/2021	CUMBE5	06			MK13584	YAT
PM133	XQ86MI	00041474	3/09/2021	CUMBE5	40			3413005	YAT
PM133	XQ86MI	00041474	3/09/2021	CUMBE5	06			FS19764	YAT
PM133	XQ86MI	00041529	7/09/2021	TYRES	15			77000194	BI
PM133	XQ86MI	00041529	7/09/2021	TYRES	15			33000051	BI
PM133	XQ86MI	00041529	7/09/2021	TYRES	15			77000194	BI
PM133	XQ86MI	00041529	7/09/2021	TYRES	15			33000051	BI
PM133	XQ86MI	00041752	14/09/2021	CUMCE5	00	LABOUR APPREN			
PM133	XQ86MI	00041752	14/09/2021	CUMCE5		SERVICE COMPLETED BY BEN AND			KEIRAN
PM133	XQ86MI	00041752	14/09/2021	CUMCE5	00	LABOUR APPREN			
PM133	XQ86MI	00041752	14/09/2021	CUMCE5	16			CON	YAT
PM133	XQ86MI	00041752	14/09/2021	CUMCE5	06			A-3380W1687	YAT
PM133	XQ86MI	00041752	14/09/2021	CUMCE5	40			3334800	YAT
PM133	XQ86MI	00041752	14/09/2021	CUMCE5	06			17237	YAT
PM133	XQ86MI	00041752	14/09/2021	CUMCE5	40			3372765	YAT
PM133	XQ86MI	00041752	14/09/2021	CUMCE5	06			T224P	YAT
PM133	XQ86MI	00041752	14/09/2021	CUMCE5	06			TRPCAF0001	YAT
PM133	XQ86MI	00041752	14/09/2021	CUMCE5	06			WF2127	YAT
PM133	XQ86MI	00041752	14/09/2021	CUMCE5	06			LF637	YAT

PM133	XQ86MI	00041752	14/09/2021	CUMCE5	06			AF1969M	YAT
PM133	XQ86MI	00041752	14/09/2021	CUMCE5	06			1409408	YAT
PM133	XQ86MI	00041752	14/09/2021	DEFECT		Reported Defect :-			
						Defect Code : 00006802 Defect Reference : WO40347 Date : 05/0			
						WARRANTY - FUEL PUMP WEEPING			
						BROWN AND HURLEY REPAIRED 13.09.2021			
PM133	XQ86MI	00041752	14/09/2021	ECO	00	LABOUR APPREN			
PM133	XQ86MI	00041752	14/09/2021	ECO		SERVICE COMPLETED BY KEIRAN			
PM133	XQ86MI	00041752	14/09/2021	ECO	16			CON	YAT
PM133	XQ86MI	00041752	14/09/2021	ECO	06			ED2175254-S	YAT
PM133	XQ86MI	00041752	14/09/2021	ECO	06			ED0037300960	YAT
PM133	XQ86MI	00041752	14/09/2021	ECO	06			ED0021751550	YAT
PM133	XQ86MI	00041752	14/09/2021	ECO	06			FS1251	YAT
PM133	XQ86MI	00041752	14/09/2021	ECO	40			10W50	YAT
PM133	XQ86MI	00041752	14/09/2021	EXOINS	01	LABOUR MECH			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S Co
PM133	XQ86MI	00041752	14/09/2021	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECTIO 1				
PM133	XQ86MI	00042213	24/09/2021	CUMAE5	00	INSPECTION COMPLETED BY KEIRAN LABOUR APPRE				
PM133	XQ86MI	00042213	24/09/2021	CUMAE5		SERVICE COMPLETED.				
PM133	XQ86MI	00042213	24/09/2021	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00043047	22/10/2021	CUMAE5	00	LABOUR APPREN				
PM133	XQ86MI	00043047	22/10/2021	CUMAE5		SERVICE COMPLETED BY KEIRAN AND MICK				
						REPLACED ALL 4 BATTERIES AS THE BOTTOM BACK HAD DF				
PM133	XQ86MI	00043047	22/10/2021	CUMAE5	00	LABOUR MECH				
PM133	XQ86MI	00043047	22/10/2021	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00043047	22/10/2021	CUMAE5	14			MF70ZZD	YAT	
PM133	XQ86MI	00043140	25/10/2021	TYRES	15			33000096		
PM133	XQ86MI	00043140	25/10/2021	TYRES	15			33000096		
PM133	XQ86MI	00043486	6/11/2021	CUMAE5	00	LABOUR MECH				
PM133	XQ86MI	00043486	6/11/2021	CUMAE5		SERVICE COMPLETED BY MICK AND BEN				
PM133	XQ86MI	00043486	6/11/2021	CUMAE5	00	LABOUR APPREN				
PM133	XQ86MI	00043486	6/11/2021	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00043728	22/11/2021	CUMAE5	01	LABOUR				
PM133	XQ86MI	00043728	22/11/2021	CUMAE5		SERVICE COMPLETED.				
PM133	XQ86MI	00043728	22/11/2021	CUMBE5	00	LABOUR APPREN				
PM133	XQ86MI	00043728	22/11/2021	CUMBE5		SERVICE COMPLETED BY KEIRAN AND MICK				
PM133	XQ86MI	00043728	22/11/2021	CUMBE5	00	REMOVED AND LOCKTIGHT BOLTS THROUGH IDLER				
PM133	XQ86MI	00043728	22/11/2021	CUMBE5	16			CON	YAT	
PM133	XQ86MI	00043728	22/11/2021	CUMBE5	06			MK13584	YAT	
PM133	XQ86MI	00043728	22/11/2021	CUMBE5	40			3413005	YAT	
PM133	XQ86MI	00044002	4/12/2021	CUMAE5	00	LABOUR MECH1				
PM133	XQ86MI	00044002	4/12/2021	CUMAE5		SERVICE COMPLETED BY IAN				
PM133	XQ86MI	00044002	4/12/2021	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00044092	8/12/2021	TYRES	15			77000180		
PM133	XQ86MI	00044092	8/12/2021	TYRES	15			33000084		
PM133	XQ86MI	00044092	8/12/2021	TYRES	15			33000084		
PM133	XQ86MI	00044092	8/12/2021	TYRES	15			77000180		
PM133	XQ86MI	00044367	21/12/2021	CUMAE5	00	LABOUR MECH1				
PM133	XQ86MI	00044367	21/12/2021	CUMAE5		SERVICE COMPLETED BY IAN				
PM133	XQ86MI	00044367	21/12/2021	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00044528	7/01/2022	CUMAE5	01	LABOUR				
PM133	XQ86MI	00044528	7/01/2022	CUMAE5		SERVICE COMPLETED KEIRAN AND MICK				
PM133	XQ86MI	00044528	7/01/2022	CUMAE5	00	* PRIMER PUMP DOESN'T STOP - WARRENTY LABOUI				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00044528	7/01/2022	CUMAE5	00	LABOUR	APPREN		
PM133	XQ86MI	00044528	7/01/2022	CUMAE5	16			CON	YAT

PM133	XQ86MI	00044528	7/01/2022	ECO		SERVICE COMPLETED KEIRAN AND MICK					
						- ADJUSTED BELTS					
PM133	XQ86MI	00044528	7/01/2022	ECO	00	LABOUR APPREN					
PM133	XQ86MI	00044528	7/01/2022	ECO	00	LABOUR APPREN					
PM133	XQ86MI	00044528	7/01/2022	ECO	16			CON		YAT	
PM133	XQ86MI	00044528	7/01/2022	ECO	40			10W50		YAT	
PM133	XQ86MI	00044528	7/01/2022	ECO	06			ED002175254-S	YAT		
PM133	XQ86MI	00044932	28/01/2022	CUMAE5	01	LABOUR					
PM133	XQ86MI	00044932	28/01/2022	CUMAE5		SERVICE COMPLETED.					
PM133	XQ86MI	00044932	28/01/2022	CUMBE5	00	LABOUR MECH1					
PM133	XQ86MI	00044932	28/01/2022	CUMBE5		SERVICE COMPLETED BY IAN AND KEIRAN					
PM133	XQ86MI	00044932	28/01/2022	CUMBE5	00	LF 14000NN FILTER KIT U/S HAD TO USE ANOTHER NI					
PM133	XQ86MI	00044932	28/01/2022	CUMBE5	16			CON		YAT	
PM133	XQ86MI	00044932	28/01/2022	CUMBE5	06			MK13584	YAT		
PM133	XQ86MI	00044932	28/01/2022	CUMBE5	06			LF14000NN	YAT		
PM133	XQ86MI	00045602	1/02/2022	GEN	39	LABOUR					
PM133	XQ86MI	00045602	1/02/2022	GEN		REPAIR COMPLETED IAN					
						- CHECKED ALL WIREING CONECTIONS, PLUGS AND TERMIN					
						- ALL OK, SEND FOR WARRANTY					
PM133	XQ86MI	00045602	1/02/2022	GEN	00	LABOUR MECH1					
PM133	XQ86MI	00045602	1/02/2022	GEN	16			CON		YAT	
PM133	XQ86MI	00045411	17/02/2022	CUMAE5	00	LABOUR MECH1					
PM133	XQ86MI	00045411	17/02/2022	CUMAE5		SERVICE COMPLETED BY IAN					
ADJUST CLUTCH CARRIED OUT A SERVICE											
PM133	XQ86MI	00045411	17/02/2022	CUMAE5	16			CON		YAT	
PM133	XQ86MI	00045411	17/02/2022	DEFECT		Reported Defect :-					
						Defect Code : 00007253 Defect Reference : WO44528 Dat					
						Description of Defect :					
						* PRIMER PUMP DOESN'T STOP - WARRENTY					
						LABOUR MECH1					
PM133	XQ86MI	00045837	5/03/2022	CUMAE5	00						
PM133	XQ86MI	00045837	5/03/2022	CUMAE5		SERVICE COMPLETED BY IAN AND BRENDAN					
PM133	XQ86MI	00045837	5/03/2022	CUMAE5	00	ADJUST TURNTABLE LABOUR SUBMEC					
PM133	XQ86MI	00045837	5/03/2022	CUMAE5	16			CON		YAT	
PM133	XQ86MI	00046166	17/03/2022	CUMAE5	00	LABOUR SUBMEC					

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00046166	17/03/2022	CUMAE5		SERVICE COMPLETED BRENDEN AND TYLER				
PM133	XQ86MI	00046166	17/03/2022	CUMAE5	00	LABOUR APPREN				
PM133	XQ86MI	00046166	17/03/2022	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00046664	4/04/2022	CUMAE5	01	LABOUR				
PM133	XQ86MI	00046664	4/04/2022	CUMAE5		SERVICE COMPLETED.				
PM133	XQ86MI	00046664	4/04/2022	CUMBE5	00	LABOUR MECH1				
PM133	XQ86MI	00046664	4/04/2022	CUMBE5		SERVICE COMPLETED BY IAN, BEN AND TYLER				
PM133	XQ86MI	00046664	4/04/2022	CUMBE5	00	ADJUST CLUTCH TIGHTEN GRILL MOUNTING BOLTS LABOUR APPRENI				
PM133	XQ86MI	00046664	4/04/2022	CUMBE5	00	LABOUR TRADEA				
PM133	XQ86MI	00046664	4/04/2022	CUMBE5	16			CON	YAT	
PM133	XQ86MI	00046664	4/04/2022	CUMBE5	06			MK13584	YAT	
PM133	XQ86MI	00046664	4/04/2022	CUMBE5	40			15W40	YAT	
PM133	XQ86MI	00046787	5/04/2022	TYRES	15			77000194	BRIAUS	
PM133	XQ86MI	00046787	5/04/2022	TYRES	15			77000194	BRIAUS	
PM133	XQ86MI	00046739	6/04/2022	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00046739	6/04/2022	DEFECT						
PM133	XQ86MI	00046739	6/04/2022	DEFECT		DEFECT CLEARED.				

PM133	XQ86MI	00046739	6/04/2022	GEN	00	LABOUR MECH1			
PM133	XQ86MI	00046739	6/04/2022	GEN		REPAIR COMPLETED BY IAN AND MICK REPAIR AIR HORN REPLACE BROKEN SUNVISOR CLIP LABOUR MECH			
PM133	XQ86MI	00046739	6/04/2022	GEN	00				
PM133	XQ86MI	00046739	6/04/2022	GEN	16		CON	YAT	
PM133	XQ86MI	00046739	6/04/2022	GEN	13		S16-1023-601	YAT	
PM133	XQ86MI	00046933	16/04/2022	CUMAE5	00	LABOUR APPRENK			
PM133	XQ86MI	00046933	16/04/2022	CUMAE5		SERVICE COMPLETED BY KEIRAN			
PM133	XQ86MI	00046933	16/04/2022	CUMAE5	16		CON	YAT	
PM133	XQ86MI	00047398	6/05/2022	CUMAE5	00	LABOUR SUBMEC			
PM133	XQ86MI	00047398	6/05/2022	CUMAE5		SERVICE COMPLETED BY BRENDAN AND TYLER *REAR NUMBER PLATE MISSING LABOUR APPREN			
PM133	XQ86MI	00047398	6/05/2022	CUMAE5	00				
PM133	XQ86MI	00047398	6/05/2022	CUMAE5	16		CON	YAT	
PM133	XQ86MI	00048099	20/05/2022	WEICAL		AIR GAUGE: 15 ADJUSTED: 14.75 WEIGHBRIDGE: 14.3			
PM133	XQ86MI	00047769	21/05/2022	CUMAE5	00	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. SUBMEC			
PM133	XQ86MI	00047769	21/05/2022	CUMAE5		SERVICE COMPLETED BY BRENDAN AND KEIRAN			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00047769	21/05/2022	CUMAE5	00	LABOUR	APPRENK		
PM133	XQ86MI	00047769	21/05/2022	CUMAE5	16			CON	YAT
PM133	XQ86MI	00047769	21/05/2022	DEFECT		Reported Defect :-Defect Code : 00007572			
PM133	XQ86MI	00047770	21/05/2022	ECO		Defect Reference : WO47398 Date : 06/05/2022 Descriptic REAR NUMBER PLATE MISSING LABOUR apprenk			
PM133	XQ86MI	00047770	21/05/2022	ECO	00	SERVICE COMPLETED BY KEIRAN AND BRENDAN			
PM133	XQ86MI	00047770	21/05/2022	ECO	00	LABOUR SUBMEC			
PM133	XQ86MI	00047770	21/05/2022	ECO	16			CON	YAT
PM133	XQ86MI	00047770	21/05/2022	ECO	06			ED2175254-S	YAT
PM133	XQ86MI	00047770	21/05/2022	ECO	40			10W50	YAT
PM133	XQ86MI	00048116	25/05/2022	WEICAL		AIR GAUGE: 14.5 ADJUSTED: 14.00 WEIGHBRIDGE: 13.58			
PM133	XQ86MI	00047930	30/05/2022	TYRES	15	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.		77000180	BI
PM133	XQ86MI	00047930	30/05/2022	TYRES	15			77000180	BI
PM133	XQ86MI	00048134	2/06/2022	WEICAL		AIR GAUGE: 15.250 ADJUSTED: 15.5 WEIGHBRIDGE: 15.8			
PM133	XQ86MI	00048091	4/06/2022	CUMAE5	00	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. LABOUR APPRENB			
PM133	XQ86MI	00048091	4/06/2022	CUMAE5		SERVICE COMPLETED BY BEN, TYLER AND BRENDAN			
PM133	XQ86MI	00048091	4/06/2022	CUMAE5	00	LABOUR APPREN			
PM133	XQ86MI	00048091	4/06/2022	CUMAE5	00	LABOUR SUBMEC			
PM133	XQ86MI	00048091	4/06/2022	CUMAE5	16			CON	YAT
PM133	XQ86MI	00048091	4/06/2022	CUMAE5	06			LF14000NN	YAT
PM133	XQ86MI	00048091	4/06/2022	CUMAE5	06			FF5776	YAT
PM133	XQ86MI	00048091	4/06/2022	CUMAE5	06			FS19764	YAT
PM133	XQ86MI	00048091	4/06/2022	CUMAE5	06			AS2474	YAT
PM133	XQ86MI	00048091	4/06/2022	CUMAE5	40			3413005	YAT
PM133	XQ86MI	00048091	4/06/2022	CUMBE5	01	LABOUR MECH			
PM133	XQ86MI	00048091	4/06/2022	CUMBE5		SERVICE COMPLETED.			
PM133	XQ86MI	00048397	18/06/2022	CUMAE5	00	LABOUR APPRENB			
PM133	XQ86MI	00048397	18/06/2022	CUMAE5		SERVICE COMPLETED BY BEN AND BRENDAN			
PM133	XQ86MI	00048397	18/06/2022	CUMAE5	00	LABOUR SUBMEC			
PM133	XQ86MI	00048397	18/06/2022	CUMAE5	16			CON	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00048638	26/06/2022	WEICAL		AIR GAUGE: 13750 ADJUSTED: 13500 WEIGHBRIDGE: 13100				
PM133	XQ86MI	00048737	2/07/2022	CUMAE5	00	AIR GAUGE CALIBRATION COMPLETED CORRECTLY. SUBMEC				
PM133	XQ86MI	00048737	2/07/2022	CUMAE5		SERVICE COMPLETED BY BRENDAN AND TYLER				
PM133	XQ86MI	00048737	2/07/2022	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00048914	8/07/2022	CUMAE5	00	LABOUR APPRENB				
PM133	XQ86MI	00048914	8/07/2022	CUMAE5		SERVICE COMPLETED BY BEN AND TYLER				
PM133	XQ86MI	00048914	8/07/2022	CUMAE5	00	DIAGNOSED AND REPAIRED LHS BULLBAR WIRING R BULLBAR INDICATOR LIGHT LABOUR APPREN				
PM133	XQ86MI	00048914	8/07/2022	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00048914	8/07/2022	CUMAE5	14			2138	YAT	
PM133	XQ86MI	00049086	8/07/2022	WEICAL		AIR GAUGE: 12500 ADJUSTED: 12750 WEIGHBRIDGE: 12420				
PM133	XQ86MI	00049212	14/07/2022	DEFECT		AIR GAUGE CALIBRATION COMPLETED CORRECTLY. CLEARED BY BEN 14.07.2022				
PM133	XQ86MI	00049212	14/07/2022	GEN	39	DEFECT: 08537 REPORTED BY: BRENDO CLUTCH BRAKE ONLY WORKS WHEN IT WANTS TO. N CLUTCH ADJUSTMENT AS WELL. LABOUR APPRENB				
PM133	XQ86MI	00049212	14/07/2022	GEN		REPAIR COMPLETED BY BEN AND MICK 14.07.2022				
PM133	XQ86MI	00049212	14/07/2022	GEN	00	ADJUSTED CLUTCH LABOUR MECH				
PM133	XQ86MI	00049212	14/07/2022	GEN	16			CON	YAT	
PM133	XQ86MI	00049204	19/07/2022	GEN	39	LABOUR APPRENB				
PM133	XQ86MI	00049204	19/07/2022	GEN		REPAIR COMPLETED BY BEN, MICK AND KEIRAN.				
PM133	XQ86MI	00049204	19/07/2022	GEN	00	REPLACED CLUTCH AND KIT REPLACED TURBO TIGHTENED LHS STEER SHOCK UPPER MOUNT. LABOUR APPRENK				
PM133	XQ86MI	00049204	19/07/2022	GEN	00	LABOUR MECH				
PM133	XQ86MI	00049204	19/07/2022	GEN	16			CON	YAT	
PM133	XQ86MI	00049204	19/07/2022	GEN	07			K-4460-PAC	YAT	
PM133	XQ86MI	00049358	25/07/2022	CUMAE5	00	LABOUR APPRENK				
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00049358	25/07/2022	CUMAE5		SERVICE COMPLETED BY KEIRAN AND TYLER				
PM133	XQ86MI	00049358	25/07/2022	CUMAE5	00	INJECTOR FITTING FOR AFTER TREAT BROKEN REPL AND INJECTOR LABOUR APPREN				
PM133	XQ86MI	00049358	25/07/2022	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00049358	25/07/2022	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00049358	25/07/2022	DEFECT						
PM133	XQ86MI	00049358	25/07/2022	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00049404	27/07/2022	GEN	39			LAB	BROHU	
PM133	XQ86MI	00049404	27/07/2022	GEN	39			LAB	BROHU	
PM133	XQ86MI	00049547	29/07/2022	GEN	39			308935.515PAC	BROHU	
PM133	XQ86MI	00049547	29/07/2022	GEN	39			K-4460-PAC	BROHU	
PM133	XQ86MI	00049547	29/07/2022	GEN	39			PART	BROHU	
PM133	XQ86MI	00049547	29/07/2022	GEN	39			PART	BROHU	
PM133	XQ86MI	00049547	29/07/2022	GEN	39			K-4460-PAC	BROHU	
PM133	XQ86MI	00049547	29/07/2022	GEN	39			308935.515PAC	BROHU	
PM133	XQ86MI	00049873	13/08/2022	CUMAE5	01	LABOUR				
PM133	XQ86MI	00049873	13/08/2022	CUMAE5		SERVICE COMPLETED.				
PM133	XQ86MI	00049873	13/08/2022	CUMBE5	00	LABOUR APPRENB				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00049873	13/08/2022	CUMBE5		SERVICE COMPLETED BY BEN AND TYLER			
PM133	XQ86MI	00049873	13/08/2022	CUMBE5	00	FRONT DRIVE LHS SHOCK MISTING BAD COMPRESSO OIL LABOUR APPREN			
PM133	XQ86MI	00049873	13/08/2022	CUMBE5	16			CON	YAT
PM133	XQ86MI	00049873	13/08/2022	CUMBE5	06			MK13584	YAT
PM133	XQ86MI	00049873	13/08/2022	CUMBE5	40			3413005	YAT
PM133	XQ86MI	00049873	13/08/2022	CUMBE5	06			FS19764	YAT
PM133	XQ86MI	00050185	24/08/2022	GEN	39			LAB	BROHU
PM133	XQ86MI	00050185	24/08/2022	GEN	39			M10403070EPD	BROHU
PM133	XQ86MI	00050185	24/08/2022	GEN	39			PART	BROHU
PM133	XQ86MI	00050185	24/08/2022	GEN		REPAIR COMPLETED BY BROWN & HURLEY INV# 256			
PM133	XQ86MI	00050185	24/08/2022	GEN	39	PLEASE REFER TO ATTACHED INVOICE PART		BROHUR01	
PM133	XQ86MI	00050185	24/08/2022	GEN	39			M10403070EPD	BROHU
PM133	XQ86MI	00050185	24/08/2022	GEN	39			LAB	BROHU
PM133	XQ86MI	00050336	2/09/2022	CUMAE5	00	LABOUR APPREN			
PM133	XQ86MI	00050336	2/09/2022	CUMAE5		SERVICE COMPLETED BY TYLER			
PM133	XQ86MI	00050336	2/09/2022	CUMAE5	16			CON	YAT
PM133	XQ86MI	00050416	5/09/2022	TYRES	15			33000051	BRIAUS
PM133	XQ86MI	00050416	5/09/2022	TYRES	15			33000051	BRIAUS
PM133	XQ86MI	00050821	24/09/2022	CUMAE5	00	LABOUR MECH1			
PM133	XQ86MI	00050821	24/09/2022	CUMAE5		SERVICE COMPLETED BY KEIRAN AND TYLER			
PM133	XQ86MI	00050821	24/09/2022	CUMAE5	16	REMINDER - MICK - ASAP OIL LEAK FROM BACK OF FU YAT			
PM133	XQ86MI	00050995	29/09/2022	CUMAE5	01	LABOUR MECH			
PM133	XQ86MI	00050995	29/09/2022	CUMAE5		SERVICE COMPLETED BENNY			
PM133	XQ86MI	00050995	29/09/2022	CUMAE5	00	- CHECKED BOLTS ON FUEL PUMP - COMPLETED DOSA FLUSH LABOUR APPRENB			
PM133	XQ86MI	00050995	29/09/2022	CUMAE5	16			CON	YAT
PM133	XQ86MI	00050995	29/09/2022	ECO	01	LABOUR MECH			
PM133	XQ86MI	00050995	29/09/2022	ECO		SERVICE COMPLETED BENNY			
PM133	XQ86MI	00050995	29/09/2022	ECO	00	LABOUR APPRENB			
PM133	XQ86MI	00050995	29/09/2022	ECO	40			10W50	YAT
PM133	XQ86MI	00050995	29/09/2022	ECO	06			ED2175254-S	YAT
PM133	XQ86MI	00051368	14/10/2022	CUMAE5	01	LABOUR MECH			
PM133	XQ86MI	00051368	14/10/2022	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00051368	14/10/2022	CUMBE5	01	LABOUR MECH			
PM133	XQ86MI	00051368	14/10/2022	CUMBE5		SERVICE COMPLETED BY BENNY			
PM133	XQ86MI	00051368	14/10/2022	CUMBE5	00	LABOUR APPRENB			
PM133	XQ86MI	00051368	14/10/2022	CUMBE5	16			CON	YAT
PM133	XQ86MI	00051368	14/10/2022	CUMBE5	06			MK13584	YAT
PM133	XQ86MI	00051368	14/10/2022	CUMBE5	40			3413005	YAT
PM133	XQ86MI	00051890	8/11/2022	CUMAE5	00	LABOUR MECH1			
PM133	XQ86MI	00051890	8/11/2022	CUMAE5		PRIMER PUMP DOESNT STOP			
PM133	XQ86MI	00051890	8/11/2022	CUMAE5	16	SERVICE COMPLETED BY KEIRAN CON		YAT	
PM133	XQ86MI	00051961	8/11/2022	CUMCE5	00	LABOUR MECH1			
PM133	XQ86MI	00051961	8/11/2022	CUMCE5		TOPPED UP POWER STEERING OIL			
PM133	XQ86MI	00051961	8/11/2022	CUMCE5	00	SERVICE COMPLETED BY KEIRAN AND BEN LABOUR			
PM133	XQ86MI	00051961	8/11/2022	CUMCE5	16			CON	YAT
PM133	XQ86MI	00051961	8/11/2022	CUMCE5	06			T224P	YAT
PM133	XQ86MI	00051961	8/11/2022	CUMCE5	06			WF2127	YAT
PM133	XQ86MI	00051961	8/11/2022	CUMCE5	06			LF637	YAT
PM133	XQ86MI	00051961	8/11/2022	CUMCE5	06			A-3380W1687	YAT
PM133	XQ86MI	00051961	8/11/2022	CUMCE5	06			17237	YAT
PM133	XQ86MI	00051961	8/11/2022	CUMCE5	06			TRPCAF0001	YAT
PM133	XQ86MI	00051961	8/11/2022	CUMCE5	06			AF1969M	YAT
PM133	XQ86MI	00051961	8/11/2022	CUMCE5	40			85W140	YAT

PM133	XQ86MI	00051961	8/11/2022	CUMCE5	40			3372765	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00051890	8/11/2022	DEFECT		Reported Defect :-Defect Code : 00008174			
PM133	XQ86MI	00051963	8/11/2022	ECO		Defect Reference : 08539 Date : 08/11/2022 Description of DUE FOR A SERVICE DEFECT CLEARED BY KEIRAN 08/11/2022 LABOUR AP			
PM133	XQ86MI	00051963	8/11/2022	ECO	00	SERVICE COMPLETED BY BEN			
PM133	XQ86MI	00051963	8/11/2022	ECO	16			CON	YAT
PM133	XQ86MI	00051963	8/11/2022	ECO	06			ED0037300960	YAT
PM133	XQ86MI	00051963	8/11/2022	ECO	11			MOT-3083	YAT
PM133	XQ86MI	00051963	8/11/2022	ECO	11			BS358N70	YAT
PM133	XQ86MI	00051963	8/11/2022	ECO	40			10W50	YAT
PM133	XQ86MI	00051963	8/11/2022	ECO	06			FS1251	YAT
PM133	XQ86MI	00051962	8/11/2022	EXOINS	00	LABOUR MECH1			
PM133	XQ86MI	00051962	8/11/2022	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECTIC			
PM133	XQ86MI	00052459	25/11/2022	CUMAE5	00	INSPECTION COMPLETED BY KEIRAN LABOUR APPRE			
PM133	XQ86MI	00052459	25/11/2022	CUMAE5		CLEANED WASHER NOZZLES			
PM133	XQ86MI	00052459	25/11/2022	CUMAE5	00	SERVICE COMPLETED BY MICK AND TYLER LABOUR			
PM133	XQ86MI	00052459	25/11/2022	CUMAE5	16			CON	YAT
PM133	XQ86MI	00052459	25/11/2022	DEFECT		Reported Defect :-Defect Code : 00008344			
PM133	XQ86MI	00052330	25/11/2022	GEN		Defect Reference : 08539 Date : 25/11/2022 Description of DEFECT CLEARED BY MICK LABOUR APPRENF			
PM133	XQ86MI	00052330	25/11/2022	GEN	00	RADIATOR AND INTERCOOLER WASH			
PM133	XQ86MI	00052330	25/11/2022	GEN	00	REPAIR COMPLETED BY FKYNN AND MICK LABOUR M			
PM133	XQ86MI	00052330	25/11/2022	GEN	16			CON	YAT
PM133	XQ86MI	00052667	12/12/2022	CUMAE5	01	LABOUR MECH			
PM133	XQ86MI	00052667	12/12/2022	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00052667	12/12/2022	CUMBE5	00	LABOUR APPREN			
PM133	XQ86MI	00052667	12/12/2022	CUMBE5		REPLACED RIGHT HAND STEER HUB SEAL DUE TO LE			
PM133	XQ86MI	00052667	12/12/2022	CUMBE5	06	COMPLETED BY TYLER MK13584 YAT			
PM133	XQ86MI	00052667	12/12/2022	CUMBE5	40			3413005	YAT
PM133	XQ86MI	00052667	12/12/2022	CUMBE5	11			43764S	YAT
PM133	XQ86MI	00052667	12/12/2022	CUMBE5	16			CON	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00053009	28/12/2022	CUMAE5	01	LABOUR MECH			
PM133	XQ86MI	00053009	28/12/2022	CUMAE5		SERVICE COMPLETED BEN AND FLYNN			
PM133	XQ86MI	00053009	28/12/2022	CUMAE5	00	- REPLACED TANK DIVIDER - CABLE ON TANK - MIDDL APPRENB			
PM133	XQ86MI	00053009	28/12/2022	CUMAE5	00	LABOUR APPRENF			
PM133	XQ86MI	00053009	28/12/2022	CUMAE5	16			CON	YAT
PM133	XQ86MI	00053522	21/01/2023	DEFECT	00	LABOUR APPRENK			
PM133	XQ86MI	00053522	21/01/2023	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00053522	21/01/2023	DEFECT		DONE A FULL FLUSH OF THE ADBLUE SYSTEM, LIGHT ALL CAB COMPONETS TO MINAMISE RATTLE ADJUSTED MICRO SWITCH WILL INSPECT TEMP GAUGE FURTHER Reported Defect :-			

							Defect Code : 00008604 Defect Reference : 14753 Date : 2			
							AFTER TREAT LIGHT ON			
							CLUTCH MICRO SWITCH NEEDS ADJUSTMENT LARGI			
							TEM GUEGE NOT WORKING LABOUR APPREN			
PM133	XQ86MI	00053522	21/01/2023	DEFECT	00					
PM133	XQ86MI	00053522	21/01/2023	DEFECT	16			CON	YAT	
PM133	XQ86MI	00053589	24/01/2023	GEN			AC FAULT DIAGNOSE AC FAULT			
							RECOVER GAS AND PRESSURE TEST SYSTEM REPL/			
							ADD OIL AND DYE TO SYSTEM VAC + CHARGE WITH (			
							OK CLEAN AIR FILTER			
							INSPECT EVAPORTOR OK			
PM133	XQ86MI	00053589	24/01/2023	GEN	39			LABEXT		
PM133	XQ86MI	00053589	24/01/2023	GEN	39			CON		
PM133	XQ86MI	00053589	24/01/2023	GEN	39			ENVLEV		
PM133	XQ86MI	00053589	24/01/2023	GEN	39			ENVLEV		
PM133	XQ86MI	00053589	24/01/2023	GEN	39			CON		
PM133	XQ86MI	00053589	24/01/2023	GEN	39			LABEXT		
PM133	XQ86MI	00053631	27/01/2023	CUMAE5	00		LABOUR APPREN			
PM133	XQ86MI	00053631	27/01/2023	CUMAE5			SERVICE COMPLETED.			
PM133	XQ86MI	00053631	27/01/2023	CUMAE5	00		LABOUR APPRENF			
PM133	XQ86MI	00053631	27/01/2023	CUMAE5	06			CON	YAT	
PM133	XQ86MI	00053631	27/01/2023	DEFECT	01		LABOUR MECH			
PM133	XQ86MI	00053631	27/01/2023	DEFECT						
PM133	XQ86MI	00053631	27/01/2023	DEFECT			DEFECT CLEARED.			

Asset Code	Registratio n	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S Cc
PM133	XQ86MI	00053930	6/02/2023	GEN		Complaint:				
PM133	XQ86MI	00053930	6/02/2023	GEN		D-Check items replaced during warranty repairs				
						Cause:				
						D-check items Correction:				
						Guidanz SO Number: 490435 Hrs/Klms: 581652 klms / 737				
						296447 ltrs				
						Download ECM data, filled out hard card, carried out				
						pre-checks and JSA. Replaced d-check items during warra				
						Removed and replaced				
						* turbocharger				
						* air compressor				
						* air governor valve				
						Removed and replaced fuel filters & radiator cap				
						Checked over, packed up, filled out paperwork and returne				
						service.				
						********** Lab				
						GST				
						Turbocharger: $4,466.67 + GST Air compressor: $3,270.52				
						governor: $56.40 + GST Gaskets: $101.44 + GST				
						Fuel filters: $104.83 + GST Radiator cap: $31.83 + GST Cc				
						$56.12 + GST				
						********** TOT				
						+ GST				
						LABEXT		CUMMIN01		
					39					
PM133	XQ86MI	00053930	6/02/2023	GEN	39			LABEXT	CUMMI	
PM133	XQ86MI	00054155	17/02/2023	CUMAE5	00	LABOUR APPRENB				
PM133	XQ86MI	00054155	17/02/2023	CUMAE5		SERVICE COMPLETED. TOPPED UP ENGINE OIL LABC				
PM133	XQ86MI	00054155	17/02/2023	CUMAE5	00					

PM133	XQ86MI	00054155	17/02/2023	CUMAE5	40			3413004	YAT
PM133	XQ86MI	00054155	17/02/2023	CUMAE5	16			CON	YAT
PM133	XQ86MI	00054155	17/02/2023	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00054155	17/02/2023	DEFECT					
PM133	XQ86MI	00054155	17/02/2023	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00054348	27/02/2023	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00054348	27/02/2023	DEFECT					
PM133	XQ86MI	00054348	27/02/2023	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00054348	27/02/2023	GEN	00	LABOUR APPRENF			
PM133	XQ86MI	00054348	27/02/2023	GEN		REPAIR COMPLETED.			
PM133	XQ86MI	00054348	27/02/2023	GEN	16	REPLACED NEW EBS PLUG ON BACK OF TRUCK 82196 YAT			
PM133	XQ86MI	00054348	27/02/2023	GEN	16			CON	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00054770	2/03/2023	GE		Inspect driver reported clutch issue. Complete tests and c Grease clutch linkages. Check clutch adjustment - OK.				
PM133	XQ86MI	00054770	2/03/2023	GEN	39			LABEXT		
PM133	XQ86MI	00054770	2/03/2023	GEN	39			SUND		
PM133	XQ86MI	00054770	2/03/2023	GEN	39			CON		
PM133	XQ86MI	00054770	2/03/2023	GEN	39			CON		
PM133	XQ86MI	00054770	2/03/2023	GEN	39			SUND		
PM133	XQ86MI	00054770	2/03/2023	GEN	39			LABEXT		
PM133	XQ86MI	00054637	2/03/2023	TYRES	15			99015526		
PM133	XQ86MI	00054637	2/03/2023	TYRES	15			77000194		
PM133	XQ86MI	00054637	2/03/2023	TYRES	15			33000084		
PM133	XQ86MI	00054637	2/03/2023	TYRES	15			33000517		
PM133	XQ86MI	00054637	2/03/2023	TYRES	15			33000051		
PM133	XQ86MI	00054637	2/03/2023	TYRES	15			33000051		
PM133	XQ86MI	00054637	2/03/2023	TYRES	15			33000517		
PM133	XQ86MI	00054637	2/03/2023	TYRES	15			33000084		
PM133	XQ86MI	00054637	2/03/2023	TYRES	15			77000194		
PM133	XQ86MI	00054637	2/03/2023	TYRES	15			99015526		
PM133	XQ86MI	00054457	3/03/2023	CUMAE5	01	LABOUR MECH				
PM133	XQ86MI	00054457	3/03/2023	CUMAE5		SERVICE COMPLETED.				
PM133	XQ86MI	00054457	3/03/2023	CUMBE5	00	LABOUR MECH1				
PM133	XQ86MI	00054457	3/03/2023	CUMBE5		SERVICE COMPLETED. COULD NOT FAULT #8175 DEFECT RH FRONT SHOCK APPERED TO BE MISTING BADLY, STILL F REPLACED LIGHT LEAD				
PM133	XQ86MI	00054457	3/03/2023	CUMBE5	16			MK13584	YAT	
PM133	XQ86MI	00054457	3/03/2023	CUMBE5	40			3413005	YAT	
PM133	XQ86MI	00054457	3/03/2023	CUMBE5	16			82506	YAT	
PM133	XQ86MI	00054457	3/03/2023	CUMBE5	16			CON	YAT	
PM133	XQ86MI	00054457	3/03/2023	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00054457	3/03/2023	DEFECT						
PM133	XQ86MI	00054457	3/03/2023	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00054457	3/03/2023	DEFECT		Reported Defect :- Defect Code : 00007466 Defect Reference : 08535 Date : 06/04/2022 Description of Defect : AIR HORN NOT WORKING				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00054457	3/03/2023	DEFECT		Reported Defect :-Defect Code : 00007902			
PM133	XQ86MI	00054457	3/03/2023	DEFECT		Defect Reference : WO49873 Date : 13/08/2008 Descriptic FRONT DRIVE LHS SHOCK MISTING BAD COMPRESSC OIL Reported Defect :-			

						Defect Code : 00008175 Defect Reference : 51890 Date : 0 Description of Defect : PRIMER PUMP DOESNT STOP LABOUR APPRENF				
PM133	XQ86MI	00054505	3/03/2023	ECO	00					
PM133	XQ86MI	00054505	3/03/2023	ECO		SERVICE COMPLETED.				
PM133	XQ86MI	00054505	3/03/2023	ECO	40			10W50	YAT	
PM133	XQ86MI	00054505	3/03/2023	ECO	06			ED2175254-S	YAT	
PM133	XQ86MI	00054505	3/03/2023	ECO	16			CON	YAT	
PM133	XQ86MI	00054593	6/03/2023	WEICAL		AIR GAUGE: 14500 ADJUSTED: 14200 WEIGHBRIDGE: 14000				
PM133	XQ86MI	00054774	14/03/2023	GEN		AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
PM133	XQ86MI	00054780	14/03/2023	GEN	39	Travel to site. Diagnose A/C system, Identified faulty condenser fan (cust Remove and replace fan. Check A/C pressure and temps, LABEXT		BDSMEC01		
PM133	XQ86MI	00054774	14/03/2023	GEN	39			LABEXT		BDSME
PM133	XQ86MI	00054780	14/03/2023	GEN	39			TRAVEL FEE		BDSME
PM133	XQ86MI	00054774	14/03/2023	GEN	39			TRAVEL FEE		BDSME
PM133	XQ86MI	00054900	20/03/2023	CUMAE5	00	LABOUR MECH 1				
PM133	XQ86MI	00054900	20/03/2023	CUMAE5		SERVICE COMPLETED. ADJUSTED CLUTCH LABOUR				
PM133	XQ86MI	00054900	20/03/2023	CUMAE5	00					
PM133	XQ86MI	00054900	20/03/2023	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00055438	6/04/2023	CUMAE5	00	LABOUR MECH 3				
PM133	XQ86MI	00055438	6/04/2023	CUMAE5		SERVICE COMPLETED.				
PM133	XQ86MI	00055438	6/04/2023	CUMAE5		REPLACED TANK CABLE RHS TANK REPLACED 4 SHC ABSORBER LABOUR APPRENF				
PM133	XQ86MI	00055438	6/04/2023	CUMAE5	00					
PM133	XQ86MI	00055438	6/04/2023	CUMAE5	16			PART	YAT	
PM133	XQ86MI	00055438	6/04/2023	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00055438	6/04/2023	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00055652	18/04/2023	TYRES	15			11006520		BRIAUS

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00055652	18/04/2023	TYRES	15			22001381	
PM133	XQ86MI	00055652	18/04/2023	TYRES	15			33000084	
PM133	XQ86MI	00055652	18/04/2023	TYRES	15			33000241	
PM133	XQ86MI	00055652	18/04/2023	TYRES	15			33000125	
PM133	XQ86MI	00055652	18/04/2023	TYRES	15			33000125	
PM133	XQ86MI	00055652	18/04/2023	TYRES	15			33000241	
PM133	XQ86MI	00055652	18/04/2023	TYRES	15			33000084	
PM133	XQ86MI	00055652	18/04/2023	TYRES	15			22001381	
PM133	XQ86MI	00055652	18/04/2023	TYRES	15			11006520	
PM133	XQ86MI	00055668	19/04/2023	TYRES	15			33000188	
PM133	XQ86MI	00055668	19/04/2023	TYRES	15			33000188	
PM133	XQ86MI	00055769	24/04/2023	CUMAE5	00	LABOUR MECH 3			
PM133	XQ86MI	00055769	24/04/2023	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00055769	24/04/2023	CUMAE5	00	LABOUR APPRENF			
PM133	XQ86MI	00055769	24/04/2023	CUMAE5	16			CON	YAT
PM133	XQ86MI	00056083	8/05/2023	CUMAE5	01	LABOUR MECH			
PM133	XQ86MI	00056083	8/05/2023	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00056083	8/05/2023	CUMBE5	00	LABOUR MECH 3			
PM133	XQ86MI	00056083	8/05/2023	CUMBE5		SERVICE COMPLETED.			
PM133	XQ86MI	00056083	8/05/2023	CUMBE5	00	LABOUR APPRENF			
PM133	XQ86MI	00056083	8/05/2023	CUMBE5	16			MK13584	YAT
PM133	XQ86MI	00056083	8/05/2023	CUMBE5	40			3413005	YAT
PM133	XQ86MI	00056083	8/05/2023	CUMBE5	16			CON	YAT
PM133	XQ86MI	00056372	22/05/2023	CUMAE5	00	LABOUR MECH 3			
PM133	XQ86MI	00056372	22/05/2023	CUMAE5		SERVICE COMPLETED. REPLACE GRILL			
PM133	XQ86MI	00056372	22/05/2023	CUMAE5	00	BOLTS LABOUR APPRENF			
PM133	XQ86MI	00056372	22/05/2023	CUMAE5	16			CON	YAT

PM133	XQ86MI	00056891	2/06/2023	TYRES	15			11004493	
PM133	XQ86MI	00056916	2/06/2023	TYRES	15			33000188	
PM133	XQ86MI	00056891	2/06/2023	TYRES	15			77000180	
PM133	XQ86MI	00056916	2/06/2023	TYRES	15			33000188	
PM133	XQ86MI	00056891	2/06/2023	TYRES	15			33000084	
PM133	XQ86MI	00056891	2/06/2023	TYRES	15			33000517	
PM133	XQ86MI	00056891	2/06/2023	TYRES	15			33000118	
PM133	XQ86MI	00056891	2/06/2023	TYRES	15			11004493	
PM133	XQ86MI	00056891	2/06/2023	TYRES	15			77000180	
PM133	XQ86MI	00056891	2/06/2023	TYRES	15			33000084	
PM133	XQ86MI	00056891	2/06/2023	TYRES	15			33000517	
PM133	XQ86MI	00056891	2/06/2023	TYRES	15			33000118	
PM133	XQ86MI	00056860	5/06/2023	CUMAE5	00	LABOUR MECH 3			
PM133	XQ86MI	00056860	5/06/2023	CUMAE5		SERVICE COMPLETED. DRIVE BRAKES ADJUSTED ABS POWER CHECKD			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00056860	5/06/2023	CUMAE5	00	LABOUR	APPRENF		
PM133	XQ86MI	00056860	5/06/2023	CUMAE5	16			CON	YAT
PM133	XQ86MI	00057494	26/06/2023	CUMAE5	00	LABOUR MECH 1			
PM133	XQ86MI	00057494	26/06/2023	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00057494	26/06/2023	CUMAE5	00	REPLACED HUB SWITCH BEHIND DASH REPAIRED WIRING HANGING DOWN IN PASSENGER \			
PM133	XQ86MI	00057494	26/06/2023	CUMAE5	16			CON	YAT
PM133	XQ86MI	00058018	14/07/2023	ECO	00	LABOUR MECH 1			
PM133	XQ86MI	00058018	14/07/2023	ECO		SERVICE COMPLETED.			
PM133	XQ86MI	00058018	14/07/2023	ECO	00	LABOUR APPRENF			
PM133	XQ86MI	00058018	14/07/2023	ECO	16			CON	YAT
PM133	XQ86MI	00058018	14/07/2023	ECO	40			3413005	YAT
PM133	XQ86MI	00058018	14/07/2023	ECO	06			ED2175254-S	YAT
PM133	XQ86MI	00058021	17/07/2023	CUMAE5	01	LABOUR MECH			
PM133	XQ86MI	00058021	17/07/2023	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00058021	17/07/2023	CUMBE5	00	LABOUR APPRENF			
PM133	XQ86MI	00058021	17/07/2023	CUMBE5		SERVICE COMPLETED.			
PM133	XQ86MI	00058021	17/07/2023	CUMBE5	00	LABOUR MECH 1			
PM133	XQ86MI	00058021	17/07/2023	CUMBE5	16			CON	YAT
PM133	XQ86MI	00058021	17/07/2023	CUMBE5	40			3413005	YAT
PM133	XQ86MI	00058021	17/07/2023	CUMBE5	06			AS2474	YAT
PM133	XQ86MI	00058021	17/07/2023	CUMBE5	11			12PK2380	YAT
PM133	XQ86MI	00058021	17/07/2023	CUMBE5	11			6PK1625	YAT
PM133	XQ86MI	00058021	17/07/2023	CUMBE5	06			LF14000NN	YAT
PM133	XQ86MI	00058021	17/07/2023	CUMBE5	06			FF5776	YAT
PM133	XQ86MI	00058029	17/07/2023	GEN	15			11004493	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			33000125	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			33000084	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			33000241	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			33000237	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			33000237	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			33000237	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			33000237	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			11004493	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			33000125	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			33000084	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			33000241	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			33000237	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			33000237	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			33000237	
PM133	XQ86MI	00058029	17/07/2023	GEN	15			33000237	
PM133	XQ86MI	00058115	17/07/2023	TYRES	15			33000096	
PM133	XQ86MI	00058117	17/07/2023	TYRES	15			33000096	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00058115	17/07/2023	TYRES	15			33000096	
PM133	XQ86MI	00058117	17/07/2023	TYRES	15			33000118	
PM133	XQ86MI	00058117	17/07/2023	TYRES	15			33000096	
PM133	XQ86MI	00058117	17/07/2023	TYRES	15			33000118	

PM133	XQ86MI	00058132	18/07/2023	GEN	14			MF70ZZD	
PM133	XQ86MI	00058132	18/07/2023	GEN	39			BREAKDOWN	
PM133	XQ86MI	00058132	18/07/2023	GEN	39			CON	
PM133	XQ86MI	00058132	18/07/2023	GEN	14			MF70ZZD	
PM133	XQ86MI	00058132	18/07/2023	GEN	39			BREAKDOWN	
PM133	XQ86MI	00058132	18/07/2023	GEN	39			CON	
PM133	XQ86MI	00058449	31/07/2023	CUMAE5	00	LABOUR MECH 3			
PM133	XQ86MI	00058449	31/07/2023	CUMAE5		SERVICE COMPLETED.			
						A-SERVICE ADJUST DRIVE BRAKES TOP UP COOLANT REAFFIX LOOSE STACK PIPE. LABOUR APPRENF			
PM133	XQ86MI	00058449	31/07/2023	CUMAE5	00				
PM133	XQ86MI	00058449	31/07/2023	CUMAE5	16		CON	YAT	
PM133	XQ86MI	00058549	2/08/2023	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00058549	2/08/2023	DEFECT					
PM133	XQ86MI	00058549	2/08/2023	DEFECT		DEFECT CLEARED BY FLYNN ON 02/08/2023.			
PM133	XQ86MI	00058549	2/08/2023	DEFECT		TIGHTENED BOLTS ON STACK. Reported Defect :-			
						Defect Code : 00009609 Defect Reference : 08543 Date : 0 Description of Defect : STACK IS A LITTLE LOOSE LABOUR APPRENF			
PM133	XQ86MI	00058549	2/08/2023	GEN	00				
PM133	XQ86MI	00058549	2/08/2023	GEN		REPAIR COMPLETED BY FLYNN ON 02/08/2023.			
PM133	XQ86MI	00058549	2/08/2023	GEN	16	TIGHTENED BOLTS ON STACK. CON YAT			
PM133	XQ86MI	00058845	14/08/2023	CUMAE5	01	LABOUR MECH 3			
PM133	XQ86MI	00058845	14/08/2023	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00058845	14/08/2023	CUMAE5	00	LABOUR APPRENF			
PM133	XQ86MI	00058845	14/08/2023	CUMAE5	16		CON	YAT	
PM133	XQ86MI	00058845	14/08/2023	CUMAE5	40		3413005	YAT	
PM133	XQ86MI	00059353	23/08/2023	WEICAL		AIR GAUGE: 16250 ADJUSTED: 16250 WEIGHBRIDGE: 15900			

AIR GAUGE CALIBRATION COMPLETED CORRECTLY.

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00059481	4/09/2023	CUMAE5	01	LABOUR APPREN			
PM133	XQ86MI	00059481	4/09/2023	CUMAE5		SERVICE COMPLETED BY TYLER & FLYNN ON 02/09/2			
PM133	XQ86MI	00059481	4/09/2023	CUMAE5	00	LABOUR APPRENF			
PM133	XQ86MI	00059481	4/09/2023	CUMAE5	16			CON	YAT
PM133	XQ86MI	00059737	6/09/2023	GEN	39			82536	
PM133	XQ86MI	00059737	6/09/2023	GEN	39			82536	
PM133	XQ86MI	00060145	25/09/2023	CUMAE5	01	LABOUR MECH			
PM133	XQ86MI	00060145	25/09/2023	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00060145	25/09/2023	CUMBE5	01	LABOUR APPREN			
PM133	XQ86MI	00060145	25/09/2023	CUMBE5		SERVICE COMPLETED BY TYLER, MATT & BEN ON 23/			
PM133	XQ86MI	00060145	25/09/2023	CUMBE5	00	LABOUR MECH 3			
PM133	XQ86MI	00060145	25/09/2023	CUMBE5	00	LABOUR APPRENB			
PM133	XQ86MI	00060145	25/09/2023	CUMBE5	16			CON	YAT
PM133	XQ86MI	00060145	25/09/2023	CUMBE5	06			MK13584	YAT
PM133	XQ86MI	00060145	25/09/2023	CUMBE5	40			3413005	YAT
PM133	XQ86MI	00060145	25/09/2023	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00060145	25/09/2023	DEFECT					
PM133	XQ86MI	00060145	25/09/2023	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00060576	9/10/2023	CUMAE5	01	LABOUR MECH 3			
PM133	XQ86MI	00060576	9/10/2023	CUMAE5		SERVICE COMPLETED BY MATT & FLYNN ON 09/10/20			
PM133	XQ86MI	00060576	9/10/2023	CUMAE5	00	LABOUR APPRENF			
PM133	XQ86MI	00060576	9/10/2023	CUMAE5	16			CON	YAT
PM133	XQ86MI	00060576	9/10/2023	DEFECT	01	LABOUR MECH			

PM133	XQ86MI	00060577	9/10/2023	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00060578	9/10/2023	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00060836	9/10/2023	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00060576	9/10/2023	DEFECT						
PM133	XQ86MI	00060577	9/10/2023	DEFECT						
PM133	XQ86MI	00060578	9/10/2023	DEFECT						
PM133	XQ86MI	00060836	9/10/2023	DEFECT						
PM133	XQ86MI	00060576	9/10/2023	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00060577	9/10/2023	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00060578	9/10/2023	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00060836	9/10/2023	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00060577	9/10/2023	ECO	01	LABOUR APPRENF				
PM133	XQ86MI	00060577	9/10/2023	ECO		SERVICE COMPLETED BY FLYNN ON 09/10/2023.				
PM133	XQ86MI	00060577	9/10/2023	ECO	16			CON	YAT	
PM133	XQ86MI	00060577	9/10/2023	ECO	40			3413005	YAT	
PM133	XQ86MI	00060577	9/10/2023	ECO	06			ED2175254-S	YAT	
PM133	XQ86MI	00060578	9/10/2023	GEN	39	LABOUR MECH 1				
PM133	XQ86MI	00060836	9/10/2023	GEN	01	LABOUR APPRENB				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00060578	9/10/2023	GEN		REPAIR COMPLETED BY MATT ON 09/10/2023.				
PM133	XQ86MI	00060836	9/10/2023	GEN		DISASSEMBLE AND CLEAN - INSPECT AND REASSEMB MIDLIFE SERVICE COMPLETED BY BEN ON 09/10/2023.				
PM133	XQ86MI	00060578	9/10/2023	GEN	16			CON	YAT	
PM133	XQ86MI	00060836	9/10/2023	GEN	03			5607734RX	YAT	
PM133	XQ86MI	00060578	9/10/2023	GEN	12			43764	YAT	
PM133	XQ86MI	00060836	9/10/2023	GEN	03			3690864RX	YAT	
PM133	XQ86MI	00060578	9/10/2023	GEN	12			453795	YAT	
PM133	XQ86MI	00060836	9/10/2023	GEN	03			5273337RX	YAT	
PM133	XQ86MI	00060836	9/10/2023	GEN	03			275707	YAT	
PM133	XQ86MI	00060836	9/10/2023	GEN	03			5440813	YAT	
PM133	XQ86MI	00060836	9/10/2023	GEN	03			2866337	YAT	
PM133	XQ86MI	00060836	9/10/2023	GEN	16			CON	YAT	
PM133	XQ86MI	00060669	11/10/2023	GEN	15			11004496		
PM133	XQ86MI	00060669	11/10/2023	GEN	15			77000194		
PM133	XQ86MI	00060669	11/10/2023	GEN	15			33000084		
PM133	XQ86MI	00060669	11/10/2023	GEN	15			33000517		
PM133	XQ86MI	00060669	11/10/2023	GEN	15			33000118		
PM133	XQ86MI	00060669	11/10/2023	GEN	15			33000540		
PM133	XQ86MI	00060669	11/10/2023	GEN	15			11004496		
PM133	XQ86MI	00060669	11/10/2023	GEN	15			77000194		
PM133	XQ86MI	00060669	11/10/2023	GEN	15			33000084		
PM133	XQ86MI	00060669	11/10/2023	GEN	15			33000517		
PM133	XQ86MI	00060669	11/10/2023	GEN	15			33000118		
PM133	XQ86MI	00060669	11/10/2023	GEN	15			33000540		
PM133	XQ86MI	00060921	18/10/2023	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00060921	18/10/2023	DEFECT						
PM133	XQ86MI	00060921	18/10/2023	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00060921	18/10/2023	GEN	39	LABOUR MECH 3				
PM133	XQ86MI	00060921	18/10/2023	GEN		REPAIR COMPLETED BY MATT & FLYNN ON 18/10/202				
PM133	XQ86MI	00060921	18/10/2023	GEN	00	LABOUR APPRENF				
PM133	XQ86MI	00060921	18/10/2023	GEN	16			CON	YAT	
PM133	XQ86MI	00060953	21/10/2023	CUMAE5	01	LABOUR MECH 3				
PM133	XQ86MI	00060953	21/10/2023	CUMAE5		SERVICE COMPLETED BY MATT & FLYNN ON 21/10/20 REPAIRED INDICATOR PARK CIRCUIT AND ALSO RUBBED TH				
PM133	XQ86MI	00060953	21/10/2023	CUMAE5	00	LABOUR APPRENF				
PM133	XQ86MI	00060953	21/10/2023	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00060953	21/10/2023	CUMAE5	14			2110-24V	YAT	
PM133	XQ86MI	00060953	21/10/2023	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00060953	21/10/2023	DEFECT						

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00060953	21/10/2023	DEFECT		DEFECT	CLEARED.		

PM133	XQ86MI	00061214	24/10/2023	GEN	39					0A5801F1F1A0A
PM133	XQ86MI	00061214	24/10/2023	GEN	39					AW-IVU-TRANS
PM133	XQ86MI	00061214	24/10/2023	GEN	39					AW-BYPASS-12
PM133	XQ86MI	00061214	24/10/2023	GEN	39					AW-AIR-KW
PM133	XQ86MI	00061214	24/10/2023	GEN	39					AWIMM TRUCK
PM133	XQ86MI	00061214	24/10/2023	GEN	39					0A5801F1F1A0A
PM133	XQ86MI	00061214	24/10/2023	GEN	39					AW-IVU-TRANS
PM133	XQ86MI	00061214	24/10/2023	GEN	39					AW-BYPASS-12
PM133	XQ86MI	00061214	24/10/2023	GEN	39					AW-AIR-KW
PM133	XQ86MI	00061214	24/10/2023	GEN	39					AWIMM TRUCK
PM133	XQ86MI	00070486	26/10/2023	WEICAL		CALIBRATED BY NATHAN BENNETT 26/10/2023 AIR GAUGE: ADJUSTED: WEIGHBRIDGE: AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
PM133	XQ86MI	00061957	16/11/2023	CUMCE5	01	LABOUR MECH 3				
PM133	XQ86MI	00061957	16/11/2023	CUMCE5		SERVICE COMPLETED BY MATT, TYLER, FLYNN & JOS TEMP GAUGE BOLT WAS LOOSE. TIGHTENED IT UP N				
PM133	XQ86MI	00061957	16/11/2023	CUMCE5	00	DEFECT NOTED: REQUIRES TRACTOR PROTECTION LABOUR APPREN				
PM133	XQ86MI	00061957	16/11/2023	CUMCE5	00	LABOUR APPRENJ				
PM133	XQ86MI	00061957	16/11/2023	CUMCE5	00	LABOUR APPRENF				
PM133	XQ86MI	00061957	16/11/2023	CUMCE5	16			CON	YAT	
PM133	XQ86MI	00061957	16/11/2023	CUMCE5	06			WF2127	YAT	
PM133	XQ86MI	00061957	16/11/2023	CUMCE5	06			T224P		YAT
PM133	XQ86MI	00061957	16/11/2023	CUMCE5	06			A-3380W1687	YAT	
PM133	XQ86MI	00061957	16/11/2023	CUMCE5	06			17237	YAT	
PM133	XQ86MI	00061956	16/11/2023	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00061957	16/11/2023	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00061967	16/11/2023	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00061956	16/11/2023	DEFECT						
PM133	XQ86MI	00061957	16/11/2023	DEFECT						
PM133	XQ86MI	00061967	16/11/2023	DEFECT						
PM133	XQ86MI	00061956	16/11/2023	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00061957	16/11/2023	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00061967	16/11/2023	DEFECT		DEFECT CLEARED.				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00061957	16/11/2023	DEFECT		Reported Defect :-Defect Code : 00009828 Defect Reference : 00059481 Date : 02/09/2023 Descriptic				
PM133	XQ86MI	00061957	16/11/2023	DEFECT		DEFECT CHECKED BY MATT ON 16/11/2023 NOTED: M Reported Defect :- Defect Code : 00009992 Defect Reference : 00060145 Dat NEEDS A JAW KIT NEXT SERVICE				
PM133	XQ86MI	00061957	16/11/2023	DEFECT		DEFECT CLEARED 16/11/2023 NO MOVEMENT EVIDEN Reported Defect :- Defect Code : 00009995 Defect Reference : 36861 Date : 2 COOLANT TEMP GAUGE NOT WORKING				

						DEFECT CLEARED ON 16/11/2023
PM133	XQ86MI	00061956	16/11/2023	ECO	01	LOOSE TERMINAL CAUSED LOOSE CONNECTION RES
						Labour
PM133	XQ86MI	00061956	16/11/2023	ECO		SERVICE COMPLETED BY JOSEPH & TYLER ON 16/11/
PM133	XQ86MI	00061956	16/11/2023	ECO	00	LABOUR APPREN
PM133	XQ86MI	00061956	16/11/2023	ECO	06	0021751550 YAT
PM133	XQ86MI	00061956	16/11/2023	ECO	06	ED0037300960 YAT
PM133	XQ86MI	00061956	16/11/2023	ECO	06	ED2175254-S YAT
PM133	XQ86MI	00061956	16/11/2023	ECO	06	FS1251 YAT
PM133	XQ86MI	00061956	16/11/2023	ECO	40	10W50 YAT
PM133	XQ86MI	00061956	16/11/2023	ECO	16	CON YAT
PM133	XQ86MI	00061967	16/11/2023	EXOINS	01	LABOUR MECH 3
PM133	XQ86MI	00061967	16/11/2023	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECTIO

1ST INSPECTION COMPLETED BY MATT, TYLER & FLYNN ON
NOTED UPON FIRST INSPECTION - GAUGE SENDER LOOSE \

2ND INSPECTION COMPLETED BY MATT, TYLER & FLYNN ON

PM133	XQ86MI	00061967	16/11/2023	EXOINS	00			LABOUR APPREN	
PM133	XQ86MI	00061967	16/11/2023	EXOINS	00			LABOUR APPRENF	
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00062409	28/11/2023	GEN	39			LABEXT	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			LBP2189GH	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			3682249	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			3691283	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			D84-1000-31223	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			CC36084	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			TRAVEL FEE	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			CON	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			FREIGHT	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			LABEXT	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			LBP2189GH	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			3682249	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			3691283	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			D84-1000-31223	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			CC36084	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			TRAVEL FEE	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			CON	
PM133	XQ86MI	00062409	28/11/2023	GEN	39			FREIGHT	
PM133	XQ86MI	00062845	9/12/2023	GEN	39			LABEXT	
PM133	XQ86MI	00062845	9/12/2023	GEN	14			BATTERY	
PM133	XQ86MI	00062845	9/12/2023	GEN	16			CON	
PM133	XQ86MI	00062845	9/12/2023	GEN	39			LABEXT	
PM133	XQ86MI	00062845	9/12/2023	GEN	14			BATTERY	
PM133	XQ86MI	00062845	9/12/2023	GEN	16			CON	
PM133	XQ86MI	00063283	29/12/2023	GEN	39			LABEXT	
PM133	XQ86MI	00063283	29/12/2023	GEN	17			PART	
PM133	XQ86MI	00063283	29/12/2023	GEN	17			MUDFLAP	
PM133	XQ86MI	00063283	29/12/2023	GEN	16			CON	
PM133	XQ86MI	00063283	29/12/2023	GEN	16			CON	
PM133	XQ86MI	00063283	29/12/2023	GEN	17			MUDFLAP	
PM133	XQ86MI	00063283	29/12/2023	GEN	16			CON	
PM133	XQ86MI	00063283	29/12/2023	GEN	39			LABEXT	
PM133	XQ86MI	00063283	29/12/2023	GEN	17			PART	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00063283	29/12/2023	GEN	17			MUDFLAP	
PM133	XQ86MI	00063283	29/12/2023	GEN	16			CON	
PM133	XQ86MI	00063283	29/12/2023	GEN	16			CON	
PM133	XQ86MI	00063283	29/12/2023	GEN	17			MUDFLAP	
PM133	XQ86MI	00063283	29/12/2023	GEN	16			CON	
PM133	XQ86MI	00063218	3/01/2024	CUMAE5	01	LABOUR MECH			
PM133	XQ86MI	00063218	3/01/2024	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00063218	3/01/2024	CUMBE5	01	LABOUR MECH 3			
PM133	XQ86MI	00063218	3/01/2024	CUMBE5		SERVICE COMPLETED BY MATT, TYLER & AARON ON			
						GOVERNOR VALVE REPLACED & AIR SUPPLY SYSTEI CARRIED OUT			
						NOTED: FRONT DIFF OUTPUT SHAFT SEAL REQUIRES REPL/ DEFECT NO. 00010584 CREATED			
PM133	XQ86MI	00063218	3/01/2024	CUMBE5	00	LABOUR APPREN			
PM133	XQ86MI	00063218	3/01/2024	CUMBE5	00	LABOUR MECH 4			
PM133	XQ86MI	00063218	3/01/2024	CUMBE5	16			CON	YAT
PM133	XQ86MI	00063218	3/01/2024	CUMBE5	03			275707	YAT
PM133	XQ86MI	00063218	3/01/2024	CUMBE5	06			T224P	YAT
PM133	XQ86MI	00063218	3/01/2024	CUMBE5	06			MK13584	YAT
PM133	XQ86MI	00063218	3/01/2024	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00063218	3/01/2024	DEFECT					
PM133	XQ86MI	00063218	3/01/2024	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00063218	3/01/2024	DEFECT		Reported Defect :-Defect Code : 00009828 Defect Reference : 00059481 Date : 02/09/2023 Descriptic			
						DEFECT CHECKED BY MATT ON 16/11/2023 NOTED MI			
PM133	XQ86MI	00064065	8/01/2024	DEFECT	01	DEFECT CLEARED 03/01/2023 NOT DONE BUT NEW DEFECT CREATED IN PLACE OF LABOUR MECH			
PM133	XQ86MI	00064065	8/01/2024	DEFECT					
PM133	XQ86MI	00064065	8/01/2024	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00064065	8/01/2024	GEN	39	LABOUR			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00064065	8/01/2024	GEN		REPAIR COMPLETED 08/01/2024				

Blown turbo - customer charge items

Part Number Part Description Quantity Total Cost QFC72910 CHARG
FREIGHT FREIGHT 1.00 35.00
K264-84 GROMMET-TIE ROD,RAD 1.00 18.88
DCT110H1RW-10P CABLE TIE BRAKE HOSE (10PK) 1.00 49.00 BI
3539458 CLAMP V BAND 1.00 205.10
3606847 CLAMP V BAND 1.00 171.47
3391271 LUBRIPLATE 105 GREASE 10OZ TBE 1.00 17.32
L0C51531 LOCTITE 515 FLEXIBLE MASTER 1.00 30.56
3413003 VECTON 15W-40 CK-4/E9 20L AZ 2.00 268.46
L0C34238 LOCTITE 5699 GREY MAXX 1.00 18.80 6PK1590 DAYCO
Parts Totals: 14.00 $6,112.73

Warranty Repairs/Service At No Charge PROMO ID: 1334858
***EXTENDED COVERAGE CERT NO: 12905 ***
Connected Insite and followed troubleshooting for Turbocharger Noise
Lower Bull bar
Restricted intake air filter: Visually inspect vehicle intake system for bl
air intake system for leak ? leak found. Visually
inspect air compressor plumbing for possible air leaks. Visually inspe
? Leak found. Visually inspect the intake plumbing for possible leaks
possible air leaks ? Leak found. Pressure test the charge air cooler to
Leaks in the exhaust system: YES Turbocharger is malfunctioning:

Warranty Repairs/Service At No Charge
Removed CAC hoses and air intake manifold, removed all exhaust pi
Found exhaust system full of oil contaminating the EGP. Removed an
AC amount of 1.47kg. Removed front grill to allow for removal of cond
followed by condenser and shroud. Removed valve cover and drained
the engine. Checked for metal contamination in the oil. Removed and
Cummins procedure, a full main bearing replacement and oil cooler re
Removed coolant
transfer pipe, removed oil cooler housing, replaced oil cooler element

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C

thermostat and O-ring.
Replaced oil cooler housing gasket. Refitted housing with new oil c
with new O?rings. Installed new turbo with new gaskets and O-rings
Installed new pyro
sensor and AFT injector due to the compressor wheel causing dam
due to contamination, all metal pieces were flushed through the hot
pickup before having to weld nuts on the end of the stiffener plate b
Removed sump gasket. Clean lubricating oil pan. Remove and insp
rod bearings ? replaced components. As per Cummins procedure,
lubriplate on new bearings and thrust washer. Followed Cummins p
Measured crank end clearance and within specs. Measured idler ar
found pitting in gears, as per Cummins procedure, replaced oil pum
new oil pump, torqued bolts. Refitted stiffener plate with new bolts.
Re-installed oil sump with new
gasket and Greymaxx on the corners. Tied up all harnesses under
Vectron oil and fitted grill. R&R air cleaner. Fitted grommet in front
injector rail plug and cranked. Refitted plug and started truck. Ran f
Flexi piece of exhaust due to oil contamination and refitted all rema
receiver/dryer. Full QA as per workshop procedure. Road test vehic
CLAIM# 871625
Workshop Sublet - 512004- Claytons Towing

PM133	XQ86MI	00064065	8/01/2024	GEN	39			K264-84		
PM133	XQ86MI	00064065	8/01/2024	GEN	39			QFC72910		
PM133	XQ86MI	00064065	8/01/2024	GEN	39			FREIGHT		
PM133	XQ86MI	00064065	8/01/2024	GEN	39			DCT110H1RW-1		
PM133	XQ86MI	00064065	8/01/2024	GEN	39			CON		
PM133	XQ86MI	00064065	8/01/2024	GEN	39			3606847		
PM133	XQ86MI	00064065	8/01/2024	GEN	39			3413003		
PM133	XQ86MI	00064065	8/01/2024	GEN	39			6PK1590		
PM133	XQ86MI	00064065	8/01/2024	GEN	39			CON		

PM133	XQ86MI	00064065	8/01/2024	GEN	39			CON	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			3539458	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			3391271	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			LOC51531	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00064065	8/01/2024	GEN	39			K264-84	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			QFC72910	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			FREIGHT	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			DCT110H1RW-1	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			CON	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			3606847	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			3413003	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			6PK1590	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			CON	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			CON	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			3539458	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			3391271	
PM133	XQ86MI	00064065	8/01/2024	GEN	39			LOC51531	
PM133	XQ86MI	00065006	27/02/2024	GEN	03			PART	
PM133	XQ86MI	00065006	27/02/2024	GEN	03			PART	
PM133	XQ86MI	00065006	27/02/2024	GEN	03			PART	
PM133	XQ86MI	00065006	27/02/2024	GEN	03			PART	
PM133	XQ86MI	00065006	27/02/2024	GEN	03			PART	
PM133	XQ86MI	00065006	27/02/2024	GEN	03			PART	
PM133	XQ86MI	00065288	8/03/2024	CUMAE5	01	LABOUR MECH			
PM133	XQ86MI	00065288	8/03/2024	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00065288	8/03/2024	CUMBE5	01	LABOUR MECH 4			
PM133	XQ86MI	00065288	8/03/2024	CUMBE5		SERVICE COMPLETED BY ETHAN & NICK ON 08/03/202			
PM133	XQ86MI	00065288	8/03/2024	CUMBE5	00	BELLY BAR BOLTS AS THEY WERE LOOSE. RETIGHTE GRILL AS ALL BOLTS LOOSE REMOVED AND REPLAC IT'S PERISHING. LABOUR MECH 1			
PM133	XQ86MI	00065288	8/03/2024	CUMBE5	16			CON	YAT
PM133	XQ86MI	00065288	8/03/2024	CUMBE5	11			12PK2380	YAT
PM133	XQ86MI	00065288	8/03/2024	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00065288	8/03/2024	DEFECT					
PM133	XQ86MI	00065288	8/03/2024	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00065685	20/03/2024	GEN	15			11006520	BI
PM133	XQ86MI	00065685	20/03/2024	GEN	15			33000084	BI
PM133	XQ86MI	00065685	20/03/2024	GEN	15			33000370	BI
PM133	XQ86MI	00065685	20/03/2024	GEN	15			33000518	BI
PM133	XQ86MI	00065685	20/03/2024	GEN	15			33000118	BI
PM133	XQ86MI	00065685	20/03/2024	GEN	15			11006520	BI
PM133	XQ86MI	00065685	20/03/2024	GEN	15			33000084	BI
PM133	XQ86MI	00065685	20/03/2024	GEN	15			33000370	BI
PM133	XQ86MI	00065685	20/03/2024	GEN	15			33000518	BI
PM133	XQ86MI	00065685	20/03/2024	GEN	15			33000118	BI
PM133	XQ86MI	00065937	27/03/2024	CUMAE5	01	LABOUR MECH			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00065937	27/03/2024	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	01	LABOUR MECH			
PM133	XQ86MI	00065937	27/03/2024	CUMBE5		SERVICE COMPLETED BY BROWN & HURLEY BOHLE 3165262			

Complete Exodas B Service Sheet
Defects found
-Through shaft weeping found blocked breather washed and test dr
-Drive shaft slip joint seal cover has failed on front driveshaft.
-Gearbox airlines leaking. Installed 5/32s brass push fittings as requ
-Engine filler tube hose weeping.
-Rear cab mounts worn

HORTON FAN STUCK ON
Labour:
Cause: No issues found Correction:
- Shut ac off and disconnected ac pressure switch to confirm switch
- Reconnected pressure switch and shook harness trying to get fan
- Connected ac machine and monitored pressures found no issues.
- Test drove truck to see if fan would come on using insite to monitc

BURNING OIL SMELL - NOT SURE WHERE COMING FROM
Labour:
Cause: Could not locate burnt oil smell Correction:
- Looked over truck for obvious leaks
Test drove truck to see if I could get the burnt oil smell to occur - di

PM133	XQ86MI	00065937	27/03/2024	CUMBE5	01			LABEXT	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	06			LF14000NN	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	06			FF5776	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	06			FS19764	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	06			AS2474	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	40			3413005	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	16			GREASE	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	16			84103	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	06			AF1969M	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	39			LABEXT	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	39			LABEXT	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	16			CON	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	16			ENVLEV	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	01			LABEXT	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	06			LF14000NN	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	06			FF5776	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	06			FS19764	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	06			AS2474	BI
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	40			3413005	BI

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	16			GREASE	
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	16			84103	
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	06			AF1969M	
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	39			LABEXT	
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	39			LABEXT	
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	16			CON	
PM133	XQ86MI	00065937	27/03/2024	CUMBE5	16			ENVLEV	
PM133	XQ86MI	00065937	27/03/2024	DEFECT	01	LABOUR	MECH		
PM133	XQ86MI	00065937	27/03/2024	DEFECT					
PM133	XQ86MI	00065937	27/03/2024	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00066759	30/04/2024	CUMAE5	01	LABOUR MECH			
PM133	XQ86MI	00066759	30/04/2024	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00066759	30/04/2024	CUMBE5	01	LABOUR APPRENJ			
PM133	XQ86MI	00066759	30/04/2024	CUMBE5		'B' SERVICE COMPLETED BY JOSEPH, BEN, TYLER & I			
PM133	XQ86MI	00066759	30/04/2024	CUMBE5	00	HORTON FAN KIT AS FAN WAS SLIPPING REPLACED WORN REPLACED BOTH HEAD LIGHTS DRIVE HUBS ARE GO A/C HAS BEEN DONE LABOUR APPRENB			
PM133	XQ86MI	00066759	30/04/2024	CUMBE5	00	LABOUR APPREN			
PM133	XQ86MI	00066759	30/04/2024	CUMBE5	00	LABOUR MECH 4			
PM133	XQ86MI	00066759	30/04/2024	CUMBE5	16			CON	YAT
PM133	XQ86MI	00066759	30/04/2024	CUMBE5	13			WDH-7R7HM-CR	YAT
PM133	XQ86MI	00066759	30/04/2024	CUMBE5	06			MK13584	YAT
PM133	XQ86MI	00066759	30/04/2024	CUMBE5	03			F35008SD	YAT
PM133	XQ86MI	00066759	30/04/2024	CUMBE5	03			SK3321-50	YAT
PM133	XQ86MI	00066759	30/04/2024	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00066760	30/04/2024	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00066759	30/04/2024	DEFECT					
PM133	XQ86MI	00066760	30/04/2024	DEFECT					
PM133	XQ86MI	00066759	30/04/2024	DEFECT		DEFECT CLEARED.			

PM133	XQ86MI	00066760	30/04/2024	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00066759	30/04/2024	DEFECT		Reported Defect :- Defect Code : 00010939 Defect Reference : 08549 Date : 15/02/2024 Description of Defect : DUE FOR SERVICE				
						DEFECT CLEARED ON 30/04/2024 SERVICE CARRIED OUT				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00066759	30/04/2024	DEFECT		Reported Defect :-Defect Code : 00010940 Defect Reference : 08550 Date : 15/02/2024 Description of LEFT DRIVE STEER HUB LEAKING OIL			
PM133	XQ86MI	00066759	30/04/2024	DEFECT		DEFECT CLEARED ON 30/04/2024 DRIVE HUBS ARE GOOD Reported Defect :- Defect Code : 00011193 Defect Reference : 68504 Date : 23/03/2024 Description of Defect : WATER IN HEADLIGHT BULB			
PM133	XQ86MI	00066759	30/04/2024	DEFECT		DEFECT CLEARED ON 30/04/2024 REPLACED BOTH HEAD LIGHTS Reported Defect :- Defect Code : 00011195 Defect Reference : 68506 Date : 23/03/2024 Description of Defect : A/C HEATER DOESN'T WORK			
PM133	XQ86MI	00066760	30/04/2024	ECO	01	DEFECT CLEARED ON 30/04/2024 A/C HAS BEEN DONE LABOUR APPRENJ			
PM133	XQ86MI	00066760	30/04/2024	ECO		SLEEPER AIR SERVICE COMPLETED BY JOSEPH & ETHAN ON 3			
PM133	XQ86MI	00066760	30/04/2024	ECO	00	LABOUR MECH 4			
PM133	XQ86MI	00066760	30/04/2024	ECO	16			CON	YAT
PM133	XQ86MI	00066760	30/04/2024	ECO	40			10W50	YAT
PM133	XQ86MI	00066760	30/04/2024	ECO	06			ED002175254-S	YAT
PM133	XQ86MI	00067604	29/05/2024	CUMAE5	01	LABOUR MECH 5			
PM133	XQ86MI	00067604	29/05/2024	CUMAE5		'A' SERVICE COMPLETED BY BEN & JOSEPH ON 29/05			
PM133	XQ86MI	00067604	29/05/2024	CUMAE5		VALVE. RUNNING FINE. REPLACED HEATER TAP BEHIND TURBO			
					00	LABOUR APPRENJ			
PM133	XQ86MI	00067604	29/05/2024	CUMAE5	16			CON	YAT
PM133	XQ86MI	00067604	29/05/2024	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00067604	29/05/2024	DEFECT					
PM133	XQ86MI	00067604	29/05/2024	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00067604	29/05/2024	DEFECT		Reported Defect :-Defect Code : 00010307 Defect Reference : PM133 Date : 16/11/2023 Description o REQUIRES TRACTOR PROTECTION VALVE				
PM133	XQ86MI	00068037	10/06/2024	CUMAE5	01	DEFECT CLEARED ON 29/05/2024 TESTED TRACTOR LABOUR MECH 1				
PM133	XQ86MI	00068037	10/06/2024	CUMAE5		'A' SERVICE COMPLETED BY NICK & JOSEPH ON 10/0				
PM133	XQ86MI	00068037	10/06/2024	CUMAE5	00	BLADES LABOUR APPRENJ				
PM133	XQ86MI	00068037	10/06/2024	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00068037	10/06/2024	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00068037	10/06/2024	DEFECT						
PM133	XQ86MI	00068037	10/06/2024	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00068831	1/07/2024	CUMAE5	01	LABOUR MECH 6				
PM133	XQ86MI	00068831	1/07/2024	CUMAE5		SERVICE COMPLETED BY WORKSHOP 01/07/2024				

							ADDED 4L ENGINE OIL ADDED 4L OF COOLANT FIXED A COUPLE OF AIRLEAKS CHANGED OUT WIPEI			
PM133	XQ86MI	00068831	1/07/2024	CUMAE5	00					
PM133	XQ86MI	00068831	1/07/2024	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00068831	1/07/2024	CUMAE5	40			3413005	YAT	
PM133	XQ86MI	00068831	1/07/2024	DEFECT	01		LABOUR MECH			
PM133	XQ86MI	00068831	1/07/2024	DEFECT						
PM133	XQ86MI	00068831	1/07/2024	DEFECT			DEFECT CLEARED.			
PM133	XQ86MI	00069003	8/07/2024	CUMAE5	01		LABOUR MECH			
PM133	XQ86MI	00069003	8/07/2024	CUMAE5			SERVICE COMPLETED.			
PM133	XQ86MI	00069003	8/07/2024	CUMBE5	01		LABOUR MECH 1			
PM133	XQ86MI	00069003	8/07/2024	CUMBE5			"B" SERVICE COMPLETED BY WORKSHOP 08/07/2024.			
PM133	XQ86MI	00069003	8/07/2024	CUMBE5	00		REPLACED REDIATOR STAY RUBBERS REPAIRED W/ MECH 6			
PM133	XQ86MI	00069003	8/07/2024	CUMBE5	16			CON	YAT	
PM133	XQ86MI	00069003	8/07/2024	CUMBE5	40			3413005	YAT	
PM133	XQ86MI	00069003	8/07/2024	CUMBE5	06			LF14000NN	YAT	
PM133	XQ86MI	00069003	8/07/2024	CUMBE5	06			FF5776	YAT	
PM133	XQ86MI	00069003	8/07/2024	CUMBE5	06			AS2474	YAT	
PM133	XQ86MI	00069003	8/07/2024	DEFECT	01		LABOUR MECH			
PM133	XQ86MI	00069003	8/07/2024	DEFECT						
PM133	XQ86MI	00069003	8/07/2024	DEFECT			DEFECT CLEARED.			
PM133	XQ86MI	00069179	11/07/2024	DEFECT	01		LABOUR MECH			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00069179	11/07/2024	DEFECT						
PM133	XQ86MI	00069179	11/07/2024	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00069179	11/07/2024	GEN		REPAIR COMPLETED BY ONTRACK AUTO ELECTRICAL INV-8818				
						Travelled to site. Fitted AC gauges to system. System was operational and c fan was not working. Lifted cab and tested for power, fan had power no operatior Re-fitted AC condenser fan. Tested operation of AC, system cycling and cold. Examined charge rate of another truck sleeper in yard in ya				
						LABEXT		ONTRAC01	EX00035284	Lab
PM133	XQ86MI	00069179	11/07/2024	GEN	39					
PM133	XQ86MI	00069179	11/07/2024	GEN	39			diagnose a/c not working. remove LABEXT	ONTRA	
PM133	XQ86MI	00069147	12/07/2024	DEFECT	01	diagnose a/c not working. removed & replaced fan., LABOUR MECH				
PM133	XQ86MI	00069147	12/07/2024	DEFECT						
PM133	XQ86MI	00069147	12/07/2024	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00069147	12/07/2024	GEN	39	LABOUR MECH 4				
PM133	XQ86MI	00069147	12/07/2024	GEN		REPAIR COMPLETED BY WORKSHOP 12/07/2024				
						REMOVED AND STRAIGHTEND RHS TANK CHROME GUARD A REPLACED 2 X TANK STARPS				
PM133	XQ86MI	00069147	12/07/2024	GEN	16			CON	YAT	
PM133	XQ86MI	00069648	2/08/2024	CUMAE5	01	LABOUR MECH 4				
PM133	XQ86MI	00069648	2/08/2024	CUMAE5		'A' SERVICE COMPLETED BY ETHAN, JOSEPH, NICK & ALEX ON				
						REPLACED LIGHT PLUG DUE TO DAMAGE REPAIRED CONTROL VALVE TIGHTENED BELLY BAR BOLTS REPACED OLVIE & SPIGOT TO THE HEIGHT CONTROI PLATE ON THE RHS REAR LABOUR APPRENJ				
PM133	XQ86MI	00069648	2/08/2024	CUMAE5	00					
PM133	XQ86MI	00069648	2/08/2024	CUMAE5	00	LABOUR MECH 1				
PM133	XQ86MI	00069648	2/08/2024	CUMAE5	00	LABOUR APPRENA				
PM133	XQ86MI	00069648	2/08/2024	CUMAE5	16			CON	YAT	
PM133	XQ86MI	00069648	2/08/2024	CUMAE5	31			82161/25	YAT	

PM133	XQ86MI	00069648	2/08/2024	CUMAE5	40			3413005	YAT
PM133	XQ86MI	00069648	2/08/2024	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00069649	2/08/2024	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00069648	2/08/2024	DEFECT					
PM133	XQ86MI	00069649	2/08/2024	DEFECT					
PM133	XQ86MI	00069648	2/08/2024	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00069649	2/08/2024	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00069649	2/08/2024	ECO	01	LABOUR APPRENA			
PM133	XQ86MI	00069649	2/08/2024	ECO		SLEEPER AIR SERVICE COMPLETED BY ALEX ON 02/(			
PM133	XQ86MI	00069649	2/08/2024	ECO	16			CON	YAT
PM133	XQ86MI	00069649	2/08/2024	ECO	40			10W50	YAT
PM133	XQ86MI	00069649	2/08/2024	ECO	06			ED002175254-S	YAT
PM133	XQ86MI	00069757	6/08/2024	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00069757	6/08/2024	DEFECT					
PM133	XQ86MI	00069757	6/08/2024	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00069757	6/08/2024	DEFECT		Reported Defect :-Defect Code : 00012085			
PM133	XQ86MI	00069757	6/08/2024	GEN		Defect Reference : 68507 Date : 07/07/2024 Description of LIGHTS LEAD FROM PRIME MOVER IS A BIT RATTY PL			
						LABOUR APPRENJ			
PM133	XQ86MI	00069757	6/08/2024	GEN	39	REPAIR COMPLETED BY JOSEPH (WORKSHOP) ON 0(			
PM133	XQ86MI	00069757	6/08/2024	GEN	16	REPLACED LIGHT PLUG CON YAT			
PM133	XQ86MI	00070798	7/09/2024	CUMAE5	01	LABOUR MECH			
PM133	XQ86MI	00070798	7/09/2024	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00070798	7/09/2024	CUMBE5	01	LABOUR MECH 1			
PM133	XQ86MI	00070798	7/09/2024	CUMBE5		'B' SERVICE COMPLETED BY BEN, TYLER & JOSH (WORKSHOP)			
PM133	XQ86MI	00070798	7/09/2024	CUMBE5	00	LABOUR APPREN			
PM133	XQ86MI	00070798	7/09/2024	CUMBE5	00	LABOUR APPRENJC			
PM133	XQ86MI	00070798	7/09/2024	CUMBE5	16			CON	YAT
PM133	XQ86MI	00070798	7/09/2024	CUMBE5	40			3413005	YAT
PM133	XQ86MI	00070798	7/09/2024	CUMBE5	06			MK13584	YAT
PM133	XQ86MI	00070798	7/09/2024	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00070798	7/09/2024	DEFECT					
PM133	XQ86MI	00070798	7/09/2024	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			11003134	
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			33000084	
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			33000371	
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			33000118	
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			11006520	
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			33000084	
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			33000371	
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			33000517	
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			11003134	
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			33000084	
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			33000371	
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			33000118	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			11006520	
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			33000084	
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			33000371	
PM133	XQ86MI	00070869	10/09/2024	TYRES	15			33000517	
PM133	XQ86MI	00070971	14/09/2024	DEFECT	01	LABOUR	MECH		
PM133	XQ86MI	00070971	14/09/2024	DEFECT					
PM133	XQ86MI	00070971	14/09/2024	DEFECT		DEFECT	CLEARED.		
PM133	XQ86MI	00070971	14/09/2024	GEN	39	LABOUR APPRENJC			
PM133	XQ86MI	00070971	14/09/2024	GEN		REPAIR COMPLETED BY JOSH (WORKSHOP) ON 14/0(			
						REPLACED BOTH LH & RH WEATHER SHIELDS DUE TO PLAS			
PM133	XQ86MI	00070971	14/09/2024	GEN	16			CON	YAT
PM133	XQ86MI	00070971	14/09/2024	GEN	13			KW1001DL	YAT
PM133	XQ86MI	00070971	14/09/2024	GEN	13			KW1001DR	YAT

PM133	XQ86MI	00071413	24/09/2024	CUMAE5	01	LABOUR APPRENJ				
PM133	XQ86MI	00071413	24/09/2024	CUMAE5		SERVICE COMPLETED.				
PM133	XQ86MI	00071413	24/09/2024	CUMAE5	00	LABOUR MECH 6				
PM133	XQ86MI	00071413	24/09/2024	CUMAE5	16			CON		YAT
PM133	XQ86MI	00071413	24/09/2024	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00071413	24/09/2024	DEFECT						
PM133	XQ86MI	00071413	24/09/2024	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00071895	3/10/2024	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00071895	3/10/2024	DEFECT						
PM133	XQ86MI	00071895	3/10/2024	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00071882	3/10/2024	GEN	39			LABEXT		
PM133	XQ86MI	00071882	3/10/2024	GEN	39			LABEXT		
PM133	XQ86MI	00071895	3/10/2024	GEN	39	LABOUR MECH 5				
PM133	XQ86MI	00071895	3/10/2024	GEN		REPAIR COMPLETED BY BEN & JOSEPH (WORKSHOP				
PM133	XQ86MI	00071895	3/10/2024	GEN	00	REPLACED QUADRAN ARM AS IT WAS MISSING REPA LABOUR APPRENJ				
PM133	XQ86MI	00071895	3/10/2024	GEN	16			CON		YAT
PM133	XQ86MI	00071895	3/10/2024	GEN	13			K-4464		YAT
PM133	XQ86MI	00072066	8/10/2024	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00072066	8/10/2024	DEFECT						
PM133	XQ86MI	00072066	8/10/2024	DEFECT		DEFECT CLEARED.				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00072066	8/10/2024	GE		REPAIR COMPLETED BY BROWN & HURLEY BUNDA				

Receive afterhours callout request reporting vehicle breakdown at (
& equipment from
workshop to complete repair; travel out to vehicle roadside; arrive c
on batteries; confirm all batteries charges & measuring CCA in spe
check all terminals on starter; found earth wire from main solenoid t
correct earth; earth on vehicle is non serviceable; remove failed sta
supply correct; start engine; confirm complaint rectified; return vehi

PM133	XQ86MI	00072066	8/10/2024	GEN	39			CALL OUT FEE		
PM133	XQ86MI	00072066	8/10/2024	GEN	39			LABEXT		
PM133	XQ86MI	00072066	8/10/2024	GEN	39			CALL OUT FEE		
PM133	XQ86MI	00072066	8/10/2024	GEN	03			PART		
PM133	XQ86MI	00072066	8/10/2024	GEN	39			TRAVEL FEE		
PM133	XQ86MI	00072066	8/10/2024	GEN	16			CON		
PM133	XQ86MI	00072066	8/10/2024	GEN	16			ENVLEV		
PM133	XQ86MI	00072066	8/10/2024	GEN	39			CALL OUT FEE		
PM133	XQ86MI	00072066	8/10/2024	GEN	39			LABEXT		
PM133	XQ86MI	00072066	8/10/2024	GEN	39			CALL OUT FEE		
PM133	XQ86MI	00072066	8/10/2024	GEN	03			PART		
PM133	XQ86MI	00072066	8/10/2024	GEN	39			TRAVEL FEE		
PM133	XQ86MI	00072066	8/10/2024	GEN	16			CON		
PM133	XQ86MI	00072066	8/10/2024	GEN	16			ENVLEV		
PM133	XQ86MI	00073106	31/10/2024	CUMAE5	01	LABOUR APPREN				
PM133	XQ86MI	00073106	31/10/2024	CUMAE5		'A' SERVICE COMPLETED BY TYLER & JOSH (WORKSHOP) ON 3				
PM133	XQ86MI	00073106	31/10/2024	CUMAE5	00	REPLACED REAR DRIVE BRAKES LABOUR APPRENJC				
PM133	XQ86MI	00073106	31/10/2024	CUMAE5	16			CON		YAT
PM133	XQ86MI	00073106	31/10/2024	CUMAE5	02			KSMA2124707Q		YAT
PM133	XQ86MI	00073107	31/10/2024	CUMCE5	01	LABOUR APPREN				
PM133	XQ86MI	00073107	31/10/2024	CUMCE5		'C' SERVICE COMPLETED BY TYLER, BEN & JOSH (WORKSHOP)				

PM133	XQ86MI	00073107	31/10/2024	CUMCE5	00	REPLACED BELT TENSIONER LABOUR MECH 5			
PM133	XQ86MI	00073107	31/10/2024	CUMCE5	00	LABOUR APPRENJC			
PM133	XQ86MI	00073107	31/10/2024	CUMCE5	16			CON	YAT
PM133	XQ86MI	00073107	31/10/2024	CUMCE5	06			TRPCAF0001	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00073107	31/10/2024	CUMCE5	06			LF637	YAT
PM133	XQ86MI	00073107	31/10/2024	CUMCE5	06			17237	YAT
PM133	XQ86MI	00073107	31/10/2024	CUMCE5	06			A-3380W1687	YAT
PM133	XQ86MI	00073107	31/10/2024	CUMCE5	06			WF2127	YAT
PM133	XQ86MI	00073107	31/10/2024	CUMCE5	06			T224P	YAT
PM133	XQ86MI	00073107	31/10/2024	CUMCE5	06			AF1969M	YAT
PM133	XQ86MI	00073107	31/10/2024	CUMCE5	40			3430336	YAT
PM133	XQ86MI	00073107	31/10/2024	CUMCE5	40			3430284	YAT
PM133	XQ86MI	00073107	31/10/2024	CUMCE5	11			89440	YAT
PM133	XQ86MI	00073106	31/10/2024	DEFECT	01	LABOUR	MECH		
PM133	XQ86MI	00073107	31/10/2024	DEFECT	01	LABOUR	MECH		
PM133	XQ86MI	00073108	31/10/2024	DEFECT	01	LABOUR	MECH		
PM133	XQ86MI	00073106	31/10/2024	DEFECT					
PM133	XQ86MI	00073107	31/10/2024	DEFECT					
PM133	XQ86MI	00073108	31/10/2024	DEFECT					
PM133	XQ86MI	00073106	31/10/2024	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00073107	31/10/2024	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00073108	31/10/2024	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00073108	31/10/2024	EXOINS	01	LABOUR APPREN			
PM133	XQ86MI	00073108	31/10/2024	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECTIC			
						INSPECTION COMPLETED BY TYLER (WORKSHOP) OI			
PM133	XQ86MI	00073109	1/11/2024	DEFECT	01	NO DEFECTS IDENTIFIED LABOUR MECH			
PM133	XQ86MI	00073109	1/11/2024	DEFECT					
PM133	XQ86MI	00073109	1/11/2024	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00073109	1/11/2024	ECO	01	LABOUR APPREN			
PM133	XQ86MI	00073109	1/11/2024	ECO		SLEEPER AIR SERVICE COMPLETED BY TYLER (WC			
						WASHED DOWN MOTOR AFTER SERVICE USING DEGREASE WAS NO NEED TO TIGHTEN BELTS			
PM133	XQ86MI	00073109	1/11/2024	ECO	16			CON	YAT
PM133	XQ86MI	00073109	1/11/2024	ECO	06			ED0037300960	YAT
PM133	XQ86MI	00073109	1/11/2024	ECO	06			ED0021751550	YAT
PM133	XQ86MI	00073109	1/11/2024	ECO	06			ED0012002340-	YAT
PM133	XQ86MI	00073109	1/11/2024	ECO	06			FS1251	YAT
PM133	XQ86MI	00073109	1/11/2024	ECO	06			ED002175254-S	YAT
PM133	XQ86MI	00073109	1/11/2024	ECO	40			10W50	YAT
PM133	XQ86MI	00073479	19/11/2024	GEN	15			LABEXT	
PM133	XQ86MI	00073840	19/11/2024	GEN	15			LABEXT	
PM133	XQ86MI	00073841	19/11/2024	GEN	39			LABEXT	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00073479	19/11/2024	GEN	15			CON	
PM133	XQ86MI	00073840	19/11/2024	GEN	16			CON	
PM133	XQ86MI	00073841	19/11/2024	GEN	16			CON	
PM133	XQ86MI	00073479	19/11/2024	GEN	15			LABEXT	
PM133	XQ86MI	00073840	19/11/2024	GEN	15			LABEXT	
PM133	XQ86MI	00073841	19/11/2024	GEN	39			LABEXT	
PM133	XQ86MI	00073479	19/11/2024	GEN	15			CON	
PM133	XQ86MI	00073840	19/11/2024	GEN	16			CON	
PM133	XQ86MI	00073841	19/11/2024	GEN	16			CON	
PM133	XQ86MI	00073828	2/12/2024	DEFECT	01	LABOUR	MECH		
PM133	XQ86MI	00073828	2/12/2024	DEFECT					
PM133	XQ86MI	00073828	2/12/2024	DEFECT		DEFECT	CLEARED.		

PM133	XQ86MI	00073828	2/12/2024	GEN	39	LABOUR APPRENJ			
PM133	XQ86MI	00073828	2/12/2024	GEN		REPAIR COMPLETED BY JOSEPH (WORKSHOP) ON 0			
PM133	XQ86MI	00073828	2/12/2024	GEN	16	REPLACED MALE EBS PLUG. RE-ZIPTIED UP SUZI CO CON YAT			
PM133	XQ86MI	00073828	2/12/2024	GEN	31		82196	YAT	
PM133	XQ86MI	00074042	11/12/2024	CUMAE5	01	LABOUR MECH			
PM133	XQ86MI	00074042	11/12/2024	CUMAE5		SERVICE COMPLETED.			
PM133	XQ86MI	00074042	11/12/2024	CUMBE5	01	LABOUR MECH 5			
PM133	XQ86MI	00074042	11/12/2024	CUMBE5		'B' SERVICE COMPLETED BY BEN & JOSH (WORKSHO			
PM133	XQ86MI	00074042	11/12/2024	CUMBE5	00	REPAIRED ROAD TRAIN SIGNS F/E EXP : APRIL 2025 EYEWASH BOTTLE EXP : FEB 2025 LABOUR APPRENJ			
PM133	XQ86MI	00074042	11/12/2024	CUMBE5	16		CON	YAT	
PM133	XQ86MI	00074042	11/12/2024	CUMBE5	06		MK13584	YAT	
PM133	XQ86MI	00074042	11/12/2024	CUMBE5	40		3413005	YAT	
PM133	XQ86MI	00074042	11/12/2024	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00074042	11/12/2024	DEFECT					
PM133	XQ86MI	00074042	11/12/2024	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00074042	11/12/2024	DEFECT		Reported Defect :-Defect Code : 00013129 Defect Reference : 58551 Date : 11/12/2024 Description of			
						DEFECT CLEARED ON 11/12/2024 SERVICE CARRIED			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00074305	23/12/2024	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00074305	23/12/2024	DEFECT					
PM133	XQ86MI	00074305	23/12/2024	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00074305	23/12/2024	GEN	39	LABOUR APPRENJC			
PM133	XQ86MI	00074305	23/12/2024	GEN		REPAIR COMPLETED BY JOSH (WORKSHOP) ON 23/1			
PM133	XQ86MI	00074305	23/12/2024	GEN	31	REPLACED SUZI COILS DUE TO BEING SNAPPED. 61-SC3MTLTSE YAT			
PM133	XQ86MI	00074305	23/12/2024	GEN	16			CON	YAT
PM133	XQ86MI	00074783	13/01/2025	TYRES	15			11003134	
PM133	XQ86MI	00074783	13/01/2025	TYRES	15			33000084	
PM133	XQ86MI	00074783	13/01/2025	TYRES	15			33001507	
PM133	XQ86MI	00074783	13/01/2025	TYRES	15			33000531	
PM133	XQ86MI	00074783	13/01/2025	TYRES	15			11003134	
PM133	XQ86MI	00074783	13/01/2025	TYRES	15			33000084	
PM133	XQ86MI	00074783	13/01/2025	TYRES	15			33001507	
PM133	XQ86MI	00074783	13/01/2025	TYRES	15			33000531	
PM133	XQ86MI	00075298	31/01/2025	CUMAE5	01	LABOUR MECH 5			
PM133	XQ86MI	00075298	31/01/2025	CUMAE5		'A' SERVICE COMPLETED BY BEN, NICK & JOSH (WORI			
PM133	XQ86MI	00075298	31/01/2025	CUMAE5	00	REPLACED ALL STEERING WHEEL SWITCHES (2ND HA ADJUSTED CLUTCH TIGHTENED GRILL BOLTS REPAIRED LHS TANK LIGHT SKIRT HARNESS F/E EXP : APRIL 2025 LABOUR MECH 1			
PM133	XQ86MI	00075298	31/01/2025	CUMAE5	00	LABOUR APPRENJC			
PM133	XQ86MI	00075298	31/01/2025	CUMAE5	16			CON	YAT
PM133	XQ86MI	00075298	31/01/2025	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00075298	31/01/2025	DEFECT					
PM133	XQ86MI	00075298	31/01/2025	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00075953	25/02/2025	CUMAE5	00	LABOUR APPREN			
PM133	XQ86MI	00075953	25/02/2025	CUMAE5		A SERVICE COMPLETED BY TYLER & JOSH (WORKSHOP) ON 25			
PM133	XQ86MI	00075953	25/02/2025	CUMAE5	16	FIRE EXT EXP: APRIL 2025		CON	YAT

PM133	XQ86MI	00075953	25/02/2025	CUMAE5	00	LABOUR APPRENJC			
PM133	XQ86MI	00075953	25/02/2025	CUMAE5	40			3413005	YAT
PM133	XQ86MI	00075953	25/02/2025	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00075953	25/02/2025	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00076025	27/02/2025	TYRES	15			33000096	
PM133	XQ86MI	00076025	27/02/2025	TYRES	15			33000118	
PM133	XQ86MI	00076025	27/02/2025	TYRES	15			33000096	
PM133	XQ86MI	00076025	27/02/2025	TYRES	15			33000118	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00076318	15/03/2025	CUMAE5	00	LABOUR MECH 1			
PM133	XQ86MI	00076318	15/03/2025	CUMAE5		A SERVICE COMPLETED. BY WORKSHOP 15/03/2025 FIRE EXT EXP: APRIL 2025 CHECKED DEFECT 1584 FOR LEAKING THROUGH STAFT SEA REPLACED LIGHT PLUB CASE ON BACK OF TRUCK CHECK DIFF AND GEAR BOX OILS FOR CONTAM,INATION FR DEFECT 13525 CHECKED AND REPAIRED BY TYLER			
PM133	XQ86MI	00076318	15/03/2025	CUMAE5	16			CON	YAT
PM133	XQ86MI	00076318	15/03/2025	CUMAE5	00	LABOUR APPRENJ			
PM133	XQ86MI	00076318	15/03/2025	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00076318	15/03/2025	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00076318	15/03/2025	DEFECT		Reported Defect :-Defect Code : 00010584			
PM133	XQ86MI	00076318	15/03/2025	DEFECT		Defect Reference : PM133 Date : 03/01/2024 Description o FRONT DIFF OUTPUT SHAFT SEAL REQUIRES REPLA Reported Defect :- Defect Code : 00013525 Defect Reference : PM133 Date : MONITOR STEREO CUT OUT AT BUMPS LABOUR MECH			
PM133	XQ86MI	00076808	3/04/2025	DEFECT	01				
PM133	XQ86MI	00076808	3/04/2025	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00076808	3/04/2025	GEN	39	LABOUR APPRENJC			
PM133	XQ86MI	00076808	3/04/2025	GEN		REPAIR COMPLETED BY WORKSHOP 03/04/2025 REPLACED MALE EBS PLUG & 30 AMP FUSE			
PM133	XQ86MI	00076808	3/04/2025	GEN	16			CON	YAT
PM133	XQ86MI	00077436	11/04/2025	GEN	39			LAB	
PM133	XQ86MI	00077436	11/04/2025	GEN	39			TRAVEL FEE	
PM133	XQ86MI	00077436	11/04/2025	GEN		REPAIR COMPLETED BY EXPRESS TRUCK MAINTENAN After hours call out to Warnervale depot vehicle in derate for got going and waited to see if he called up and no call so retu			
PM133	XQ86MI	00077436	11/04/2025	GEN	39			LAB	E
PM133	XQ86MI	00077436	11/04/2025	GEN	39			TRAVEL FEE	E
PM133	XQ86MI	00077308	24/04/2025	TYRES	15			11006520	BI
PM133	XQ86MI	00077308	24/04/2025	TYRES	15			33000084	BI
PM133	XQ86MI	00077308	24/04/2025	TYRES	15			33000370	BI

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00077308	24/04/2025	TYRES	15			33000518	
PM133	XQ86MI	00077308	24/04/2025	TYRES	15			33000118	
PM133	XQ86MI	00077308	24/04/2025	TYRES	15			33000118	
PM133	XQ86MI	00077308	24/04/2025	TYRES	15			33000518	
PM133	XQ86MI	00077308	24/04/2025	TYRES	15			33000370	
PM133	XQ86MI	00077308	24/04/2025	TYRES	15			33000084	
PM133	XQ86MI	00077308	24/04/2025	TYRES	15			11006520	
PM133	XQ86MI	00077295	28/04/2025	CUMAE5	00	LABOUR MECH			
PM133	XQ86MI	00077295	28/04/2025	CUMAE5		A SERVICE COMPLETED.			
PM133	XQ86MI	00077295	28/04/2025	CUMAE5	16	FIRE EXT EXP: CON			YAT

PM133	XQ86MI	00077295	28/04/2025	CUMBE5	01	LABOUR APPRENJ				
PM133	XQ86MI	00077295	28/04/2025	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 23/04/2025				
						FIRE EXT EXP: SEP 25				
						HINGE ON TOP GLOVE COMPARTMENT BEEN FIXED T SHOCK MOUNT REPLACED ALL 4 BATTERIES SFTER REAR MALELIGHT PLUG CON YAT				
PM133	XQ86MI	00077295	28/04/2025	CUMBE5	16					
PM133	XQ86MI	00077295	28/04/2025	CUMBE5	00	LABOUR APPREN				
PM133	XQ86MI	00077295	28/04/2025	CUMBE5	16			RSK154	YAT	
PM133	XQ86MI	00077295	28/04/2025	CUMBE5	06			Z1006	YAT	
PM133	XQ86MI	00077295	28/04/2025	CUMBE5	16			3413005	YAT	
PM133	XQ86MI	00077295	28/04/2025	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00077295	28/04/2025	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00077642	12/05/2025	CUMAE5	00	LABOUR MECH 5				
PM133	XQ86MI	00077642	12/05/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 12.05.2025				
						FIRE EXT EXP: SEPTEMBER 2025				
PM133	XQ86MI	00077642	12/05/2025	CUMAE5	16	REPLACED CRUISE ENGINE RETARDER, AFTER TREA MALE EBS PLUG AND REPLACED FUSE CON YAT				
PM133	XQ86MI	00077641	12/05/2025	GEN	39	LABOUR MECH 5				
PM133	XQ86MI	00077641	12/05/2025	GEN		REPAIR COMPLETED BY WORKSHOP 12.05.2025				
PM133	XQ86MI	00077641	12/05/2025	GEN	16			CON	YAT	
PM133	XQ86MI	00077641	12/05/2025	GEN	06			ED002175254-S	YAT	
PM133	XQ86MI	00077641	12/05/2025	GEN	40			10W50	YAT	
PM133	XQ86MI	00078729	23/06/2025	CUMAE5	00	LABOUR MECH 1				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00078729	23/06/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 23.06.2025				
						FIRE EXT EXP: SEPTEMBER 2025				
						DEFECT N# 13720 / 58806 CHECKED + FRIDGE IS COL				
						TIGHTENED FRONT LEFT SHOCKY MOUNT REFIT ROA				
PM133	XQ86MI	00078729	23/06/2025	CUMAE5	16	R/H AIR HORN ASSY MISSING D# 14521 CON YAT				
PM133	XQ86MI	00078729	23/06/2025	CUMAE5	00	LABOUR APPREN				
PM133	XQ86MI	00078729	23/06/2025	CUMAE5	00	LABOUR APPRENJ				
PM133	XQ86MI	00079532	26/07/2025	CUMAE5	00	LABOUR APPREN				
PM133	XQ86MI	00079532	26/07/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 26/7/2025				
						FIRE EXT EXP: SEPTEMBER 2025				
						REPLACED RHS AIRHORN FIXED AIRLINE BEHIND SEA HINGE HAS BEEN REPAIRED IN PRIOR SERVICE REPL ADJUSTED CLUTCH CON YAT				
PM133	XQ86MI	00079532	26/07/2025	CUMAE5	16					
PM133	XQ86MI	00079532	26/07/2025	CUMAE5	00	LABOUR APPRENJC				
PM133	XQ86MI	00079532	26/07/2025	CUMAE5	00	LABOUR MECH 5				
PM133	XQ86MI	00079532	26/07/2025	CUMAE5	16			KN31200	YAT	
PM133	XQ86MI	00079532	26/07/2025	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00079532	26/07/2025	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00079532	26/07/2025	DEFECT		Reported Defect :-Defect Code : 00014521				
PM133	XQ86MI	00079532	26/07/2025	DEFECT		Defect Reference : PM133 Date : 23/06/2025 Description o R/H AIR HORN ASSY MISSING Reported Defect :-				
						Defect Code : 00014668 Defect Reference : 58805 Date : 1 Description of Defect :				

PM133	XQ86MI	00079641	29/07/2025	GEN	39	HINGE ON CENTRE GLOVE COMPARTMENT BROKEN MISCON		NABQAN01	EX00041172	MIS
PM133	XQ86MI	00079641	29/07/2025	GEN	39			CONSUMABLES,HAULMAX 11R MISCON		NABQAI
PM133	XQ86MI	00079864	8/08/2025	CUMAE5	00	CONSUMABLES,HAULMAX 11R22.5 16PR TL ATT312 P LABOUR MECH				

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00079864	8/08/2025	CUMAE5		A SERVICE COMPLETED.			
						FIRE EXT EXP:			
PM133	XQ86MI	00079864	8/08/2025	CUMAE5	16			CON	YAT
PM133	XQ86MI	00079864	8/08/2025	CUMBE5	01	LABOUR MECH 5			
PM133	XQ86MI	00079864	8/08/2025	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 08/08/2025 FIRE EXT EXP: SEPTEMBER 2025 MOVED OIL FILTER NECK UP TO STOP IT RUBBING CL BLUE INJECTOR FLUSHED ALL ADD BLUE LINES AND DOSER PUMP			
PM133	XQ86MI	00079864	8/08/2025	CUMBE5	16	CON YAT			
PM133	XQ86MI	00079864	8/08/2025	CUMBE5	00	LABOUR APPRENJC			
PM133	XQ86MI	00079864	8/08/2025	CUMBE5	00	LABOUR APPRENJ			
PM133	XQ86MI	00079864	8/08/2025	CUMBE5	16			Z1006	YAT
PM133	XQ86MI	00079864	8/08/2025	CUMBE5	16			RSK154	YAT
PM133	XQ86MI	00079864	8/08/2025	CUMBE5	16			3413005	YAT
PM133	XQ86MI	00079865	11/08/2025	CUMAE5	00	LABOUR MECH			
PM133	XQ86MI	00079865	11/08/2025	CUMAE5		A SERVICE COMPLETED.			
PM133	XQ86MI	00079865	11/08/2025	CUMAE5	16	FIRE EXT EXP: CON YAT			
PM133	XQ86MI	00079865	11/08/2025	CUMBE5	01	LABOUR APPRENJC			
PM133	XQ86MI	00079865	11/08/2025	CUMBE5		B SERVICE COMPLETED.			
PM133	XQ86MI	00079865	11/08/2025	CUMBE5	16	FIRE EXT EXP: CON YAT			
PM133	XQ86MI	00079865	11/08/2025	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00079865	11/08/2025	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00080380	15/08/2025	TYRES	15			11003134	BRIAUS
PM133	XQ86MI	00080380	15/08/2025	TYRES	15			77000232	BRIAUS
PM133	XQ86MI	00080380	15/08/2025	TYRES	15			33000084	BRIAUS
PM133	XQ86MI	00080380	15/08/2025	TYRES	15			33000517	BRIAUS
PM133	XQ86MI	00080380	15/08/2025	TYRES	15			33000118	BRIAUS
PM133	XQ86MI	00080380	15/08/2025	TYRES	15			11003134	BRIAUS
PM133	XQ86MI	00080380	15/08/2025	TYRES	15			77000232	BRIAUS
PM133	XQ86MI	00080380	15/08/2025	TYRES	15			33000084	BRIAUS
PM133	XQ86MI	00080380	15/08/2025	TYRES	15			33000517	BRIAUS
PM133	XQ86MI	00080380	15/08/2025	TYRES	15			33000118	BRIAUS
PM133	XQ86MI	00080180	21/08/2025	GEN	39			LABEXT	BROHU
PM133	XQ86MI	00080180	21/08/2025	GEN	39			5307918	BROHU
PM133	XQ86MI	00080180	21/08/2025	GEN	39			CON	BROHU
PM133	XQ86MI	00080180	21/08/2025	GEN	39			ENVLEV	BROHU
PM133	XQ86MI	00080180	21/08/2025	GEN	39			LABEXT	BROHU

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00080180	21/08/2025	GEN	39			5307918	
PM133	XQ86MI	00080180	21/08/2025	GEN	39			CON	
PM133	XQ86MI	00080180	21/08/2025	GEN	39			ENVLEV	
PM133	XQ86MI	00080297	26/08/2025	TYRES	15			33000125	
PM133	XQ86MI	00080657	26/08/2025	TYRES	15			33000237	
PM133	XQ86MI	00080297	26/08/2025	TYRES	15			33000096	
PM133	XQ86MI	00080657	26/08/2025	TYRES	15			33000237	
PM133	XQ86MI	00080297	26/08/2025	TYRES	15			22001129	

PM133	XQ86MI	00080657	26/08/2025	TYRES	15			33000125
PM133	XQ86MI	00080297	26/08/2025	TYRES	15			33000237
PM133	XQ86MI	00080657	26/08/2025	TYRES	15			33000096
PM133	XQ86MI	00080297	26/08/2025	TYRES	15			33000237
PM133	XQ86MI	00080657	26/08/2025	TYRES	15			22001129
PM133	XQ86MI	00080657	26/08/2025	TYRES	15			33000237
PM133	XQ86MI	00080657	26/08/2025	TYRES	15			33000237
PM133	XQ86MI	00080657	26/08/2025	TYRES	15			33000125
PM133	XQ86MI	00080657	26/08/2025	TYRES	15			33000096
PM133	XQ86MI	00080657	26/08/2025	TYRES	15			22001129
PM133	XQ86MI	00080958	19/09/2025	CUMAE5	00	LABOUR APPREN		
PM133	XQ86MI	00080958	19/09/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 19/9/2025 FIRE EXT EXP: MARCH 2026 ADJUSTED TURNTABLE FITTED NEW NHVE STICKER BRAKES CON YAT		
PM133	XQ86MI	00080958	19/09/2025	CUMAE5	16			
PM133	XQ86MI	00080958	19/09/2025	CUMAE5	00	LABOUR APPREND		
PM133	XQ86MI	00080958	19/09/2025	DEFECT	01	LABOUR MECH		
PM133	XQ86MI	00080958	19/09/2025	DEFECT		DEFECT CLEARED.		
PM133	XQ86MI	00080958	19/09/2025	DEFECT		Reported Defect :-Defect Code : 00014822 Defect Reference : PM133 Date : 08/08/2025 Description o		

NEED NEW NHVR STICKER - MADI TO ORDER

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00081523	30/09/2025	GEN	39			LABEXT	
PM133	XQ86MI	00081523	30/09/2025	GEN	39			FS19764	
PM133	XQ86MI	00081523	30/09/2025	GEN	39			4954245	
PM133	XQ86MI	00081523	30/09/2025	GEN	39			4307195	
PM133	XQ86MI	00081523	30/09/2025	GEN	39			WU0890108700	
PM133	XQ86MI	00081523	30/09/2025	GEN	39			WORKSHOP	
PM133	XQ86MI	00081523	30/09/2025	GEN	39			FREIGHT	
PM133	XQ86MI	00081523	30/09/2025	GEN	39			ROUNDING	
PM133	XQ86MI	00081523	30/09/2025	GEN		REPAIR COMPLETED BY INLAND TRUCK CENTRES 30/9 INVOICE #876992 CHECK AND REPAIR - AFTERTREAT LIGHT "ACTIVE", DERATING. . MOVED TRUCK INTO WORKBAY. CONNECT LAPTOP AN AS PER INSITE. REPLACED FUEL FILTER AS STARTING FUEL PRESSURE SENSOR AND RELEIF VALVE. CODE N TRUCK TO SERVICE, CLEANED WORKBAY AND DID PA			
PM133	XQ86MI	00081523	30/09/2025	GEN	39			LABEXT	IN
PM133	XQ86MI	00081523	30/09/2025	GEN	39			FS19764	IN
PM133	XQ86MI	00081523	30/09/2025	GEN	39			4954245	IN
PM133	XQ86MI	00081523	30/09/2025	GEN	39			4307195	IN
PM133	XQ86MI	00081523	30/09/2025	GEN	39			WU0890108700	IN
PM133	XQ86MI	00081523	30/09/2025	GEN	39			WORKSHOP	IN
PM133	XQ86MI	00081523	30/09/2025	GEN	39			FREIGHT	IN
PM133	XQ86MI	00081523	30/09/2025	GEN	39			ROUNDING	IN
PM133	XQ86MI	00081397	11/10/2025	CUMAE5	00	LABOUR APPRENJ			
PM133	XQ86MI	00081397	11/10/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 11/10/2025 FIRE EXT EXP: FEBRUARY 2026			

PM133	XQ86MI	00081397	11/10/2025	CUMAE5	16	REPLACED STEER BRAKES AND CHECKED ADJUSTM CON YAT			
PM133	XQ86MI	00081397	11/10/2025	CUMAE5	00	LABOUR APPRENJC			
PM133	XQ86MI	00081397	11/10/2025	CUMAE5	16	KSMA2124715Q YAT			
PM133	XQ86MI	00081397	11/10/2025	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00081397	11/10/2025	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00081397	11/10/2025	DEFECT		Reported Defect :-Defect Code : 00015148			
PM133	XQ86MI	00081475	14/10/2025	GEN	39	Defect Reference : PM133 Date : 19/09/2025 Description o STEER BRAKES GETTING LOW RHS GENERAL PART BROHUR01 EX00042432			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00081475	14/10/2025	GEN	39			LABEXT	
PM133	XQ86MI	00081475	14/10/2025	GEN	39			CON	
PM133	XQ86MI	00081475	14/10/2025	GEN	39			ENVLEV	
PM133	XQ86MI	00081475	14/10/2025	GEN		REPAIR COMPLETED BY BROWN N HURLEY 14/10/2025 INVOICE #3681367 SET UP TRUCK IN WORKSHOP, FOUND BLOWER FAN N REMOVE AND REPLACE BLOWER FAN - A/C SYSTEM N WORK AREA AND COMPLETE PAPERWORK			
PM133	XQ86MI	00081475	14/10/2025	GEN	39			GENERAL PART	
PM133	XQ86MI	00081475	14/10/2025	GEN	39			LABEXT	
PM133	XQ86MI	00081475	14/10/2025	GEN	39			CON	
PM133	XQ86MI	00081475	14/10/2025	GEN	39			ENVLEV	
PM133	XQ86MI	00082019	3/11/2025	CUMAE5	00	LABOUR MECH			
PM133	XQ86MI	00082019	3/11/2025	CUMAE5		A SERVICE COMPLETED.			
PM133	XQ86MI	00082019	3/11/2025	CUMAE5	16	FIRE EXT EXP: CON			YAT
PM133	XQ86MI	00082019	3/11/2025	CUMBE5	01	LABOUR MECH 1			
PM133	XQ86MI	00082019	3/11/2025	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 03/11/2025 FIRE EXT EXP: MARCH 2026 EYEWASH EXP - FEBRUARY 2028 REPLACE EYEWASH BOTTLE REPAIR 2 X CLAMPS FOR CHECKER DEFECT 14726 - DONE OK DEFECT 14668 - DONE OK DEFECT 15149 - DONE OK CON			PLATE
PM133	XQ86MI	00082019	3/11/2025	CUMBE5	16				YAT
PM133	XQ86MI	00082019	3/11/2025	CUMBE5	00	LABOUR APPRENJC			
PM133	XQ86MI	00082019	3/11/2025	CUMBE5	06			RSK154	YAT
PM133	XQ86MI	00082019	3/11/2025	CUMBE5	06			Z1006	YAT
PM133	XQ86MI	00082019	3/11/2025	CUMBE5	40			3413005	YAT
PM133	XQ86MI	00082019	3/11/2025	CUMBE5	16			Anti-Freeze Cool	YAT
PM133	XQ86MI	00082019	3/11/2025	CUMBE5	40			3430536	YAT
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	01	LABOUR MECH 1			
PM133	XQ86MI	00082020	3/11/2025	CUMCE5		C SERVICE COMPLETED BY WORKSHOP 03/11/2025 FIRE EXT EXP: MARCH 2026 REPLACE 2 X TORQUE ROD BUSHES AT 2ND DRIVE A 1 X TORQUE ROD BUSH AT 1ST DRIVE SCLE ADJUST WHEEL BEARING			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	16			CON	YAT
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	00	LABOUR	APPRENJC		
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	06			UF110	YAT
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	06			LF637	YAT
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	06			T224P	YAT
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	06			WF2127	YAT

PM133	XQ86MI	00082020	3/11/2025	CUMCE5	06			17237	YAT
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	06			A3380W1687	YAT
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	06			F37-TP-1000	YAT
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	40			3430336	YAT
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	40			3430284	YAT
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	06			HDA5979	YAT
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	11			6PK1590	YAT
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	11			12PK2380	YAT
PM133	XQ86MI	00082020	3/11/2025	CUMCE5	16			839310	YAT
PM133	XQ86MI	00082019	3/11/2025	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00082019	3/11/2025	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00082019	3/11/2025	DEFECT		Reported Defect :-Defect Code : 00014726			
PM133	XQ86MI	00082019	3/11/2025	DEFECT		Defect Reference : XQ86MI Date : 18/07/2025 Description ADJUST CLUTCH BRAKE BAD AIR LEAK BEHIND DRIVERS SEAT Reported Defect :-			
PM133	XQ86MI	00082019	3/11/2025	DEFECT		Defect Code : 00014668 Defect Reference : 58805 Date : 1 HINGE ON CENTRE GLOVE COMPARTMENT BROKEN Reported Defect :-			
PM133	XQ86MI	00082019	3/11/2025	DEFECT		Defect Code : 00015149 Defect Reference : PM133 Date : TORQUE ROD BUSHES FRONT DIFF ON WAY OUT LABOUR APPREND			
PM133	XQ86MI	00082022	3/11/2025	ECO	01				
PM133	XQ86MI	00082022	3/11/2025	ECO		ECO WIND SERVICE COMPLETED BY WORKSHOP 03/			
PM133	XQ86MI	00082022	3/11/2025	ECO	16			CON	YAT
PM133	XQ86MI	00082022	3/11/2025	ECO	40			3413005	YAT
PM133	XQ86MI	00082022	3/11/2025	ECO	06			SA17117	YAT
PM133	XQ86MI	00082022	3/11/2025	ECO	06			FS1251	YAT
PM133	XQ86MI	00082022	3/11/2025	ECO	06			SN 80008	YAT
PM133	XQ86MI	00082022	3/11/2025	ECO	06			SO 8010	YAT
PM133	XQ86MI	00082021	3/11/2025	EXOINS	01	LABOUR MECH 1			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S Co
PM133	XQ86MI	00082021	3/11/2025	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECTIO ATTEMPT #1 INSPECTION COMPLETED BY WORKSHOP 03/11/2025 FIRE EXT EXP - FEBRUARY 2026 EYEWASH EXP - MARCH 2028 DEFECTS IDENTIFIED - NO FAULTS FOUND ON INSPECTION				
PM133	XQ86MI	00082262	3/11/2025	TYRES	15			11006520		
PM133	XQ86MI	00082262	3/11/2025	TYRES	15			33000084		
PM133	XQ86MI	00082262	3/11/2025	TYRES	15			33000370		
PM133	XQ86MI	00082262	3/11/2025	TYRES	15			33000518		
PM133	XQ86MI	00082262	3/11/2025	TYRES	15			33000118		
PM133	XQ86MI	00082262	3/11/2025	TYRES	15			11006520		
PM133	XQ86MI	00082262	3/11/2025	TYRES	15			33000084		
PM133	XQ86MI	00082262	3/11/2025	TYRES	15			33000370		
PM133	XQ86MI	00082262	3/11/2025	TYRES	15			33000518		
PM133	XQ86MI	00082262	3/11/2025	TYRES	15			33000118		
PM133	XQ86MI	00082609	18/11/2025	GEN	39			LABEXT		
PM133	XQ86MI	00082609	18/11/2025	GEN	39			LABEXT		
PM133	XQ86MI	00082609	18/11/2025	GEN	39			27H-780HD		
PM133	XQ86MI	00082609	18/11/2025	GEN	39			MISCON		
PM133	XQ86MI	00082609	18/11/2025	GEN	39			ENVLEV		

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S Co
PM133	XQ86MI	00082609	18/11/2025	GEN		REPAIR COMPLETED BY BROWN N HURLEY 18/11/2025				

INVOICE #3720002

BREAK Break down call out - 6 HARWOOD ST BOHLE PLA
Break down call out
k039 TRUCK NEEDS TO BE JUMP STARTED AS ITS BEE
Loaded up parts and tools into ute drove around to site
Spoke with customer found he had left battery isolator off an
Jump started truck and checked charging rate showing 12.8
load tested got him to just take for a lap around the block an
Removed battery terminals and load tested batteries all still
he leaves
Drove back to workshop
Unpack ute and lock up workshop
K039-1 TRUCK WONT START AGAIN 19-11-25 LEFT THE
DRIVER THINKS A BATTERY MAY HAVE DROPPED A CE
Pack tools and parts Attend location of vehicle Tilt cab, test
Check charge rate 13.8v ok
Return to workshop, unpack tools

PM133	XQ86MI	00082609	18/11/2025	GEN	39			LABEXT		
PM133	XQ86MI	00082609	18/11/2025	GEN	39			LABEXT		
PM133	XQ86MI	00082609	18/11/2025	GEN	39			27H-780HD		
PM133	XQ86MI	00082609	18/11/2025	GEN	39			MISCON		
PM133	XQ86MI	00082609	18/11/2025	GEN	39			ENVLEV		
PM133	XQ86MI	00082490	19/11/2025	CUMAE5	00	LABOUR MECH 5				
PM133	XQ86MI	00082490	19/11/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 19/11/2025 FIRE EXT EXP: MARCH 2026				
PM133	XQ86MI	00082490	19/11/2025	CUMAE5	16	FITTED NEW SPOT LIGHTS TIGHTENED STEERING CO CON YAT				
PM133	XQ86MI	00082490	19/11/2025	CUMAE5	00	LABOUR APPRENJC				
PM133	XQ86MI	00082490	19/11/2025	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00082490	19/11/2025	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00082490	19/11/2025	DEFECT		Reported Defect :-Defect Code : 00015628 Defect Reference : PM133 Date : 18/11/2025 Description o				

DASH LIGHTS KEEP FLICKERING. OIL PRESS LIGHT
STEERING WHEEL ROCKS SIDE TO SIDE

PM133	XQ86MI	00082715	20/11/2025	TYRES	15			33000096		BI
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	
PM133	XQ86MI	00082715	20/11/2025	TYRES	15			33000118		
PM133	XQ86MI	00082715	20/11/2025	TYRES	15			33000096		
PM133	XQ86MI	00082715	20/11/2025	TYRES	15			33000118		
PM133	XQ86MI	00083416	20/12/2025	CUMAE5	00	LABOUR APPREN				
PM133	XQ86MI	00083416	20/12/2025	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 20/12/2025 FIRE EXT EXP: FEBRUARY 2026				
PM133	XQ86MI	00083416	20/12/2025	CUMAE5	16	TOP UP ENGINE OIL REPLACE D2 GOVERNOR VALVE CON YAT				
PM133	XQ86MI	00083416	20/12/2025	CUMAE5	00	LABOUR MECH 1				
PM133	XQ86MI	00083416	20/12/2025	CUMAE5	00	LABOUR APPRENJC				
PM133	XQ86MI	00083416	20/12/2025	CUMAE5	40			3413005	YAT	
PM133	XQ86MI	00083416	20/12/2025	CUMAE5	16			277486	YAT	
PM133	XQ86MI	00083644	28/12/2025	TYRES	15			33000096		BI
PM133	XQ86MI	00083644	28/12/2025	TYRES	15			33000125		BI
PM133	XQ86MI	00083644	28/12/2025	TYRES	15			33000096		BI
PM133	XQ86MI	00083644	28/12/2025	TYRES	15			33000125		BI
PM133	XQ86MI	00083990	1/01/2026	TYRES	15			11003134		BI
PM133	XQ86MI	00083990	1/01/2026	TYRES	15			77000232		BI
PM133	XQ86MI	00083990	1/01/2026	TYRES	15			33000084		BI
PM133	XQ86MI	00083990	1/01/2026	TYRES	15			33000517		BI

PM133	XQ86MI	00083990	1/01/2026	TYRES	15			33000118	BI
PM133	XQ86MI	00083990	1/01/2026	TYRES	15			11003134	BI
PM133	XQ86MI	00083990	1/01/2026	TYRES	15			77000232	BI
PM133	XQ86MI	00083990	1/01/2026	TYRES	15			33000084	BI
PM133	XQ86MI	00083990	1/01/2026	TYRES	15			33000517	BI
PM133	XQ86MI	00083990	1/01/2026	TYRES	15			33000118	BI
PM133	XQ86MI	00084041	8/01/2026	GEN	39			LABEXT	TC
PM133	XQ86MI	00084041	8/01/2026	GEN	39			CALL OUT FEE	TC
PM133	XQ86MI	00084041	8/01/2026	GEN	39			CALL OUT FEE	TC
PM133	XQ86MI	00084041	8/01/2026	GEN	39			GENERAL PART	TC
PM133	XQ86MI	00084041	8/01/2026	GEN	39			FF5776	TC
PM133	XQ86MI	00084041	8/01/2026	GEN	39			FS19764	TC
PM133	XQ86MI	00084041	8/01/2026	GEN	39			DEGREASER	TC
PM133	XQ86MI	00084041	8/01/2026	GEN	39			116	TC
PM133	XQ86MI	00084041	8/01/2026	GEN	39			2872513	TC
PM133	XQ86MI	00084041	8/01/2026	GEN	39			3963990	TC
PM133	XQ86MI	00084041	8/01/2026	GEN	39			2872663	TC
PM133	XQ86MI	00084041	8/01/2026	GEN	39			3963988	TC
PM133	XQ86MI	00084041	8/01/2026	GEN	39			CON	TC
PM133	XQ86MI	00084041	8/01/2026	GEN	39			2872661RX	TC

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00084041	8/01/2026	GEN	39			OF	
PM133	XQ86MI	00084041	8/01/2026	GEN	39			4954245	
PM133	XQ86MI	00084041	8/01/2026	GEN	39			OF	
PM133	XQ86MI	00084041	8/01/2026	GEN	39			ROUNDING	
PM133	XQ86MI	00084041	8/01/2026	GEN		REPAIR COMPLETED BY TORQUE N DIESEL 08/01/202			
						INVOICE #000023340			
						8/01/2026 REMOVE & REPLACE FUEL REGULATOR VALVE ON B PUMP PLUGGED IN SCANNER, NEEDED PRESSURES, STANDARD CARRIED OIT CLUTCH ADJUSTMENTS AT BREAKDOWN AT AMPOL M4 WESTBOUND DIAGNOSE DE RATE ISSUE FOUND FUEL PRESSURE MONITORING FAULT CHECK FUEL SYSTEM DATA ALL OK CHECK POWER T SENSOR LABEXT TORDIE01			
PM133	XQ86MI	00084041	8/01/2026	GEN	39				
PM133	XQ86MI	00084041	8/01/2026	GEN	39			CALL OUT FEE	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			CALL OUT FEE	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			GENERAL PART	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			FF5776	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			FS19764	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			DEGREASER	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			116	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			2872513	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			3963990	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			2872663	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			3963988	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			CON	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			2872661RX	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			OF	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			4954245	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			OF	TORDIE
PM133	XQ86MI	00084041	8/01/2026	GEN	39			ROUNDING	TORDIE
PM133	XQ86MI	00083917	10/01/2026	GEN	39			LABEXT	BROHU
PM133	XQ86MI	00083917	10/01/2026	GEN	39			K-4464	BROHU
PM133	XQ86MI	00083917	10/01/2026	GEN	39			22	BROHU
PM133	XQ86MI	00083917	10/01/2026	GEN	39			MISCON	BROHU

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00083917	10/01/2026	GEN	39			ENVLEV	
PM133	XQ86MI	00083917	10/01/2026	GEN	39			ROUNDING	
PM133	XQ86MI	00083917	10/01/2026	GEN		REPAIR COMPLETED BY BROWN N HURLEY COFFS HA			
						INVOICE #3763073			
						INSTALL SAFETY EQUIPMENT. COMPLETED QUICK CHI CLUTCH ADJUSTER BOLT 0401654274			
						TRAVEL TO URUNGA, LOCATED VEHICLE TO FIND CLU ADJUSTER SCREW AND LOCKING NUT, ADJUSTED CLI			
PM133	XQ86MI	00083917	10/01/2026	GEN	39			LABEXT	
PM133	XQ86MI	00083917	10/01/2026	GEN	39			K-4464	
PM133	XQ86MI	00083917	10/01/2026	GEN	39			22	
PM133	XQ86MI	00083917	10/01/2026	GEN	39			MISCON	
PM133	XQ86MI	00083917	10/01/2026	GEN	39			ENVLEV	
PM133	XQ86MI	00083917	10/01/2026	GEN	39			ROUNDING	
PM133	XQ86MI	00083955	17/01/2026	CUMAE5	00	LABOUR MECH			
PM133	XQ86MI	00083955	17/01/2026	CUMAE5		A SERVICE COMPLETED.			
PM133	XQ86MI	00083955	17/01/2026	CUMAE5	16	FIRE EXT EXP: CON			YAT
PM133	XQ86MI	00083955	17/01/2026	CUMBE5	01	LABOUR MECH 1			
PM133	XQ86MI	00083955	17/01/2026	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 17/01/2026			
						FIRE EXT EXP: MARCH 2026 EYEWASH EXP - MAY 203			
						REPLACE 2 X BULLBAR MARKER/INDICATOR LIGHTS			
PM133	XQ86MI	00083955	17/01/2026	CUMBE5	16	DEFECT 16011 - SERVICED AFTER TREAT AND CHECI			
PM133	XQ86MI	00083955	17/01/2026	CUMBE5	00	LABOUR APPREN			
PM133	XQ86MI	00083955	17/01/2026	CUMBE5	00	LABOUR APPREND			
PM133	XQ86MI	00083955	17/01/2026	CUMBE5	40			3413005	YAT
PM133	XQ86MI	00083955	17/01/2026	CUMBE5	06			rsk154	YAT
PM133	XQ86MI	00083955	17/01/2026	CUMBE5	06			z1006	YAT
PM133	XQ86MI	00083955	17/01/2026	CUMBE5	16			2110-12V	YAT
PM133	XQ86MI	00083955	17/01/2026	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00083955	17/01/2026	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00083955	17/01/2026	DEFECT		Reported Defect :-Defect Code : 00016011				
PM133	XQ86MI	00084582	11/02/2026	CUMAE5	00	Defect Reference : PM133 Date : 07/01/2026 Description o DRIVER TROY S REPORTS HIS K200 WAS GOING INTO IS CURRENTLY IN SYDNEY AND IS DUE TO DEPART A LABOUR APPREN				
PM133	XQ86MI	00084582	11/02/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 11/02/2026				
PM133	XQ86MI	00084582	11/02/2026	CUMAE5	16	FIRE EXT EXP: MARCH 2026 CON	YAT			C
PM133	XQ86MI	00084582	11/02/2026	CUMAE5	00	LABOUR APPRENJC				
PM133	XQ86MI	00084870	21/02/2026	CUMAE5	00	LABOUR MECH 1				
PM133	XQ86MI	00084870	21/02/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 21/02/2026				
PM133	XQ86MI	00084870	21/02/2026	CUMAE5	16	FIRE EXT EXP: MARCH 2026 CON	YAT			C
PM133	XQ86MI	00084870	21/02/2026	CUMAE5	00	LABOUR APPRENJC				
PM133	XQ86MI	00084870	21/02/2026	CUMAE5	00	LABOUR APPREN				
PM133	XQ86MI	00084870	21/02/2026	CUMAE5	40			3413005	YAT	
PM133	XQ86MI	00084943	24/02/2026	GEN	39	LABOUR MECH 1				
PM133	XQ86MI	00084966	24/02/2026	GEN	39	LABOUR APPRENJC				
PM133	XQ86MI	00084943	24/02/2026	GEN		REPAIR COMPLETED BY WORKSHOP 24/02/2026				

						JOB COMPLAINT - 7 PIN PLUG DAMAGED				
PM133	XQ86MI	00084966	24/02/2026	GEN		REPLACED 7 PIN PLUG REPAIR COMPLETED BY WORKSHOP 24/02/2026				
				GEN	16	REPLACED FAN FOR SLEEPER AIR FOUND OIL LEAK COMING FROM FRONT COVER, TIGH CON YAT C				
PM133	XQ86MI	00084943	24/02/2026							
PM133	XQ86MI	00084966	24/02/2026	GEN	16			CON	YAT	
PM133	XQ86MI	00084966	24/02/2026	GEN	16	fa0023 YAT 12				
PM133	XQ86MI	00087218	26/02/2026	WEICAL		EMPTY WEIGHBRIDGE LOADED WEIGHBRIDGE: 15600 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
PM133	XQ86MI	00085317	5/03/2026	GEN	39			LABEXT		
PM133	XQ86MI	00085317	5/03/2026	GEN	39			CALL OUT FEE		
PM133	XQ86MI	00085317	5/03/2026	GEN	39			CON		T
PM133	XQ86MI	00085317	5/03/2026	GEN	39			116		T

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00085317	5/03/2026	GEN	39			GENERAL PART	
PM133	XQ86MI	00085317	5/03/2026	GEN	39			GENERAL PART	
PM133	XQ86MI	00085317	5/03/2026	GEN		REPAIR COMPLETED BY TORQUE N DIESEL 05/03/2026 INVOICE #23695 ATTEND BREAKDOWN AT MARSDEN PARK DIAGNOSE COOLANT LEAK AND FOUND TOP RADIATO DIAGNOSE OIL LEAK FOUND FILTER LEAKING FIT NEW FILTER AND RECHECK			
PM133	XQ86MI	00085317	5/03/2026	GEN	39			LABEXT	TORDIE
PM133	XQ86MI	00085317	5/03/2026	GEN	39			CALL OUT FEE	TORDIE
PM133	XQ86MI	00085317	5/03/2026	GEN	39			CON	TORDIE
PM133	XQ86MI	00085317	5/03/2026	GEN	39			116	TORDIE
PM133	XQ86MI	00085317	5/03/2026	GEN	39			GENERAL PART	TORDIE
PM133	XQ86MI	00085317	5/03/2026	GEN	39			GENERAL PART	TORDIE
PM133	XQ86MI	00085899	26/03/2026	CUMAE5	00	LABOUR MECH			
PM133	XQ86MI	00085899	26/03/2026	CUMAE5		A SERVICE COMPLETED.			
PM133	XQ86MI	00085899	26/03/2026	CUMAE5	16	FIRE EXT EXP: CON YAT			
PM133	XQ86MI	00085899	26/03/2026	CUMBE5	01	LABOUR APPRENJC			
PM133	XQ86MI	00085899	26/03/2026	CUMBE5		B SERVICE COMPLETED.BY WORKSHOP 26/03/2026 FIRE EXT EXP: OCTOBER 2026 EYEWASH EXP - MAY 2 REPLACED SUMP GASKET REPLACED FRONT DRIVE BRAKE SHOES REBUILT HC REPLACED FRONT COVER GASKET REPLACED FAN E BELT REPLACED 4 X BATTERIES CON YAT			
PM133	XQ86MI	00085899	26/03/2026	CUMBE5	16				
PM133	XQ86MI	00085899	26/03/2026	CUMBE5	00	LABOUR APPREN			
PM133	XQ86MI	00085899	26/03/2026	CUMBE5	06			RSK154	YAT
PM133	XQ86MI	00085899	26/03/2026	CUMBE5	40			3413005	YAT
PM133	XQ86MI	00085899	26/03/2026	CUMBE5	16			4026684	YAT
PM133	XQ86MI	00085899	26/03/2026	CUMBE5	16			KSMA2124707Q	YAT
PM133	XQ86MI	00085899	26/03/2026	CUMBE5	11			12PK2380	YAT
PM133	XQ86MI	00085899	26/03/2026	CUMBE5	11			6PK1590	YAT
PM133	XQ86MI	00085899	26/03/2026	CUMBE5	16			MF70ZZDT	YAT
PM133	XQ86MI	00085899	26/03/2026	CUMBE5	16			6303173	YAT
PM133	XQ86MI	00085899	26/03/2026	DEFECT	01	LABOUR MECH			
PM133	XQ86MI	00085899	26/03/2026	DEFECT		DEFECT CLEARED.			

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00085899	26/03/2026	DEFECT		Reported Defect :-Defect Code : 00016382			
PM133	XQ86MI	00086058	9/04/2026	DEFECT	01	Defect Reference : PM133 Date : 11/02/2026 Description o			
						LEAKING			
						LABOUR MECH			
PM133	XQ86MI	00086058	9/04/2026	DEFECT		DEFECT CLEARED.			
PM133	XQ86MI	00086058	9/04/2026	DEFECT		Reported Defect :-Defect Code : 00017037			
PM133	XQ86MI	00086058	9/04/2026	GEN	39	Defect Reference : 51406 Date : 09/04/2026 Description of			
						CLUTCH PEDAL HAS 5-6CM OF TRAVEL/PLAY			
						LABOUR APPREN			
PM133	XQ86MI	00086058	9/04/2026	GEN		REPAIR COMPLETED BY WORKSHOP 09/04/2026			
						JOB COMPLAINT			
						-CLUTCH ADJUSTMENT NEEDED			
						COULDNT FAULT, GOOD FREE TRAVEL AND CLUTCH			
PM133	XQ86MI	00086058	9/04/2026	GEN	16			CON	YAT
PM133	XQ86MI	00086134	15/04/2026	GEN	39			LABEXT	
PM133	XQ86MI	00086134	15/04/2026	GEN	39			61-SC3MTLTSE	
PM133	XQ86MI	00086134	15/04/2026	GEN	39			ASA93-35	
PM133	XQ86MI	00086134	15/04/2026	GEN	39			ASA93-90	
PM133	XQ86MI	00086134	15/04/2026	GEN	39			MISCON	
PM133	XQ86MI	00086134	15/04/2026	GEN	39			ENVLEV	
PM133	XQ86MI	00086134	15/04/2026	GEN		REPAIR COMPLETED BY BROWN N HURLEY DARRA 15			
						INVOICE #3846171			
						QC INSTALL SAFETY EQUIPMENT. Completed Quick Che			
						K011 Blue suzie linie ripped out replace both with new set			
						Found suzi line snapped 1ft up away from fitting, suspect line			
						strapped together and fit to vehicle, tested operation, all okay			
PM133	XQ86MI	00086134	15/04/2026	GEN	39			LABEXT	BI
PM133	XQ86MI	00086134	15/04/2026	GEN	39			61-SC3MTLTSE	BI
PM133	XQ86MI	00086134	15/04/2026	GEN	39			ASA93-35	BI
PM133	XQ86MI	00086134	15/04/2026	GEN	39			ASA93-90	BI
PM133	XQ86MI	00086134	15/04/2026	GEN	39			MISCON	BI
PM133	XQ86MI	00086134	15/04/2026	GEN	39			ENVLEV	BI
PM133	XQ86MI	00086386	24/04/2026	GEN	39			SO 8010	KI
PM133	XQ86MI	00086386	24/04/2026	GEN	39			GENERAL PART	KI

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00086386	24/04/2026	GEN	39			GENERAL PART	
PM133	XQ86MI	00086386	24/04/2026	GEN	39			2175254	
PM133	XQ86MI	00086386	24/04/2026	GEN	39			1200234	
PM133	XQ86MI	00086386	24/04/2026	GEN	39			LABEXT	
PM133	XQ86MI	00086386	24/04/2026	GEN		WORK COMPLETED BY KENNY'S AUTO ELECTRICAL 24			
						INVOICE #63557			
						REMOVED BOTH LEAKING FUEL LINES AND MADE NEW			
						RAN THE ENGINE FOR A WHILE AND NOTHING WAS W			
PM133	XQ86MI	00086386	24/04/2026	GEN	39			SO 8010	KI
PM133	XQ86MI	00086386	24/04/2026	GEN	39			GENERAL PART	KI
PM133	XQ86MI	00086386	24/04/2026	GEN	39			GENERAL PART	KI
PM133	XQ86MI	00086386	24/04/2026	GEN	39			2175254	KI
PM133	XQ86MI	00086386	24/04/2026	GEN	39			1200234	KI
PM133	XQ86MI	00086386	24/04/2026	GEN	39			LABEXT	KI

PM133	XQ86MI	00086616	6/05/2026	CUMAE5	00	LABOUR MECH 7					
PM133	XQ86MI	00086616	6/05/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 06/05/2026					
						FIRE EXT EXP: NOVEMBER 2026					
PM133	XQ86MI	00086616	6/05/2026	CUMAE5	16	REPLACED LOWER HEATER TAP AS NEEDED, TOP UI YAT					
PM133	XQ86MI	00086616	6/05/2026	CUMAE5	00	LABOUR APPREND					
PM133	XQ86MI	00086616	6/05/2026	CUMAE5	00	LABOUR MECH 6					
PM133	XQ86MI	00086617	6/05/2026	DEFECT	01	LABOUR MECH					
PM133	XQ86MI	00086617	6/05/2026	DEFECT		DEFECT CLEARED.					
PM133	XQ86MI	00086617	6/05/2026	DEFECT		Reported Defect :-Defect Code : 00017241 Defect Reference : PM133 Date : 04/05/2026 Description of Defect :					
						ICEPACK DROPPED ALL OF ITS OIL OUT NOT SURE Y IT WAS					
PM133	XQ86MI	00086617	6/05/2026	ECO	01	LABOUR MECH 7					
PM133	XQ86MI	00086617	6/05/2026	ECO		ECO WIND SERVICE COMPLETED BY WORKSHOP 06/					
						SERVICED SLEEPER AS IT HAD DROPPED ALL OIL, CHECK F INJECTOR					
PM133	XQ86MI	00086617	6/05/2026	ECO	16			CON	YAT		
PM133	XQ86MI	00086617	6/05/2026	ECO	06			SA17117	YAT		
PM133	XQ86MI	00086617	6/05/2026	ECO	40			10W50	YAT		
PM133	XQ86MI	00086693	11/05/2026	CUMAE5	00	LABOUR APPRENJC					
Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code		W/H Code	S C
PM133	XQ86MI	00086693	11/05/2026	CUMAE5		A SERVICE COMPLETED BY WORKSHOP 11/05/2026					
						FIRE EXT EXP: NOVEMBER 2026					
PM133	XQ86MI	00086693	11/05/2026	CUMAE5	16	REPLACED MIRROR HEATER SWITCH REPLACED UNI 2ND JOINTS CON YAT					
PM133	XQ86MI	00086693	11/05/2026	CUMAE5	00	LABOUR MECH 6					
PM133	XQ86MI	00086693	11/05/2026	CUMAE5	00	LABOUR MECH 7					
PM133	XQ86MI	00086693	11/05/2026	CUMAE5	40			3413005	YAT		
PM133	XQ86MI	00086693	11/05/2026	CUMAE5	16			P27-1187-002	YAT		
PM133	XQ86MI	00086693	11/05/2026	CUMAE5	16			CP25RPLS1PZ	YAT		
PM133	XQ86MI	00086693	11/05/2026	DEFECT	01	LABOUR MECH					
PM133	XQ86MI	00086693	11/05/2026	DEFECT		DEFECT CLEARED.					
PM133	XQ86MI	00086693	11/05/2026	DEFECT		Reported Defect :-Defect Code : 00017085					
PM133	XQ86MI	00086693	11/05/2026	DEFECT		Defect Reference : PM133 Date : 16/04/2026 Description o ICE PACK IS NOT STARTING/WORK IVE NOTIFIED THE Reported Defect :-					
						Defect Code : 00017232 Defect Reference : PM133 Date : WILL NEED TO BE LOOKED AT WHEN IT RETURNS TC Reported Defect :-					
PM133	XQ86MI	00086693	11/05/2026	DEFECT		Defect Code : 00017240 Defect Reference : PM133 Date : MIRROR HEATERS NOT WORKING SWITCH Reported Defect :-					
PM133	XQ86MI	00086693	11/05/2026	DEFECT		Defect Code : 00015150 Defect Reference : PM133 Date : MINOR MOVEMENT IN FIRST UNI JOINT Reported Defect :-					
PM133	XQ86MI	00086693	11/05/2026	DEFECT		Defect Code : 00016522 Defect Reference : PM133 Date : DRIVER WINDOW SOMETIMES WONT GO DOWN AND LABOUR MECH 7					
PM133	XQ86MI	00086694	11/05/2026	GEN	39						

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00086694	11/05/2026	GEN		REPAIR COMPLETED BY WORKSHOP 11/05/2026				
						JOB COMPLAINT -SLEEPER 'RAN ON'				
						DRIVER STATES SLEEPER 'FAN ON' SO HE HAS UNPL INSPECT AND FOUN D TO HAVE 1.75L OF OIL IN SUMF FOUND MULTIPLE FUEL LEAKS, SO HAVE REPLACED RUN UP OK FILL ENGINE OIL TO MAX LINE EXACTLY AND RUN FOI				
						CON	YAT			C
PM133	XQ86MI	00086694	11/05/2026	GEN	16					
PM133	XQ86MI	00086694	11/05/2026	GEN	16			ED0065851390S	YAT	
PM133	XQ86MI	00086694	11/05/2026	GEN	40			10W50	YAT	
PM133	XQ86MI	00086694	11/05/2026	GEN	06			SA17117	YAT	
PM133	XQ86MI	00086694	11/05/2026	GEN	06			SN 80008	YAT	
PM133	XQ86MI	00087000	22/05/2026	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00087000	22/05/2026	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00087000	22/05/2026	GEN	39	LABOUR MECH 7				
PM133	XQ86MI	00087000	22/05/2026	GEN		REPAIR COMPLETED BY WORKSHOP 22/05/2026				
						REMOVE AND REPLACE FUEL LIFT PUMP ON SLEEPER AS W REPLACED AIR FILTER AND CLEAN OFF SIDE OF SLEEPER F REPLACE HEATER TAP ON REAR OF MOTOR TOP UP COOLA				
PM133	XQ86MI	00087000	22/05/2026	GEN	16			CON	YAT	
PM133	XQ86MI	00087000	22/05/2026	GEN	00	LABOUR MECH 5				
PM133	XQ86MI	00087000	22/05/2026	GEN	16			SA17117	YAT	
PM133	XQ86MI	00087000	22/05/2026	GEN	16			15W40REDS	YAT	
PM133	XQ86MI	00087000	22/05/2026	GEN	16			L-0065850960	YAT	
PM133	XQ86MI	00089057	2/07/2026	TYRES	15			YFPSI		
PM133	XQ86MI	00089057	2/07/2026	TYRES		COMPLETED BY YOKOHAMA 02/07/2026				
						INVOICE #IN-100808-2026				
										PO:PM133- YFS:1261
PM133	XQ86MI	00089057	2/07/2026	TYRES	15					Y
PM133	XQ86MI	00089795	31/08/2026	TYRES	39			29580225124R	YOKTYF	
PM133	XQ86MI	00089795	31/08/2026	TYRES	39			YFSFTB	YOKTYI	
PM133	XQ86MI	00089795	31/08/2026	TYRES	39			YFBALTB	YOKTYI	
PM133	XQ86MI	00089795	31/08/2026	TYRES	39			YFDCTB	YOKTYF	
PM133	XQ86MI	00089795	31/08/2026	TYRES		SERVICE COMPLETED BY YOKOHAMA 31/08/2026 - FL				
PM133	XQ86MI	00089795	31/08/2026	TYRES	39			29580225124R	YOKTYF	
PM133	XQ86MI	00089795	31/08/2026	TYRES	39			YFSFTB	YOKTYI	

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	
PM133	XQ86MI	00089795	31/08/2026	TYRES	39			YFBALTB	YOKTYI	
PM133	XQ86MI	00089795	31/08/2026	TYRES	39			YFDCTB	YOKTYF	
PM133	XQ86MI	00089558	2/09/2026	CUMAE5	00	LABOUR MECH				
PM133	XQ86MI	00089558	2/09/2026	CUMAE5		A SERVICE COMPLETED.				
PM133	XQ86MI	00089558	2/09/2026	CUMAE5	16	FIRE EXT EXP: CON	YAT			C
PM133	XQ86MI	00089558	2/09/2026	CUMBE5	01	LABOUR BILLY				
PM133	XQ86MI	00089558	2/09/2026	CUMBE5		B SERVICE COMPLETED BY WORKSHOP 02/09/2026				
						FIRE EXT EXP: OCTOBER 2026				
PM133	XQ86MI	00089558	2/09/2026	CUMBE5	16	REPLACED FRONT ENGINE MOUNTS AS REQUIRED CON	YAT			C
PM133	XQ86MI	00089558	2/09/2026	CUMBE5	00	LABOUR APPREND				
PM133	XQ86MI	00089558	2/09/2026	CUMBE5	06			MK13555	YAT	
PM133	XQ86MI	00089558	2/09/2026	CUMBE5	06			AS2474	YAT	
PM133	XQ86MI	00089558	2/09/2026	CUMBE5	40			3413005	YAT	
PM133	XQ86MI	00089558	2/09/2026	CUMBE5	03			K066-404	YAT	
PM133	XQ86MI	00089558	2/09/2026	CUMBE5	03			D13-1012	YAT	
PM133	XQ86MI	00089567	2/09/2026	GEN	39			LABEXT		

PM133	XQ86MI	00089567	2/09/2026	GEN		REPAIR COMPLETED BY QUALITY WINDSCREENS 02/						
						INVOICE #9026						
						SERVICES						
PM133	XQ86MI	00089567	2/09/2026	GEN	39	SUPPLY AND FIT FRONT WINDSCREEN RHS KENWOF						
						LABEXT	QUAWIND01 9026					Lat
PM133	XQ86MI	00089692	4/09/2026	CUMCE5	01	LABOUR BILLY						
PM133	XQ86MI	00089692	4/09/2026	CUMCE5		C SERVICE COMPLETED BY WORKSHOP 04/09/2026						
						FIRE EXT EXP: JAN 2027						
PM133	XQ86MI	00089692	4/09/2026	CUMCE5	16	CON	YAT					C
PM133	XQ86MI	00089692	4/09/2026	CUMCE5	00	LABOUR APPREND						
PM133	XQ86MI	00089692	4/09/2026	CUMCE5	16			F37-TP-1000	YAT			
PM133	XQ86MI	00089692	4/09/2026	CUMCE5	16		A-3380W1687	YAT				
PM133	XQ86MI	00089692	4/09/2026	CUMCE5	16		17237	YAT				
PM133	XQ86MI	00089692	4/09/2026	CUMCE5	16		LF637	YAT				
PM133	XQ86MI	00089692	4/09/2026	CUMCE5	16		WF2127	YAT				
PM133	XQ86MI	00089692	4/09/2026	DEFECT	01	LABOUR MECH						
PM133	XQ86MI	00089693	4/09/2026	DEFECT	01	LABOUR MECH						
PM133	XQ86MI	00089710	4/09/2026	DEFECT	01	LABOUR MECH						
PM133	XQ86MI	00089692	4/09/2026	DEFECT		DEFECT CLEARED.						
PM133	XQ86MI	00089693	4/09/2026	DEFECT		DEFECT CLEARED.						
PM133	XQ86MI	00089710	4/09/2026	DEFECT		DEFECT CLEARED.						
PM133	XQ86MI	00089693	4/09/2026	EXOINS	01	LABOUR BILLY						

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code	S C
PM133	XQ86MI	00089693	4/09/2026	EXOINS		VEHICLE PASSED ANNUAL ROADWORTHY INSPECTIC				
						#1				
						INSPECTION COMPLETED BY WORKSHOP				
PM133	XQ86MI	00089786	4/09/2026	GEN	16	R945008		BROHUR01		
PM133	XQ86MI	00089710	4/09/2026	GEN	39	LABOUR BILLY				
PM133	XQ86MI	00089786	4/09/2026	GEN	16			K1T2637	BROHU	
PM133	XQ86MI	00089710	4/09/2026	GEN		REPAIR COMPLETED BY WORKSHOP 04/09/2026				
						REPLACED BACK DRIVE HUB SEALS				
						REPLACED BACK DRIVE BRAKE SHOES, DRUMS REPL				
						REPLACED BACKING PLATE ON STEER				
						REPLACED LEAKING THROUGH SHAFT SEAL 3 NUT WA				
PM133	XQ86MI	00089786	4/09/2026	GEN	16			R945008		
PM133	XQ86MI	00089710	4/09/2026	GEN	16			CON	YAT	
PM133	XQ86MI	00089786	4/09/2026	GEN	16			K1T2637		
PM133	XQ86MI	00089710	4/09/2026	GEN	00	LABOUR APPREND				
PM133	XQ86MI	00089710	4/09/2026	GEN	16			43764	YAT	
PM133	XQ86MI	00089710	4/09/2026	GEN	16			KSMA2124707Q	YAT	
PM133	XQ86MI	00089710	4/09/2026	GEN	16			DB017TRP	YAT	
PM133	XQ86MI	00089710	4/09/2026	GEN	16			1K9541	YAT	
PM133	XQ86MI	00089710	4/09/2026	GEN	16			R945008	YAT	
PM133	XQ86MI	00089710	4/09/2026	GEN	16			2637	YAT	
PM133	XQ86MI	00089710	4/09/2026	GEN	16			A3264S227	YAT	
PM133	XQ86MI	00089710	4/09/2026	GEN	16			235 KIT	YAT	
PM133	XQ86MI	00089729	8/09/2026	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00089729	8/09/2026	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00089729	8/09/2026	GEN	39	LABOUR				
PM133	XQ86MI	00089729	8/09/2026	GEN		REPAIR COMPLETED BY WORKSHOP 08/09/2026				
						CLEANED RADIATOR AS PER REQUES				
PM133	XQ86MI	00089729	8/09/2026	GEN	16			CON	YA	
PM133	XQ86MI	00089729	8/09/2026	GEN	00	LABOUR RAM				
PM133	XQ86MI	00089822	10/09/2026	DEFECT	01	LABOUR MECH				
PM133	XQ86MI	00089822	10/09/2026	DEFECT		DEFECT CLEARED.				
PM133	XQ86MI	00089822	10/09/2026	ECO	01	LABOUR APPRENJC				
PM133	XQ86MI	00089822	10/09/2026	ECO		ECO WIND SERVICE COMPLETED BY WROKSHOP ON				
						NO COMMENTS				
PM133	XQ86MI	00089822	10/09/2026	ECO	16	3413005	YAT			
PM133	XQ86MI	00089822	10/09/2026	ECO	16			SO8010	YAT	

PM133	XQ86MI	00089822	10/09/2026	ECO	16			CON	YAT
PM133	XQ86MI	00089822	10/09/2026	ECO	16			SN80008	YAT
PM133	XQ86MI	00089822	10/09/2026	ECO	16			Z119	YAT

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code
PM133	XQ86MI	00089822	10/09/2026	ECO	16			SA17117	YAT
PM133	XQ86MI	00089822	10/09/2026	ECO	16			13A0980	YAT
PM133	XQ86MI	00089839	11/09/2026	DEFECT	01	LABOUR	MECH		
PM133	XQ86MI	00089839	11/09/2026	DEFECT		DEFECT	CLEARED.		
PM133	XQ86MI	00089839	11/09/2026	GEN	39	LABOUR APPRENJC			
PM133	XQ86MI	00089839	11/09/2026	GEN		REPAIR COMPLETED BY WORKSHOP ON 11/09/2026			
						R+ R SLEEPER AIT MOTOR COMPLETED - FULL SERVICE ON			
						R+R FAN BELT TENSIONER			
						REPLACED 4X REAR GUARDS AND CHROME STRIPS R+R FA			
						REPLACED RHS TANK STRAP RUBBER REPLACED MUD FLAI			
PM133	XQ86MI	00089839	11/09/2026	GEN	16			CON	YAT
PM133	XQ86MI	00089839	11/09/2026	GEN	16			CA5709M	YAT
PM133	XQ86MI	00089839	11/09/2026	GEN	16			12PK2380	YAT
PM133	XQ86MI	00089839	11/09/2026	GEN	16			6PK1590	YAT
PM133	XQ86MI	00089839	11/09/2026	GEN	16			89440	YAT
PM133	XQ86MI	00090231	11/09/2026	TYRES	15			YFSFTBX	Y(
PM133	XQ86MI	00090231	11/09/2026	TYRES		SERVICE COMPLETED BY YOKOHAMA 11/09/2026 - F			
						ODO:305062KM - FN:PM133 - RN:11-9-2026 fit 2 run ou			
PM133	XQ86MI	00090231	11/09/2026	TYRES	15			YFSFTBX	Y(

Asset Code	Registration	Work Order Code	Work Order Date	Service Code	RM Categor	Task Code	Employee Code	Product Code	W/H Code

Report Options:

Sort By	- AssetCode
Starting Asset Code	- PM133
To	- PM133
Starting Registration	-
To	-
Starting Operations No	-
To	-
From: Work Order Location	-
To	-
From: Work Order Date	- 01/01/1901
To	- 31/12/9999
From: Completion Date	-
To	-
From: RM Category Code	-
To	-
Starting Category Code	-
To	-
Starting Owned By	-
To	-
Starting Based By	-
To	-
Starting Location	-
To	-
Assets For	- All Assets
Include Disposed Assets	- no
Warranty Items Only	- no
Include Non Active Assets	- no
Exclude Estimates	- no
Fleet Assets Only	- no
Service Code	-
Task Code	-
Mechanic Code	-
Product Code	-
Warehouse	-
WO Supplier Code	-
Include All	- yes
Labour	- yes
Parts	- yes
Supplies	- yes

Tyres	- yes
Comments	- yes

Supplier Code	Invoice	Details	Purchase Order
		Labour	
		Labour - Internal	
		KINGS DRIVING LIGHTS 9"	
		Consumables	
BROHUR01	EX00015527	VECTON 15W40 CK4 BULK,	EX0001552
BROHUR01	EX00015527	Diff/Gear Oil 80W90 Castrol,	EX0001552
BROHUR01	EX00015527	Power Steer Filter LF637,	EX0001552
BROHUR01	EX00015527	Filter Element Gearbox Eaton,	EX0001552
BROHUR01	EX00015527	Element 10 Micron,	EX0001552
BROHUR01	EX00015527	Ad Blue filter Kenworth,	EX0001552
BROHUR01	EX00015527	Filter Diff,	EX0001552
BROHUR01	EX00015527	Oil Filter (was LF9080),	EX0001552
BROHUR01	EX00015527	ES Water Filter,	EX0001552
BROHUR01	EX00015527	FF5776 Fuel Filter,	EX0001552
BROHUR01	EX00015527	GREASE,	EX0001552
BROHUR01	EX00015527	ENVIRONMENTAL LEVY,	EX0001552
BROHUR01	EX00015527	ROUNDING,	EX0001552
BROHUR01	2003142	VECTON 15W40 CK4 BULK,	EX0001552
BROHUR01	2003142	Diff/Gear Oil 80W90 Castrol,	EX0001552
BROHUR01	2003142	Power Steer Filter LF637,	EX0001552
BROHUR01	2003142	Filter Element Gearbox Eaton,	EX0001552
BROHUR01	2003142	Element 10 Micron,	EX0001552
BROHUR01	2003142	Ad Blue filter Kenworth,	EX0001552
BROHUR01	2003142	Filter Diff,	EX0001552
BROHUR01	2003142	Oil Filter (was LF9080),	EX0001552
BROHUR01	2003142	ES Water Filter,	EX0001552
BROHUR01	2003142	FF5776 Fuel Filter,	EX0001552
BROHUR01	2003142	GREASE,	EX0001552
BROHUR01	2003142	ENVIRONMENTAL LEVY,	EX0001552
BROHUR01	2003142	ROUNDING,	EX0001552

Labour		0.75
Labour - Internal		0.75
Consumables		3.00

Supplier Code	Invoice	Details	Purchase Order
		Labour	0.00
		Labour	4.00
UR APPREN			
		Labour - Internal	3.00
		Consumables	6.00
		FILTER KIT, OIL & FUEL FILTER, (E5)	1.00
		Ad Blue filter Kenworth	1.00
		OIL 15W-40, CK 4/E9	48.00
		EBS Plug, 7 pin 12/24v	1.00
		Element 10 Micron	1.00

)7/10/2020 Description of Defect :
S IN THE WRONG SPOT

)7/10/2020

LABOUR

		Labour	0.25
		Labour - Internal	0.25
		Consumables	2.00
		Air Filter Sleeper Air	1.00
		HITECH SYNPLUS 10W50	1.00
		Labour	1.00
		Labour - Internal	1.00
		Consumables	3.00

Supplier Code	Invoice	Details	Purchase Order
:CH		Labour	0.00
RIAUS01	EX00016883	ROTATE TBR TYRE,	EX0001688
RIAUS01	EX00016883	BALANCE TBR,	EX0001688
RIAUS01	85053092	BALANCE TBR,	EX0001688
RIAUS01	85053092	ROTATE TBR TYRE,	EX0001688
		Labour	
		Labour - Internal	0.75
		Labour - Internal	0.50
		Consumables	4.00

Defect : DUE

)9/01/2021

)7/10/2020

Supplier Code	Invoice	Details	Purchase Order

Defect :

:4/11/2020

		Labour		0.00
		Labour		3.00

RICAL COIL

		Labour - Internal		
		MAINTENANCE KIT		
		OIL 15W-40, CK 4/E9		
BRIAUS01	EX00017612	case stock 295/80-22.5,PM133	EX0001761	
BRIAUS01	EX00017612	BALANCE TBR,PM133	EX0001761	
BRIAUS01	85351968	case stock 295/80-22.5,PM133	EX0001761	
BRIAUS01	85351968	BALANCE TBR,PM133	EX0001761	
		Labour		0.00
		Labour		1.00

:1 LABOUR

		Labour - Internal		1.00
		Consumables		3.00
		Labour		1.00

REN

				1.00
		Consumables		8.00

upplier ode	Invoice	Details	Purchase Order

AIR GAUGE:

LABOUR

	Labour		0.00
	Labour		1.25
	Consumables		2.00
	MAINTENANCE KIT		1.00
	Element 10 Micron		1.00

Defect : DUE

.5/04/2021

0

AIR GAUGE: 15-

upplier ɔde	Invoice	Details	Purchase Order
LABOUR MECH1			
		Labour	0.75
		Labour - Internal	0.75
		Consumables	2.00
		Labour	0.50
		Labour - Internal	0.50
			2.00
		AIR FILTER SLEEPER AIR	1.00
		HITECH SYNPLUS 10W50	1.00
		Labour	1.00
		Labour - Internal	1.00
		Consumables	4.00
		Labour	0.75
		Labour - Internal	0.75
		Consumables	3.00
		Labour	3.00
PLATE 'LUG FITTED POGO STICK E			
		Labour - Internal	1.00
		Consumables	10.00
		Suzi Coil Long Tail	1.00
		Suzi Coil Long LONG TAIL SUZI COIL	1.00
		EBS Plug, 7 pin 12/24v	
briaus01	EX00019340	BALANCE TBR,PM133	EX0001934
briaus01	86032186	BALANCE TBR,PM133	EX0001934
		Labour	
		Labour	

Supplier Code	Invoice	Details	Purchase Order

		Consumables	
		MAINTENANCE KIT	
		OIL 15W-40, CK 4/E9	
		Labour - Internal	
		Consumables	
		AIR FILTER SLEEPER AIR	
		HITECH SYNPLUS 10W50	
NABQAN01	EX00019772	Labour,XQ86MI	EX0001977
NABQAN01	EX00019983	Labour,XQ86MI	EX0001998
NABQAN01	EX00020061	Labour,REVERSAL	EX0002006
NABQAN01	EX00019772	Consumables	EX0001977
NABQAN01	EX00019983	,XQ86MI	EX0001998
		Consumables	
NABQAN01	EX00020061	,PM133 GENERAL PART CODE,PM133	EX0002006
NABQAN01	EX00019772	ENVIRONMENTAL LEVY,XQ86MI	EX0001977
NABQAN01	EX00019983	ENVIRONMENTAL LEVY,PM133	EX0001998
NABQAN01	1023121	Labour,XQ86MI	EX0001977
NABQAN01	1023121	Consumables	EX0001977
NABQAN01	1023121	,XQ86MI ENVIRONMENTAL LEVY,XQ86MI	EX0001977
		Labour	
		Consumables	
		OIL 15W-40, CK 4/E9	
BROHUR01	EX00019804	GENERAL PART CODE,XQ86MI	EX0001980
BROHUR01	2237072	GENERAL PART CODE,XQ86MI	EX0001980
		Labour	
		Consumables	

Supplier Code	Invoice	Details	Purchase Order
		Labour	
		Labour	
		Labour - Internal	
		Consumables	
		MAINTENANCE KIT	
		OIL 15W-40, CK 4/E9	
		Element 10 Micron	
RIAUS01	EX00020427	case stock 295/80-22.5,PM133	EX0002042
RIAUS01	EX00020427	BALANCE TBR,PM133	EX0002042
RIAUS01	86448218	case stock 295/80-22.5,PM133	EX0002042
RIAUS01	86448218	BALANCE TBR,PM133	EX0002042
		Labour	
		Consumables	
		DIFF FILTER	
		Diff/Gear Oil 80W90 Castrol	
		Filter Element Gearbox Eaton	
		Syntrans Gear Oil 75w-90	
		Turbo 2000 Air dryer	
		TRP KW CAB AIR FILTER	
		ES Water Filter	
		Power Steer Filter LF637	

		Air Filter	
		Filter, Adblue	

3/2021 Description of Defect :

		Labour	1.00
		Consumables	3.00
		AIR FILTER SLEEPER AIR	1.00
		Fuel Filter (Sleeper Air)	1.00
		Oil Filter Eco/Sleeper	1.00
		Fuel/Water seperator filter	1.00
		HITECH SYNPLUS 10W50	1.00
		Labour	0.00

upplier ode	Invoice	Details	Purchase Order

ON. ATTEMPT #

EN

		Labour	1.00
		Consumables	3.00
		Labour	2.00

ROPPED A CELL PUT LOCKLITE ON BOTTOM GRILL BOLTS

		Labour - Internal	
		Consumables	
		DEEP CYCLE BATTERY	
BRIAUS01	EX00021045	PUNCTURE REPAIR TBR,PM133	EX0002104
BRIAUS01	86685770	PUNCTURE REPAIR TBR,PM133	EX0002104
		Labour	1.00
		Labour - Internal	1.00
		Consumables	3.00
		Labour	0.00
		Labour	1.50

BRACKET LABOUR MECH

		Labour - Internal	1.50
		Consumables	2.00
		MAINTENANCE KIT	1.00
		OIL 15W-40, CK 4/E9	47.00
		Labour	0.50
		Consumables	3.00
BRIAUS01	EX00021575	CASE STOCK 11-22.5,PM133	EX0002157
BRIAUS01	EX00021575	FIT TBR TYRE,PM133	EX0002157
BRIAUS01	86931410	FIT TBR TYRE,PM133	EX0002157
BRIAUS01	86931410	CASE STOCK 11-22.5,PM133	EX0002157
		Labour	
		Consumables	
		Labour	0.00

R MECH

		Labour - Internal	1.00

Supplier Code	Invoice	Details	Purchase Order
		Labour - Internal	
		Consumables	

		Labour - Internal	0.50
		Labour - Internal	0.50
		Consumables	3.00
		HITECH SYNPLUS 10W50	1.00
		Air Filter Sleeper Air	1.00
		Labour	0.00
		Labour	1.50
EW FILTER LABOUR APPREN			
		Labour - Internal	1.50
		Consumables	4.00
		MAINTENANCE KIT	1.00
		Oil Filter (was LF9080)	1.00
		Labour	0.00

IALS ARE CONECTED AND NOT WATER DAMAGED.

		Labour - Internal	0.50
		Consumables	2.00
		Labour	1.00
		Consumables	4.00

e : 07/01/2022

		Labour	1.00
		Labour - Internal	1.00
		Consumables	4.00
		Labour	1.00

upplier ode	Invoice	Details	Purchase Order
		Labour - Internal	
		Consumables	
		Labour	
		Labour	
3		Labour - Internal	
		Labour - Internal	
		Consumables	
		MAINTENANCE KIT	
		ENGINE OIL	
01	EX00023285	case stock 295/80-22.5,PM133	EX0002328
01	87529847	case stock 295/80-22.5,PM133	EX0002328
		Labour	

Labour

Labour - Internal

Consumables
CLIP VISOR
Labour

Consumables
Labour

Labour - Internal

Consumables

LABOUR

Labour

Supplier Code	Invoice	Details	Purchase Order
		Labour - Internal	
		Consumables	

on of Defect :

		Labour	0.50
		Labour - Internal	0.50
		Consumables	2.00
		AIR FILTER SLEEPER AIR	1.00
		HITECH SYNPLUS 10W50	1.00
RIAUS01	EX00023779	CASE STOCK 11-22.5,PM133	EX0002377
RIAUS01	87803796	CASE STOCK 11-22.5,PM133	EX0002377
		Labour	1.50
J			
		Labour - Internal	1.50
		Labour - Internal	1.50
		Consumables	5.00
		Oil Filter (was LF9080)	1.00
		FF5776 Fuel Filter	1.00
		Element 10 Micron	1.00
		Ad Blue filter Kenworth	1.00
		OIL 15W-40, CK 4/E9	48.00
		Labour	0.00
			0.50
		Labour - Internal	0.50
		Consumables	3.00

upplier ode	Invoice	Details	Purchase Order
LABOUR			
		Labour	1.00
		Consumables	3.00
		Labour	2.00
EPLACED LHS			
		Labour - Internal	0.50
		Consumables	5.00
		Indicator LED Hella	1.00
DEFECT			
NEEDS			
		Labour	0.25
		Labour - Internal	0.25
		Consumables	1.00
		Labour	18.00
		Labour - Internal	10.00
		Labour - Internal	12.00
		Consumables	11.00
		CLUTCH KIT INC KW X SHAFTS	1.00
		Labour	1.00

upplier ode	Invoice	Details	Purchase Order
LACED FITTING			
		Labour - Internal	
		Consumables	
		Labour	
IR01	EX00024535	Labour,XQ86MI	EX0002453
IR01	2539136	Labour,XQ86MI	EX0002453
R01	EX00024596	CLUTCH KIT-ADVANTAGE,XQ86MI	EX0002459
R01	EX00024596	CLUTCH KIT INC KW X SHAFTS,XQ86MI	EX0002459
IR01	EX00024596	GENERAL PART CODE,XQ86MI	EX0002459
IR01	2542217	GENERAL PART CODE,XQ86MI	EX0002459
R01	2542217	CLUTCH KIT INC KW X SHAFTS,XQ86MI	EX0002459
R01	2542217	CLUTCH KIT-ADVANTAGE,XQ86MI	EX0002459
		Labour	
		Labour	

OR LEAKING			
		Labour - Internal	
		Consumables	
		MAINTENANCE KIT	
		OIL 15W-40, CK 4/E9	
		Element 10 Micron	
IR01	EX00024866	Labour,XQ86MI	EX0002486
R01	EX00024866	ENGINE MOUNT,PM133	EX0002486
IR01	EX00024866	GENERAL PART CODE,PM133	EX0002486
1608			
	2561608	GENERAL PART CODE,PM133	EX0002486
R01	2561608	ENGINE MOUNT,PM133	EX0002486
IR01	2561608	Labour,XQ86MI	EX0002486
		Labour	
		Consumables	
01	EX00025017	BALANCE TBR,PM133	EX0002501
01	88319798	BALANCE TBR,PM133	EX0002501

Supplier Code	Invoice	Details	Purchase Order	
		Labour		1.00
JEL PUMP CON				
		Consumables		3.00
		Labour		0.00
		Labour - Internal		1.25
		Consumables		4.00
		Labour		0.00
		Labour - Internal		0.50
				1.00
		AIR FILTER SLEEPER AIR		1.00
		Labour		0.00
		Labour		0.00
		Labour - Internal		2.50
		Consumables		4.00
		MAINTENANCE KIT		1.00
		OIL 15W-40, CK 4/E9		49.00
		Labour		1.00
		Consumables		3.00
		Labour		3.50
APPRENB				
		Labour - Internal		3.50
		Consumables		4.00
		Turbo 2000 Air dryer		1.00
		ES Water Filter		1.00
		Power Steer Filter LF637		1.00
		DIFF FILTER		1.00
		Filter Element Gearbox Eaton		1.00
		TRP KW CAB AIR FILTER		1.00
		Air Filter		1.00
		DIFF OIL AEM		34.00

		Syntrans Gear Oil 75w-90		12.00
Supplier Code	Invoice	Details	Purchase Order	
Defect :				
PRENB				
		Labour		1.00
		Consumables		3.00
		Fuel Filter (Sleeper Air)		1.00
		OIL STRAINER		1.00
		BS358N 70 O-RING 142.24 X 5.3		1.00
		HITECH SYNPLUS 10W50		1.00
		Fuel/Water seperator filter		1.00
		Labour		1.00
ON. ATTEMPT # 1				
EN		Labour		1.00
MECH		Labour - Internal		0.50
		Consumables		3.00
Defect : DUE FOR SERVICE				
		Labour		1.00
IECH		Labour - Internal		1.00
		Consumables		2.00
		Labour		0.00
		Labour		6.00
EAKING SERVICE		MAINTENANCE KIT		1.00
		OIL 15W-40, CK 4/E9		49.00
		Seal -Steer MFS73		1.00
		Consumables		5.00
Supplier Code	Invoice	Details	Purchase Order	
		Labour		0.00
.E TANK RHS LABOUR		Labour - Internal		0.50
		Labour - Internal		1.00
		Consumables		4.00
		Labour		1.00
T HAS GONE OUT GREASED				

20/01/2023 Description of Defect :

E RATTLE UNDER FRONT END

Labour - Internal		1.00
Consumables		3.00

ACE LEAKING VALVES
GAS TEST AC SYSTEM - ALL

BDSMEC01	EX00026800	Labour External,	EX0002680
BDSMEC01	EX00026800	Workshop Consumables	EX0002680
BDSMEC01	EX00026800	,	EX0002680
		ENVIRONMENTAL LEVY,	
BDSMEC01	GC-RIN02990	ENVIRONMENTAL LEVY,	EX0002680
BDSMEC01	GC-RIN02990	Workshop Consumables	EX0002680
BDSMEC01	GC-RIN02990	,	EX0002680
		Labour External,	
		Labour	
		Labour - Internal	
		Consumables	
		Labour	

upplier ode	Invoice	Details	Purchase Order

70 hrs Fuel Burn:

nty repairs.

d vehicle to

our: $595.20 +

2 + GST Air

onsumables:

TAL: $8,683.01

	EX00027021	Labour External + Parts,	EX0002702
N01	9663403	Labour External + Parts,	EX0002702
		Labour	
OUR APPREN			
		Labour - Internal	

VECTRON 15W-40 CK-4/E9	
Consumables	
Labour	
Labour	
Labour	0.50
EBS Plug, 7 pin 12/24v	1.00
Consumables	3.00

upplier ode	Invoice	Details	Purchase Order

checks and found bolt on clutch arm missing. Fit replacement bolt and nut.

AUTELE01	EX00027551	Labour External,	EX0002755
AUTELE01	EX00027551	SUNDRIES - GREASE,	EX0002755
AUTELE01	EX00027551	Consumables	EX0002755
AUTELE01	00009853	, Consumables	EX0002755
AUTELE01	00009853	, SUNDRIES - GREASE,	EX0002755
AUTELE01	00009853	Labour External,	EX0002755
BRIAUS01	EX00027468	RUNOUT TYRE,PM133	EX0002746
BRIAUS01	EX00027468	case stock 295/80-22.5,PM133	EX0002746
BRIAUS01	EX00027468	FIT TBR TYRE,PM133	EX0002746
BRIAUS01	EX00027468	REMOVAL: CUSTOMER PULL	EX0002746
BRIAUS01	EX00027468	POINT,PM133 BALANCE TBR,PM133	EX0002746
BRIAUS01	89265458	BALANCE TBR,PM133	EX0002746
BRIAUS01	89265458	REMOVAL: CUSTOMER PULL	EX0002746
BRIAUS01	89265458	POINT,PM133 FIT TBR TYRE,PM133	EX0002746
BRIAUS01	89265458	case stock 295/80-22.5,PM133	EX0002746
BRIAUS01	89265458	RUNOUT TYRE,PM133	EX0002746
		Labour	
		Labour	

UNCTIONED WELL, CLEARED ALL DOWN WILL MONITOR

MAINTENANCE KIT	1.00
OIL 15W-40, CK 4/E9	48.00
Suzi Coil Long Tail	1.00
Consumables	4.00
Labour	0.00

Supplier Code	Invoice	Details	Purchase Order

on of Defect :
OR LEAKING

)8/11/2022

		Labour	
		HITECH SYNPLUS 10W50	
		AIR FILTER SLEEPER AIR	
		Consumables	

SLEEPER A/C

ɔmer supplied).
all ok.

	EX00027565	Labour External,	EX0002756
C01	EX00027557	Labour External,	EX0002755
C01	EX00027565	Travel Fee to Breakdowns,	EX0002756
C01	EX00027557	Travel Fee to Breakdowns,	EX0002755
		Labour	

APPRENF

		Labour - Internal	
		Consumables	
		Labour	

)CK

		Labour - Internal	
		GENERAL PART CODE - T5418 SHOCK ABSORBER	
		Consumables	
		TANK CABLE	
		Consumables	
;01	EX00028092	295/80R22.5 152/148M BS R154 ECO,	EX0002809

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	EX00028092	EQUAL POWDER - DROP IN,	EX0002809
BRIAUS01	EX00028092	FIT TBR TYRE,	EX0002809
BRIAUS01	EX00028092	SCRAP TYRES TBR,	EX0002809
BRIAUS01	EX00028092	ETA MIN FEE,	EX0002809
BRIAUS01	4720108125	ETA MIN FEE,	EX0002809
BRIAUS01	4720108125	SCRAP TYRES TBR,	EX0002809
BRIAUS01	4720108125	FIT TBR TYRE,	EX0002809
BRIAUS01	4720108125	EQUAL POWDER - DROP IN,	EX0002809
BRIAUS01	4720108125	295/80R22.5 152/148M BS R154 ECO,	EX0002809
BRIAUS01	EX00028103	B FLEET PRESSURE CHECK,	EX0002810
BRIAUS01	89512660	B FLEET PRESSURE CHECK,	EX0002810
		Labour	
		Labour - Internal	
		Consumables	
		Labour	
		Labour	
		Labour - Internal	
		MAINTENANCE KIT	
		OIL 15W-40, CK 4/E9	
		Consumables	
		Labour	
		Labour - Internal	
		Consumables	

BRIAUS01	EX00028897	11R22.5 148/145L BS M866,	EX0002889
BRIAUS01	EX00028914	B FLEET PRESSURE CHECK,	EX0002891
BRIAUS01	EX00028897	CASE STOCK 11-22.5,	EX0002889
BRIAUS01	89759358	B FLEET PRESSURE CHECK,	EX0002891
BRIAUS01	EX00028897	FIT TBR TYRE,	EX0002889
BRIAUS01	EX00028897	REMOVAL: CUSTOMER PULL POINT,	EX0002889
BRIAUS01	EX00028897	SCHEDULED DEPOT SERVICE 15MIN,	EX0002889
BRIAUS01	89759356	11R22.5 148/145L BS M866,	EX0002889
BRIAUS01	89759356	CASE STOCK 11-22.5,	EX0002889
BRIAUS01	89759356	FIT TBR TYRE,	EX0002889
BRIAUS01	89759356	REMOVAL: CUSTOMER PULL POINT,	EX0002889
BRIAUS01	89759356	SCHEDULED DEPOT SERVICE 15MIN,	EX0002889
		Labour	

Supplier Code	Invoice	Details	Purchase Order
		Labour - Internal	
		Consumables	
		Labour	1.50
/INDOW LABOUR APPREN			
		Labour - Internal	1.50
		Consumables	
		Labour	
		Labour - Internal	
		Consumables	
		OIL 15W-40, CK 4/E9	
		AIR FILTER SLEEPER AIR	
		Labour	
		Labour	
		Labour - Internal	
		Consumables	
		OIL 15W-40, CK 4/E9	
		Ad Blue filter Kenworth	
		Drive Belt, K200	
		M/Ribbed belt (A/C)	
		Oil Filter (was LF9080)	
		FF5776 Fuel Filter	
BRIAUS01	EX00029523	11R22.5 148/145L BS M866,	EX0002952
BRIAUS01	EX00029523	ETA MIN FEE,	EX0002952
BRIAUS01	EX00029523	FIT TBR TYRE,	EX0002952
BRIAUS01	EX00029523	SCRAP TYRES TBR,	EX0002952
BRIAUS01	EX00029523	POS 8,	EX0002952
BRIAUS01	EX00029523	SERVICE FITTER ETHAN,	EX0002952
BRIAUS01	EX00029523	ETA 137368,	EX0002952
BRIAUS01	EX00029523	DRIVER BRENDON WILLIAMS,	EX0002952
BRIAUS01	89986939	11R22.5 148/145L BS M866,	EX0002952
BRIAUS01	89986939	ETA MIN FEE,	EX0002952
BRIAUS01	89986939	FIT TBR TYRE,	EX0002952
BRIAUS01	89986939	SCRAP TYRES TBR,	EX0002952
BRIAUS01	89986939	POS 8,	EX0002952
BRIAUS01	89986939	SERVICE FITTER ETHAN,	EX0002952
BRIAUS01	89986939	ETA 137368,	EX0002952
BRIAUS01	89986939	DRIVER BRENDON WILLIAMS,	EX0002952
BRIAUS01	EX00029563	PUNCTURE REPAIR TBR,	EX0002956
BRIAUS01	EX00029565	PUNCTURE REPAIR TBR,	EX0002956

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	89986155	PUNCTURE REPAIR TBR,	EX0002956
BRIAUS01	EX00029565	SCHEDULED DEPOT SERVICE 15MIN,	EX0002956
BRIAUS01	89986059	PUNCTURE REPAIR TBR,	EX0002956
BRIAUS01	89986059	SCHEDULED DEPOT SERVICE 15MIN,	EX0002956

BNTAUT01	EX00029580	BATTERY PRO CHOICE MF70ZZ,	EX0002958
BNTAUT01	EX00029580	CALLOUT (BREAKDOWN),	EX0002958
BNTAUT01	EX00029580	Consumables	EX0002958
BNTAUT01	17514	,	EX0002958
		BATTERY PRO CHOICE MF70ZZ,	
BNTAUT01	17514	CALLOUT (BREAKDOWN),	EX0002958
BNTAUT01	17514	Consumables	EX0002958
		,	
		Labour	1.00
		Labour - Internal	1.00
		Consumables	3.00
		Labour	0.00

)2/08/2023

		Labour	0.50
		Consumables	3.00
		Labour	1.00
		Labour - Internal	1.00
		Consumables	3.00
		OIL 15W-40, CK 4/E9	4.00

Supplier Code	Invoice	Details	Purchase Order
		Labour	1.00
023.			
		Labour - Internal	1.00
		Consumables	
BROHUR01	EX00030392	ELECTRIC SUZI COIL. 7PIN METAL PLUGS,	EX0003039
BROHUR01	2982657	LONG,	EX0003039
		ELECTRIC SUZI COIL. 7PIN METAL	
		PLUGS, LONG,	
		Labour	0.00
		Labour	1.50
'09/2023.			
		Labour - Internal	1.50
		Labour - Internal	1.50
		Consumables	3.00
		MAINTENANCE KIT	1.00
		OIL 15W-40, CK 4/E9	49.00
		Labour	0.00
		Labour	1.00
23.			
		Labour - Internal	1.00
		Consumables	3.00
		Labour	0.00

		Labour	0.00
		Labour	0.00
		Labour	0.00
		Labour	1.00
		Consumables	3.00
		OIL 15W-40, CK 4/E9	1.00
		AIR FILTER SLEEPER AIR	1.00
		Labour	1.00
		Labour	6.00

upplier ode	Invoice	Details	Purchase Order

LE, REFILL OIL TO CAPACITY AND TENSION WHEEL NUTS AND READJUST BOTH STEER BRAKES

		Consumables	
		RECON TURBOCHARGER KIT	
		CR SEAL - HUB SEAL	
		AIR COMPRESSOR SX, RECONDITIONED	
		GASKET SUIT HUB CAP SEAL 1613	
		(Exodas Stock)	
		RECON DOSER PUMP 12 V KW	
		Valve Governor	
		GASKET ACC DRIVE SUPPORT	
		Gasket, Exhaust Flex, K200	
		Consumables	
BRIAUS01	EX00030835	295/80R22.5 152M BS R154,	EX0003083
BRIAUS01	EX00030835	case stock 295/80-22.5,	EX0003083
BRIAUS01	EX00030835	FIT TBR TYRE,	EX0003083
BRIAUS01	EX00030835	REMOVAL: CUSTOMER PULL POINT,	EX0003083
BRIAUS01	EX00030835	SCHEDULED DEPOT SERVICE 15MIN,	EX0003083
BRIAUS01	EX00030835	FLIP TRUCK TYRE OR RETREAD,	EX0003083
BRIAUS01	187459665	295/80R22.5 152M BS R154,	EX0003083
BRIAUS01	187459665	case stock 295/80-22.5,	EX0003083
BRIAUS01	187459665	FIT TBR TYRE,	EX0003083
BRIAUS01	187459665	REMOVAL: CUSTOMER PULL POINT,	EX0003083
BRIAUS01	187459665	SCHEDULED DEPOT SERVICE 15MIN,	EX0003083
BRIAUS01	187459665	FLIP TRUCK TYRE OR RETREAD,	EX0003083
		Labour	
		Labour	0.75

3.

		Labour - Internal	0.75
		Consumables	3.00
		Labour	1.50

23.

ROUGH WIRING

		Labour - Internal	1.50
		Consumables	3.00
		LED SLIM SURFACE COMBI LAMF	1.00
		Labour	0.00

Supplier Code	Invoice	Details	Purchase Order

EMAX01	EX00031093	5800 SERIES TRUCK KIT DUAL HEIGHT	EX0003109
EMAX01	EX00031093	CONTROL,	EX0003109
		Transtech lead for IVU,	
EMAX01	EX00031093	12V BYPASS KIT,	EX0003109
EMAX01	EX00031093	Airweigh Airline Fitting for Kenworth,	EX0003109
EMAX01	EX00031093	Airweigh Truck Installation,	EX0003109
EMAX01	7130130	5800 SERIES TRUCK KIT DUAL HEIGHT	EX0003109
EMAX01	7130130	CONTROL,	EX0003109
		Transtech lead for IVU,	
EMAX01	7130130	12V BYPASS KIT,	EX0003109
EMAX01	7130130	Airweigh Airline Fitting for Kenworth,	EX0003109
EMAX01	7130130	Airweigh Truck Installation,	EX0003109

Labour 0.50

EPH ON 16/11/2023.
IOW. TEMP GAUGE IS NOW WORKING. REPLACED WIPER BLADES X 2

VALVE. DEFECT CREATED - NO.10307

Labour - Internal	0.50
Labour - Internal	1.00
Labour - Internal	0.50
Consumables	6.00
ES Water Filter	1.00
Turbo 2000 Air dryer	1.00
DIFF FILTER	1.00
Filter Element Gearbox Eaton	1.00
Labour	0.00
Labour	0.00
Labour	0.00

upplier ɔde	Invoice	Details	Purchase Order

ɔn of Defect : MONITOR OUTPUT SEAL

INOR SEEPING (NOT DONE)

e : 23/09/2023 Description of Defect :

IT CHECK WITH TURN TABLE TOOL

23/09/2023 Description of Defect :

SULTING IN TEMP GAUGE NOT WORKING LABOUR APPRENJ 2.00

/2023.

Labour - Internal	1.00
Eco Oil Filter Cartridge	1.00
Fuel Filter (Sleeper Air)	1.00
AIR FILTER SLEEPER AIR	1.00
Fuel/Water seperator filter	1.00
HITECH SYNPLUS 10W50	1.00
Consumables	3.00
Labour	2.00

ON. ATTEMPT # 2 ON 16/11/2023

16/11/2023
WIRE ON BLOCK - DEFECT REPAIRED 16/11/2023.

16/11/2023 - NO FAULTS FOUND

Labour - Internal	2.00
Labour - Internal	1.00

Supplier Code	Invoice	Details	Purchase Order
NABQAN01	EX00031713	CHECK & REPAIR - ALTERNATOR SEIZED, BELT	EX0003171
NABQAN01	EX00031713	DAMAGED & LOST COOLANT, ALTERNATOR-L/N 160A PAD MT,	EX0003171
NABQAN01	EX00031713	PULLEY ALTERNATOR,	EX0003171
NABQAN01	EX00031713	TENSIONER BELT,	EX0003171
NABQAN01	EX00031713	Belt-Fan Drive	EX0003171
NABQAN01	EX00031713	, COOLANT PG PLATINUM - 20 LTR,	EX0003171
NABQAN01	EX00031713	Travel Fee to Breakdowns,	EX0003171
NABQAN01	EX00031713	WORKSHOP SUPPLIES,	EX0003171
NABQAN01	EX00031713	Freight	EX0003171
NABQAN01	872148	, CHECK & REPAIR - ALTERNATOR SEIZED, BELT DAMAGED & LOST COOLANT,	EX0003171
NABQAN01	872148	ALTERNATOR-L/N 160A PAD MT,	EX0003171
NABQAN01	872148	PULLEY ALTERNATOR,	EX0003171
NABQAN01	872148	TENSIONER BELT,	EX0003171
NABQAN01	872148	Belt-Fan Drive	EX0003171
NABQAN01	872148	, COOLANT PG PLATINUM - 20 LTR,	EX0003171
NABQAN01	872148	Travel Fee to Breakdowns,	EX0003171
NABQAN01	872148	WORKSHOP SUPPLIES,	EX0003171
NABQAN01	872148	Freight ,	EX0003171
ROU2AUT01	EX00031938	LABOUR - AFTER HOURS - SUPPLY AND FIT NEW BATTERIES,	EX0003193
ROU2AUT01	EX00031938	EXIDE XN70ZZMF BATTERY,	EX0003193
ROU2AUT01	EX00031938	Consumables ,	EX0003193
ROU2AUT01	INV-1162	LABOUR - AFTER HOURS - SUPPLY AND FIT NEW BATTERIES,	EX0003193
ROU2AUT01	INV-1162	EXIDE XN70ZZMF BATTERY,	EX0003193
ROU2AUT01	INV-1162	Consumables ,	EX0003193
RCCLOW01	EX00032134	TIGHTEN LOOSE MUDGUARD BRACKET,	EX0003213
RCCLOW01	EX00032134	MUDGUARD,	EX0003213
RCCLOW01	EX00032134	MUDFLAP,	EX0003213
RCCLOW01	EX00032134	STRAPS,	EX0003213
RCCLOW01	EX00032134	MOUNTING BRACKET,	EX0003213
RCCLOW01	EX00032134	MIDDLE MUDFLAP,	EX0003213
RCCLOW01	EX00032134	Consumables ,	EX0003213
RCCLOW01	36522	TIGHTEN LOOSE MUDGUARD BRACKET,	EX0003213
RCCLOW01	36522	MUDGUARD,	EX0003213

Supplier Code	Invoice	Details	Purchase Order
RCCLOW01	36522	MUDFLAP,	EX0003213
RCCLOW01	36522	STRAPS,	EX0003213
RCCLOW01	36522	MOUNTING BRACKET,	EX0003213
RCCLOW01	36522	MIDDLE MUDFLAP,	EX0003213
RCCLOW01	36522	Consumables	EX0003213
		,	
		Labour	0.00
		Labour	3.00

03/01/2023.

M CHECKED. B-SERVICE

ACEMENT NEXT SERVICE.

	Labour - Internal	3.00
	Labour - Internal	3.00
	Consumables	5.00
	Valve Governor	1.00
	Turbo 2000 Air dryer	1.00
	MAINTENANCE KIT	1.00
	Labour	0.00

on of Defect : MONITOR OUTPUT SEAL

INOR SEEPING (NOT DONE)

E THIS ONE WITH UPDATED INFORMATION.

Labour		0.00
Labour		0.00

upplier ode	Invoice	Details	Purchase Order

GE AIR COOLER 1.00 5,240.10

BC4 BRAKE CLEANER 400GM AEROSOL 1.00 5.35

D BLUE LABEL BELT 1.00 39.10 Y99-KW-1004-1L KW DEGREASER 1L 1.00 13.59

e :

ockage or damage ? No signs Charge air cooler or exhaust system leak: Engine not running. Visually inspect

ct the exhaust piping for leaks , cracks and loose connections
? Leak found. Visually inspect the charge air cooler hoses for
check for leaks ? Oil found. Leaks in the air intake system: YES

eces, removed blown turbo and took photos of failed parts.
d replaced intercooler, Removed A/C condenser, recovered
lenser. Photographed oil in intercooler. Fitted new intercooler,
l engine oil due to turbo failure, oil had made its way through
opened oil filter; found metal contamination in filter. As per
eplacement is required. Took photos.

and replaced gaskets. Replaced oil

upplier ode	Invoice	Details	Purchase Order
BROHUR01	EX00032533	GROMMET-TIE ROD, RAD,	EX0003253
BROHUR01	EX00032533	CHARGE AIR COOLER,	EX0003253
BROHUR01	EX00032533	Freight	EX0003253
BROHUR01	EX00032533	, CABLE TIE BRAKE HOSE,	EX0003253
BROHUR01	EX00032533	BBC4 BRAKE CLEANER,	EX0003253
BROHUR01	EX00032533	CLAMP V BAND,	EX0003253
BROHUR01	EX00032533	VECTON 15W40 CK4 20L,	EX0003253
BROHUR01	EX00032533	Fan Belt,	EX0003253
BROHUR01	EX00032533	DEGREASER,	EX0003253

ooler element. Torqued all bolt and refitted coolant transfer pipe
s, replaced 2 studs, torqued mounting nuts.

aged to both parts . Refitted all air intake with new CAC hoses
wash to clean out oil as well exhaust pieces. Removed sump, oil
olts to be able to remove stiffener plate as all bolts were seized.
ect lubricating oil pump for reuse. No damage found on 1 and 4
replaced all main bearings and thrust washers on 4. Used
rocedure step by step and used correct torque sequence.
nd gear backlash and within specs. Pulled down oil pump and
ap. Measured idler and gear backlash and within specs. Installed
Refitted oil pickup with new O-ring.

sump with zip ties . Fitted new engine oil filter, refilled with 50L of
cover which was removed to turn the engine over. Removed fuel
or a period and burnt remaining oil out of exhaust. Replaced
ining exhaust. Re- gassed A/C, replaced O-rings and replaced
cle and washed down truck ready for collection.

BROHUR01	EX00032533	LOCTITE 5699 GREY,	EX0003253
BROHUR01	EX00032533	CLAMP V BAND,	EX0003253
BROHUR01	EX00032533	LUBRIPLATE 105 GREASE 10OZ TBE,	EX0003253
BROHUR01	EX00032533	LOCTITE 515 FLEXIBLE MASTER,	EX0003253

Supplier Code	Invoice	Details	Purchase Order
BROHUR01	3109306	GROMMET-TIE ROD, RAD,	EX0003253
BROHUR01	3109306	CHARGE AIR COOLER,	EX0003253
BROHUR01	3109306	Freight	EX0003253
BROHUR01	3109306	, CABLE TIE BRAKE HOSE,	EX0003253
BROHUR01	3109306	BBC4 BRAKE CLEANER,	EX0003253
BROHUR01	3109306	CLAMP V BAND,	EX0003253
BROHUR01	3109306	VECTON 15W40 CK4 20L,	EX0003253
BROHUR01	3109306	Fan Belt,	EX0003253
BROHUR01	3109306	DEGREASER,	EX0003253
BROHUR01	3109306	LOCTITE 5699 GREY,	EX0003253
BROHUR01	3109306	CLAMP V BAND,	EX0003253
BROHUR01	3109306	LUBRIPLATE 105 GREASE 10OZ TBE,	EX0003253
BROHUR01	3109306	LOCTITE 515 FLEXIBLE MASTER,	EX0003253
BROHUR01	EX00033011	STUD,	EX0003301
BROHUR01	EX00033011	CONNECTOR,	EX0003301
BROHUR01	EX00033011	PIPE-EXH 5 FLEX,	EX0003301
BROHUR01	3134914	STUD,	EX0003301
BROHUR01	3134914	CONNECTOR,	EX0003301
BROHUR01	3134914	PIPE-EXH 5 FLEX,	EX0003301
		Labour	0.00
		Labour	0.50

24. TORQUED
ENED FRONT
ED BELT AS

	Labour - Internal	0.50
	Consumables	3.00
	Drive Belt, K200	1.00
	Labour	0.00

RIAUS01	EX00033398	295/80R22.5 152/148M BS R154 ECO,	EX0003339
RIAUS01	EX00033398	FIT TBR TYRE,	EX0003339
RIAUS01	EX00033398	TYRE HELD FOR RUNOUT,	EX0003339
RIAUS01	EX00033398	REMOVAL: CUSTOMER REQUEST,	EX0003339
RIAUS01	EX00033398	SCHEDULED DEPOT SERVICE 15MIN,	EX0003339
RIAUS01	188316445	295/80R22.5 152/148M BS R154 ECO,	EX0003339
RIAUS01	188316445	FIT TBR TYRE,	EX0003339
RIAUS01	188316445	TYRE HELD FOR RUNOUT,	EX0003339
RIAUS01	188316445	REMOVAL: CUSTOMER REQUEST,	EX0003339
RIAUS01	188316445	SCHEDULED DEPOT SERVICE 15MIN,	EX0003339

Supplier Code	Invoice	Details	Purchase Order
		Labour	0.00

ON 27/03/2024. INVOICE NO.

ove to ensure no leaks.

uired to stop leak.

ı was working fan came on .
to come on.
.
ɔr no issues were found

d not find anything

ROHUR01	EX00033594	CARRY OUT 'B' SERVICE,	EX0003359
ROHUR01	EX00033594	Oil Filter (was LF9080),	EX0003359
ROHUR01	EX00033594	FF5776 Fuel Filter,	EX0003359
ROHUR01	EX00033594	Element 10 Micron,	EX0003359
ROHUR01	EX00033594	Ad Blue filter Kenworth,	EX0003359
ROHUR01	EX00033594	OIL 15W-40, CK 4/E9,	EX0003359
ROHUR01	EX00033594	GREASE,	EX0003359
ROHUR01	EX00033594	JOINER FITTING 5/32 (PUSH),	EX0003359
ROHUR01	EX00033594	Air Filter,	EX0003359
ROHUR01	EX00033594	REPAIR HORTON FAN STUCK ON,	EX0003359
ROHUR01	EX00033594	INVESTIGATE BURNING OIL SMELL,	EX0003359
ROHUR01	EX00033594	Consumables	EX0003359
ROHUR01	EX00033594	, ENVIRONMENTAL LEVY,	EX0003359
ROHUR01	3165262	CARRY OUT 'B' SERVICE,	EX0003359
ROHUR01	3165262	Oil Filter (was LF9080),	EX0003359
ROHUR01	3165262	FF5776 Fuel Filter,	EX0003359
ROHUR01	3165262	Element 10 Micron,	EX0003359
ROHUR01	3165262	Ad Blue filter Kenworth,	EX0003359
ROHUR01	3165262	OIL 15W-40, CK 4/E9,	EX0003359

Supplier Code	Invoice	Details	Purchase Order
BROHUR01	3165262	GREASE,	EX0003359
BROHUR01	3165262	JOINER FITTING 5/32 (PUSH),	EX0003359
BROHUR01	3165262	Air Filter,	EX0003359
BROHUR01	3165262	REPAIR HORTON FAN STUCK ON,	EX0003359
BROHUR01	3165262	INVESTIGATE BURNING OIL SMELL,	EX0003359
BROHUR01	3165262	Consumables	EX0003359
BROHUR01	3165262	, ENVIRONMENTAL LEVY,	EX0003359

Labour

Labour 0.00

Labour 1.50

ETHAN ON REPLACED 30/04/2024
JAW AS TURNTABLE Labour - Internal

OD

1.50

Labour - Internal	1.50
Labour - Internal	3.50
Consumables	6.00
7"HEADLIGHT ROUND HI/LOW	2.00
MAINTENANCE KIT	1.00
HT/S SUPER DUTY OEM KIT	1.00
JAWKIT (JSK37)	1.00
Labour	0.00
Labour	0.00

Supplier Code	Invoice	Details	Purchase Order
Defect :			
		Labour	0.50
30/04/2024.			
		Labour - Internal	0.50
		Consumables	2.00
		HITECH SYNPLUS 10W50	1.00
		Air Filter Sleeper Air	1.00
		Labour	1.00
/2024. TESTED TRACTOR			
		Labour - Internal	1.00
		Consumables	4.00
		Labour	0.00

upplier ode	Invoice	Details	Purchase Order
f Defect :			
VALVE. RUNNING FINE			
		Labour	1.00
3/2024. REPLACED WIPER			
		Labour - Internal	1.00
		Consumables	6.00
		Labour	0.00
		Labour	2.00

R BLADES LABOUR APPRENJ

	Labour - Internal	1.00
	Consumables	5.00
	OIL 15W-40, CK 4/E9	4.00
	Labour	0.00
	Labour	0.00
	Labour	2.00

ALKWAY BRACKETS LABOUR

	Labour - Internal	2.00
	Consumables	6.00
	OIL 15W-40, CK 4/E9	50.00
	Oil Filter (was LF9080)	1.00
	FF5776 Fuel Filter	1.00
	Ad Blue filter Kenworth	1.00
	Labour	0.00
	Labour	0.00

upplier ode	Invoice	Details	Purchase Units	Rate

. & REPAIR ON 11/07/2024.

old notice high pressure, checked operation of condenser

ı. Removed and replaced fan from workshop stock.

rd. Charge rate good.
our & Consumables - Inspect &

EX0003528

d & replaced fan.,

C01	INV-8818	Labour & Consumables - Inspect &	EX0003528
		Labour	
		Labour	

AND REFITTED.

	Consumables	4.00
	Labour	1.00

01/08/2024.
AIR LINE TO HEIGHT

L VALVE REPLACED DECK

	Labour - Internal	1.50
	Labour - Internal	1.50
	Labour - Internal	1.50
	Consumables	5.00
	MALE TRAILER PLUG	1.00

		OIL 15W-40, CK 4/E9	5.00
		Labour	0.00
		Labour	0.00

Supplier Code	Invoice	Details	Purchase Order
		Labour	1.00

)8/2024.

		Consumables	3.00
		HITECH SYNPLUS 10W50	1.00
		Air Filter Sleeper Air	1.00
		Labour	0.00

Defect :
.AYS UP WITH TRAILERS

		Labour	0.25

5/08/2024.

		Consumables	1.00
		Labour	0.00
		Labour	1.50

ON 07/09/2024.

		Labour - Internal	
		Labour - Internal	
		Consumables	
		OIL 15W-40, CK 4/E9	
		MAINTENANCE KIT	
		Labour	

BRIAUS01	EX00036142	11R22.5 148/145L BS M749II ECO,	EX0003614
BRIAUS01	EX00036142	FIT TBR TYRE,	EX0003614
BRIAUS01	EX00036142	TYRE SENT FIR CAPPING,	EX0003614
BRIAUS01	EX00036142	SCHEDULED DEPOT SERVICE 15MIN,	EX0003614
BRIAUS01	EX00036142	295/80R22.5 152/148M BS R154 ECO,	EX0003614
BRIAUS01	EX00036142	FIT TBR TYRE,	EX0003614
BRIAUS01	EX00036142	TYRE SENT FIR CAPPING,	EX0003614
BRIAUS01	EX00036142	REMOVAL: CUSTOMER PULL POINT,	EX0003614
BRIAUS01	189257367	11R22.5 148/145L BS M749II ECO,	EX0003614
BRIAUS01	189257367	FIT TBR TYRE,	EX0003614
BRIAUS01	189257367	TYRE SENT FIR CAPPING,	EX0003614
BRIAUS01	189257367	SCHEDULED DEPOT SERVICE 15MIN,	EX0003614

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	189257367	295/80R22.5 152/148M BS R154 ECO,	EX0003614
BRIAUS01	189257367	FIT TBR TYRE,	EX0003614
BRIAUS01	189257367	TYRE SENT FIR CAPPING,	EX0003614
BRIAUS01	189257367	REMOVAL: CUSTOMER PULL POINT,	EX0003614
		Labour	

		Labour	1.50

9/2024.

:TICS DETERIORATING

		Consumables	
		Weather shield Kenworth LHS	
		Weather shield Kenworth RHS	

		Labour		
		Labour - Internal		
		Consumables		
		Labour		
		Labour		
NABQAN01	EX00036502	TRAVEL TO COOLONGOLOOK HILL	EX0003650	
NABQAN01	369237184	NORTHBOUND. PULL B DOUBLE OFF HILL, TRAVEL TO COOLONGOLOOK HILL	EX0003650	
		NORTHBOUND. PULL B DOUBLE OFF HILL,		
		Labour		0.50

') ON 03/10/2024.

IRED EBS PLUG ON BACK

		Labour - Internal		0.50
		Consumables		2.00
		LEVER		1.00
		Labour		0.00

upplier ode	Invoice	Details	Purchase Order

BERG ON 08/10/2024. INVOICE NO. 3344104

Gin Gin Puma Service Station; collect parts

n site; inspect no start complaint; cab over vehicle; conduct test
ecification; test power to starter motor; confirm power present;
to starter motor body loose causing arc out by not allowing
rter motor; install new PACCAR unit; test & confirm power
cle to service; pack up gear & return to workshop.

BROHUR01	EX00036569	Call Out After Hours/Off Site,	EX0003656
BROHUR01	EX00036569	TROUBLESHOOT NO START COMPLAINT.,	EX0003656
BROHUR01	EX00036569	PARTS CALL OUT FEE,	EX0003656
BROHUR01	EX00036569	STARTER - PACCAR DP60, KWA,	EX0003656
BROHUR01	EX00036569	Travel Fee to Breakdowns,	EX0003656
BROHUR01	EX00036569	Consumables	EX0003656
BROHUR01	EX00036569	, ENVIRONMENTAL LEVY,	EX0003656
BROHUR01	3344104	Call Out After Hours/Off Site,	EX0003656
BROHUR01	3344104	TROUBLESHOOT NO START COMPLAINT.,	EX0003656
BROHUR01	3344104	PARTS CALL OUT FEE,	EX0003656
BROHUR01	3344104	STARTER - PACCAR DP60, KWA,	EX0003656
BROHUR01	3344104	Travel Fee to Breakdowns,	EX0003656
BROHUR01	3344104	Consumables	EX0003656
BROHUR01	3344104	, ENVIRONMENTAL LEVY,	EX0003656
		Labour	

1/10/2024.

Labour - Internal		1.00
Consumables		3.00
Kit Q-Plus Brake Shoe		2.00
Labour		4.00

ON 31/10/2024.

		Labour - Internal	4.00
		Labour - Internal	4.00
		Consumables	4.00
		TRP KW CAB AIR FILTER	1.00

Supplier Code	Invoice	Details	Purchase Order
		Power Steer Filter LF637	
		Filter Element Gearbox Eaton	
		DIFF FILTER	
		ES Water Filter	
		Turbo 2000 Air dryer	
		Air Filter	
		TRANS MAN HVY DUTY 75W90 205L	
		TRANS DYNADRIVE LL 80W90	
		BELT TENSIONER	
		Labour	
		Labour	
		Labour	

		Labour	3.00

ON. ATTEMPT # 1

N 31/10/2024

		Labour	0.00
		Labour	1.50

RKSHOP) ON 01/11/2024.

:R

		Consumables	
		Fuel Filter (Sleeper Air)	
		Oil Filter Eco/Sleeper	
		Eco/Sleeper Oil Cover Oring	
		Fuel/Water seperator filter	
		Air Filter Sleeper Air	
		HITECH SYNPLUS 10W50	
TYRMOR01	EX00037218	PUNCTURE REPAIR - TRUCK TYRE FITTED ON	EX0003721
TYRMOR01	EX00037466	TRUCK,	EX0003746
NABQAN01	EX00037467	PUNCTURE REPAIR - TYRE FITTED ON TRUCK, PUNCTURE REPAIR - TRUCK TYRE FITTED ON TRUCK,	EX0003746

Supplier Code	Invoice	Details	Purchase Order
TYRMOR01	EX00037218	116 SLEEVE,	EX0003721
TYRMOR01	EX00037466	116 SLEEVE,	EX0003746
NABQAN01	EX00037467	116 SLEEVE,	EX0003746
TYRMOR01	1136659	PUNCTURE REPAIR - TRUCK TYRE FITTED ON	EX0003721
TYRMOR01	1136659R	TRUCK,	EX0003746
NABQAN01	1136659-A	PUNCTURE REPAIR - TYRE FITTED ON TRUCK, PUNCTURE REPAIR - TRUCK TYRE FITTED ON TRUCK, 116 SLEEVE,	EX0003746
TYRMOR01	1136659		EX0003721
TYRMOR01	1136659R	116 SLEEVE,	EX0003746
NABQAN01	1136659-A	116 SLEEVE,	EX0003746
		Labour	

		Labour	0.50

2/12/2024.

ILS.

		Consumables	3.00
		EBS Plug, 7 pin 12/24v	1.00
		Labour	0.00
		Labour	1.50

P) ON 11/12/2024.

IC

		Labour - Internal	1.50
		Consumables	3.00
		MAINTENANCE KIT	1.00
		OIL 15W-40, CK 4/E9	50.00
		Labour	0.00

Defect : SERVICE DUE

OUT

Supplier Code	Invoice	Details	Purchase Order
		Labour	0.00
		Labour	0.75

2/2024.

		Suzi Coil Long	1.00
		Consumables	
BRIAUS01	EX00038077	11R22.5 148/145L BS M749II ECO,	EX0003807
BRIAUS01	EX00038077	FIT TBR TYRE,	EX0003807
BRIAUS01	EX00038077	CUSTOMER SCRAPPED OWN TYRE,	EX0003807
BRIAUS01	EX00038077	REMOVAL: FLAT OR UNDER INFLATED,	EX0003807
BRIAUS01	189953636	11R22.5 148/145L BS M749II ECO,	EX0003807
BRIAUS01	189953636	FIT TBR TYRE,	EX0003807
BRIAUS01	189953636	CUSTOMER SCRAPPED OWN TYRE,	EX0003807
BRIAUS01	189953636	REMOVAL: FLAT OR UNDER INFLATED,	EX0003807
		Labour	

SHOP) ON 31/01/2025.

ND) SCALES IS OLD DEFECT

		Labour - Internal	0.50
		Labour - Internal	0.50
		Consumables	5.00
		Labour	0.00
		Labour - Internal	1.00

/02/2025.

		Consumables	

Labour - Internal
OIL 15W-40, CK 4/E9
Labour

BRIAUS01	EX00038678	PUNCTURE REPAIR TBR,	EX0003867
BRIAUS01	EX00038678	SCHEDULED DEPOT SERVICE 15MIN,	EX0003867
BRIAUS01	190217153	PUNCTURE REPAIR TBR,	EX0003867
BRIAUS01	190217153	SCHEDULED DEPOT SERVICE 15MIN,	EX0003867

Supplier Code	Invoice	Details	Purchase Order
		Labour - Internal	1.00

AL NOT FAULT FOUND AL OK

OM FLOODS

Consumables	3.00
	1.00
Labour	0.00

f Defect :
CEMENT NEXT SERVICE

31/01/2025 Description of Defect :

Labour

0.00

Labour 0.75

Consumables

EXPMAI01	EX00039686	Labour,	EX0003968
EXPMAI01	EX00039686	Travel Fee to Breakdowns,	EX0003968

NCE 11/04/2025 INV# INV-4144

emissions. checked and cleared many faults and vehicle faults went away and couldn't get to re fault. driver urned to home.

XPMAI01	INV-4144	Labour,	EX0003968
XPMAI01	INV-4144	Travel Fee to Breakdowns,	EX0003968
RIAUS01	EX00039593	295/80R22.5 152/148M BS R154 ECO,	EX0003959
RIAUS01	EX00039593	FIT TBR TYRE,	EX0003959
RIAUS01	EX00039593	TYRE HELD FOR RUNOUT,	EX0003959

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	EX00039593	REMOVAL: CUSTOMER REQUEST,	EX0003959
BRIAUS01	EX00039593	SCHEDULED DEPOT SERVICE 15MIN,	EX0003959
BRIAUS01	190527744	SCHEDULED DEPOT SERVICE 15MIN,	EX0003959
BRIAUS01	190527744	REMOVAL: CUSTOMER REQUEST,	EX0003959
BRIAUS01	190527744	TYRE HELD FOR RUNOUT,	EX0003959
BRIAUS01	190527744	FIT TBR TYRE,	EX0003959
BRIAUS01	190527744	295/80R22.5 152/148M BS R154 ECO,	EX0003959
		Labour - Internal	0.00

Consumables 0.00

		Labour - Internal		2.00

TIGHTENED LH STEER TOP
TESTING FAULTY REOLACED

		Consumables		5.00
				2.00
		SERVICE KIT		1.00
		AIR OIL FILTER		1.00
		OIL 15W-40, CK 4/E9		51.00
		Labour		0.00
		Labour - Internal		1.50

AT DASH LIGHTS REPLACED

		Consumables		5.00
		Labour		0.50
		Consumables		3.00
		Air Filter Sleeper Air		1.00
		HITECH SYNPLUS 10W50		1.00
		Labour - Internal		1.00

upplier ode	Invoice	Details	Purchase Order

D - OK

ADTRAIN COVER LHS

		Consumables		4.00
		Labour - Internal		1.00
		Labour - Internal		1.00
		Labour - Internal		1.50

AT
LACED PRESSURE VALVE

		Consumables		6.00
		Labour - Internal		1.50
		Labour - Internal		1.50
		VALVE		1.00
		Labour		0.00

f Defect :

3/03/2025

NEEDS REPLACING (STORAGE COMPARTMENT ON HEADBOARD)
CELLANEOUS EX0004117

22.5 16PR TL ATT312 PREM DR
\01 117429 MISCELLANEOUS EX0004117

REM DR
Labour - Internal

Supplier Code	Invoice	Details	Purchase Order
		Consumables	0.00
		Labour - Internal	

.EANED ADD

		Consumables	
		Labour - Internal	
		Labour - Internal	
		AIR OIL FILTER	
		SERVICE KIT	
		OIL 15W-40, CK 4/E9	
		Labour - Internal	
		Consumables	
		Labour - Internal	
		Consumables	
		Labour	
;01	EX00041698	11R22.5 148/145L BS M749II ECO,	EX0004169
01	EX00041698	CASE STOCK 11R22.5 ECOPIA,	EX0004169
01	EX00041698	FIT TBR TYRE,	EX0004169
01	EX00041698	REMOVAL: CUSTOMER PULL POINT,	EX0004169
;01	EX00041698	SCHEDULED DEPOT SERVICE 15MIN,	EX0004169
;01	191247087	11R22.5 148/145L BS M749II ECO,	EX0004169
01	191247087	CASE STOCK 11R22.5 ECOPIA,	EX0004169
01	191247087	FIT TBR TYRE,	EX0004169
01	191247087	REMOVAL: CUSTOMER PULL POINT,	EX0004169
;01	191247087	SCHEDULED DEPOT SERVICE 15MIN,	EX0004169
R01	EX00041561	Labour External,	EX0004156
R01	EX00041561	DOSER INJECTOR, AD BLUE,	EX0004156
R01	EX00041561	Consumables	EX0004156
R01	EX00041561	, ENVIRONMENTAL LEVY,	EX0004156
R01	3628772	Labour External,	EX0004156

Supplier Code	Invoice	Details	Purchase Order
BROHUR01	3628772	DOSER INJECTOR, AD BLUE,	EX0004156
BROHUR01	3628772	Consumables	EX0004156
BROHUR01	3628772	, ENVIRONMENTAL LEVY,	EX0004156
BRIAUS01	EX00041650	ETA MIN FEE,	EX0004165
BRIAUS01	EX00041875	JOB 50365 RRGN:XQ86MI ODO:109796 DRIVER:	EX0004187
BRIAUS01	EX00041650	BRETT FOSTOR FLEET PM 133, PUNCTURE REPAIR TBR,	EX0004165
BRIAUS01	EX00041875	JOB COMPLETED 10/08/25 @ BP GOONDIWINDI	EX0004187
BRIAUS01	EX00041650	PR ON DRIVE - FRONT AXLE, RHS, OUTER, RADIAL #116 SLEEVE,	EX0004165

BRIAUS01	EX00041875	ETA MIN FEE,	EX0004187
BRIAUS01	EX00041650	JOB 50365 RRGN:XQ86MI ODO:109796 DRIVER:	EX0004165
BRIAUS01	EX00041875	BRETT FOSTER FLEET: PM133,	EX0004187
		PUNCTURE REPAIR TBR,	
BRIAUS01	EX00041650	JOB COMPLETED 10/08/2028 @BP GOONDIWINDI	EX0004165
BRIAUS01	EX00041875	PR ON DRIVE - FRONT AXLE, RHS, OUTER,	EX0004187
		RADIAL #116 SLEEVE,	
BRIAUS01	191227257	JOB 50365 RRGN:XQ86MI ODO:109796 DRIVER:	EX0004187
BRIAUS01	191227257	BRETT FOSTOR FLEET PM 133,	EX0004187
		JOB COMPLETED 10/08/25 @ BP	
		GOONDIWINDI PR ON DRIVE - FRONT AXLE,	
BRIAUS01	191227257	RHS, OUTER,	EX0004187
		ETA MIN FEE,	
BRIAUS01	191227257	PUNCTURE REPAIR TBR,	EX0004187
BRIAUS01	191227257	RADIAL #116 SLEEVE,	EX0004187
		Labour - Internal	1.00

ADJUSTED

Consumables	3.00
Labour - Internal	1.00
Labour	0.00

f Defect :

Supplier Code	Invoice	Details	Purchase Order
INLTRU01	EX00042455	Labour External,	EX0004245
INLTRU01	EX00042455	Element 10 Micron,	EX0004245
INLTRU01	EX00042455	SENSOR PRESSURE,	EX0004245
INLTRU01	EX00042455	VALVE PRESSURE RELIEF,	EX0004245
INLTRU01	EX00042455	BRAKE CLEAN 700ML,	EX0004245
INLTRU01	EX00042455	WORKSHOP SUPPLIES,	EX0004245
INLTRU01	EX00042455	Freight	EX0004245
INLTRU01	EX00042455	, ROUNDING,	EX0004245

9/2025

ND FOUND CODES FOR LOW FUEL PRESSURE. FOLLOWED AND CARRIED OUT TROUBLESHOOTING
POINT, CODE STILL ACTIVE. REPLACED
NOW CLEARED. RETURNED
PERWORK.

ILTRU01	876992	Labour External,	EX0004245
ILTRU01	876992	Element 10 Micron,	EX0004245
ILTRU01	876992	SENSOR PRESSURE,	EX0004245
ILTRU01	876992	VALVE PRESSURE RELIEF,	EX0004245
ILTRU01	876992	BRAKE CLEAN 700ML,	EX0004245
ILTRU01	876992	WORKSHOP SUPPLIES,	EX0004245
ILTRU01	876992	Freight	EX0004245
ILTRU01	876992	, ROUNDING,	EX0004245
		Labour - Internal	

IENT

Consumables

Labour - Internal
Kit Brake Shoe Steer MFS73
Labour

f Defect :

		Parts Supplied,	EX0004243
Supplier Code	Invoice	Details	Purchase Order
BROHUR01	EX00042432	Labour External,	EX0004243
BROHUR01	EX00042432	Consumables	EX0004243
BROHUR01	EX00042432	,	EX0004243
		ENVIRONMENTAL LEVY,	

NOT WORKING. REMOVE KICK PANNEL AND DASH ON LEFT SIDE. TEST POWER AT FAN - GOOD
OW WORKING. REPLACE PANNELS, CLEAN

BROHUR01	3681367	Parts Supplied,	EX0004243
BROHUR01	3681367	Labour External,	EX0004243
BROHUR01	3681367	Consumables	EX0004243
BROHUR01	3681367	,	EX0004243
		ENVIRONMENTAL LEVY,	
		Labour - Internal	

Consumables

Labour - Internal 1.50

Consumables	3.00
Labour - Internal	0.50
SERVICE KIT	1.00
AIR OIL FILTER	1.00
OIL 15W-40, CK 4/E9	51.00
Anti-Freeze Coolant	2.00
TRANS ATF HEAVY DUTY 20L	1.00
Labour - Internal	5.50

XLE REPLACE
RIGHT STEER

Supplier Code	Invoice	Details	Purchase Order
		Consumables	
		Labour - Internal	
		REPLACEMENT ELEMENT INLINE FILTER	
		Power Steer Filter LF637	
		Turbo 2000 Air Drier	
		ES Water Filter	

	Filter Element Gearbox Eaton	
	Filter Diff	
	FILTER CABIN K200	
	TRANS MAN HVY DUTY 75W90 205L	
	TRANS DYNADRIVE LL 80W90	
	AIR FILTER	
	Fan Belt	
	Drive Belt, K200	
	Torque Rod Bush	
Labour		0.00

of Defect :

.3/03/2025 Description of Defect :
NEEDS REPLACING (STORAGE COMPARTMENT ON HEADBOARD)

19/09/2025 Description of Defect :

Labour		
		1.00
11/2025		
Consumables		3.00
	OIL 15W-40, CK 4/E9	1.00
	KOHLER AIR FILTER	1.00
	Fuel/Water seperator filter	1.00
	KOHLER FUEL FILTER	1.00
	KOHLER OIL FILTER CARTRIDGE	1.00
Labour		1.00

upplier ode	Invoice	Details	Purchase Order
ON.			
BRIAUS01	EX00042941	295/80R22.5 152/148M BS R154 ECO,	EX0004294
BRIAUS01	EX00042941	FIT TBR TYRE,	EX0004294
BRIAUS01	EX00042941	TYRE HELD FOR RUNOUT,	EX0004294
BRIAUS01	EX00042941	REMOVAL: CUSTOMER REQUEST,	EX0004294
BRIAUS01	EX00042941	SCHEDULED DEPOT SERVICE 15MIN,	EX0004294
BRIAUS01	191641672	295/80R22.5 152/148M BS R154 ECO,	EX0004294
BRIAUS01	191641672	FIT TBR TYRE,	EX0004294
BRIAUS01	191641672	TYRE HELD FOR RUNOUT,	EX0004294
BRIAUS01	191641672	REMOVAL: CUSTOMER REQUEST,	EX0004294
BRIAUS01	191641672	SCHEDULED DEPOT SERVICE 15MIN,	EX0004294
BROHUR01	EX00043136	Labour External,	EX0004313
BROHUR01	EX00043136	Labour External,	EX0004313
BROHUR01	EX00043136	BATT-12V DELKOR,	EX0004313
BROHUR01	EX00043136	MISCELLANEOUS CONSUMABLES,	EX0004313
BROHUR01	EX00043136	ENVIRONMENTAL LEVY,	EX0004313

upplier ode	Invoice	Details	Purchase Order

ANES - DRIVER 0487089086

:N SITTING AWHILE

d truck sitting for a few days
5 volts and batteries are still pretty new but customer requested to be
d get some charge into them first When he got back dropped bulbar and lifted cab
very flat but all showing around 50% health Customer is just going to leave ice pack running for a while before

ICE PACK ON LAST NIGHT
ELL
batteries failed Replace 4x batteries

BROHUR01	3720002	Labour External,	EX0004313
BROHUR01	3720002	Labour External,	EX0004313
BROHUR01	3720002	BATT-12V DELKOR,	EX0004313
BROHUR01	3720002	MISCELLANEOUS CONSUMABLES,	EX0004313
BROHUR01	3720002	ENVIRONMENTAL LEVY,	EX0004313
		Labour - Internal	1.50

OLUMN

Consumables	4.00
Labour - Internal	1.50
Labour	0.00

f Defect :

KEEPS COMING ON OIL PRESS READS 250KPA.

RIAUS01	EX00043225	PUNCTURE REPAIR TBR,	EX0004322

Supplier Code	Invoice	Details	Purchase Order
BRIAUS01	EX00043225	SCHEDULED DEPOT SERVICE 15MIN,	EX0004322
BRIAUS01	191728621	PUNCTURE REPAIR TBR,	EX0004322
BRIAUS01	191728621	SCHEDULED DEPOT SERVICE 15MIN,	EX0004322
		Labour - Internal	1.00

Consumables	4.00
Labour - Internal	1.00
Labour - Internal	1.00
OIL 15W-40, CK 4/E9	6.00
D2 GOVERNOR - 1.8"	1.00

RIAUS01	EX00043905	PUNCTURE REPAIR TBR,	EX0004390
RIAUS01	EX00043905	ETA MIN FEE,	EX0004390
RIAUS01	191940799	PUNCTURE REPAIR TBR,	EX0004390
RIAUS01	191940799	ETA MIN FEE,	EX0004390
RIAUS01	EX00044123	11R22.5 148/145L BS M749II ECO,	EX0004412
RIAUS01	EX00044123	CASE STOCK 11R22.5 ECOPIA,	EX0004412
RIAUS01	EX00044123	FIT TBR TYRE,	EX0004412
RIAUS01	EX00044123	REMOVAL: CUSTOMER PULL POINT,	EX0004412

RIAUS01	EX00044123	SCHEDULED DEPOT SERVICE 15MIN,	EX0004412
RIAUS01	192027717	11R22.5 148/145L BS M749II ECO,	EX0004412
RIAUS01	192027717	CASE STOCK 11R22.5 ECOPIA,	EX0004412
RIAUS01	192027717	FIT TBR TYRE,	EX0004412
RIAUS01	192027717	REMOVAL: CUSTOMER PULL POINT,	EX0004412
RIAUS01	192027717	SCHEDULED DEPOT SERVICE 15MIN,	EX0004412
ORDIE01	EX00044165	Labour External,	EX0004416
ORDIE01	EX00044165	Call Out After Hours/Off Site,	EX0004416
ORDIE01	EX00044165	Call Out After Hours/Off Site,	EX0004416
ORDIE01	EX00044165	Parts Supplied,FUEL ACTUATOR	EX0004416
ORDIE01	EX00044165	FF5776 Fuel Filter,	EX0004416
ORDIE01	EX00044165	Element 10 Micron,	EX0004416
ORDIE01	EX00044165	DEGREASER,	EX0004416
ORDIE01	EX00044165	TOLL CHARGES,	EX0004416
ORDIE01	EX00044165	GASKET FUEL PUMP,	EX0004416
ORDIE01	EX00044165	WASHER SEALING,	EX0004416
ORDIE01	EX00044165	GASKET FUEL PUMP,	EX0004416
ORDIE01	EX00044165	WASHER SEALING,	EX0004416
ORDIE01	EX00044165	Consumables	EX0004416
ORDIE01	EX00044165	, RECON FUEL PUMP HEAD ISX,	EX0004416

Supplier Code	Invoice	Details	Purchase Order
TORDIE01	EX00044165	OPENING FEE,CUMMINS OPENING FEE	EX0004416
TORDIE01	EX00044165	SENSOR PRESSURE,	EX0004416
TORDIE01	EX00044165	OPENING FEE,GILBERT & ROACH STORE OPEN	EX0004416
TORDIE01	EX00044165	FEE ROUNDING,	EX0004416

6

ACK OF FUEL
, WAS BELOW
TEND

TO PRESSURE

	000043340	Labour External,	EX0004416
:01	000043340	Call Out After Hours/Off Site,	EX0004416
:01	000043340	Call Out After Hours/Off Site,	EX0004416
:01	000043340	Parts Supplied,FUEL ACTUATOR	EX0004416
01	000043340	FF5776 Fuel Filter,	EX0004416
:01	000043340	Element 10 Micron,	EX0004416
:01	000043340	DEGREASER,	EX0004416
:01	000043340	TOLL CHARGES,	EX0004416
:01	000043340	GASKET FUEL PUMP,	EX0004416
:01	000043340	WASHER SEALING,	EX0004416
:01	000043340	GASKET FUEL PUMP,	EX0004416
:01	000043340	WASHER SEALING,	EX0004416
:01	000043340	Consumables	EX0004416
01	000043340	, RECON FUEL PUMP HEAD ISX,	EX0004416
:01	000043340	OPENING FEE,CUMMINS OPENING FEE	EX0004416
:01	000043340	SENSOR PRESSURE,	EX0004416
:01	000043340	OPENING FEE,GILBERT & ROACH STORE OPEN	EX0004416
01	000043340	FEE ROUNDING,	EX0004416
R01	EX00044067	Labour External,	EX0004406
R01	EX00044067	LEVER,	EX0004406
IR01	EX00044067	TRAVEL,	EX0004406
R01	EX00044067	MISCELLANEOUS CONSUMABLES,	EX0004406

Supplier Code	Invoice	Details	Purchase Order
BROHUR01	EX00044067	ENVIRONMENTAL LEVY,	EX0004406
BROHUR01	EX00044067	ROUNDING,	EX0004406

\RBOUR 10/01/2026

ECK BREAKDOWN AT URUNGA

ITCH ADJUSTER SCREW HAD FELL OUT AND WAS MISSING, VEHICLE HAD NO CLUTCH, FITTED NEW
JTCH AND CHECKED OPERATION, ALL OKAY, TRAVELLED BACK TO WORKSHOP

BROHUR01	3763073	Labour External,	EX0004406
BROHUR01	3763073	LEVER,	EX0004406
BROHUR01	3763073	TRAVEL,	EX0004406
BROHUR01	3763073	MISCELLANEOUS CONSUMABLES,	EX0004406
BROHUR01	3763073	ENVIRONMENTAL LEVY,	EX0004406
BROHUR01	3763073	ROUNDING,	EX0004406

Labour - Internal

Consumables

Labour - Internal 2.50

0

KED OK CON YAT

Consumables 4.00

Labour - Internal 2.50

Labour - Internal 2.50

OIL 15W-40, CK 4/E9 51.00

SERVICE KIT 1.00

AIR OIL FILTER 1.00

LED FRONT DIRECTION LAMP 2.00

Labour 0.00

upplier ode	Invoice	Details	Purchase Order

f Defect :
O LIMP MODE WITH THE WARNING 'AFTER TREAT' SHOWING AT MT WHITE. HE
PPROX 1900HRS WITH DIRECT LOAD

Labour - Internal

1.00

onsumables 3.00

Labour - Internal 1.00

Labour - Internal 1.00

onsumables 3.00

Labour - Internal 1.00

Labour - Internal 1.00

OIL 15W-40, CK 4/E9 4.00

Labour 0.50

Labour 1.50

HTENED FRONT COVER CLEANED AND SET OUT AS INSTRUCTED
onsumables

	3.00
Consumables	0.00
2" 24V 85W REVERSIBLE FAN - CONDENSOR	1.00

TORDIE01	EX00044969	Labour External,	EX0004496
TORDIE01	EX00044969	Call Out After Hours/Off Site,	EX0004496
ORDIE01	EX00044969	Consumables	EX0004496
ORDIE01	EX00044969	, TOLL CHARGES,	EX0004496

Supplier Code	Invoice	Details	Purchase Order
TORDIE01	EX00044969	Parts Supplied,OIL FILTER - CUMMINS	EX0004496
TORDIE01	EX00044969	Parts Supplied,HOSE CLAMPS	EX0004496

R HOSE CLAMP BROKEN FIT NEW HOSE CLAMPS

:01	000023695	Labour External,	EX0004496
:01	000023695	Call Out After Hours/Off Site,	EX0004496
:01	000023695	Consumables	EX0004496
E01	000023695	, TOLL CHARGES,	EX0004496
:01	000023695	Parts Supplied,OIL FILTER - CUMMINS	EX0004496
:01	000023695	Parts Supplied,HOSE CLAMPS	EX0004496
		Labour - Internal	
		Consumables	
		Labour - Internal	

2030

ORTON FAN
BELT AND AC

Consumables
Labour - Internal
SERVICE KIT
OIL 15W-40, CK 4/E9
GASKET OIL PAN
Kit Q-Plus Brake Shoe
Drive Belt, K200
Fan Belt
BATTERY DEEP CYCLE & TRUCK
SEAL FRONT COVER
Labour

Supplier Code	Invoice	Details	Purchase Order
f Defect : SUMP GASKET			
		Labour	0.00
Defect :			
		Labour	0.50
BRAKE			
		Consumables	
BROHUR01	EX00045530	Labour External,	EX0004553
BROHUR01	EX00045530	Suzi Coil Long,	EX0004553
BROHUR01	EX00045530	SELF SEALING 1/2" KIT,	EX0004553
BROHUR01	EX00045530	ADAPTOR,	EX0004553
BROHUR01	EX00045530	MISCELLANEOUS CONSUMABLES,	EX0004553
BROHUR01	EX00045530	ENVIRONMENTAL LEVY,	EX0004553
/04/2026			
ck. INSTALL SAFETY EQUIPMENT. Completed Quick Check.			
e snagged on skid plate, removed old suzis, fit new fittings to lines, y			
ROHUR01	3846171	Labour External,	EX0004553
ROHUR01	3846171	Suzi Coil Long,	EX0004553
ROHUR01	3846171	SELF SEALING 1/2" KIT,	EX0004553
ROHUR01	3846171	ADAPTOR,	EX0004553
ROHUR01	3846171	MISCELLANEOUS CONSUMABLES,	EX0004553
ROHUR01	3846171	ENVIRONMENTAL LEVY,	EX0004553
ENAUT01	EX00045750	KOHLER OIL FILTER CARTRIDGE,	EX0004575
ENAUT01	EX00045750	Parts Supplied,RYCO FUEL FILTER SPIN ON	EX0004575

Supplier Code	Invoice	Details	Purchase Order
KENAUT01	EX00045750	Parts Supplied,PENRITE CONVOY MONO TRUCK	EX0004575
KENAUT01	EX00045750	40 ENGINE OIL 20L AIR CLEANER CARTRIDGE KOHLER	EX0004575
KENAUT01	EX00045750	SLEEPER AIR, KOHLER OIL FILTER COVER ORING,	EX0004575
KENAUT01	EX00045750	Labour External,	EX0004575
4/04/2026			
V ONES TO REPLACED THEM. DROPPED OIL AND REPLACED ALL FILTERS. RE FILLED THE OIL AND RONG. NOTHING ELSE IS LEAKING AND ENGINE IS RUNNING WELL, AC IS COLD			
ENAUT01	63557	KOHLER OIL FILTER CARTRIDGE,	EX0004575
ENAUT01	63557	Parts Supplied,RYCO FUEL FILTER SPIN ON	EX0004575
ENAUT01	63557	Parts Supplied,PENRITE CONVOY	EX0004575
ENAUT01	63557	MONO TRUCK 40 ENGINE OIL 20L AIR CLEANER CARTRIDGE KOHLER	EX0004575
ENAUT01	63557	SLEEPER AIR, KOHLER OIL FILTER COVER ORING,	EX0004575
ENAUT01	63557	Labour External,	EX0004575

		Labour - Internal	1.50
P COOLANT CON			
		Consumables	7.00
		Labour - Internal	1.00
		Labour - Internal	2.00
		Labour	0.00

JUST SERVIED MAYBE OIL FILTER WAS NOT DONE UP ENOUGH

		Labour	1.00

05/2026

OR LEAKS, NONE FOUND, CLEAN

		Consumables	3.00
		KOHLER AIR FILTER	1.00
		HITECH SYNPLUS 10W50	1.00
		Labour - Internal	6.00

upplier ode	Invoice	Details	Purchase Order

I IN 1ST AND

		Consumables	3.00
		Labour - Internal	6.00
		Labour - Internal	1.00
		OIL 15W-40, CK 4/E9	5.00
		SWITCH- MIRROR MODULES	1.00
		UNI JOINT-PERMABLUBE 25	2.00
	Labour		0.00

f Defect :
E YATALA WORKSHOP OF IT

04/05/2026 Description of Defect :
BRISBANE

04/05/2026 Description of Defect :

19/09/2025 Description of Defect :

14/10/2025 Description of Defect :
HEAD UNIT TURNS OFF WHEN YOU HIT A BUMP

	Labour		4.00

upplier ode	Invoice	Details	Purchase Order
.UGGED SLEEPER			
› AND SMELLED LIKE FUEL, REMOVE AND REPLACE FUEL PUMP, HAVE THEN			
IN LINE FILTER AND MOST FUEL LINES, CLEAN OFF ENGINE AND COMPLETE			
R 3 HOURS, NO LEAKS, NO NOISES, OIL IS STILL SPOT ON			
onsumables			
			6.00
		Fuel Pump	1.00
		HITECH SYNPLUS 10W50	1.00
		KOHLER AIR FILTER	1.00
		KOHLER FUEL FILTER	1.00
		Labour	0.00
		Labour	1.00
'ELL AS ROCKET COVER TO TRY SAVE OIL DUMP/OVER FUELLING ISSUE			
ILL WITH FRESH OIL			
,NT			
		Consumables	
		KOHLER AIR FILTER	
		15W40 ENGINE OIL - REDS	
		ECO WIND LIFT PUMP	
YOKTYR01	EX00047602	PRESSURE CHECK PER TYRE,	EX0004760
L - REGO:XQ86MI - ODO:296671KM - FN:PM133 - RN:Tyre Pressure check Fleet check			
′FPSI	YOKTYR01	IN-100808-202PRESSURE CHECK PER TYRE, Mareeba Depo	EX0004760
R01	EX00048168	295/80R22.5 154M 124R - B5059,	EX0004816
R01	EX00048168	TRUCK TYRE - STRIP AND FITTING,	EX0004816
R01	EX00048168	TRUCK WHEEL - BALANCE,	EX0004816
R01	EX00048168	COUNTRY DISPOSAL - TRUCK,	EX0004816
AT SPOTS ON STEERS, END OF SERVICE			
R01	IN-127922-202	295/80R22.5 154M 124R - B5059,	EX0004816
R01	IN-127922-202	TRUCK TYRE - STRIP AND FITTING,	EX0004816
Supplier Code	Invoice	Details	Purchase Order
R01	IN-127922-202	TRUCK WHEEL - BALANCE,	EX0004816
R01	IN-127922-202	COUNTRY DISPOSAL - TRUCK,	EX0004816
		Labour - Internal	
onsumables			
		Labour - Internal	
onsumables			
		Labour - Internal	
		FILTER KIT, OIL & FUEL FILTER, (E5)	
		Ad Blue filter Kenworth	
		OIL 15W-40, CK 4/E9	
		BUSHING-FRONT ENGINE	
		BUSHING-FRONT ENGINE	
QUAWIND01	EX00048000	Labour External,	EX0004800

09/2026

RTH K200
bour External, EX0004800

Labour - Internal

onsumables

FILTER CABIN K200
DIFF FILTER
Filter Element Gearbox Eaton
Power Steer Filter LF637
ES Water Filter
Labour
Labour
Labour

Labour

upplier ode	Invoice	Details	Purchase Order
ON. ATTEMPT			
	EX00048159	Seal - Thru RP23160,	EX0004815
		Labour	
R01	EX00048159	Thru shaft Nut Kit,	EX0004815

ACED 1X KW DRIVE AIRBAG

ASHER -REMOVED 3 PUT GASKET IN AIR DRYER

BROHUR01	3982449	Seal - Thru RP23160,	EX0004815
		Consumables	
BROHUR01	3982449	Thru shaft Nut Kit,	EX0004815
		Labour - Internal	
		CR SEAL - HUB SEAL	
		2	
		TRP 16.5 X 7 STEEL JACKET DRU RACK44FL KW 10.5" RIDE HEIGHT AG 400	
		Seal - Thru RP23160	
		HARDWARE KIT	
		SHIELD ASSY	
		235 Service Kit, Air Dryer	
		Labour	
		Labour	0.00
T			
T		Consumables	3.00
			2.00
		Labour	0.00
		Labour	1.00
10/09/2026			
		OIL 15W-40, CK 4/E9	1.00
		KOHLER OIL FILTER CARTRIDGE	1.00

		Consumables		3.00
		KOHLER FUEL FILTER		1.00
		FUEL FILTER		1.00
Supplier Code	Invoice	Details	Purchase Order	
		KOHLER AIR FILTER		
		BELT DAYCO		
		Labour		
		Labour		13.00

NEW ONE AND REPLACED BELTS AND TESTED AND RAN ALL IN WOKRING ORDER

N AND AC BELTS
PS

		Consumables		
		DRESS STRIPS S/STEEL SUIT MAXUS GUARDS		
		FAN BELT		
		A/C BELT		
		BELT TENSIONER		
OKTYR01	EX00048516	TRUCK TYRES STRIP AND FIT,	EX0004851	

PO:PM133 - YFS:1795 - REGO:XQ80MI -
t to steers truck being sold RSD 038242- Pos 1&2

OKTYR01	IN-131969-202	TRUCK TYRES STRIP AND FIT,	EX0004851	
Supplier Code	Invoice	Details	Purchase Order	