Vehicle History Summary

[redacted]

Fleet #	PM01
Registration	[redacted]
Make	Western Star
Model	2021 Prime Mover
VIN / Chassis #	5KKJBEBG9KPKX1024
Build Date	2021

Date	Reading / Units	Type / Repairer Notes	Repairer
31/08/2026		**Electrical** R-3387 see attached invoice for details	KENNYS AUTO ELECTRICAL TSV
20/08/2026	227,955 kms	**Fault** R-3312 REMOVED HOLD DOWN BOLTS STRAIGHTENED PLATES AND REFIT TO TRUCK REWIRED BROKEN NUMBER PLATE LIGHTS BOLTED REAR COVER BACK TO TRUCK	[redacted]
19/08/2026	277,955 kms	**Truck Wash** R-3341 WASHED TRUCK AS REQUESTED	[redacted]
10/08/2026		**NEW** T-1397 REPLACED 8 X DRIVE TYRES	RPM TYRE CENTRE
31/07/2026	217,620 kms	**C - 100k/Annual** S-1480 BRAKES 12MM ADJUSTED CLUTCH REWIRE RHS FRONT INDICATOR LIGHT , REPLACED WIRING FOR LHS FRONT BONNET INDICATOR REFIT SLEEPER AIR/ NUMBER PLATE COVER ON REAR OF TRUCK AD BLUE LEAK FROM DOSER PUMP LH FRONT FUEL TANK HOSES LEAKING MONITOR POWER STEERING BOX STARTING TO LEAK FROM BOTH SEALS COOLANT LEAK BACK OF WATER PUMP FRONT DIFF GASKET AND OUTPUT SEAL STARTING TO LEAK EXHAUST Y PIECE CRACKED THROUGH MIDDLE LH BONNET CABLE BROKEN	[redacted]
15/07/2026		**Fault** R-3244	KENNYS AUTO ELECTRICAL TSV
15/07/2026		**Fault** R-3219 REPAIRED IN WORKSHOP SEE ATTACHED	Truckline
16/06/2026	187,350 kms	**TURNTABLE** R-3047 INSPECTED TURNTABLE ALL GOOD REFIT DOOR GLASS TO PASSENGER SIDE REPLACE CABIN FILTERS REFIT PLUG FOR INSIDE OUTSIDE AIR FLAP AS FOUND DISCONNECTED	[redacted] Truckline
16/06/2026	187,720 kms	**Fault** R-3107 NOT A ROADWORTHY ISSUE	
16/06/2026	187,720 kms	**Fault** R-3106 REPLACED BELTS WITH NEW BELTS	[redacted]
16/06/2026	187,350 kms	**Fault** R-3104 see attached invoices for details	PENSKE
16/06/2026	187,350 kms	**Fault** R-3061 PREVIOUSLY REPAIRED BY MIKAYLA	[redacted]
16/06/2026	187,350 kms	**Fault** R-3040 DRIVER SEAT FOUND LOOSE COMING OFF TRACKS, FOUND ROLLER BEARINGS WORN AND 1 SNAPPED OFF REMOVED FRAME AND WELD BRACKET, REPLACED ROLLERS AND RE ASSEMBLED SEAT, REPLACED DRIVERS SEAT BELT.	PENSKE
15/06/2026		**Engine** R-3130	KENNYS AUTO ELECTRICAL TSV

Date	Reading / Units	Type / Repairer Notes	Repairer
05/06/2026	161,449 kms	**Fault** R-3038 REPLACED PASSENGER SPOTTER MIRROR	[redacted]
29/04/2026	1,155,472 kms	**A - 10k** S-1402 replace lateral torque rods replaced fan and alternator belts removed rear sleeper air cover plate had repaired then refitted completed service as per paperwork john 1 puncture repair 9 pressure checks	[redacted]
24/04/2026		**Fault** R-2972	
15/04/2026		**Electrical** R-2983 penske cairns to repair	[redacted] Penske
13/04/2026	1,143,007 kms	**A - 10k** S-1379 SEE ATTACHED FOR DETAILS	[redacted]
13/04/2026		**Fault** R-2973 REPAIRED IN SERVICE S-1379	
17/03/2026	120,663 kms	**Electrical** R-2883 REQUIRED NEW GUIDES AND REMOVED DAMAGED TINT TO INCREASE VISABILITY	
17/03/2026	120,663 kms	**Driveline** R-2949 REPLACED BROKEN WHEEL STUDS, ADJUSTED FRONT BRAKES AND TENSION WHEEL NUTS	[redacted]
17/03/2026	120,663 kms	**Driveline** R-2936 REPLACE WHEEL STUDS AND NUTS SEE ATTACHED JOB CARD	[redacted]
06/03/2026	114,322 kms	**Main/inspect, Runout** T-1280 1 x run out 9 x pressure checks 1 x tyre disposal	[redacted]
27/02/2026	111,160 kms	**B - 40k** S-1289 INSPECT KNOCK IN CAB FOUND U BLOTS LOOSE ON CROSSMEMBER, TIGHTENED NO MORE KNOCKING TOPPED UP SLEEPER AIR OIL 1L TOPPED UP COOLANT AND REPLACED RADIATOR CAP SLEEPER AIR FILTERS OUT OF STOCK REQUIRED FOR NEXT SERVICE, ALSO SLEEPER AIR ALTERNATOR NOT CHARGING	[redacted]
25/02/2026	108,472 kms	**Cab** R-2836 Tightened Nuts and Bolts on cab mount bracket. Replaced 2 x Wheel nuts and Studs on FR Replaced 2 x Wheel nuts and studs on FL	[redacted]
24/02/2026	108,472 kms	**Fault, PUNCTURE** T-1239 Other. . LHS rear outside drive tyre has a slow leak - Replaced LH Outer Rear	[redacted]
23/02/2026	101,894 kms	**Exhaust** R-2563	[redacted]
23/02/2026		**Chassis** R-2770	[redacted]
23/02/2026		**Engine** R-2652 SEE ATTACHED QUOTE FROM NAPA, PO SENT. NAPA INVOICE 1430380449 ATTACHED. NO REQUIRED - TRUCK STILL STATRTING.	[redacted] Napa Auto Parts
23/02/2026		**Cab** R-2570	
23/02/2026		**Cab** R-2567	
12/02/2026	101,004 kms	**Brakes** R-2799 Found Park brake not activating when buttons realeased. checked invevsion valve in chassis, touched exhaust port and brake came on. replaced with new valve. no further issues.	[redacted] Penske
23/01/2026	89,282 kms	**Main/inspect** T-1168 SEE ATTACHED TYRE JOBCARD - RUNOUT X 1. PRESSURE CHECKS X 9.	
19/01/2026	85,958 kms	**Chassis** R-2727	[redacted]

Date	Reading / Units	Type / Repairer Notes	Repairer
		SEE ATTACHED REPAIR JOBCARD - REMOVED DRIVE STEER TYRE & DRUM, REPLACED 5 X BROKEN STUDS. REFIT DRUM & ADJUST BRAKES, REFIT TYRE AND TENSION WHEEL NUTS TO 460FT-LB.	
10/01/2026	80,781 kms	**Cab** R-2684	[redacted]
		SEE ATTACHED REPAIR JOBCARD - REMOVE SIDE PANELS & FLOOR INSULATION. UNBOLT CAB MOUNTS, JACKED UP & REPLACED BOTH L/H & R/H MOUNTS. REFIT FLOOR INSULATION & SIDE PANELS. MECHANICS BREAKDOWN TIMES: NATHAN 2HR MIKAYLA 1HR	
09/01/2026	79,856 kms	**Steering** R-2672	[redacted]
		SEE ATTACHED TRUCKLINE INVOICE 1054947 FOR HUB CAP. SEE ATTACHED REPAIR JOBCARD -REPLACED L/H STEER HUB GASKET & 1 STUD. REGAS A/C.	
08/01/2026	39,856 kms	**Main/inspect** T-1115	[redacted]
		SEE ATTACHED TYRE JOBCARD - 1 PUNCTURE REPAIR.	
02/01/2026	1,074,068 kms	**Driveline** R-2638	[redacted]
02/01/2026	1,074,068 kms	**Runout** T-1095	[redacted]
31/12/2025		**Glass** R-2134	
31/12/2025		**Lights** R-2584	[redacted]
31/12/2025		**Fault** T-999	[redacted]
18/12/2025		**Icepack** R-2564	[redacted]
		18/12-ADVISED TO MONITOR/CLOSE	
18/12/2025		**Chassis** R-2565	[redacted]
		18/12-ADVISED TO MONITOR/CLOSE.	
15/12/2025	62,698 kms	**Driveline** R-2593	[redacted]
		SEE ATTACHED REPAIR JOBCARD 2593-CHECK TOE IN/OUT STEER WHEELS, FOUND TO BE OUT 5MM, REALIGNESD TO 0MM.*REMOVED DRIVER WHEEL & BRAKE DRUM TO INSPECT FOR CLICK SOUND BUT FOUND NO FAULT, CLEAN OUT DRUM & SHOES THEN REFIT DRUM & WHEEL, TOPPED UP STEER HUBS, GREASED KINGPINS & ADJUST BRAKES. NO MORE CLICKING SOUND HEARD.	
04/12/2025		**Chassis** R-2439	[redacted]
03/12/2025		**Chassis** R-2381	[redacted]
		SEE ATTACHED NAPA INVOICE #1430367067, OTHERS WENT INTO STOREROOM STOCK. SEE ATTACHED SERVICE JOBCARD 1128 WITH "FAULT FIXED"	
03/12/2025		**Cab** R-2306	Penske
		CONTACTED PENSKE (LEO) FOR BREAKDOWN OF PARTS DIAGRAM FOR GEARSTICK. NATHAN REQUESTED EXTENDER. EMAIL SENT TO LEO REQUESTING QUOTE FOR A GEARSTICK. SEE ATTACHED REPAIR JOBCARD.klms 1,011,920klms. Emailed Brian (Penske) quoted price $280 +gst. waiting on document quote so PO can be sent. SEE ATTACHED QUOTE FROM BRIAN., PO SENT. SEE ATTACHED INVOICE DTH109089T SEE ATTACHED SERVICE JOBCARD 1128 WITH FAULT FIXED.	
03/12/2025		**Coolant, Electrical, Engine** R-2012	[redacted]
		NATHAN ADV "UNKNOWN YET". SEE ATTACHED SERVICE JOBCARD 976. SEE ATTACHED SERVICE JOBCARD 1128 WITH FAULT FIXED.	
03/12/2025	1,054,726 kms	**C - 100k/Annual** S-1128	[redacted]
		PENSKE PARTS QUOTE DTH40612T. SEE ATTACHED PENSKE INVOICE DTH109995T. SEE ATTACHED PENSKE INVOICE DTH110361T FOR PRESSURE SWITCH. SEE ATTACHED SERVICE JOBCARD 1128	
03/12/2025		**Lights** R-2500	
		SEE ATTACHED SERVICE JOBCARD 1128 WITH NOTE "FAULT FIXED".	
29/11/2025	862,633 kms	**Chassis** R-2514	[redacted]

Date	Reading / Units	Type / Repairer Notes	Repairer
		SEE ATTACHED SERVICE REPAIR JOBCARD 1128 WITH FAULT FIXED TICKED. SEE ATTACHED REPAIR JOBCARD 2514.	
30/10/2025	30,184 kms	**Chassis** R-2406	[redacted]
22/10/2025	24,748 kms	**Chassis** R-2364	Truckline
		TRUCKLINE QUOTE 819626. PO1752. SEE ATTACHED INVOICE 10415080. 24HOUR HOSE INVOICE GT10754. SEE ATTACHED REPAIR JOBCARD 2364.	
30/09/2025	8,655 kms	**Engine** R-2281	[redacted]
		SEE ATTACHED REPAIR JOBCARD	
25/09/2025	4,054 kms	**Chassis** R-2257	[redacted]
		SEE ATTACHED REPAIR JOB CARD.	
24/09/2025	997,456 kms	**AdBlue** R-2265	Cummins
		VEHICLE DIAGNOSED BY CUMMINS. SEE ATTACHED INVOICE 1745737	
19/09/2025	998,992 kms	**Rotate** T-1070	[redacted]
15/09/2025	995,890 kms	**Cab** R-2233	[redacted]
		Replace wiper blades done on this repair. see attached repair job card.	
08/09/2025		**Chassis** R-2181	[redacted]
		SEE ATTACHED INVOICE FROM TRUCKLINE.	
14/08/2025	973,493 kms	**Lights** R-2030	[redacted]
		SEE ATTACHED REPAIR JOBCARD COMPLETED BY NATHAN 6/8/25. SEE ATTACHED REPAIR JOBCARD COMPLETED BY KENNYS AUTO ON 11/8/25. SEE ATTACHED INVOICE 61362.	
06/08/2025	971,357 kms	**Electrical** R-2007	Penske
		Replace 7 pin trailer plug. REPAIRED BY PENSKE.	
06/08/2025	971,357 kms	**C - 100k/Annual** S-976	[redacted]
		SEE ATTACHED JOBCARD.	
24/07/2025	13,733 kms	**Engine** R-1974	Penske
		As per attached from Penske	
23/07/2025		**Driveline** R-1751	
08/07/2025	958,304 kms	**Chassis** R-1892	
		Found oil leaking out fill pipe and auto tensioner spring broken. Remove and inspect all belts. Replaced auto tensioner for fan belt then refit both belts.	
19/06/2025	950,709 kms	**Driveline** R-1799	[redacted]
		Top up oil in hub and replace plug R/H side	
12/06/2025		**AdBlue** R-1786	
		Flush lines	
12/06/2025	868,061 kms	**Glass** R-1020	
12/06/2025		**Glass** R-1791	
26/05/2025	935,796 kms	**Pressure Check** T-824	[redacted]
		10x Pressure Check	
23/05/2025	933,629 kms	**Lights** R-1709	

Date	Reading / Units	Type / Repairer Notes	Repairer
		Unscrew L/H rear reverse light and found LED lights and cover has separated and filled with dust. Clean and check LED lights again and found to be bright still. Cleaned cover and reflector plate then used clear silicon to reseal light together. Remove tail light bolt that now visible and added large washer and silicon behind tail light. Refit repaired reverse light and looks new again. Park in yard and complete paperwork.	
22/05/2025	933,629 kms	**Cab** R-1704 Open bonnet. Replace wiper blacks. Topped up washer fluid. Test washers. Bend wiper arms until blades are straight with windscreen (90) and washer jets cover whole windscreen.	
22/05/2025	933,629 kms	**A - 10k** S-873 Flush/change clutch fluid. Carried out clutch adjustment.	
22/05/2025	933,629 kms	**Driveline** R-1678	
07/05/2025	924,968 kms	**Rotate** T-791 Side to side steer rotation Pressure Check	[redacted]
10/04/2025	911,193 kms	**Cab** R-1447 Inspect fuses as windows wont go up or down. Found wrong size fuses were used (too small) and replaced with correct size. Go over and replace all wrong fuses - found 8 too small and 4 other fuses that were only in wrong positions and swapped these back. Moved trailers out of workshop before putting truck in.	[redacted]
10/04/2025	911,193 kms	**B - 40k** S-838 Oil leak from engine oil spout, missing caps from sleeper a/c lines. Rekit L/H kingpin with meritor no-ream kit, remove and replace both steer hubs wheel seals. Degrease and trash steer hubs and brake assemblies of oil. Tighten driver back up light on mirror. 4hr service - 4hr repairs	[redacted]
07/04/2025	905,359 kms	**Cab** R-1410	KENNYS AUTO ELECTRICAL TSV
01/04/2025	906,529 kms	**Exhaust** R-1407 Unbolt 5" Step clamp, refit exhaust, tighten clamp with rattle gun	[redacted]
28/03/2025	904,421 kms	**Runout** T-731 1 Flip on Rim left outer rear 1 Runout right front outer Pressure Check	[redacted]
26/03/2025	904,031 kms	**Lights** R-1209 Awaiting new light Put plug on wiring as requested. Sourced new replacement headlights from JAS then returned lights as they don't fit. Sourced headlights at NAPA but still had trouble with fitment, removed all headlight cradles and modified to fit new lights. **Kenney's Auto Electrical did the fault finding, removal, rewiring and fitment of headlights** Tested operation and looks good.	[redacted] KENNYS AUTO ELECTRICAL TSV
26/03/2025	904,031 kms	**Exhaust** R-1375 Cut zipties holding exhaust stack on left side up. Remove head shield and loosen top clamp, unbolt top stack bracket and remove both halves from cab and exhaust, clean and tack bracket together, run die grinder along split then fill with weld, refit bracket to exhaust then bolt to cab, tighten clamps then refit heatshield.	
14/03/2025		**Fault Report** I-41 all gauges working at time of inspection	[redacted]
03/03/2025	890,867 kms	**Lights** R-1223 Test wiring to see if new light works, step up bolt hole size on mirror light bracket and fit new work light check position and adjust. Replaced suzi lead 7 pin lights plug as pins were missing.	[redacted]
03/03/2025	890,867 kms	**Cab** R-1217 Tightened all mirrors bolts/nuts, cleaned up workshop and completed all paperwork before leaving	[redacted]
28/02/2025	888,280 kms	**Cab** R-1211 Found power steering Res Cap Seal Leaking Found engine oil leaking from behind timing case	Primary Mechanical Repairs
24/02/2025	885,261 kms 3,892 hrs	**Chassis** R-1153 Found had alternator fault found loose belts & alternator faulty & was not charging so replaced alternator	KENNYS AUTO ELECTRICAL TSV

Date	Reading / Units	Type / Repairer Notes	Repairer
24/01/2025	867,993 kms 11,846 hrs	**Brakes** R-1034	Cummins
		- Truck arrived with complaint of high air system pressure causing seals to blow out in air system. - Complete ECM download and JSA. - Repair air leak at high pressure relief valve at air dryer. - Test operation and found that no signal is being sent to the air compressor to activate the unloaded valve. - Manually test operation of unloader valve, all ok. - The air governor valve is built into the air dryer assembly. - Air pressure builds to over 900kpa with no output from governor. - An attempt to adjust the governor to as unsuccessful. - Abnormal amounts of moisture are found in air system which indicates dryer is not functioning correctly. - Advise customer who decided to install a new air dryer assembly. - Pickup and install new dryer. - Test operation of air system, all ok compressor now unloads at 850kpa. - Perform test drive, all ok no air system faults and pressure maintained 850kpa. - After a test drive and a warmup, it was noticed that the air compressor was quite noisy with a slight air leak at the rear of the compressor head. - Although functioning correctly it is advised that the compressor should be changed to prevent future breakdowns. - The moisture in the air system and over pumping of the compressor due to governor malfunctioning is likely the cause of worn compressor. - Drained coolant. - Removed and replaced worn compressor as previously diagnosed. - Filled engine with coolant. - Engine started and checked for leaks, all ok. - Engine steam cleaned, and truck test driven, all ok. - Truck returned to service.	
24/01/2025	868,503 kms	**Cab** R-1032	[redacted]
		Unbolt remaining mudflap bracket, mark holes and drill marker sign, fit new marker sign, mudflap and bracket to L/H side, removed R/H mudflap and sign, drill and fit sign and mudflap the same way as the L/H side	
23/01/2025	868,473 kms	**Brakes** R-1028	[redacted]
		Compressor wont decompress and beeps blowing o-ring out refit valve, drove out to DC twice to refit o-ring during unloading then truck sent to cummins to get compressor fitted	
22/01/2025	868,061 kms	**Brakes** R-1013	[redacted]
		Drain tanks of air, remove bung from driver pre-tank and found full of water, remove and replace air drier filter, start truck to blow out remaining water and refit bung. Found compressor is not de-compressing at pull pressure.	
09/01/2025		**Engine** R-763	[redacted]
		17.09.2024 850834km -Inspect and noted down leaks, inspect over truck for further repairs required.	
09/01/2025		**Cab, Suspension** R-763	[redacted]
		17.09.2024 850834km -Unbolt shock mount from cab and bottom of shock and removed from vehicle for further repair	
09/01/2025	862,527 kms	**A - 10k** S-718	[redacted]
05/12/2024		**Glass** R-892	
05/12/2024	839,349 kms	**Cab, Electrical** R-892	[redacted]
		Wired new ABS plug onto end of suzi lead. Unplug airlines and unscrew gear handle, refit handle with thread locker and refit hoses.	
05/12/2024	839,349 kms	**C - 100k/Annual** S-666	[redacted]
		-ABS PLUG MISSING. -GEAR STICK HANDLE FACING SIDEWAYS. -CRACKS THROUGHOUT WINDSCREEN	
01/11/2024	808,160 kms	**B - 40k** S-592	Penske
18/09/2024		**Driveline** R-787	Penske
		REPAIRED BY PENKSE LYNTON	
17/09/2024		**Air Conditioner Cabin Truck dash** R-563	[redacted]
		sleeper air motor has failed17.09.24	
25/07/2024		**Flashing Light** R-563	[redacted]
25/07/2024		**Glass** R-563	
25/07/2024		**Driveline** R-563	[redacted]
		Unbolt and remove rear driveshaft uni to access front input	
25/07/2024		**Cab** R-563	[redacted]
25/07/2024	763,892 kms	**Cab** R-563	[redacted]

Date	Reading / Units	Type / Repairer Notes	Repairer
		Replaced wiper blades	
17/07/2024		**AdBlue** R-655	Penske
		refer to attached Penske invoice	
25/06/2024	763,892 kms	**Chassis** R-563	[redacted]
		Lubricate and remove all bolts and broken mudguards, use bolt holes from old guards and copy onto new guards, center punch all marks and drill each hole stepping drill bits up 7 times each hole. Fit new guards and remove plastic covers	
25/06/2024	763,892 kms	**A - 10k** S-433	[redacted]
21/06/2024		**Pressure Check** T-305	[redacted]
		Pressure check tyres x10	
21/06/2024		**Pressure Check** T-331	
18/06/2024		**Engine** R-538	LS Contracting
13/06/2024		**Engine** R-430	[redacted]
28/05/2024	752,683 kms	**A - 10k** S-379	[redacted]
		Delete 1 line from labour please	
28/05/2024	752,269 kms	**Electrical** R-417	[redacted]
		Disconnected battery terminals, remove cables from starter, unbolt and remove old starter, clean up cable terminals, fit new starter and fit cables, refit battery terminals.	
28/05/2024		**Driveline** R-417	[redacted]
27/05/2024	749,513 kms	**Air Conditioner Cabin Truck dash** R-417	[redacted]
		Inspect and found withing to a/c pressure switch corroded, remove pin and clean with wire brush, bent pins to side slightly for better contact and refit, no more issues found with a/c.	
27/05/2024	752,269 kms	**Engine** R-439	[redacted]
		Topped up engine oil	
27/05/2024	752,269 kms	**Air Conditioner Cabin Truck dash** R-439	[redacted]
		Replaced wiring going to a/c pressure switch	
27/05/2024		**Electrical** R-438	M green family trust
27/05/2024		**Glass** R-430	
27/05/2024	749,513 kms	**Lights** R-417	[redacted]
		Pop rivet L/H rear side light bracket back onto tail bar. No faults found with lights	
22/05/2024	749,513 kms	**B - 40k** S-357	[redacted]
		Passenger windscreen cracked. Clutch springs fallen out inspection hole.	
21/05/2024	749,513 kms 1 hrs	**Main/inspect** T-231	
21/05/2024		**New** T-230	[redacted]
01/05/2024	739,336 kms	**A - 10k** S-286	[redacted]
16/04/2024		**Driveline** R-198	24 Hour Hose
08/04/2024		**Trailer Clean/Sanitation Exterior 2hrs** R-264	[redacted]
16/02/2024	708,339 kms	**Brakes** R-53	

Date	Reading / Units	Type / Repairer Notes	Repairer
		Inspect for airleaks, found supply hose from compressor perished and cab ride hieght constantly exhausting, remove and replace cab ride hieght under parts warranty. repairer came out to remove and replace hose. (Found that driver was actually referring to the idle alarm when sitting to long in one place) PARTS WARRANTY - PENSKE PART TO BE ADDED AS -1 WHEN CREDIT COMES.	
16/02/2024	708,339 kms	**Suspension** R-53 Inspect but found no fault, believe repair was rectified previously. No labour - Charged as part of C service from NQFM invoice.	
16/02/2024	708,339 kms	**Electrical** R-56 Found horn wire in steering wheel broken. Cut, strip and fit new terminal to wire and fit back onto horn button, horn still not working. Inspect fuses and found no fuse for horn, fit new fuse and horn is working again, test park brake door alarm and horn comes on with door open. 0.5 hours deleted, as NQFM charged as part of the service invoice.	NQ Fuel & Maintenance (RCC Lowth Pty Ltd)
16/02/2024	708,339 kms	**Engine** R-56 Found bolt missing on radiator cross member on driver side which caused bonnet support connected to move and rub on hose on reservoir. Removed driver air cleaner stack for access to bolt hole, upon removal found bolt had fallen down into brake hose and was still usable, refit bolt with thread locker and refit air cleaner stack. Not enough hose to cut back and refit, remove and replaced hose and clamps provided by 24hr hose. Topped up coolant and checked for further leaks. *added another job line for 24 hour hose work* 2.0 hours deleted from this job, as NQFM charged as part of the service.	NQ Fuel & Maintenance (RCC Lowth Pty Ltd)
16/02/2024	708,339 kms	**Engine** R-53 Inspect cruise control and found to be working, driver didnt know how to work W/Star switch	
16/02/2024	711,631 kms	**Air Conditioner Cabin Truck dash** R-53 Wrong truck NIL	
16/02/2024	708,339 kms	**C - 100k/Annual** S-172 Carried out Sleeper Air service along side C service. SLEEPER HRS:2556 (Next Service 2806Hrs) Drain bung on sleeper is seized, had to remove all covers and drain from other side of motor, found rear sleeper face plate (Rego cover) has broken around bolt on R/h side, tightened belts while cover was off, cut back fuel hose where hose had worn through and made sure hose wouldn't rub again, refit rego cover with larger washer on R/h side. Test sleeper air operation. John checked all tyres.	NQ Fuel & Maintenance (RCC Lowth Pty Ltd)
16/02/2024	708,339 kms	**Lights** R-56 Fabricate 90° light bracket out of old sign, fit new side marker light and bracket to R/h of rear bar. Inspect wiring for l/h front tank lights, found connecter pin pulled out, refit pin and tied up wiring. 0.75 hours deleted off this job, as NQFM charged as part of the service invoice.	NQ Fuel & Maintenance (RCC Lowth Pty Ltd)
16/02/2024	711,631 kms	**Fuel** R-53 Clean contacts on fuel guage and refit wiring, guage is now working. No labour - Charged as part of C service from NQFM invoice.	
16/02/2024	711,631 kms	**Cab** R-53 Found washer bottle was empty and no other repair required, cleaned bugs off wiper path and replaced wiper blades. No labour - Charged as part of C service from NQFM invoice.	
16/02/2024	708,339 kms	**Engine** R-53 Inspect Kysor Fan, found air leaking from clutch and slight movement in bearings, remove fan belt and fan, remove airline then unbolt and remove kysor fan. Upon disassembly found that bearings had collapsed and clutch with need replacment from damage. Rekit fan hub and fit new kysor fan clutch, fit fan clutch assembly to engine and test operation.	
16/02/2024	711,631 kms	**Air Conditioner Cabin Truck dash** R-53 Diagnose and found broken wire around compressor, works when moving wiring, further testing found issue was with a/c pressure switch power wire, cut out wire and solder in new length, test operation and tie all wiring away. fit p/clamp where previous clamp had broken off on a/c compressor discharge hose. No labour - Charged as part of C service from NQFM invoice.	
09/02/2024	708,339 kms	**Coolant** R-56 Work carried out by 24 Hour Hose.	24 Hour Hose
18/01/2024		**Battery** R-68	Outback Batteries
25/10/2023	643,443 kms	**C - 100k/Annual** S-15	NQ Fuel & Maintenance (RCC Lowth Pty Ltd)

Date	Reading / Units	Type / Repairer Notes	Repairer
		C SERVICE	
27/09/2023	627,778 kms	**B - 40k** S-16	Primary Mechanical Repairs
		B SERVICE	

Signed: _____

Name: _____

Date: _____