CUSTOMER #: 369
UNIT# B1351
IBS - Barney Trucking
IBS Cust#:569874
235 SO SR24
SALINA, UT 84654
HOME:315-800-2438 CONT:435-529-3701
BUS: 435-529-3701 CELL:

13737S

INVOICE

PAGE 1

JACKSON GROUP PETERBILT - SALINA
385 E. 1620 S.
Salina, Utah 84654
Phone: (435) 562-7383

Jackson Group
PO Box 2208
Decatur, AL 35609-2208
Phone: (800) 332-9140

SERVICE ADVISOR: 1935 JOSH ALLAN

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
BLUE	22	PETERBILT 579	1XPBDP9X1ND796388		215825/215825	TB1351

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP21 DD			23:00 30MAY23	7-329163	0.00	IBS	28JUN23

R.O. OPENED	READY	OPTIONS:
30MAY23	28JUN23	STK:ND796388 DLR:P250 ENG:Y260596

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
A ENGINE DAMAGED DUE TO LACK OF OIL INSTALL SWING ENGINE			
CAUSE: ENGINE			
ENG ENGINE REPAIRS			
1948CBRGM			
3493CBRGM			
2854CBRGM			
3645CBRGM			
3672CBRGM			
		4350.00	4350.00
2 9212TRP CLAMP-HOSE W/LINER #12	3.52	1.64	3.28
3 9208TRP CLAMP-HOSE W/LINER #8	3.38	1.56	4.68
1 6306LLUA1C3/2E BEARING	22.98	13.79	13.79
2 1844896PE GASKET-EXHAUST CIRCULAR 4"	15.91	12.25	24.50
2 90-0012 CLAMP-V BAND 4"	19.11	10.52	21.04
1 1923003PE GASKET	15.77	10.07	10.07
2 123130EXX MOBIL ATF D/M CASE 6X1QT	7.07	5.70	11.40
6 EC3101 COOLANT-TRP ELC CONCENTRATE JUG	18.50	13.88	83.28
1 F51-6008M14 FAN-11 BLADE 31' OD 3.62" PW			
10.43" PD	306.96	191.85	191.85
1 SWINGENGINE SWING ENGINE	27395.26	27395.26	27395.26
1 P2127 M10 X 4 BOLT	2.53	2.53	2.53
TECH TECHNOLOGY FEE			
1948 CTEC		50.00	50.00
215825 ENGINE 1948 DRAINED COOLING SYSTEM, RECOVERED FREON, REMOVED RADIATOR ASSEMBLY, REMOVED ENGINE FAN AND SHROUD, FOUND ENGINE FAN WAS BROKEN, REMOVED WINDSHIELD COWLING, REMOVED WIPER ASSEMBLY, REMOVED AIR FILTER HOUSING AND TUBING, REMOVED COOLANT RESERVOIR, CAGED CLUTCH, REMOVED CLUTCH SERVO, REMOVED CLUTCH BOLTS, REMOVED LOWER BELL HOUSING BOLTS, SUPPORTED TRANSMISSION WITH JACK, REMOVED TRANS ACCESS COVER IN CAB, REMOVED GEAR STICK, REMOVED COOLANT LINES FROM TRANS COOLER, REMOVED UPPER BELL HOUSING BOLTS, DISCONNECTED AIR LINES, DISCONNECTED ALL FUEL LINES FROM ENGINE, DISCONNECTED OEM ENGINE HARNESS FROM FIREWALL, REMOVED BATTERY CABLES FROM STARTER, REMOVED POWER STEERING LINES FROM CHASSIS, DISCONNECTED EXHAUST FROM CHASSIS, REMOVED ENGINE			

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item\items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

CUSTOMER #: 369
UNIT# B1351
IBS - Barney Trucking
IBS Cust#:569874
235 SO SR24
SALINA, UT 84654
HOME:315-800-2438 CONT:435-529-3701
BUS: 435-529-3701 CELL:

13737S

INVOICE

PAGE 2

JACKSON GROUP PETERBILT - SALINA
385 E. 1620 S.
Salina, Utah 84654
Phone: (435) 562-7383

Jackson Group
PO Box 2208
Decatur, AL 35609-2208
Phone: (800) 332-9140

SERVICE ADVISOR: 1935 JOSH ALLAN

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
BLUE	22	PETERBILT 579	1XPBDP9X1ND796388		215825/215825	TB1351

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP21 DD			23:00 30MAY23	7-329163	0.00	IBS	28JUN23

R.O. OPENED	READY	OPTIONS:
30MAY23	28JUN23	STK:ND796388 DLR:P250 ENG:Y260596

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
MOTOR MOUNT BOLTS, LIFTED ENGINE, REMOVED FRONT CROSS MEMBER, REMOVED ENGINE FROM CHASSIS, REMOVED ALL ACCESSORY COMPONENTS AND OEM ENGINE HARNESS FROM SWING ENGINE, INSTALLED ALL ACCESSORY COMPONENTS AND OEM ENGINE HARNESS ONTO NEW ENGINE, INSTALLED NEW ENGINE INTO CHASSIS, INSTALLED FRONT CROSS MEMBER, INSTALLED MOTOR MOUNT BOLTS, INSTALLED TRANSMISSION BELL HOUSING BOLTS, INSTALLED CLUTCH BOLTS, REMOVED CLUTCH CAGE BOLTS, RECONNECTED OEM ENGINE HARNESS TO FIREWALL, RECONNECTED ALL BATTERY CABLES TO STARTER, RECONNECTED POWER STEERING LINES, INSTALLED NEW ENGINE FAN, INSTALLED SHROUD, INSTALLED RADIATOR ASSEMBLY, INSTALLED COOLANT RESERVOIR, RECONNECTED ALL COOLANT LINES FILLED COOLING SYSTEM WITH NEW COOLANT, RECONNECTED FUEL LINES, RECONNECTED EXHAUST WITH NEW CLAMPS AND GASKETS, VACUUMED AND CHARGED AC, MOTOR WAS ALL FILLED WITH NEW OIL FROM FACTORY, INSTALLED WIPER ASSEMBLY, INSTALLED WINDSHIELD COWLING, INSTALLED AIR FILTER HOUSING AND TUBING, BLED FUEL SYSTEM, STARTED ENGINE AND CHECKED FOR LEAKS, NO LEAKS PRESENT, RECONNECTED GEAR STICK, RECONNECTED ALL AIR LINES, REINSTALLED TRANSMISSION ACCESS COVER I CAB, HOOKED TO DAVIE AND PROGRAMMED PCI TO CHASSIS, CLEARED POWER DOWN MEMORY, CLEARED ALL CODES AND ROAD TESTED, NO CODES RETURNED AND NO LEAKS PRESENT							
**********							
B** IBS APPROVAL CODE LS7944 IF CUSTOMER INFO							
	1935		C		0.00	0.00	
**********							
MISC ** ENVIRONMENTAL FEE **							
			C		25.00	25.00	

****

ESTIMATE: 0.00 30MAY23 14:16 SA: 1935
CONTACT:

****

CUSTOMER PAY Misc. Shop Supplies for Repair Order FOR REPAIR ORDER 437.50

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item\items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

CUSTOMER #: 369
UNIT# B1351
IBS - Barney Trucking
IBS Cust#:569874
235 SO SR24
SALINA, UT 84654
HOME:315-800-2438 CONT:435-529-3701
BUS: 435-529-3701 CELL:

13737S

INVOICE

PAGE 3

JACKSON GROUP PETERBILT - SALINA
385 E. 1620 S.
Salina, Utah 84654
Phone: (435) 562-7383

Jackson Group
PO Box 2208
Decatur, AL 35609-2208
Phone: (800) 332-9140

SERVICE ADVISOR: 1935 JOSH ALLAN

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
BLUE	22	PETERBILT 579	1XPBDP9X1ND796388		215825/215825	TB1351

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP21 DD			23:00 30MAY23	7-329163	0.00	IBS	28JUN23

R.O. OPENED	READY	OPTIONS:
30MAY23	28JUN23	STK:ND796388 DLR:P250 ENG:Y260596

LINE	OPCODE	TECH	TYPE	HOURS		LIST	NET	TOTAL
DAMAGED ENGINE					PETERBILT "TRUCKCARE" (800)473-8372 24 HOUR EMERGENCY ROADSIDE SERVICE WWW.PETERBILT.COM			

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item\items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	4400.00
PARTS AMOUNT	27761.68
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	462.50
TOTAL CHARGES	32624.18
LESS INSURANCE	0.00
SALES TAX	2153.20
PLEASE PAY THIS AMOUNT	34777.38

CUSTOMER COPY