

PLANT MAINTENANCE RECORD

Asset No.

AB-347

Last updated: 18/04/2017
Last reviewed: 18/04/2017

PURCHASE DATE 4-10-2017		DESCRIPTION Ingersoll Rand		REG No.	
MODEL HP-7000	BUILT 2017	OIL ENGINE		OIL DRUM	
SERIAL NO. 70 000567		OIL HYDRAULICS		OIL TORQUE DRUM	
ENGINE NO.		OIL TRANSMISSION		COOLANT	
VIN NO.		OIL DIFFERENTIAL			
		OIL FINAL DRIVE			
FILTER ENGINE		TYRE FRONT		PRESSURE	
ENGINE BYPASS		TYRE REAR		PRESSURE	
FILTER HYDRAULICS					
AXLE BREATHER		BATTERY			
FILTER FAN					
FILTER TRANSMISSION					
FILTER AIR INNER	OUTER	SERVICE PERIOD		HOURS	
FILTER FUEL				Km	
FILTER FUEL SECONDARY					
WATER SEPARATOR		OTHER			
FILTER AIRCON					
FILTER CAB					
BELTS					
OTHER					

WORKSHOP JOB CARD

Last updated: 18/04/2017
Last reviewed: 18/04/2017

AS-347

DATE	FITTERS NAME	WORK DETAILS	
10-10-17	James Duggan	Took the delivery of the Indeco Bearer HP-7000	
11/11/17	Scott / Keith.	TURN & MOW AROUND 180'. FIT NEW ROLL PINS TO RETAINERS, GREASE OIL.	
12/11/17	SCOTT.	ATTEND LULDALE, FIT CHISEL POINT MOW.	34 HPS ON MACHINE.
28/11/17	SCOTT.	MAKE UP 1 1/4 BSP WITH CHAIN LINK WELDED ON FOR HOSE STORAGE	
1-9-18	Indeco	Supply a New Chisel Point	BE-253237
2-10-18	Indeco	Supply a New Bunt Tool	BE-253546
9/11/18	SCOTT / KRIS.	FIT NEW BLUNT MOWIE. CID FROM WORK OUT.	
1/11/18	SCOTT / KRIS.	FIT NEW POINTED CHISEL FOR WORK ON HILL TO RETRIEVE STABS OF STONE. POINT LOST BY END OF DAY. CHISEL LEFT ON FOR BRENNAN BACK IN CRUSHING ZONE.	BE-253237
1-1-19	Hose Use	Supply a New Hose for the Hammer.	BE-255838
1-1-19	James Duggan	Wave Up and Fit Wear Plates to the Base of the Hammer and Hoe	BE-255875
3-3-19	Scott / Kris	Free Leverage Edgers Fit Second hand Flat chisel Reused all old Retainer Pads	
3/4/19.	KRIS.	REPLACE BOTTOM BECAUSE BUSH AND CIRCUIT. FIT NEW FEAT MOWIE , REPLACE BOTH RETAINING PLATES, AS OLD ITEMS SECTIONS BROKEN CUT FROM AFFRONT DET FILLING. HEAD RATE CHANGED OUT TO UNIT FOR FITMENT TO 349D. NEW Roll PINS FITTED TO RETAINING PINS. HAMMER FITTED UP TO AS343 AND TOWNS CHECKED.	BE-26422.
30/4/19.	SCOTT.	FIT HEAD RATE TO SUIT 336E EXCAVATOR.	
6/8/19	Paul / Kris	Remove worn out flat chisel . Replace with New Flat chisel	BE-27054
8/9/19.	SCOTT	leave to Run for 2 hours, then replace with Sharp chisel	100696
8/10/19	SCOTT	REPLACE NYLON GREASE LINE AND FITTINGS. LINE RUNS FROM PISTER. TO CHISEL BORE HOSE AND FITTINGS SOURCED FROM PISTER.	BE-27340.
3/10/19	PAUL HINES	REPLACE BRASS COMPRESSION FITTING FOR GREASE LINE , FITTING BROKEN OFF. REPLACE WEEDING HAMMER RETURN HYDRAULIC HOSE REPLACEMENT HOSE FROM STOCK, WINS MADE BY HOSE-IT.	
10-10-19	Hose Use	Supply 1x New Pressure Hose , 1x New Return Hose	BE-275448

DATE	FITTERS NAME	WORK DETAILS	
16/10/19	KRIS / SCOTT	COLLECT BLACK AND PLASTIC GREASE LINE FITTINGS FOR BOTTOM LINE, AUTO GREASER. FIT TO HAMMER + TEST (OIL) BR27340. PROBLEM.	BR27351.
20/10/19	KRIS	Reported oil leaking into grease cartridge checked auto greaser piston + seal damaged. pump needs replacing.	
31/10/19	KRIS	Replaced auto greaser pump + tighten side cover plate that had rattled loose.	BR27352.
1/11/19	KRIS	Reported oil leak from hammer found frequency valve broken remove broken halves of plug from hammer shims + spring were lost pick up shiny spring + New Blunt chisel from index. fit New frequency valve with 2 shims	BR27353
1/11/19	SCOTT.	REMOVE WORN OUT MALLE, ONE BRICK RETAINING PIN BROKEN, BRONZE BUSH WORN DOWN TO CIRCIP. CUT OUT BUSH, CLEAN UP, ON INSPECTION SPACER AROUND ANVIL FOUND TO BE CRACKED, HAMMER CONVERTED TO INDECO TO BE STRIPPED/REPAIRED.	BR27354
22/11/19	INDECO.	HAMMER RETURNED TO SITE AFTER REPAIRS BY INDECO.	BR-27355
22/11/19	KRIS.	NEW MALLE FITTED, BROKEN BRICK RETAINING PIN REPLACED. HAMMER PUT BACK INTO SERVICE.	
29/11/19.	SCOTT.	INSPECT HAMMER & AUTO GREASER NOT WORKING. BLEED SYSTEM, TURN ADJUSTMENT IN 1/2 TURNS. RUN HAMMER WITH GREASE LINE DISCONNECTED FROM UNIT. CONFIRM UNIT PUMPING GREASE. RE-CONNECT AND PUT BACK INTO SERVICE.	
20/11/19.	SCOTT.	REPLACE LEAKING GREASE MALLE, FRONT OF HAMMER, AUTO GREASE LUBE BLEED.	
01/12/20	KRIS	Remove 2X Frequency Valve Shims to slow down hammer.	
31/2/20	SCOTT	INSPECT & REPAIR AUTO GREASER NOT WORKING. SWAP CARTRIDGES WITH NEW	

DATE	FILTERS NAME	WORK DETAILS	
		UNITS FROM SANDO'S MACHINE WHICH ARE KNOWN TO BE WORKING. BREAK OFF LEVER ADJUSTER - BLEED AND TEST. APPEARS TO BE WORKING OK.	
29/2/20	SCOTT.	FT NEW BLUNT MOULE TO HAMMER WITH NEW ROLL PINS.	BP28138.
23/5/20.	SCOTT.	FT USED POINTED CHISEL AND NEW REMAINING ROLL PINS.	BP28706.
26/2/20	KRIS	Make up impact wear plates and weld to lower edge of hammer body	336121304r
21/6/20	Scott/Kris	Replace Blunt Mogle + Roll pins	BP29065
01/7/20	Paul/Kris	Replace Mogle Retainers Run again Roll pins Replaced.	BR30165
21/9/20.	SCOTT / PAUL HINES.	REPLACE HAMMER MOULE AND ROLL PINS.	BP30458
21/9/20	SCOTT	EXTRACT BROKEN OFF CAP SCREW FROM CREOSSE BLOCK. FT NEW CAP SCREW AND LOCK WASHERS	BP30458.
21/3/21	CRALG - DOZER/UNED.	WELD UP CRACKS AROUND THE PINS ON HEAD PLATE. 336E UNIT.	B 31841.
1/2/21.	SCOTT / KRIS	CHANGE HEAD OVER TO ITEM TO SUIT 349 QUICK HITCH. FT NEW POINTED CHISEL TO HAMMER TO BE SENT TO PARKENTHAM.	
1/5/21	Kris / Paul	Change over Head Plate to suit 336E	
2/6/21	Kris	Remove Slug, Spool + Shims from frequency valve to slow hammer down.	
4/6/21	Kris	Replace blunt Mogle Replace both Retainer plates back Pins + Roll pins	B32186.
9.6.22	CRALG	Replace LHS hammer hose, part taken from store	B335638
3/2/22.	SCOTT.	REFIT R/H HAMMER HOSE.	
21/4/22	RONNY	IF DROP HAMMER TO INDECO FOR INSPECTION & HAMMER NOT FIRING.	
	RONNY	COLLECT HAMMER COGE FROM INDECO. WELD ON HEEL BLOCKS, correct Blocks etc TO BASE AS BASE WORN OUT. GET RIGHTER BLOCKS ETC	B35534.
5/5/22.	INDECO LIVERTON.	REPAIRS TO HAMMER, STRIP AND INSPECT. SIDE TIE RODS FOUND TO BE BROKEN, INTERNALS COCKED SIDEWAYS JAMMING UP HAMMER. REPAIR AS NECESSARY, FT NEW	

AS 347

[illegible]



A TOOL FOR EVERY JOB

ACN 056 693 344 ABN 96 056 693 344

1 Burgess Street
Brooklyn, Vic 3012
Tel: 03 9315 3266
Fax: 03 9314 4140
Parts Fax: 03 9318 0507
Email: indeco@indeco.com.au

Unit 10, 135 Long Street
Smithfield, NSW 2164
Tel: 02 9725 4522
Fax: 02 9604 7545
Email: indeconsw@indeco.com.au

Tax Invoice

507240

Date: 3/06/2022
Customer Code: BAY010
Customer Order: B-35690
ABN Number: 82 128 854 124

Page 1 of 2

Sold To:

BAYPORT CIVIL PTY LTD
55 COLMANS ROAD
CARRUM DOWNS
VIC

3201

Deliver To:

BAYPORT GROUP PTY LTD
55 COLMANS ROAD
CARRUM DOWNS
VIC

3201

Job Description: REPAIR HAMMER AS PER QUOTE

Cost Centre Desc	Cost Centre	Code	Description	Quantity	Unit	Price	Disc%	Tax%	Total Value
Job Details... 32335			HP7000 BAYPORT S/N 0567						
			REPAIR HAMMER AS PER QUOTE						
PARTS	SP		UPPER BUSH - 7000 SERIES	1.00	EA	2,191.20		10.00	2,410.32
PARTS	SP		ELASTIC PIN -181 > 350 -1200 - 5000 > 7000 SERIES	2.00	EA	8.70		10.00	19.14
PARTS	SP		GREASING PIN - 7000 > 12000	1.00	EA	35.70		10.00	39.27
PARTS	SP		SEAT - 2000 > 18000 SERIES	1.00	EA	111.40		10.00	122.54
PARTS	SP		PLATE - 2000 > 18000 SERIES	1.00	EA	11.90		10.00	13.09
PARTS	SP		FLANGE - 2000 > 18000 SERIES	1.00	EA	34.70		10.00	38.17
PARTS	SP		INSERT BUSH *BRONZE * - 7000 SERIES	1.00	EA	1,938.10		10.00	2,131.91
PARTS	SP		INSERT BUSH CIRCLIP - 7000 SERIES	1.00	EA	29.20		10.00	32.12
PARTS	SP		SIDE BOLT RUBBER - 7000 SERIES	4.00	EA	1,307.60		10.00	5,753.44
PARTS	SP		INDECOIL SIDE BOLT NUT - 7000 SERIES	4.00	EA	188.20		10.00	828.08
PARTS	SP		RUBBER STOP 5000 - 7000 SERIES	4.00	EA	13.00		10.00	57.20
PARTS	SP		SIDE BOLT LOCK - 7000 SERIES	4.00	EA	20.60		10.00	90.64
PARTS	SP		WASHER - 2000 > 12000 SERIES	2.00	EA	14.10		10.00	31.02
PARTS	SP		SEEGER - 2000 > 12000 SERIES	2.00	EA	9.80		10.00	21.56
PARTS	SP		SPACING DISC - 3000 > 4000 SERIES	1.00	EA	21.70		10.00	23.87
PARTS	SP		DIAPHRAGM (POLYURETHANE) - 7000 > 9000 SERIES	1.00	EA	670.60		10.00	737.66
PARTS	SP		INFLATING SCREW - 500 > 18000 SERIES	1.00	EA	35.70		10.00	39.27
PARTS	SP		SEALING RING - 500 > 18000 SERIES	1.00	EA	9.80		10.00	10.78
PARTS	SP		FIXING SCREW - 7000 > 18000 SERIES	4.00	EA	11.90		10.00	52.36



A TOOL FOR EVERY JOB

ACN 056 693 344 ABN 96 056 693 344

1 Burgess Street
Brooklyn, Vic 3012
Tel: 03 9315 3266
Fax: 03 9314 4140
Parts Fax: 03 9318 0507
Email: indeco@indeco.com.au

Unit 10, 135 Long Street
Smithfield, NSW 2164
Tel: 02 9725 4522
Fax: 02 9604 7545
Email: indeconsw@indeco.com.au

Tax Invoice

507240

Date: 3/06/2022
Customer Code: BAY010
Customer Order: B-35690
ABN Number: 82 128 854 124

Page 2 of 2

Sold To:

BAYPORT CIVIL PTY LTD
55 COLMANS ROAD
CARRUM DOWNS
VIC

3201

Deliver To:

BAYPORT GROUP PTY LTD
55 COLMANS ROAD
CARRUM DOWNS
VIC

3201

Job Description: REPAIR HAMMER AS PER QUOTE

Cost Centre Desc	Cost Centre	Code	Description	Quantity	Unit	Price	Disc%	Tax%	Total Value
PARTS	SP		SPHERICAL WASHER - 7000 > 18000 SERIES	4.00	EA	26.00		10.00	114.40
PARTS	SP		WEARPLATE - 7000 >12000 SERIES	4.00	EA	143.90		10.00	633.16
PARTS	SP		WEARPLATE SHIM - 7000 > 12000 SERIES	4.00	EA	23.80		10.00	104.72
PARTS	SP		SEAL KIT - 7000 SERIES FROM S/No 0206 (-07/-09)	1.00	EA	1,017.70		10.00	1,119.47
PARTS	SP		BLUNT TOOL - 7000 SERIES 1450 LG	1.00	EA	3,611.20		10.00	3,972.32
		6015.03	GAS FOR BREAKER	1.00		50.00		10.00	55.00
		6015.03	REPAIRS SERVICING	28.00		100.00		10.00	3,080.00
		6015.03	SHRINK WELD UPPER BUSH & BUILD UP SPACER	1.00		0.00		0.00	660.00
		6015.03	MACKINE SPACER AND STRIKE FACE ON PISTON	1.00		0.00		0.00	670.00
		7115.03	CONSUMABLES	1.00		100.00		10.00	110.00

Payment Terms: 1 Month after the End of the Month

BANKING DETAILS. (ANZ). BSB 013-373, ACCOUNT 287365372

LEGAL & EQUITABLE PROPERTY OF GOODS SHALL NOT BE PASS TO THE BUYER UNTIL FULL PAYMENT HAS BEEN RECEIVED

Returned items may be subject to a 15% restocking fee
All freight is the purchaser's Responsibility

Tax: 1,967.41
Total Value: 22,971.51











