

ANNUAL VEHICLE INSPECTION REPORT

Detroit Rebuild Specialist, LLC
 1347 Meredith Park Drive
 McDonough, GA 30253
 770-262-9119
 mcreacasey@yahoo.com
<https://detroitrebuildspecialist.com/>



INVOICE

BILL TO

Komi sogbo
 Komi sogbo

INVOICE # 259881
DATE 11/17/2025
DUE DATE 11/17/2025

STOCK #
 jn2497

MILEAGE
 611392

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
Valve Adjustment	Adjust all valves back to factory specs		599.99	599.99T
DD13 Valve Cover Gasket	DD13 Valve Cover Gasket		67.84	67.84T
Labor	Replace leaking injector harnesses while valve cover is off.	1	185.00	185.00
Front Injector Harness	Front Injector Harness		116.04	116.04T
Rear Injector Harness	Rear Injector Harness		116.04	116.04T
Labor	Perform PM service. Change transmission fluid and differential fluids.	2.50	185.00	462.50
Oil Filter	Oil Filter		44.13	44.13T
2 Fuel Filter Kit	2 Fuel Filter Kit		97.63	97.63T
Air Filter	Air Filter		120.90	120.90T
75w 90 Synthetic Gear Oil	75W 90 Synthetic Gear Oil	3	185.85	557.55T
15w40 Engine Oil	15w40 Synthetic Blend Engine Oil	11	21.99	241.89T
Grease	Lubricating Grease		8.99	8.99T
Labor	Replace leaking oil pressure sensor, and replace old air dryer filter.	2	185.00	370.00
Oil Pressure Sensor	Oil Pressure Sensor		93.84	93.84T
Air Dryer Filter	Air dryer cartridge		110.83	110.83T
Labor	Drop oil pan to replace suction manifold. Replace suction manifold, tube o rings, oil pan drain plug o rings, and oil pan gasket while pan is down. Put the oil pan back up.	4	185.00	740.00
Gen 5 Oil Manifold	Gen 5 Oil Suction Manifold		213.84	213.84T
Pick Up Tube Orings	Oil pick up tube orings		65.00	65.00T
DD13 Oil Pan Gasket	DD13 Oil pan gasket		69.12	69.12T
Oil Pan Drain Plug Seal	Oil Pan Drain Plug Seal	2	13.89	27.78T
Labor	Check driver side and passenger side EGR pipes for potential coolant. Remove delta pressure sensor to inspect and clean. Remove 7th injector to inspect and clean. Replace cabin air filter.	2	185.00	370.00
Cabin air filter	Cabin air filter		17.76	17.76T
Labor	Hook up laptop and go into the programming to change speed limit and cruise to 75. Turn off idle shut down. Remove battery cover and terminals to check life of all batteries.		185.00	185.00

DISCLAIMER OF W: The seller hereby is expressing all W, either expressed or implied.

All invoices paid by credit or debit card will be subject to a 3% fee. A 3% fee on total labor will be applied to cover the cost of non-billable items used during repairs. These include but are not limited to: Starting Fluid, Brake Cleaner, Shop Towels, Silicone, Buffing Pads, Bolts, Nuts Waste Disposal, Etc

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
259881	182497
DATE	

MOTOR CARRIER OPERATOR To Go Freight LLC	INSPECTOR'S NAME (PRINT OR TYPE) Casey McCreary
ADDRESS 19 Millstream Ct	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE Newnan GA 30263	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 3AK5GBDV555JN2497
VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED													
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM		
1. BRAKE SYSTEM													
✓			a. Service Brakes				6. SAFE LOADING	✓			10. TIRES		
✓			b. Parking Brake System					✓				a. Tires on any steering axle of a power unit.	
✓			c. Brake Drums or Rotors	✓								b. All other tires.	
✓			d. Brake Hose									c. Installation of speed-restricted tires unless specifically designated by motor carrier.	
✓			e. Brake Tubing										
✓			f. Low Pressure Warning Device	✓									
✓			g. Tractor Protection Valve										
✓			h. Air Compressor	✓									
✓			i. Electric Brakes										
✓			j. Hydraulic Brakes										
✓			k. Vacuum Systems										
✓			l. Antilock Brake System										
✓			m. Automatic Brake Adjusters										
2. COUPLING DEVICES													
✓			a. Fifth Wheels				7. STEERING MECHANISM	✓			11. WHEELS AND RIMS		
✓			b. Pintle Hooks									a. Lock or Side Ring	
✓			c. Drawbar/Towbar Eye	✓								b. Wheels and Rims	
✓			d. Drawbar/Towbar Tongue	✓								c. Fasteners	
✓			e. Safety Devices	✓								d. Welds	
✓			f. Saddle-Mounts	✓									
3. EXHAUST SYSTEM													
✓			a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.	✓									
✓			b. Bus exhaust system leaking or discharging in violation of standard.	✓									
✓			c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	✓									
4. FUEL SYSTEM													
✓			a. Visible leak.				8. SUSPENSION	✓			12. WINDSHIELD GLAZING		
✓			b. Fuel tank filler cap missing.									Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).	
✓			c. Fuel tank securely attached.	✓									
5. LIGHTING DEVICES													
✓			All lighting devices and reflectors required by Part 393 shall be operable.	✓									
9. FRAME													
			a. Frame Members										
			b. Tire and Wheel Clearance										
			c. Adjustable Axle Assemblies (Sliding Subframes)	✓									
13. WINDSHIELD WIPERS													
											Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.		
14. MOTORCOACH SEATS													
											Any passenger seat that is not securely fastened to the vehicle structure.		
15. OTHER													
											List any other condition(s) which may prevent safe operation of this vehicle.		

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
DOT Inspection	DOT Inspection	1	185.00	185.00T
Labor	Replace leaking water pump.	3	185.00	555.00
DD15 Water Pump	Variable Speed Water Pump		849.21	849.21T
Labor	Replace old loud belt tensioner and both belts.	2	185.00	370.00
Belt Tensioner	Belt Tensioner		302.90	302.90T
Fan Belt	Fan Belt		49.71	49.71T
Accessory Drive Belt	Accessory Drive Belt		69.84	69.84T
Labor	Remove hood, bumper and left fender. Repair all parts possible and replace with what customer supplied. Paint everything to match.		3,000.00	3,000.00
Shop Supplies	Shop Supplies		45.00	45.00T
Processing Fee	Card processing fee. (This fee is charged by the CARD PROCESSING COMPANY)		319.02	319.02

Thank you for your business.

Pay invoice

SUBTOTAL 10,627.35
TAX 325.67
TOTAL 10,953.02
BALANCE DUE **\$10,953.02**

DISCLAIMER OF W: The seller hereby is expressing all W, either expressed or implied.

All invoices paid by credit or debit card will be subject to a 3% fee. A 3% fee on total labor will be applied to cover the cost of non-billable items used during repairs. These include but are not limited to: Starting Fluid, Brake Cleaner, Shop Towels, Silicone, Buffing Pads, Bolts, Nuts Waste Disposal, Etc